

MAZDA												
Ltr.												
1,1 B1 B116	38-42 kW (52-57 PS)	121	10/87→		<b>H80918-00</b> B376-10-271 A 73 Ø 	<b>X83210-01</b> B630-10-235 		<b>X89660-01</b> B301-13-111 		<b>X82191-01</b> B301-13-460 		
1,1 E1	40 kW (54 PS)	323	11/80-10/89	<b>S37224-00</b> ⑫ E101-99-101	<b>H80896-00</b> E101-10-271 72 Ø 	<b>V37944-00</b> 		<b>X89614-01</b> E331-40-581 B 		<b>X82139-01</b> E301-13-510 A 	<b>X54865-01</b> E301-23-099 	
1,3 B3	40-44 kW (55-60 PS)	121 323	04/87-11/90	<b>S80918-00</b> ⑫ ⑬ 8ABF-10-271 <b>D80918-00</b> ⑫ 8ABF-10-271 HS	<b>H80918-00</b> B376-10-271 A 73 Ø 	<b>X83210-01</b> B630-10-235 	<b>N93041-00</b> B630-10-155 (8x)	<b>X89660-01</b> B301-13-111 		<b>X82191-01</b> B301-13-460 	<b>X54881-01</b> B630-10-431 A 	<b>P77577-01</b> K ← B630-10-602 30x44x7 A SL RD NBR <b>P77541-01</b> K → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01</b> N B630-10-602 30x44x7 A SL RD NBR
1,3 B3 (16V)	53 kW (72 PS)	DEMIO 323	08/98-05/04	<b>S40072-00</b> ⑫ ⑬ 8DDJ-10-271A <b>D40072-00</b> ⑫	<b>H40072-00</b> B31R-10-271 72,5 Ø MLS 	<b>X83247-01</b> B366-10-235 B 	<b>N92012-05</b> KL02-10-155 (16x)	<b>X89772-01</b> B3C7-13-111 		<b>X82295-01</b> B3C7-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428  <b>70-31414-10</b> 	<b>P77489-01</b> K ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01</b> K → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01</b> N B630-10-602 30x44x7 A SL RD NBR
1,3 B3 (16V)	53-54 kW (72-73 PS)	121 323	11/90-03/96	<b>S80964-00</b> ⑫ ⑬ 8CB6-10-271 <b>D80964-00</b> ⑫ 8CB6-10-235	<b>H80964-00</b> B3F2-10-271A 72,9 Ø 	<b>X83247-01</b> B366-10-235 B 	<b>N92012-01</b> B660-10-155 (16x)	<b>X89772-01</b> B3C7-13-111 		<b>X82295-01</b> B3C7-13-460 	<b>E37928-00</b>  <b>70-31414-10</b> 	<b>P77489-01</b> K ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01</b> K → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01</b> N B630-10-602 30x44x7 A SL RD NBR
1,3 B3 (16V)	54 kW (73 PS)	323	08/94-09/98	<b>S80964-00</b> ⑫ ⑬ 8CB6-10-271 →12/96 <b>S40072-00</b> ⑫ ⑬ 8DDJ-10-271A 01/97→ <b>D80964-00</b> ⑫ 8CB6-10-235 →12/96 <b>D40072-00</b> ⑫ 01/97→	<b>H80964-00</b> B3F2-10-271A 72,9 Ø →12/96  <b>H40072-00</b> B31R-10-271 72,5 Ø MLS 01/97→ 	<b>X83247-01</b> B366-10-235 B 	<b>N92012-01</b> B660-10-155 (16x) →12/96 <b>N92012-05</b> KL02-10-155 (16x) 01/97→	<b>X89772-01</b> B3C7-13-111 		<b>X82295-01</b> B3C7-13-460 	<b>E37928-00</b> →12/96  <b>E37923-00</b> B6F4-10-427 +B6F4-10-428 01/97→  <b>70-31414-10</b> 	<b>P77489-01</b> K ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01</b> K → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01</b> N B630-10-602 30x44x7 A SL RD NBR

MAZDA													
Ltr.													
1,3 DHF DHG	55 kW (75 PS)	121	03/96-04/03	<b>D36695-00</b> <sup>(12)</sup> <sup>(31)</sup> →11/99 <b>D36696-00</b> <sup>(12)</sup> 12/99→  <b>B32223-00</b> <sup>(13)</sup> →11/99 <b>B36094-00</b> <sup>(13)</sup> <sup>(35)</sup> 12/99→	<b>H50460-00</b> 1E05-10-271A 72,9 Ø MLS →05/98  <b>H80458-00</b> 1E05-10-271C 73 Ø MLS 06/98→ 	<b>T37958-00</b> C605-10-135 	<b>X53260-01</b> <sup>(31)</sup> NBR  <b>X83117-01</b> <sup>(34)</sup> C201-10-235 NBR 	<b>N92981-01</b> C201-10-155 (8x) +C201-10-1F5 (8x)	<b>X57798-01</b> 1E05-13-111A →11/99  <b>X88196-01</b> C201-13-111 12/99→ 	2x  4x	<b>X51627-01</b> 	<b>X54222-01</b> 1E05-10-431 Aluminium →11/99  <b>70-31414-10</b> 12/99→ 	<b>P76481-01</b> K ← C201-10-602 33x47x5 A SL RD FPM <b>P76482-01</b> K → →11/99 <b>P77248-01</b> K → C201-11-311 80x182x19,4 PTFE FPM 12/99→ <b>P76483-01</b> N 2x C201-10-231 38x52x6 A SL RD NBR
1,3 E3	44 kW (60 PS)	323	11/80-05/89	<b>S80897-02</b> <sup>(12)</sup> <sup>(13)</sup> 8AB5-10-271 01/85→ <b>D80897-01</b> <sup>(12)</sup> E5A1-99-100 AHS →12/84 <b>D80897-02</b> <sup>(12)</sup> 8AB5-10-271 HS 01/85→	<b>H80897-20</b> E580-10-271 B 79 Ø 		<b>V37944-00</b> 	<b>N93001-00</b> RF01-10-F155F (8x)	<b>X89626-01</b> E5A1-13-111 A →12/84  <b>X89627-01</b> E563-13-111 A 01/85→ 		<b>X82139-01</b> E301-13-510 A 	<b>X54865-01</b> E301-23-099 	<b>P76115-00</b> K ← 0187-10-507B 40x55x8 A SL RD MVQ <b>P77508-01</b> K → 0370-11-399 70x88x12 A SL LD MVQ
1,3 E3	50 kW (68 PS)	323	09/85-03/87	<b>S80897-02</b> <sup>(12)</sup> <sup>(13)</sup> 8AB5-10-271 <b>D80897-02</b> <sup>(12)</sup> 8AB5-10-271 HS	<b>H80897-20</b> E580-10-271 B 79 Ø 		<b>V37944-00</b> 	<b>N93001-00</b> RF01-10-F155F (8x)	<b>X89627-01</b> E563-13-111 A 		<b>X82139-01</b> E301-13-510 A 	<b>X54865-01</b> E301-23-099 	<b>P76115-00</b> K ← 0187-10-507B 40x55x8 A SL RD MVQ <b>P77508-01</b> K → 0370-11-399 70x88x12 A SL LD MVQ
1,3 FUJA	55 kW (75 PS)	DEMIO 2	02/03→	<b>D36720-00</b> <sup>(12)</sup>  <b>B36094-00</b> <sup>(13)</sup> <sup>(35)</sup>	<b>H80585-00</b> C201-10-271A 73 Ø MLS 	<b>T37958-00</b> C605-10-135 	<b>X53260-01</b> <sup>(31)</sup> NBR  <b>X83117-01</b> <sup>(34)</sup> C201-10-235 NBR 	<b>N92981-01</b> C201-10-155 (8x) +C201-10-1F5 (8x)	<b>X88199-01</b> C201-13-111 	4x	<b>X81687-01</b> C601-13-460 →11/03  <b>X87773-01</b> C201-13-460 11/03→ 	<b>70-31414-10</b> 	<b>P76481-01</b> K ← C201-10-602 33x47x5 A SL RD FPM <b>P77248-01</b> K → C201-11-311 80x182x19,4 PTFE FPM <b>P76483-01</b> N 2x C201-10-231 38x52x6 A SL RD NBR
1,3 JJK JJM J4R J4T	37-44 kW (50-60 PS)	121	03/96-04/03	<b>S32680-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>S36093-00</b> <sup>(12)</sup> <b>D32680-00</b> <sup>(12)</sup> <b>B32680-00</b> <sup>(13)</sup> <b>B36093-00</b> <sup>(13)</sup> <sup>(24)</sup>	<b>H50074-01</b> 1E03-10-271 75,5 Ø 	<b>T50076-00</b> 1E03-10-135 (10x) 	<b>X07211-01</b> 1E03-10-235 Kork 	<b>N92470-00</b> 1E03-10-155 (8x) <b>P76652-00</b> 1E03-10-155	<b>X58326-01</b> 1E03-13-111B 	8x	<b>X51172-01</b> 1E03-13-460 	<b>E31451-00</b> <sup>(24)</sup> 1E03-10-431  <b>X54482-01</b> 1E03-10-431 Aluminium NBR 	<b>P76079-01</b> K ← 1E03-10-602A 36,5x52,5x8 A SL RD MVQ <b>P76266-01</b> K → 60,3x76,2x11,1 A SL LD MVQ

MAZDA													
1,3 ZJ-VE	62 kW (84 PS)	2	01/10-06/15	<b>S40660-01</b> <sup>12</sup> <sup>13</sup> 8LB4-10-271B	<b>H40660-00</b> ZJ01-10-271A 76 Ø MLS 	<b>T40660-00</b> ZJ01-10-135 (10X) 	<b>X59527-01</b> ZJ20-10-235 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x)	<b>X59483-01</b> Z6TM-13-111 4x 	<b>X59458-01</b> Z668-13-460A 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ	
1,4 B3 ME	54 kW (73 PS)	323	09/98-01/01	<b>S40071-00</b> <sup>12</sup> <sup>13</sup> 8DDC-10-271 <b>D40071-00</b> <sup>12</sup>	<b>H40071-00</b> B3D2-10-271A 72,5 Ø 		<b>X83247-01</b> B366-10-235 B 	<b>N92012-05</b> KL02-10-155 (16x) <b>P76957-00</b> 16x	<b>X89772-01</b> B3C7-13-111 	<b>X82295-01</b> B3C7-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> ← B630-10-602 30x44x7 A SL RD NBR	
1,4 FXJA	59 kW (80 PS)	DEMIO 2	02/03→	<del><b>D36723-00</b> <sup>12</sup></del> <del><b>B36722-00</b> <sup>13</sup></del>	<b>H80586-00</b> C401-10-271 77 Ø MLS 	<b>T37958-00</b> C605-10-135 	<b>X53260-01</b> <sup>31</sup> NBR  <b>X83117-01</b> <sup>34</sup> C201-10-235 NBR 	<b>N92981-01</b> C201-10-155 (8x) +C201-10-1F5 (8x)	<b>X88199-01</b> C201-13-111 4x 	<b>X81687-01</b> C601-13-460 →10/03  <b>X87773-01</b> C201-13-460 11/03→ 	<b>70-31414-10</b> 	<b>P76481-01 K</b> ← C201-10-602 33x47x5 A SL RD FPM <b>P77248-01 K</b> → C201-11-311 80x182x19,4 PTFE FPM <b>P76483-01 N</b> 2x C201-10-231 38x52x6 A SL RD NBR	
1,4 F6JA F6JB Y404 <b>[NEW]</b>	50 kW (68 PS)	2	04/03→	<del><b>D36724-00</b> <sup>12</sup></del> <del><b>B36724-00</b> <sup>13</sup></del>	<b>H08129-00</b> Y401-10-271 1,2 mm 2 MLS <b>H08129-10</b> Y401-10-272 1,3 mm 3 MLS <b>H08129-20</b> Y401-10-273 1,35 mm 1 MLS <b>H18129-30</b> Y401-10-274 1,4 mm 4 MLS <b>H18129-40</b> Y401-10-2H1 74,7 Ø 1,45 mm 5 MLS 	<b>T08130-00</b> Y601-10-135A (10x) 	<b>V38516-00</b> Y401-10-235 +Y401-13-113 (4x) +Y401-10-219 (2x)  <b>X83035-01</b> Y401-10-235 NBR 	<b>N92983-00</b> Y401-10-155 (8x) <b>P76779-00</b> Y401-10-155	<b>W88317-01</b> Y401-13-113 4x 8x 	<b>X81696-01</b> Y401-13-460 	<b>70-31414-10</b> 	<b>P77361-01 K</b> ← Y401-10-602 40x55x6,4 A SL RD PTFE ACM <b>P77362-01 K</b> → Y401-11-312 85x105x8,8 A SL LD PTFE ACM <b>P77668-01 N</b> Y401-12-602 27x47x7 A SL RD PTFE ACM	
1,4 ZJ-VE	55-63 kW (75-86 PS)	2	10/07-06/15	<b>S40660-01</b> <sup>12</sup> <sup>13</sup> 8LB4-10-271B	<b>H40660-00</b> ZJ01-10-271A 76 Ø MLS 	<b>T40660-00</b> ZJ01-10-135 (10X) 	<b>X59527-01</b> ZJ20-10-235 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x)	<b>X59483-01</b> Z6TM-13-111 4x 	<b>X59458-01</b> Z668-13-460A 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ	

MAZDA													
Ltr.			<b>1</b>										
1,4 ZJ-VE	62 kW (84 PS)	3	10/03-06/09	<b>S40660-00</b> <sup>12</sup> <sup>13</sup> 8LD1-10-271 →02/05 <b>S40660-01</b> <sup>12</sup> <sup>13</sup> 8LB4-10-271B 03/05→	<b>H40660-00</b> ZJ01-10-271A 76 Ø MLS 	<b>T40660-00</b> ZJ01-10-135 (10X) 	<b>X59503-01</b> ZJ01-10-235 →02/05  <b>X59527-01</b> ZJ20-10-235 03/05→ 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) 	<b>X59483-01</b> Z6TM-13-111 4x 	<b>X59458-01</b> Z668-13-460A 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ	
1,5 B5	54-55 kW (73-75 PS)	323	01/87-09/91	<b>S80919-02</b> <sup>12</sup> <sup>13</sup> 8ABS-10-271 <b>D80919-01</b> <sup>12</sup>	<b>H80919-00</b> B630-10-271 A 80 Ø 		<b>X83210-01</b> B630-10-235 	<b>N93041-00</b> B630-10-155 (8x) 	<b>X89662-01</b> B501-13-111 2x 	<b>X82151-01</b> B630-13-460 A 	<b>X54881-01</b> B630-10-431 A 	<b>P77577-01 K</b> ← B630-10-602 30x44x7 A SL RD NBR <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> B630-10-602 30x44x7 A SL RD NBR	
1,5 B5	55 kW (75 PS)	DEMIO	04/00-07/03	<b>S37225-00</b> <sup>12</sup> <sup>13</sup> 8HBW-10-271 <b>D37225-00</b> <sup>12</sup>	<b>H40372-00</b> B5C7-10-271 79,5 Ø MLS 		<b>X83247-01</b> B366-10-235 B 	<b>N92012-05</b> KL02-10-155 (16x) <b>P76957-00</b> 16x 	<b>X89966-01</b> B34M-13-111 	<b>X82295-01</b> B3C7-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> B630-10-602 30x44x7 A SL RD NBR	
1,5 E5	65 kW (88 PS)	323	03/82-05/89	<b>S80897-00</b> <sup>12</sup> <sup>13</sup> E580-99-100 D →11/82 <b>S80897-01</b> <sup>12</sup> <sup>13</sup> E5A1-99-100 A 12/82→ <b>D80897-04</b> <sup>12</sup> E580-99-101 →11/82 <b>D80897-01</b> <sup>12</sup> E5A1-99-100 AHS 12/82-12/84 <b>D80897-03</b> <sup>12</sup> 8AB3-10-271 HS 01/85→	<b>H80897-20</b> E580-10-271 B 79 Ø →12/84 <b>H80897-10</b> E5D7-10-271 79 Ø 01/85→ 		<b>V37944-00</b> 	<b>N93001-00</b> RF01-10-F155F (8x) 	<b>X89614-01</b> E331-40-581 B →11/82  <b>X89626-01</b> E5A1-13-111 A 12/82→ 	<b>X82140-01</b> E504-13-502 →11/82  <b>X82139-01</b> E301-13-510 A 12/82-12/84  <b>X82150-01</b> E5B6-13-510 A 01/85→ 	<b>X54865-01</b> E301-23-099 	<b>P76115-00 K</b> ← 0187-10-507B 40x55x8 A SL RD MVQ <b>P77508-01 K</b> → 0370-11-399 70x88x12 A SL LD MVQ	
1,5 ZL05 ZL06	65 kW (88 PS)	323	09/98-01/01	<b>S40066-00</b> <sup>12</sup> <sup>13</sup> 8HBN-10-271 <b>D40066-00</b> <sup>12</sup>	<b>H40066-00</b> ZL01-10-271A 79,5 Ø 0,3 mm MLS 		<b>X83303-01</b> ZL01-10-235 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x) 	<b>X89762-01</b> ZL01-13-111 	<b>X82282-01</b> ZL01-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77584-01 N</b> ← F801-10-602 34x48x7 A SL RD NBR	



MAZDA													
Ltr.													
1,5 ZY-DE ZY-VE ZY05 ZY66 <b>[NEW]</b>	75-82 kW (102-111 PS)	2	04/03→	<b>S40568-01</b> ⑫ ⑬ 8LBU-10-271	<b>H40568-00</b> ZY01-10-271A 80 Ø MLS 	<b>T40660-00</b> ZJ01-10-135 (10x) 	<b>X59527-01</b> ZJ20-10-235 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5	<b>X59483-01</b> Z6TM-13-111 4x 8x 8x 	<b>X59458-01</b> Z668-13-460A 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ	
1,5 Z5-DE	65 kW (88 PS)	323	07/94-09/98	<b>S40002-00</b> ⑫ ⑬ 8EBC-10-271 <b>D40002-00</b> ⑫ 	<b>H40002-00</b> Z501-10-271 76,5 Ø MLS 		<b>X83262-01</b> Z505-10-235A 	<b>N93046-00</b> Z501-10-155 (8x) +Z501-10-1F5 (8x)	<b>X89693-01</b> Z501-13-111 	<b>X82220-01</b> Z501-13-460 	<b>X54901-01</b> 2x  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77584-01 N</b> ← F801-10-602 34x48x7 A SL RD NBR	
1,6 B6	65-66 kW (88-90 PS)	323	08/89-10/94	<b>S40073-00</b> ⑫ ⑬ 8CBY-10-271 <b>D40073-00</b> ⑫ 8CBY-10-235	<b>H40073-00</b> B64D-10-271A 79,5 Ø 1,3 mm 		<b>X83247-01</b> B366-10-235 B 	<b>N92012-01</b> B660-10-155 (16x)	<b>X89772-01</b> B3C7-13-111 	<b>X82295-01</b> B3C7-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> ← B630-10-602 30x44x7 A SL RD NBR	
1,6 B6 (DOHC) B6D	79 kW (107 PS)	MX-3 XEDOS	01/94-10/99	<b>S40065-00</b> ⑫ ⑬ 8DC3-10-271 <b>D40065-00</b> ⑫	<b>H40065-00</b> B6DC-10-271 79,5 Ø 	<b>T40362-00</b> B660-10-135A (10x) 	<b>X83261-01</b> B6S7-10-235A 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x)	<b>X89761-01</b> B69F-13-111 	<b>X82267-01</b> B6S7-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77584-01 N</b> ← 2x F801-10-602 34x48x7 A SL RD NBR	
1,6 B6 (SOHC)	63-77 kW (85-105 PS)	323	08/85-10/95	<b>S80919-00</b> ⑫ ⑬ 8AB7-10-271 →12/87 <b>S80919-01</b> ⑫ ⑬ 8ABT-10-271 A 01/88→ <b>D80919-00</b> ⑫ 8AB1-10-235	<b>H80919-00</b> B630-10-271 A 80 Ø 		<b>X83210-01</b> B630-10-235 	<b>N93041-00</b> B630-10-155 (8x)	<b>X89628-01</b> B630-13-111 	<b>X82151-01</b> B630-13-460 A 	<b>X54881-01</b> B630-10-431 A 	<b>P77577-01 K</b> ← B630-10-602 30x44x7 A SL RD NBR <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> B630-10-602 30x44x7 A SL RD NBR	

MAZDA														
Ltr.			<b>1</b>											
1,6 B6 Turbo	103 kW (140 PS)	323	10/85-08/93	<b>S80920-01</b> <sup>12</sup> <sup>13</sup> 8ABD-10-271 <b>D80920-00</b> <sup>12</sup> 8AB3-10-235	<b>H80920-00</b> B6F4-10-271 B 79,5 Ø 	<b>T40362-00</b> B660-10-135A (10x) 	<b>V37948-00</b> B660-10-235A 	<b>N92012-01</b> B660-10-155 (16x) 	<b>X89629-01</b> BJ01-13-111 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428 04/87→  <b>X54881-01</b> B630-10-431 A →03/87  <b>70-31414-10</b> 04/87→ 	<b>P77577-01 K</b> ← B630-10-602 30x44x7 <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77584-01 N</b> ← 2x F801-10-602 34x48x7 A SL RD NBR			
1,6 B6E	62-63 kW (84-86 PS)	323	09/86-10/95	<b>S80966-00</b> <sup>12</sup> <sup>13</sup> BCB1-10-271  <b>D80966-00</b> <sup>12</sup> 8AB4-10-235	<b>H80966-00</b> B61L-10-271 79,8 Ø 	<b>T40362-00</b> B660-10-135A (10x) 	<b>X83247-01</b> B366-10-235 B 	<b>N93041-00</b> B630-10-155 (8x) 	<b>X89661-01</b> B61K-13-111 	<b>X82193-01</b> B61K-13-460 A 	<b>70-31414-10</b> 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> B630-10-602 30x44x7 A SL RD NBR		
1,6 B6ZE Z6	77 kW (105 PS)	3	10/03-06/09	<b>S40568-00</b> <sup>12</sup> <sup>13</sup> 8LB9-10-271 →02/05 <b>S40568-01</b> <sup>12</sup> <sup>13</sup> 8LBU-10-271 03/05→	<b>H40568-00</b> ZY01-10-271A 80 Ø MLS 		<b>X59503-01</b> ZJ01-10-235 →02/05  <b>X59527-01</b> ZJ20-10-235 03/05→ 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5	<b>X59483-01</b> 4x Z6TM-13-111 8x 	<b>X59458-01</b> Z668-13-460A 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ		
1,6 B64F 8AN1	66-85 kW (90-115 PS)	MX-5	05/90-04/98	<b>S80920-00</b> <sup>12</sup> <sup>13</sup> 8DN1-10-271 <b>D80920-01</b> <sup>12</sup>	<b>H80920-00</b> B6F4-10-271 B 79,5 Ø 	<b>T40362-00</b> B660-10-135A (10x) 	<b>X83301-01</b> B61P-10-235B 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x)	<b>X89759-01</b> B61-P13-111 	<b>X82152-01</b> B695-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77584-01 N</b> ← 2x F801-10-602 34x48x7 A SL RD NBR		
1,6 B69	65 kW (88 PS)	MX-3	07/91-10/97	<b>S40073-00</b> <sup>12</sup> <sup>13</sup> 8CBY-10-271 <b>D40073-00</b> <sup>12</sup> 8CBY-10-235	<b>H40073-00</b> B64D-10-271A 79,5 Ø 1,3 mm 		<b>X83247-01</b> B366-10-235 B 	<b>N92012-01</b> B660-10-155 (16x) 	<b>X89772-01</b> B3C7-13-111 	<b>X82295-01</b> B3C7-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> ← B630-10-602 30x44x7 A SL RD NBR		

MAZDA												
Ltr.												
1,6 FYJA	74 kW (100-101 PS)	DEMIO 2	02/03→	<p><b>D37048-00</b> ⑫ →09/03</p> <p><del></del></p> <p><b>D36728-00</b> ⑫ 10/03→</p> <p><del></del></p> <p><b>B36722-00</b> ⑬</p>	<p><b>H80588-00</b> C601-10-271A 80 Ø MLS →09/03</p> <p><b>H80591-00</b> C601-10-271B 80 Ø MLS 10/03→</p>	<p><b>T37958-00</b> C605-10-135</p>	<p><b>X53260-01</b> ⑳ NBR</p> <p><b>X83117-01</b> ㉔ C201-10-235 NBR</p>	<p><b>N92981-01</b> C201-10-155 (8x) +C201-10-1F5 (8x)</p>	<p><b>X88199-01</b> C201-13-111</p> <p>4x</p>	<p><b>X81687-01</b> C601-13-460 →11/03</p> <p><b>X87773-01</b> C201-13-460 12/03→</p>	<p><b>70-31414-10</b></p>	<p><b>P76481-01</b> K ← C201-10-602 33x47x5 A SL RD FPM <b>P77248-01</b> K → </p> <p>C201-11-311 80x182x19,4 PTFE FPM <b>P76483-01</b> N 2x C201-10-231 38x52x6 A SL RD NBR</p>
1,6 F6	59-60 kW (80-82 PS)	B-SERIE 626	11/82-03/96	<p><b>S80898-00</b> ⑫ ⑬ F601-99-100</p> <p><b>D80898-00</b> ⑫ F601-99-101</p>	<p><b>H80898-00</b> F601-10-271 D 83 Ø</p>		<p><b>X83194-01</b> F801-10-235 C</p>	<p><b>N93001-00</b> RF01-10-F155F (8x)</p>	<p><b>X89631-01</b> F801-13-111 A</p>	<p><b>X82155-01</b> F801-13-460 A</p>	<p><b>X54853-01</b> 0221-10-431</p>	<p><b>P77584-01</b> K ← F801-10-602 34x48x7 A SL RD NBR <b>P77528-01</b> K → F285-11-399 90x110x9,5 A SL LD FPM/ACM <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR</p>
1,6 Y406 Y601 Y642 Y646 <b>[NEW]</b>	66-80 kW (90-109 PS)	3 3 CD 3 DI TURBO	06/04→	<p><del></del></p> <p><b>D36730-00</b> ⑫</p> <p><del></del></p> <p><b>B36724-00</b> ⑬</p>	<p><b>H08130-00</b> Y601-10-271 76 Ø 1,25 mm 4 </p> <p>MLS</p> <p><b>H08130-10</b> Y601-10-272 76 Ø 1,3 mm 5 </p> <p>MLS</p> <p><b>H08130-20</b> Y601-10-273 76 Ø 1,35 mm 3 </p> <p>MLS</p> <p><b>H18130-30</b> Y601-10-274 76 Ø 1,4 mm 6 </p> <p>MLS</p> <p><b>H18130-40</b> Y601-10-2H1 76 Ø 1,45 mm 7 </p> <p>MLS</p>	<p><b>T08130-00</b> Y601-10-135A (10x)</p>	<p><b>X83038-01</b> Y601-10-235 NBR</p>	<p><b>N93118-00</b> Y601-10-155 (16x)</p> <p><b>P76780-00</b> Y601-10-155</p> <p>16x</p>	<p><b>W88321-01</b> Y601-13-113</p> <p>4x</p> <p><b>W88322-01</b> Y601-10-238</p> <p>4x</p>	<p><b>X81696-01</b> Y401-13-460</p>	<p><b>70-31414-10</b></p>	<p><b>P77361-01</b> K ← Y401-10-602 40x55x6,4 A SL RD PTFE ACM <b>P77362-01</b> K → Y401-11-312 85x105x8,8 A SL LD PTFE ACM <b>P77668-01</b> N Y401-12-602 27x47x7 A SL RD PTFE ACM</p>

MAZDA														
Ltr.														
1,6 Y650 Y655 Y661 <b>[NEW]</b>	70-85 kW (95-116 PS)	2 3 5	09/10→	<b>D83409-00</b> <sup>12</sup>  <b>B38558-00</b> <sup>13</sup>	<b>H40595-00</b> Y650-10-271 A 75,7 Ø 1,25 mm 5 MLS <b>H40595-10</b> Y650-10-272 B 75,7 Ø 1,3 mm 6 MLS <b>H40595-20</b> Y650-10-273 B 75,7 Ø 1,35 mm 4 MLS <b>H40595-30</b> Y650-10-274 B 75,7 Ø 1,4 mm 7 MLS <b>H40595-40</b> Y650-10-2H1 B 75,7 Ø 1,45 mm 8 MLS 	<b>T08130-00</b> Y601-10-135A (10x) 	<b>X83409-01</b> Y650-10-235 	<b>N92983-00</b> Y401-10-155 (8x) <b>P76779-00</b> Y401-10-155 8x		<b>X59533-01</b> Y650-13-460 	<b>70-31414-10</b> 	<b>P77361-01 K</b> ← Y401-10-602 40x55x6,4 A SL RD PTFE ACM <b>P77362-01 K</b> → Y401-11-312 85x105x8,8 A SL LD PTFE ACM <b>P77668-01 N</b> Y401-12-602 27x47x7 A SL RD PTFE ACM		
1,6 ZM	70-72 kW (95-98 PS)	323	01/01-05/04	<b>S40066-01</b> <sup>12</sup> <sup>13</sup> 8LB2-10-271A <b>D40066-01</b> <sup>12</sup>	<b>H40066-00</b> ZL01-10-271A 79,5 Ø 0,3 mm MLS 		<b>X83303-01</b> ZL01-10-235 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x)	<b>X89762-01</b> ZL01-13-111 		<b>X82282-01</b> ZL01-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77576-01 K</b> → B366-11-310C <b>P77584-01 N</b> ← F801-10-602 34x48x7 A SL RD NBR	
1,6 Z6	79 kW (107 PS)	3	01/10-12/13	<b>S40568-01</b> <sup>12</sup> <sup>13</sup> 8LBU-10-271	<b>H40568-00</b> ZY01-10-271A 80 Ø MLS 		<b>X59527-01</b> ZJ20-10-235 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5 8x 8x	<b>X59483-01</b> Z6TM-13-111 4x 		<b>X59458-01</b> Z668-13-460A 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ	
1,7 PN26 PN27 PN46 PN54 PN62	40-44 kW (54-60 PS)	323 D	01/86→	<b>S80921-00</b> <sup>12</sup> <sup>13</sup> 8EB2-10-271 <b>D80921-00</b> <sup>12</sup> 8EB2-10-235 A	<b>H80921-00</b> PN11-10-271 B 79,5 Ø 		<b>X83211-01</b> PN11-10-235 A 							<b>P77577-01 K</b> ← B630-10-602 30x44x7 A SL RD NBR <b>P77541-01 K</b> → BP05-11-312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> ← B630-10-602 30x44x7 A SL RD NBR

MAZDA													
1.7 4EE1-T	60 kW (82 PS)	323 TD	05/94-09/98	<p>S31177-00 <sup>12</sup> <sup>13</sup></p> <p>D31177-00 <sup>12</sup></p>	<p>H02839-00 1,45 mm MLS</p> <p>H12839-10 1,5 mm 1 </p> <p>MLS</p> <p>H22839-20 80 Ø 1,55 mm 2 </p> <p>MLS</p>	<p>T07916-00</p>	<p>X07915-01</p> <p>X07918-01</p>		<p>X07912-01</p>		<p>X07917-01</p>	<p>X07944-01</p>	<p>P76136-01 K ← 40x52x6 A SL RD ACM</p> <p>P76373-01 K → 87x100x8 A SL LD ACM</p> <p>P76136-01 N 40x52x6 A SL RD ACM</p>
1.8 BP	76 kW (103 PS)	323	08/89-07/94	<p>S40031-00 <sup>12</sup> <sup>13</sup></p> <p>8CB2-10-271A</p> <p>D40031-00 <sup>12</sup></p> <p>8AB5-10-235</p>	<p>H40031-00 BP26-10-271 84,5 Ø MLS</p>	<p>T40362-00 B660-10-135A (10x)</p>	<p>X83282-01 BP01-10-235A</p>	<p>N92012-01 B660-10-155 (16x)</p>	<p>X89726-01 BP01-13-111</p>		<p>X82247-01 BP01-13-460</p>	<p>X54900-01 B541-10-427 +B541-10-428</p>	<p>P77577-01 K ← B630-10-602 30x44x7 A SL RD NBR</p> <p>P77541-01 K → BP05-11-312 83x100x9 A SL LD MVQ</p> <p>P77577-01 N ← B630-10-602 30x44x7 A SL RD NBR</p>
1.8 BP (DOHC) BP22 BP31	94-103 kW (128-140 PS)	323	06/89-07/94	<p>S40001-00 <sup>12</sup> <sup>13</sup></p> <p>D40001-00 <sup>12</sup></p>	<p>H40001-00 BP01-10-271 84,5 Ø MLS</p>	<p>T40362-00 B660-10-135A (10x)</p>	<p>X83260-01 BP05-10-235</p>	<p>N92012-01 B660-10-155 (16x)</p>	<p>X89689-01 BP05-13-111</p>		<p>X82217-01 BP05-13-460</p>	<p>X54900-01 B541-10-427 +B541-10-428</p>	<p>P77489-01 K ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ</p> <p>P77541-01 K → BP05-11-312 83x100x9 A SL LD MVQ</p> <p>P77584-01 N ← F801-10-602 34x48x7 A SL RD NBR</p>
1.8 BPD BP-ZE	102-107 kW (139-146 PS)	MX-5	01/98-10/05	<p>S40067-00 <sup>12</sup> <sup>13</sup></p> <p>8DN5-10-271</p> <p>D40067-00 <sup>12</sup></p>	<p>H40067-00 BP6D-10-271 84,5 Ø 0,75 mm MLS</p>	<p>T40362-00 B660-10-135A (10x)</p>	<p>X83304-01 BP6D-10-235A</p>	<p>N92012-04 KL02-10-155 (8x) +KL01-10-155 (8x)</p>	<p>X89760-01 BP4W-13-111</p>		<p>X82281-01 BPD3-13-460</p>	<p>E37923-00 B6F4-10-427 +B6F4-10-428</p> <p>70-31414-10</p>	<p>P77489-01 K ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ</p> <p>P77541-01 K → BP05-11-312 83x100x9 A SL LD MVQ</p> <p>P77584-01 N ← F801-10-602 34x48x7 A SL RD NBR</p> <p>P77618-01 N ZL09-10-602 47x61x7 A SL RD MVQ</p>
1.8 BPF1 BP-ZE	84-96 kW (114-131 PS)	MX-5 323	09/93-09/98	<p>S40031-01 <sup>12</sup> <sup>13</sup></p> <p>8DN3-10-271</p> <p>D40031-01 <sup>12</sup></p> <p>8AN3-10-235</p>	<p>H40031-00 BP26-10-271 84,5 Ø MLS</p>	<p>T40362-00 B660-10-135A (10x)</p>	<p>X83302-01 BP05-10-235C</p>	<p>N92012-04 KL02-10-155 (8x) +KL01-10-155 (8x)</p>	<p>X89689-01 BP05-13-111</p>		<p>X82281-01 BPD3-13-460</p>	<p>E37923-00 B6F4-10-427 +B6F4-10-428</p> <p>70-31414-10</p>	<p>P77489-01 K ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ</p> <p>P77541-01 K → BP05-11-312 83x100x9 A SL LD MVQ</p> <p>P77584-01 N ← F801-10-602 34x48x7 A SL RD NBR</p>



MAZDA														
1,8 BP-ZE	103 kW (140 PS)	MX-5	05/98-10/05	<b>S40067-00</b> <sup>12</sup> <sup>13</sup> 8DN5-10-271 08/00→ <b>D40067-00</b> <sup>12</sup> 08/00→	<b>H40067-00</b> BP6D-10-271 84,5 Ø 0,75 mm MLS 08/00→ 	<b>T40362-00</b> B660-10-135A (10x) 	<b>X83304-01</b> BP6D-10-235A 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x)	<b>X89760-01</b> BP4W-13-111 		<b>X82281-01</b> BPD3-13-460 	<b>E37923-00</b> B6F4-10-427 +B6F4-10-428  <b>70-31414-10</b> 	<b>P77489-01</b> K ← B3C7-10-602 36,5x50,5x7 A SL RD MVQ <b>P77541-01</b> K → BP05-11-312 83x100x9 A SL LD MVQ <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR <b>P77618-01</b> N ZL09-10-602 47x61x7 A SL RD MVQ	
1,8 FP FPY3	66-84 kW (90-114 PS)	MX-6 PREMACY 626	12/95-03/05	<b>S40000-01</b> <sup>12</sup> <sup>13</sup> 8FG6-10-271  <b>D40000-01</b> <sup>12</sup>	<b>H40000-00</b> FP39-10-271 84,5 Ø MLS 	<b>T50396-00</b> FS01-10-135 (10x) 	<b>V37990-00</b> FSD7-10-235 +FS01-10-237A 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x)	<b>X86175-01</b> FSJ2-13-111A 		<b>X82216-01</b> FS01-13-460 	<b>70-31414-10</b> 	<b>P77432-01</b> K ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77433-01</b> K → FS01-11-399 89x109x9/10 A SL LD <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR	
1,8 FP	77-78 kW (105-106 PS)	626	08/91-06/97	<b>S40000-00</b> <sup>12</sup> <sup>13</sup> 8AGX-10-271  <b>D40000-00</b> <sup>12</sup> 8AG6-10-235	<b>H40000-00</b> FP39-10-271 84,5 Ø MLS 	<b>T50396-00</b> FS01-10-135 (10x) 	<b>X83259-01</b> FS01-10-235B 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x)	<b>X86175-01</b> FSJ2-13-111A 		<b>X82216-01</b> FS01-13-460 	<b>70-31414-10</b> 	<b>P77432-01</b> K ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77433-01</b> K → FS01-11-399 89x109x9/10 A SL LD <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR	
1,8 F8 (8V)	62-67 kW (84-91 PS)			<b>S80901-00</b> <sup>12</sup> <sup>13</sup> FE01-99-100 <b>D80901-00</b> <sup>12</sup> FE01-99-101N	<b>H80901-20</b> F801-10-271 AN 88 Ø 		<b>X83194-01</b> F801-10-235 C 	<b>N93001-00</b> RF01-10-F155F (8x)	<b>X89631-01</b> F801-13-111 A 		<b>X82155-01</b> F801-13-460 A 	<b>X54866-01</b> F801-10-431 	<b>P77584-01</b> K ← F801-10-602 34x48x7 A SL RD NBR <b>P77529-01</b> K → 90x110x9 A SL LD NBR <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR	
1,8 F8 (12V)	65-69 kW (88-94 PS)	626	09/87-05/92	<b>S80972-00</b> <sup>12</sup> <sup>13</sup> 8AG5-10-271 <b>D80972-00</b> <sup>12</sup>	<b>H80972-00</b> FE1H-10-271 B 87,5 Ø 		<b>X83246-01</b> F201-10-235 D 	<b>N93010-00</b> B630-10-155 (12x)			<b>X82192-01</b> F201-13-460 B 	<b>X54866-01</b> F801-10-431 	<b>P77584-01</b> K ← F801-10-602 34x48x7 A SL RD NBR <b>P77528-01</b> K → F285-11-399 90x110x9,5 A SL LD FPM/ACM <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR	

MAZDA												
Ltr.												
1,8 K819 K838	95-98 kW (129-133 PS) MX-3 V6	01/92-10/97	<b>S40068-00</b> <sup>12</sup> <sup>13</sup> 8DE1-10-271 <b>D40068-00</b> 8DE1-10-235	<b>H40068-00 R</b> K801-10-271B 76 Ø 0,35 mm MLS  <b>H40069-00 L</b> K801-10-272B 76 Ø 0,35 mm MLS 	<b>V37991-00 R</b> KL01-10-235B +FS01-10-237A (9x) +KL01-10-243A (2x)  <b>V37992-00 L</b> KL01-10-2D5B +FS01-10-237A (9x) +KL01-10-243A (3x) 	<b>N92012-00</b> KL01-10-155 (12x) +KL02-10-155 (12x) 	<b>X89170-01</b> KL02-13-111A 2x 	<b>X81932-01</b> KL68-13-460 2x 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77680-01 K</b> → KL01-11-312 75x93x9 A SL LD MVQ <b>P77577-01 N</b> 2x B630-10-602 30x44x7 A SL RD NBR		
1,8 L8-DE	93 kW (126 PS) MX-5	03/05→	<b>S37227-00</b> <sup>12</sup> <sup>13</sup> <b>D37228-00</b> <sup>12</sup>	<b>H80594-00</b> L802-10-271 85 Ø MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36733-00</b> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5 8x 	<b>X89970-01</b> LFE2-13-111 8x  <b>X59208-01</b> <sup>10</sup> LFE2-13-135 8x 	<b>X82385-01</b> L327-13-460B 	<b>70-31414-10</b> 	<b>P77364-01 K</b> ← LF01-10-602 37x50x8 A SL RD PTFE <b>P77365-01 K</b> → LF01-11-310 PTFE	
1,8 L813 L823	85-88 kW (116-120 PS) 5 6	08/02→	<b>S36733-00</b> <sup>12</sup> <sup>13</sup>  <b>D36733-00</b> <sup>12</sup> <b>B37229-00</b> <sup>13</sup> 	<b>H80594-00</b> L802-10-271 85 Ø MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36733-00</b> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) 	<b>X88195-01</b> LF01-13-111 4x 	<b>X88193-01</b> L327-13-460A 	<b>70-31414-10</b> 	<b>P77364-01 K</b> ← LF01-10-602 37x50x8 A SL RD PTFE <b>P77365-01 K</b> → LF01-11-310 PTFE	
1,8 RTJ RTK	44 kW (60 PS) 121	03/96-04/03	<b>S36983-00</b> <sup>12</sup> →08/98  <b>S36984-00</b> <sup>12</sup> <sup>13</sup> <sup>35</sup> 09/98→  <b>D36988-00</b> <sup>12</sup> →08/98  <b>D36984-00</b> <sup>12</sup> 09/98→  <b>B31656-00</b> →08/98	<b>H09153-00</b> 1E07-10-271A 83,8 Ø 1,5 mm 2 ■ <b>H19153-10</b> 1E16-10-271A 83,8 Ø 1,6 mm 3 ■ <b>H29153-20</b> 1E24-10-271A 83,8 Ø 1,65 mm 4 ■ 	<b>T09153-00</b> 1E07-10-135 (10x) 	<b>X53132-01</b> 1E07-10-235 NBR →08/98  <b>X53883-01</b> 1E07-10-235A NBR 09/98→ 	<b>N92985-00</b> 1E07-10-155 (8x) <b>P76791-00</b> 1E07-10-155 8x 	<b>X56010-01</b> 1E07-13-111 	<b>X51175-01</b> 1E07-13-460 	<b>X54149-01</b> 1E07-10-431A NBR 	<b>P76285-01 K</b> ← 66,6x89,3x10 AB SL RD NBR <b>P76323-11 K</b> → LE04-11-312 79,38x95,25x11 A SL LD FPM →08/98 <b>P77366-01 K</b> → 79,38 FPM 09/98→ <b>P76043-01 N</b> 28x38x7 A SL RD FPM	

MAZDA														
Ltr.														
2,0 FE (12V) FEY9	71-81 kW (97-110 PS)	E-SERIE 626	09/87-08/98	<b>S80972-03</b> <sup>12</sup> <sup>13</sup> 8AS9-10-271  <b>D80972-03</b> <sup>12</sup>	<b>H80972-00</b> FE1H-10-271 B 87,5 Ø 		<b>X83246-01</b> F201-10-235 D 	<b>N93010-00</b> B630-10-155 (12x)	<b>X89763-01</b> F285-13-111A 		<b>X82283-01</b> FE1H-13-460A 	<b>X54866-01</b> F801-10-431  <b>70-31414-10</b> 	<b>P77584-01</b> K ← F801-10-602 34x48x7 A SL RD NBR <b>P77546-01</b> K → G601-11-399 90x110x8,5 A SL LD MVQ <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR	
2,0 FE (16V)	103-109 kW (140-148 PS)	626	06/87-05/92	<b>S80922-00</b> <sup>12</sup> <sup>13</sup> 8AG6-10-271 <b>D80922-00</b> <sup>12</sup> 8AG6-10-271 HS	<b>H80922-00</b> FE3N-10-271 87,5 Ø 		<b>X83212-01</b> FE3N-10-235 A 	<b>N92012-01</b> B660-10-155 (16x)	<b>X89717-01</b> FE3N-13-111 		<b>X82239-01</b> FE3N-13-460 	<b>X54866-01</b> F801-10-431 	<b>P77584-01</b> K ← F801-10-602 34x48x7 A SL RD NBR <b>P77529-01</b> K → 90x110x9 A SL LD NBR <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR	
2,0 FE (8V) FE-FA FEV4 FE18 FE58 FE60 FE61	60-88 kW (82-120 PS)	E 2000 ,2200 626 929	03/83-05/03	<b>S80901-00</b> <sup>12</sup> <sup>13</sup> FE01-99-100 <b>D80901-00</b> <sup>12</sup> FE01-99-101N	<b>H80901-20</b> F801-10-271 AN 88 Ø 		<b>X83194-01</b> F801-10-235 C 	<b>N93001-00</b> RF01-10-F155F (8x)	<b>X89631-01</b> F801-13-111 A 		<b>X82155-01</b> F801-13-460 A 	<b>X54866-01</b> F801-10-431 	<b>P77584-01</b> K ← F801-10-602 34x48x7 A SL RD NBR <b>P77529-01</b> K → 90x110x9 A SL LD NBR <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR	
2,0 FS	85 kW (115-116 PS)	626	08/91-04/97	<b>S40000-00</b> <sup>12</sup> <sup>13</sup> 8AGX-10-271  <b>D40000-00</b> <sup>12</sup> 8AG6-10-235	<b>H40000-00</b> FP39-10-271 84,5 Ø MLS 	<b>T50396-00</b> FS01-10-135 (10x) 	<b>X83259-01</b> FS01-10-235B 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x)	<b>X86175-01</b> FSJ2-13-111A 		<b>X82216-01</b> FS01-13-460 	<b>70-31414-10</b> 	<b>P77432-01</b> K ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77433-01</b> K → FS01-11-399 89x109x9/10 A SL LD <b>P77584-01</b> N ← 2x F801-10-602 34x48x7 A SL RD NBR	
2,0 FS FS-DS FS2C FS7E FS7G	85-100 kW (115-136 PS)	MPV PREMACY 323 626	05/97-03/05	<b>S40074-00</b> <sup>12</sup> <sup>13</sup> 8CG7-10-271 <b>D40074-00</b> <sup>12</sup>	<b>H40074-00</b> FSH9-10-271 84,5 Ø 0,95 mm MLS 	<b>T50396-00</b> FS01-10-135 (10x) 	<b>V37990-00</b> FSD7-10-235 +FS01-10-237A 	<b>N92012-04</b> KL02-10-155 (8x) +KL01-10-155 (8x)	<b>X86175-01</b> FSJ2-13-111A 		<b>X82216-01</b> FS01-13-460 	<b>70-31414-10</b> 	<b>P77432-01</b> K ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77433-01</b> K → FS01-11-399 89x109x9/10 A SL LD <b>P77584-01</b> N ← 2x F801-10-602 34x48x7 A SL RD NBR	

MAZDA													
Ltr.													
2,0 KF KF1	103-106 kW (140-144 PS) XEDOS V6 323	01/92-01/00	<b>S80998-00</b> <sup>(12) (13)</sup> 8AC2-10-271A  <b>D80998-00</b> <sup>(12)</sup>	<b>H80998-00 R</b> KF01-10-271A 79,5 Ø MLS 	<b>V36993-00 L</b> 	<b>N92012-03</b> B660-10-155 (24x)	<b>X89170-01</b> KL02-13-111A 2x 	<b>X81932-01</b> KL68-13-460 2x 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77680-01 K</b> → KL01-11-312 75x93x9 A SL LD MVQ <b>P77577-01 N</b> 2x B630-10-602 30x44x7 A SL RD NBR			
2,0 LF-DE	110 kW (150 PS) 3	06/09→	<b>S37230-01</b> <sup>(12) (13) (38)</sup> 8LBN-10-271 →01/11 <b>S37230-02</b> <sup>(12) (13) (38)</sup> 8LBZ-10-271 02/11→	<b>H40373-00</b> L3G2-10-271A MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36733-00</b> <sup>(34)</sup> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5	<b>X88195-01</b> LF01-13-111 4x 	<b>X82385-01</b> L327-13-460B →01/11  <b>X59772-01</b> L572-13-460 02/11→ 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← L3G6-10-602 37x50x6 A SL RD <b>P77365-01 K</b> → LF01-11-310 PTFE		
2,0 LF-DE	114 kW (155 PS) 6	01/10→	<b>S40668-01</b> <sup>(12) (13) (38)</sup> 8LBV-10-271	<b>H40668-00</b> LF3F-10-271 89 Ø MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V38534-00</b> L3K9-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5	<b>X59770-01</b> L807-13-111 4x 	<b>X82385-01</b> L327-13-460B 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← L3G6-10-602 37x50x6 A SL RD <b>P77365-01 K</b> → LF01-11-310 PTFE		
2,0 LFF7	107 kW (146 PS) 5	03/05→	<b>S36737-00</b> <sup>(12) (13) (35)</sup> 8LG1-10-271 →08/07  <b>S37230-00</b> <sup>(12) (13)</sup> 09/07→ <b>D36737-00</b> <sup>(12) (34)</sup> →08/07 <b>D36991-00</b> <sup>(12) (31)</sup> →08/07 <b>D37230-00</b> <sup>(12)</sup> 09/07→	<b>H80478-00</b> L309-10-271 89 Ø MLS →08/07  <b>H40373-00</b> L3G2-10-271A MLS 09/07→ 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36732-00</b> <sup>(31)</sup> LF01-10-230  <b>V36733-00</b> <sup>(34)</sup> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5	<b>X88195-01</b> LF01-13-111 4x 	<b>X88193-01</b> L327-13-460A →08/07  <b>X82385-01</b> L327-13-460B 09/07→ 	<b>70-31414-10</b> 	<b>P77364-01 K</b> ← LF01-10-602 37x50x8 A SL RD PTFE <b>P77365-01 K</b> → LF01-11-310 PTFE		
2,0 LFVE LF62	118 kW (160 PS) MX-5	09/08→	<b>S37230-00</b> <sup>(12) (13)</sup> <b>D37230-00</b> <sup>(12)</sup>	<b>H40373-00</b> L3G2-10-271A MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36733-00</b> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5	<b>X89970-01</b> LFE2-13-111 8x  <b>X59208-01</b> <sup>(10)</sup> LFE2-13-135 8x 	<b>X82385-01</b> L327-13-460B 	<b>70-31414-10</b> 	<b>P77364-01 K</b> ← LF01-10-602 37x50x8 A SL RD PTFE <b>P77365-01 K</b> → LF01-11-310 PTFE		
2,0 LFX PEY4 PEY5 PEY6 PEY7 <b>[NEW]</b>	88-121 kW (120-165 PS) CX-5 3 6	11/11→	<b>S40759-00</b> <sup>(12) (13)</sup> 8LAA-10-271B	<b>H40759-00</b> PE01-10-271 87,5 Ø MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>X71007-01</b> PE01-10-235 	<b>N93209-00</b> PE01-10-155 (8x) +PE01-10-1F5 (8x) <b>P76969-00</b> PE01-10-155 <b>P76970-00</b> PE01-10-1F5	<b>X71008-01</b> PE01-13-111 4x 	<b>X71009-01</b> PE17-13-460 	<b>70-31414-10</b> 	<b>P77869-01 K</b> ← PE01-10-602 43x56x6 A SL RD FPM <b>P77870-01 K</b> → PE01-11-312 83x100x9 A SL LD FPM		

MAZDA													
2,0 LFZB LF5H <b>[NEW]</b>	106-110 kW (144-150 PS)	5	09/10→	<b>S40668-01</b> <sup>12 13 38</sup> 8LBV-10-271 →01/11 <b>S40668-00</b> <sup>12 13 38</sup> 8LC3-10-271 02/11→	<b>H40668-00</b> LF3F-10-271 89 Ø MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V38534-00</b> L3K9-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5 8x 	<b>X59770-01</b> L807-13-111 4x 	<b>X82385-01</b> L327-13-460B →01/11  <b>X59772-01</b> L572-13-460 02/11→ 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← L3G6-10-602 37x50x6 A SL RD <b>P77365-01 K</b> → LF01-11-310 PTFE	
2,0 LF17 LF18	104 kW (141 PS)	6	06/02-08/07	<b>S36737-00</b> <sup>12 13 35</sup> 8LG1-10-271 →02/05  <b>S37230-00</b> <sup>12 13</sup> 03/05→ <b>D36737-00</b> <sup>12 34</sup> →02/05 <b>D36991-00</b> <sup>12 31</sup> →02/05 <b>D37230-00</b> <sup>12</sup> 03/05→	<b>H80478-00</b> L309-10-271 89 Ø MLS →02/05  <b>H40373-00</b> L3G2-10-271A MLS 03/05→ 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36732-00</b> <sup>31</sup> LF01-10-230  <b>V36733-00</b> <sup>34</sup> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5 8x 	<b>X88195-01</b> LF01-13-111 4x 	<b>X88193-01</b> L327-13-460A →02/05  <b>X82385-01</b> L327-13-460B 03/05→ 	<b>70-31414-10</b> 	<b>P77364-01 K</b> ← LF01-10-602 37x50x8 A SL RD PTFE <b>P77365-01 K</b> → LF01-11-310 PTFE	
2,0 LF17	104-110 kW (141-150 PS)	3	10/03-06/09	<b>S36737-00</b> <sup>12 13 35</sup> 8LG1-10-271 →02/06  <b>S37230-00</b> <sup>12 13</sup> 03/06→ <b>D36737-00</b> <sup>12 34</sup> →02/06 <b>D36991-00</b> <sup>12 31</sup> →02/06 <b>D37230-00</b> <sup>12</sup> 03/06→	<b>H80478-00</b> L309-10-271 89 Ø MLS →02/06  <b>H40373-00</b> L3G2-10-271A MLS 03/06→ 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36732-00</b> <sup>31</sup> LF01-10-230  <b>V36733-00</b> <sup>34</sup> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5 8x 	<b>X88195-01</b> LF01-13-111 4x 	<b>X88193-01</b> L327-13-460A →02/06  <b>X82385-01</b> L327-13-460B 03/06→ 	<b>70-31414-10</b> 	<b>P77364-01 K</b> ← LF01-10-602 37x50x8 A SL RD PTFE <b>P77365-01 K</b> → LF01-11-310 PTFE	
2,0 LF17	110 kW (150 PS)	3	06/09→	<b>S37230-00</b> <sup>12 13</sup> <b>D37230-00</b> <sup>12</sup>	<b>H40373-00</b> L3G2-10-271A MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36732-00</b> <sup>31</sup> LF01-10-230  <b>V36733-00</b> <sup>34</sup> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5 8x 	<b>X88195-01</b> LF01-13-111 4x 	<b>X82385-01</b> L327-13-460B 	<b>70-31414-10</b> 	<b>P77364-01 K</b> ← LF01-10-602 37x50x8 A SL RD PTFE <b>P77365-01 K</b> → LF01-11-310 PTFE	
2,0 LF5H LF5W	108-111 kW (147-151 PS)	3 3 DISI	06/09→	<b>S40668-00</b> <sup>12 13 38</sup> 8LC3-10-271	<b>H40668-00</b> LF3F-10-271 89 Ø MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V38534-00</b> L3K9-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5 8x 	<b>X59770-01</b> L807-13-111 4x 	<b>X59772-01</b> L572-13-460 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← L3G6-10-602 37x50x6 A SL RD <b>P77365-01 K</b> → LF01-11-310 PTFE	



MAZDA																								
2,0 MA	66 kW (90 PS)	626 929	05/79-12/87	<b>S80900-00</b> <sup>12</sup> <sup>13</sup> HE26-99-100 B <b>D80900-00</b> <sup>12</sup> HE26-99-101 BN	<b>H80900-10</b> 0453-10-271 D 81 Ø 					<b>V37935-00</b> 	<b>N93001-00</b> RF01-10-F155F (8x)												<b>X54853-01</b> 0221-10-431 	
2,0 RF RFG5	55-60 kW (75-82 PS)	626 D	10/92-09/97	<b>S40029-00</b> <sup>12</sup> <sup>13</sup> 8AU3-10-271 B <b>D40029-00</b> <sup>12</sup> 8AU3-10-235	<b>H40029-00</b> RFJ5-10-271 C 87,6 Ø MLS 					<b>X83198-01</b> RF01-10-235 	<b>N93001-00</b> RF01-10-F155F (8x)		<b>X89630-01</b> RF01-13-111 					<b>X82153-01</b> RF01-13-462 		<b>X54866-01</b> F801-10-431 			<b>P77584-01</b> K ← F801-10-602 34x48x7 A SL RD NBR <b>P77529-01</b> K → 90x110x9 A SL LD NBR <b>P77584-01</b> N ← F801-10-602 34x48x7 A SL RD NBR	
2,0 RF-3F RF-4F	66-74 kW (90-101 PS)	PREMACY TD 323 DiTD 323 TD 626 DI 626 DiTD	04/98-03/05	<b>S40070-01</b> <sup>12</sup> <sup>13</sup> 8LB2-10-271 <b>D40070-01</b> <sup>12</sup>	<b>H40070-00</b> RF2A-10-271A 87,5 Ø MLS 					<b>X83305-01</b> RF2A-10-235 	<b>N92012-05</b> KL02-10-155 (16x) <b>P76957-00</b> 16x		<b>X89764-01</b> RF2A-13-111A 				<b>M37909-00</b> RF5C-13-460 (2x) 		<b>70-31414-10</b> 			<b>P77549-01</b> K ← RF2A-10-602 51,5x64x6 A SL RD NBR <b>P77546-01</b> K → G601-11-399 90x110x8,5 A SL LD MVQ <b>P77577-01</b> N B630-10-602 30x44x7 A SL RD NBR		
2,0 RF5C	89-100 kW (121-136 PS)	MPV Di 6 DI	06/02-08/07	<b>S40070-00</b> <sup>12</sup> <sup>13</sup> 8LG3-10-271 <b>D40070-00</b> <sup>12</sup>	<b>H40070-00</b> RF2A-10-271A 87,5 Ø MLS 	<b>T40070-00</b> RF5C-10-135 (10x) 				<b>X83306-01</b> RF5C-10-235 	<b>N92012-05</b> KL02-10-155 (16x) <b>P76957-00</b> 16x		<b>X89764-01</b> RF2A-13-111A 				<b>M37909-00</b> RF5C-13-460 (2x) 		<b>70-31414-10</b> 			<b>P77549-01</b> K ← RF2A-10-602 51,5x64x6 A SL RD NBR <b>P77546-01</b> K → G601-11-399 90x110x8,5 A SL LD MVQ <b>P77577-01</b> N B630-10-602 30x44x7 A SL RD NBR		
2,0 RF7J	81-105 kW (110-143 PS)	3 5 CD 6 6 DI	03/05→	<b>S40070-02</b> <sup>12</sup> <sup>13</sup> 8LBF-10-271 <b>D40070-02</b> <sup>12</sup>	<b>H40070-00</b> RF2A-10-271A 87,5 Ø MLS 	<b>T40070-00</b> RF5C-10-135 (10x) 				<b>X83306-01</b> RF5C-10-235 	<b>N92012-05</b> KL02-10-155 (16x) <b>P76957-00</b> 16x		<b>X89764-01</b> RF2A-13-111A 				<b>M37909-00</b> RF5C-13-460 (2x) 		<b>70-31414-10</b> 			<b>P77549-01</b> K ← RF2A-10-602 51,5x64x6 A SL RD NBR <b>P77546-01</b> K → G601-11-399 90x110x8,5 A SL LD MVQ <b>P77577-01</b> N B630-10-602 30x44x7 A SL RD NBR		

MAZDA												
Ltr.			<b>1</b>									
2,0 YF	91 kW (124 PS)	TRIBUTE	03/00-05/08	<b>B36731-00</b> <sup>13</sup>	<b>H80058-00</b> YF09-10-271B 86 Ø 0,6 mm MLS 	<b>T50067-00</b> YF09-10-135 	<b>X83036-01</b> YF-09-10-235B NBR 	<b>N92995-00</b> YF09-13-111 (8x)	<b>X88318-01</b> YF09-13-111 4x 	<b>X81697-01</b> YF09-13-461 	<b>X54597-01</b> YF09-10-431 NBR 	<b>P77681-01</b> K ← YF10-10-602A 35x50x7 <b>A SL RD PTFE ACM</b> <b>P77684-01</b> K → YF09-11-399 89x108x8 <b>A SL LD ACM</b>
2,2 F2	85 kW (115 PS)	626 12V	11/87-11/96	<b>S80972-01</b> <sup>12</sup> <sup>13</sup> 8AGB-10-271 B 01/88-12/90 <b>S80972-02</b> <sup>12</sup> <sup>13</sup> 8AU8-10-271 01/91→ <b>D80972-01</b> <sup>12</sup> 8AG3-10-235 A 01/88-12/90 <b>D80972-02</b> <sup>12</sup> 01/91→	<b>H80972-00</b> FE1H-10-271 B 87,5 Ø 		<b>X83246-01</b> F201-10-235 D 	<b>N93010-00</b> B630-10-155 (12x)	<b>X89663-01</b> F201-13-111 	<b>X82192-01</b> F201-13-460 B →12/90  <b>X82155-01</b> F801-13-460 A 01/91→ 	<b>X54866-01</b> F801-10-431 	<b>P77584-01</b> K ← F801-10-602 34x48x7 <b>A SL RD NBR</b> <b>P77528-01</b> K → F285-11-399 90x110x9,5 <b>A SL LD FPM/ACM</b> <b>P77584-01</b> N ← F801-10-602 34x48x7 <b>A SL RD NBR</b>
2,2 F2	85 kW (115 PS)	929 12V	01/88-04/89	<b>S80972-01</b> <sup>12</sup> <sup>13</sup> 8AGB-10-271 B →12/90 <b>D80972-01</b> <sup>12</sup> 8AG3-10-235 A	<b>H80972-00</b> FE1H-10-271 B 87,5 Ø 		<b>X83246-01</b> F201-10-235 D 	<b>N93010-00</b> B630-10-155 (12x)	<b>X89663-01</b> F201-13-111 	<b>X82192-01</b> F201-13-460 B →12/90 	<b>X54866-01</b> F801-10-431 	<b>P77584-01</b> K ← F801-10-602 34x48x7 <b>A SL RD NBR</b> <b>P77528-01</b> K → F285-11-399 90x110x9,5 <b>A SL LD FPM/ACM</b> <b>P77584-01</b> N ← F801-10-602 34x48x7 <b>A SL RD NBR</b>
2,2 F2	94 kW (128 PS)	929 12V	04/89-06/91	<b>S80972-01</b> <sup>12</sup> <sup>13</sup> 8AGB-10-271 B →12/90 <b>S80972-02</b> <sup>12</sup> <sup>13</sup> 8AU8-10-271 01/91→ <b>D80972-01</b> <sup>12</sup> 8AG3-10-235 A →12/90 <b>D80972-02</b> <sup>12</sup> 01/91→	<b>H80972-00</b> FE1H-10-271 B 87,5 Ø 		<b>X83246-01</b> F201-10-235 D 	<b>N93010-00</b> B630-10-155 (12x)	<b>X89663-01</b> F201-13-111 	<b>X82192-01</b> F201-13-460 B →12/90  <b>X82155-01</b> F801-13-460 A 01/91→ 	<b>X54866-01</b> F801-10-431 	<b>P77584-01</b> K ← F801-10-602 34x48x7 <b>A SL RD NBR</b> <b>P77528-01</b> K → F285-11-399 90x110x9,5 <b>A SL LD FPM/ACM</b> <b>P77584-01</b> N ← F801-10-602 34x48x7 <b>A SL RD NBR</b>
2,2 R2 R203 R207 R281 R290	46-52 kW (63-71 PS)	B-SERIE B-SERIE D E 2000D , E2200D E-SERIE	01/84-05/03	<b>S80923-00</b> <sup>12</sup> <sup>13</sup> RF01-99-100 <b>D80923-00</b> <sup>12</sup> R202-99-101	<b>H80923-10</b> R2B6-10-271 B 87,5 Ø MLS 		<b>X83198-01</b> RF01-10-235 	<b>N93001-00</b> RF01-10-F155F (8x)	<b>X89630-01</b> RF01-13-111 	<b>X82153-01</b> RF01-13-462 	<b>X54866-01</b> F801-10-431 	<b>P77584-01</b> K ← F801-10-602 34x48x7 <b>A SL RD NBR</b> <b>P77529-01</b> K → 90x110x9 <b>A SL LD NBR</b> <b>P77577-01</b> N B630-10-602 30x44x7 <b>A SL RD NBR</b>

MAZDA													
2,2 R2AA R2BF <b>[NEW]</b>	95-136 kW (129-185 PS)	CX-7 3 3 CD 6 6 D	01/09→	<b>S40760-00</b> <sup>12</sup> <sup>13</sup> 8LE4-10-271	<b>H40760-00</b> R2AA-10-271C 87 Ø MLS 	<b>T40760-00</b> R2AA-10-135 (10x) 	<b>X71014-01</b> R2AA-10-235 	<b>N92012-05</b> KL02-10-155 (16x) <b>P76957-00</b>	<b>X71010-01</b> R2AA-13-111 16x 		<b>X71011-01</b> R2AA-13-460 	<b>70-31414-10</b> 	<b>P77871-01 K</b> ← R2AA-10-602 59x70,5x6 A SL RD FPM <b>P77528-01 K</b> → F285-11-399 90x110x9,5 A SL LD FPM/ACM
2,2 SHY1	110-129 kW (150-175 PS)	CX-5 CX-5 D 3 6 6 D	04/12→	<b>S40761-00</b> <sup>12</sup> <sup>13</sup> 8LK1-10-271	<b>H40761-00</b> SH01-10-271C 85 Ø MLS 	<b>T40761-00</b> SH01-10-135 (10x) 	<b>X71015-01</b> SH01-10-235 	<b>N93210-00</b> SH01-10-155 (8x) +SH01-10-1F5 (8x) <b>P76971-00</b> SH01-10-155 <b>P76972-00</b> PE01-10-1F5	<b>X71012-01</b> SH01-13-111 8x 		<b>X71013-01</b> SH01-13-460 	<b>70-31414-10</b> 	<b>P77872-01 K</b> ← SH01-10-602 51,5x64x7 A SL RD FPM <b>P77873-01 K</b> → SH01-11-312 90x110x7 A SL LD FPM
2,3 KJ -ZEM	155 kW (211 PS)	XEDOS V6	02/95-01/00	<b>S40657-00</b> <sup>12</sup> <sup>13</sup> 8DK3-10-271	<b>H40657-00 R</b> KJ01-10-271 81,5 Ø MLS  <b>H40658-00 L</b> KJ01-10-272 81,5 Ø MLS 		<b>V38523-00 R</b> KJ01-10-235 +FS01-10-237A (11x)  <b>V38524-00 L</b> KJ01-10-2D5 +FS01-10-237A (11x) 	<b>N92012-00</b> KL01-10-155 (12x) +KL02-10-155 (12x)	<b>X59751-01</b> 2x KJ01-13-111 		<b>X81932-01</b> 2x KL68-13-460 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77680-01 K</b> → KL01-11-312 75x93x9 A SL LD MVQ <b>P77577-01 N</b> 2x B630-10-602 30x44x7 A SL RD NBR
2,3 L3 L3C1 L3-VE	104-122 kW (141-166 PS)	MPV TRIBUTE 6	06/02-05/08	<b>S36737-00</b> <sup>12</sup> <sup>13</sup> <sup>35</sup> 8LG1-10-271  <b>D36737-00</b> <sup>12</sup> <sup>34</sup> <b>D36991-00</b> <sup>12</sup> <sup>31</sup>	<b>H80478-00</b> L309-10-271 89 Ø MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36732-00</b> <sup>31</sup> LF01-10-230  <b>V36733-00</b> <sup>34</sup> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x) <b>P76781-00</b> L807-10-155 <b>P76782-00</b> LF01-10-1F5	<b>X88195-01</b> 4x KF01-13-111 8x 		<b>X88193-01</b> L327-13-460A 	<b>70-31414-10</b> 	<b>P77364-01 K</b> ← LF01-10-602 37x50x8 A SL RD PTFE <b>P77365-01 K</b> → LF01-11-310 PTFE
2,3 L3KG L3N9 L3-VDT L3YH	175-191 kW (238-260 PS)	CX-7 3 6	12/05→	<b>S40659-00</b> <sup>12</sup> <sup>13</sup> <sup>38</sup> 8LAB-10-271	<b>H40659-00</b> L3K9-10-271C 89 Ø MLS 		<b>V38534-00</b> L3K9-10-230 	<b>N93184-00</b> L3K9-10-155A (8x) +L3K9-10-1F5A (8x)	<b>X59750-01</b> L3K9-13-111 		<b>X59749-01</b> L3K9-13-460 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← L3G6-10-602 37x50x6 A SL RD <b>P77365-01 K</b> → LF01-11-310 PTFE
2,5 GY-DE	125 kW (170 PS)	MPV V6	09/99-03/02	<b>D32227-00</b> <sup>12</sup> <b>B32227-00</b> <sup>13</sup> AJ03-10-SH0	<b>H50464-00 R</b> GY01-10-272B MLS  <b>H50465-00 L</b> GY01-10-271A 83,5 Ø MLS 	<b>T50464-00</b> GY01-10-135A (16x) 	<b>X53262-01 R</b> GY01-10-235  <b>X83039-01 L</b> GY01-10-2D5 	<b>N93064-00</b> GY01-10-155 (24x) <b>P76665-00</b> GY01-10-155	<b>X57655-01</b> 24x GY01-13-135  <b>X88324-01</b> <sup>10</sup> 2x GY01-13-111 		<b>X51629-01</b> 2x GY01-13-460A 	<b>X54223-01</b> GY01-10-431 NBR 	<b>P77370-01 K</b> ← AJ03-10-602A 47,6x63,5x8,9 AB SL RD ACM <b>P77371-01 K</b> → AJ03-11-312A 91x108x9,5 AB LD NBR

MAZDA												
2,5 KL	120-123 kW (163-167 PS)	MX-6 V6 XEDOS V6 626 V6	01/92-09/02	<b>S36994-00</b> <sup>12</sup> <sup>13</sup> 8CG5-10-271 <b>D36994-00</b> <sup>12</sup>	<b>H40021-00 R</b> KL01-10-271B 85,5 Ø MLS 	<b>V36993-00 L</b>  <b>V36994-00 R</b> 	<b>N92012-00</b> KL01-10-155 (12x) +KL02-10-155 (12x)	<b>X89170-01</b> KL02-13-111A 2x 	<b>X81932-01</b> KL68-13-460 2x 	<b>70-31414-10</b> 	<b>P77432-01 K</b> ← FS01-10-602 42,5x54,5x6 A SL RD <b>P77680-01 K</b> → KL01-11-312 75x93x9 A SL LD MVQ <b>P77577-01 N</b> 2x B630-10-602 30x44x7 A SL RD NBR	
2,5 L5-VE	120-125 kW (163-170 PS)	CX-7 3 6	08/07→	<b>S40667-00</b> <sup>12</sup> <sup>13</sup> <sup>38</sup> 8LGE-10-271 →09/10 <b>S40667-01</b> <sup>12</sup> <sup>13</sup> <sup>38</sup> 8LC2-10-271 10/10→	<b>H40667-00</b> L504-10-271 90,5 Ø MLS 	<b>T80478-00</b> LF01-10-135 (10x) 	<b>V36733-00</b> LF14-10-230 	<b>N92984-00</b> L807-10-155 (8x) +LF01-10-1F5 (8x)	<b>X59771-01</b> L505-13-111 	<b>X82385-01</b> L327-13-460B →09/10 <b>X59772-01</b> L572-13-460 10/10→ 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← L3G6-10-602 37x50x6 A SL RD <b>P77365-01 K</b> → LF01-11-310 PTFE
2,5 MD25NA MD25TI WLE7 WLE9 WLF5 WL-T <b>[NEW]</b>	57-86 kW (78-117 PS)	B-SERIE D B-SERIE TD MPV TD	05/96→	<b>S40020-00</b> <sup>12</sup> <sup>13</sup> 8ASX-10-271 <b>D40020-00</b> <sup>12</sup>	<b>H40020-00</b> WL01-10-271B 94,5 Ø MLS 	<b>T50015-00</b> WL51-10-135B (10x) +WL51-10-136B (8x) 	<b>V37968-00</b> WL01-10-235 	<b>N93017-00</b> WL01-10-155 (12x)	<b>X89710-01</b> WL51-13-111 	<b>X82231-01</b> WL51-13-460A 	<b>70-31414-10</b> 	<b>P77545-01 K</b> ← VS01-10-602 53x70x11 A SL RD <b>P77546-01 K</b> → G601-11-399 90x110x8,5 A SL LD MVQ <b>P77615-01 N</b> RF03-12-603A 32x46x7 A SL RD MVQ
2,5 WLAA WLAT (16 V)	105 kW (143 PS)	BT-50	12/06→	<b>D38551-00</b> <sup>12</sup>  <b>B38543-00</b> <sup>13</sup>	<b>H40669-00</b> WLAA-10-273B 94 Ø 0,82 mm 1 MLS <b>H40669-10</b> WLAA-10-271B 94 Ø 0,87 mm 0 MLS <b>H40669-20</b> WLAA-10-272B 94 Ø 0,92 mm 2 MLS 	<b>T40663-00</b> WL51-10-135B (10x) +WL51-10-136B (4x) +WL51-10-137A (4x) 	<b>X59780-01</b> WE01-10-235 	<b>N92012-05</b> KL02-10-155 (16x) <b>P76957-00</b> 16x	<b>X59768-01</b> WE01-13-111 	<b>X59773-01</b> WE01-13-460 	<b>70-31414-10</b> 	<b>P77829-01 K</b> ← WE01-10-602 60,5x77,35x8 A SL RD FPM/ACM <b>P77830-01 K</b> → WL51-11-399 90x110x8,5 A SL LD FPM <b>P77615-01 N</b> 2x RF03-12-603A 32x46x7 A SL RD MVQ
2,6 G6	89-91 kW (121-124 PS)	B-SERIE	11/89-10/91	<b>S80928-00</b> <sup>12</sup> <sup>13</sup> AM21-10-271A <b>D80928-00</b> <sup>12</sup>	<b>H80928-00</b> AM21-10-271A 93 Ø 	<b>V37941-00</b> 	<b>N93011-00</b> AM01-10-155 (8x)	<b>X89633-01</b> AM01-13-111A 	<b>X82163-01</b> AM01-13-460 	<b>X54882-01</b> AM01-10-431 	<b>P77517-01 K</b> → AM01-11-399 80x96x9 A SL LD MVQ	

MAZDA													
Ltr.													
2,6 G6 (12V)	90-92 kW (122-125 PS)	B-SERIE	01/90-11/06	<b>S40003-00</b> <sup>12</sup> <sup>13</sup> 8AL1-10-271 <b>D40003-00</b> <sup>12</sup> 8AL1-10-235	<b>H40003-00</b> G601-10-271 93,5 Ø 		<b>V37964-00</b> G601-10-235 +G601-10-231 (2x) 	<b>N93010-00</b> B630-10-155 (12x)	<b>X89692-01</b> G601-13-111A 		<b>X82218-01</b> G601-13-460 <b>X82320-01</b> <sup>13</sup> 	<b>X54902-01</b> G601-10-431  <b>70-31414-10</b> 	<b>P77529-01 K</b> → 90x110x9 A SL LD NBR
3,0 AJ	145 kW (197 PS)	TRIBUTE V6	03/00-05/08	<b>D37083-00</b> <sup>12</sup> AJ03-10-SF0 →12/03 <b>D37083-01</b> <sup>12</sup> 01/04→ <b>B32227-00</b> <sup>13</sup> AJ03-10-SH0 →02/05 <b>B37083-00</b> <sup>13</sup> 03/05→	<b>H80743-00 R</b> AJ03-10-271 91 Ø MLS  <b>H80744-00 L</b> AJ03-10-272 91 Ø MLS 	<b>T50464-00</b> GY01-10-135A (16x) 	<b>X83136-01 R</b> AJ03-10-235 NBR  <b>X83137-01 L</b> AJ03-10-2D5 NBR 	<b>N93064-00</b> GY01-10-155 (24x) <b>P76665-00</b> GY01-10-155 24x	<b>X89305-01</b> AJ03-13-111B 6x  <b>X89306-01</b> <sup>10</sup> AJ03-13-135 →12/03 6x  <b>X59964-01</b> <sup>10</sup> AJB4-13-135 01/04→ 6x 	<b>X51629-01</b> GY01-13-460A 2x 	<b>X54223-01</b> GY01-10-431 NBR →02/05  <b>X54819-01</b> ZZC1-10-431 NBR 03/05→ 	<b>P77370-01 K</b> ← AJ03-10-602A 47,6x63,5x8,9 AB SL RD ACM <b>P77371-01 K</b> → AJ03-11-312A 91x108x9,5 AB LD NBR	
3,0 AJ	149 kW (203 PS)	TRIBUTE V6	04/04-05/08	<b>D37083-01</b> <sup>12</sup> <b>B32227-00</b> <sup>13</sup> AJ03-10-SH0 →02/05 <b>B37083-00</b> <sup>13</sup> 03/05→	<b>H80743-00 R</b> AJ03-10-271 91 Ø MLS  <b>H80744-00 L</b> AJ03-10-272 91 Ø MLS 	<b>T50464-00</b> GY01-10-135A (16x) 	<b>X83136-01 R</b> AJ03-10-235 NBR  <b>X83137-01 L</b> AJ03-10-2D5 NBR 	<b>N93064-00</b> GY01-10-155 (24x) <b>P76665-00</b> GY01-10-155 24x	<b>X89305-01</b> AJ03-13-111B 6x  <b>X59964-01</b> <sup>10</sup> AJB4-13-135 6x 	<b>X51629-01</b> GY01-13-460A 2x 	<b>X54223-01</b> GY01-10-431 NBR →02/05  <b>X54819-01</b> ZZC1-10-431 NBR 03/05→ 	<b>P77370-01 K</b> ← AJ03-10-602A 47,6x63,5x8,9 AB SL RD ACM <b>P77371-01 K</b> → AJ03-11-312A 91x108x9,5 AB LD NBR	
3,0 HA	50-66 kW (68-90 PS)			<b>S80924-00</b> <sup>12</sup> <sup>13</sup> SE45-99-100	<b>H80924-00</b> SE01-10-271 99,6 Ø 		<b>X83213-01</b> SE01-10-235 	<b>N93018-00</b>			<b>X82154-01</b> SE01-13-461 4x 	<b>E37924-00</b> SE01-99-104 	<b>P77538-01 K</b> ← 51x70x11 A SL RD MVQ <b>P77539-01 K</b> → 102x125x13 A SL MVQ
3,0 WEAT	115 kW (156 PS)	BT-50	12/06→	<b>D38551-00</b> <sup>12</sup>  <b>B38543-00</b> <sup>13</sup>	<b>H40670-00</b> WE01-10-273B 97 Ø 0,95 mm 1 MLS <b>H40670-10</b> WE01-10-271B 97 Ø 1 mm 0 MLS <b>H40670-20</b> WE01-10-272B 97 Ø 1,05 mm 2 MLS 	<b>T40663-00</b> WL51-10-135B (10x) +WL51-10-136B (4x) +WL51-10-137A (4x) 	<b>X59780-01</b> WE01-10-235 	<b>N92012-05</b> KL02-10-155 (16x)	<b>X59768-01</b> WE01-13-111 		<b>X59773-01</b> WE01-13-460 	<b>70-31414-10</b> 	<b>P77829-01 K</b> ← WE01-10-602 60,5x77,35x8 A SL RD FPM/ACM <b>P77830-01 K</b> → WL51-11-399 90x110x8,5 A SL LD FPM <b>P77615-01 N</b> 2x RF03-12-603A 32x46x7 A SL RD MVQ



MAZDA

Ltr. 





















3,7 CA

204 kW  
(277 PS)

CX-9

1

01/07→

									
	<p><b>H40661-00 R</b> CA01-10-271B MLS </p> <p><b>H40662-00 L</b> CA01-10-272 MLS </p>	<p><b>T40661-00</b> CY01-10-135 (8X) </p>	<p>2x <b>X59777-01 R</b> CY01-10-235A </p> <p><b>X59778-01 L</b> CY01-10-2D5 </p>	<p><b>N93188-00</b> CY01-10-155A (12X) <b>P76958-00</b> CY01-10-155A</p>	<p>2x <b>X59769-01</b> ZZJ1-13-11 24x </p>	6x	<p><b>X59821-01</b> CY01-13-460A 2x </p>	<p><b>70-31414-10</b> </p>	<p><b>P77827-01 K ←</b> CY01-10-602 48x63,4x12,5 A SL RD FPM/ACM <b>P77828-01 K →</b> CY01-11-312A 92x109x14 A SL LD FPM</p>

