

KIA													
Ltr.													
1,0 G4HE	45-46 kW (61-63 PS)	PICANTO	04/04→	<b>S40110-00</b> <sup>13</sup> 20910-02H00  <b>D40110-00</b>	<b>H40110-00</b> 22311-02760 MLS 		<b>X83312-01</b> 22441-02400 	<b>N76832-00</b> 22224-02500 (12x) <b>P76832-00</b> 22224-02500	12x <b>X89748-01</b> 28411-02500 		<b>X82290-01</b> 28521-02700 	<b>70-31414-10</b> 	<b>P77579-01 K</b> ← 21421-21030 30x46x7 <b>A SL RD NBR</b> <b>P77542-01 K</b> → 21443-02500 60x75x8 <b>A SL LD NBR</b> <b>P77585-01 N</b> 22144-3B001 35x50x8 <b>A SL RD NBR</b>
1,1 B1	38 kW (52 PS)	PRIDE	01/91→		<b>H80918-00</b> 73 Ø 		<b>X83210-01</b> 	<b>N93041-00</b>	<b>X89660-01</b> 		<b>X82191-01</b> 	<b>X54881-01</b> 	<b>P77577-01 K</b> ← KKY01 12 602 30x44x7 <b>A SL RD NBR</b> <b>P77541-01 K</b> → 0K201 11 312 83x100x9 <b>A SL LD MVQ</b> <b>P77577-01 N</b> KKY01 12 602 30x44x7 <b>A SL RD NBR</b>
1,1 G4HG	48 kW (65 PS)	PICANTO	04/04→	<b>S40110-00</b> <sup>13</sup> 20910-02H00  <b>D40110-00</b>	<b>H40110-00</b> 22311-02760 MLS 		<b>X83312-01</b> 22441-02400 	<b>N92108-01</b> 22224-02500 (12x)	<b>X89748-01</b> 28411-02500 		<b>X82290-01</b> 28521-02700 	<b>70-31414-10</b> 	<b>P77579-01 K</b> ← 21421-21030 30x46x7 <b>A SL RD NBR</b> <b>P77542-01 K</b> → 21443-02500 60x75x8 <b>A SL LD NBR</b> <b>P77585-01 N</b> 22144-3B001 35x50x8 <b>A SL RD NBR</b>
1,3 B3	44-53 kW (60-72 PS)	PRIDE	01/90→	<b>S80964-00</b> <sup>12 13</sup> <b>D80964-00</b> <sup>12</sup>	<b>H80964-00</b> 72,9 Ø 		<b>X83247-01</b> 	<b>N92012-01</b> 0KL02 10 155 (16x)	<b>X89675-01</b> 		<b>X82238-01</b> 	<b>E37928-00</b>  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← 0B3C7 10 602B 36,5x50,5x7 <b>A SL RD MVQ</b> <b>P77541-01 K</b> → 0K201 11 312 83x100x9 <b>A SL LD MVQ</b> <b>P77577-01 N</b> KKY01 12 602 30x44x7 <b>A SL RD NBR</b>
1,3 B3	55-60 kW (75-82 PS)	RIO	08/00-02/05	<b>S40061-00</b> <sup>12 13</sup> 0K30C 10 270 <b>D40061-00</b> <sup>12</sup>	<b>H40061-00</b> 0K30C 10 271A 76,5 Ø MLS 	<b>T40365-00</b> 0K30C 10 135A (10x) 	<b>X83297-01</b> 0K30C 10 235A 	<b>N93042-00</b> 0K30C 10 155B (8x)	<b>X89753-01</b> 0K30C 13 111C 		<b>X82276-01</b> 28521-2X600 	<b>E37932-00</b> 21522-2X00 +21521-2X00  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← 0B3C7 10 602B 36,5x50,5x7 <b>A SL RD MVQ</b> <b>P77541-01 K</b> → 0K201 11 312 83x100x9 <b>A SL LD MVQ</b>
1,4 G4EE	71 kW (97 PS)	PRIDE RIO	03/05→	<b>S40316-01</b> <sup>13</sup> KSN61 10 270 +21421-22020 	<b>H40316-00</b> 22311-26603 	<b>T40677-00</b> 22321-26000 (10x) 	<b>V38550-00</b> 22441-26020 (1x) +22442-23500 (2x) +22443-23001 (4x) 	<b>N93053-00</b> 22224-23500 (16x)	<b>X89805-01</b> 28411-26011 		<b>X82316-01</b> 28521-26600 	<b>70-31414-10</b> 	<b>P77575-01 K</b> ← 21421-22020 35x48x8 <b>A SL RD FPM</b> <b>P77509-01 K</b> → 21443-22000 72x96x9 <b>A SL LD MVQ</b> <b>P77585-01 N</b> 22144-3B001 35x50x8 <b>A SL RD NBR</b>

KIA												
Ltr.												
1,4 G4FA G4FA-L <b>[NEW]</b>	66-77 kW (90-105 PS) CEE'D PRO CEE'D	06/10→	<b>S40555-00</b> 12 13 20910-2BB01  <b>D40555-00</b> 12 20920-2BB01	<b>H40555-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 	<b>V59399-00</b> 22441-2B002 	<b>N93145-00</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>P76884-00</b> AS 22224-2B000 <b>P76885-00</b> ES 22224-2B010	<b>X59397-01</b> 28411-2B000  8x	<b>X59398-01</b> 28521-2B400 	<b>70-31414-10</b> 	<b>P77737-01</b> K ← 21421-2B030 26x37,5x6 A SL RD FPM <b>P77738-01</b> K → 21443-2B010 76x108x8 A SL LD FPM		
1,4 G4FA	77-80 kW (105-109 PS) CEE'D PRO CEE'D	12/06-12/12	<b>S40553-00</b> 12 13 KSR62-10270 →08/08  <b>S40554-00</b> 12 13 KSR62-10270A 08/08-09/08  <b>S40555-00</b> 12 13 20910-2BB01 09/08→  <b>D40553-00</b> 12 →08/08 <b>D40554-00</b> 12 08/08-09/08 <b>D40555-00</b> 12 20920-2BB01 09/08→	<b>H40553-00</b> 22311-2B000 78,5 Ø 0,5 mm MLS →08/08  <b>H40554-00</b> 22311-2B001 78,5 Ø 0,5 mm MLS 08/08-09/08  <b>H40555-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 09/08→ 	<b>V59399-00</b> 22441-2B002 	<b>N93145-00</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>P76884-00</b> AS 22224-2B000 <b>P76885-00</b> ES 22224-2B010	<b>X59397-01</b> 28411-2B000  8x	<b>X59398-01</b> 28521-2B400 	<b>70-31414-10</b> 	<b>P77737-01</b> K ← 21421-2B030 26x37,5x6 A SL RD FPM <b>P77738-01</b> K → 21443-2B010 76x108x8 A SL LD FPM		
1,4 G4FA-L <b>[NEW]</b>	66 kW (90 PS) VENGA	02/10→	<b>S90192-00</b> 12 13 20910-2BG01  <b>D90218-00</b> 12 20920-2BG01	<b>H40555-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 	<b>V59399-00</b> 22441-2B002 	<b>N93145-00</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>P76884-00</b> AS 22224-2B000 <b>P76885-00</b> ES 22224-2B010	<b>X90273-01</b> 28411-2B350  8x	<b>X59398-01</b> 28521-2B400 	<b>70-31414-10</b> 	<b>P77737-01</b> K ← 21421-2B030 26x37,5x6 A SL RD FPM <b>P77738-01</b> K → 21443-2B010 76x108x8 A SL LD FPM		
1,5 B3	72 kW (98 PS) RIO	09/00-02/05	<b>S40063-00</b> 12 13 OK30E 10 270 <b>D40063-00</b> 12	<b>H40063-00</b> OK30E 10 271A 76,5 Ø MLS 	<b>X83299-01</b> OK30E 10 235 	<b>N93043-00</b> OK30E 10 155 (16x)	<b>X89757-01</b> OK30E 13 111C 	<b>X82278-01</b> OK30E 13 460C 	<b>E37933-00</b> MB6F4 10 428  <b>70-31414-10</b> 	<b>P77541-01</b> K → OK201 11 312 83x100x9 A SL LD MVQ <b>P77617-01</b> N ← 34x52x7 A SL RD MVQ		

KIA													
Ltr.													
1,5 B5	59 kW (80 PS) SEPHIA	02/96-10/97	<b>S40109-00</b> ⑫ ⑬ OK20W 10 270B <b>D40109-00</b> ⑫	<b>H40109-00</b> 0B61L 10 271A 	<b>X83328-01</b> OK2A1 10 235A FPM 	<b>N76831-00</b> MB630 10 155 (8x) <b>P76831-00</b> MB630 10 155	<b>X89802-01</b> OK201 13 111 8x 	<b>X82314-01</b> OK201 13 460A 	<b>E37931-00</b> 21521 2X000 +21522 2X000  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → OK201 11 312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> KKY01 12 602 30x44x7 A SL RD NBR			
1,6 B6	59 kW (80 PS) SEPHIA	09/93-10/97	<b>S40109-00</b> ⑫ ⑬ OK20W 10 270B <b>D40109-00</b> ⑫	<b>H40109-00</b> 0B61L 10 271A 	<b>X83328-01</b> OK2A1 10 235A FPM 	<b>N76831-00</b> MB630 10 155 (8x) <b>P76831-00</b> MB630 10 155	<b>X89802-01</b> OK201 13 111 8x 	<b>X82314-01</b> OK201 13 460A 	<b>E37931-00</b> 21521 2X000 +21522 2X000  <b>70-31414-10</b> 	<b>P77489-01 K</b> ← 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → OK201 11 312 83x100x9 A SL LD MVQ <b>P77577-01 N</b> KKY01 12 602 30x44x7 A SL RD NBR			
1,6 G4ED	82 kW (112 PS) RIO	03/05→	<b>S40316-02</b> ⑫ ⑬ KSR61 10 270 	<b>H40316-00</b> 22311-26603 	<b>T40677-00</b> 22321-26000 (10x) 	<b>V38801-00</b> 22441-26801 +22443-23001 (4x) +22442-23500 (2x) 	<b>N93053-00</b> 22224-23500 (16x) 	<b>X71006-01</b> 28411-26900 	<b>X82316-01</b> 28521-26600 	<b>70-31414-10</b> 	<b>P77575-01 K</b> ← 21421-22020 35x48x8 A SL RD FPM <b>P77509-01 K</b> → 21443-22000 72x96x9 A SL LD MVQ <b>P77585-01 N</b> 22144-3B001 35x50x8 A SL RD NBR		
1,6 G4FC	85-93 kW (115-126 PS) CEE'D PRO CEE'D	12/06-12/12	<b>S40553-00</b> ⑫ ⑬ KSR62-10270 →08/08  <b>S40554-00</b> ⑫ ⑬ KSR62-10270A 08/08-09/08  <b>S40555-00</b> ⑫ ⑬ 20910-2BB01 09/08→  <b>D40553-00</b> ⑫ →08/08 <b>D40554-00</b> ⑫ 08/08-09/08 <b>D40555-00</b> ⑫ 20920-2BB01 09/08→	<b>H40553-00</b> 22311-2B000 78,5 Ø 0,5 mm MLS →08/08  <b>H40554-00</b> 22311-2B001 78,5 Ø 0,5 mm MLS 08/08-09/08  <b>H40555-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 09/08→ 	<b>V59399-00</b> 22441-2B002 	<b>N93145-00</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>P76884-00 AS</b> 22224-2B000 <b>P76885-00 ES</b> 22224-2B010	<b>X59397-01</b> 28411-2B000 8x  8x	<b>X59398-01</b> 28521-2B400 	<b>70-31414-10</b> 	<b>P77737-01 K</b> ← 21421-2B030 26x37,5x6 A SL RD FPM <b>P77738-01 K</b> → 21443-2B010 76x108x8 A SL LD FPM			

KIA														
Ltr.														
1,6 G4FC	90 kW (122 PS) CERATO	05/06→		<b>S40553-00</b> <sup>12</sup> <sup>13</sup> KSR62-10270 →08/08  <b>S40554-00</b> <sup>12</sup> <sup>13</sup> KSR62-10270A 08/08-10/08  <b>S40555-00</b> <sup>12</sup> <sup>13</sup> 20910-2BB01 11/08→  <b>D40553-00</b> <sup>12</sup> →08/08 <b>D40554-00</b> <sup>12</sup> 08/08-10/08 <b>D40555-00</b> <sup>12</sup> 20920-2BB01 11/08→	<b>H40553-00</b> 22311-2B000 78,5 Ø 0,5 mm MLS →08/08  <b>H40554-00</b> 22311-2B001 78,5 Ø 0,5 mm MLS 08/08-10/08  <b>H40555-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 11/08→ 					<b>V59399-00</b> 22441-2B002  <b>N93145-00</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>P76884-00</b> AS 22224-2B000 <b>P76885-00</b> ES 22224-2B010	<b>X59397-01</b> 28411-2B000 8x  8x <b>X59398-01</b> 28521-2B400 		<b>70-31414-10</b>  <b>P77737-01</b> K ← 21421-2B030 26x37,5x6 A SL RD FPM <b>P77738-01</b> K → 21443-2B010 76x108x8 A SL LD FPM	
1,6 G4FC	92-97 kW (125-132 PS) CARENS CEE'D PRO CEE'D SOUL	02/09→		<b>S40555-00</b> <sup>12</sup> <sup>13</sup> 20910-2BB01  <b>D40555-00</b> <sup>12</sup> 20920-2BB01	<b>H40555-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 					<b>V59399-00</b> 22441-2B002  <b>N93145-00</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>P76884-00</b> AS 22224-2B000 <b>P76885-00</b> ES 22224-2B010	<b>X59397-01</b> 28411-2B000 8x  8x <b>X59398-01</b> 28521-2B400 	<b>70-31414-10</b>  <b>P77737-01</b> K ← 21421-2B030 26x37,5x6 A SL RD FPM <b>P77738-01</b> K → 21443-2B010 76x108x8 A SL LD FPM		
1,6 G4FD <b>[NEW]</b>	97-103 kW (132-140 PS) CEE'D PRO CEE'D SOUL SPORTAGE	02/11→		<b>S40555-01</b> <sup>12</sup> <sup>13</sup> 20910-2BK01  <b>D40555-01</b> <sup>12</sup> 20920-2BK01	<b>H40555-00</b> 22311-2B003 78,5 Ø 0,5 mm MLS 					<b>X90210-01</b> ACM  <b>N93145-00</b> 22224-2B000 (8x) +22224-2B010 (8x) <b>P76884-00</b> AS 22224-2B000 <b>P76885-00</b> ES 22224-2B010	<b>X90249-01</b> 28411-2B600 8x  8x <b>X59398-01</b> 28521-2B400 	<b>70-31414-10</b>  <b>P77737-01</b> K ← 21421-2B030 26x37,5x6 A SL RD FPM <b>P77738-01</b> K → 21443-2B010 76x108x8 A SL LD FPM		
1,8 OK24N OK26Y	82 kW (112 PS) SEPHIA	01/95-10/97		<b>S38532-00</b> <sup>12</sup> <sup>13</sup> OK9A0 10 270B 	<b>H40062-00</b> OK247 10 271C 81,5 Ø MLS 	<b>T40062-00</b> OK247 10 135 (10x) 				<b>X83298-01</b> OK247 10 235B  <b>N93187-00</b> OKL01 10 155 (8x) +OKL02 10 155 (8x) <b>P76956-00</b> ES OKL01 10 155 <b>P76957-00</b> AS OKL02 10 155	<b>X89754-11</b> A OK247 13 135D 8x  <b>X89755-01</b> I OK247 13 111A 8x 	<b>70-31414-10</b>  <b>P77489-01</b> K ← 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>P77550-01</b> K → OK247 11 312 88x104x8,5 A LD MVQ <b>P77584-01</b> N OK013 10 602 34x48x7 A SL RD NBR		

KIA													
Ltr.				1									
1,8 T8	81 kW (110 PS)	SHUMA	10/97-03/01	<b>S40062-00</b> ⑫ ⑬ OK2BC 10 270 <b>D40062-00</b> ⑫	<b>H40062-00</b> OK247 10 271C 81,5 Ø MLS 	<b>T40062-00</b> OK247 10 135 (10x) 	<b>X83298-01</b> OK247 10 235B 	<b>N93006-01</b>	<b>X89754-01 A</b> OK2A5 13 135  <b>X89755-01 I</b> OK247 13 111A 		<b>X82277-01</b> OK2A5 13 460 	<b>70-31414-10</b> 	<b>P77489-01 K</b> ← 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>P77550-01 K</b> → OK247 11 312 88x104x8,5 A LD MVQ <b>P77584-01 N</b> ← OK013 10 602 34x48x7 A SL RD NBR
1,8 T8	81-85 kW (110-116 PS)	CARENS CLARUS	07/96→	<b>S40062-01</b> ⑫ ⑬ OK2CA 10 270 <b>D40062-01</b> ⑫	<b>H40062-00</b> OK247 10 271C 81,5 Ø MLS 	<b>T40062-00</b> OK247 10 135 (10x) 	<b>X83298-01</b> OK247 10 235B 	<b>N93006-01</b>	<b>X89754-01</b> OK2A5 13 135 		<b>X82277-01</b> OK2A5 13 460 	<b>70-31414-10</b> 	<b>P77489-01 K</b> ← 0B3C7 10 602B 36,5x50,5x7 A SL RD MVQ <b>P77541-01 K</b> → OK201 11 312 83x100x9 A SL LD MVQ <b>P77584-01 N</b> ← OK013 10 602 34x48x7 A SL RD NBR
2,0 D4EA	83-110 kW (112-150 PS)	CARENS CRDi CERATO CRDi MAGENTIS CRDi SPORTAGE CRDi	07/02→	<b>S37987-00</b> ⑫ ⑬   <b>D37987-00</b> ⑫ 	<b>H01070-00</b> 84 Ø 1,1 mm MLS <b>H11070-10</b> 84 Ø 1,2 mm 2 MLS <b>H21070-20</b> 84 Ø 1,3 mm 3 MLS 	<b>V37987-00</b> 22441-27400 +22443-27001 (4x) 	<b>N93039-01</b> 22224-27900 (16x)	<b>X89751-01</b> 		<b>X82274-01</b> 	<b>70-31414-10</b> 	<b>P77544-01 K</b> ← 21335-27000 32x45x6 A SL RD NBR <b>P77530-01 K</b> → 21443-2A200 91x111x9 A SL LD MVQ <b>P77613-01 N</b> 22144-27000 36x50x8 A SL RD NBR	
2,0 D4EA-F	103 kW (140 PS)	CEE'D CRDi CEE'D SW CRDi PRO CEE'D CRDi	09/07-12/12	<b>S38817-00</b> ⑫ ⑬ 20910-27G10  <b>S38817-01</b> ⑫ ⑬   <b>D38817-00</b> ⑫ 20920-27G10 <b>D38817-01</b> ⑫ 	<b>H40767-00</b> ✕ 22311-27401 84,5 Ø 1,1 mm MLS <b>H40767-10</b> 22311-27411 84,5 Ø 1,2 mm 2 MLS <b>H40767-20</b> ✕ 22311-27421 84,5 Ø 1,3 mm 3 MLS 	<b>T38816-00</b> 22321-27400 (10x) 	<b>V37987-00</b> 22441-27400 +22443-27001 (4x) 	<b>N93039-01</b> 22224-27900 (16x)	<b>X71064-00</b> 28411-27400 		<b>70-31414-10</b> 	<b>P77544-01 K</b> ← 21335-27000 32x45x6 A SL RD NBR <b>P77530-01 K</b> → 21443-2A200 91x111x9 A SL LD MVQ <b>P77613-01 N</b> 22144-27000 36x50x8 A SL RD NBR	

KIA												
2,0 D4HA <b>[NEW]</b>	100-135 kW (136-184 PS)	SORENTO CRDi SPORTAGE CRDi	07/10→	<b>S90183-00</b> 12 13 38 20910-2FU00 	<b>H84844-00</b> 22311-2F610 85 Ø 1,2 mm MLS <b>H84844-10</b> ✕ 22311-2F600 85 Ø 1,3 mm MLS <b>H84844-20</b> ✕ 22311-2F620 85 Ø 1,4 mm MLS 	<b>T38812-00</b> 22321-2F000 (10x) 	<b>V38814-00</b> 22441-2F000 +22443-2F000 +22133-2F000 (4x) 	<b>N93211-00</b> 22224-2F001 (16x) <b>P76974-00</b> 22224-2F001 16x 	<b>X71061-01</b> 28312-2F000 	<b>X71062-01</b> 28521-2F600 	<b>70-31414-10</b> 	<b>P77879-01</b> K ← 21355-2F000 60x72x8 A SL RD FPM
2,0 FE (16V)	94-98 kW (128-133 PS)	CLARUS RETONA SPORTAGE	04/94→	<b>S40105-00</b> 12 13 0K01C 10 270A 	<b>H40105-00</b> 0K013 10 271 	<b>X83212-01</b> 0K955 10 235 B 	<b>N92012-01</b> 0KL02 10 155 (16x) 	<b>X89717-01</b> 0K9A4 13 111 	<b>X82239-01</b> 0FE3N 13 460 	<b>70-31414-10</b> 	<b>P77584-01</b> K ← 0K013 10 602 34x48x7 A SL RD NBR <b>P77529-01</b> K → 90x110x9 A SL LD NBR <b>P77584-01</b> N ← 2x 0K013 10 602 34x48x7 A SL RD NBR	
2,0 G4CP	102 kW (139 PS)	JOICE	02/00→	<b>S40655-00</b> 12 13 20910-33F00 	<b>H40655-00</b> 22311-33110 86,5 Ø 1,4 mm 	<b>V38514-00</b> 22441-33021 (1x) +22442-42001 (1x) +22443-33020 (4x) 	<b>N93000-04</b> 22224-38000 (8x) +22224-38010 (8x) 	<b>X59741-01</b> 28411-33012 	<b>X82224-01</b> 28521-33020 	<b>70-31414-10</b> 	<b>P77495-01</b> K ← 21421-33114 44x60x7 A SL RD MVQ <b>P77664-01</b> K → 21443-33005 80x96x9 A SL LD FPM <b>P77585-01</b> N 2x 22144-3B001 35x50x8 A SL RD NBR	
2,0 G4GC	102-105 kW (139-143 PS)	CARENS CERATO SPORTAGE	04/04→	<b>S38275-00</b> 12 13 20910-23A00A 	<b>H40368-00</b> 22311-23700 	<b>V38016-00</b> 22441-23800 +22442-23500 (3x) 	<b>N93053-00</b> 22224-23500 (16x) 	<b>X89956-01</b> 28411-23600 	<b>X82371-01</b> 28521-23005 	<b>70-31414-10</b> 	<b>P77663-01</b> K ← 21421-23020 37,6x49x7,5 A SL RD FPM <b>P77664-01</b> K → 21443-33005 80x96x9 A SL LD FPM <b>P77585-01</b> N 22144-3B001 35x50x8 A SL RD NBR	
2,0 G4GC	105 kW (143 PS)	CEE'D PRO CEE'D	12/06-12/12	<b>S38274-00</b> 13 KSS61 10 270 	<b>H40368-00</b> 22311-23700 	<b>V38016-00</b> 22441-23800 +22442-23500 (3x) 	<b>N93053-00</b> 22224-23500 (16x) 	<b>X89956-01</b> 28411-23600 	<b>X82371-01</b> 28521-23005 	<b>70-31414-10</b> 	<b>P77663-01</b> K ← 21421-23020 37,6x49x7,5 A SL RD FPM <b>P77664-01</b> K → 21443-33005 80x96x9 A SL LD FPM <b>P77585-01</b> N 22144-3B001 35x50x8 A SL RD NBR	

KIA														
Ltr.														
2,0 G4JP	100 kW (136 PS)	MAGENTIS	05/01→	S40064-00 <sup>12</sup> <sup>13</sup> 20910-38B01 D40064-00 <sup>12</sup>	H40064-00 22311-38100 86 Ø MLS 	T40363-00 22320-38000 (10x) 	V37989-00 22441-38003 +22442-23500 +22443-38010 (4x) 	N93000-01 22224-38010 (16x)	X89756-01 28411-38000 	X82224-01 28521-33020 	70-31414-10 	P77495-01 K ← 21421-33114 44x60x7 A SL RD MVQ P77522-01 K → 21443-38010 85x103x8 A SL LD MVQ P77585-01 N 22144-38001 35x50x8 A SL RD NBR		
2,0 RF	61 kW (83 PS)	RETONA TD SPORTAGE TD	10/97→	S40029-00 <sup>12</sup> <sup>13</sup> D40029-00 <sup>12</sup>	H40029-00 0K054 10 271 87,6 Ø MLS 	X83198-01 0K770 10 235B 	N93001-00	X89630-01 0K054 13 111 	X82153-01 0K054 13 460B 	X54866-01 	P77584-01 K ← 0K013 10 602 34x48x7 A SL RD NBR P77529-01 K → 90x110x9 A SL LD NBR P77584-01 N ← 0K013 10 602 34x48x7 A SL RD NBR			
2,2 D4HB	110-145 kW (150-197 PS)	CARNIVAL CRDi SORENTO CRDi	11/09→	S38813-00 <sup>12</sup> <sup>13</sup> <sup>38</sup> 20910-2FB00  S38813-01 <sup>12</sup> <sup>13</sup> <sup>38</sup> 22311-2F100  D38813-00 <sup>12</sup> 20920-2FB00 D38813-01 <sup>12</sup> 	H40766-00 <sup>X</sup> 22311-2F110 86,5 Ø 1,2 mm MLS H40766-10 22311-2F100 86,5 Ø 1,3 mm 1 <sup>M</sup> MLS H40766-20 <sup>X</sup> 22311-2F120 86,5 Ø 1,4 mm 2 <sup>M</sup> MLS 	T38812-00 22321-2F000 (10x) 	V38814-00 22441-2F000 +22443-2F000 +22133-2F000 (4x) 	N93211-00 22224-2F001 (16x) P76974-00 22224-2F001	X71061-01 28312-2F000 16x 	X71062-01 28521-2F600 	70-31414-10 	P77879-01 K ← 21355-2F000 60x72x8 A SL RD FPM		
2,2 R2	48 kW (65 PS)	BESTA D	02/96-12/03	S80923-00 <sup>12</sup> <sup>13</sup> D80923-00 <sup>12</sup>	H80923-10 87,5 Ø MLS 	X83198-01 0K770 10 235B 	N93001-00	X89630-01 0K054 13 111 	X82153-01 0K054 13 460B 	X54866-01 	P77584-01 K ← 0K013 10 602 34x48x7 A SL RD NBR P77529-01 K → 90x110x9 A SL LD NBR P77577-01 N ← KKY01 12 602 30x44x7 A SL RD NBR			
2,4 G4KE	128 kW (174 PS)	SORENTO	11/09→	S38819-00 <sup>12</sup> <sup>13</sup> 20910-2GJ01  D38819-00 <sup>12</sup> 20920-2GB01	H40768-00 22311-25212 89,5 Ø MLS 	T38818-00 22320-25000 (8x) +22321-25001 (2x) 	X71066-01 22441-2G100 	N93212-00 22224-2G000 (16x) P76975-00 22224-2G000	X71067-01 V 28313-2G000 16x  X71068-01 H 28314-2G000 2x 	X71069-01 28521-25020 	70-31414-10 	P77155-01 K ← 21421-25002 42x55x7 A SL RD FPM P77522-01 K → 21443-38010 85x103x8 A SL LD MVQ		

KIA														
Ltr.														
2,4 4G64	102 kW (139 PS)	SORENTO	08/02→	<b>S40083-00</b> 12 13 K0AH2 10 270 <b>D40083-00</b> 12	<b>H40083-00</b> 22411-38400 87,7 Ø 0,42 mm MLS 	<b>V37989-00</b> 22441-38003 +22442-23500 +22443-38010 (4x) 	<b>N93000-01</b> 22224-38010 (16x)	<b>X89756-01</b> 28411-38000 	<b>X82224-01</b> 28521-33020 	<b>70-31414-10</b> 	<b>P77495-01</b> K ← 21421-33114 44x60x7 A SL RD MVQ <b>P77522-01</b> K → 21443-38010 85x103x8 A SL LD MVQ <b>P77585-01</b> N 22144-3B001 35x50x8 A SL RD NBR	2x		
2,5 D4CB	103 kW (140 PS)	SORENTO CRDi	08/02→	<b>S83300-00</b> 12 13 K0AH4 10 270A <b>D83300-00</b> 12 	<b>H01072-00</b> 22311-4A010 92,35 Ø 0,78 mm MLS <b>H11072-10</b> 22311-4A000 92,35 Ø 0,84 mm 1 MLS <b>H21072-20</b> 22311-4A020 92,35 Ø 1 mm 2 MLS 	<b>T40361-00</b> 22321-4A000 (18x) 	<b>X83300-01</b> 22441-4A000 	<b>N93045-00</b> 22224-4A000 (16x)	<b>X89758-01</b> 28355-4A001 	<b>X82280-01</b> 28513-4A001 	<b>70-31414-10</b> 	<b>P77548-01</b> K ← 48x62x8 A SL RD FPM <b>P77547-01</b> K → 21443-4A000 91x114x9 A SL LD FPM		
2,5 KRV6	110-121 kW (150-165 PS)	CARNIVAL V6	08/99→	<b>S37217-00</b> 12 14 OK558 10 270B 	<b>H80102-00</b> 2x 22311-3Y200 82,5 Ø 	<b>T40360-00</b> 2x OK9BV 10 135 (8x) 	<b>X83325-01</b> R 2x OK9BV 10 2F5A  <b>X83374-01</b> L OK556 10 2F5 	<b>N95980-00</b> OK9BV 12 123 (24x)	<b>X85000-01</b> 2x OK9BV 13 111B 	<b>X52551-01</b> 2x OK55W 13 460 	<b>70-31414-10</b> 	<b>P77461-01</b> K ← 32x45x6,8 A RD <b>P77462-01</b> K → <b>P76054-11</b> N V 2x 30x40x7 A SL RD FPM <b>P77697-01</b> N H 4x OK9BV 10 604 30x40x7 A SL LD FPM		
2,7 G6BA <b>[NEW]</b>	129 kW (175 PS)	SPORTAGE V6	09/04→	<b>S84795-00</b> 12 13 K0AD4 10 270 	<b>H84795-00</b> L 22311-37310 88,5 Ø MLS  <b>H84796-00</b> R 22311-37320 88,5 Ø MLS 	<b>V90071-00</b> 2x 22441-37110 +22443-23001 (3x) 	<b>N93053-01</b> 2x 22224-23500 (12x)	<b>X90094-01</b> 2x 28411-37200 	<b>X90095-01</b> 2x 28521-37104 	<b>70-31414-10</b> 	<b>P93218-01</b> K ← 21421-35011 37x50x6 A SL RD FPM <b>P77530-01</b> K → 21443-2A200 91x111x9 A SL LD MVQ <b>P77598-01</b> N V 2x 22144-39001 30x42x8 SL RD MVQ <b>P77380-01</b> N H 22144-37101 30x42x8 A SL LD ACM			
2,7 J2	59-61 kW (80-83 PS)	BONGO D K2700 D PREGIO D	03/97→	<b>S40315-00</b> 12 13 OK65A 10 270D <b>D40315-00</b> 12	<b>H40315-00</b> OK65A 10 271B MLS 	<b>T38752-00</b> OVS01 10 137 A (7x) +OK413 10 136 A (11x) 	<b>X83330-01</b> OK65A 10 236C ACM 	<b>N93055-00</b> OK6A1 10 155 (8x) <b>P76828-00</b> OK6A1 10 155	<b>X89804-01</b> 4x OK72C 13 111A 	<b>X82315-01</b> OK65A 13 461B 	<b>70-31414-10</b> 	<b>P77545-01</b> K ← OVS01 10 602 53x70x11 A SL RD <b>P77574-01</b> K → 21443-4X000 90x110x9 A SL LD FPM		

KIA																
Ltr.			<b>1</b>													
2,9 J3 <b>[NEW]</b>	93 kW (126 PS)	CARNIVAL TD	08/99-10/01	<b>S40060-00</b> <sup>12</sup> <sup>13</sup> K0AJ1 10 270 →06/01  <b>S40060-01</b> <sup>12</sup> <sup>13</sup> K0AJ1 10 270A 07/01→  <b>D40060-00</b> <sup>12</sup> →06/01 <b>D40060-01</b> <sup>12</sup> 07/01→	<b>H40060-00</b> 0K56A 10 271B 100,5 Ø MLS 					<b>X83296-01</b> 0K551 10 235 	<b>N93044-00</b> 0K551 10 155 (16x)	<b>X89752-01</b> 0K552 13 111 		<b>X82275-01</b> 0K551 13 461 	<b>70-31414-10</b> 	<b>P76467-01 K</b> ← 0K551-10602 50x68x9 A SL RD FPM <b>P77529-01 K</b> → 90x110x9 A SL LD NBR <b>P77616-01 N</b> ← 0JE26 12 601A 38x52x7 A SL RD FPM
2,9 J3 <b>[NEW]</b>	106 kW (144 PS)	CARNIVAL CRDi	10/01→	<b>S40060-01</b> <sup>12</sup> <sup>13</sup> K0AJ1 10 270A →12/05  <b>D40060-01</b> <sup>12</sup> →12/05	<b>H40060-00</b> 0K56A 10 271B 100,5 Ø MLS 					<b>X83296-01</b> 0K551 10 235 	<b>N93044-00</b> 0K551 10 155 (16x)	<b>X89752-01</b> 0K552 13 111 		<b>X82275-01</b> 0K551 13 461 	<b>70-31414-10</b> 	<b>P76467-01 K</b> ← 0K551-10602 50x68x9 A SL RD FPM <b>P77529-01 K</b> → 90x110x9 A SL LD NBR <b>P77616-01 N</b> ← 0JE26 12 601A 38x52x7 A SL RD FPM
3,3 G6DB <b>[NEW]</b>	182 kW (248 PS)	SORENTO V6	11/07→	<b>S84800-00</b> <sup>13</sup> KS665 10 270	<b>H84797-00 L</b> 22311-3CAA0 MLS  <b>H84798-00 R</b> 22311-3CAB0 MLS 	<b>T81778-00</b> 22321-3C100 (16x) 			<b>X90104-01 L</b> 22453-3C110  <b>X90105-01 R</b> 22441-3C110 	<b>N95990-00</b> 22224-3CAA0 (24x) <b>P93214-00</b> 22224-3CAA0 24x	<b>X90100-01 L</b> 28411-3C612  <b>X90101-01 R</b> 28411-3C622 		<b>X90102-01 L</b> 28521-3C702  <b>X90103-01 R</b> 28521-3C712 	<b>70-31414-10</b> 	<b>P93230-01 K</b> ← 21352-3C600 45x62x6 A SL RD <b>P77530-01 K</b> → 21443-2A200 91x111x9 A SL LD MVQ	
3,5 6G74	143 kW (194 PS)	SORENTO V6	08/02→	<b>S40084-00</b> <sup>12</sup> <sup>13</sup> K0AH3 10 270 <b>D40084-00</b> <sup>12</sup>	<b>H40084-00 R</b> 22311-39501 94 Ø 0,5 mm MLS  <b>H40085-00 L</b> 22311-39502 94 Ø 0,5 mm MLS 			<b>V37999-00</b> 2x 	<b>N93000-03</b> 22224-38000(12x) +22224-38010 (12x)	<b>X89777-01</b> 2x 28411-39800  <b>X89835-01</b> <sup>10</sup> 0 29215-39800  <b>X89836-01</b> <sup>10</sup> U 29215-39850 		<b>X82297-01</b> 2x 28521-39800 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← 37x50x6 A SL RD <b>P77530-01 K</b> → 21443-2A200 91x111x9 A SL LD MVQ <b>P77598-01 N</b> 4x 22144-39001 30x42x8 SL RD MVQ		