

SEAT														
1,2	CYVA CYVB	63-81 kW (86-110 PS)	LEON TSI	04/14→	<b>D38726-00</b> <sup>12</sup> <b>B38725-00</b> <sup>13 38</sup>	<b>H40705-00</b> 04E 103 383 T 72 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 	<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 04E 109 675 A <b>P76961-00</b> ES 04E 109 675	<b>X58997-01</b> 036 129 717 E 4x 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01</b> N → 04E 103 085 24x39x8 A SL LD PTFE	
1,4	CPWA CXSA CZCA	81-92 kW (110-125 PS)	LEON TGI LEON TSI	11/12→	<b>D38727-00</b> <sup>12</sup> <b>B38725-00</b> <sup>13 38</sup>	<b>H40706-00</b> 04E 103 383 BJ 75 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 	<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 04E 109 675 A <b>P76961-00</b> ES 04E 109 675	<b>X58997-01</b> 036 129 717 E 4x 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77881-01</b> K → 04E 103 170 A PTFE <b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01</b> N → 04E 103 085 24x39x8 A SL LD PTFE	
1,4	CZEA	110 kW (150 PS)	LEON TSI	05/14→	<b>D38727-01</b> <sup>12</sup> <b>B38725-00</b> <sup>13 38</sup>	<b>H40706-00</b> 04E 103 383 BJ 75 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 	<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 04E 109 675 A <b>P76961-00</b> ES 04E 109 675	<b>X58997-01</b> 036 129 717 E 4x 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77881-01</b> K → 04E 103 170 A PTFE <b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77840-01</b> N → 04E 103 085 C 28x39x7 A SL LD PTFE	
1,8	CJSB	132 kW (180 PS)			<b>D40708-01</b> <sup>12</sup> <b>B82501-00</b> <sup>13</sup>	<b>H40708-00</b> 06K 103 383 K 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X59914-01</b> 06K 129 717 A 16x 	<b>X59924-01</b> 06L 253 039 	<b>X90114-01</b> 06K 103 649  <b>70-31414-10</b> 	<b>P77842-01</b> K ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77846-01</b> K → 06K 103 171 A PTFE	
2,0	CJXA CJXE	195-206 kW (265-280 PS)	LEON	10/13→	<b>D40708-01</b> <sup>12</sup> <b>B82501-00</b> <sup>13</sup>	<b>H40708-00</b> 06K 103 383 K 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X59914-01</b> 06K 129 717 A 16x 	<b>X59924-01</b> 06L 253 039 	<b>X90114-01</b> 06K 103 649  <b>70-31414-10</b> 	<b>P77842-01</b> K ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77846-01</b> K → 06K 103 171 A PTFE	

Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.	Ref. GLASER GLASER-Nr. GLASER-No. Réf. GLASER Rif. GLASER Glaser No.
B38725-00 B82501-00 <b>NEW</b> D38726-00 D38727-00 D38727-01 D40708-01 H40705-00 H40706-00 H40708-00 N92990-00 N93196-00 P76662-00 P76960-00 P76961-00 P77840-01 P77841-01 P77842-01 P77843-01 P77844-01 P77846-01 P77881-01 T40706-00 T40708-00 X58997-01 X59914-01 X59924-01 X59925-01 X59930-01 X90114-01 <b>NEW</b> 70-31414-10 70-31414-10									