



AUDI

AUDI

 Code 

**0-9**

1B ..... 140

1T ..... 144

1Y ..... 110

1Z ..... 110

2B ..... 140

3A ..... 134

3B ..... 138

3D ..... 142

4B ..... 92

6A ..... 136

7A ..... 142

**A**

AAD ..... 112

AAE ..... 112

AAH ..... 160-170

AAN ..... 138

AAR ..... 140

AAS ..... 142

AAT ..... 144

AAZ ..... 94

ABB ..... 70

ABC ..... 148-156

ABH ..... 194

ABK ..... 114-116

ABM ..... 70-72

ABP ..... 144

ABT ..... 116

ABY ..... 138

ABZ ..... 194

ACE ..... 118

ACZ ..... 148-156

ADA ..... 72

ADE ..... 96

ADP ..... 72

ADR ..... 86

ADU ..... 138

AEB ..... 86

AEC ..... 194-196

AEH ..... 72

AEJ ..... 168-170

AEL ..... 144

AEM ..... 194

AEW ..... 190

AFB ..... 146

AFF ..... 96

AFN ..... 98

AFY ..... 86

AGA ..... 142-144

AGB ..... 156

AGE ..... 170

AGH ..... 194

AGN ..... 86

AGR ..... 100

AGU ..... 88

AHC ..... 194

AHF ..... 102

AHH ..... 102

AHL ..... 74

AHU ..... 104



AJG ..... 142-144

AJK ..... 156

AJL ..... 88

AJM ..... 104

AJP ..... 88

 Code 

AJQ ..... 88

AKC ..... 190

AKE ..... 146

AKF ..... 188

AKG ..... 194

AKH ..... 194

AKJ ..... 190

AKL ..... 72

AKN ..... 146

ALF ..... 142-144

ALG ..... 170

ALH ..... 106

ALT ..... 118

ALW ..... 142-144

ALZ ..... 74

AMB ..... 88-90

AMF ..... 68

AMK ..... 88

AML ..... 142-144

AMM ..... 142-144

AMU ..... 88

AMX ..... 170

ANA ..... 74

ANB ..... 90

ANK ..... 196

ANQ ..... 90

ANY ..... 64

ANZ ..... 86

APB ..... 156

APC ..... 142-144

APF ..... 74

APG ..... 90

APP ..... 88

APR ..... 170

APS ..... 142-144

APT ..... 90

APU ..... 90

APX ..... 88

APY ..... 88

APZ ..... 142-144

AQA ..... 88

AQD ..... 170

AQE ..... 88

AQF ..... 196-198

AQG ..... 190

AQH ..... 196-198

AQJ ..... 196

ARE ..... 156

ARG ..... 90

ARH ..... 88

ARJ ..... 144

ARK ..... 86

ARM ..... 74

ARN ..... 142-144

ARS ..... 196

ARU ..... 196-198

ARX ..... 88

ARY ..... 88

ARZ ..... 88

ASB ..... 174

ASE ..... 192



ASG ..... 196

ASJ ..... 156

ASM ..... 144

ASN ..... 174

ASV ..... 106

 Code 

ASZ ..... 104

ATC ..... 88

ATD ..... 104

ATJ ..... 104

ATL ..... 68

ATX ..... 170

AUA ..... 68

AUK ..... 184

AUL ..... 88

AUM ..... 88

AUQ ..... 88

AUW ..... 196-198

AUX ..... 196

AVB ..... 104

AVF ..... 104

AVG ..... 102

AVJ ..... 88

AVK ..... 174

AVP ..... 196-198

AVU ..... 74

AVV ..... 90

AWA ..... 118

AWL ..... 90

AWN ..... 196

AWP ..... 88

AWT ..... 88

AWX ..... 104

AXA ..... 118

AXR ..... 104

AXW ..... 118

AXX ..... 120

AYM ..... 146

AYS ..... 196

AZA ..... 156

AZB ..... 156

AZR ..... 156

AZV ..... 120

**B**

BAD ..... 76

BAG ..... 76

BAM ..... 88

BAR ..... 198

BAS ..... 198

BAT ..... 198

BAU ..... 146

BBG ..... 170

BBJ ..... 174

BBK ..... 198

BBY ..... 68

BCS ..... 196

BCY ..... 200

BCZ ..... 146

BDB ..... 184-186

BDG ..... 146

BDH ..... 146

BDV ..... 144

BDW ..... 144

BDX ..... 172

BEA ..... 88

BEL ..... 156



BES ..... 156

BEX ..... 88-90

BFB ..... 88-90

BFC ..... 146

BFL ..... 190

 Code 

BFM ..... 88

BFQ ..... 74

BFV ..... 88

BGB ..... 120

BGU ..... 76

BHC ..... 68

BHE ..... 184-186

BHF ..... 198

BHK ..... 188

BHT ..... 206

BHZ ..... 120

BJZ ..... 120

BKC ..... 108

BKD ..... 120

BKE ..... 104

BKH ..... 184

BKN ..... 174

BLB ..... 120

BLF ..... 76

BLP ..... 76

BLR ..... 122

BLS ..... 108

BLX ..... 122

BLY ..... 122

BMB ..... 118

BMC ..... 200

BMJ ..... 184-186

BMK ..... 174

BMM ..... 122

BMN ..... 122

BNA ..... 120

BNG ..... 174

BNS ..... 198

BPF ..... 184-186

BPG ..... 120

BPJ ..... 120

BPK ..... 184

BPP ..... 88

BPW ..... 122

BPY ..... 120

BRB ..... 104

BRC ..... 122

BRD ..... 120

BRE ..... 120

BRF ..... 120

BRV ..... 200

BRY ..... 78

BSB ..... 206

BSE ..... 76

BSF ..... 76

BSG ..... 158

BSM ..... 206

BTE ..... 206

BTR ..... 200

BUB ..... 184-186

BUG ..... 174

BUL ..... 120

BUN ..... 174

BUY ..... 122

BVA ..... 120

BVF ..... 120



BVG ..... 120

BVJ ..... 198

BVN ..... 200

BVP ..... 88

BVR ..... 88

 Code 

BVY ..... 122

BVZ ..... 122

BWA ..... 120

BWE ..... 120

BWT ..... 120

BXA ..... 206

BXE ..... 108

BYH ..... 198

BYK ..... 120

BYT ..... 90

BYU ..... 184

BZB ..... 92

BZC ..... 120

**C**

CABA ..... 92

CABB ..... 92

CABD ..... 92

CADA ..... 124

CAEA ..... 124

CAEB ..... 124

CAGA ..... 124

CAGB ..... 124

CAHA ..... 124

CAHB ..... 124

CAJA ..... 176

CAKA ..... 176

CALA ..... 186

CALB ..... 186

CAMA ..... 160

CAMB ..... 160

CANA ..... 160

CANB ..... 160

CANC ..... 160

CAND ..... 160

CAPA ..... 176

CASA ..... 178

CASB ..... 178

CATA ..... 178

CAUA ..... 198

CAVG ..... 68

CAWB ..... 124

CAXC ..... 68

CAYB ..... 78

CAYC ..... 78

CBAA ..... 124

CBAB ..... 124

CBBB ..... 124

CBFA ..... 124

CBZA ..... 64

CBZB ..... 64

CCAA ..... 176

CCBA ..... 176

CCDA ..... 172

CCEA ..... 172

CCFA ..... 202

CCFC ..... 202

CCGA ..... 208

CCMA ..... 178

CCSA ..... 74

CCTA ..... 124



CCUA ..... 92

CCWA ..... 178

CCWB ..... 178

CCZA ..... 124

CCZC ..... 124

 Code 

CDA ..... 92

CDHA ..... 92

CDHB ..... 92

CDLA ..... 120

CDLB ..... 120

CDLC ..... 120

CDLH ..... 120

CDMA ..... 120

CDNA ..... 124

CDNB ..... 124

CDNC ..... 124

CDRA ..... 198

CDSB ..... 204

CDTA ..... 180

CDTB ..... 180

CDUC ..... 180

CDUD ..... 180

CDYA ..... 178

CDYB ..... 178

CDYC ..... 126

CDZA ..... 124

CEPA ..... 146-148

CEPB ..... 148

CESA ..... 176

CETA ..... 124

CEUA ..... 192

CEUC ..... 192

CFFA ..... 124-126

CFFB ..... 124-126

CFGB ..... 126

CFGC ..... 126

CFGD ..... 126

CFHB ..... 126

CFHD ..... 126

CFKA ..... 124

CFSA ..... 204

CGKA ..... 160

CGKB ..... 160

CGLA ..... 126

CGLB ..... 126

CGLC ..... 128

CGLD ..... 128

CGLE ..... 128

CGQB ..... 182

CGTA ..... 192

CGWA ..... 176

CGWB ..... 176

CGWC ..... 176

CGWD ..... 176

CGXB ..... 176

CGXC ..... 176

CHJA ..... 124

CHMA ..... 176

CHVA ..... 172

CJBA ..... 172

CJCA ..... 128

CJCB ..... 128

CJCD ..... 128

CJEB ..... 92

CJGA ..... 180

CJGC ..... 180



CJGD ..... 180

CJMA ..... 180

CJSA ..... 92

CJSB ..... 92

CJTB ..... 82

 Code 

CJTC ..... 182

CJWB ..... 182

CJWC ..... 182

CJWE ..... 176

CJZA ..... 64

CJZB ..... 64

CKVB ..... 180

CKVC ..... 180

CLAA ..... 180

CLAB ..... 180

CLHA ..... 80

CLJA ..... 126

CLLB ..... 126

CLZB ..... 180

CMBA ..... 68

CMDB ..... 176

CMEA ..... 124

CMFA ..... 128

CMFB ..... 128

CMGA ..... 126

CMGB ..... 128

CMHA ..... 180

CMSA ..... 68

CMUA ..... 176

CMXA ..... 74

CN ..... 130

CNAA ..... 182

CNCB ..... 130

CNCD ..... 130

CNDA ..... 198

CNRB ..... 180

CNVA ..... 68

CNYA ..... 172

CPAA ..... 148

CPMA ..... 124

CPNA ..... 180

CPNB ..... 180

CPSA ..... 124

CPTA ..... 68

CR ..... 80

CRBC ..... 130

CRCA ..... 180

CRFA ..... 132

CRFC ..... 132

CRKB ..... 80

CRLB ..... 130

CTHG ..... 68

CTJA ..... 68

CTTA ..... 184

CTUA ..... 184

CTUB ..... 176

CTUC ..... 176

CTUD ..... 176

CTVA ..... 176

CTWA ..... 176

CTWB ..... 176

CTXA ..... 176

CUPA ..... 132

CY ..... 80-82

**D**



DD ..... 92

DE ..... 132

DR ..... 92

DS ..... 92

DT ..... 82

 Code 

DTA ..... 82

DZ ..... 92

**E**

EP ..... 66

**F**

FS ..... 84

FY ..... 66

**G**

GV ..... 136

**H**

HB ..... 64

HC ..... 64

HD ..... 64

HH ..... 66

HP ..... 134

HX ..... 138

HY ..... 138

**J**

JK ..... 80-82

JL ..... 134

JN ..... 94

JS ..... 134

JT ..... 138

JU ..... 82

JV ..... 92

JW ..... 92

JY ..... 136

**K**

KE ..... 136

KF ..... 138

KG ..... 136

KK ..... 140

KL ..... 136, 140

KP ..... 134

KU ..... 138

KV ..... 138

KX ..... 138

KZ ..... 138

**M**

MB ..... 140

MC ..... 140

MU ..... 92

**N**

NC ..... 134

NE ..... 92

NF ..... 142

NG ..... 140-142

NP ..... 92

**P**

PH ..... 94

PM ..... 94

PP ..... 82

PS ..... 134



PT ..... 188

PV ..... 94

PX ..... 138

AUDI

AUDI

 Code 

**R**

RA ..... 82

RN ..... 82

RS ..... 94

RT ..... 134

RU ..... 92

**S**



SA ..... 82

SB ..... 82

SD ..... 94

SF ..... 92

SH ..... 92

 Code 

SK ..... 134

SL ..... 134

**W**

WA ..... 134

WB ..... 136

WC ..... 138

WE ..... 136, 140



WF ..... 134

WH ..... 108

WJ ..... 136

WN ..... 108

WR ..... 136

 Code 

WS ..... 140

WT ..... 86

WV ..... 84

WZ ..... 84

**X**

XX ..... 84



**Y**

YG ..... 84

YH ..... 84

YJ ..... 70

YK ..... 84

 Code 

YN ..... 84

YP ..... 84

YS ..... 84

YT ..... 84

YV ..... 84

YY ..... 84

YZ ..... 84

**Z**

ZA ..... 66

ZF ..... 66

AUDI

 Code 

 Code 

 Code 

 Code 

AUDI							
1,1	HB HC HD	37-44 kW (50-60 PS)	50	→8661 590 000 08/74→	<b>S30579-00</b> ⑫ ⑬ 052198001 <b>D30579-00</b> ⑫ 052 198 012 <b>B30579-00</b> ⑬ 052 198 011 A	<b>H03693-00</b> 052 103 383 AA 71 Ø 	<b>T04125-00</b> 049 103 384 B (10x) 
1,2	HB HC HD	37-44 kW (50-60 PS)	50	→8661 590 001→ 08/74→	<b>S30580-00</b> ⑫ ⑬ 052198001L <b>D30580-00</b> ⑫ 052 198 012 AF <b>B30579-00</b> ⑬ 052 198 011 A	<b>H04132-00</b> 052 103 383 AB 71 Ø 	<b>T04125-00</b> 049 103 384 B (10x) 
1,2	ANY	45 kW (61 PS)	A2 TDI	03/01-08/05	<b>D36624-00</b> ⑫  <b>B32959-00</b> ⑬ ⑳ 	<b>H09197-00</b> 045 103 383 C 1,45 mm 1 MLS <b>H19197-10</b> 045 103 383 D 1,53 mm 2 MLS <b>H29197-20</b> 045 103 383 E 77,5 Ø 1,61 mm 3 MLS 	
1,2	CBZA CBZB	63-77 kW (86-105 PS)	A1 TFSI A3 TSI	03/10→	<b>D40579-00</b>  <b>B38301-00</b> ⑬ ㉓ 	<b>H40579-00</b> 03F 103 383 E 72 Ø MLS 	<b>T40579-00</b> WHT 004 790 (10x) 
1,2	CJZA CJZB	63-77 kW (86-105 PS)	A3 TFSI	02/13→	<b>D38726-00</b> ⑫ <b>B38725-00</b> ⑬ ㉓ 	<b>H40705-00</b> 04E 103 383 T 72 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 














㉓ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала  
 ㉓ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач

































<b>X03744-01</b> ✕ Kork  <b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x 	<b>X03745-01</b> 030 129 717 D 	<b>X03743-01</b> 2x 030 253 039 A  <b>X51310-01</b> ㉓ 861 253 115 A 	<b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>X03744-01</b> ✕ Kork  <b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x 	<b>X03742-01</b> 036 129 717 C 	<b>X03743-01</b> 2x 030 253 039 A  <b>X51310-01</b> ㉓ 861 253 115 A 	<b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>X83111-01</b> 045 103 483 C NBR 	<b>N92001-00</b> 027 109 675 (6x) <b>P76532-00</b> 027 109 675 6x 	<b>X86491-01</b> 045 129 717 	<b>X52968-01</b> 045 253 039 	<b>70-31414-10</b> 	<b>P76096-11</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X59883-01</b> ✕ 03F 103 483 A Metall  <b>70-31414-10</b> 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x 	<b>X59475-01</b> 1x 03F 129 717 A  <b>X59480-01</b> 4x 03F 129 717 	<b>X82520-01</b> 03F 253 041 P 	<b>70-31414-10</b> 	<b>P77181-01</b> K ← 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77479-01</b> K → 036 103 171 B PTFE
<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 8x 04E 109 675 A <b>P76961-00</b> ES 8x 04E 109 675	<b>X58997-01</b> 4x 036 129 717 E 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01</b> N → 04E 103 085 24x39x8 A SL LD PTFE

AS lado de escape / Auslaßseite / exhaust side / côté échappement / lato scarico / сторона выпуска  
 ES lado de admisión / Einlaßseite / intake side / côté admission / lato aspirazione / сторона впуска



AUDI				  			
1,3 EP	44 kW (60 PS)	80	→81 D 250 000	09/78-07/86	<b>D30584-00</b> ⑫ 056 198 012 D <b>B30584-00</b> ⑬ 037 198 011 C	<b>H04128-00</b> 049 103 383 M 78,5 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 
1,3 EP	44 kW (60 PS)	80	→81 E 000 001→	09/78-07/86	<b>S31194-00</b> ⑫ ⑬ <b>D31194-00</b> ⑫ 056 198 012 G <b>B30584-00</b> ⑬ 037 198 011 C	<b>H07850-00</b> 056 103 383 L 79 Ø 1,8 mm 	<b>T04125-00</b> 049 103 384 B (10x) 
1,3 FY HH	40-44 kW (55-60 PS)	50 80		08/77-07/81	<b>S30583-00</b> ⑫ ⑬ <b>D30583-00</b> ⑫ 052 198 012 AB <b>B30579-00</b> ⑬ 052 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 
1,3 ZA ZF	40-44 kW (55-60 PS)	80	→82 42 202 719	05/72-07/78	<b>D30584-00</b> ⑫ 056 198 012 D	<b>H04128-00</b> 049 103 383 M 78,5 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 
1,3 ZA ZF	40-44 kW (55-60 PS)	80	→85 52 000 099→	05/72-07/78	<b>S30584-00</b> ⑫ ⑬ 056198001A <b>D30584-00</b> ⑫ 056 198 012 D <b>B30584-00</b> ⑬ 037 198 011 C	<b>H04128-00</b> 049 103 383 M 78,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 



     					
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x <b>X07854-01</b> ⚠ 841 253 115 B 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x <b>X07854-01</b> ⚠ 841 253 115 B 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X03744-01</b> ✗ Kork  <b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X03742-01</b> 036 129 717 C  <b>X03745-01</b> 030 129 717 D 	<b>X03743-01</b> 030 253 039 A 2x <b>X51310-01</b> ⚠ 861 253 115 A 	<b>X03370-01</b> 032 103 609 B 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V31265-00</b> ✗ 056 198 025 6,5 mm 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x <b>X07854-01</b> ⚠ 841 253 115 B 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V31265-00</b> ✗ 056 198 025 6,5 mm 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x <b>X07854-01</b> ⚠ 841 253 115 B 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI						
Ltr.						
1,4 AMF ATL BHC	55-66 kW (75-90 PS) A2 TDI	02/00-08/05	 <b>D36624-00</b> ⑫  <b>B32959-00</b> ⑬ ⑳	<b>H09198-00</b> 045 103 383 F 1,45 mm MLS <b>H19198-10</b> 045 103 383 G 1,53 mm MLS <b>H29198-20</b> 045 103 383 H 80,5 Ø 1,61 mm MLS	<b>T09198-00</b> 038 103 384 (8x) 	  
1,4 AUA BBY	55 kW (75 PS) A2	02/00-08/05	<b>D36621-00</b> ⑫ <b>B32957-00</b> ⑬ ⑳ 036 198 011	<b>H80140-00</b> 036 103 383 AL 77,5 Ø MLS	<b>T50943-00</b> 036 103 384 B (10x) 	  
1,4 CAVG CAXC CMSA CNVA CTHG CTJA	90-136 kW (122-185 PS) A1 TFSI A3 TFSI	09/07→	<b>S37091-00</b> ⑫ ⑬ ⑳	<b>H80752-00</b> 03C 103 383 R 77,5 Ø MLS	<b>T80752-00</b> WHT 000 912 (10x) 	  
1,4 CMBA	90 kW (122 PS) A3 TFSI	04/12→	<b>D38727-00</b> ⑫ <b>B38725-00</b> ⑬ ⑳	<b>H40706-00</b> 04E 103 383 BJ 75 Ø MLS	<b>T40706-00</b> WHT 004 926 (10x) 	  
1,4 CPTA	103 kW (140 PS) A1 TFSI A3 TFSI	04/12→	<b>D38727-01</b> ⑫ <b>B38725-00</b> ⑬ ⑳	<b>H40706-00</b> 04E 103 383 BJ 75 Ø MLS	<b>T40706-00</b> WHT 004 926 (10x) 	  

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

⑬ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



<b>X83111-01</b> 045 103 483 C NBR 	<b>N92001-00</b> 027 109 675 (6x) <b>P76532-00</b> 027 109 675 6x	<b>X86491-01</b> 045 129 717 	<b>X52968-01</b> 045 253 039  <b>X52970-01</b> X 1H0 253 115 A 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X58997-01</b> 036 129 717 E 4x 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X87493-01</b> 03C 129 717 C  <b>X89175-01</b> ⑩ 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE
<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 8x 04E 109 675 A <b>P76961-00</b> ES 8x 04E 109 675	<b>X58997-01</b> 036 129 717 E 4x 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01 N</b> → 04E 103 085 24x39x8 A SL LD PTFE
<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 8x 04E 109 675 A <b>P76961-00</b> ES 8x 04E 109 675	<b>X58997-01</b> 036 129 717 E 4x 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77840-01 N</b> → 04E 103 085 C 28x39x7 A SL LD PTFE

AS lado de escape / Auslaßseite / exhaust side / côté échappement / lato scarico / сторона выпуска

ES lado de admisión / Einlaßseite / intake side / côté admission / lato aspirazione / сторона впуска



AUDI

AUDI			
1.5 YJ	55 kW (75 PS) 80	05/72-08/75	
1.6 ABB	75 kW (102 PS) 80 →8C P 220 000	08/90-10/91	
1.6 ABB	75 kW (102 PS) 80 →8C P 220 001→	08/90-10/91	
1.6 ABM	52 kW (71 PS) 80 →8C S 170 000	09/91-12/94	

Part No.	Material	Dimensions	Image
<b>D30584-00</b> ⑫	056 198 012 D		
<b>H04128-00</b>	049 103 383 M	78,5 Ø 1,75 mm	
<b>T04132-00</b>	049 103 385 (10x)		
<b>S31443-00</b> ⑫ ⑬	037 198 011 C		
<b>D31443-00</b> ⑫			
<b>B30584-00</b> ⑬			
<b>H04843-00</b>	026 103 383 P	82 Ø 1,75 mm	
<b>T04125-00</b>	049 103 384 B (10x)		
<b>B31443-00</b> ⑫			
<b>B32952-00</b> ⑬			
<b>H04843-00</b>	026 103 383 P	82 Ø 1,75 mm	
<b>T04125-00</b>	049 103 384 B (10x)		

Part No.	Material	Dimensions	Image
<b>V30584-00</b>	026 198 025 A	8,5 mm Kork	
<b>V31265-00</b> ✗	056 198 025	6,5 mm	
<b>N90300-00</b>	026 109 675 (8x)	8x	
<b>P76531-00</b>	026 109 675		
<b>X04875-01</b>	026 129 717 D		
<b>X03747-01</b>	026 129 589 A	4x	
<b>X07854-01</b>	841 253 115 B		
<b>E30584-00</b>	044 103 609 D	+N 905 927 02 (20x)	
<b>P76087-01</b> K ←	068 103 085 E	32x47x10	
	A SL WD FPM		
<b>P76355-11</b> K →	068 103 051 P	85x105x9	
	A SL LD FPM		
<b>P76087-01</b> N	068 103 085 E	32x47x10	
	A SL WD FPM		
<b>V30584-00</b>	026 198 025 A	8,5 mm Kork	
<b>V53509-00</b> ✗	026 198 025 C	6,5 mm Gummi	
<b>N90300-00</b>	026 109 675 (8x)	8x	
<b>P76531-00</b>	026 109 675		
<b>X04875-01</b>	026 129 717 D		
<b>X03747-01</b>	026 129 589 A	4x	
<b>X51157-01</b>	433 253 115		
<b>X51169-01</b>	431 253 115 A		
<b>E30584-00</b>	044 103 609 D	+N 905 927 02 (20x)	
<b>P76087-01</b> K ←	068 103 085 E	32x47x10	
	A SL WD FPM		
<b>P76355-11</b> K →	068 103 051 P	85x105x9	
	A SL LD FPM		
<b>P76087-01</b> N	068 103 085 E	32x47x10	
	A SL WD FPM		
<b>V30584-00</b>	026 198 025 A	8,5 mm Kork	
<b>V53509-00</b> ✗	026 198 025 C	6,5 mm Gummi	
<b>N90300-00</b>	026 109 675 (8x)	8x	
<b>P76531-00</b>	026 109 675		
<b>X04875-01</b>	026 129 717 D		
<b>X03747-01</b>	026 129 589 A	4x	
<b>X51157-01</b>	433 253 115		
<b>X51169-01</b>	431 253 115 A		
<b>X54624-01</b>	044 103 609 D	ACM	
<b>P76087-01</b> K ←	068 103 085 E	32x47x10	
	A SL WD FPM		
<b>P76355-11</b> K →	068 103 051 P	85x105x9	
	A SL LD FPM		
<b>P76087-01</b> N	068 103 085 E	32x47x10	
	A SL WD FPM		
<b>X53263-01</b>	051 103 483 A	ACM	
<b>N90300-00</b>	026 109 675 (8x)	8x	
<b>P76531-00</b>	026 109 675		
<b>X04875-01</b>	026 129 717 D		
<b>X03747-01</b>	026 129 589 A	4x	
<b>X51169-01</b>	431 253 115 A		
<b>X54624-01</b>	044 103 609 D	ACM	
<b>P76087-01</b> K ←	068 103 085 E	32x47x10	
	A SL WD FPM		
<b>P76355-11</b> K →	068 103 051 P	85x105x9	
	A SL LD FPM		
<b>P76087-01</b> N	068 103 085 E	32x47x10	
	A SL WD FPM		

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



AUDI

AUDI				
Ltr.				
1,6 ABM	52 kW (71 PS) 80	09/91-12/94	8C S 170 001 →	1
		<b>D36400-00</b> ⑫ <b>B32952-00</b> ⑬	<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 
1,6 ADA	74 kW (101 PS) 80	06/93-01/96	8C S 170 000	
		<b>B32952-00</b> ⑬	<b>H04843-00</b> 026 198 025 C 82 Ø 1,75 mm Gummi 	<b>T04125-00</b> 049 103 384 B (10x) 
1,6 ADA	74 kW (101 PS) 80	06/93-01/96	8C S 170 001 →	
		<b>B32952-00</b> ⑬	<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 
1,6 ADP	74 kW (100 PS) A4	11/94-09/01		
		<b>S32242-00</b> ⑫ ⑬ <b>D32242-00</b> ⑫ 050 198 012 B <b>B32242-00</b> ⑬ 050 198 011	<b>H50475-00</b> 050 103 383 82,5 Ø MLS 	<b>T50469-00</b> 050 103 384 (10x) 
1,6 AEH AKL	74 kW (101 PS) A3	09/96-05/03		
		<b>S32239-00</b> ⑫ ⑬ <b>D32239-00</b> ⑫ 06A 198 012 <b>B32239-00</b> ⑬ ⑳ 06A 198 011	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X53263-01</b> 051 103 483 A ACM  2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X86528-01</b> 048 129 717 D  <b>X07853-01</b> ⑩ 035 121 171 C 	<b>X03747-01</b> 026 129 589 A  <b>X51169-01</b> 431 253 115 A 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) → ADA 034 669 <b>N91190-00</b> 027 109 675 (8x) → ADA 034 670 → <b>P76531-00</b> 026 109 675 → ADA 034 669 <b>P76532-00</b> 027 109 675 → ADA 034 670 → 8x	<b>X55626-01</b> 048 129 717 A 	<b>X03747-01</b> 026 129 589 A  <b>X51169-01</b> 431 253 115 A 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) → ADA 034 669 <b>N91190-00</b> 027 109 675 (8x) → ADA 034 670 → <b>P76531-00</b> 026 109 675 → ADA 034 669 <b>P76532-00</b> 027 109 675 → ADA 034 670 → 8x	<b>X55626-01</b> 048 129 717 A 	<b>X03747-01</b> 026 129 589 A  <b>X51169-01</b> 431 253 115 A 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X53263-01</b> 051 103 483 A ACM  2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X57668-01</b> 037 129 717 C 	<b>X51641-01</b>  <b>X51156-01</b> 443 253 115 A 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X53263-01</b> 051 103 483 A ACM  2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X57666-01</b> 06A 133 398 F 	4x <b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI						
Ltr.						
1,6 AHL	74 kW (100 PS) A4	11/94-09/01	<b>D36630-00</b> <b>B32936-00</b>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS	<b>T50474-00</b> 06A 103 384 C (10x)	
1,6 ALZ	75 kW (102 PS) A4	07/00-06/08	<b>D36631-00</b> <b>B32936-00</b>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS	<b>T50474-00</b> 06A 103 384 C (10x)	
1,6 ANA ARM	74 kW (100 PS) A4	11/94-09/01	<b>D36630-00</b> <b>B32936-00</b>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS	<b>T50474-00</b> 06A 103 384 C (10x)	
1,6 APF	74 kW (101 PS) A3	09/96-05/03	<b>D36632-00</b> <b>B32936-00</b>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS	<b>T50474-00</b> 06A 103 384 C (10x)	
1,6 AVU BFQ CCSA CMXA	75 kW (102 PS) A3	08/00→	<b>D36633-00</b> <b>B32936-00</b>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS	<b>T50474-00</b> 06A 103 384 C (10x)	

Ⓢ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X57668-01</b> 037 129 717 C <b>X87424-01</b> 06B 129 717 A	<b>X03747-01</b> 026 129 589 A	4x <b>70-31414-10</b>	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83001-01</b> 06B 103 483 L NBR	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	<b>X87424-01</b> 06B 129 717 A	<b>X03747-01</b> 026 129 589 A	4x <b>70-31414-10</b>	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X57666-01</b> 06A 133 398 F	<b>X52965-01</b> 06A 253 039 L	4x <b>70-31414-10</b>	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83001-01</b> 06B 103 483 L NBR	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	<b>X57666-01</b> 06A 133 398 F	<b>X52965-01</b> 06A 253 039 L <b>X07867-01</b> 533 253 115 D	4x <b>70-31414-10</b>	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM





AUDI						
Ltr.						
1,6 BAD	81 kW (110 PS) A2 FSI	05/02-08/05	<b>D36705-00</b> ⑫ <b>B36705-00</b> ⑬ ⑳	<b>H80344-00</b> 036 103 383 AB 77 Ø MLS 	<b>T80344-00</b> 036 103 384 E (10x) 	
1,6 BAG BLP	85 kW (115 PS) A3 FSI	08/03→	<b>S36776-00</b> ⑫ ⑬ ⑳ <b>D36776-00</b> ⑫	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	
1,6 BGU BSE BSF	75 kW (102 PS) A3	05/03→	<b>D36633-00</b> ⑫ <b>B36706-00</b> ⑬ ⑳	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	
1,6 BLF	85 kW (115 PS) A3 FSI →8P 4 103 000	08/03→	<b>S36776-00</b> ⑫ ⑬ ⑳ <b>D36776-00</b> ⑫	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	
1,6 BLF	85 kW (115 PS) A3 FSI →8P 4 103 001→	08/03→	<b>S36776-00</b> ⑫ ⑬ ⑳ <b>D36776-00</b> ⑫	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

⑳ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X87493-01</b> 03C 129 717 C  <b>X87494-01</b> ⑩ 036 129 717 K 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K ←</b> 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77351-01 K →</b> 030 103 171 L PTFE <b>P77329-01 N ←</b> 036 103 085 A 27x42x8 A SL RD NBR <b>P77342-01 N →</b> 036 103 085 F 35x46x7 A SL RD FPM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X87493-01</b> 03C 129 717 C  <b>X89175-01</b> ⑩ 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D  <b>X52978-01</b>	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77350-01 K →</b> 030 103 171 K PTFE
<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	8x <b>X57666-01</b> 4x 06A 133 398 F  <b>X88303-01</b> ⑩ 4x 06A 133 227 B 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77352-01 K →</b> 06B 103 171 E <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X87493-01</b> 03C 129 717 C  <b>X89175-01</b> ⑩ 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D  <b>X52978-01</b>	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77350-01 K →</b> 030 103 171 K PTFE
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X87493-01</b> 03C 129 717 C  <b>X89175-01</b> ⑩ 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D  <b>X52978-01</b>	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77376-01 K →</b> 030 103 171 S PTFE

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI						
Ltr.			<b>1</b>			
1,6 BRY	74 kW (101 PS)				<b>H80447-00</b> 06A 103 383 AE MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 
1,6 CAYB CAYC	66-77 kW (90-105 PS)	A1 TDI	05/10→	<b>D38310-00</b> <sup>(12)</sup>  <b>B38300-00</b> <sup>(13) (35)</sup>	<b>H40582-00</b> 03L 103 383 J 80,5 Ø 1,55 mm 1	<b>T50034-00</b> WHT 002 131 (10x) 
				<b>H40582-10</b> 03L 103 383 K 80,5 Ø 1,63 mm 2		
				<b>H40582-20</b> 03L 103 383 L 80,5 Ø 1,71 mm 3		
1,6 CAYB CAYC	66-77 kW (90-105 PS)	A3 TDI	05/09→	<b>D38310-00</b> <sup>(12)</sup>  <b>B38300-00</b> <sup>(13) (35)</sup>	<b>H40582-00</b> 03L 103 383 J 80,5 Ø 1,55 mm 1	<b>T50034-00</b> WHT 002 131 (10x) 
				<b>H40582-10</b> 03L 103 383 K 80,5 Ø 1,63 mm 2		
				<b>H40582-20</b> 03L 103 383 L 80,5 Ø 1,71 mm 3		

<sup>(12)</sup> junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x	<b>X57666-01</b> 06A 133 398 F 4x  <b>X88303-01</b> <sup>(10)</sup> 06A 133 227 B 4x 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59477-01</b> 03L 129 717 J 4x  <b>X59479-01</b> 03L 129 717 H 4x 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <sup>(1)</sup> →06/12 <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V59484-01</b> 03L 103 483 H +03L 103 070 A (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59477-01</b> 03L 129 717 J 4x  <b>X59479-01</b> 03L 129 717 H 4x 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM <sup>(1)</sup> →09/09 <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM <sup>(1)</sup> 10/09→
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x) 					
<b>X59484-01</b> 03L 103 483 H 					
<b>X59500-01</b> 03L 103 483 C 					

<sup>(35)</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



AUDI						
Ltr.						
1,6 CLHA CRKB <b>[NEW]</b>	77-81 kW (105-110 PS) A3 TDI	10/12→		<b>D38750-00</b> (12) 	<b>H40700-00</b> 04L 103 383 C 80,5 Ø 1,55 mm 1 MLS <b>H40700-10</b> 04L 103 383 D 80,5 Ø 1,63 mm 2 MLS <b>H40700-20</b> 04L 103 383 E 80,5 Ø 1,71 mm 3 	<b>T40709-00</b> WHT 005 673 (10x) 
1,6 CR	40 kW (54 PS) 80 D	08/80-08/86		<b>S30435-00</b> (12) (13) 068 198 001  <b>D30435-00</b> (12) 068 198 012 L  <b>B30584-00</b> (13) 037 198 011 C	<b>H02633-00</b> 068 103 383 ES 1,5 mm 1 → CR 176 338 <b>H12633-10</b> 068 103 383 ET 1,6 mm 2 → CR 176 338 <b>H22633-20</b> 068 103 383 FA 78 Ø 1,7 mm 3 → CR 176 338  <b>H02673-00</b> 068 103 383 FE 1,4 mm 1 → CR 176 339→ <b>H12673-10</b> 068 103 383 FF 1,5 mm 2 → CR 176 339→ <b>H22673-20</b> 068 103 383 FG 78 Ø 1,6 mm 3 → CR 176 339→ 	<b>T02673-00</b> 068 103 384 A (10x) 
1,6 CY JK	40-51 kW (54-70 PS) 80 D 80 TD 90 TD	08/80-08/91	→81 F 220 000 →81 F 220 000 →81 F 220 000	<b>S30435-00</b> (12) (13) 068 198 001  <b>D30435-00</b> (12) 068 198 012 L  <b>B30584-00</b> (13) 037 198 011 C	<b>H02673-00</b> 068 103 383 FE 1,4 mm 1 <b>H12673-10</b> 068 103 383 FF 1,5 mm 2 <b>H22673-20</b> 068 103 383 FG 78 Ø 1,6 mm 3 	<b>T02673-00</b> 068 103 384 A (10x) 



<b>V59933-00</b> 03L 103 483 S +04L 103 070 (4x)  <b>X59933-01</b> 03L 103 483 S 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59929-01</b> 04L 129 717 B 	<b>X59927-01</b> 04L 253 039 B 	<b>70-31414-10</b> 	<b>P77831-01 K</b> → 04L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> 026 198 025 C 6,5 mm Gummi 1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D  <b>X55899-01</b> 068 129 717 E 	<b>X03747-01</b> 026 129 589 A 4x  <b>X07854-01</b> 841 253 115 B  <b>X51157-01</b> 433 253 115 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> 026 198 025 C 6,5 mm Gummi 1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D  <b>X55899-01</b> 068 129 717 E 	<b>X03747-01</b> 026 129 589 A 4x  <b>X07854-01</b> 841 253 115 B  <b>X51157-01</b> 433 253 115 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI							
1,6 CY JK	40-51 kW (54-70 PS)	80 D 80 TD 90 TD	81 G 000 001→ 81 G 000 001→ 81 G 000 001→	08/80-08/91	<b>S30435-00</b> 068 198 001  <b>D30435-00</b> 068 198 012 L  <b>B30584-00</b> 037 198 011 C	<b>H02674-00</b> 068 103 383 EH 1,6 mm 1 <b>H12674-10</b> 068 103 383 EJ 1,65 mm 2 <b>H22674-20</b> 068 103 383 EK 78 Ø 1,7 mm 3	<b>T02673-00</b> 068 103 384 A (10x) 
1,6 DT DTA JU PP SA	51-55 kW (69-75 PS)	80		08/78→	<b>S31446-00</b> <b>D31446-00</b> 050 198 012 A <b>B30584-00</b> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 
1,6 RA SB	59 kW (80 PS)	80 TD 90 TD		09/86-09/91	<b>S30435-00</b> 068 198 001  <b>D30435-00</b> 068 198 012 L  <b>B30584-00</b> 037 198 011 C	<b>H02674-00</b> 068 103 383 EH 1,6 mm 1 <b>H12674-10</b> 068 103 383 EJ 1,65 mm 2 <b>H22674-20</b> 068 103 383 EK 78 Ø 1,7 mm 3	<b>T02673-00</b> 068 103 384 A (10x) 
1,6 RN	55 kW (75 PS)	80		09/86-08/91	<b>S31448-00</b> <b>D31448-00</b> 026 198 012 AD <b>B30584-00</b> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 

Ⓜ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi 1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D  <b>X55899-01</b> 068 129 717 E 	<b>X03747-01</b> 026 129 589 A 4x  <b>X07854-01</b> 841 253 115 B  <b>X51157-01</b> 433 253 115 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi 1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D  <b>X55170-01</b> 026 129 717 F  <b>X07853-01</b> Ⓜ 035 121 171 C 	<b>X03747-01</b> 026 129 589 A 4x  <b>X07854-01</b> 841 253 115 B  <b>X51156-01</b> 443 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi 1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D  <b>X55899-01</b> 068 129 717 E 	<b>X03747-01</b> 026 129 589 A 4x 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI							
Ltr.							
1,6 WV XX YN YP YS YT YY	51-81 kW (70-110 PS) COUPE 80	1 09/73-07/86	→8192 242 682 →8192 242 682	056 198 012 D <b>B30584-00</b> 037 198 011 C	⑫ ⑬	<b>H04129-00</b> 049 103 383 K 81 Ø 1,75 mm	<b>T04132-00</b> 049 103 385 (10x)
1,6 WV WZ XX YG YH YN YP YS YT YY	51-81 kW (70-110 PS) COUPE 80	09/73→	→8192 242 683→ →8192 242 683→	<b>S30587-00</b> ⑫ ⑬ <b>D30587-00</b> ⑫ 049 198 012 H <b>B30584-00</b> ⑬ 037 198 011 C	⑫ ⑬ ⑫ ⑬	<b>H04129-00</b> 049 103 383 K 81 Ø 1,75 mm	<b>T04125-00</b> 049 103 384 B (10x)
1,6 YK	61 kW (83 PS)			<b>S30587-00</b> ⑫ ⑬ <b>D30587-00</b> ⑫ 049 198 012 H <b>B30584-00</b> ⑬ 037 198 011 C	⑫ ⑬ ⑫ ⑬	<b>H04128-00</b> 049 103 383 M 78,5 Ø 1,75 mm  <b>H04129-00</b> 049 103 383 K 81 Ø 1,75 mm	<b>T04132-00</b> 049 103 385 (10x)
1,6 YV YZ FS	63-81 kW (85-110 PS) 100 80	08/76-12/86		<b>S30587-00</b> ⑫ ⑬ <b>D30587-00</b> ⑫ 049 198 012 H <b>B30584-00</b> ⑬ 037 198 011 C	⑫ ⑬ ⑫ ⑬	<b>H04129-00</b> 049 103 383 K 81 Ø 1,75 mm	<b>T04132-00</b> 049 103 385 (10x)



<b>V30584-00</b> 026 198 025 A 8,5 mm Kork	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D	<b>X03747-01</b> 026 129 589 A <b>X07854-01</b> 841 253 115 B	4x	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)
<b>V31265-00</b> ✗ 056 198 025 6,5 mm					<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D	<b>X03747-01</b> 026 129 589 A <b>X07854-01</b> 841 253 115 B	4x	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)
<b>V31265-00</b> ✗ 056 198 025 6,5 mm					<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D	<b>X03747-01</b> 026 129 589 A <b>X07854-01</b> 841 253 115 B	4x	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)
<b>V31265-00</b> ✗ 056 198 025 6,5 mm					<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi					
<b>1 Dichtlippe</b>					
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D	<b>X03747-01</b> 026 129 589 A <b>X07854-01</b> 841 253 115 B	4x	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)
<b>V31265-00</b> ✗ 056 198 025 6,5 mm					<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi					
<b>1 Dichtlippe</b>					



AUDI		1					
1,7 WT	58 kW (78 PS)			<b>S30587-00</b> ⑫ ⑬ <b>D30587-00</b> ⑫ 049 198 012 H <b>B30584-00</b> ⑬ 037 198 011 C	<b>H04129-00</b> 049 103 383 K 81 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 	
1,8 ADR AEB AFY ANZ ARK	85-110 kW (115-150 PS)	A4 A4 T A6 A6 T CABRIOLET	01/95→	<b>S32232-00</b> ⑫ ⑬ <b>D32232-00</b> ⑫ 058 198 012 +058 198 025 A <b>B32232-00</b> ⑬ 058 198 011 <b>B37030-00</b> ⑬ ⑳  <b>Z36190-00</b> ⑧ 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T10468-00</b> 058 103 385 A (10x) 	
1,8 AGN	92 kW (125 PS)	A3	↔8L V 200 000	09/96-05/03	<b>S32240-00</b> ⑫ ⑬ <b>D32240-00</b> ⑫ 06A 198 012 A <b>B32239-00</b> ⑬ ⑳ 06A 198 011 <b>Z36190-00</b> ⑧ 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T80109-00</b> 06A 103 385 C (10x) ↳AGN 107 000  <b>T50468-00</b> 06A 103 385 A (10x) ↳AGN 107 001→ 
1,8 AGN	92 kW (125 PS)	A3	↔8L W 000 001→	09/96-05/03	<b>D36707-00</b> ⑫ <b>B32934-00</b> ⑬ ⑳ 06A 198 011 A <b>Z36190-00</b> ⑧ 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T80109-00</b> 06A 103 385 C (10x) ↳AGN 107 000  <b>T50468-00</b> 06A 103 385 A (10x) ↳AGN 107 001→ 

⑫ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала  
 ⑬ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V31265-00</b> ✗ 056 198 025 6,5 mm 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D 	<b>X03747-01</b> 4x 026 129 589 A <b>X07854-01</b> ⚠ 841 253 115 B 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 20x 036 109 675	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L 	<b>X54226-01</b> 058 103 609 Aluminium  <b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P77317-01 K</b> → ⚠ 028 103 171 B PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 20x 036 109 675	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L  <b>X07867-01</b> ✗ ⚠ 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → ⚠ 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 20x 036 109 675	<b>X88304-01</b> 4x 06A 133 398 D 	<b>X51632-01</b> 058 253 039 L  <b>X07867-01</b> ✗ ⚠ 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → ⚠ 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI							
Ltr.							
1,8	AGU AJQ AMK AMU APP APX APY AQA ARX ARY ARZ ATC AUL AUM AUQ AVJ AWP AWT BAM BEA BFV BVP BVR	110-176 kW (150-240 PS)	A3 S3 A3 T A4 T A6 T TT T	01/95→	<b>D32934-00</b> ⑫ <b>B32934-00</b> ⑬ ⑳ 06A 198 011 A <b>Z36190-00</b> ⑧ 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x) 
1,8	AJL	132 kW (180 PS)	A4 T A6 T	12/97-01/05	<b>S32232-00</b> ⑫ ⑬ <b>D32232-00</b> ⑫ 058 198 012 +058 198 025 A <b>B37030-00</b> ⑬ ⑳ 	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T10468-00</b> 058 103 385 A (10x) 
1,8	AJP AQE ARH	92 kW (125 PS)	A6	07/97-01/05	<b>D32936-00</b> ⑫ 06B 198 012 <b>B32936-00</b> ⑬ ⑳ <b>Z36190-00</b> ⑧ 058 198 217	<b>H50997-00</b> 06B 103 383 B 82 Ø 1,6 mm MLS 	<b>T80109-00</b> 06A 103 385 C (10x) 
1,8	AMB BEX BFB	120-140 kW (163-190 PS)	A4 T	07/01-03/09	<b>D32934-00</b> ⑫ <b>B32934-00</b> ⑬ ⑳ 06A 198 011 A <b>Z36190-00</b> ⑧ 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x) 

⑫ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала

⑬ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L <b>X07867-01</b> ✕ 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L 	<b>X54226-01</b> 058 103 609 Aluminium  <b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P77317-01 K</b> → 028 103 171 B PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L <b>X51169-01</b> ✕ 431 253 115 A 	<b>X54808-01</b> 06B 103 609 Aluminium  <b>70-31414-10</b> 	<b>P76096-11 K</b> ← 068 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI							
Ltr.							
1,8 AMB BEX BFB	120-140 kW (163-190 PS)	A4 T	8E 4 000 001 →	07/01-03/09	<b>D36707-00</b> <b>B32934-00</b> 06A 198 011 A <b>Z36190-00</b> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS	<b>T50468-00</b> 06A 103 385 A (10x)
1,8 ANB APT APU ARG AVV	92-110 kW (125-150 PS)	A4 A4 T A6 T		01/95-01/05	<b>D32232-00</b> 058 198 012 +058 198 025 A <b>B37030-00</b> <b>Z36190-00</b> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS	<b>T10468-00</b> 058 103 385 A (10x)
1,8 ANQ	92 kW (125 PS)	A6		07/97-01/05	<b>D32934-00</b> <b>B32934-00</b> 06A 198 011 A <b>Z36190-00</b> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS	<b>T50468-00</b> 06A 103 385 A (10x)
1,8 APG	92 kW (125 PS)	A3		09/96-05/03	<b>D36707-00</b> <b>B36707-00</b> <b>Z36190-00</b> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS	<b>T50468-00</b> 06A 103 385 A (10x)
1,8 AWL	110 kW (150 PS)	A6 T		01/97-01/05	<b>D32240-00</b> 06A 198 012 A <b>B32934-00</b> 06A 198 011 A <b>Z36190-00</b> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS	<b>T50468-00</b> 06A 103 385 A (10x)
1,8 BYT	118 kW (160 PS)	A3 TFSI		11/06 →		<b>H80727-00</b> 06H 103 383 Q 82,5 Ø MLS	<b>T80727-00</b> 06D 103 385 D (10x)

Ⓜ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала

Ⓝ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V53271-00</b> 058 198 025 A	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X81684-01</b> 06B 129 717 F	<b>X51632-01</b> 058 253 039 L	<b>70-31414-10</b>	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>V53271-00</b> 058 198 025 A	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B	<b>X51632-01</b> 058 253 039 L	<b>X54226-01</b> 058 103 609 Aluminium	<b>P76087-01 K ←</b> 068 103 085 E 32x47x10 A SL RD FPM <b>P77317-01 K →</b> 028 103 171 B PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V53271-00</b> 058 198 025 A	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B	<b>X51632-01</b> 058 253 039 L <b>X07867-01</b> 533 253 115 D	<b>70-31414-10</b>	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>V53271-00</b> 058 198 025 A	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X88304-01</b> 4x 06A 133 398 D	<b>X51632-01</b> 058 253 039 L	<b>70-31414-10</b>	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>V53271-00</b> 058 198 025 A	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B	<b>X51632-01</b> 058 253 039 L <b>X07867-01</b> 533 253 115 D	<b>70-31414-10</b>	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b>	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89272-01</b> 06J 129 717	<b>X81829-01</b> 06F 253 039 F	<b>70-31414-10</b>	<b>P77451-01 K ←</b> 06H 103 383 G 45x60x8 AB SL RD FPM

Ⓝ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач





AUDI						
Ltr.						
1.8 BZB CABA CABB CABD	88-125 kW (120-170 PS)	A3 TFSI A4 TFSI A5 TFSI	11/06→	<b>D40567-00</b> ⑫ <b>B38289-00</b> ⑬ ⑳	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 
1.8 CCUA CDAA CDHA CDHB	88-118 kW (120-160 PS)	A3 TFSI A4 TFSI A5 TFSI TT TFSI	11/06→	<b>D40567-00</b> ⑫ <b>B38289-00</b> ⑬ ⑳	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x)  <b>T80727-00</b> 06D 103 385 D (10x) 
1.8 CJEB <b>[NEW]</b>	125 kW (170 PS)	A4 TFSI A5 TFSI	10/07→	<b>D40708-00</b> ⑫ <b>B38749-00</b> ⑬	<b>H40708-00</b> 06K 103 383 E 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 
1.8 CJSA CJSB <b>[NEW]</b>	132 kW (180 PS)	A3 TFSI	04/12→	<b>D40708-01</b> ⑫ <b>B38749-00</b> ⑬	<b>H40708-00</b> 06K 103 383 E 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 
1.8 DD DR DS JV JW NP SH 4B	55-66 kW (75-90 PS)	COUPE 100 80	08/81-11/90	<b>S31192-00</b> ⑫ ⑬ <b>D31192-00</b> ⑫ 026 198 012 AB <b>B30584-00</b> ⑬ 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 
1.8 DZ MU NE RU SF	55-82 kW (75-112 PS)	COUPE 80	08/84→	<b>S31448-00</b> ⑫ ⑬ <b>D31448-00</b> ⑫ 026 198 012 AD <b>B30584-00</b> ⑬ 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X89272-01</b> 06J 129 717 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K ←</b> 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K →</b> 06H 103 171 F 85x132/152x15,7 PTFE
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X89272-01</b> 06J 129 717  <b>X89273-01</b> 06F 129 717 D 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K ←</b> 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K →</b> 06H 103 171 F 85x132/152x15,7 PTFE
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X59914-01</b> 06K 129 717 A 	<b>X51947-01</b> 037 253 039 	<b>X59956-01</b> 06L 103 649  <b>70-31414-10</b> 	<b>P77842-01 K ←</b> 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77846-01 K →</b> 06K 103 171 A PTFE
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X59914-01</b> 06K 129 717 A 	<b>X59924-01</b> 06L 253 039 	<b>X59956-01</b> 06L 103 649  <b>70-31414-10</b> 	<b>P77842-01 K ←</b> 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77846-01 K →</b> 06K 103 171 A PTFE
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi  1 Dichtlippe 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x <b>X04875-01</b> 026 129 717 D  <b>X55170-01</b> 026 129 717 F  <b>X07853-01</b> ⑩ 035 121 171 C 	<b>X03747-01</b> 4x 026 129 589 A  <b>X07854-01</b> 841 253 115 B  <b>X07867-01</b> ✗ 533 253 115 D 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K ←</b> 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi  1 Dichtlippe 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x <b>X04875-01</b> 026 129 717 D  <b>X55170-01</b> 026 129 717 F 	<b>X03747-01</b> 4x 026 129 589 A  <b>X51169-01</b> 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K ←</b> 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

⑳ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



AUDI						
Ltr.						
1,8 JN PH PM PV RS	55-81 kW (75-110 PS) COUPE 100 80	08/82-10/91	<b>S31443-00</b> (12) (13) <b>D31443-00</b> (12) <b>B30584-00</b> (13) 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	
1,8 SD	83 kW (113 PS) 80	09/86-08/90	<b>S31449-00</b> (12) (13) <b>D31449-00</b> (12) 053198012A <b>B30584-00</b> (13) 037 198 011 C	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	
1,9 AAZ	55 kW (75 PS) 80 TD	09/91-12/94	<b>S31598-00</b> (12) (13)  <b>D31598-00</b> (12) 028 198 012 B  <b>B31598-00</b> (13) 028 198 011 B 	<b>H02390-00</b> 028 103 383 BB 1,6 mm 1 →AAZ462614 <b>H12390-10</b> 028 103 383 BC 1,65 mm 2 →AAZ462614 <b>H22390-20</b> 028 103 383 BD 81 Ø 1,7 mm 3 →AAZ462614  <b>H02391-00</b> 028 103 383 BH 1,53 mm 1 MLS →AAZ462615→ <b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 MLS →AAZ462615→ <b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 MLS →AAZ462615→ 	<b>T02673-00</b> 068 103 384 A (10x) 	



<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X04875-01</b> 026 129 717 D  <b>X55170-01</b> 026 129 717 F 	<b>X03747-01</b> 026 129 589 A 4x  <b>X51157-01</b> 433 253 115 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X55170-01</b> 026 129 717 F 	<b>X03747-01</b> 026 129 589 A 4x  <b>X51169-01</b> 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V31598-00</b> 028 198 025  <b>X53152-01</b> 028 103 483 B ACM 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x  <b>X81385-01</b> 155 253 115 	<b>X54361-01</b> 037 115 220 B NBR 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM



AUDI				
Ltr.				
1,9 ADE	55 kW (75 PS)	1		
		<p><b>D32718-00</b> <sup>(12)</sup>                        → ADE 003 235</p> <p><b>D32719-00</b> <sup>(12)</sup>                        → ADE 003 236</p> <p><b>B32231-00</b> <sup>(13)</sup>                      028 198 011 D                      → ADE 004 200</p> <p><b>B32239-00</b> <sup>(13) (38)</sup>                      06A 198 011                      → ADE 004 201</p>	<p><b>H02391-00</b>                      028 103 383 BH                      1,53 mm 1 </p> <p><b>H12391-10</b>                      028 103 383 BJ                      1,57 mm 2 </p> <p><b>H22391-20</b>                      028 103 383 BK                      81 Ø                      1,61 mm 3 </p> <p></p>	<p><b>T02673-00</b>                      068 103 384 A (10x)  </p>
1,9 AFF	55 kW (75 PS) A4 TDI	12/95-09/01		
		<p><b>S32231-00</b> <sup>(12) (13)</sup>                        → AFF 002 000</p> <p><b>S32721-00</b> <sup>(12) (13)</sup>                        → AFF 002 001</p> <p><b>D32231-00</b> <sup>(12)</sup>                      028 198 012 C                      → AFF 002 000</p> <p><b>D32721-00</b> <sup>(12)</sup>                      028 198 012 F                      → AFF 002 001</p> <p><b>B32231-00</b> <sup>(13)</sup>                      028 198 011 D</p> <p><b>B37015-00</b> <sup>(13) (35)</sup>  </p>	<p><b>H02392-00</b>                      028 103 383 BL                      1,45 mm 1 </p> <p><b>H12392-10</b>                      028 103 383 BM                      1,53 mm 2 </p> <p><b>H22392-20</b>                      028 103 383 BN                      81 Ø                      1,61 mm 3 </p> <p></p>	<p><b>T02673-00</b>                      068 103 384 A (10x)  </p>

<sup>(35)</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V31598-00</b> 028 198 025 	<b>N90300-00</b> 026 109 675 (8x) → ADE 003 235 <b>N91190-00</b> 027 109 675 (8x) → ADE 003 236 <b>P76531-00</b> 026 109 675 8x <b>P76532-00</b> 027 109 675 8x → ADE 003 236	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x  <b>X51641-01</b> 	<b>X54361-01</b> <sup>(X)</sup> 037 115 220 B NBR  <b>X54624-01</b> <sup>(X)</sup> 044 103 609 D ACM 	<b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM → ADE 004 200 <b>P77317-01 K</b> → 028 103 171 B PTFE → ADE 004 201 <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x) 	<b>N90300-00</b> 026 109 675 (8x) → AFF 002 000 <b>N91190-00</b> 027 109 675 (8x) → AFF 002 001 <b>P76531-00</b> 026 109 675 8x <b>P76532-00</b> 027 109 675 8x → AFF 002 001	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x 	<b>X54361-01</b> 037 115 220 B NBR  <b>X54624-01</b> 044 103 609 D ACM  <b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM → 12/97 <b>P77317-01 K</b> → 028 103 171 B PTFE → 01/98 <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

<sup>(38)</sup> sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI				
Ltr.				
1,9 AFN	81 kW (110 PS) A4 TDI A6 TDI	10/95-09/01		
		<p><b>S32231-00</b> <sup>(12) (13)</sup>   → AFN 002 000</p> <p><b>S32721-00</b> <sup>(12) (13)</sup>   → AFN 002 001 →</p> <p><b>D32231-00</b> <sup>(12)</sup>            028 198 012 C   → AFN 002 000</p> <p><b>D32721-00</b> <sup>(12)</sup>            028 198 012 F   → AFN 002 001 →</p> <p><b>B32231-00</b> <sup>(13)</sup>            028 198 011 D   → AFN 576 000</p> <p><b>B37015-00</b> <sup>(13) (35)</sup>   → AFN 576 001 →</p>	<p><b>H02392-00</b>            028 103 383 BL            1,45 mm 1 </p> <p><b>H12392-10</b>            028 103 383 BM            1,53 mm 2 </p> <p><b>H22392-20</b>            028 103 383 BN            81 ∅            1,61 mm 3 </p> <p></p>	<p><b>T02673-00</b>            068 103 384 A (10x)  </p>

<sup>(35)</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x) 	<b>N90300-00</b> 026 109 675 (8x) → AFN 002 000 <b>N91190-00</b> 027 109 675 (8x) → AFN 002 001 → <b>P76531-00</b> 026 109 675 → AFN 002 000 <b>P76532-00</b> 027 109 675 → AFN 002 001 →	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 	4x <b>X54361-01</b> 037 115 220 B NBR  <b>X54624-01</b> 044 103 609 D ACM  <b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



<b>AUDI</b>				
Ltr.				
1,9 AGR	66 kW (90 PS) A3 TDI	09/96-07/01	<b>S32241-00</b> <sup>(12)</sup> <sup>(13)</sup>	<b>H06033-00</b>
				038 103 383 G 1,45 mm 1
			<b>D32241-00</b> <sup>(12)</sup> 038 198 012	→ AGR 151 000
				<b>H16033-10</b>
				038 103 383 F 1,53 mm 2
			<b>B32241-00</b> <sup>(13)</sup> <sup>(38)</sup> 038 198 011	→ AGR 151 000
				<b>H26033-20</b>
				038 103 383 E 80,5 ∅ 1,61 mm 3
				→ AGR 151 000
				<b>H03518-00</b>
				038 103 383 AL 1,47 mm 1
				MLS
				AGR 151 001 →
				<b>H13518-10</b>
				038 103 383 AM 1,57 mm 2
				MLS
				AGR 151 001 →
				<b>H23518-20</b>
				038 103 383 AN 80,5 ∅ 1,67 mm 3
				MLS
				AGR 151 001 →
				<b>T02673-00</b>
				068 103 384 A (10x)

<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 026 129 589 A 4x	<b>70-31414-10</b> 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	
		<b>X51638-01</b> × 037 253 039 D 	<b>X51706-01</b> 3A0 253 115 		
		<b>X52970-01</b> × 1H0 253 115 A 			

<sup>(38)</sup> sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI						
Ltr.						
1,9 AHF	81 kW (110 PS) A3 TDI	08/97-07/01				
			<b>S32241-00</b> (12) (13) 038 198 012	<b>H06033-00</b> 038 103 383 G 1,45 mm 1 MLS → AHF 140 000 <b>H16033-10</b> 038 103 383 F 1,53 mm 2 MLS → AHF 140 000 <b>H26033-20</b> 038 103 383 E 80,5 Ø 1,61 mm 3 MLS → AHF 140 000  <b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS → AHF 140 001→ <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS → AHF 140 001→ <b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS → AHF 140 001→ 	<b>T02673-00</b> 068 103 384 A (10x) 	
1,9 AHH AVG	66-81 kW (90-110 PS) A4 TDI A6 TDI	01/95-09/01	<b>D32721-00</b> (12) 028 198 012 F	<b>H02392-00</b> 028 103 383 BL 1,45 mm 1 MLS <b>H12392-10</b> 028 103 383 BM 1,53 mm 2 MLS <b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 	

35 contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 026 129 589 A 4x <b>X51638-01</b> X 037 253 039 D  <b>X51706-01</b> 3A0 253 115  <b>X52970-01</b> X 1H0 253 115 A 	<b>70-31414-10</b> 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	
<b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x) 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x 	<b>X54624-01</b> 044 103 609 D ACM  <b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P77317-01 K</b> → 028 103 171 B PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

36 sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI						
Ltr.						
1,9 AHU	66 kW (90 PS) A4 TDI A6 TDI CABRIOLET TDI	06/94-09/01	<b>S32721-00</b> <sup>(12) (13)</sup>  <b>D32721-00</b> <sup>(12)</sup> 028 198 012 F  <b>B32231-00</b> <sup>(13)</sup> 028 198 011 D 	<b>H02392-00</b> 028 103 383 BL 1,45 mm 1 MLS <b>H12392-10</b> 028 103 383 BM 1,53 mm 2 MLS <b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 	
1,9 AJM ASZ ATD ATJ AVB AVF AWX AXR BKE BRB	74-96 kW (100-130 PS) A3 TDI A4 TDI A6 TDI	03/00-06/08	<b>D32937-00</b> <sup>(12)</sup>  <b>B32937-00</b> <sup>(13) (35)</sup> 	<b>H09538-00</b> 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS <b>H19538-10</b> 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS <b>H29538-20</b> 038 103 383 DG 80,5 Ø 1,61 mm 3 MLS 	<b>T03518-00</b> 038 103 384 (10x) 	

<sup>(35)</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x) 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 	<b>X54361-01</b> 037 115 220 B NBR  <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K ←</b> 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X53715-01</b> 038 103 483 D ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A  <b>X51638-01</b> 037 253 039 D  <b>X51706-01</b> 3A0 253 115 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM



AUDI

AUDI							
Ltr.	1,9 ALH	66 kW (90 PS)	A3 TDI	09/96-07/01	<p><b>S32241-00</b> <sup>(12) (13)</sup></p> <p></p> <p><b>D32241-00</b> <sup>(12)</sup></p> <p>038 198 012</p> <p></p> <p><b>B32241-00</b> <sup>(13) (38)</sup></p> <p>038 198 011</p> <p></p>	<p><b>H06033-00</b></p> <p>038 103 383 G</p> <p>1,45 mm 1 </p> <p>MLS</p> <p> → ALH 085 000</p> <p><b>H16033-10</b></p> <p>038 103 383 F</p> <p>1,53 mm 2 </p> <p>MLS</p> <p> → ALH 085 000</p> <p><b>H26033-20</b></p> <p>038 103 383 E</p> <p>80,5 Ø</p> <p>1,61 mm 3 </p> <p>MLS</p> <p> → ALH 085 000</p> <p></p> <p><b>H03518-00</b></p> <p>038 103 383 AL</p> <p>1,47 mm 1 </p> <p>MLS</p> <p> ALH 085 001 →</p> <p><b>H13518-10</b></p> <p>038 103 383 AM</p> <p>1,57 mm 2 </p> <p>MLS</p> <p> ALH 085 001 →</p> <p><b>H23518-20</b></p> <p>038 103 383 AN</p> <p>80,5 Ø</p> <p>1,67 mm 3 </p> <p>MLS</p> <p> ALH 085 001 →</p> <p></p>	<p><b>T02673-00</b></p> <p>068 103 384 A (10x)</p> <p></p>
Ltr.	1,9 ASV	81 kW (110 PS)	A3 TDI	08/97-07/01	<p><b>S32241-00</b> <sup>(12) (13)</sup></p> <p></p> <p><b>D32241-00</b> <sup>(12)</sup></p> <p>038 198 012</p> <p></p> <p><b>B32241-00</b> <sup>(13) (38)</sup></p> <p>038 198 011</p> <p></p>	<p><b>H03518-00</b></p> <p>038 103 383 AL</p> <p>1,47 mm 1 </p> <p>MLS</p> <p><b>H13518-10</b></p> <p>038 103 383 AM</p> <p>1,57 mm 2 </p> <p>MLS</p> <p><b>H23518-20</b></p> <p>038 103 383 AN</p> <p>80,5 Ø</p> <p>1,67 mm 3 </p> <p>MLS</p> <p></p>	<p><b>T02673-00</b></p> <p>068 103 384 A (10x)</p> <p></p>

<sup>(38)</sup> sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



<p><b>N91190-00</b></p> <p>027 109 675 (8x)</p> <p><b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b> 4x</p> <p>026 129 589 A</p> <p></p> <p><b>X51638-01</b> <sup>(X)</sup></p> <p>037 253 039 D</p> <p></p> <p><b>X51706-01</b></p> <p>3A0 253 115</p> <p></p> <p><b>X52970-01</b> <sup>(X) (A)</sup></p> <p>1H0 253 115 A</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>P76096-01 K</b> ←</p> <p>069 115 147 C</p> <p>35x48x10</p> <p>A SL RD FPM</p> <p><b>P77183-01 K</b> → </p> <p>06A 103 171 A</p> <p>85x131/152x15,7</p> <p>PTFE</p> <p><b>P76087-01 N</b></p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p>	
<p><b>N91190-00</b></p> <p>027 109 675 (8x)</p> <p><b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b> 4x</p> <p>026 129 589 A</p> <p></p> <p><b>X51638-01</b> <sup>(X)</sup></p> <p>037 253 039 D</p> <p></p> <p><b>X51706-01</b></p> <p>3A0 253 115</p> <p></p> <p><b>X52970-01</b> <sup>(X) (A)</sup></p> <p>1H0 253 115 A</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>P76096-01 K</b> ←</p> <p>069 115 147 C</p> <p>35x48x10</p> <p>A SL RD FPM</p> <p><b>P77183-01 K</b> → </p> <p>06A 103 171 A</p> <p>85x131/152x15,7</p> <p>PTFE</p> <p><b>P76087-01 N</b></p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p>	





AUDI						
Ltr.						
1,9 BKC BXE	77 kW (105 PS) A3 TDI	05/03-05/10	<b>D32937-00</b> <sup>(12)</sup>  <b>B36708-00</b> <sup>(13) (35)</sup>	<b>H09538-00</b> 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS <b>H19538-10</b> 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS <b>H29538-20</b> 038 103 383 DG 80,5 Ø 1,61 mm 3 	<b>T03518-00</b> 038 103 384 (10x) 	
1,9 BLS	77 kW (105 PS) A3 TDI	05/03→	<b>D37051-00</b> <sup>(12)</sup>  <b>B36708-00</b> <sup>(13) (35)</sup>	<b>H09538-00</b> 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS <b>H19538-10</b> 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS <b>H29538-20</b> 038 103 383 DG 80,5 Ø 1,61 mm 3 	<b>T03518-00</b> 038 103 384 (10x) 	
1,9 WH WN	74-85 kW (100-115 PS) COUPE 100 80	08/80-07/84	<b>S31200-00</b> <sup>(12) (13)</sup> <b>D31200-00</b> <sup>(12)</sup> 035 198 012 L <b>B30567-00</b> <sup>(13)</sup> 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	

<sup>(35)</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X53715-01</b> 038 103 483 D ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x 	<b>X51638-01</b> 037 253 039 D <b>X51706-01</b> 3A0 253 115 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83120-01</b> 03G 103 483 D NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x 	<b>X81833-01</b> 03G 253 039 A 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>V30567-00</b> 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	<b>X02658-01</b> 034 129 717 M 10x 	<b>X03747-01</b> 026 129 589 A 5x  <b>X51169-01</b> 431 253 115 A 	<b>X02643-01</b> 054 103 609 	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM



AUDI				
Ltr.				
1,9 1Y	50 kW (68 PS) 80 D	08/89-08/91	<b>S31598-00</b> (12) (13)  <b>D31598-00</b> 028 198 012 B  <b>B31598-00</b> 028 198 011 B 	<b>H02390-00</b> 028 103 383 BB 1,6 mm 1 → 1Y315599 <b>H12390-10</b> 028 103 383 BC 1,65 mm 2 → 1Y315599 <b>H22390-20</b> 028 103 383 BD 81 Ø 1,7 mm 3 → 1Y315599  <b>H02391-00</b> 028 103 383 BH 1,53 mm 1 MLS → 1Y315600→ <b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 MLS → 1Y315600→ <b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 MLS → 1Y315600→ 
1,9 1Z	66 kW (90 PS) A4 TDI A6 TDI CABRIOLET TDI 80 TDI	09/91-09/01	<b>S32231-00</b> (12) (13) → 1Z 770 000  <b>S32721-00</b> (12) (13) → 1Z 770 001→  <b>D32231-00</b> (12) 028 198 012 C → 1Z 770 000  <b>D32721-00</b> (12) 028 198 012 F → 1Z 770 001→  <b>B32231-00</b> (13) 028 198 011 D 	<b>H02392-00</b> 028 103 383 BL 1,45 mm 1 MLS <b>H12392-10</b> 028 103 383 BM 1,53 mm 2 MLS <b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 MLS 



<b>V31598-00</b> 028 198 025  <b>X53152-01</b> 028 103 483 B ACM 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A  <b>X81385-01</b> 155 253 115 	4x <b>X54361-01</b> 037 115 220 B NBR 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x) 	<b>N90300-00</b> 026 109 675 (8x) → 1Z 770 000 <b>N91190-00</b> 027 109 675 (8x) → 1Z 770 001→ <b>P76531-00</b> 026 109 675 → 1Z 770 000 <b>P76532-00</b> 027 109 675 → 1Z 770 001→	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 	4x <b>X54361-01</b> 037 115 220 B NBR  <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI						
Ltr.						
2,0 AAD	82-85 kW (112-115 PS)	COUPE 100 80	05/89-12/96	<b>S31636-00</b> ⑫ ⑬ <b>D31636-00</b> ⑫ 048 198 012 <b>B31640-00</b> ⑬ 037 198 011 E	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 
2,0 AAE	74 kW (100 PS)	100	12/90-06/94	<b>D31636-00</b> ⑫ 048 198 012 <b>B32233-00</b> ⑬ 037 198 011 G	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 
2,0 AAE	74 kW (100 PS)	100	12/90-06/94	<b>D32688-00</b> ⑫ 048 198 012 B <b>B32233-00</b> ⑬ 037 198 011 G	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 
2,0 AAE	74 kW (100 PS)	A6	06/94-12/97	<b>D37006-00</b> ⑫ 048 198 012 C → AAE 032 209 <b>D32234-00</b> ⑫ 048 198 012 D → AAE 032 210 → <b>B32233-00</b> ⑬ 037 198 011 G	<b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✗ 026 198 025 C 6,5 mm Gummi 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 	<b>X04875-01</b> 026 129 717 D  <b>X55626-01</b> 048 129 717 A 	<b>X03747-01</b> 4x 026 129 589 A  <b>X51169-01</b> △ 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)  <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 	<b>X04875-01</b> 026 129 717 D  <b>X55430-01</b> 048 129 717 A  <b>X07853-01</b> ⑩ 035 121 171 C 	<b>X03747-01</b> 4x 026 129 589 A  <b>X51947-01</b> 037 253 039  <b>X51169-01</b> △ 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)  <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>X53263-01</b> 051 103 483 A ACM 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 	<b>X04875-01</b> 026 129 717 D  <b>X55430-01</b> 048 129 717 A  <b>X07853-01</b> ⑩ 035 121 171 C 	<b>X03747-01</b> 4x 026 129 589 A  <b>X51947-01</b> 037 253 039  <b>X51169-01</b> △ 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)  <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>X53263-01</b> 051 103 483 A ACM 	<b>N90300-00</b> 026 109 675 (8x) → AAE 032 209 <b>N91190-00</b> 027 109 675 (8x) → AAE 032 210 → <b>P76531-00</b> 026 109 675 → AAE 032 209 <b>P76532-00</b> 027 109 675 → AAE 032 210 →	<b>X04875-01</b> 026 129 717 D  <b>X55430-01</b> 048 129 717 A  <b>X07853-01</b> ⑩ 035 121 171 C 	<b>X03747-01</b> 4x 026 129 589 A → AAE 032 209 <b>X51947-01</b> 037 253 039 → AAE 032 210 → <b>X51169-01</b> △ 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)  <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM



AUDI					
Ltr.					
2,0 ABK	85 kW (115 PS) A6	06/94-06/96	<p><b>D32688-00</b> (12) 048 198 012 B →4A S 110 000 <b>D37006-00</b> (12) 048 198 012 C →4A S 110 001→ →ABK 245 263 <b>D32234-00</b> (12) 048 198 012 D →ABK 245 264→ <b>B32233-00</b> (13) 037 198 011 G</p>	<p><b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm →4A S 110 000</p> <p><b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS →4A S 110 001→</p>	<p><b>T04125-00</b> 049 103 384 B (10x) →4A S 110 000</p> <p><b>T50469-00</b> 050 103 384 (10x) →4A S 110 001→</p>
2,0 ABK	85 kW (115 PS) CABRIOLET	01/93-09/98	<p><b>D31636-00</b> (12) 048 198 012 →8G P 006 500 <b>D32688-00</b> (12) 048 198 012 B →8G P 006 501→ →8G S 009 000 <b>D37006-00</b> (12) 048 198 012 C →8G S 009 001→ →ABK 245 263 <b>D32234-00</b> (12) 048 198 012 D →ABK 245 264→ <b>B32233-00</b> (13) 037 198 011 G</p>	<p><b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm →8G S 009 000</p> <p><b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS →8G S 009 001→</p>	<p><b>T04125-00</b> 049 103 384 B (10x) →8G S 009 000</p> <p><b>T50469-00</b> 050 103 384 (10x) →8G S 009 001→</p>
2,0 ABK	85 kW (115 PS) COUPE	08/91-12/95	<p><b>D31636-00</b> (12) 048 198 012 →8B P 006 500 <b>D32688-00</b> (12) 048 198 012 B →8B P 006 501→ →8B S 009 000 <b>D37006-00</b> (12) 048 198 012 C →8B S 009 001→ →ABK 245 263 <b>D32234-00</b> (12) 048 198 012 D →ABK 245 264→ <b>B32233-00</b> (13) 037 198 011 G</p>	<p><b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm →8B S 009 000</p> <p><b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS →8B S 009 001→</p>	<p><b>T04125-00</b> 049 103 384 B (10x) →8B S 009 000</p> <p><b>T50469-00</b> 050 103 384 (10x) →8B S 009 001→</p>

Ⓔ de una pieza / einteilig / one-piece / en une pièce / monopezzo / цельный



<b>X53263-01</b> 051 103 483 A	<b>N90300-00</b> 026 109 675 (8x) →ABK 245 263 <b>N91190-00</b> 027 109 675 (8x) →ABK 245 264→ <b>P76531-00</b> 026 109 675 →ABK 245 263 <b>P76532-00</b> 027 109 675 →ABK 245 264→	<b>X55626-01</b> 048 129 717 A	<b>X03747-01</b> 026 129 589 A 4x <b>X51947-01</b> (49) 037 253 039 <b>X51169-01</b> 431 253 115 A	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10
<b>V30584-00</b> 026 198 025 A →8G P 006 500	<b>N90300-00</b> 026 109 675 (8x) →ABK 245 263 <b>N91190-00</b> 027 109 675 (8x) →ABK 245 264→ <b>P76531-00</b> 026 109 675 →ABK 245 263 <b>P76532-00</b> 027 109 675 →ABK 245 264→	<b>X55626-01</b> 048 129 717 A	<b>X03747-01</b> 026 129 589 A 4x <b>X51947-01</b> (49) 037 253 039 <b>X51169-01</b> 431 253 115 A	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A →8B P 006 500	<b>N90300-00</b> 026 109 675 (8x) →ABK 245 263 <b>N91190-00</b> 027 109 675 (8x) →ABK 245 264→ <b>P76531-00</b> 026 109 675 →ABK 245 263 <b>P76532-00</b> 027 109 675 →ABK 245 264→	<b>X55626-01</b> 048 129 717 A	<b>X03747-01</b> 026 129 589 A 4x <b>X51947-01</b> (49) 037 253 039 <b>X51169-01</b> 431 253 115 A	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI

AUDI					
Ltr.					
2,0 ABK	85 kW (115 PS) 100	01/93-07/94			
			<b>D32688-00</b> ⑫ 048 198 012 B <b>B32233-00</b> ⑬ 037 198 011 G	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 
2,0 ABK	85 kW (115 PS) 80	01/91-07/95	<b>D31636-00</b> ⑫ 048 198 012 →8C P 185 164 <b>D32688-00</b> ⑫ 048 198 012 B →8C P 185 165→ →8C S 170 000 <b>D37006-00</b> ⑫ 048 198 012 C →8C S 170 001→ →ABK 245 263 <b>D32234-00</b> ⑫ 048 198 012 D →ABK 245 264→ <b>B32233-00</b> ⑬ 037 198 011 G	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm →8C S 170 000  <b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS →8C S 170 001→ 	<b>T04125-00</b> 049 103 384 B (10x) →8C S 170 000  <b>T50469-00</b> 050 103 384 (10x) →8C S 170 001→ 
2,0 ABT	66 kW (90 PS) 80	09/91-01/96	<b>S31636-00</b> ⑫ ⑬ <b>D31636-00</b> ⑫ 048 198 012 <b>B32688-00</b> ⑬	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 
2,0 ABT	66 kW (90 PS) 80	09/91-01/96	<b>S32688-00</b> ⑫ ⑬ <b>D32688-00</b> ⑫ 048 198 012 B →ABT 246 861 <b>B32688-00</b> ⑬	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 

④ de una pieza / einteilig / one-piece / en une pièce / monopezzo / цельный



<b>X53263-01</b> 051 103 483 A  2 Dichtlippen	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X55626-01</b> 048 129 717 A  <b>X57858-01</b> 048 129 717 B 	<b>X03747-01</b> 4x 026 129 589 A  <b>X51947-01</b> ④9 037 253 039  <b>X51169-01</b> 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)  <b>X54624-01</b> 044 103 609 D 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A →8C P 185 164  <b>X53509-00</b> →8C P 185 164 <b>X53263-01</b> 051 103 483 A →8C P 185 165→  2 Dichtlippen	<b>N90300-00</b> 026 109 675 (8x) →ABK 245 263 <b>N91190-00</b> 027 109 675 (8x) →ABK 245 264→ <b>P76531-00</b> 026 109 675 →ABK 245 263 <b>P76532-00</b> 027 109 675 →ABK 245 264→	<b>X55626-01</b> 048 129 717 A  <b>X57858-01</b> 048 129 717 B 	<b>X03747-01</b> 4x 026 129 589 A  <b>X51947-01</b> ④9 037 253 039  <b>X51169-01</b> 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)  <b>X54624-01</b> 044 103 609 D 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X53263-01</b> 051 103 483 A ACM  2 Dichtlippen	<b>N90300-00</b> 026 109 675 (8x) →ABT 246 861 <b>N91190-00</b> ✗ 027 109 675 (8x) →ABT 246 862→ <b>P76531-00</b> 026 109 675 →ABT 246 861 <b>P76532-00</b> ✗ 027 109 675 →ABT 246 862→	<b>X57858-01</b> 048 129 717 B 	<b>X03747-01</b> 4x 026 129 589 A  <b>X51947-01</b> 037 253 039 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)  <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI

AUDI						
Ltr.						
2,0 ACE	103 kW (140 PS) A6 CABRIOLET COUPE 100 80	01/92-12/97	<b>S31638-00</b> (12) (13) → ACE 017 542 <b>S32233-00</b> (12) (13) → ACE 017 543→ <b>D31638-00</b> (12) 053 198 012 C → ACE 017 542 <b>D32233-00</b> (12) 053198012D → ACE 017 543→ <b>B31640-00</b> (13) 037 198 011 E → ACE 017 542 <b>B32233-00</b> (13) 037 198 011 G → ACE 017 543→	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm → ACE 017 542  <b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS → ACE 017 543→ 	<b>T04843-00</b> 027 103 385 C (10x) → ACE 017 542  <b>T50151-00</b> 053 103 385 (10x) → ACE 017 543→ 	
2,0 ALT	96 kW (130 PS) A4 A6	11/00-06/08	<b>D36711-00</b> (12) <b>B36711-00</b> (13) (38)	<b>H50827-00</b> 06B 103 383 R 83,5 Ø MLS 	<b>T50827-00</b> 06B 103 385 (10x) 	
2,0 AWA AXW BMB	110 kW (150 PS) A3 FSI A4 FSI	07/02→	<b>D36713-00</b> (12) <b>B36711-00</b> (13) (38)	<b>H80451-00</b> 06D 103 383 L 84 Ø MLS 	<b>T80450-00</b> 06D 103 385 (10x) 	
2,0 AXA	85 kW (115 PS)		<b>D36712-00</b> (12) <b>B32937-00</b> (13) (35)	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	

(12) junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора  
 (35) contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V31196-00</b> 027 198 025 → ACE 017 542  <b>V32233-00</b> 051 198 025 → ACE 017 543→ 	<b>N92850-00</b> 027 109 675 (16x) <b>P76532-00</b> 027 109 675	<b>X07866-01</b> 037 129 717 F  <b>X07865-01</b> (10) 027 129 717 D 	<b>X07855-01</b> 027 129 589 A → ACE 017 542  <b>X03747-01</b> 026 129 589 A → ACE 017 543→ 	<b>X04116-01</b> 026 103 609 D → ACE 017 542  <b>X54624-01</b> 044 103 609 D ACM → ACE 017 543→ 	<b>P76087-01 K ←</b> 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X83031-01</b> 06B 103 483 H NBR 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X88305-01</b> 058 129 717 C 	<b>X81686-01</b> 06B 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> (38) 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77352-01 K →</b> (38) 06B 103 171 E <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83032-01</b> 06D 103 483 D 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X88306-01</b> 06D 129 717 D 	<b>X81686-01</b> 06B 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> (38) 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77352-01 K →</b> (38) 06B 103 171 E <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X53809-01</b> NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X57668-01</b> 037 129 717 C  <b>X52681-01</b> (10) 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P77183-01 K →</b> (38) 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

(38) sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI								
Ltr.								
2,0	AXX BGB BHZ BPG BPJ BPY BUL BWA BWE BWT BYK BZC CDLA CDLB CDLC CDLH CDMA	125-200 kW (170-272 PS)	A1 TFSI A3 S3 A3 TFSI A4 FSI A4 TFSI A6 TFSI S3 TT TFSI	09/04→	<b>D37050-00</b> <b>B36707-00</b>  	<sup>12</sup> <sup>13</sup> <sup>35</sup>	<b>H80449-00</b> 06F 103 383 G 83,5 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 
2,0	AZV BKD	100-103 kW (136-140 PS)	A3 TDI	05/03→	<b>D36710-00</b>  <b>B36708-00</b> 	<sup>12</sup> <sup>13</sup> <sup>35</sup>	<b>H08124-00</b> 03G 103 383 1,55 mm MLS <b>H18124-10</b> 03G 103 383 A 1,63 mm MLS <b>H28124-20</b> 03G 103 383 B 82 Ø 1,7 mm MLS 	<b>T08124-00</b> 03G 103 384 (10x) 
2,0	BJZ	85 kW (115 PS)			<b>D36712-00</b> <b>B32937-00</b>  	<sup>12</sup> <sup>13</sup> <sup>35</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 
2,0	BLB BNA BRD BRE BRF BVA BVF BVG	89-125 kW (121-170 PS)	A4 TDI A6 TDI	07/04→	<b>D36709-00</b>  <b>B36708-00</b> 	<sup>12</sup> <sup>13</sup> <sup>35</sup>	<b>H08124-00</b> 03G 103 383 1,55 mm MLS <b>H18124-10</b> 03G 103 383 A 1,63 mm MLS <b>H28124-20</b> 03G 103 383 B 82 Ø 1,7 mm MLS 	<b>T08124-00</b> 03G 103 384 (10x) 

<sup>35</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X83119-01</b> 06F 103 483 D NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X89273-01</b> 06F 129 717 D 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83030-01</b> 03G 103 483 NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X87466-01</b> 03G 129 717 B 	<b>X81685-01</b> 03G 253 039 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM 2x
<b>X53809-01</b> NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X75011-01</b> 4x 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83029-01</b> 03G 103 483 B NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X87466-01</b> 03G 129 717 B 	<b>X81685-01</b> 03G 253 039 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM 2x



AUDI								
Ltr.								
2,0 BLR BLX BLY BVY BVZ	110 kW (150 PS) A3 FSI	05/03→	<b>D37018-00</b> ⑫ <b>B36711-00</b> ⑬ ⑳	<b>H80451-00</b> 06D 103 383 L 84 Ø MLS 	<b>T80450-00</b> 06D 103 385 (10x) 			
2,0 BMM	103 kW (140 PS) A3 TDI	06/05-06/08	<b>D37051-00</b> ⑫  <b>B36708-00</b> ⑬ ⑳	<b>H08008-00</b> 038 103 383 CP 1,45 mm 1 MLS <b>H18008-10</b> 038 103 383 CQ 1,53 mm 2 MLS <b>H28008-20</b> 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	<b>T03518-00</b> 038 103 384 (10x) 			
2,0 BMN BUY	120-125 kW (163-170 PS) A3 TDI	03/06→	<b>D37052-00</b> ⑫  <b>B36708-00</b> ⑬ ⑳	<b>H08124-00</b> 03G 103 383 1,55 mm 1 MLS <b>H18124-10</b> 03G 103 383 A 1,63 mm 2 MLS <b>H28124-20</b> 03G 103 383 B 82 Ø 1,7 mm 3 MLS 	<b>T08124-00</b> 03G 103 384 (10x) 			
2,0 BPW BRC	100-103 kW (136-140 PS) A4 TDI	11/04→	<b>D32937-00</b> ⑫  <b>B32937-00</b> ⑬ ⑳	<b>H08008-00</b> 038 103 383 CP 1,45 mm 1 MLS <b>H18008-10</b> 038 103 383 CQ 1,53 mm 2 MLS <b>H28008-20</b> 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	<b>T03518-00</b> 038 103 384 (10x) 			

⑳ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X83112-01</b> 06D 103 483 E NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X88306-01</b> 06D 129 717 D 	<b>X81686-01</b> 06B 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM			
<b>X83120-01</b> 03G 103 483 D NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X55431-01</b> 028 129 717 D 	<b>X81833-01</b> 03G 253 039 A 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM			
<b>X83121-01</b> 03G 103 483 C NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X87466-01</b> 03G 129 717 B  <b>X89274-01</b> 03G 129 717 C 	<b>X81981-01</b> 03G 253 039 C 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM			
<b>X53715-01</b> 038 103 483 D ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X55431-01</b> 028 129 717 D 	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM			

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач





AUDI						
Ltr.						
2,0 CADA CAEA CAEB CAWB CBFA CCTA CCZA CESA CETA CFKA	132-155 kW (180-211 PS)	A3 TFSI A4 TFSI A5 TFSI A6 TFSI Q5 TFSI TT TFSI	09/04→	<b>D40567-00</b> ⑫ <b>B38289-00</b> ⑬ ⑳	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x)  <b>T80727-00</b> 06D 103 385 D (10x) 
2,0 CAGA CAGB CAHA CAHB CBAA CBAB CBBB CMEA	100-125 kW (136-170 PS)	A3 TDI A4 TDI A5 TDI A6 TDI Q5 TDI TT TDI	05/03→	<b>D38107-00</b> ⑫  <b>B38109-00</b> ⑬ ⑳	<b>H01461-00</b> 03L 103 383 82 Ø 1,55 mm 1 □ MLS <b>H11461-10</b> 03L 103 383 A 82 Ø 1,63 mm 2 □ MLS <b>H21461-20</b> 03L 103 383 B 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 
2,0 CCZC CDNA CDNB CDNC CDZA CHJA CPMA CPSA	125-155 kW (170-211 PS)	A4 TFSI A5 TFSI A6 TFSI A8 TFSI Q3 TFSI Q5 TFSI	06/08→	<b>D40567-00</b> ⑫ <b>B38289-01</b> ⑬ ⑳	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x)  <b>T80727-00</b> 06D 103 385 D (10x) 
2,0 CFFA CFFB	100-103 kW (136-140 PS)	Q3 TDI	09/11→	<b>D38308-00</b> ⑫  <b>B38299-01</b> ⑬ ⑳	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 

⑳ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89273-01</b> 06F 129 717 D 16x 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K ←</b> 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K →</b> 06H 103 171 F 85x132/152x15,7 PTFE
<b>X83360-01</b> 03L 103 483 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89884-01</b> 03L 129 717 16x 	<b>X81685-01</b> 03G 253 039 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89273-01</b> 06F 129 717 D 16x 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77842-01 K ←</b> 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77754-01 K →</b> 06H 103 171 F 85x132/152x15,7 PTFE
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X59474-01</b> 03L 129 717 E 16x 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE ① →11/11 <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>X59500-01</b> 03L 103 483 C 					

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI								
2.0	CFFA CFFB CGLA CGLB CLJA CMGA	100-125 kW (136-170 PS)	A3 TDI Q5 TDI		05/03→	 <b>D38308-00</b> ⑫  <b>B38299-00</b> ⑬ ⑳	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 
2.0	CFGB CFGC CFGD CLLB <b>[NEW]</b>	120-130 kW (163-177 PS)	A3 TDI Q3 TDI TT TDI		03/06→	 <b>D38731-00</b> ⑫  <b>B38299-01</b> ⑬ ⑳	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 
2.0	CFHB CFHD	100-105 kW (136-143 PS)	A1 TDI		09/11→	 <b>D38308-00</b> ⑫  <b>B38299-01</b> ⑬ ⑳	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 

⑳ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59474-01</b> 03L 129 717 E 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59474-01</b> 03L 129 717 E 	<b>X59891-01</b> 04L 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE ① →11/11 <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59474-01</b> 03L 129 717 E 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE ① →06/12 <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



AUDI						
Ltr.			<b>1</b>			
2,0 CGLC CGLD CMGB	120-130 kW (163-177 PS)			<b>D38731-00</b> <sup>(12)</sup>  <b>B38299-01</b> <sup>(13) 38</sup>	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 	<b>T50034-00</b> WHT 002 131 (10x) 
2,0 CGLE CJCA CJCB CMFA	100-105 kW (136-143 PS)	A4 TDI A5 TDI A6 TDI Q5 TDI	11/07→	<b>D38308-00</b> <sup>(12)</sup>  <b>B38299-01</b> <sup>(13) 38</sup>	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 	<b>T50034-00</b> WHT 002 131 (10x) 
2,0 CJCD CMFB	110 kW (150 PS)	A4 TDI A5 TDI Q5 TDI	05/13→	<b>D38308-00</b> <sup>(12)</sup>  <b>B38299-01</b> <sup>(13) 38</sup>	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 	<b>T50034-00</b> WHT 002 131 (10x) 

<sup>38</sup> sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59474-01</b> 03L 129 717 E 	<b>X59891-01</b> 04L 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE →08/12 <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59474-01</b> 03L 129 717 E 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE →09/12 <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59474-01</b> 03L 129 717 E 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM



AUDI

AUDI						
Ltr.						
2,0 CN	51 kW (70 PS) 100 D	08/78-11/90	<b>D30568-00</b> <sup>12</sup> 069198012B ↔ 43 B 077 979→  <b>B30567-00</b> <sup>13</sup> 034 198 011 C	<b>H17895-00</b> 78,5 Ø 1,5 mm 1 □ <b>H27895-20</b> 78,5 Ø 1,6 mm 3 □ ↔ 43 B 077 979→ ↔ →44 F 300 000  <b>H07896-00</b> 069 103 383 CM 78 Ø 1,53 mm 1 □ <b>H17896-10</b> 069 103 383 CN 78 Ø 1,57 mm 2 □ <b>H27896-20</b> 069 103 383 CP 78 Ø 1,61 mm 3 □ ↔ →44 G 000 001→ 	<b>T07896-00</b> 068 103 384 A (12x) ↔ 43 B 077 979→ 	
2,0 CNCB CNCB <b>[NEW]</b>	132-165 kW (180-224 PS) A4 TFSI A5 TFSI Q5 TFSI	08/09→	<b>D40708-00</b> <sup>12</sup> <b>B38749-00</b> <sup>13</sup>	<b>H40708-00</b> 06K 103 383 E 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 	
2,0 CRBC CRLB <b>[NEW]</b>	110 kW (150 PS) A3 TDI	04/12→	<b>D38750-00</b> <sup>12</sup>  	<b>H40701-00</b> 04L 103 383 AC 82 Ø 1,55 mm 1 □ MLS <b>H40701-10</b> 04L 103 383 AD 82 Ø 1,63 mm 2 □ MLS <b>H40701-20</b> 04L 103 383 AE 82 Ø 1,71 mm 3 □ MLS 	<b>T40709-00</b> WHT 005 673 (10x) 	



<b>V31163-00</b> 069 198 025 C ↔ 43 B 077 979→ 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X07945-01</b> 034 129 717 L 	<b>X03747-01</b> 026 129 589 A 5x <b>X51157-01</b> 433 253 115 	<b>X02643-01</b> 054 103 609 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59914-01</b> 06K 129 717 A 	<b>X51947-01</b> 037 253 039 	<b>X59956-01</b> 06L 103 649  <b>70-31414-10</b> 	<b>P77842-01 K</b> ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77846-01 K</b> → 06K 103 171 A PTFE
<b>V59933-00</b> 03L 103 483 S +04L 103 070 (4x)  <b>X59933-01</b> 03L 103 483 S 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59929-01</b> 04L 129 717 B 	<b>X59927-01</b> 04L 253 039 B 	<b>70-31414-10</b> 	<b>P77831-01 K</b> → 04L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM



AUDI

AUDI											
Ltr.											
2,0 CRFA CRFC	81-105 kW (110-143 PS)	A3 TDI	09/12→	<b>D38750-01</b> (12) 	<b>H40701-00</b> 04L 103 383 AC 82 Ø 1,55 mm 1 MLS <b>H40701-10</b> 04L 103 383 AD 82 Ø 1,63 mm 2 MLS <b>H40701-20</b> 04L 103 383 AE 82 Ø 1,71 mm 3 	<b>T40709-00</b> WHT 005 673 (10x) 					
2,0 CUPA	135 kW (184 PS)			<b>D38750-00</b> (12) 	<b>H40704-00</b> 04L 103 383 AT 82 Ø 1,55 mm 1 MLS <b>H40704-10</b> 04L 103 383 BA 82 Ø 1,63 mm 2 MLS <b>H40704-20</b> 04L 103 383 BB 82 Ø 1,71 mm 3 	<b>T40709-00</b> WHT 005 673 (10x) 					
2,0 DE	64 kW (87 PS)	100 D 100 TD	↔ 44 F 300 000 ↔ 44 F 300 000	08/82-02/88	<b>S31163-00</b> (12) (13) 	<b>H07895-00</b> 069 103 383 CT 1,4 mm 1 <b>H17895-10</b> 069 103 383 DB 1,5 mm 2 <b>H27895-20</b> 78,5 Ø 1,6 mm 3 	<b>T07896-00</b> 068 103 384 A (12x) 				
2,0 DE	64 kW (87 PS)	100 D 100 TD	↔ 44 G 000 001→ ↔ 44 G 000 001→	08/82-02/88	<b>S31163-00</b> (12) (13) 	<b>H07896-00</b> 069 103 383 CM 1,53 mm 1 <b>H17896-10</b> 069 103 383 CN 1,57 mm 2 <b>H27896-20</b> 069 103 383 CP 78 Ø 1,61 mm 3 	<b>T07896-00</b> 068 103 384 A (12x) 				



<b>V59933-00</b> 03L 103 483 S +04L 103 070 (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59929-01</b> 04L 129 717 B 	<b>X59891-01</b> 04L 253 039 D 	<b>70-31414-10</b> 	<b>P77831-01 K</b> → 04L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V59933-00</b> 03L 103 483 S +04L 103 070 (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59929-01</b> 04L 129 717 B 	<b>X59927-01</b> 04L 253 039 B 	<b>70-31414-10</b> 	<b>P77831-01 K</b> → 04L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V31163-00</b> 069 198 025 C 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x 	<b>X02643-01</b> 054 103 609 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V31163-00</b> 069 198 025 C 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x 	<b>X02643-01</b> 054 103 609 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI						
Ltr.						
2,0 HP JL JS KP RT SK SL	09/83→	81-85 kW (110-115 PS)	COUPE 100 80 90	<b>S30567-00</b> ⑫ ⑬ <b>D30567-00</b> ⑫ 035 198 012 N <b>B30567-00</b> ⑬ 034 198 011 C	<b>H02641-00</b> 034 103 383 AA 82,7 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 
2,0 NC	03/88-11/90	74 kW (100 PS)	100 D 100 TD	<b>S31163-00</b> ⑫ ⑬  <b>D31163-00</b> ⑫ 069 198 012 C  <b>B30567-00</b> ⑬ 034 198 011 C	<b>H07896-00</b> 069 103 383 CM 1,53 mm 1 <b>H17896-10</b> 069 103 383 CN 1,57 mm 2 <b>H27896-20</b> 069 103 383 CP 78 Ø 1,61 mm 3	<b>T07896-00</b> 068 103 384 A (12x) 
2,0 PS	07/88-09/91	85 kW (115 PS)	90	<b>S31634-00</b> ⑫ ⑬ <b>D31634-00</b> ⑫ 034 198 012 H <b>B30567-00</b> ⑬ 034 198 011 C	<b>H02641-00</b> 034 103 383 AA 82,7 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 
2,0 WA WF	06/76→	77-85 kW (105-115 PS)	100	<b>D31645-00</b> ⑫ 047 198 012 B <b>B37007-00</b> ⑬ 060 198 011 B	<b>H50164-00</b> 046 103 383 J 88,5 Ø 1,55 mm 	
2,0 3A	08/88-10/90	82-83 kW (112-113 PS)	COUPE 80	<b>S31449-00</b> ⑫ ⑬ <b>D31449-00</b> ⑫ 053198012A <b>B30584-00</b> ⑬ 037 198 011 C	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>V30567-00</b> X 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x  <b>X51169-01</b> 431 253 115 A 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V31163-00</b> 069 198 025 C 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M  <b>X57857-01</b> X ⑩ 069 129 717 	<b>X03747-01</b> 026 129 589 A 5x  <b>X81078-01</b> X 433 253 115 A 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30567-00</b> X 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X55159-01</b> 034 129 717 F  <b>X55158-01</b> ⑩ 034 129 717 E 	<b>X03747-01</b> 026 129 589 A 5x 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V31645-00</b> 060 198 025 A 	<b>N92632-00</b> 046 109 675 A (8x) <b>P76661-00</b> 046 109 675 A 8x	<b>X56304-01</b> 060 129 717 A 	<b>X52208-01</b> 048 129 589 A 4x  <b>X51169-01</b> 431 253 115 A 	<b>E37007-00</b> 060 198 041 A 	<b>P77438-01</b> K ← 048 115 147 35x54x10 A SL RD FPM <b>P77439-01</b> K → 059 103 051 D 96x117x10,5/12 A SL LD NBR <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30584-00</b> 026 198 025 A 8,5 mm Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X55170-01</b> 026 129 717 F 	<b>X03747-01</b> 026 129 589 A 4x  <b>X51169-01</b> 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM



AUDI							
Ltr.							
2,0 6A	101 kW (137 PS)	COUPE 80	03/90-07/92	<b>S31638-00</b> <b>D31638-00</b> 053 198 012 C <b>B31640-00</b> 037 198 011 E	⑫ ⑬	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm	<b>T50151-00</b> 053 103 385 (10x)
2,1 GV WJ WR	125-147 kW (170-200 PS)	QUATTRO Turbo 200 ↔85 B 900 158 ↔43 A 020 000	10/79-07/87	<b>S32689-00</b> <b>D32689-00</b> 035198012A <b>B30567-00</b> 034 198 011 C	⑫ ⑬	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm	<b>T07872-00</b> 049 103 385 (12x)
2,1 GV KG WJ WR	125-147 kW (170-200 PS)	QUATTRO Turbo 200 200 Turbo ↔85 B 900 159→ ↔43 B 000 001→	10/79-01/88	<b>S32872-00</b> <b>D32872-00</b> 035 198 012 K <b>B30567-00</b> 034 198 011 C	⑫ ⑬	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm	<b>T02641-00</b> 049 103 384 B (12x)
2,1 JY	134 kW (182 PS)	200 Turbo	09/83-01/88	<b>S32872-00</b> <b>D32872-00</b> 035 198 012 K <b>B30567-00</b> 034 198 011 C	⑫ ⑬	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm	<b>T04125-00</b> 049 103 384 B (10x)
2,1 KE KL WB WE	79-96 kW (107-131 PS)	COUPE 100	07/77-08/84	<b>S31200-00</b> <b>D31200-00</b> 035 198 012 L <b>B30567-00</b> 034 198 011 C	⑫ ⑬	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm	<b>T02641-00</b> 049 103 384 B (12x)



<b>V31196-00</b> 027 198 025	<b>N92850-00</b> 027 109 675 (16x) <b>P76532-00</b> 027 109 675	<b>X07866-01</b> 037 129 717 F	<b>X07855-01</b> 027 129 589 A	4x	<b>X04116-01</b> 026 103 609 D	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x
<b>V31597-00</b> 035 198 025 D	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	<b>X02658-01</b> 034 129 717 M	<b>X03747-01</b> 026 129 589 A <b>X81940-01</b> ✗ ⚠ 437 253 115	5x	<b>X02643-01</b> 054 103 609	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x
<b>V30567-00</b> ✗ 034 198 025 Kork <b>V31634-00</b> 034 198 025 D NBR	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	<b>X02658-01</b> 034 129 717 M	<b>X03747-01</b> 026 129 589 A <b>X81940-01</b> ✗ ⚠ 437 253 115	5x	<b>X02643-01</b> 054 103 609	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x
<b>V30567-00</b> ✗ 034 198 025 Kork <b>V31634-00</b> 034 198 025 D NBR	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	<b>X02658-01</b> 034 129 717 M	<b>X03747-01</b> 026 129 589 A <b>X51169-01</b> ✗ ⚠ 431 253 115 A <b>X52305-01</b> ✗ ⚠ 447 253 115	5x	<b>X02643-01</b> 054 103 609	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x
<b>V30567-00</b> ✗ 034 198 025 Kork <b>V31634-00</b> 034 198 025 D NBR	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	<b>X02658-01</b> 034 129 717 M	<b>X03747-01</b> 026 129 589 A	5x	<b>X02643-01</b> 054 103 609	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x



AUDI						
2,1 WC	100 kW (136 PS)	100 200	03/77-07/84	<b>S31507-00</b> (12) (13) → WC 139 411 <b>S31200-00</b> (12) (13) → WC 139 412→ <b>D31507-00</b> (12) 035 198 012 J → WC 139 411 <b>D31200-00</b> (12) 035 198 012 L → WC 139 412→ <b>B30567-00</b> (13) 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T07872-00</b> 049 103 385 (12x) → WC 139 411  <b>T02641-00</b> 049 103 384 B (12x) → WC 139 412→ 
2,2 AAN ABY ADU 3B	162-232 kW (220-315 PS)	A6 S6 COUPE S2 100 S4 200 Turbo 80 RS2 80 S2	03/89-12/97	<b>D36080-00</b> (12) 034 198 012 M <b>B36080-00</b> (13) 034 198 011 B	<b>H50998-00</b> 034 103 383 AD 82 Ø 1,65 mm MLS 	<b>T50127-00</b> 034 103 385 C (12x) 
2,2 HX HY JT KU KV KX PX	85-101 kW (115-137 PS)	COUPE 100 200 90	07/81-09/91	<b>S30567-00</b> (12) (13) <b>D30567-00</b> (12) 035 198 012 N <b>B30567-00</b> (13) 034 198 011 C	<b>H02641-00</b> 034 103 383 AA 82,7 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 
2,2 KF	96 kW (130-131 PS)	100	08/82-07/84	<b>S31507-00</b> (12) (13) <b>D31507-00</b> (12) 035 198 012 J <b>B30567-00</b> (13) 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T07872-00</b> 049 103 385 (12x) 
2,2 KF	96 kW (130-131 PS)	100	08/82-07/84	<b>S31200-00</b> (12) (13) <b>D31200-00</b> (12) 035 198 012 L <b>B30567-00</b> (13) 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 



<b>V31597-00</b> 035 198 025 D → WC 139 411  <b>V30567-00</b> ✗ 034 198 025 Kork → WC 139 412→  <b>V31634-00</b> 034 198 025 D NBR → WC 139 412→ 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x  <b>X51169-01</b> ⚠ 431 253 115 A → WC 139 411 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V36080-00</b> 034 198 025 F 	<b>N92111-00</b> 027 109 675 (20x) <b>P76532-00</b> 027 109 675 20x	<b>X58941-01</b> 034 129 717 K 	<b>X52304-01</b> 034 129 589 A  <b>X52305-01</b> ✗ ⚠ 447 253 115 	<b>X54131-01</b> 074 103 609 F 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30567-00</b> ✗ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x  <b>X51169-01</b> ⚠ 431 253 115 A 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V31597-00</b> 035 198 025 D 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x  <b>X51169-01</b> ⚠ 431 253 115 A 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30567-00</b> ✗ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM



AUDI



AUDI						
Ltr.						
2,2 KK KL WE	85-100 kW (115-136 PS)	80	10/80-07/84	<b>S31200-00</b> ⑫ ⑬ <b>D31200-00</b> ⑫ 035 198 012 L <b>B30567-00</b> ⑬ 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 
2,2 MB MC 1B 2B	121-147 kW (165-200 PS)	QUATTRO Turbo 100 Turbo 200 Turbo	09/83-12/91	<b>S31506-00</b> ⑫ ⑬ <b>D31506-00</b> ⑫ 035 198 012 P <b>B30567-00</b> ⑬ 034 198 011 C	<b>H02641-00</b> 034 103 383 AA 82,7 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 
2,2 WS	125 kW (170 PS)	200 → 43 A 020 000	08/80-12/81	<b>S32689-00</b> ⑫ ⑬ <b>D32689-00</b> ⑫ 035 198 012 A <b>B30567-00</b> ⑬ 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T07872-00</b> 049 103 385 (12x) 
2,2 WS	125 kW (170 PS)	200 → 43 B 000 001 →	08/80-12/81	<b>S32872-00</b> ⑫ ⑬ <b>D32872-00</b> ⑫ 035 198 012 K <b>B30567-00</b> ⑬ 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 
2,3 AAR NG	98-100 kW (133-136 PS)	A6 CABRIOLET COUPE 100 80 90 → 8A L 200 001 → → 8B L 014 001 → → 8A L 200 001 → → 8A L 200 001 →	01/87-12/96	<b>S31508-00</b> ⑫ ⑬ <b>D31508-00</b> ⑫ 034 198 012 L <b>B30567-00</b> ⑬ 034 198 011 C	<b>H50153-00</b> 054 103 383 G 83,5 Ø 1,82 mm 	<b>T02641-00</b> 049 103 384 B (12x) 

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>V30567-00</b> ✕ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x 	<b>X02643-01</b> 054 103 609 	<b>P76087-01</b> K ← 2x 068 103 085 E 32x47x10 A SL WD FPM <b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V30567-00</b> ✕ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x <b>X51169-01</b> ✕ ⚠ 431 253 115 A  <b>X52305-01</b> ✕ ⚠ 447 253 115 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V31597-00</b> 035 198 025 D 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x <b>X81940-01</b> ✕ ⚠ 437 253 115 	<b>X02643-01</b> 054 103 609 	<b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30567-00</b> ✕ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 034 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x <b>X81940-01</b> ✕ ⚠ 437 253 115 	<b>X02643-01</b> 054 103 609 	<b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>V30567-00</b> ✕ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X55159-01</b> 034 129 717 F  <b>X55158-01</b> ⑩ 034 129 717 E 	<b>X03747-01</b> 026 129 589 A 5x <b>X51169-01</b> ✕ ⚠ 431 253 115 A 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM



AUDI								
2,3 NF	100 kW (136 PS)	100 200		08/86-09/91	<b>D36393-00</b> ⑫ 034 198 012 K ↔→44 J 200 099 <b>D37038-00</b> ⑫ 034 198 012 E ↔→44 J 200 100→ ↔→44 L 072 000 <b>D31508-00</b> ⑫ 034 198 012 L ↔→44 L 072 001→ <b>B30567-00</b> ⑬ 034 198 011 C	<b>H50153-00</b> 054 103 383 G 83,5 Ø 1,82 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	
2,3 NG	98-100 kW (133-136 PS)	CABRIOLET COUPE 80 90		01/87-12/96	<b>D37038-00</b> 034 198 012 E <b>B30567-00</b> 034 198 011 C	<b>H50153-00</b> 054 103 383 G 83,5 Ø 1,82 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	
2,3 7A	123-125 kW (167-170 PS)	COUPE 90		06/88-12/96	<b>D37039-00</b> 054 198 012 A <b>B36080-00</b> ⑬ 034 198 011 B	<b>H50033-00</b> 054 103 383 J 	<b>T50127-00</b> 034 103 385 C (12x) 	
2,4 AAS 3D	60 kW (82 PS)	100 D		08/89-06/94	<b>S31637-00</b> ⑫ ⑬  <b>D31637-00</b> ⑫ 074 198 012  <b>B31637-00</b> ⑬ 074 198 011 A	<b>H02394-00</b> 074 103 383 C 1,53 mm 1 <b>H12394-10</b> 074 103 383 D 1,57 mm 2 <b>H22394-20</b> 074 103 383 E 81 Ø 1,61 mm 3	<b>T07896-00</b> 068 103 384 A (12x) 	
2,4 AGA AJG ALF ALW AML AMM APC APS APZ ARN	100-121 kW (136-165 PS)	A4 A6		02/97-12/05	<b>D32939-00</b> ⑫ 078 198 012 D <b>Z36190-00</b> ⑧ 2x 058 198 217	<b>H50999-00</b> 2x 078 103 383 K 83,5 Ø MLS 	<b>T50999-00</b> 078 103 385 K (14x) 	

⑫ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала



<b>V31634-00</b> 034 198 025 D ↔→44 L 072 000 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	<b>X55159-01</b> 034 129 717 F <b>X55158-01</b> 034 129 717 E 	<b>X03747-01</b> 026 129 589 A <b>X81409-01</b> 034 129 589 B <b>X51169-01</b> 431 253 115 A	3x 2x	<b>X02643-01</b> 054 103 609 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V30567-00</b> ✗ 034 198 025 Kork <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	<b>X55159-01</b> 034 129 717 F <b>X55158-01</b> ⑩ 034 129 717 E 	<b>X03747-01</b> 026 129 589 A <b>X51169-01</b> ✗ 431 253 115 A	10x	<b>X02643-01</b> 054 103 609 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V36080-00</b> 034 198 025 F 	<b>N93137-00</b> 027 109 675 (10x) <b>P76532-00</b> 027 109 675	<b>X58941-01</b> 034 129 717 K 	<b>X07855-01</b> 027 129 589 A 	2x 20x	<b>X54131-01</b> 074 103 609 F 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V31637-00</b> 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	<b>X56210-01</b> 074 129 717 	<b>X03747-01</b> 026 129 589 A 	10x	<b>X54131-01</b> 074 103 609 F 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V53716-00</b> 2x 078 198 025 	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675	<b>X58942-01</b> 2x 078 129 717 J 	<b>X52306-01</b> 2x 078 253 039 C 	30x	<b>X54463-01</b> 078 103 610 E  <b>70-31414-10</b> 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



AUDI									
Ltr.									
2,4	AGA AJG ALF ALW AML AMM APC APS APZ ARN	100-121 kW (136-165 PS)	A4 A6	8D W 180 001→ 4B W 150 001→	02/97-12/05	<b>D37040-00</b> 078 198 012 G +068 103 085 E (2x) <b>Z36190-00</b> ⑧ 058 198 217	<b>H50999-00</b> 078 103 383 K 83,5 Ø MLS	2x 	<b>T50999-00</b> 078 103 385 K (16x) 
2,4	ARJ ASM BDV	100-125 kW (136-170 PS)	A4 A6		02/97-12/05	<b>D37040-00</b> 078 198 012 G +068 103 085 E (2x) <b>Z36190-00</b> ⑧ 058 198 217	<b>H50999-00</b> 078 103 383 K 83,5 Ø MLS	2x 	<b>T50999-00</b> 078 103 385 K (16x) 
2,4	BDW	130 kW (177 PS)	A6		05/04-10/08	<b>D37053-00</b> ⑫ <b>B37053-00</b> ⑬	<b>H80728-00</b> 06E 103 148 P 82,5 Ø MLS Zyl. 1 - 3		<b>T80728-00</b> 06E 103 385 (8x) 
							<b>H80729-00</b> 06E 103 149 P 82,5 Ø MLS Zyl. 4 - 6		
2,5	AAT ABP AEL 1T	84-103 kW (114-140 PS)	A6 TDI 100 TDI		01/90-12/97	<b>D31639-00</b> ⑫ 046 198 012 A 	<b>H02396-00</b> 074 103 383 AJ 1,53 mm MLS <b>H12396-10</b> 074 103 383 AH 1,57 mm MLS <b>H22396-20</b> 074 103 383 AG 82 Ø 1,61 mm MLS	1 2 3	<b>T07896-00</b> 068 103 384 A (12x) 

⑧ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала



<b>V53716-00</b> 078 198 025 	2x	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675	30x	<b>X58942-01</b> 078 129 717 J 	2x	<b>X52308-01</b> 078 253 039 G 	2x	<b>X54463-01</b> 078 103 610 E 	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	4x
<b>V53716-00</b> 078 198 025 	2x	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675	30x	<b>X58942-01</b> 078 129 717 J 	2x	<b>X52308-01</b> 078 253 039 G 	2x	<b>X54463-01</b> 078 103 610 E 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	4x
<b>X83122-01</b> 06E 103 183 G Zyl. 4 - 6 NBR 	2x	<b>N92993-00</b> 036 109 675 (12x) <b>P76662-00</b> 036 109 675	24x	<b>X89276-01</b> 06E 129 717 B 	6x	<b>X81442-01</b> 06E 253 039 C 	2x	<b>70-31414-10</b> 	<b>P77452-01 K ←</b> 06E 103 153 E PTFE <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM	
<b>X83123-01</b> 06E 103 484 G Zyl. 1 - 3 NBR 										
<b>X53063-01</b> 046 103 483 A NBR 		<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	10x	<b>X56210-01</b> 074 129 717 		<b>X03747-01</b> 026 129 589 A 	5x	<b>X02643-01</b> 054 103 609 	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x



AUDI

AUDI						
Ltr.						
2,5 AFB AKE AKN	110-132 kW (150-180 PS) ALLROAD TDI A4 TDI A6 TDI A8 TDI	01/97-08/05	1	<b>D32940-00</b> ⑫  <b>B32940-00</b> ⑬ 	<b>H03136-00</b> 2x 059 103 383 BQ 1,1 mm 1 MLS <b>H13136-10</b> 2x 059 103 383 BR 1,15 mm 2 MLS <b>H23136-20</b> 2x 059 103 383 BS 79 Ø 1,2 mm 3 MLS 	<b>T03136-00</b> 059 103 384 (16x) 
2,5 AYM BFC	114-120 kW (155-163 PS) A4 TDI A6 TDI	08/01-12/05		<b>D32940-00</b> ⑫  <b>B32940-00</b> ⑬ 	<b>H03136-00</b> 2x 059 103 383 BQ 1,1 mm 1 MLS <b>H13136-10</b> 2x 059 103 383 BR 1,15 mm 2 MLS <b>H23136-20</b> 2x 059 103 383 BS 79 Ø 1,2 mm 3 MLS 	<b>T03136-00</b> 059 103 384 (16x) 
2,5 BAU BCZ BDG BDH	120-132 kW (163-180 PS) ALLROAD TDI A4 TDI A6 TDI	02/00-05/06		<b>D32940-00</b> ⑫  <b>B32940-00</b> ⑬ 	<b>H03136-00</b> 2x 059 103 383 BQ 1,1 mm 1 MLS <b>H13136-10</b> 2x 059 103 383 BR 1,15 mm 2 MLS <b>H23136-20</b> 2x 059 103 383 BS 79 Ø 1,2 mm 3 MLS 	<b>T80448-00</b> 057 103 384 A (16x) 
2,5 CEPA <b>[NEW]</b>	250 kW (340 PS) TT TFSI	07/09→		<b>D40720-00</b> ⑫	<b>H40720-00</b> 07K 103 383 K 83,3 Ø MLS 	<b>T80754-00</b> 06D 103 385 D (12x) 

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



<b>V32940-00</b> 2x 059 198 025 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>X58943-01</b> 2x 059 129 717 G 	<b>X52307-01</b> 6x 059 253 039 B <b>X52930-01</b>	<b>X54465-01</b> 059 103 609 J  <b>70-31414-10</b>  <b>X54464-01</b> ⑪ 059 103 610 B 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P77440-01</b> K → 070 103 051 A 85x105x12 A SL LD PTFE <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V32940-00</b> 2x 059 198 025 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>X58943-01</b> 2x 059 129 717 G 	<b>X52307-01</b> 6x 059 253 039 B <b>X52930-01</b>	<b>70-31414-10</b> 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V32940-00</b> 2x 059 198 025 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>X58943-01</b> 2x 059 129 717 G 	<b>X52307-01</b> 6x 059 253 039 B <b>X52930-01</b>	<b>70-31414-10</b> 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>X59948-01</b> 07K 103 483 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 20x 036 109 675	<b>X59884-01</b> 07K 133 379 A 	<b>X59874-01</b> 07K 253 039 D 	<b>70-31414-10</b> 	<b>P77440-01</b> K → 070 103 051 A 85x105x12 A SL LD PTFE ⑪ →08/10 <b>P77766-01</b> K → 059 103 051 H 85x105x8 A SL LD FPM ⑪ 09/10→



AUDI						
Ltr.						
2,5 CEPA CEPB <b>[NEW]</b>	250-265 kW (340-360 PS) RS3 TT TFSI	01/11→	<b>D40720-00</b> <sup>(12)</sup>	<b>H40720-00</b> 07K 103 383 K 83,3 Ø MLS 	<b>T80754-00</b> 06D 103 385 D (12x) 	
2,5 CPAA <b>[NEW]</b>	150 kW (204 PS) A8 TFSI	07/12→	<b>D40695-01</b> <sup>(12)</sup> <b>B38111-00</b> <sup>(13) (35)</sup>	<b>H40695-00</b> 06E 103 148 AJ 81 Ø MLS Zyl. 1-3  <b>H40696-00</b> 06E 103 149 AJ 81 Ø MLS Zyl. 4-6 	<b>T40707-00</b> 2x WHT 005 739 (8x) 	
2,6 ABC ACZ	102-110 kW (139-150 PS) A4	01/95-09/01	<b>D32235-00</b> 078 198 012 ↔8D T 076 000 <b>D36088-00</b> 078 198 012 A ↔8D T 076 001→ <b>B32883-00</b> <sup>(13)</sup> 078 198 011 A	<b>H50471-00</b> 2x 078 103 383 E 84 Ø 	<b>T50471-00</b> 2x 078 103 385 J (8x) 	

<sup>(11)</sup> junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



<b>X59948-01</b> 07K 103 483 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x	<b>X59884-01</b> 07K 133 379 A 	<b>X59874-01</b> 07K 253 039 D 	<b>70-31414-10</b> 	<b>P77766-01 K</b> → 059 103 051 H 85x105x8 A SL LD FPM
<b>X83361-01</b> 06E 103 484 N Zyl. 1-3  <b>X83362-01</b> 06E 103 483 P Zyl. 4-6 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675 24x	<b>M38701-00</b> 06E 198 717 	<b>X81442-01</b> 2x 06E 253 039 C 	<b>70-31414-10</b> 	<b>P77362-01 K</b> ← 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P77452-01 K</b> → 06E 103 153 E PTFE
<b>X53719-01</b> 2x 078 103 483 L ↔8D T 076 000  <b>X53267-01</b> 2x 078 103 483 J ↔8D T 076 001→ 	<b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675 12x	<b>X57669-01</b> 2x 078 129 717 A  <b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 2x 078 129 589 	<b>X54440-01</b> 078 103 609 F  <b>X57837-01</b> <sup>(11)</sup> 078 103 609 G 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

<sup>(35)</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



AUDI							
Ltr.							
2,6 ABC ACZ	102-110 kW (139-150 PS)	A6	08/94-02/97	<b>D32235-00</b> 078 198 012 ↔→4A T 029 512 <b>D36088-00</b> 078 198 012 A ↔→4A T 029 513→ <b>B32235-00</b> ⑬ 078 198 011 ↔→4A S 026 714 <b>B32883-00</b> ⑬ 078 198 011 A ↔→4A S 026 715→	<b>H50471-00</b> 078 103 383 E 84 Ø 	<b>T50471-00</b> 078 103 385 J (8x) 	2x 2x

<b>X53719-01</b> 078 103 483 L ↔→4A T 029 512 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 12x 026 109 675 ↔→4A S 026 714 <b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 12x 027 109 675 ↔→4A S 026 715→	<b>X57669-01</b> 078 129 717 A 	<b>X51635-01</b> 078 129 589 	<b>X54441-01</b> 078 103 609 E ↔→4A S 026 714 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>X53267-01</b> 078 103 483 J ↔→4A T 029 513→ 		<b>X57662-01</b> 078 129 717 C 		<b>X54440-01</b> 078 103 609 F ↔→4A S 026 715→ 	
				<b>X58824-01</b> ⑪ 078 103 610 A ↔→4A S 026 714 	
				<b>X57837-01</b> ⑪ 078 103 609 G ↔→4A S 026 715→ 	

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



AUDI																	
Ltr.																	
2,6 ABC ACZ	102-110 kW (139-150 PS)	CABRIOLET	08/94-02/97	<b>D32235-00</b> 078 198 012 ↔8G T 004 318 <b>D36088-00</b> 078 198 012 A ↔8G T 004 319→ <b>B32235-00</b> ⑬ 078 198 011 ↔8G S 001 302 <b>B32883-00</b> ⑬ 078 198 011 A ↔8G S 001 303→	<b>H50471-00</b> 078 103 383 E 84 Ø 	<b>T50471-00</b> 078 103 385 J (8x) 	<b>X53719-01</b> 078 103 483 L ↔8G T 004 318 	<b>X53267-01</b> 078 103 483 J ↔8G T 004 319→ 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 026 109 675 ↔8G S 001 302 <b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675 ↔8G S 001 303→	<b>X57669-01</b> 078 129 717 A 	<b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 078 129 589 	<b>X54441-01</b> 078 103 609 E ↔8G S 001 302 	<b>X54440-01</b> 078 103 609 F ↔8G S 001 303→ 	<b>X58824-01</b> ⑪ 078 103 610 A ↔8G S 001 302 	<b>X57837-01</b> ⑪ 078 103 609 G ↔8G S 001 303→ 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



AUDI



AUDI						
Ltr.						
2,6 ABC ACZ	102-110 kW (139-150 PS) COUPE	08/92-02/96	<b>D32235-00</b> 078 198 012 ↔8B T 002 000 <b>D36088-00</b> 078 198 012 A ↔8B T 002 001→ <b>B32235-00</b> ⑬ 078 198 011 ↔8B S 000 544 <b>B32883-00</b> ⑬ 078 198 011 A ↔8B S 000 545→	<b>H50471-00</b> 2x 078 103 383 E 84 Ø 	<b>T50471-00</b> 2x 078 103 385 J (8x) 	
2,6 ABC ACZ	102-110 kW (139-150 PS) 100	03/92-06/94	<b>D32235-00</b> 078 198 012 <b>B32235-00</b> ⑬ 078 198 011	<b>H50471-00</b> 2x 078 103 383 E 84 Ø 	<b>T50471-00</b> 2x 078 103 385 J (8x) 	

⑬ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



<b>X53719-01</b> 2x 078 103 483 L ↔8B T 002 000 	<b>N91210-00</b> 12x 026 109 675 (12x) <b>P76531-00</b> 026 109 675 ↔8B S 000 544 <b>N92450-00</b> 12x 027 109 675 (12x) <b>P76532-00</b> 027 109 675 ↔8B S 000 545→	<b>X57669-01</b> 2x 078 129 717 A  <b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 2x 078 129 589 	<b>X54441-01</b> 078 103 609 E ↔8B S 000 544  <b>X58824-01</b> ⑪ 078 103 610 A ↔8B S 000 544  <b>X57837-01</b> ⑪ 078 103 609 G ↔8B S 000 545→ 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X53719-01</b> 2x 078 103 483 L 	<b>N91210-00</b> 12x 026 109 675 (12x) <b>P76531-00</b> 026 109 675	<b>X57669-01</b> 2x 078 129 717 A  <b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 2x 078 129 589 	<b>X54441-01</b> 078 103 609 E  <b>X58824-01</b> ⑪ 078 103 610 A 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI



AUDI						
Ltr.						
2,6 ABC ACZ	102-110 kW (139-150 PS)	80	06/92-01/96	<b>D32235-00</b> 078 198 012 <b>B32235-00</b> ⑬ 078 198 011 →8C S 025 820 <b>B32883-00</b> ⑬ 078 198 011 A →8C S 025 821→	<b>H50471-00</b> 2x 078 103 383 E 84 Ø 	<b>T50471-00</b> 2x 078 103 385 J (8x) 
2,7 AGB AJK APB ARE AZA AZB BEL BES	169-195 kW (230-265 PS)	ALLROAD ALLROAD T A4 S4 A4 TURBO A6 T	09/97-08/05	<b>D32941-00</b> 2x 078 198 012 E +068 103 085 E (2x) <b>Z36190-00</b> ⑧ 2x 058 198 217	<b>H50999-00</b> 2x 078 103 383 K 83,5 Ø MLS 	<b>T50999-00</b> 2x 078 103 385 K (16x) 
2,7 ASJ AZR	280 kW (380 PS)	A4 RS4	05/00-09/01	<b>Z36190-00</b> ⑧ 2x 058 198 217	<b>H80592-00</b> 2x 078 103 383 Q 82 Ø MLS 	<b>T50999-00</b> 2x 078 103 385 K (16x) 

⑧ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала



<b>X53719-01</b> 2x 078 103 483 L 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 12x 026 109 675 →8C S 025 820 <b>N92450-00</b> 12x 027 109 675 (12x) <b>P76532-00</b> 12x 027 109 675 →8C S 025 821→	<b>X57669-01</b> 2x 078 129 717 A  <b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 2x 078 129 589 	<b>X54441-01</b> 078 103 609 E →8C S 025 820  <b>X54440-01</b> 078 103 609 F →8C S 025 821→  <b>X58824-01</b> ⑪ 078 103 610 A →8C S 025 820  <b>X57837-01</b> ⑪ 078 103 609 G →8C S 025 821→ 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V53716-00</b> 2x 078 198 025 	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 30x 036 109 675	<b>X58944-01</b> 2x 078 129 717 N 	<b>X52308-01</b> 2x 078 253 039 G  <b>X81688-01</b> 2x 8D0 253 115 F 	<b>X54463-01</b> 078 103 610 E  <b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM
<b>V53716-00</b> 2x 078 198 025 	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 30x 036 109 675	<b>X58944-01</b> 2x 078 129 717 N 	<b>X52308-01</b> 2x 078 253 039 G  <b>X81688-01</b> 2x 8D0 253 115 F 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 N</b> 3x 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77182-01 N</b> 028 103 086 32x47x10 A SL LD PTFE

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



AUDI

AUDI													
Ltr.													
2,7 BPP BSG	120-132 kW (163-180 PS) A4 TDI A6 TDI	11/04-08/11	<b>D37054-00</b> ⑫ Zyl. 1 - 3  <b>D37055-00</b> ⑫ Zyl. 4 - 6  <b>B37054-00</b> ⑬	<b>H01841-00</b> 059 103 383 CM 1,1 mm 1 MLS Zyl. 1 - 3 <b>H11841-10</b> 059 103 383 CN 1,15 mm 2 MLS Zyl. 1 - 3 <b>H21841-20</b> 059 103 383 CP 1,2 mm 3 MLS Zyl. 1 - 3  <b>H01842-00</b> 059 103 383 CQ 1,1 mm 1 MLS Zyl. 4 - 6 <b>H11842-10</b> 059 103 383 CR 1,15 mm 2 MLS Zyl. 4 - 6 <b>H21842-20</b> 059 103 383 CS 1,2 mm 3 MLS Zyl. 4 - 6 	<b>T80448-00</b> 057 103 384 A (16x) 	<b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR  <b>X83106-01</b> 059 103 483 M Zyl. 4 - 6 NBR 	<b>N92993-00</b> 2x 036 109 675 (12x) <b>P76662-00</b> 24x 036 109 675	<b>X89125-01</b> 2x 059 129 717 J 	<b>X81941-01</b> 2x 059 253 039 D 	<b>70-31414-10</b> 	<b>P77441-01 K ←</b> 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM		
			⑫  ⑬	L  R	←  →	K	N	(A)					

AUDI

AUDI							
Ltr.							
2,7	CAMA CAMB CANA CANB CANC CAND CGKA CGKB	120-140 kW (163-190 PS)	A4 TDI A5 TDI A6 TDI	11/04→	<p><b>D37055-01</b> ⑫ Zyl. 4 - 6</p> <p></p> <p><b>D38060-00</b> ⑫ Zyl. 1-3</p> <p></p> <p><b>B38110-00</b> ⑬</p>	<p><b>H01404-00</b> 059 103 383 EP 84 Ø 1,1 mm 1 □ MLS Zyl. 4-6</p> <p><b>H11404-10</b> 059 103 383 EQ 84 Ø 1,15 mm 2 □ MLS Zyl. 4-6</p> <p><b>H21404-20</b> 059 103 383 ER 84 Ø 1,2 mm 3 □ MLS Zyl. 4-6</p> <p></p> <p><b>H01406-00</b> 059 103 383 ES 84 Ø 1,1 mm 1 □ MLS Zyl. 1-3</p> <p><b>H11406-10</b> 059 103 383 ET 84 Ø 1,15 mm 2 □ MLS Zyl. 1-3</p> <p><b>H21406-20</b> 059 103 383 FA 84 Ø 1,2 mm 3 □ MLS Zyl. 1-3</p> <p></p>	<p><b>T80448-00</b> 057 103 384 A (16x)</p> <p></p>
2,8	AAH	102-110 kW (139-150 PS)	A4	01/95-09/01	<p><b>D32235-00</b> 078 198 012 ↔→8D T 076 000</p> <p><b>D36088-00</b> 078 198 012 A ↔8D T 076 001→</p> <p><b>B32883-00</b> ⑬ 078 198 011 A</p>	<p><b>H50471-00</b> 2x 078 103 383 E 84 Ø</p> <p></p>	<p><b>T50471-00</b> 2x 078 103 385 J (8x)</p> <p></p>

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



<p><b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR</p> <p></p> <p><b>X83106-01</b> 059 103 483 M Zyl. 4 - 6 NBR</p> <p></p>	<p><b>N92830-00</b> 036 109 675 (24x)</p> <p><b>P76662-00</b> 24x 036 109 675</p>	<p><b>X89125-01</b> 2x 059 129 717 J</p> <p></p>	<p><b>X81941-01</b> 2x 059 253 039 D</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>P77441-01 K ←</b> 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>
<p><b>X53719-01</b> 2x 078 103 483 L ↔→8D T 076 000</p> <p></p> <p><b>X53267-01</b> 2x 078 103 483 J ↔8D T 076 001→</p> <p></p>	<p><b>N92450-00</b> 027 109 675 (12x)</p> <p><b>P76532-00</b> 12x 027 109 675</p>	<p><b>X57669-01</b> 2x 078 129 717 A</p> <p></p> <p><b>X57662-01</b> 078 129 717 C</p> <p></p>	<p><b>X51635-01</b> 2x 078 129 589</p> <p></p>	<p><b>X54440-01</b> 078 103 609 F</p> <p></p> <p><b>X57837-01</b> ⑪ 078 103 609 G</p> <p></p>	<p><b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>



AUDI																	
Ltr.																	
2,8 AAH	102-110 kW (139-150 PS)	CABRIOLET	08/94-02/97	<b>D32235-00</b> 078 198 012 ↔8G T 004 318 <b>D36088-00</b> 078 198 012 A ↔8G T 004 319→ <b>B32235-00</b> ⑬ 078 198 011 ↔8G S 001 302 <b>B32883-00</b> ⑬ 078 198 011 A ↔8G S 001 303→	<b>H50471-00</b> 078 103 383 E 84 Ø 	<b>T50471-00</b> 078 103 385 J (8x) 	<b>X53719-01</b> 078 103 483 L ↔8G T 004 318 	<b>X53267-01</b> 078 103 483 J ↔8G T 004 319→ 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 026 109 675 ↔8G S 001 302 <b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675 ↔8G S 001 303→	<b>X57669-01</b> 078 129 717 A 	<b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 078 129 589 	<b>X54441-01</b> 078 103 609 E ↔8G S 001 302 	<b>X54440-01</b> 078 103 609 F ↔8G S 001 303→ 	<b>X58824-01</b> ⑪ 078 103 610 A ↔8G S 001 302 	<b>X57837-01</b> ⑪ 078 103 609 G ↔8G S 001 303→ 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



AUDI

AUDI						
Ltr.						
2,8 AAH	102-110 kW (139-150 PS)	COUPE	08/92-02/96	<b>D32235-00</b> 078 198 012 ↔8B T 002 000 <b>D36088-00</b> 078 198 012 A ↔8B T 002 001→ <b>B32235-00</b> ⑬ 078 198 011 ↔8B S 000 544 <b>B32883-00</b> ⑬ 078 198 011 A ↔8B S 000 545→	<b>H50471-00</b> 2x 078 103 383 E 84 Ø 	<b>T50471-00</b> 2x 078 103 385 J (8x) 
2,8 AAH	102-110 kW (139-150 PS)	100	03/92-06/94	<b>D32235-00</b> 078 198 012 <b>B32235-00</b> ⑬ 078 198 011	<b>H50471-00</b> 2x 078 103 383 E 84 Ø 	<b>T50471-00</b> 2x 078 103 385 J (8x) 

⑬ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



<b>X53719-01</b> 2x 078 103 483 L ↔8B T 002 000 	<b>N91210-00</b> 12x 026 109 675 (12x) <b>P76531-00</b> 026 109 675 ↔8B S 000 544 <b>N92450-00</b> 12x 027 109 675 (12x) <b>P76532-00</b> 027 109 675 ↔8B S 000 545→	<b>X57669-01</b> 2x 078 129 717 A  <b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 2x 078 129 589 	<b>X54441-01</b> 078 103 609 E ↔8B S 000 544  <b>X58824-01</b> ⑪ 078 103 610 A ↔8B S 000 544  <b>X57837-01</b> ⑪ 078 103 609 G ↔8B S 000 545→ 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
<b>X53719-01</b> 2x 078 103 483 L 	<b>N91210-00</b> 12x 026 109 675 (12x) <b>P76531-00</b> 026 109 675	<b>X57669-01</b> 2x 078 129 717 A  <b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 2x 078 129 589 	<b>X54441-01</b> 078 103 609 E  <b>X58824-01</b> ⑪ 078 103 610 A 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM



<b>AUDI</b>						
Ltr.			1			
2,8 AAH	102-110 kW (139-150 PS)	80	06/92-01/96	<b>D32235-00</b> 078 198 012 <b>B32235-00</b> ⑬ 078 198 011 ↔8C S 025 820 <b>B32883-00</b> ⑬ 078 198 011 A ↔8C S 025 821→	<b>H50471-00</b> 078 103 383 E 84 Ø 	<b>T50471-00</b> 078 103 385 J (8x) 

<b>X53719-01</b> 078 103 483 L 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 12x 026 109 675 ↔8C S 025 820 <b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 12x 027 109 675 ↔8C S 025 821→	<b>X57669-01</b> 078 129 717 A  <b>X57662-01</b> 078 129 717 C 	<b>X51635-01</b> 078 129 589 	<b>X54441-01</b> 078 103 609 E ↔8C S 025 820  <b>X54440-01</b> 078 103 609 F ↔8C S 025 821→  <b>X58824-01</b> ⑪ 078 103 610 A ↔8C S 025 820  <b>X57837-01</b> ⑪ 078 103 609 G ↔8C S 025 821→ 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



AUDI																
Ltr.																
2,8 AAH AEJ	102-110 kW (139-150 PS) A6	08/94-02/97														
		1	<b>D32235-00</b> 078 198 012 ↔ →4A T 029 512 <b>D36088-00</b> 078 198 012 A ↔ →4A T 029 513→ <b>B32235-00</b> ⑬ 078 198 011 ↔ →4A S 026 714 <b>B32883-00</b> ⑬ 078 198 011 A ↔ →4A S 026 715→	<b>H50471-00</b> 078 103 383 E 84 Ø 	2x <b>T50471-00</b> 078 103 385 J (8x) 	2x <b>X53719-01</b> 078 103 483 L ↔ →4A T 029 512 	2x <b>X53267-01</b> 078 103 483 J ↔ →4A T 029 513→ 	12x <b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 026 109 675 ↔ →4A S 026 714 <b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675 ↔ →4A S 026 715→	2x <b>X57669-01</b> 078 129 717 A 	2x <b>X57662-01</b> 078 129 717 C 	2x <b>X51635-01</b> 078 129 589 	2x <b>X54441-01</b> 078 103 609 E ↔ →4A S 026 714 	2x <b>X54440-01</b> 078 103 609 F ↔ →4A S 026 715→ 	2x <b>X58824-01</b> ⑪ 078 103 610 A ↔ →4A S 026 714 	2x <b>X57837-01</b> ⑪ 078 103 609 G ↔ →4A S 026 715→ 	<b>P76096-01</b> K ↔ 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



AUDI

AUDI							
Ltr.							
2.8 AAH AEJ	102-110 kW (139-150 PS)	A8	08/94-02/97	<b>D32235-00</b> 078 198 012 ↔→4D T 003 800 <b>D36088-00</b> 078 198 012 A ↔→4D T 003 801→ <b>B32235-00</b> ⑬ 078 198 011 ↔→4D S 000 496 <b>B32883-00</b> ⑬ 078 198 011 A ↔→4D S 000 497→	<b>H50471-00</b> 2x 078 103 383 E 84 Ø 	<b>T50471-00</b> 2x 078 103 385 J (8x) 	
2.8 AGE ALG AMX APR AQD ATX	132-142 kW (180-193 PS)	A4 A6 A8	04/96-01/05	<b>D36714-00</b> 078 198 012 B <b>Z36190-00</b> ⑧ 058 198 217	<b>H80491-00</b> 2x 078 103 383 L 83,5 Ø MLS 	<b>T50999-00</b> 2x 078 103 385 K (16x) 	
2.8 AGE ALG AMX APR AQD ATX	132-142 kW (180-193 PS)	A4 A6 A8	04/96-01/05	<b>D36715-00</b> 078 198 012 F +068 103 085 E (2x) <b>Z36190-00</b> ⑧ 058 198 217	<b>H80491-00</b> 2x 078 103 383 L 83,5 Ø MLS 	<b>T50999-00</b> 2x 078 103 385 K (16x) 	
2.8 BBG	140 kW (190 PS)	A6	07/99-01/05	<b>D36715-00</b> 078 198 012 F +068 103 085 E (2x) <b>Z36190-00</b> ⑧ 058 198 217	<b>H80491-00</b> 2x 078 103 383 L 83,5 Ø MLS 	<b>T50999-00</b> 2x 078 103 385 K (16x) 	

⑧ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала



	<b>X53719-01</b> 2x 078 103 483 L ↔→4D T 003 800 	<b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675 12x	<b>X57669-01</b> 2x 078 129 717 A 	<b>X51635-01</b> 2x 078 129 589 	<b>X54441-01</b> 078 103 609 E ↔→4D S 000 496 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9/11 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
	<b>X53267-01</b> 2x 078 103 483 J ↔→4D T 003 801→ 		<b>X57662-01</b> 078 129 717 C 		<b>X54440-01</b> 078 103 609 F ↔→4D S 000 497→ 	
					<b>X58824-01</b> ⑪ 078 103 610 A ↔→4D S 000 496 	
					<b>X57837-01</b> ⑪ 078 103 609 G ↔→4D S 000 497→ 	
	<b>V53716-00</b> 2x 078 198 025 	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675 30x	<b>X58942-01</b> 2x 078 129 717 J 	<b>X52306-01</b> 2x 078 253 039 C 	<b>X54463-01</b> 078 103 610 E 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM 4x
	<b>V53716-00</b> 2x 078 198 025 	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675 30x	<b>X58942-01</b> 2x 078 129 717 J 	<b>X52308-01</b> 2x 078 253 039 G 	<b>X54463-01</b> 078 103 610 E 	<b>P76096-01 K</b> ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM 4x
	<b>V53716-00</b> 2x 078 198 025 	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675 30x	<b>X58942-01</b> 2x 078 129 717 J 	<b>X52308-01</b> 2x 078 253 039 G 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM 4x

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



AUDI



AUDI						
Ltr.						
2,8 BDX CCDA CCEA CJBA	140-170 kW (190-231 PS) A6 FSI A8 FSI	11/06→		<b>D80730-00</b> ⑫ <b>B37053-00</b> ⑬	<b>H80730-00</b> 06E 103 148 M 86 Ø MLS Zyl. 1 - 3  <b>H80731-00</b> 06E 103 149 M 86 Ø MLS Zyl. 4 - 6 	<b>T80728-00</b> 2x 06E 103 385 (8x) 
2,8 CHVA CNYA <b>[NEW]</b>	150 kW (204 PS) A6 FSI A7 FSI	10/10→		<b>D80730-00</b> ⑫ ① →05/12 <b>D40702-00</b> ⑫ ① 06/12→ <b>B37053-00</b> ⑬	<b>H80730-00</b> 06E 103 148 M 86 Ø MLS Zyl. 1 - 3 ① →05/12  <b>H80731-00</b> 06E 103 149 M 86 Ø MLS Zyl. 4 - 6 ① →05/12  <b>H40702-00</b> 06E 103 148 AN 85 Ø MLS Zyl. 1-3 ① 06/12→  <b>H40703-00</b> 06E 103 149 AN 85 Ø MLS Zyl. 4-6 ① 06/12→ 	<b>T80728-00</b> 2x 06E 103 385 (8x) ① →06/11  <b>T40707-00</b> 2x WHT 005 739 (8x) ① 07/11→ 



<b>X83361-01</b> 06E 103 484 N Zyl. 1-3  <b>X83362-01</b> 06E 103 483 P Zyl. 4-6 	<b>N92993-00</b> 2x 036 109 675 (12x) <b>P76662-00</b> 24x 036 109 675	<b>X89276-01</b> 6x 06E 129 717 B 	<b>X81442-01</b> 2x 06E 253 039 C 	<b>70-31414-10</b> 	<b>P77452-01 K</b> ← 06E 103 153 E PTFE <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM
<b>X83361-01</b> 06E 103 484 N Zyl. 1-3  <b>X83362-01</b> 06E 103 483 P Zyl. 4-6 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>M38701-00</b> 06E 198 717 	<b>X81442-01</b> 2x 06E 253 039 C 	<b>70-31414-10</b> 	<b>P77452-01 K</b> ← 06E 103 153 E PTFE <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM



AUDI						
Ltr.						
3,0 ASB BKN BMK BNG BUG BUN	150-171 kW (204-233 PS)	A3 TDI A4 TDI A6 TDI A8 TDI Q7 TDI	08/03-08/11	<b>D37054-00</b> ⑫ Zyl. 1 - 3  <b>D37055-00</b> ⑫ Zyl. 4 - 6  <b>B37054-00</b> ⑬	<b>H01841-00</b> 059 103 383 CM 1,1 mm 1 MLS Zyl. 1 - 3 <b>H11841-10</b> 059 103 383 CN 1,15 mm 2 MLS Zyl. 1 - 3 <b>H21841-20</b> 059 103 383 CP 1,2 mm 3 MLS Zyl. 1 - 3  <b>H01842-00</b> 059 103 383 CQ 1,1 mm 1 MLS Zyl. 4 - 6 <b>H11842-10</b> 059 103 383 CR 1,15 mm 2 MLS Zyl. 4 - 6 <b>H21842-20</b> 059 103 383 CS 1,2 mm 3 MLS Zyl. 4 - 6 	<b>T80448-00</b> 057 103 384 A (16x) 
3,0 ASN AVK BBJ	160-162 kW (218-220 PS)	A4 A6 A8	11/00-07/06	<b>D36781-00</b> ⑫ 2x	<b>H80446-00</b> 2x 06C 103 383 H 83 Ø 1,2 mm MLS 	<b>T80446-00</b> 2x 06B 103 385 (8x) 



<b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR  <b>X83106-01</b> 059 103 483 M Zyl. 4 - 6 NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>N92993-00</b> 2x 036 109 675 (12x) <b>P76662-00</b> 24x 036 109 675	<b>X89125-01</b> 2x 059 129 717 J 	<b>X81941-01</b> 2x 059 253 039 D 	<b>70-31414-10</b> 	<b>P77441-01 K</b> ← 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X83107-01</b> 2x 06C 103 483 J NBR 	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 30x 036 109 675	<b>X58942-01</b> 2x 078 129 717 J  <b>X59571-01</b> 2x 078 129 717 P 	<b>X52308-01</b> 2x 078 253 039 G 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77442-01 N</b> 4x 06C 103 085 42x55x7 RD PTFE



AUDI						
Ltr.						
3,0 CAJA CAKA CCAA CCBA CGWA CGWB CGWC CGWD CGXB CGXC CHMA CJWE CMDA CMUA CTUB CTUC CTUD CTVA CTWA CTWB CTXA	200-260 kW (272-354 PS)	A4 S4 A4 TFSI A5 TFSI A6 TFSI A7 TFSI A8 TFSI Q5 TFSI Q7 TFSI S4 S5	10/08→	<b>D38069-00</b> ⑫ Zyl. 1-3 <b>D38070-00</b> ⑫ Zyl. 4-6 <b>B38111-00</b> ⑬ ⑮	<b>H40461-00</b> 06E 103 148 AD 85,2 Ø MLS Zyl. 1-3  <b>H40462-00</b> 06E 103 149 AD 85,2 Ø MLS Zyl. 4-6 	<b>T80728-00</b> 2x 06E 103 385 (8x) 
3,0 CAPA	176 kW (240 PS)	A4 TDI A5 TDI	06/07→	<b>D37055-01</b> ⑫ Zyl. 4 - 6  <b>D38060-00</b> ⑫ Zyl. 1-3  <b>B38110-00</b> ⑬	<b>H01841-00</b> 059 103 383 CM 1,1 mm 1 MLS Zyl. 1 - 3 <b>H11841-10</b> 059 103 383 CN 1,15 mm 2 MLS Zyl. 1 - 3 <b>H21841-20</b> 059 103 383 CP 1,2 mm 3 MLS Zyl. 1 - 3  <b>H01842-00</b> 059 103 383 CQ 1,1 mm 1 MLS Zyl. 4 - 6 <b>H11842-10</b> 059 103 383 CR 1,15 mm 2 MLS Zyl. 4 - 6 <b>H21842-20</b> 059 103 383 CS 1,2 mm 3 MLS Zyl. 4 - 6 	<b>T80448-00</b> 057 103 384 A (16x) 

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83361-01</b> 06E 103 484 N Zyl. 1-3  <b>X83362-01</b> 06E 103 483 P Zyl. 4-6 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>X59476-01</b> 6x 079 129 717 D  <b>X89852-01</b> ⑩ 6x 079 129 717 B 	<b>X81442-01</b> 2x 06E 253 039 C 	<b>70-31414-10</b> 	<b>P77452-01 K ←</b> ⑮ 06E 103 153 E PTFE <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM
<b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR  <b>X83106-01</b> 059 103 483 M Zyl. 4 - 6 NBR 	<b>N92993-00</b> 2x 036 109 675 (12x) <b>P76662-00</b> 24x 036 109 675	<b>X89125-01</b> 2x 059 129 717 J 	<b>X81941-01</b> 2x 059 253 039 D 	<b>70-31414-10</b> 	<b>P77441-01 K ←</b> 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

⑮ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



AUDI															
Ltr.															
3,0	CASA CASB CATA CCMA CCWA CCWB CDYA CDYB CDYC	155-176 kW (211-240 PS)	A4 TDI A5 TDI A6 TDI Q5 TDI Q7 TDI	05/04→											
					<b>D37055-01</b> ⑫ Zyl. 4 - 6	<b>D38060-00</b> ⑫ Zyl. 1-3	<b>B38110-00</b> ⑬	<b>H01404-00</b> 059 103 383 EP 84 Ø 1,1 mm 1 □ MLS Zyl. 4-6 <b>H11404-10</b> 059 103 383 EQ 84 Ø 1,15 mm 2 □ MLS Zyl. 4-6 <b>H21404-20</b> 059 103 383 ER 84 Ø 1,2 mm 3 □ MLS Zyl. 4-6 	<b>T80448-00</b> 057 103 384 A (16x) 	<b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR 	<b>N92993-00</b> 2x 036 109 675 (12x) <b>P76662-00</b> 24x 036 109 675	<b>X89125-01</b> 2x 059 129 717 J 	<b>X81941-01</b> 2x 059 253 039 D 	<b>70-31414-10</b> 	<b>P77441-01 K ←</b> 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM



AUDI																
Ltr.																
3,0	CDTA CDTB CDUC CDUD CJGA CJGC CJGD CJMA CKVB CKVC CLAA CLAB CLZB CMHA CNRB CPNA CPNB CRCA	150-184 kW (204-250 PS)	A4 TDI A5 TDI A6 TDI A7 TDI A8 TDI Q5 TDI Q7 TDI	11/07→	 <b>D38407-00</b> ⑫  <b>B38736-00</b> ⑬	<b>H40585-00</b> 059 103 383 JL 84 Ø 1,58 mm 1 □ MLS Zyl. 1-3 <b>H40585-10</b> 059 103 383 JM 84 Ø 1,63 mm 2 □ MLS Zyl. 1-3 <b>H40585-20</b> 059 103 383 JN 84 Ø 1,68 mm 3 □ MLS Zyl. 1-3  <b>H40586-00</b> 059 103 383 JP 84 Ø 1,58 mm 1 □ MLS Zyl. 4-6 <b>H40586-10</b> 059 103 383 JQ 84 Ø 1,63 mm 2 □ MLS Zyl. 4-6 <b>H40586-20</b> 059 103 383 JR 84 Ø 1,68 mm 3 □ MLS Zyl. 4-6 	<b>T40585-00</b> WHT 005 262 (8x) 	2x	<b>X83407-01</b> 059 103 484 Zyl. 1-3  <b>X83408-01</b> 059 103 483 T Zyl. 4-6 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675 24x	<b>X59478-01</b> 059 129 717 N  <b>X59481-01</b> 059 129 718 A 	6x 6x	<b>X82514-01</b> 059 253 039 N 	2x	<b>70-31414-10</b> 	<b>P77765-01 K ←</b> 057 103 051 55x70x8 A SL RD FPM <b>P77766-01 K →</b> 059 103 051 H 85x105x8 A SL LD FPM

[NEW]

AUDI



AUDI						
Ltr.						
3,0 CGQB	230 kW (313 PS) A6 TDI A7 TDI SQ5	11/11→				
<b>[NEW]</b>			<b>D38407-01</b> ⑫  <b>B38736-00</b> ⑬	<b>H40697-00</b> 059 103 383 NK 84 Ø 1,58 mm 1 □ MLS Zyl. 4-6 <b>H40697-10</b> 059 103 383 NL 84 Ø 1,63 mm 2 □ MLS Zyl. 4-6 <b>H40697-20</b> 059 103 383 NM 84 Ø 1,68 mm 3 □ MLS Zyl. 4-6  <b>H40698-00</b> 059 103 383 NG 84 Ø 1,58 mm 1 □ MLS Zyl. 1-3 <b>H40698-10</b> 059 103 383 NH 84 Ø 1,63 mm 2 □ MLS Zyl. 1-3 <b>H40698-20</b> 059 103 383 NJ 84 Ø 1,68 mm 3 □ MLS Zyl. 1-3 	<b>T40585-00</b> 2x WHT 005 262 (8x) 	
3,0 CJTB CJTC CJWB CJWC CNA	200-245 kW (272-333 PS) Q7 TFSI	05/10→	<b>D38069-00</b> ⑫ Zyl. 1-3 <b>D38070-00</b> ⑫ Zyl. 4-6	<b>H40461-00</b> 06E 103 148 AD 85,2 Ø MLS Zyl. 1-3  <b>H40462-00</b> 06E 103 149 AD 85,2 Ø MLS Zyl. 4-6 	<b>T80728-00</b> 2x 06E 103 385 (8x) 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission /  
guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83407-01</b> 059 103 484 Zyl. 1-3  <b>X83408-01</b> 059 103 483 T Zyl. 4-6 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>X59478-01</b> 6x 059 129 717 N  <b>X59481-01</b> 6x 059 129 718 A 	<b>X59928-01</b> 2x 059 253 039 Q 	<b>70-31414-10</b> 	<b>P77765-01 K ←</b> 057 103 051 55x70x8 A SL RD FPM <b>P77766-01 K →</b> 059 103 051 H 85x105x8 A SL LD FPM
<b>X83361-01</b> 06E 103 484 N Zyl. 1-3  <b>X83362-01</b> 06E 103 483 P Zyl. 4-6 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>X59476-01</b> 6x 079 129 717 D  <b>X89852-01</b> ⑩ 6x 079 129 717 B 	<b>X81442-01</b> 2x 06E 253 039 C 	<b>70-31414-10</b> 	<b>P77452-01 K ←</b> 06E 103 153 E PTFE <b>P77766-01 K →</b> 059 103 051 H 85x105x8 A SL LD FPM



AUDI							
3.0	CTTA CTUA	228 kW (310 PS)	A6 TFSI A7 TFSI	01/11→	<b>D38069-00</b> ⑫ Zyl. 1-3 <b>D38070-00</b> ⑫ Zyl. 4-6	<b>H40461-00</b> 06E 103 148 AD 85,2 Ø MLS Zyl. 1-3  <b>H40462-00</b> 06E 103 149 AD 85,2 Ø MLS Zyl. 4-6 	<b>T40707-00</b> 2x WHT 005 739 (8x) 
3.2	AUK BKH BPK BYU	183-191 kW (249-260 PS)	A4 FSI A6 FSI A8 FSI	05/04-07/10	<b>D37056-00</b> ⑫ <b>B37053-00</b> ⑬	<b>H80730-00</b> 06E 103 148 M 86 Ø MLS Zyl. 1 - 3  <b>H80731-00</b> 06E 103 149 M 86 Ø MLS Zyl. 4 - 6 	<b>T80728-00</b> 2x 06E 103 385 (8x) 
3.2	BDB BHE BMJ BPF BUB	184 kW (250 PS)	A3 A3 TT	07/03-05/09	<b>D37008-00</b> ⑫ →8P 5A087 000 →8P 5B006 000 →8N 5 012 200	<b>H80453-00</b> 022 103 383 M 85 Ø MLS 	<b>T80453-00</b> 022 103 384 L (13x) +022 103 384 M (7x) 

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83361-01</b> 06E 103 484 N Zyl. 1-3  <b>X83362-01</b> 06E 103 483 P Zyl. 4-6 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>X59476-01</b> 6x 079 129 717 D  <b>X89852-01</b> ⑩ 6x 079 129 717 B 	<b>X81442-01</b> 2x 06E 253 039 C 	<b>70-31414-10</b> 	<b>P77452-01 K ←</b> 06E 103 153 E PTFE <b>P77766-01 K →</b> 059 103 051 H 85x105x8 A SL LD FPM
<b>X83122-01</b> 06E 103 183 G Zyl. 4 - 6 NBR  <b>X83123-01</b> 06E 103 484 G Zyl. 1 - 3 NBR 	<b>N92993-00</b> 2x 036 109 675 (12x) <b>P76662-00</b> 24x 036 109 675	<b>X89276-01</b> 6x 06E 129 717 B 	<b>X81442-01</b> 2x 06E 253 039 C 	<b>70-31414-10</b> 	<b>P77452-01 K ←</b> 06E 103 153 E PTFE <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM
<b>X83108-01</b> 022 103 483 E NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675	<b>X89128-01</b> 022 133 237 C 	<b>X81441-01</b> 022 253 050 C Zyl. 4 - 6  <b>X81963-01</b> 022 253 039 E Zyl. 1 - 3 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K →</b> 021 103 051 C 85x105x11 A SL LD PTFE ACM



AUDI						
Ltr.						
3,2 BDB BHE BMJ BPF BUB	184 kW (250 PS) A3 A3 TT	07/03-05/09 1	<b>D37008-00</b> ⑫	<b>H80453-00</b> 022 103 383 M 85 Ø MLS 	<b>T80453-00</b> 022 103 384 L (13x) +022 103 384 M (7x) 	
3,2 BUB	184 kW (250 PS) TT	08/06-06/10	<b>D37008-00</b> ⑫	<b>H80453-00</b> 022 103 383 M 85 Ø MLS 	<b>T80453-00</b> 022 103 384 L (13x) +022 103 384 M (7x) 	
3,2 CALA CALB	195-199 kW (265-270 PS) A4 FSI A5 FSI A5 TFSI A6 FSI Q5 FSI	06/07→	<b>D38064-00</b> ⑫ Zyl. 4-6 <b>D38065-00</b> ⑫ Zyl. 1-3 <b>B38111-00</b> ⑬ ⑮	<b>H40459-00</b> 06E 103 149 AC 86,2 Ø MLS Zyl. 4-6  <b>H40460-00</b> 06E 103 148 AC 86,2 Ø MLS Zyl. 1-3 	<b>T80728-00</b> 06E 103 385 (8x) 	2x

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83108-01</b> 022 103 483 E NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675 24x	<b>X89128-01</b> 022 133 237 C 	<b>X81441-01</b> 022 253 050 C Zyl. 4 - 6  <b>X81963-01</b> 022 253 039 E Zyl. 1 - 3 	<b>70-31414-10</b> 	<b>P77820-01 K</b> ← 022 103 151 D <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
<b>X83108-01</b> 022 103 483 E NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675 24x	<b>X89128-01</b> 022 133 237 C 	<b>X81441-01</b> 022 253 050 C Zyl. 4 - 6  <b>X81963-01</b> 022 253 039 E Zyl. 1 - 3 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77820-01 K</b> ← 022 103 151 D <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
<b>X83361-01</b> 06E 103 484 N Zyl. 1-3  <b>X83362-01</b> 06E 103 483 P Zyl. 4-6 		<b>X89276-01</b> 06E 129 717 B 6x  <b>X89852-01</b> ⑩ 6x 079 129 717 B 	<b>X81442-01</b> 06E 253 039 C 2x 		<b>P77452-01 K</b> ← 06E 103 153 E PTFE <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM

⑮ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



AUDI



<b>AUDI</b>							
Ltr.			1				
3,3 AKF	165 kW (224 PS) A8 TDI		06/00-09/02		<b>H01891-00</b> 057 103 383 J 1,1 mm MLS Zyl. 1 - 4 <b>H11891-10</b> 057 103 383 K 1,15 mm MLS Zyl. 1 - 4 <b>H21891-20</b> 057 103 383 L 80 Ø 1,2 mm MLS Zyl. 1 - 4  <b>H01892-00</b> 057 103 383 M 1,1 mm MLS Zyl. 1 - 8 <b>H11892-10</b> 057 103 383 N 1,15 mm MLS Zyl. 5 - 8 <b>H21892-20</b> 057 103 383 P 80 Ø 1,2 mm MLS Zyl. 5 - 8 	<b>T80610-00</b> 057 103 384 A (10x) 	2x
3,6 BHK	206 kW (280 PS) Q7 FSI		08/06-05/10	<b>D37064-00</b> <sup>(12)</sup> 	<b>H80734-00</b> 03H 103 383 H 85 Ø MLS 	<b>T80734-00</b> WHT 000 497 A (13x) +WHT 000 789 A (7x) 	
3,6 PT	180-184 kW (245-250 PS) V8		10/88-02/94	<b>D37009-00</b> 077 198 012 A	<b>H80546-00</b> 077 103 383 S 82 Ø 1,75 mm 	<b>T80546-00</b> 077 103 385 (10x) 	2x

	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	2x 32x	<b>X87467-01</b> 057 129 717 B 	2x	<b>X52307-01</b> 059 253 039 B 	8x	<b>70-31414-10</b> 	<b>P76443-01 K ←</b> 55x68x8 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	4x
<b>X83128-01</b> 03H 103 483 C NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	24x	<b>X89300-01</b> 03H 133 237 B 		<b>X81832-01</b> 03H 253 039 E Zyl. 1 - 3  <b>X81834-01</b> 03H 253 050 B Zyl. 4 - 6 		<b>70-31414-10</b> 	<b>P77354-01 K →</b> 021 103 051 C 85x105x11 A SL LD PTFE ACM	
	<b>N92850-00</b> 027 109 675 (16x) <b>P76532-00</b> 027 109 675	2x 32x							



AUDI						
Ltr.						
3,7 AEW AKJ	169 kW (230 PS) A8	→4D T 008 226	07/95-12/98	<b>D37010-00</b> Zyl. 1 - 4 <b>D37011-00</b> Zyl. 5 - 8	<b>H80003-00</b> 077 103 383 AD 85,3 Ø 1,75 mm Zyl. 5 - 8  <b>H80004-00</b> 077 103 383 AC 85,3 Ø 1,75 mm Zyl. 1 - 4 	<b>T80546-00</b> 2x 077 103 385 (10x) 
3,7 AEW AKJ	169 kW (230 PS) A8	→4D T 008 227→	07/95-12/98	<b>D37010-00</b> Zyl. 1 - 4 <b>D37011-00</b> Zyl. 5 - 8	<b>H80003-00</b> 077 103 383 AD 85,3 Ø 1,75 mm Zyl. 5 - 8  <b>H80004-00</b> 077 103 383 AC 85,3 Ø 1,75 mm Zyl. 1 - 4 	<b>T80546-00</b> 2x 077 103 385 (10x) 
3,7 AKC AQG BFL	191-206 kW (260-280 PS) A6 A8		11/98-05/06	<b>D32944-00</b> ⑫ 077198012E	<b>H80001-00</b> 077 103 383 BS 86 Ø MLS Zyl. 5 - 8  <b>H80002-00</b> 077 103 383 BT 86 Ø MLS Zyl. 1 - 4 	<b>T80002-00</b> 2x 077 103 385 D (10x) 

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



<b>V37010-00</b> 2x 077 198 025 	<b>N92850-00</b> 2x 027 109 675 (16x) <b>P76532-00</b> 32x 027 109 675	<b>X58948-01</b> 2x 077 129 717 N 	<b>X81762-01</b> 2x 077 253 039 B 	<b>X54467-01</b> 2x 077 103 609 E  <b>X54466-01</b> ⑪ 077 103 610 C 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V37010-00</b> 2x 077 198 025 	<b>N92990-00</b> 2x 036 109 675 (16x) <b>P76662-00</b> 32x 036 109 675	<b>X58948-01</b> 2x 077 129 717 N 	<b>X81762-01</b> 2x 077 253 039 B 	<b>X54467-01</b> 2x 077 103 609 E  <b>X54466-01</b> ⑪ 077 103 610 C 	<b>P76096-01</b> K ← 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V32944-00</b> 2x 077 198 025 A 	<b>N90298-00</b> 2x 036 109 675 (20x) <b>P76662-00</b> 40x 036 109 675	<b>X58947-01</b> 2x 077 129 717 Q 	<b>X52312-01</b> 2x 077 253 039 C 	<b>70-31414-10</b> 	<b>P76443-01</b> K ← 55x68x8 A SL RD FPM <b>P76087-01</b> N 4x 068 103 085 E 32x47x10 A SL WD FPM



AUDI

AUDI													
Ltr.													
4,0 ASE	202 kW (275 PS) A8 TDI	05/03-07/05	1	<p><b>H01893-00</b> 057 103 383 BQ 1,1 mm 1 </p> <p>MLS Zyl. 1 - 4</p> <p><b>H11893-10</b> 057 103 383 BR 1,15 mm 2 </p> <p>MLS Zyl. 1 - 4</p> <p><b>H21893-20</b> 057 103 383 BS 82,5 Ø 1,2 mm 3 </p> <p>MLS Zyl. 1 - 4</p> <p><b>H01894-00</b> 057 103 383 CC 1,1 mm 1 </p> <p>MLS Zyl. 5 - 8</p> <p><b>H11894-10</b> 057 103 383 CD 1,15 mm 2 </p> <p>MLS Zyl. 5 - 8</p> <p><b>H21894-20</b> 057 103 383 CE 82,5 Ø 1,2 mm 3 </p> <p>MLS Zyl. 5 - 8</p>	<p><b>T80610-00</b> 2x 057 103 384 A (10x)</p>	<p><b>X83124-01</b> 057 103 483 H Zyl. 1 - 4 NBR</p>	<p><b>X83125-01</b> 057 103 483 G Zyl. 5 - 8 NBR</p>	<p><b>X89278-01</b> 8x 057 129 717 F</p>	<p><b>X52307-01</b> 8x 059 253 039 B</p>	<p><b>70-31414-10</b></p>	<p><b>P76443-01 K ←</b> 55x68x8 A SL RD FPM <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM</p>		
4,0 CEUA CEUC CGTA	309-382 kW (420-520 PS) S6 S7 S8	02/12→	[NEW]	<p><b>H40710-00</b> 079 103 383 DE 85 Ø MLS Zyl. 1-4</p> <p><b>H40711-00</b> 079 103 383 DF 85 Ø MLS Zyl. 5-8</p>				<p><b>N92990-00</b> 2x 036 109 675 (16x)</p> <p><b>P76662-00</b> 32x 036 109 675</p>	<p><b>X59877-01</b> 2x 079 253 039 M</p>	<p><b>70-31414-10</b></p>	<p><b>P77444-01 K ←</b> 079 103 051 G 55x72x8 A SL RD FPM <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM</p>		

AUDI



AUDI								
4,2 ABH	206 kW (280 PS)	V8 100 S4		10/91-06/94	<b>D32946-00</b> 077 198 012 B <sup>12</sup>	<b>H80003-00</b> 077 103 383 AD 85,3 Ø 1,75 mm Zyl. 5 - 8	<b>T80546-00</b> 077 103 385 (10x)	2x
						<b>H80004-00</b> 077 103 383 AC 85,3 Ø 1,75 mm Zyl. 1 - 4		
4,2 ABZ AEM AGH AHC AKG AKH	180-250 kW (245-340 PS)	A8 A8 S8	↔→4D T 008 226 ↔→4D T 008 226	03/94-06/99	<b>D37010-00</b> Zyl. 1 - 4 <b>D37011-00</b> Zyl. 5 - 8	<b>H80003-00</b> 077 103 383 AD 85,3 Ø 1,75 mm Zyl. 5 - 8	<b>T80546-00</b> 077 103 385 (10x)	2x
						<b>H80004-00</b> 077 103 383 AC 85,3 Ø 1,75 mm Zyl. 1 - 4		
4,2 ABZ AEM AGH AHC AKG AKH	180-250 kW (245-340 PS)	A8 A8 S8	↔ 4D T 008 227→ ↔ 4D T 008 227→	03/94-06/99	<b>D37010-00</b> Zyl. 1 - 4 <b>D37011-00</b> Zyl. 5 - 8	<b>H80003-00</b> 077 103 383 AD 85,3 Ø 1,75 mm Zyl. 5 - 8	<b>T80546-00</b> 077 103 385 (10x)	2x
						<b>H80004-00</b> 077 103 383 AC 85,3 Ø 1,75 mm Zyl. 1 - 4		
4,2 AEC	213 kW (290 PS)	A6 S6 100 S4	↔→4A T 075 000 ↔→4A T 075 000	03/94-12/97	<b>D32946-00</b> 077 198 012 B <sup>12</sup>	<b>H80003-00</b> 077 103 383 AD 85,3 Ø 1,75 mm Zyl. 5 - 8	<b>T80546-00</b> 077 103 385 (10x)	2x
						<b>H80004-00</b> 077 103 383 AC 85,3 Ø 1,75 mm Zyl. 1 - 4		

<sup>11</sup> junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



<b>V37010-00</b> 077 198 025	2x	<b>N92850-00</b> 027 109 675 (16x) <b>P76532-00</b> 027 109 675	2x 32x	<b>X58948-01</b> 077 129 717 N	2x	<b>X70699-01</b> 077 129 589 E	8x	<b>X54467-01</b> 077 103 609 E	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x
								<b>X54466-01</b> 077 103 610 C <sup>11</sup>		
<b>V37010-00</b> 077 198 025	2x	<b>N92850-00</b> 027 109 675 (16x) <b>P76532-00</b> 027 109 675	2x 32x	<b>X58948-01</b> 077 129 717 N	2x	<b>X81762-01</b> 077 253 039 B	2x	<b>X54467-01</b> 077 103 609 E	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x
								<b>X54466-01</b> 077 103 610 C <sup>11</sup>		
<b>V37010-00</b> 077 198 025	2x	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	2x 32x	<b>X58948-01</b> 077 129 717 N	2x	<b>X81762-01</b> 077 253 039 B	2x	<b>X54467-01</b> 077 103 609 E	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x
								<b>X54466-01</b> 077 103 610 C <sup>11</sup>		
<b>V37010-00</b> 077 198 025	2x	<b>N92850-00</b> 027 109 675 (16x) <b>P76532-00</b> 027 109 675	2x 32x	<b>X58948-01</b> 077 129 717 N	2x	<b>X70699-01</b> 077 129 589 E	8x	<b>X54467-01</b> 077 103 609 E	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	2x
								<b>X54466-01</b> 077 103 610 C <sup>11</sup>		



AUDI							
4.2 AEC	213 kW (290 PS)	A6 S6 100 S4	4A T 075 001 → 4A T 075 001 →	03/94-12/97		<b>H80003-00</b> 077 103 383 AD 85,3 Ø 1,75 mm Zyl. 5 - 8	<b>T80546-00</b> 077 103 385 (10x) 2x
						<b>H80004-00</b> 077 103 383 AC 85,3 Ø 1,75 mm Zyl. 1 - 4	
4.2 ANK AQJ ARS ASG AUX AWN AYS BCS BFM	220-265 kW (299-360 PS)	A6 A6 S6 A8		11/98 →	<b>D32944-00</b> ⑫ 077198012E	<b>H80001-00</b> 077 103 383 BS 86 Ø MLS Zyl. 5 - 8	<b>T80002-00</b> 077 103 385 D (10x) 2x
						<b>H80002-00</b> 077 103 383 BT 86 Ø MLS Zyl. 1 - 4	
4.2 AQF AQH ARU AUW AVP	175-265 kW (238-360 PS)	A8 A8 S8	→4D X 013 000 →4D X 013 000	11/98-09/02	<b>D32945-00</b> ⑫ 077 198 012 D	<b>H80001-00</b> 077 103 383 BS 86 Ø MLS Zyl. 5 - 8	<b>T80002-00</b> 077 103 385 D (10x) 2x
						<b>H80002-00</b> 077 103 383 BT 86 Ø MLS Zyl. 1 - 4	

<b>V37010-00</b> 077 198 025 2x	<b>N92990-00</b> 036 109 675 (16x) 2x <b>P76662-00</b> 036 109 675 32x	<b>X58948-01</b> 077 129 717 N 2x	<b>X07855-01</b> 027 129 589 A 8x	<b>X54467-01</b> 077 103 609 E	<b>P76096-01 K ←</b> 069 115 147 C 35x48x10 A SL RD FPM <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V32944-00</b> 077 198 025 A 2x	<b>N90298-00</b> 036 109 675 (20x) 2x <b>P76662-00</b> 036 109 675 40x	<b>X58947-01</b> 077 129 717 Q 2x	<b>X52312-01</b> 077 253 039 C 2x	<b>70-31414-10</b> ⑪	<b>P76443-01 K ←</b> 55x68x8 A SL RD FPM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM
<b>V37010-00</b> 077 198 025 2x	<b>N90298-00</b> 036 109 675 (20x) 2x <b>P76662-00</b> 036 109 675 40x	<b>X58947-01</b> 077 129 717 Q 2x	<b>X52312-01</b> 077 253 039 C 2x	<b>70-31414-10</b>	<b>P76443-01 K ←</b> 55x68x8 A SL RD FPM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM

⑪ junta carter / Dichtung Ölsumpf / oil pan gasket / joint de carter d'huile / guarnizione coppa dell'olio / прокладка поддона картер



AUDI													
4.2	AQF AQH ARU AUW AVP	175-265 kW (238-360 PS)	A8 A8 S8	11/98-09/02	<b>D32944-00</b> 077198012E	<b>H80001-00</b> 077 103 383 BS 86 Ø MLS Zyl. 5 - 8 	<b>T80002-00</b> 077 103 385 D (10x) 	<b>V32944-00</b> 077 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X58947-01</b> 077 129 717 Q 	<b>X52312-01</b> 077 253 039 C 	<b>70-31414-10</b> 	<b>P76443-01 K ←</b> 55x68x8 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
4.2	BAR BNS BVJ BYH CAUA CDRA CNDA	257-316 kW (350-430 PS)	A4 RS4 A6 FSI A8 FSI Q7 FSI R8 FSI S5	09/05→		<b>H80764-00</b> 079 103 383 AQ MLS Zyl. 1 - 4 			<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675			<b>70-31414-10</b> 	<b>P77444-01 K ←</b> 079 103 051 G 55x72x8 A SL RD FPM <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM
4.2	BAS BAT BBK BHF	220-253 kW (299-344 PS)	ALLROAD V8 A4 S4 A6	07/02-03/09		<b>H80717-00</b> 079103383S 86 Ø MLS Zyl. 1 - 4 	<b>T80002-00</b> 077 103 385 D (10x) 	<b>V38061-00</b> 077 198 025 B Zyl. 1-4 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X58947-01</b> 077 129 717 Q 	<b>X52312-01</b> 077 253 039 C 	<b>70-31414-10</b> 	<b>P77444-01 K ←</b> 079 103 051 G 55x72x8 A SL RD FPM <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM
						<b>H80765-00</b> 079 103 383 AR MLS Zyl. 5 - 8 		<b>V38062-00</b> 077 198 025 C Zyl. 5-8 					
						<b>H80718-00</b> 079103383T 86 Ø MLS Zyl. 5 - 8 		<b>X83109-01</b> 079 103 483 K Zyl. 1 - 4 NBR 					
								<b>X83110-01</b> 079 103 483 L Zyl. 5 - 8 NBR 					

AUDI						
Ltr.						
4,2 BCY BRV	331-353 kW (450-480 PS) A6 RS6	07/02-01/05		<p><b>H80719-00</b> 077 103 383 BQ 86 Ø MLS Zyl. 1 - 4</p> <p><b>H80720-00</b> 077 103 383 BR 86 Ø MLS Zyl. 5 - 8</p>	<p><b>T80002-00</b> 077 103 385 D (10x)</p>	2x
4,2 BMC BTR BVN	235-240 kW (320-326 PS) A8 TDI Q7 TDI	01/05-07/10		<p><b>H40576-00</b> 057 103 383 EM 83,5 Ø 1  MLS Zyl. 1-4</p> <p><b>H40576-10</b> 057 103 383 EN 83,5 Ø 2  MLS Zyl. 1-4</p> <p><b>H40576-20</b> 057 103 383 EP 83,5 Ø 3  MLS Zyl. 1-4</p> <p><b>H40577-00</b> 057 103 383 EQ 83,5 Ø 1  MLS Zyl. 5-8</p> <p><b>H40577-10</b> 057 103 383 ER 83,5 Ø 2  MLS Zyl. 5-8</p> <p><b>H40577-20</b> 057 103 383 ES 83,5 Ø 3  MLS Zyl. 5-8</p>	<p><b>T80610-00</b> 057 103 384 A (10x)</p>	2x

0 arriba / oben / top / haut / superiore / сверху



<p><b>V32944-00</b> 077 198 025 A</p>	<p><b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675</p>	<p><b>X89177-01</b> 077 129 717 R</p>	<p><b>X52312-01</b> 077 253 039 C</p>	<p><b>70-31414-10</b></p>	<p><b>P76443-01 K ←</b> 55x68x8 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>
<p><b>X59505-01</b> 057 103 484 Zyl. 1-4</p> <p><b>X59506-01</b> 057 103 483 J Zyl. 5-8</p>	<p><b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675</p>	<p><b>X59471-01</b> O 2x 057 129 717 H</p> <p><b>X59472-01</b> U 2x 057 129 717 G</p>	<p><b>X82515-01</b> 057 253 039 D</p> <p><b>X82516-01</b> 059 253 039 E</p>	<p><b>70-31414-10</b></p>	<p><b>P77441-01 K ←</b> 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM</p>

U debajo / unten / bottom / bas / inferiore / снизу



<b>AUDI</b> Ltr. <b>1</b> 4,2 CCFA CCFC 250 kW (340 PS) Q7 TDI 05/09→											
		<p><b>H40580-00</b> 057 103 383 HF 84 Ø 1,1 mm 1 </p> <p><b>H40580-10</b> 057 103 383 HG 84 Ø 1,15 mm 2 </p> <p><b>H40580-20</b> 057 103 383 HH 84 Ø 1,2 mm 3 </p>	<p><b>T80610-00</b> 2x 057 103 384 A (10x)</p>	<p><b>X59505-01</b> 057 103 484 Zyl. 1-4</p>	<p><b>N92990-00</b> 2x 036 109 675 (16x) <b>P76662-00</b> 32x 036 109 675</p>	<p><b>X59471-01</b> 0 2x 057 129 717 H</p> <p><b>X59472-01</b> U 2x 057 129 717 G</p>	<p><b>X59646-01</b> 2x 057 253 039 K</p> <p><b>X59647-01</b> 2x 057 253 039 K</p>	<p><b>70-31414-10</b></p>	<p><b>P77765-01</b> K ← 057 103 051 55x70x8 A SL RD FPM <b>P77766-01</b> K → 059 103 051 H 85x105x8 A SL LD FPM <b>P77182-01</b> N 028 103 086 32x47x10 A SL LD PTFE</p>		

0 arriba / oben / top / haut / superiore / сверху

U debajo / unten / bottom / bas / inferiore / снизу





<b>AUDI</b>				
Ltr.				
4,2 CDSB	258 kW (351 PS) A8 TDI	11/09→		
			<p><b>H40580-00</b> 057 103 383 HF 84 Ø 1,1 mm 1 □ MLS Zyl. 1-4</p> <p><b>H40580-10</b> 057 103 383 HG 84 Ø 1,15 mm 2 □ MLS Zyl. 1-4</p> <p><b>H40580-20</b> 057 103 383 HH 84 Ø 1,2 mm 3 □ MLS Zyl. 1-4</p>	<p><b>T80610-00</b> 2x 057 103 384 A (10x)</p>
			<p><b>H40581-00</b> 057 103 383 HJ 84 Ø 1,1 mm 1 □ MLS Zyl. 5-8</p> <p><b>H40581-10</b> 057 103 383 HK 84 Ø 1,15 mm 2 □ MLS Zyl. 5-8</p> <p><b>H40581-20</b> 057 103 383 HL 84 Ø 1,2 mm 3 □ MLS Zyl. 5-8</p>	
4,2 CFSA	331 kW (450 PS) R S4 RS 5 RS5	03/10→	<p><b>H40692-00</b> 079 103 383 BR 86 Ø MLS Zyl. 5-8</p> <p><b>H40693-00</b> 079 103 383 BQ 86 Ø MLS Zyl. 1-4</p>	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X59505-01</b> 057 103 484 Zyl. 1-4	<b>N92990-00</b> 2x 036 109 675 (16x) <b>P76662-00</b> 32x 036 109 675	<b>X59471-01</b> 0 2x 057 129 717 H	<b>X82515-01</b> 2x 057 253 039 D	<b>70-31414-10</b>	<b>P77765-01 K ←</b> 057 103 051 55x70x8 A SL RD FPM <b>P77766-01 K →</b> 059 103 051 H 85x105x8 A SL LD FPM <b>P77182-01 N</b> 028 103 086 32x47x10 A SL LD PTFE
<b>X59506-01</b> 057 103 483 J Zyl. 5-8		<b>X59472-01</b> U 2x 057 129 717 G	<b>X82516-01</b> 2x 059 253 039 E		
<b>X59872-01</b> R 079 103 484 C	<b>N92990-00</b> 2x 036 109 675 (16x)	<b>X89852-01</b> ⑩ 8x 079 129 717 B	<b>X59878-01</b> 2x 079 253 039 G		<b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM
<b>X59873-01</b> L 079 103 483 T					

0 arriba / oben / top / haut / superiore / сверху  
U debajo / unten / bottom / bas / inferiore / снизу



<b>AUDI</b>						
Ltr.						
5,2 BSM BXA	320-331 kW (435-450 PS) A6 S6 A8 S8	03/06-08/11		<p><b>H80750-00</b> 07L 103 383 N MLS Zyl. 6 - 10</p> <p><b>H80751-00</b> 07L 103 383 P MLS Zyl. 1 - 5</p>		
6,0 BHT BSB BTE	331 kW (450 PS) A8 W12	12/03-07/10		<p><b>H80732-00</b> 07C 103 148 R MLS Zyl. 1 - 6</p> <p><b>H80733-00</b> 07C 103 149 N MLS Zyl. 7 - 12</p>	<p><b>T80732-00</b> 2x 07D 103 384 A (14x) +07D 103 385 A (7x)</p>	

	<p><b>N90298-00</b> 2x 036 109 675 (20x) <b>P76662-00</b> 40x 036 109 675</p>			<p><b>70-31414-10</b></p>	<p><b>P77444-01 K ←</b> 079 103 051 G 55x72x8 A SL RD FPM <b>P77362-01 K →</b> 079 103 051 F 85x105x8,8 A SL LD PTFE ACM</p>
<p><b>X83346-01</b> 07C 103 484 C Zyl. 7-12</p> <p><b>X83347-01</b> 07C 103 483 C Zyl. 1-6</p>	<p><b>N92830-00</b> 2x 036 109 675 (24x) <b>P76662-00</b> 48x 036 109 675</p>	<p><b>X89279-01</b> 07C 133 238 H</p>	<p><b>X81983-01</b> 4x 07C 253 039 D</p>	<p><b>70-31414-10</b></p>	<p><b>P77442-01 K ←</b> 06C 103 085 42x55x7 AB SL RD PTFE ACM <b>P77354-01 K →</b> 021 103 051 C 85x105x11 A SL LD PTFE ACM</p>



AUDI										
Ltr.										
6,0 CCGA	368 kW (500 PS) Q7 TDI	09/08→								
			<p><b>H01423-00</b> 05A 103 383 BF 84 Ø 1,1 mm 1 □ MLS Zyl. 7-12</p> <p><b>H11423-10</b> 05A 103 383 BG 84 Ø 1,15 mm 2 □ MLS Zyl. 7-12</p> <p><b>H21423-20</b> 05A 103 383 BH 84 Ø 1,2 mm 3 □ MLS Zyl. 7-12</p> <p><b>H01424-00</b> 05A 103 383 BJ 84 Ø 1,1 mm 1 □ MLS Zyl. 1-6</p> <p><b>H11424-10</b> 05A 103 383 BK 84 Ø 1,15 mm 2 □ MLS Zyl. 1-6</p> <p><b>H21424-20</b> 05A 103 383 BL 84 Ø 1,2 mm 3 □ MLS Zyl. 1-6</p>	<p><b>X83351-01</b> 05A 103 483 A Zyl. 7-12</p> <p><b>X83352-01</b> 05A 103 484 A Zyl. 1-6</p>	<p><b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 24x 036 109 675</p>	<p><b>X82342-01</b> 2x 06A 253 039 D</p>	<p><b>70-31414-10</b></p>	<p><b>P77441-01 K ←</b> 079 103 051 D 55x70x8 A SL RD PTFE</p>		

