

SUZUKI													
0,8 AB51 F8B	25-30 kW (34-41 PS)	ALTO	06/82→ 	<b>D80940-00</b> <sup>12</sup> 11100-78830	<b>H80940-00</b> 11141-78402 68,7 Ø 		<b>X83230-01</b> 11189-78100 	<b>N93015-00</b> 09289-070005-000 (6x)			<b>X82170-01</b> 14140-78100 	<b>X54890-01</b> 11529-79110 	<b>P77582-01 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>P77503-01 K</b> → 09283-60009 60x80x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
0,8 AB51	29 kW (39 PS)	ALTO	01/86-12/88	<b>S80940-00</b> <sup>12 13</sup> 11400-84824 <b>D80940-01</b> <sup>12</sup> 11400-84824 HS	<b>H80940-00</b> 11141-78402 68,7 Ø 			<b>N93015-00</b> 09289-070005-000 (6x)			<b>X82170-01</b> 14140-78100 	<b>X54890-01</b> 11529-79110 	<b>P77582-01 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>P77503-01 K</b> → 09283-60009 60x80x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
0,8 F8A	27-29 kW (37-39 PS)	ALTO CARRY LJ 80	01/80-10/85		<b>H80941-00</b> 11141-73002 64 Ø 		<b>X83202-01</b> 11189-73001 	<b>N93015-01</b> 09289-07007 (8x)	<b>X89615-01</b> 2x 13119-73000 		<b>X82142-01</b> 14140-73001 	<b>X54869-01</b> 11529-73001 	<b>P77582-01 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>P77503-01 K</b> → 09283-60009 60x80x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
1,0 F10A	30-33 kW (41-45 PS)	SAMURAI SJ 410 SUPER CARRY	09/81-12/04	<b>S80904-01</b> <sup>12 13</sup> 11400-85820 <b>D80904-01</b> <sup>12</sup> 11100-85820	<b>H80904-10</b> 11141-75102 67 Ø 		<b>X83202-01</b> 11189-73001 	<b>N93015-01</b> 09289-07007 (8x)	<b>X89615-01</b> 2x 13119-73000 		<b>X82142-01</b> 14140-73001 	<b>X54889-01</b> 11529-80000 	<b>P77582-01 K</b> ← 09283-32016 32x47x8 A SL RD NBR <b>P77503-01 K</b> → 09283-60009 60x80x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
1,0 G10	37 kW (50 PS)	SWIFT	10/83-03/89	<b>S37215-00</b> <sup>12 13</sup> 11400-82814 <b>D37215-00</b> <sup>12</sup> 11100-82814	<b>H40367-00</b> 11141-82001 75,2 Ø 		<b>X83373-01</b> 11189-82000 	<b>N93015-00</b> 09289-070005-000 (6x)			<b>X82372-01</b> 14140-82000 	<b>70-31414-10</b> 	
1,0 G10A	37-40 kW (50-54 PS)	SWIFT WAGON R	10/83-12/05	<b>S40013-00</b> <sup>12 13</sup> <b>D40013-00</b> <sup>12</sup>	<b>H40013-00</b> 75 Ø 		<b>X83268-01</b> 	<b>N90112-01</b> 09289-05012-000 (6x)	<b>X89706-01</b> 		<b>X82228-01</b> 	<b>70-31414-10</b> 	<b>P77581-01 K</b> ← 09283-32042 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68002 68x86x8 A SL LD MVQ <b>P77581-01 N</b> 09283-32042 32x47x6 A SL RD MVQ

SUZUKI													
1,0 K10A	48-51 kW (65-69 PS)	WAGON R+	02/98-07/03	<b>D40039-00</b> <sup>12</sup> 11401-75812-000	<b>H40039-00</b> 11141-75F10-000 MLS 		<b>X83284-01</b> 11189-75F01-000 	<b>N93135-00</b> 09289-05012 (16x)	<b>X89728-01</b> 13119-75F00-000 		<b>X82250-01</b> 14141-75F00-000 	<b>70-31414-10</b> 	
1,0 K10B	48-50 kW (65-68 PS)	ALTO SPLASH	01/08→	<b>D38090-00</b> <sup>12</sup>	<b>H40476-00</b> 11141-51K00 MLS 	<b>T50156-00</b> 11117-69J00 (8x) 	<b>X83371-01</b> 11189-51K00 	<b>N93134-00</b> 09289-05012 (12x)	<b>X89890-01</b> 13119-51K00  <b>X89853-01</b> <sup>10</sup> 13118-51K00 		<b>X82373-01</b> 14140-51K00 	<b>70-31414-10</b> 	<b>P77453-01</b> K ← 09283-41001 41x53x6 FPM <b>P77679-01</b> K → 09283-83002 83x97x7 LD FPM/ACM
1,0 Z 10 XEP <b>[NEW]</b>	44 kW (60 PS)	WAGON R+	06/04-08/05	<b>D36283-00</b> <sup>12</sup> <b>B36283-00</b> <sup>13</sup>	<b>H40388-00</b> ✕ 0,57 mm MLS <b>H80771-00</b> 0,32 mm MLS 	<b>T80082-00</b> 	<b>X53918-01</b> NBR 	<b>N92114-00</b> <b>P76707-00</b> 12x	<b>X88909-01</b> 3x 		<b>X52442-01</b> 	<b>X54490-01</b> ACM 	<b>P77155-01</b> K ← 42x55x7 A SL RD FPM <b>P76341-01</b> K → 80x98x10 A SL LD FPM
1,1 F10D F10DN <b>[NEW]</b>	46 kW (63 PS)	ALTO	09/04-12/08	<b>S38809-00</b> <sup>12</sup> <sup>13</sup> 99000M24120-665 +11189M79F30 +09289-05012 (16x) +09283M35047 <b>D38810-00</b> <sup>12</sup>	<b>H40764-00</b> 11141M79F10 69,3 Ø 		<b>X71054-01</b> 11189M79F30 	<b>N93135-00</b> 09289-05012 (16x)	<b>X71055-01</b> 13119M79F10 		<b>X71056-01</b> 14141M79GA0 	<b>70-31414-10</b> 	<b>P77581-01</b> K ← 09283-32042 32x47x6 A SL RD MVQ <b>P77503-01</b> K → 09283-60009 60x80x8 A SL LD MVQ <b>P77878-01</b> N 09283-35047 35x47x6 A SL RD FPM/ACM
1,2 K12A	51 kW (69 PS)	WAGON R+	02/98-05/00	<b>D40046-00</b> <sup>12</sup>	<b>H40046-00</b> 11141-75F30-000 MLS 		<b>X83284-01</b> 11189-75F01-000 	<b>N93135-00</b> 09289-05012 (16x)	<b>X89728-01</b> 13119-75F00-000 		<b>X82250-01</b> 14141-75F00-000 	<b>70-31414-10</b> 	
1,2 K12B	63-69 kW (86-94 PS)	SPLASH SWIFT SWIFT IV	01/08→	<b>D38091-00</b> <sup>12</sup>	<b>H40477-00</b> 11141-73K00 MLS 	<b>T50157-00</b> 117-69J00 (10x) 	<b>X83370-01</b> 11189-73K00 	<b>N93135-00</b> 09289-05012 (16x)	<b>X89891-01</b>  <b>X89854-01</b> <sup>10</sup> 13118-73K00 		<b>X82374-01</b> 14140-73K01 	<b>70-31414-10</b> 	<b>P77453-01</b> K ← 09283-41001 41x53x6 FPM <b>P77679-01</b> K → 09283-83002 83x97x7 LD FPM/ACM

SUZUKI												
Ltr.												
1,2 Z 12 XEP <b>[NEW]</b>	59 kW (80 PS)	WAGON R+	06/04-08/05	D36802-00 <sup>12</sup> B32992-00 <sup>13</sup>	H40390-00 <sup>X</sup> 79,5 Ø 0,57 mm MLS H80490-00 79,5 Ø 0,32 mm MLS 	T80083-00 	V53917-01  X53917-01 NBR 	N92115-00 P76707-00 16x	X88909-01  4x	X52443-01 X81822-01 	X54489-01 ACM 	P77155-01 K ← 42x55x7 A SL RD FPM P76341-01 K → 80x98x10 A SL LD FPM
1,3 D13A Z13DT Z13DTJ	51-55 kW (69-75 PS)	IGNIS SPLASH CDTI SWIFT WAGON R+	09/03→	D36649-00 <sup>12</sup>  B36649-00 <sup>13</sup> 	H08120-00 11141N86J000A0 70,5 Ø 0,72 mm MLS H18120-10 11141N86J00-0B0 70,5 Ø 0,82 mm 1 MLS H28120-20 11141N86J00-0C0 70,5 Ø 0,92 mm 2 MLS 	T08128-00  RIBE	X83008-01 11189N86J00 Metall 	N92990-00 12919-84A00 (16x) P76662-00 12919-84A00	X87558-01 13119N86J00 16x 	X81490-01 14140N86J00 	70-31414-10 	P77355-01 K ← 16115N86J00 40x52x7 AB SL RD ACM FPM P77340-01 K → 12361N86J00 78x100x9 A SL LD PTFE
1,3 G13A G13B (8V) G13BA	44-59 kW (60-80 PS)	BALENO SAMURAI SJ 413 SWIFT	09/84→	S40079-01 <sup>12</sup> <sup>13</sup> 11402-61834 D40079-01 <sup>12</sup>	H40079-00 11141-86502 75 Ø 		X83231-01 11189-82600 	N93015-01 09289-07007 (8x)	X89643-01 13119-63B11 	X82169-01 14141-51G00 	X54891-01 11510-71C01 	P77581-01 K ← 09283-32042 32x47x6 A SL RD MVQ P77505-01 K → 09283-68002 68x86x8 A SL LD MVQ P77581-01 N 09283-32042 32x47x6 A SL RD MVQ
1,3 G13B	74 kW (101 PS)	SWIFT	08/85-05/01	S40079-03 <sup>12</sup> <sup>13</sup> 11400-61848 D40079-03 <sup>12</sup> 11100-86822	H40079-00 11141-86502 75 Ø 		X83232-01 11189-86500 	N90112-00 09289-05012-000 (16x)	X89958-01 13119-64B00 	X82375-01 14141-64B00 	70-31414-10 	P77581-01 K ← 09283-32042 32x47x6 A SL RD MVQ P77505-01 K → 09283-68002 68x86x8 A SL LD MVQ P77581-01 N 09283-32042 32x47x6 A SL RD MVQ 2x
1,3 G13BB	56-63 kW (76-86 PS)	ALTO BALENO CARRY GRAND VITARA JIMNY SWIFT WAGON R+	07/95→	S40079-02 <sup>12</sup> <sup>13</sup> 11402-61862 D40079-02 <sup>12</sup>	H40079-00 11141-86502 75 Ø 		V38569-00 11189-71C00 +11179-71C01 (4x) 	N90112-00 09289-05012-000 (16x)	X89830-01 14141-51G00 	X82229-01 14140-52G00 	70-31414-10 	P77581-01 K ← 09283-32042 32x47x6 A SL RD MVQ P77505-01 K → 09283-68002 68x86x8 A SL LD MVQ P77581-01 N 09283-32042 32x47x6 A SL RD MVQ 2x

SUZUKI													
Ltr.													
1,3 M13A	60-69 kW (82-94 PS)	GRAND VITARA IGNIS JIMNY LIANA SWIFT WAGON R+	03/98→	<b>D36974-02</b> 11400-86875	<b>H80735-00</b> 11141-69G03 79 Ø MLS 		<b>X83316-01</b> 11189-54GE0 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89959-01</b> 13119-86G00 		<b>X81988-01</b> 14140-69G01 	<b>70-31414-10</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77454-01 K</b> → 09283-83001 83,5x103x8 FPM
1,3 M13A VVT	69 kW (94 PS)	IGNIS	09/03→	<b>D36974-01</b> <sup>12</sup> 11400-69853	<b>H80735-00</b> 11141-69G03 79 Ø MLS 		<b>X83129-01</b> 11189-54G00 NBR 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89779-01</b> 13119-69G00 		<b>X81988-01</b> 14140-69G01 	<b>70-31414-10</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77454-01 K</b> → 09283-83001 83,5x103x8 FPM
1,4 8HY	66 kW (90 PS)	LIANA	04/04→	<b>S36724-00</b> <sup>12</sup> <sup>13</sup>  <b>D36724-01</b> <sup>12</sup>  <b>B36724-00</b> <sup>13</sup>	<b>H08129-00</b> 1,2 mm 2 MLS <b>H08129-10</b> 1,3 mm 3 MLS <b>H08129-20</b> 1,35 mm 1 MLS <b>H18129-30</b> 1,4 mm 4 MLS <b>H18129-40</b> 74,7 Ø 1,45 mm 5 MLS 	<b>T08130-00</b> 	<b>V38516-00</b>  <b>X83035-01</b> NBR 	<b>N92983-00</b> <b>P76779-00</b> 2x 16x	<b>W88317-01</b> 4x 		<b>X81696-01</b> 	<b>70-31414-10</b> 	<b>P77361-01 K</b> ← 40x55x6,4 A SL RD PTFE ACM <b>P77362-01 K</b> → 85x105x8,8 A SL LD PTFE ACM <b>P77668-01 N</b> 27x47x7 A SL RD PTFE ACM
1,5 K9K 700	48 kW (65 PS)	JIMNY	12/03→	<b>D36520-00</b> <sup>12</sup> Mot.→040519 <b>D37078-00</b> <sup>12</sup> Mot.040520→ <b>B36520-00</b> <sup>13</sup> Mot.→040329 <b>B37078-00</b> <sup>13</sup> Mot.040330→	<b>H80363-00</b> 77,5 Ø 0,6 mm MLS Mot.→040519 <b>H80363-10</b> 77,5 Ø 0,9 mm MLS Mot.→040519  <b>H80740-00</b> 77,5 Ø 0,7 mm MLS Mot.040520→ <b>H80740-10</b> 77,5 Ø 0,9 mm MLS Mot.040520→ 	<b>T80363-00</b> 11117-84A00 	<b>X53956-01</b> 11179-84A00 	<b>N92991-00</b> 12919-84A00 (8x) <b>P76662-00</b> 8x 12919-84A00		<b>X81990-01</b> 14140-84A00 	<b>X54674-01</b> Mot.→040329  <b>X54666-01</b> Mot.040330→ 	<b>P77412-01 K</b> ← 16114-84A00 35x47x7 A SL RD NBR PTFE <b>P77296-01 K</b> → 80x100x9 LD PTFE <b>P77154-01 N</b> 28x42x5 A SL RD FPM	

SUZUKI													
1,5 M15A	73-82 kW (99-112 PS)	IGNIS LIANA SWIFT SX4	09/03→	<b>D36974-02</b> 11400-86875	<b>H80735-00</b> 11141-69G03 79 Ø MLS 		<b>X83316-01</b> 11189-54GE0 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89959-01</b> 13119-86G00 		<b>X81988-01</b> 14140-69G01 	<b>70-31414-10</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77454-01 K</b> → 09283-83001 83,5x103x8 FPM
1,6 G16A (8V) G16K-C	59-60 kW (80-82 PS)	VITARA	07/88-03/98	<b>S80959-00</b> ⑫ ⑬ 11400-60821 <b>D80959-00</b> ⑫ 11100-60811	<b>H80959-00</b> 11141-60A00 76 Ø 		<b>X83231-01</b> 11189-82600 	<b>N93015-01</b> 09289-07007 (8x)	<b>X89653-01</b> 13119-60A00 		<b>X82184-01</b> 14140-60A20 	<b>70-31414-10</b> 	<b>P77581-01 K</b> ← 09283-32042 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68002 68x86x8 A SL LD MVQ <b>P77582-01 N</b> 09283-32016 32x47x8 A SL RD NBR
1,6 G16B	68-73 kW (92-99 PS)	ALTO BALENO GRAND VITARA GRAND VITARA SWIFT VITARA X-90	03/89-07/03	<b>S40014-00</b> ⑫ ⑬ 11400-71812 <b>D40014-00</b> ⑫ 11100-58810	<b>H40014-00</b> 11141-71C00 76 Ø 		<b>X83269-01</b> 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89707-01</b> 		<b>X82229-01</b> 14140-52G00  <b>X82324-01</b> ⚠ 	<b>70-31414-10</b> 	<b>P77581-01 K</b> ← 09283-32042 32x47x6 A SL RD MVQ <b>P77505-01 K</b> → 09283-68002 68x86x8 A SL LD MVQ <b>P77581-01 N</b> 09283-32042 32x47x6 A SL RD MVQ
1,6 M16A	73-92 kW (99-125 PS)	GRAND VITARA JIMNY LIANA SWIFT SX4	03/02→	<b>D36974-01</b> ⑫ 11400-69853	<b>H80735-00</b> 11141-69G03 79 Ø MLS 		<b>X83129-01</b> 11189-54G00 NBR 	<b>N90112-00</b> 09289-05012-000 (16x)	<b>X89779-01</b> 13119-69G00 		<b>X81988-01</b> 14140-69G01 	<b>70-31414-10</b> 	<b>P77453-01 K</b> ← 09283-41001 41x53x6 FPM <b>P77454-01 K</b> → 09283-83001 83,5x103x8 FPM
1,6 9HX	66 kW (90 PS)	SX4	04/07→	<b>S36730-00</b> ⑫ ⑬  <b>D36730-00</b> ⑫  <b>B36724-00</b> ⑬	<b>H08130-00</b> 76 Ø 1,25 mm 4 ■ MLS <b>H08130-10</b> 76 Ø 1,3 mm 5 ■ MLS <b>H08130-20</b> 76 Ø 1,35 mm 3 ■ MLS <b>H18130-30</b> 76 Ø 1,4 mm 6 ■ MLS <b>H18130-40</b> 76 Ø 1,45 mm 7 ■ MLS 	<b>T08130-00</b> 	<b>X83038-01</b> NBR 	<b>N93118-00</b> <b>P76780-00</b> 16x	<b>W88321-01</b> 4x  <b>W88322-01</b> 4x 		<b>X81696-01</b> 	<b>70-31414-10</b> 	<b>P77361-01 K</b> ← 40x55x6,4 A SL RD PTFE ACM <b>P77362-01 K</b> → 85x105x8,8 A SL LD PTFE ACM <b>P77668-01 N</b> 27x47x7 A SL RD PTFE ACM

SUZUKI												
Ltr.												
1,8 G18 J18A	89 kW (121 PS) BALENO GRAND VITARA	03/96-05/02	<b>D40040-01</b> <sup>12</sup> 11401-77862-000	<b>H40040-00</b> 11141-21111-000 MLS 		<b>X83285-01</b> 11189-77E00-000 	<b>N92012-01</b> 09289-06003-000 (16x)	<b>X89729-01</b> 13119-77EA0-000 		<b>X82257-01</b> 14140-65D01-000 	<b>70-31414-10</b> 	<b>P77581-01 N</b> 09283-32042 32x47x6 A SL RD MVQ
1,9 F9QB	95 kW (129 PS) GRAND VITARA	10/05-02/15	<b>D37129-00</b> <sup>12</sup>  <b>B37116-00</b> <sup>13</sup>	<b>H40379-00</b> 11141-67JG2 81 Ø 1,25 mm MLS <b>H40379-10</b> 81 Ø 1,6 mm MLS 	<b>T09339-00</b> 11146-67JG0 (10x) 	<b>X53517-01</b> 11179-67JG0 NBR 	<b>N91190-00</b> 12919-67JG0 (8x) <b>P76532-00</b> 12919-67JG0		<b>X89338-01</b> <sup>7</sup> 13119-67JG1 		<b>X54451-01</b> 11515-67JG1 	<b>P77069-01 K</b> ← 42x54x5,8 A SL RD FPM <b>P77117-01 K</b> → 85x105x11/6,8 A SL LD FPM <b>P76039-01 N</b> 25x42x8 A SL RD FPM
1,9 XUD9 XUD9A	46-50 kW (63-68 PS) SAMURAI TD VITARA D	01/95-12/04	<b>S30527-00</b> <sup>12</sup> <sup>13</sup>  <b>D30527-00</b> <sup>12</sup>  <b>B30527-00</b> <sup>13</sup>	<b>H05876-00</b> 1,36 mm 1 <b>H05876-10</b> 1,4 mm 2 <b>H05876-20</b> 1,44 mm 3 <b>H07781-00</b> 1,58 mm <b>H15876-30</b> 1,48 mm 4 <b>H15876-40</b> 84 Ø 1,53 mm 5 <b>H17781-10</b> 1,7 mm 	<b>T08280-00</b> 	<b>X07796-01</b> 	<b>N90300-00</b> <b>P76531-00</b>	<b>X55498-01</b>  <b>X55499-01</b> 		<b>X07782-01</b>  <b>X03013-01</b> <sup>7</sup> 	<b>X07793-01</b> 11515-67JG1 	<b>P76151-01 K</b> ← 16114-66G00 42x62x7 A RD FPM <b>P76386-01 K</b> → 16121-66G10 90x110x7 A SL LD FPM <b>P76099-11 N</b> 35x50x8 A SL WD FPM
1,9 XUD9SD	55 kW (75 PS) VITARA D	08/96-03/99	<b>S31582-00</b> <sup>12</sup> <sup>13</sup>  <b>D31582-00</b>  <b>B31582-00</b> <sup>13</sup>	<b>H02360-00</b> 1,65 mm <b>H05877-00</b> 1,36 mm 1 MLS <b>H05877-10</b> 1,4 mm 2 MLS <b>H05877-20</b> 1,44 mm 3 MLS <b>H12360-10</b> 1,75 mm  <b>H15877-30</b> 1,48 mm 4 MLS <b>H15877-40</b> 84 Ø 1,53 mm 5 MLS 	<b>T02360-00</b> 	<b>X07796-01</b> 	<b>N90300-00</b> <b>P76531-00</b>		<b>X51239-01</b> <sup>7</sup> 	<b>X03013-01</b> <sup>7</sup> 	<b>X07793-01</b> 11515-67JG1 	<b>P76151-01 K</b> ← 16114-66G00 42x62x7 A RD FPM <b>P76386-01 K</b> → 16121-66G10 90x110x7 A SL LD FPM <b>P76099-11 N</b> 35x50x8 A SL WD FPM

SUZUKI												
Ltr.												
2,0 H 20 A	100 kW (136 PS)	VITARA V6	12/94-03/98	S40015-00 <sup>12</sup> <sup>13</sup> D40015-00 <sup>12</sup>	H40015-00 L 79 Ø  H40016-00 R 79 Ø 	X83270-01 R 11176-85FA0  X83271-01 L 11186-85FA0 	N92012-03 09289-06003 (24x)	X89708-01 13119-77E00 2x 	X82230-01 14140-77E00 2x 	70-31414-10 	P77483-01 K ← 25x35x6 A SL RD NBR P77580-01 N 32x46x6 A SL RD MVQ	
2,0 J20A	94-107 kW (128-146 PS)	GRAND VITARA SX4 VITARA	12/96→	D40040-00 <sup>12</sup> 11400-65862-000	H40040-00 11141-21111-000 MLS 	X83285-01 11189-77E00-000 	N92012-01 09289-06003-000 (16x)	X89729-01 13119-77EA0-000 	X82251-01 11140-65D01-000 	70-31414-10 	P77581-01 N 09283-32042 32x47x6 A SL RD MVQ	
2,0 RF	52-64 kW (71-87 PS)	GRAND VITARA TD VITARA TD	12/94-07/03	S40029-00 <sup>12</sup> <sup>13</sup> D40029-00 <sup>12</sup>	H40029-00 87,6 Ø MLS 	X83198-01 	N93001-00	X89630-01 	X82153-01 	X54866-01 	P77584-01 K ← 34x48x7 A SL RD NBR P77529-01 K → 90x110x9 A SL LD NBR P77584-01 N ← 34x48x7 A SL RD NBR	
2,0 RHW	80 kW (109 PS)	GRAND VITARA HDI	07/01-09/05	S36517-00 <sup>12</sup> <sup>13</sup>  D36517-00 <sup>12</sup>  B36517-00 <sup>13</sup> 	H01900-00 11141-67J01-001 86 Ø 1,25 mm 2 MLS H11900-10 11141-67J01-002 86 Ø 1,3 mm 3 MLS H21900-20 11141-67J01-003 86 Ø 1,35 mm 4 MLS H31900-30 11141-67J01-004 86 Ø 1,4 mm 5 MLS 	T17586-00 11117-67G01 (10x) 	X53953-01 11189-67J00 	N92635-00 12919-67G00 (8x) P76698-00 16x 12919-67G00	X81070-01 14141-67G10 	70-31414-10 	P76151-01 K ← 16114-66G00 42x62x7 A RD FPM P76386-01 K → 16121-66G10 90x110x7 A SL LD FPM P77142-01 N 12746-67G00 27x47x7 A SL RD FPM	

SUZUKI													
Ltr.													
2,0 RHZ	80 kW (109 PS)	GRAND VITARA	07/01-09/05	<p><b>S36550-00</b> <sup>12</sup> <sup>13</sup></p> <p><b>D36550-00</b> <sup>12</sup></p> <p><b>B32989-00</b> <sup>13</sup></p>	<p><b>H05133-00</b> 1,3 mm 1 </p> <p><b>H05133-10</b> 1,35 mm 2 </p> <p><b>H05133-20</b> 1,4 mm 3 </p> <p><b>H15133-30</b> 1,45 mm 4 </p> <p><b>H15133-40</b> 86 Ø</p> <p>1,5 mm 5 </p> <p>MLS</p>	<p><b>T05133-00</b></p>	<p><b>X53885-01</b></p>	<p><b>N92991-00</b> 12919-84A00 (8x) Mot.→08331</p> <p><b>N92635-00</b> 12919-67G00 (8x) Mot.08332→</p> <p><b>P76662-00</b> 12919-84A00</p> <p>Mot.→08331</p> <p><b>P76698-00</b> 12919-67G00 Mot.08332→</p>	<p><b>X58968-01</b></p> <p>8x</p> <p>8x</p>	<p><b>X52326-01</b></p>	<p><b>70-31414-10</b></p>	<p><b>P76151-01</b> K ← 16114-66G00 42x62x7 A RD FPM</p> <p><b>P76386-01</b> K → 16121-66G10 90x110x7 A SL LD FPM</p> <p><b>P77142-01</b> N 12746-67G00 27x47x7 A SL RD FPM</p>	
2,0 XUD9TE	64 kW (87 PS)	VITARA TD	12/95-03/98	<p><b>S30527-00</b> <sup>12</sup> <sup>13</sup></p> <p><b>D30527-00</b> <sup>12</sup></p> <p><b>B30527-00</b> <sup>13</sup></p>	<p><b>H02360-00</b> 1,65 mm</p> <p><b>H05877-00</b> 1,36 mm 1 </p> <p>MLS</p> <p><b>H05877-10</b> 1,4 mm 2 </p> <p>MLS</p> <p><b>H05877-20</b> 1,44 mm 3 </p> <p>MLS</p> <p><b>H12360-10</b> 1,75 mm</p> <p><b>H15877-30</b> 1,48 mm 4 </p> <p>MLS</p> <p><b>H15877-40</b> 84 Ø</p> <p>1,53 mm 5 </p> <p>MLS</p>	<p><b>T02360-00</b></p>	<p><b>X07796-01</b></p>	<p><b>N90300-00</b> <b>P76531-00</b></p>	<p><b>X55498-01</b> 2x</p> <p><b>X55499-01</b></p>	<p><b>X07782-01</b> 2x</p> <p><b>X03013-01</b> </p>	<p><b>X07793-01</b> 2x 11515-67JG1</p>	<p><b>P76151-01</b> K ← 16114-66G00 42x62x7 A RD FPM</p> <p><b>P76386-01</b> K → 16121-66G10 90x110x7 A SL LD FPM</p> <p><b>P76099-11</b> N 35x50x8 A SL WD FPM</p>	
2,4 J24B	122-138 kW (166-188 PS)	GRAND VITARA KIZASHI	01/09→	<p><b>S38811-00</b> <sup>12</sup> <sup>13</sup> 11400-57831</p>	<p><b>H40765-00</b> 11141-78K01 93 Ø MLS</p>		<p><b>X71057-01</b> 11189-78K00</p>	<p><b>N93135-00</b> 09289-05012 (16x)</p>	<p><b>X71058-01</b> 4x 13119-80J00</p>		<p><b>X71059-01</b> 14140-78K00</p>	<p><b>70-31414-10</b></p>	<p><b>P77876-01</b> K ← 11389-54L00 FPM/ACM</p> <p><b>P77877-01</b> K → 09283-98003 FPM/ACM</p> <p><b>P77878-01</b> N 09283-35047 35x47x6 A SL RD FPM/ACM</p>



SUZUKI

Ltr. 




**1**




2,5 H 25 A    106-116 kW (144-158 PS)    GRAND VITARA V6    04/98-07/03

**D40088-00** <sup>12</sup>  
11400-65874


**H40088-00 L**  
11142-86FA1  
85 Ø  
1,3 mm




**H40089-00 R**  
11141-86FA1  
85 Ø  
1,3 mm



**X83270-01 R**  
11176-85FA0




**X83271-01 L**  
11186-85FA0




**N92012-03**  
09289-06003 (24x)


**X89708-01**  
13119-77E00    2x



**X82299-01**  
14140-67D03    2x



**70-31414-10**




**P77560-01 K** ←  
09283-45012  
45x63x7,5  
A SL RD NBR  
**P77559-01 K** →  
09283-98002  
98x116x10  
A SL LD NBR  
**P77580-01 N**    2x  
32x46x6  
A SL RD MVQ


2,7 H 27 A    127-135 kW (173-184 PS)    GRAND VITARA    09/01-07/03

**D40086-00** <sup>12</sup>  
11400-52823


**H40086-00 R**  
11141-52D01  
89,5 Ø  
0,7 mm  
MLS




**H40087-00 L**  
11142-52D01  
89,5 Ø  
0,7 mm  
MLS



**X83270-01 R**  
11176-85FA0




**X83271-01 L**  
11186-85FA0




**N92012-03**  
09289-06003 (24x)


**X89708-01**  
13119-77E00    2x



**X82299-01**  
14140-67D03    2x



**70-31414-10**



**P77560-01 K** ←  
09283-45012  
45x63x7,5  
A SL RD NBR  
**P77559-01 K** →  
09283-98002  
98x116x10  
A SL LD NBR  
**P77580-01 N**    2x  
32x46x6  
A SL RD MVQ