








# New Products

for TecDoc release


**OE #**
**GLASER**


CUMMINS		ISX12	2881966	<a href="#">B93338-00</a>	06-2021
CUMMINS		ISX12	4975069	<a href="#">X90882-01</a>	06-2021
CUMMINS		QSL9	5448124 (24X)	<a href="#">N96073-00</a>	06-2021
CUMMINS		QSL9	5448124	<a href="#">P93942-00</a>	06-2021
DEUTZ		TCD 2.2 L3	0066 1771 (6X)	<a href="#">N96074-00</a>	06-2021
LANDROVER		Range Rover 306PS	LR078819 (24X)	<a href="#">N96075-00</a>	06-2021
MAN		TGS/TGX D1556 LF07/08/09	51.00900.6837	<a href="#">D90500-00</a>	06-2021
MAN		TGS/TGX D1556 LF07/08/09	51.04902.0039(12X) PLUS	<a href="#">N96068-01</a>	06-2021
MAN		TGS/TGX D1556 LF07/08/09	51.04902.0051	<a href="#">P93944-00</a>	06-2021
MAN		TGS/TGX D1556 LF07/08/09	51.00900.6841	<a href="#">S90500-00</a>	06-2021
MAZDA		CX9 PY/PYZ4	8LT1-10-271 A	<a href="#">S90490-00</a>	06-2021
MAZDA		CX9 PY/PYZ4	PY8W-10-235	<a href="#">X90884-01</a>	06-2021
MB		A 200 M 282.914	282 098 03 00	<a href="#">X90883-01</a>	06-2021
MB		A45 AMG 139980	139 016 03 00 (10X)	<a href="#">T85040-00</a>	06-2021
MB		GLS400 256925	000 016 04 00 (10X)	T85041-00	06-2021
RENAULT		A160 608915	110448928R	<a href="#">H85149-00</a>	06-2021
SUBARU		Levorg FB16/FB16E/FB16F	11044-AA880	<a href="#">H85147-00</a>	06-2021

**Glaser - Premium Aftermarket Quality**

The listed original part number and/or engine number/type designation are provided for comparison purposes only.

## New Products






for TecDoc release



**OE #**

**GLASER**

**1**

SUBARU		Levorg FB16/FB16E/FB16F	10944-AA170	<a href="#">H85148-00</a>	06-2021
SUZUKI		Swift K14D	11400-53840	<a href="#">D90498-00</a>	06-2021
TOYOTA		Yaris M15AFKS	90910-02202 (4X)(PLUS)	T85014-01	06-2021
VOLKSWAGEN		A3 DTUA		<a href="#">D90499-00</a>	06-2021
VOLVO		XC60 D420T2	31460664	<a href="#">P93945-00</a>	06-2021