

| CITROEN | | | | | | | | | | | | |
|------------------------------|----------------|-------------------|-------------|---|--|---|---|--|--|--|--|--|
| 1.9 WJZ (DW8) | 51 kW (69 PS) | JUMPY D | 04/98→ | <p>S32985-00 ⑫ ⑬ 0197.X6 +0127.28 +0326.22 +0807.14</p> <p></p> <p>D32985-00 ⑫ 0197.X5 +0807.14</p> <p></p> <p>B32989-00 ⑬</p> | <p>H05616-00 0209.X0 84 Ø 1,26 mm 3 ■ MLS</p> <p>H05616-10 0209.X1 1,3 mm 4 ■ MLS</p> <p>H05616-20 0209.X2 1,34 mm 5 ■ MLS</p> <p>H15616-30 0209.X3 1,38 mm 6 ■ MLS</p> <p>H15616-40 0209.X4 1,42 mm 7 ■ MLS</p> <p>H15616-50 0209.1C 84 Ø 1,47 mm 4 ■ MLS</p> <p></p> | <p>T08280-00 0204.65 (10x) Mot.→08469</p> <p></p> <p>T05616-00 0204.97 (10x) Mot.08470→</p> <p></p> | <p>X53733-01 U 0249.97</p> <p></p> <p>X53780-01 O 0249.95</p> <p></p> | <p>N90300-00 0249.48 (8x) P76531-00 0249.48</p> | <p>X58969-01 0348.N2</p> <p>8x </p> <p>X58970-01 0348.N1</p> <p></p> | <p>X52327-01 0349.H7</p> <p>2x </p> | <p>X07793-01 0304.34</p> <p>2x </p> | <p>P76151-01 K ← 0326.12 42x62x7 A RD FPM</p> <p>P76386-01 K → 0127.28 90x110x7 A SL LD FPM</p> <p>P76099-11 N 0236.14 35x50x8 A SL WD FPM</p> |
| 2.0 RFW (XU10J2U) | 80 kW (109 PS) | JUMPER JUMPER Bus | 02/94-04/02 | <p>S31581-00 ⑫ ⑬ 9568993</p> <p>D31581-00 ⑫ 0197.G6 +0209.J8</p> <p>B31581-00 ⑬</p> | <p>H50161-00 0209.J8 87 Ø 1,2 mm</p> <p></p> | <p>T08280-00 0204.65 (10x)</p> <p></p> | <p>X01021-01 0249.48</p> <p></p> | <p>N90300-00 0249.48 (8x) P76531-00 0249.48</p> | <p>X56171-01 0348.F6</p> <p>8x </p> <p>X56170-01 ⑩ 0348.E6</p> <p></p> | <p>X01022-01 0349.70</p> <p>4x </p> | <p>70-31414-10</p> <p></p> | <p>P76151-01 K ← 0326.12 42x62x7 A RD FPM</p> <p>P76386-01 K → 0127.28 90x110x7 A SL LD FPM</p> <p>P76133-01 N 0236.21 36x50x7 A RD FPM</p> |
| 2.0 RHK (DW10UTED4) (120 PS) | 88 kW | JUMPY HDI 120 | 01/07→ | <p>D37090-01 ⑫ 0197.AN +0348.S3</p> <p></p> | <p>H01900-00 0209.AV 86 Ø 1,25 mm 2 ■ MLS</p> <p>H11900-10 0209.AW 86 Ø 1,3 mm 3 ■ MLS</p> <p>H21900-20 0209.AX 86 Ø 1,35 mm 4 ■ MLS</p> <p>H31900-30 0209.AY 86 Ø 1,4 mm 5 ■ MLS</p> <p></p> | <p>T05133-00 0204.A6 (10x)</p> <p></p> | <p>V37090-00 0348.S3</p> <p></p> | <p>N92635-00 0956.48 (8x) P76698-00 0956.48</p> <p>2x</p> <p>16x</p> | | <p>X82339-01 0349.L9</p> <p></p> | <p>70-31414-10</p> <p></p> | <p>P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE</p> <p>P77465-01 K → 0127.45 90x110x7 A SL LD PTFE</p> <p>P77142-01 N 0807.28 27x47x7 A SL RD FPM</p> |

| CITROEN | | | | | | | | | | | | | |
|---|---------------------------|--------|--|---|---|---|---|---|---|--|---|---|--|
| Ltr. | | | | | | | | | | | | | |
| 2,0 RHV (DW10UTD) 62 kW (84 PS) | JUMPER Bus HDI JUMPER HDI | 11/01→ | | <p>S36550-00 ¹² ¹³ 0197.X4 +0249.99</p> <p></p> <p>D36550-00 ¹² 0197.X3 +0249.99</p> <p></p> <p>B32989-00 ¹³</p> | <p>H05133-00 0209.X5 1,3 mm 1 </p> <p>MLS</p> <p>H05133-10 0209.X6 1,35 mm 2 </p> <p>MLS</p> <p>H05133-20 0209.X7 1,4 mm 3 </p> <p>MLS</p> <p>H15133-30 0209.X8 1,45 mm 4 </p> <p>MLS</p> <p>H15133-40 0209.X9 86 Ø 1,5 mm 5 </p> <p>MLS</p> <p></p> | <p>T05133-00 0204.A6 (10x)</p> <p></p> | <p>X53885-01 0249.99</p> <p></p> | <p>N92635-00 0956.48 (8x)</p> <p>P76698-00 0956.48</p> | <p>X58968-01 0348.N4</p> <p>8x </p> | <p>X52326-01 0349.H4</p> <p></p> | <p>70-31414-10</p> <p></p> | <p>P76151-01 K ← 0326.12 42x62x7 A RD FPM</p> <p>P76386-01 K → 0127.28 90x110x7 A SL LD FPM</p> <p>P77142-01 N 0807.28 27x47x7 A SL RD FPM</p> | |
| 2,0 RHX (DW10BTED) 69-80 kW (94-109 PS) RHZ (DW10ATED) | JUMPY HDI | 10/99→ | | <p>S36550-00 ¹² ¹³ 0197.X4 +0249.99</p> <p></p> <p>D36550-00 ¹² 0197.X3 +0249.99</p> <p></p> <p>B32989-00 ¹³</p> | <p>H05133-00 0209.X5 1,3 mm 1 </p> <p>MLS</p> <p>H05133-10 0209.X6 1,35 mm 2 </p> <p>MLS</p> <p>H05133-20 0209.X7 1,4 mm 3 </p> <p>MLS</p> <p>H15133-30 0209.X8 1,45 mm 4 </p> <p>MLS</p> <p>H15133-40 0209.X9 86 Ø 1,5 mm 5 </p> <p>MLS</p> <p></p> | <p>T05133-00 0204.A6 (10x)</p> <p></p> | <p>X53885-01 0249.99</p> <p></p> | <p>N92991-00 0956.38 (8x) Mot.→08331</p> <p>N92635-00 0956.48 (8x) Mot.08332→</p> <p>P76662-00 0956.38 Mot.→08331</p> <p>P76698-00 0956.48 Mot.08332→</p> | <p>X58968-01 0348.N4</p> <p>8x </p> | <p>X52326-01 0349.H4</p> <p></p> | <p>70-31414-10</p> <p></p> | <p>P76151-01 K ← 0326.12 42x62x7 A RD FPM</p> <p>P76386-01 K → 0127.28 90x110x7 A SL LD FPM</p> <p>P77142-01 N 0807.28 27x47x7 A SL RD FPM</p> | |
| 2,0 XU10J2 81 kW (110 PS) | JUMPER JUMPER Bus | 04/02→ | | <p>D32987-00 ¹² 0197.T4 +0209.J8</p> <p>B31581-00 ¹³</p> | <p>H50161-00 0209.J8 87 Ø 1,2 mm</p> <p></p> | <p>T08280-00 0204.65 (10x)</p> <p></p> | <p>X01021-01 0249.48</p> <p></p> | <p>N90300-00 0249.48 (8x)</p> <p>P76531-00 0249.48</p> | <p>X56171-01 0348.F6</p> <p>8x </p> <p>X56170-01 ¹⁰ 0348.E6</p> <p>2x </p> | <p>X06151-01 0349.70</p> <p>4x </p> | <p>X07793-01 0304.34</p> <p></p> | <p>P76151-01 K ← 0326.12 42x62x7 A RD FPM</p> <p>P76386-01 K → 0127.28 90x110x7 A SL LD FPM</p> <p>P76133-01 N 0236.21 36x50x7 A RD FPM</p> | |

| CITROEN | | | | | | | | | | | | |
|---------------------------------|-----------------------------|--|--|---|---|--|---|--|---|---------------------------------|--|--|
| Ltr. | | | | | | | | | | | | |
| 2,5 THX (DJ5TED) 79 kW (107 PS) | JUMPER BusTDI JUMPER TDI | 12/96-04/02 | S32990-00 ⑫ ⑬ 0197.W4 +0209.T5 D32990-00 ⑫ 0197.W3 +0209.T5 B32148-00 ⑬ | H80034-00 0209.T5 93 Ø | T80034-00 0204.87 (14x) +0204.88 (8x) | X53585-01 0249.79 | N91190-00 0956.19 (8x) P76532-00 0956.19 | X58971-01 0348.K4 8x | 2x | X52328-01 0349.G4 | 70-31414-10 | P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P76098-01 N V 0514.15 35x50x7 A SL RD FPM P77143-01 N H 0807.26 32x52x7 A SL LD FPM |
| 2,5 T8A (DJ5T) T9A (DJ5) | 63-76 kW (86-103 PS) | JUMPER Bus D JUMPER Bus TD JUMPER D JUMPER TD | 03/94-04/02 | S32148-00 ⑫ ⑬ 0197.T7 +0209.R3 D32148-00 ⑫ 0197.T6 +0209.R3 B32148-00 ⑬ | H50390-00 0209.R3 93 Ø | T50390-00 0204.74 (14x) +0204.75 (8x) | X53585-01 0249.79 | N92450-00 0659.19 (12x) P76532-00 0956.19 | X56189-01 0348.K1 12x X57008-01 ⑩ 0348.F9 | X51508-01 0349.E7 | 70-31414-10 | P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P76098-01 N ← 0514.15 35x50x7 A SL RD FPM P76034-01 N → ⑳ 0807.15 40x62x7 A SL LD ACM FPM P76047-01 N → ㉑ 0807.21 47,5x62x7 A SL LD ACM FPM |
| 2,8 F28TDCR | 94 kW (128 PS) | JUMPER HDI | 02/02-06/06 | H08023-01 0209.0C 1,3 mm H18023-11 0209.0E 1,4 mm H28023-21 0209.0F 1,5 mm | T07684-00 | X53812-01 0249.C3 | N93138-00 P76804-00 | X07692-01 4x | 4x | X07689-01 4x | | |
| 2,8 8140.43S | 93-94 kW (126-128 PS) | JUMPER JUMPER BusHDI JUMPER HDI | 09/00→ | S38249-02 ⑫ ⑭ 0197.Y2 D38249-02 ⑫ | H08023-01 0209.0C 1,3 mm H18023-11 0209.0E 1,4 mm H28023-21 0209.0F 1,5 mm | X53812-01 X 0249.C3 X59298-01 0249.A0 | N93138-00 P76804-00 | X07692-01 8x | 4x | X51326-11 0349.H5 | X54494-01 X NBR X59306-01 Gummi | |