

PEUGEOT													
Ltr.			1										
1,1 TU1JP (HFV) 44 kW (60 PS)	PARTNER	06/96→	D36677-00 ⁽¹²⁾ B37002-00 ⁽¹³⁾	H80370-00 0209.Y0 73,5 Ø 1,25 mm 	T01004-00 0204.83 (10x) 	X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19	X87172-01 0342.E0 4x 		X82381-01 ⁽⁵¹⁾ 0349.J6 X82382-01 0349.K1 X81500-01 ^(A) 1709.25 	X54035-01 ⁽⁵¹⁾ 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM	
1,1 TU1M (HDZ) 44 kW (60 PS)	PARTNER	06/96→	S31062-00 ⁽¹²⁾ ⁽¹³⁾ ⁽⁵¹⁾ 95619476+97520616 D31062-00 ⁽¹²⁾ ⁽⁵¹⁾ 0197.A7 B31062-00 ⁽¹³⁾ ⁽⁵¹⁾ R30712-00 ⁽³⁾ 7701348178 (x4)	H01004-10 ⁽⁵¹⁾ 0209.CJ 76,3 Ø 1,3 mm H11004-20 ⁽⁵¹⁾ 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x) 	X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19	X56780-01 8x 		X06306-01 0349.A6 X06310-01 ^(A) 1709.10 	X54035-01 ⁽⁵¹⁾ 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM	
1,4 TU3JP (KFW) 54-55 kW (73-75 PS)	PARTNER	06/96→	S32984-00 ⁽¹²⁾ ⁽¹³⁾ D32984-00 ⁽¹²⁾ 0197.H8+0209.CJ B31600-00 ⁽¹³⁾ R30712-00 ⁽³⁾ 7701348178 (x4)	H01004-10 ⁽⁵¹⁾ 0209.CJ 76,3 Ø 1,3 mm H11004-20 ⁽⁵¹⁾ 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x) 	X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19	X87172-01 0342.E0 4x 		X06306-01 0349.A6 X82381-01 ⁽⁵¹⁾ 0349.J6 X82382-01 ⁽⁵¹⁾ 0349.K1 X06310-01 ^(A) 1709.10 	X54035-01 ⁽⁵¹⁾ 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM	
1,5 XB5 XB5P	J7	08/68→	A30791-00 ⁽¹²⁾ ⁽¹⁴⁾ 0198.35 D30791-00 ⁽¹²⁾ 0199.36 R30553-00 ⁽³⁾ 0112.17(4)	H03545-00 0203.26 82,5 Ø 		X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	X04834-01 0348.06 8x 		X04833-01 0349.03 X03013-01 ^(A) 1721.01 X05087-01 ^(A) 1710.15 	X04838-01 0304.03 Kork 		
1,6 TU5JP4 (NFU) 80 kW (109 PS)	PARTNER PARTNER 16V	09/00→	D36693-00 ⁽¹²⁾ B36693-00 ⁽¹³⁾	H80497-10 98 045 482 80 79,8 Ø 0,6 mm MLS 	T04220-00 0204.81 (10x) 	X83028-01 0249.A9 NBR Mot.→2336722 X59782-01 ⁽⁵¹⁾ Mot.2336723→ 	N92004-00 0956.40 (16x) P76809-00 0956.40	M74443-00 0348.Q5 16x 		X81664-01 0349.L3 X81500-01 ^(A) 1709.25 	X54807-01 0304.55 NBR 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77141-01 N 0807.24 38x50x6 A SL RD FPM	

PEUGEOT													
Ltr.													
1,6 XC5P	50 kW (68 PS)	J7 J7 Bus	08/68-03/80	A30548-00 ⑫ ⑭ 0199.40 D30548-00 ⑫ 0199.84 R30553-00 ③ 0112.17(4)	H04608-00 0203.24 86,8 Ø 		X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 	X04834-01 0348.06 8x 	4x	X04833-01 0349.03 X03013-01 ⚠ 1721.01 X04201-01 ⚠ 1710.09 X05087-01 ⚠ 1710.15 	X04838-01 0304.03 Kork 	
1,6 XC7P	44 kW (60 PS)	J7 J7 Bus	08/68-03/80	A30547-00 ⑫ ⑭ D30547-00 ⑫ R30547-00 ③	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x) 	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 	8x		X04833-01 0349.03 X03013-01 ⚠ 1721.01 X04201-01 ⚠ 1710.09 X05087-01 ⚠ 1710.15 	X54253-01 Kork 	
1,6 XC7P	44 kW (60 PS)	J9	03/80-06/87	A30547-00 ⑫ ⑭ D30547-00 ⑫ R30547-00 ③	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x) →06/85 T02760-00 0204.51 (10x) 07/85→ 	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 	8x		X04833-01 0349.03 X03013-01 ⚠ 1721.01 X04201-01 ⚠ 1710.09 X05087-01 ⚠ 1710.15 	X54253-01 Kork 	
1,6 1580 SPI (222A2)	58 kW (79 PS)	EXPERT	02/96→	S32919-00 ⑫ ⑬ D32919-00 ⑫ B32919-00 ⑬	H00593-10 0209.P9 87 Ø 	T05082-00 	X01619-01 U X53175-01 0 X53734-01 0249.84 Kork 	N90300-00 0249.48 (8x) P76531-00 0249.48 	8x	X51425-01 ⑦ 	X00688-01 0304.49 Gummi 	P76117-01 K ← 40x56x7 A SL RD MVQ P76273-01 K → 64x80x8 A SL LD MVQ P76060-01 N 30x52x7 AB SL RD FPM	


















































PEUGEOT														
Ltr.														
1,8 XM7P	48 kW (65 PS)	J7 J7 Bus	07/70-03/80	A30547-00 ⁽¹²⁾ ⁽¹⁴⁾ D30547-00 ⁽¹²⁾ R30547-00 ⁽³⁾	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x) 	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	8x	X04833-01 0349.03 X03013-01 ^(A) 1721.01 X04201-01 ^(A) 1710.09 X05087-01 ^(A) 1710.15 	X54253-01 Kork 			
1,8 XM7T (169B)	51 kW (69 PS)	J5	01/83-11/88	S30778-00 ⁽¹²⁾ ⁽¹³⁾ D30778-00 ⁽¹²⁾	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x) →06/85 T02760-00 0204.51 (10x) 07/85→ 	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	8x	X07480-01 0348.33 	X04833-01 0349.03 X04848-01 0127.05 NBR X54253-01 Kork 	2x	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR	
1,8 XM7T (169B)	51 kW (69 PS)	J5	09/90-01/94	S30778-00 ⁽¹²⁾ ⁽¹³⁾ D30778-00 ⁽¹²⁾	H02666-00 86,7 Ø 	T01025-00 0204.57 (10x) 	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	8x	X07480-01 0348.33 	X04833-01 0349.03 X04848-01 0127.05 NBR X54253-01 Kork 	2x	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR	
1,8 XUD7 (A9A)	43-44 kW (58-60 PS)	PARTNER D	06/96→	S30527-00 ⁽¹²⁾ ⁽¹³⁾ 0197.H5 D30527-00 ⁽¹²⁾ 0197.37 +0956.22 (8x) B30527-00 ⁽¹³⁾	H08280-00 0209.F9 1,57 mm 2 H18280-10 1,7 mm 3 H05875-00 0209.S0 1,36 mm 1 H05875-10 0209.S1 1,4 mm 2 H05875-20 0209.S2 1,44 mm 3 H15875-30 0209.S3 1,48 mm 4 H15875-40 0209.S4 82 Ø 1,53 mm 5 	T08280-00 0204.65 (10x) 	X07796-01 0249.46 	N90300-00 0249.48 (8x) P76531-00 0249.48	8x	X55498-01 0348.99 X55499-01 0348.98 	2x	X07782-01 0349.47 X03013-01 ^(A) 1721.01 	2x	X07793-01 0304.34 P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM

PEUGEOT												
Ltr.												
1,8 XU7JB (LFX) 66 kW (90 PS)	PARTNER	05/97→	S36241-00 ⑫ D36241-00 ⑫ B31580-00 ⑬ R31124-00 ③ 	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 		X53101-01 0249.71 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x 	X85532-01 0348.L7 4x 		X52670-01 1723.63 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
1,9 DW8 (WJZ) 51 kW (69 PS) DW8B (WJY)	EXPERT D PARTNER D	06/96→	S32985-00 ⑫ ⑬ 0197.X6 +0127.28 +0326.22 +0807.14 D32985-00 ⑫ 0197.X5 +0807.14 B32989-00 ⑬	H05616-00 0209.X0 84 Ø 1,26 mm 3 ■ MLS H05616-10 0209.X1 1,3 mm 4 ■ MLS H05616-20 0209.X2 1,34 mm 5 ■ MLS H15616-30 0209.X3 1,38 mm 6 ■ MLS H15616-40 0209.X4 1,42 mm 7 ■ MLS H15616-50 0209.1C 84 Ø 1,47 mm 4 ■ MLS 	T08280-00 0204.65 (10x) Mot.→08469 T05616-00 0204.97 (10x) Mot.08470→ 	X53733-01 U 0249.97 X53780-01 O 0249.95 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x 	X58969-01 0348.N2 2x X58970-01 0348.N1 		X52327-01 0349.H7 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM
1,9 XDP88	40 kW (55 PS) J7 Bus D J7 D	08/68-07/78	S30226-00 ⑬ 0198.14 Mot.→2053776 S30794-00 ⑫ ⑬ 0198.40 Mot.2053777→ D30226-00 0197.08 Mot.→2053776 D30794-00 ⑫ 0197.09 Mot.2053777→ B30756-00 ⑬ ⑯ Mot.4586484→ R30794-00 ③	H02668-00 0209.L2 94 Ø Mot.→2053776 H07635-00 0203.70 1,6 mm Mot.2053777→ H17635-10 94 Ø 1,7 mm Mot.2053777→ 		X06833-01 0249.25 NBR 	N90270-00 0956.01 (8x)	X06855-01 0348.52 	3x	X07092-01 0349.08 X05087-01 ⚠ 1710.15 X07094-01 ⚠ 1710.07 X07489-01 ⚠ 1710.19 	2x X03048-01 0313.19 X07098-01 0304.12 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76005-01 N 16x21x4,5 NBR

PEUGEOT												
1.9 XUD9A (DJY) 50-51 kW XUD9A (D9B) (68-70 PS) XUD9AU (D8C)	BOXER Bus D BOXER D EXPERT D J5 Bus D J5 D PARTNER D	10/90→	<p>S31582-00 ⑫ ⑬ 0197.H5</p> <p></p> <p>D31582-00 0197.37</p> <p></p> <p>B31582-00 ⑬</p>	<p>H02359-00 0209.K0 84 Ø 1,6 mm 2 </p> <p>H12359-10 84 Ø 1,7 mm 3 </p> <p>H05876-00 0209.S5 1,36 mm 1 </p> <p>H05876-10 0209.S6 1,4 mm 2 </p> <p>H05876-20 0209.S7 1,44 mm 3 </p> <p>H15876-30 0209.S8 1,48 mm 4 </p> <p>H15876-40 0209.S9 84 Ø 1,53 mm 5 </p>	<p>T08280-00 0204.65 (10x)</p> <p></p>	<p>X07796-01 0249.46</p> <p></p>	<p>N90300-00 0249.48 (8x) P76531-00 0249.48</p> <p>8x</p>	<p>X51239-01 ⑦ 0348.J0</p> <p></p>	<p>X03013-01 1721.01</p> <p></p>	<p>X07793-01 0304.34</p> <p></p>	<p>P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM</p>	
1.9 XUD9TE 66-68 kW XUD9TE (90-92 PS) (DHX) XUD9TE (DHY) XUD9TE (D8B) XUD9UTF (D8C)	BOXER BOXER Bus TD BOXER TD EXPERT TD	03/94→	<p>S31582-00 ⑫ ⑬ 0197.H5</p> <p></p> <p>D31582-00 0197.37</p> <p></p> <p>B31582-00 ⑬</p>	<p>H02360-00 0209.Q5 1,65 mm</p> <p>H12360-10 0209.Q6 1,75 mm</p> <p></p> <p>H05877-00 0209.Q8 1,36 mm 1 MLS</p> <p>H05877-10 0209.Q9 1,4 mm 2 MLS</p> <p>H05877-20 0209.R0 1,44 mm 3 MLS</p> <p>H15877-30 0209.R1 1,48 mm 4 MLS</p> <p>H15877-40 0209.R2 84 Ø 1,53 mm 5 MLS</p> <p></p>	<p>T02360-00 0204.73 (10x)</p> <p></p>	<p>X07796-01 0249.46</p> <p></p>	<p>N90300-00 0249.48 (8x) P76531-00 0249.48</p> <p>8x</p>	<p>X51239-01 ⑦ 0348.J0</p> <p></p>	<p>X03013-01 1721.01</p> <p></p>	<p>X07793-01 0304.34</p> <p></p>	<p>P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM</p>	

PEUGEOT												
Ltr.			1									
2,0 DW10ATED (RHZ) DW10BTED (RHX) DW10TD (RHY)	66-80 kW (90-109 PS) EXPERT HDI PARTNER HDI	02/00→	 	S36550-00 ⑫ ⑬ 0197.X4 +0249.99 D36550-00 ⑫ 0197.X3 +0249.99 B32989-00 ⑬	H05133-00 0209.X5 1,3 mm 1 MLS H05133-10 0209.X6 1,35 mm 2 MLS H05133-20 0209.X7 1,4 mm 3 MLS H15133-30 0209.X8 1,45 mm 4 MLS H15133-40 0209.X9 86 Ø 1,5 mm 5 MLS 	T05133-00 0204.A6 (10x) 	X53885-01 0249.99 	N92991-00 0956.38 (8x) Mot.→08331 N92635-00 0956.48 (8x) Mot.08332→ P76662-00 0956.38 8x Mot.→08331 P76698-00 0956.48 8x Mot.08332→	X58968-01 0348.N4 	X52326-01 0349.H4 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM
2,0 DW10ATED4 (RHW)	80 kW (109 PS) EXPERT EXPERT HDI	07/00→	 	S36517-00 ⑫ ⑬ 0197.Y6 D36517-00 ⑫ 0197.Y7 +0249.A6 B36517-00 ⑬	H01900-00 0209.AV 86 Ø 1,25 mm 2 MLS H11900-10 0209.AW 86 Ø 1,3 mm 3 MLS H21900-20 0209.AX 86 Ø 1,35 mm 4 MLS H31900-30 0209.AY 86 Ø 1,4 mm 5 MLS 	T17586-00 0204.96 (10x) 	X53953-01 0249.A6 	N92635-00 0956.48 (8x) 2x P76698-00 0956.48 16x	X81070-01 0349.J2 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM	

PEUGEOT												
Ltr.												
2,0 DW10UTD (RHV)	62 kW (84 PS) BOXER Bus HDI BOXER HDI	08/01→		<p>S36550-00 ¹² ¹³ 0197.X4 +0249.99</p> <p></p> <p>D36550-00 ¹² 0197.X3 +0249.99</p> <p></p> <p>B32989-00 ¹³</p>	<p>H05133-00 0209.X5 1,3 mm 1 </p> <p>MLS</p> <p>H05133-10 0209.X6 1,35 mm 2 </p> <p>MLS</p> <p>H05133-20 0209.X7 1,4 mm 3 </p> <p>MLS</p> <p>H15133-30 0209.X8 1,45 mm 4 </p> <p>MLS</p> <p>H15133-40 0209.X9 86 Ø 1,5 mm 5 </p> <p>MLS</p> <p></p>	<p>T05133-00 0204.A6 (10x)</p> <p></p>	<p>X53885-01 0249.99</p> <p></p>	<p>N92635-00 0956.48 (8x)</p> <p>P76698-00 0956.48</p>	<p>X58968-01 0348.N4</p> <p>8x </p>	<p>X52326-01 0349.H4</p> <p></p>	<p>70-31414-10</p> <p></p>	<p>P76151-01 K ← 0326.12 42x62x7 A RD FPM</p> <p>P76386-01 K → 0127.28 90x110x7 A SL LD FPM</p> <p>P77142-01 N 0807.28 27x47x7 A SL RD FPM</p>
2,0 DW10UTED4 (RHK)	88 kW (120 PS) EXPERT HDI EXPERT TEPEE HDI	01/07→		<p>D37090-01 ¹² 0197.AN +0348.S3</p> <p></p>	<p>H01900-00 0209.AV 86 Ø 1,25 mm 2 </p> <p>MLS</p> <p>H11900-10 0209.AW 86 Ø 1,3 mm 3 </p> <p>MLS</p> <p>H21900-20 0209.AX 86 Ø 1,35 mm 4 </p> <p>MLS</p> <p>H31900-30 0209.AY 86 Ø 1,4 mm 5 </p> <p>MLS</p> <p></p>	<p>T05133-00 0204.A6 (10x)</p> <p></p>	<p>V37090-00 0348.S3</p> <p></p>	<p>N92635-00 0956.48 (8x)</p> <p>P76698-00 0956.48</p>	<p>2x</p> <p>16x</p>	<p>X82339-01 0349.L9</p> <p></p>	<p>70-31414-10</p> <p></p>	<p>P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE</p> <p>P77465-01 K → 0127.45 90x110x7 A SL LD PTFE</p> <p>P77142-01 N 0807.28 27x47x7 A SL RD FPM</p>
2,0 EW10 (RFH)	103 kW (140 PS) EXPERT	01/07→		<p>S80781-00 ¹² ¹³ ¹⁹ D80781-00 ¹² ¹⁹ B38333-00 ¹³</p>	<p>H80781-00 0209.FS MLS</p> <p></p>	<p>T80768-00 0204.A3 (10x)</p> <p></p>	<p>N92657-00 0956.45 (16x)</p> <p>P76657-00 0956.45</p>	<p>X89881-01 0348.S2</p> <p>4x</p> <p>16x </p>	<p>X82335-01 0349.L4</p> <p></p>	<p>70-31414-10</p> <p></p>	<p>P77304-02 K ← 16 08 940 680 40x55x6 A SL RD PTFE</p> <p>P76386-01 K → 0127.28 90x110x7 A SL LD FPM</p> <p>P76133-01 N 0236.21 36x50x7 A RD FPM</p> <p>P77626-01 N 0236.74 39x50x7 A SL RD</p>	

PEUGEOT												
Ltr. 												
2,0 EW10J4 (RFN) 100 kW (136 PS)	EXPERT	07/00→	S36504-00 ⑫ ⑬ 0197.Y1 +0209.Z3 +0249.A4 +0249.A5 D36504-00 ⑫ B36503-00 ⑬	H80351-00 0209.Z3 85,5 Ø MLS 	T07586-00 0204.A7 (10x) 	X53933-01 L 0249.A4  X53934-01 R 0249.A5 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X86822-01 0348.P1  4x	X81109-01 0349.H8 	70-31414-10 	P77304-02 K ← 16 08 940 680 40x55x6 A SL RD PTFE P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM	
2,0 XN1P XN1T (170) XN1T (170B)	55-58 kW (75-79 PS) J5 J5 Bus	09/81-09/90	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 R30547-00 ③	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T02666-00 0204.21 (10x) →06/85  T02760-00 0204.51 (10x) 07/85-04/89  T01025-00 0204.57 (10x) 05/89→ 	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 0348.33  8x	X04833-01 0349.03 	X04848-01 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 2x 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR	
2,0 XN1P	57 kW (78 PS) J9 J9 Bus	03/80-06/87	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 R30547-00 ③	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T02666-00 0204.21 (10x) →06/85  T02760-00 0204.51 (10x) 07/85→ 	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 0348.33  8x	X04833-01 0349.03 	X04848-01 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 2x 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR	
2,0 XN1T	55 kW (75 PS) J5	09/87-08/90	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 R30547-00 ③	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T02760-00 0204.51 (10x) →04/89  T01025-00 0204.57 (10x) 05/89→ 	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 0348.33  8x	X04833-01 0349.03 	X04848-01 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 2x 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR	
2,0 XU10J2 (RFW) 80-81 kW XU10J2U (RFL)	BOXER BOXER Bus	03/94→	S31581-00 ⑫ ⑬ 9568993 D31581-00 ⑫ 0197.G6 +0209.J8 B31581-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56171-01 0348.F6  2x X56170-01 ⑩ 0348.E6  2x	X01022-01 0349.70 	70-31414-10 	P76151-01 K ← 2x 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM	

PEUGEOT												
Ltr.												
2,1 XDPX90	41 kW (56 PS)	J9 D	03/80-06/87	S30226-00 ⑬ 0198.14 Mot.→4586483 S30794-00 ⑫ ⑬ 0198.40 Mot.4586484→ D30226-00 0197.08 Mot.→4586483 D30794-00 ⑫ 0197.09 Mot.4586484→ B30756-00 ⑬ ⑯ Mot.4572282→ R30794-00 ③	H02668-00 0209.L2 94 Ø Mot.→4586483 H07635-00 0203.70 1,6 mm Mot.4586484→ H17635-10 94 Ø 1,7 mm Mot.4586484→ 		X06833-01 0249.25 NBR 	N90270-00 0956.01 (8x)	X06855-01 0348.52 3x 	X07092-01 0349.08 2x X05087-01 ⚠ 1710.15 X07094-01 ⚠ 1710.07 X07489-01 ⚠ 1710.19 	X03048-01 0313.19 X07098-01 0304.12 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76005-01 N 16x21x4,5 NBR
2,1 XDP90	42 kW (57 PS)	J7 Bus D J7 D	08/68-07/77	S30226-00 ⑬ 0198.14 Mot.→4586483 S30794-00 ⑫ ⑬ 0198.40 Mot.4586484→ D30226-00 0197.08 Mot.→4586483 D30794-00 ⑫ 0197.09 Mot.4586484→ B30756-00 ⑬ ⑯ Mot.4572282→ R30794-00 ③	H02668-00 0209.L2 94 Ø Mot.→4586483 H07635-00 0203.70 1,6 mm Mot.4586484→ H17635-10 94 Ø 1,7 mm Mot.4586484→ 		X06833-01 0249.25 NBR 	N90270-00 0956.01 (8x)	X06855-01 0348.52 3x 	X07092-01 0349.08 2x X05087-01 ⚠ 1710.15 X07094-01 ⚠ 1710.07 X07489-01 ⚠ 1710.19 	X03048-01 0313.19 X07098-01 0304.12 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76005-01 N 16x21x4,5 NBR
2,2 DW12UTED (4HY)	74 kW (101 PS)	BOXER Bus HDI BOXER HDI	04/02→	S36550-00 ⑫ ⑬ 0197.X4 +0249.99 D36550-00 ⑫ 0197.X3 +0249.99 	H06254-00 0209.AQ 1,25 mm 1 ■ MLS H06254-10 0209.AR 1,3 mm 2 ■ MLS H06254-20 0209.AS 1,35 mm 3 ■ MLS H16254-30 0209.AT 86 Ø 1,4 mm 4 ■ MLS 	T17586-00 0204.96 (10x) 	X53885-01 0249.99 	N92635-00 0956.48 (8x) P76698-00 0956.48	X58968-01 0348.N4 8x 	X52326-01 0349.H4 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM

PEUGEOT																					
2,3	XD2PX94 XD2P94	49 kW (67 PS)	J7 Bus D J7 D J9 Bus D J9 D	07/77-07/82	A30243-00 ¹² ¹⁴ 0197.25 S30243-00 ¹³ D30243-00 ¹² 0197.08 	H06656-00 0209.C2 1,58 mm 2 H16656-10 0209.C4 96 Ø 1,7 mm 3 		X06833-01 0249.25 NBR 		X08241-01 0349.44 	2x		X07092-01 0349.08 X08240-01 1710.34 X08245-01 ¹⁰ 1710.15 	2x	X08253-01 	P76150-01 K ← 0514.11 42x60x8 A RD FPM X08246-01 K → 2x 1227968610					
2,5	CRD93	54 kW (73 PS)	J5 J5 Bus D J5 D	09/81-03/94	S30253-00 ¹² ¹³ 75513625 D30253-00 ¹² B30253-00 ¹³	H06666-00 0209.75 96.3 Ø 	T06345-00 0204.41 (8x) +0204.42 (9x) 	X00742-01 5 450 155 NBR X01015-01 0249.45 	N91300-00 5469955 P76531-00 0249.48 P76543-00 0956.05	X00837-01 	4x		X00881-01 0349.F0 X07493-01 ¹⁰ 5 434 181 	4x	X07498-01 7543388080B 	P76178-11 K ← 48x65x10 A NBR P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ					
2,5	CRD93L CRD93LS	70 kW (95 PS)	J5 Bus TD J5 DT J5 TD	09/81-03/94	S31052-00 ¹² ¹³ 95593755 D31052-00 ¹² B31052-00 ¹³	H06345-00 0209.L6 95,6 Ø 	T06345-00 0204.41 (8x) +0204.42 (9x) 	X01015-01 0249.45 	N91300-00 5469955 P76531-00 0249.48 P76543-00 0956.05	X00837-01 	4x		X00881-01 0349.F0 	4x	X07498-01 7543388080B 	P76314-01 K ← 0514.32 75x90x11,5 A SL RD FPM P76368-11 K → 26126699J 95x112x12,5 LD FPM P76183-01 N 48x72x10 RD FPM					
2,5	DJ5 (T9A)	63 kW (86 PS)	BOXER Bus D BOXER D	03/94-04/02	S32148-00 ¹² ¹³ 0197.T7 +0209.R3 D32148-00 ¹² 0197.T6 +0209.R3 B32148-00 ¹³	H50390-00 0209.R3 93 Ø 	T50390-00 0204.74 (14x) +0204.75 (8x) 	X53585-01 0249.79 	N92450-00 0956.19 (12x) P76532-00 0956.19	X56189-01 0348.K1 X57008-01 ¹⁰ 0348.F9 	12x		X51508-01 0349.E7 		70-31414-10 	P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P76098-01 N ← 0807.14 35x50x7 A SL RD FPM P76034-01 N → ²⁸ 0807.15 40x62x7 A SL LD ACM FPM P76047-01 N → ²⁷ 0807.21 47,5x62x7 A SL LD ACM FPM					

PEUGEOT												
Ltr.			1									
2,5 DJ5T (T8A) 76 kW (103 PS)	BOXER Bus TD BOXER TD	03/94-04/02	<p>S32148-00 ⑫ ⑬ 0197.T7 +0209.R3</p> <p>D32148-00 ⑫ 0197.T6 +0209.R3</p> <p>B32148-00 ⑬</p>	<p>H50390-00 0209.R3 93 Ø</p>	<p>T50390-00 0204.74 (14x) +0204.75 (8x)</p>	<p>X53585-01 0249.79</p>	<p>N91190-00 0956.19 (8x)</p> <p>P76532-00 0956.19</p>	<p>X56189-01 0348.K1</p> <p>12x X57008-01 ⑩ 0348.F9</p>	<p>X51508-01 0349.E7</p>	<p>70-31414-10</p>	<p>P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM</p> <p>P76065-01 K → 0119.14 98x120x7 A SL LD FPM</p> <p>P76098-01 N ← 0807.14 35x50x7 A SL RD FPM</p> <p>P76034-01 N → ⑳ 0807.15 40x62x7 A SL LD ACM FPM</p> <p>P76047-01 N → ㉑ 0807.21 47,5x62x7 A SL LD ACM FPM</p>	
2,5 DJ5TED (THX) 79 kW (107 PS)	BOXER Bus TDI BOXER TDI	01/97-04/02	<p>S32990-00 ⑫ ⑬ 0197.W4 +0209.T5</p> <p></p> <p>D32990-00 ⑫ 0197.W3 +0209.T5</p> <p></p> <p>B32148-00 ⑬</p>	<p>H80034-00 0209.T5 93 Ø</p>	<p>T80034-00 0204.87 (14x) +0204.88 (8x)</p>	<p>X53585-01 0249.79</p>	<p>N91190-00 0956.19 (8x)</p> <p>P76532-00 0956.19</p>	<p>X58971-01 2x 0348.K4</p> <p>8x </p>	<p>X52328-01 0349.G4</p>	<p>70-31414-10</p>	<p>P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM</p> <p>P76065-01 K → 0119.14 98x120x7 A SL LD FPM</p> <p>P76098-01 N V 0807.14 35x50x7 A SL RD FPM</p> <p>P77143-01 N H 0807.26 32x52x7 A SL LD FPM</p>	
2,5 XD3P 53 kW (72 PS)	J9 Bus D J9 D	07/82-06/87	<p>S30241-00 ⑫ ⑬ 0197.P0</p> <p></p> <p>D30241-00 ⑫ 0197.N9</p> <p></p>	<p>H07986-00 1,53 mm 2 </p> <p>H17986-10 1,63 mm 3 </p> <p>H27986-20 0209.C6 96 Ø</p> <p>H27986-20 1,73 mm 4 </p>	<p>T16656-00 0204.55 (15x) +0204.56 (7x) cyl.head height 83mm</p> <p>T17986-00 0204.54 (8x) +0204.55 (7x) +0204.56 (7x) cyl.head height 73mm</p>	<p>X06833-01 0249.25 NBR</p>	<p>N92637-00 0956.01 (8x)</p>	<p>X08241-01 2x 0349.44</p>	<p>X08240-01 1710.34</p> <p>X08245-01 </p> <p>1710.15</p>	<p>X08253-01</p>	<p>P76150-01 K ← 0514.11 42x60x8 A RD FPM</p> <p>X08246-01 K → 2x 1227968610</p>	
2,8 8140.43S (F28DTCR) 93-94 kW (126-128 PS)	BOXER Bus HDI BOXER HDI	10/00→	<p>S38249-02 ⑫ ⑭ 0197.Y2</p> <p></p> <p>D38249-02 ⑫</p> <p></p>	<p>H08023-01 0209.0C 1,3 mm</p> <p>H18023-11 0209.0E 1,4 mm</p> <p>H28023-21 0209.0F 1,5 mm</p>	<p>X53812-01 X 0249.C3</p> <p>X59298-01 0249.A0</p>	<p>N93138-00 P76804-00</p>	<p>X07692-01 4x 8x </p>	<p>X51326-11 0349.H5</p>	<p>4x X54494-01 X NBR</p> <p>X59306-01 Gummi</p>			