

VOLKSWAGEN														
Ltr.			<b>1</b>											
0,9 HA	29 kW (40 PS)	DERBY POLO	→866 2500 000 09/75-09/81 →866 2500 000	<b>S30579-00</b> <sup>12</sup> <sup>13</sup> 052198001 <b>D30579-00</b> <sup>12</sup> 052 198 012 AE <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H03693-00</b> 052 103 383 AA 71 Ø 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X03744-01</b> <sup>12</sup> <sup>13</sup> 052 103 483 A Kork 	<b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X03745-01</b> 030 129 717 D →07/79 8x 	<b>X03742-01</b> 036 129 717 C 08/79→ 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>12</sup> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
0,9 HA	29 kW (40 PS)	DERBY POLO	867 2300 001→ 09/75-09/81 867 2300 001→	<b>S30580-00</b> <sup>12</sup> <sup>13</sup> 052198001L <b>D30580-00</b> <sup>12</sup> 052 198 012 AF <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H04132-00</b> 052 103 383 AB 71 Ø 	<b>T04132-00</b> 049 103 385 (10x) 	<b>X03744-01</b> <sup>12</sup> <sup>13</sup> 052 103 483 A Kork 	<b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X03745-01</b> 030 129 717 D →07/79 8x 	<b>X03742-01</b> 036 129 717 C 08/79→ 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>12</sup> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,0 AAK HZ	33-37 kW (45-50 PS)	GOLF POLO	01/85-09/94	<b>S31187-00</b> <sup>12</sup> <sup>13</sup>  <b>D31187-00</b> <sup>12</sup> 030 198 012 A <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V31187-00</b> 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X03745-01</b> 030 129 717 D 8x 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>12</sup> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM		
1,0 AAU ACM	33 kW (45 PS)	POLO	→80 N 500 000 01/85-09/94	<b>S31187-00</b> <sup>12</sup> <sup>13</sup>  <b>D31187-00</b> <sup>12</sup> 030 198 012 A <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V31187-00</b> 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X03745-01</b> 030 129 717 D 8x 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>12</sup> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM		
1,0 AAU ACM	33 kW (45 PS)	POLO	80 P 000 001→ 01/85-09/94	<b>S32714-00</b> <sup>12</sup> <sup>13</sup> <b>D32714-00</b> <sup>12</sup> 030 198 012 B <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V31187-00</b> 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X03745-01</b> 030 129 717 D 8x 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>12</sup> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM		

VOLKSWAGEN													
1,0 AER	37 kW (50 PS)	LUPO POLO	09/96-07/05	<b>D32949-00</b> <sup>12</sup> 030 198 012 F <b>B32705-00</b> <sup>13</sup> 030 198 011 A Mot.→AER 220 083 <b>B32949-00</b> <sup>13 35</sup> Mot.AER 220 084→	<b>H50943-00</b> 030 103 383 AK 68 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>M37167-00</b> 030 198 717 8x 		<b>X51584-01</b> 032 253 039 E 	<b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM Mot.→AER 220 083 <b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR Mot.AER 220 084→ <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AER 220 083 <b>P77317-01 K</b> → 028 103 171 B PTFE Mot.AER 220 084→ <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1,0 AEV	33 kW (45 PS)	POLO	10/94-12/99	<b>S32710-00</b> <sup>12 13</sup> <b>D32710-00</b> <sup>12</sup> 030 198 012 D <b>B32705-00</b> <sup>13</sup> 030 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X58344-01</b> 030 129 717 D 8x 		<b>X51584-01</b> 032 253 039 E 	<b>X03370-01</b> 032 103 609 B 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1,0 AHT	37 kW (50 PS)	LUPO	10/98-05/00	<b>D36701-00</b> <sup>12</sup> <b>B36701-00</b> <sup>13</sup>	<b>H80471-00</b> 047 103 383 B 73,5 Ø 	<b>T80471-00</b> N 907 957 01 (5x) +N 907 958 01 (4x) +N 907 956 01 (1x) 	<b>X53041-01</b> 047 103 483 NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X87468-01</b> 047 129 717 B 2x 		<b>X81438-01 L</b> 047 253 039 H  <b>X81439-01</b> 047 253 050  <b>X81682-01 R</b> 047 253 039 J 	<b>X54718-01</b> 047 103 609 B 	<b>P76230-01 K</b> ← 047 103 085 42x58x8 A SL RD FPM <b>P77290-01 K</b> → 047 103 085 A 85x105x12 A SL LD FPM
1,0 ALD ANV AUC	37 kW (50 PS)	LUPO POLO	09/98-07/05	<b>D32950-00</b> <sup>12</sup>	<b>H80093-00</b> 030 103 383 BE 68 Ø MLS 	<b>T50493-00</b> WHT 001 808 (10x) 		<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	<b>M37167-00</b> 030 198 717 8x 		<b>X51580-01</b> 030 253 039 H 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77350-01 K</b> → 030 103 171 K PTFE <b>P77313-01 N</b> 036 103 085 H 32x42x6/7 A SL RD NBR

VOLKSWAGEN													
1,0 ALL	37 kW (50 PS)	LUPO POLO	09/96-07/05	<b>D32949-00</b> <sup>12</sup> 030 198 012 F <b>B32949-00</b> <sup>13 35</sup>	<b>H50943-00</b> 030 103 383 AK 68 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>M37167-00</b> 030 198 717 8x 		<b>X51584-01</b> 032 253 039 E 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77317-01 K</b> → 028 103 171 B PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1,0 AQZ AZN BJE BJR BNW BNX BTY CCNA	40-56 kW (54-76 PS)	GOL VOYAGE	10/05→	<b>D37194-00</b> <sup>12</sup>	<b>H80796-00</b> 036 103 383 AF 68 Ø MLS 	<b>T80786-00</b> WHT 001 865 (10x) 	<b>70-31414-10</b> 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	<b>X89552-01</b> 030 129 717 E 8x 	4x	<b>X51580-01</b> 030 253 039 H 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77313-01 N</b> 036 103 085 H 32x42x6/7 A SL RD NBR
1,0 ARA	43-58 kW (58-79 PS)			<b>D37195-00</b> <sup>12</sup> <b>B37195-00</b> <sup>14</sup>	<b>H80796-00</b> 036 103 383 AF 68 Ø MLS 	<b>T80344-00</b> 036 103 384 E (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X58340-01</b> 030 129 717 F 16x 	4x	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR
1,0 AZP	51 kW (69 PS)	GOL	09/97-05/02	<b>B37195-00</b> <sup>14</sup>	<b>H80796-00</b> 036 103 383 AF 68 Ø MLS 	<b>T80344-00</b> 036 103 384 E (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X58997-01</b> 036 129 717 E 16x 	4x	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR
1,0 CHYA CHYB	44-55 kW (60-75 PS)	POLO	01/14→	<del><b>S40694-00</b> <sup>12 13 35</sup></del> <del><b>D40694-00</b> <sup>12</sup></del>	<b>H40694-00</b> 04C 103 383 H 75,5 Ø MLS 	<b>T40706-01</b> WHT 004 926 (8x) 	<b>X59949-01</b> 04C 103 483 E 	<b>N93196-01</b> 04E 109 675 (6x) +04E 109 675 A (6x) <b>P76960-00 AS</b> 04E 109 675 A <b>P76961-00 ES</b> 04E 109 675	<b>X58997-01</b> 036 129 717 E 6x 	3x	<b>X59947-01</b> 1S0 253 115 B 	<b>70-31414-10</b> 	<b>P77841-01 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01 N</b> → 04E 103 085 24x39x8 A SL LD PTFE
1,0 CHYA CHYB	44-55 kW (60-75 PS)	UP	08/11→	<del><b>S40694-00</b> <sup>12 13 35</sup></del> <del><b>D40694-00</b> <sup>12</sup></del>	<b>H40694-00</b> 04C 103 383 H 75,5 Ø MLS 	<b>T40706-01</b> WHT 004 926 (8x) 	<b>X59875-01</b> 04C 103 483 B →04/13 	<b>N93196-01</b> 04E 109 675 (6x) +04E 109 675 A (6x) <b>P76960-00 AS</b> 04E 109 675 A <b>P76961-00 ES</b> 04E 109 675	<b>X58997-01</b> 036 129 717 E 6x 	3x	<b>X59947-01</b> 1S0 253 115 B 	<b>70-31414-10</b> 	<b>P77841-01 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01 N</b> → 04E 103 085 24x39x8 A SL LD PTFE

VOLKSWAGEN												
Ltr.			<b>1</b>									
1,0 CPBA	54 kW (73 PS)				<b>H80796-00</b> 036 103 383 AF 68 Ø MLS 	<b>T80786-00</b> WHT 001 865 (10x) 	<b>70-31414-10</b> 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x		<b>X51580-01</b> 030 253 039 H 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR
1,0 CPGA	50 kW (68 PS)	UP	11/12→	<del><b>S40699-00</b> <sup>12 13 38</sup></del> <del><b>D40699-00</b> <sup>12</sup></del> 	<b>H40699-00</b> 04C 103 383 N 75,5 Ø MLS 	<b>T40706-01</b> WHT 004 926 (8x) 	<b>X59875-01</b> 04C 103 483 B →04/13  <b>X59949-01</b> 04C 103 483 E 05/13→ 	<b>N93197-00</b> 04E 109 675 A (12x) <b>P76960-00</b> 04E 109 675 A 12x	<b>X58997-01</b> 036 129 717 E 3x  <b>X59876-01</b> 04C 129 717 B 	<b>70-31414-10</b> 	<b>P77841-01 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01 N</b> → 04E 103 085 24x39x8 A SL LD PTFE	
1,0 CSEA CSEZ CWRA <b>[NEW]</b>	55-60 kW (75-82 PS)			<b>S84797-00</b> <sup>12 13 38</sup> <b>D84796-00</b> <sup>12</sup> 	<b>H40699-00</b> 04C 103 383 N 75,5 Ø MLS 	<b>T40706-01</b> WHT 004 926 (8x) 	<b>X59949-01</b> 04C 103 483 E 	<b>N93196-01</b> 04E 109 675 (6x) +04E 109 675 A (6x) <b>P76960-00 AS</b> 04E 109 675 A <b>P76961-00 ES</b> 04E 109 675 6x 6x	<b>X58997-01</b> 036 129 717 E 3x  <b>X59876-01</b> 04C 129 717 B 	<b>X59947-01</b> 1S0 253 115 B 	<b>70-31414-10</b> 	<b>P77841-01 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01 N</b> → 04E 103 085 24x39x8 A SL LD PTFE
1,0 GL GN	29-33 kW (40-45 PS)	DERBY GOLF POLO	10/81-10/86	<b>S32711-00</b> <sup>12 13</sup> <b>D32711-00</b> <sup>12</sup> 052 198 012 R <b>B30579-00</b> <sup>13</sup> 052 198 011 A 	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 	<b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X58344-01</b> 030 129 717 D 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1,1 FA GG HB HC	37-44 kW (50-60 PS)	GOLF POLO SCIROCCO	04/74-07/83	<b>S30579-00</b> <sup>12 13</sup> 052198001 →06/76 <b>S30580-00</b> <sup>12 13</sup> 052198001L 07/76→ <b>D30579-00</b> <sup>12</sup> 052 198 012 AE →06/76 <b>D30580-00</b> <sup>12</sup> 052 198 012 AF 07/76→ <b>B30579-00</b> <sup>13</sup> 052 198 011 A 	<b>H03693-00</b> 052 103 383 AA 71 Ø →06/76  <b>H04132-00</b> 052 103 383 AB 71 Ø 07/76→ 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X03744-01</b> <sup>13</sup> 052 103 483 A Kork  <b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X03742-01</b> <sup>13</sup> 036 129 717 C  <b>X03745-01</b> 030 129 717 D 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN														
1,1 FJ	38 kW (52 PS)	GOLF		08/76-07/80	<b>S30580-00</b> <sup>12</sup> <sup>13</sup> 052198001L <b>D30580-00</b> <sup>12</sup> 052 198 012 AF <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H04132-00</b> 052 103 383 AB 71 Ø 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X03742-01</b> 036 129 717 C 8x  <b>X03745-01</b> 030 129 717 D 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM	
1,1 HB	37 kW (50 PS)	DERBY		02/77-09/81	<b>S30580-00</b> <sup>12</sup> <sup>13</sup> 052198001L <b>D30580-00</b> <sup>12</sup> 052 198 012 AF <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H04132-00</b> 052 103 383 AB 71 Ø 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X03744-01</b> ✕ 052 103 483 A Kork  <b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X03742-01</b> ✕ 036 129 717 C 8x  <b>X03745-01</b> 030 129 717 D 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> <sup>13</sup> 861 253 115 A 	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM	
1,2 ANY AYZ	45 kW (61 PS)	LUPO TDI		07/99-07/05	<b>D36624-00</b> <sup>12</sup>  <b>B32959-00</b> <sup>13</sup> <sup>38</sup> 	<b>H09197-00</b> 045 103 383 C 1,45 mm 1 MLS <b>H19197-10</b> 045 103 383 D 1,53 mm 2 MLS <b>H29197-20</b> 045 103 383 E 77,5 Ø 1,61 mm 3 MLS 		<b>X83111-01</b> 045 103 483 C NBR 	<b>N92001-00</b> 027 109 675 (6x) <b>P76532-00</b> 027 109 675	<b>X86491-01</b> 045 129 717 6x 	<b>X52968-01</b> 045 253 039 	<b>70-31414-10</b> 	<b>P76096-11</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM	
1,2 AWY BMD	40 kW (54-55 PS)	FOX POLO	→9N 5 044 100, 9N 5Y 138 500	01/02→	<b>D36702-00</b> <sup>12</sup> <b>B36702-00</b> <sup>13</sup>	<b>H80386-00</b> 03D 103 383 G 77,5 Ø MLS 	<b>T80386-00</b> WHT 001 808 (8x) 	<b>70-31414-10</b> 	<b>N92024-00</b> 036 109 675 (6x) <b>P76662-00</b> 036 109 675	<b>X88298-01</b> 03D 129 717 A 3x 	<b>X81435-01</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01</b> K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	
1,2 AWY BMD	40 kW (54-55 PS)	FOX POLO	9N 5 044 101, 9N 5Y 138 001→	01/02→	<b>D36702-00</b> <sup>12</sup> <b>B36702-00</b> <sup>13</sup>	<b>H80386-00</b> 03D 103 383 G 77,5 Ø MLS 	<b>T80386-00</b> WHT 001 808 (8x) 	<b>70-31414-10</b> 	<b>N92024-00</b> 036 109 675 (6x) <b>P76662-00</b> 036 109 675	<b>W88299-01</b> 03D 129 717 B 3x 	<b>X81435-01</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01</b> K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	
1,2 AZQ BME BZG CGPA CGPB CJLA	44-55 kW (60-75 PS)	POLO		10/01→	<b>D36703-00</b> <sup>12</sup> <b>B36702-00</b> <sup>13</sup>	<b>H80385-00</b> 03E 103 383 F 77,5 Ø MLS 	<b>T80385-00</b> 036 103 384 B (8x) 	<b>70-31414-10</b> 	<b>N92993-00</b> 036 109 675 (12x) <b>P76662-00</b> 036 109 675	<b>W88302-01</b> 03E 129 717 B 3x 	<b>X81445-01</b> 03E 253 039 A 	<b>70-31414-10</b> 	<b>P76096-11</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01</b> K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	

VOLKSWAGEN														
1,2 Ltr.	BBM CHFB	40-44 kW (55-60 PS)	FOX POLO	04/05→	<b>D36702-00</b> <sup>12</sup> <b>B36702-00</b> <sup>13</sup>	<b>H80386-00</b> 03D 103 383 G 77,5 Ø MLS 	<b>T80386-00</b> WHT 001 808 (8x) 	<b>70-31414-10</b> 	<b>N92024-00</b> 036 109 675 (6x) <b>P76662-00</b> 036 109 675	<b>W88299-01</b> 03D 129 717 B 6x 	3x	<b>X81435-01</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
1,2 Ltr.	CBZA CBZB CBZC	63-77 kW (86-105 PS)	BEETLE TSI CADDY TSI GOLF TSI JETTA TSI POLO TSI TOURAN TSI	11/08→	<del><b>D40579-00</b></del> <del><b>B38301-00</b></del> <sup>13</sup> <sup>35</sup>	<b>H40579-00</b> 03F 103 383 E 72 Ø MLS 	<b>T40579-00</b> WHT 004 790 (10x) 	<b>X59883-01</b> ✕ 03F 103 483 A Metall  <b>70-31414-10</b> 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	<b>X59475-01</b> 03F 129 717 A 8x 	1x	<b>X82520-01</b> 03F 253 041 P 	<b>70-31414-10</b> 	<b>P77181-01 K</b> ← 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE
1,2 Ltr.	CFWA	55 kW (75 PS)	POLO TDI	10/09→	<b>D38304-00</b> <sup>12</sup> <b>B38298-00</b> <sup>14</sup>	<b>H40645-00</b> 03P 103 383 C 82 Ø 1,55 mm 1 MLS <b>H40645-10</b> 03P 103 383 D 82 Ø 1,63 mm 2 MLS <b>H40645-20</b> 03P 103 383 E 82 Ø 1,71 mm 3 MLS 	<b>T50034-01</b> WHT 002 131 (8x) 	<b>X59485-01</b> 03P 103 483 	<b>N92993-00</b> 036 109 675 (12x) <b>P76662-00</b> 036 109 675	<b>X59473-01</b> 03P 129 717 12x 		<b>X82519-01</b> 03P 253 039 	<b>70-31414-10</b> 	<b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
1,2 Ltr.	CHFA	44 kW (60 PS)	FOX →5Z 64 000 001	09/10→	<b>D36702-00</b> <sup>12</sup> <b>B36702-00</b> <sup>13</sup>	<b>H80386-00</b> 03D 103 383 G 77,5 Ø MLS 	<b>T80386-00</b> WHT 001 808 (8x) 	<b>70-31414-10</b> 	<b>N92024-00</b> 036 109 675 (6x) <b>P76662-00</b> 036 109 675	<b>X88298-01</b> 03D 129 717 A 6x 	3x	<b>X81435-01</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
1,2 Ltr.	CHFA	44 kW (60 PS)	FOX 5Z 64 014 186→	09/10→	<b>D36702-00</b> <sup>12</sup> <b>B36702-00</b> <sup>13</sup>	<b>H80386-00</b> 03D 103 383 G 77,5 Ø MLS 	<b>T80386-00</b> WHT 001 808 (8x) 	<b>70-31414-10</b> 	<b>N92024-00</b> 036 109 675 (6x) <b>P76662-00</b> 036 109 675	<b>W88299-01</b> 03D 129 717 B 6x 	3x	<b>X81435-01</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM

VOLKSWAGEN												
1,2 CJZA CJZB	63-77 kW (86-105 PS)	GOLF TSI	08/12→	<b>D38726-00</b> <sup>12</sup> <b>B38725-00</b> <sup>13</sup> <sup>38</sup>	<b>H40705-00</b> 04E 103 383 T 72 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 	<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 04E 109 675 A <b>P76961-00</b> ES 04E 109 675	<b>X58997-01</b> 036 129 717 E 4x 8x 8x 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77881-01</b> K → 04E 103 170 A PTFE <b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01</b> N → 04E 103 085 24x39x8 A SL LD PTFE
1,2 CJZC CJZD CYVA CYVB <b>[NEW]</b>	63-81 kW (86-110 PS)	GOLF TSI POLO TSI TOURAN TSI	08/12→	<b>D38726-00</b> <sup>12</sup> <b>B38725-00</b> <sup>13</sup> <sup>38</sup>	<b>H40705-00</b> 04E 103 383 T 72 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 	<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 04E 109 675 A <b>P76961-00</b> ES 04E 109 675	<b>X58997-01</b> 036 129 717 E 4x 8x 8x 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01</b> N → 04E 103 085 24x39x8 A SL LD PTFE
1,2 D	25 kW (34 PS)	KAEFER KARMANN	09/57-12/85	<b>A30252-00</b> <sup>14</sup> 111 198 005 <b>D30252-00</b> <sup>18</sup> 113 198 101 A	<b>H03807-00</b> 4x 113 101 343 B 90 Ø 		<b>X00991-01</b> 2x 113 101 481 F Kork 			<b>X03808-01</b> 4x 111 251 261 C 		<b>P76303-01</b> K → 113 105 245 F 70x90x10 A LD ACM
1,2 M51	22 kW (30 PS)	KAEFER	01/54-07/65	<b>S37025-00</b> <sup>16</sup> 111 198 003			<b>X83114-01</b> 2x 111 101 481 		<b>X89182-01</b> 2x N 13 821 1 			
1,3 AAV NZ 2G 3F	40-57 kW (54-78 PS)	GOLF JETTA POLO	→80 N 500 000 06/86-09/94	<b>S31187-00</b> <sup>12</sup> <sup>13</sup>  <b>D31187-00</b> <sup>12</sup> 030 198 012 A <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V31187-00</b> 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X03745-01</b> 030 129 717 D 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> 861 253 115 A	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,3 AAV NZ 2G 3F	40-57 kW (54-78 PS)	POLO	80 P 000 801→ 07/87-09/94	<b>S32714-00</b> <sup>12</sup> <sup>13</sup> <b>D32714-00</b> <sup>12</sup> 030 198 012 B <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V31187-00</b> 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X03745-01</b> 030 129 717 D 8x 	<b>X03743-01</b> 030 253 039 A <b>X51310-01</b> 861 253 115 A	2x <b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN													
Ltr.													
1,3 AB AC AR E F	27-32 kW (37-44 PS) KAEFER KARMANN	07/64-03/81	<b>A30576-00</b> <sup>(14)</sup> 111 198 007 <b>D30252-00</b> <sup>(18)</sup> 113 198 101 A				<b>X00991-01</b> 113 101 481 F Kork 	2x	<b>X00995-01</b> 113 129 717 A  <b>X03811-01</b> 311 129 707 	2x	<b>X03808-01</b> 111 251 261 C 	4x	<b>P76303-01</b> K → 113 105 245 F 70x90x10 ALD ACM
1,3 ADX	40 kW (55 PS) POLO	10/94-07/95	<b>D32713-00</b> <sup>(12)</sup> 032 198 012 A <b>B32705-00</b> <sup>(13)</sup> 030 198 011 A	<b>H50505-00</b> 030 103 383 AH 77,5 Ø MLS 	<b>T50505-00</b> 032 103 384 (10x) 	<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	8x	<b>X57506-01</b> 032 129 717 C 	<b>X51584-01</b> 032 253 039 E 	<b>X03370-01</b> 032 103 609 B  70-31414-10 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM	
1,3 EP EU	44 kW (60 PS) PASSAT	08/80-07/86	<b>S31194-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>D31194-00</b> <sup>(12)</sup> 056 198 012 G <b>B30584-00</b> <sup>(13)</sup> 037 198 011 C	<b>H07850-00</b> 056 103 383 L 79 Ø 1,8 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x	<b>X04875-01</b> 026 129 717 D 	<b>X03747-01</b> 026 129 589 A  <b>X07854-01</b> <sup>(A)</sup> 841 253 115 B 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM	
1,3 FY FZ GF GS HH HJ	40-44 kW (55-60 PS) DERBY GOLF JETTA PASSAT POLO SANTANA SCIROCCO	05/73-07/88	<b>S30583-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>D30583-00</b> <sup>(12)</sup> 052 198 012 AB <b>B30579-00</b> <sup>(13)</sup> 052 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 	<b>X03744-01</b> 052 103 483 A Kork  <b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x	<b>X03742-01</b> 036 129 717 C  <b>X03745-01</b> 030 129 717 D 	<b>X03743-01</b> 030 253 039 A  <b>X51310-01</b> <sup>(A)</sup> 861 253 115 A 	<b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM	
1,3 GK GT HK HW	37-55 kW (50-75 PS) DERBY GOLF JETTA POLO SCIROCCO	08/82-09/89	<b>S32711-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>D32711-00</b> <sup>(12)</sup> 052 198 012 R <b>B30579-00</b> <sup>(13)</sup> 052 198 011 A	<b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 	<b>X53151-01</b> 052 103 483 C Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x	<b>X58344-01</b> 030 129 717 D 	<b>X03743-01</b> 030 253 039 A  <b>X51310-01</b> <sup>(A)</sup> 861 253 115 A 	<b>X03370-01</b> 032 103 609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM	



VOLKSWAGEN												
Ltr.												
1,3 MH NU	37-40 kW (50-55 PS) GOLF JETTA POLO	08/83-09/94	<p><b>S31187-00</b> <sup>12</sup> <sup>13</sup></p> <p><b>D31187-00</b> <sup>12</sup> 030 198 012 A</p> <p><b>B30579-00</b> <sup>13</sup> 052 198 011 A</p>	<p><b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm</p>	<p><b>T04125-00</b> 049 103 384 B (10x)</p>	<p><b>V31187-00</b></p>	<p><b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675</p>	<p><b>X03745-01</b> 030 129 717 D</p>	<p><b>X03743-01</b> 030 253 039 A</p> <p><b>X51310-01</b> <sup>14</sup> <sup>15</sup> 861 253 115 A</p>	<p>2x <b>X03370-01</b> 032 103 609 B</p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	
1,3 MN	33 kW (45 PS) POLO D	08/86-08/90	<p><b>S31188-00</b> <sup>12</sup> <sup>13</sup></p> <p><b>D31188-00</b> <sup>12</sup> 031 198 012 A</p> <p><b>B30579-00</b> <sup>13</sup> 052 198 011 A</p>	<p><b>H07907-00</b> 031 103 383 M 1,53 mm 1 </p> <p><b>H17907-10</b> 031 103 383 N 1,57 mm 2 </p> <p><b>H27907-20</b> 031 103 383 P 76,5 Ø 1,61 mm 3 </p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>	<p><b>V31187-00</b></p>	<p><b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675</p>	<p><b>X03745-01</b> 030 129 717 D</p>	<p><b>X03743-01</b> 030 253 039 A</p>	<p>2x <b>X03370-01</b> 032 103 609 B</p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	
1,3 PY	83-85 kW (113-115 PS) POLO G40	01/87-09/94	<p><b>D32712-00</b> <sup>12</sup> 030 198 012 C</p> <p><b>B30579-00</b> <sup>13</sup> 052 198 011 A</p>	<p><b>H80499-00</b> 030 103 383 R 1,75 mm</p>	<p><b>T04125-00</b> 049 103 384 B (10x)</p>	<p><b>X07909-01</b> 3x NBR</p> <p><b>X53500-01</b> 030 103 483 C NBR</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X58344-01</b> 030 129 717 D</p>	<p><b>X03743-01</b> 030 253 039 A</p>	<p>2x <b>X03370-01</b> 032 103 609 B</p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	
1,3 ZA ZF	40-44 kW (55-60 PS) PASSAT	05/73-01/78	<p><b>S30584-00</b> <sup>12</sup> <sup>13</sup> 056198001A</p> <p><b>D30584-00</b> <sup>12</sup> 056 198 012 D</p> <p><b>B30584-00</b> <sup>13</sup> 037 198 011 C</p>	<p><b>H04128-00</b> 049 103 383 M 78,5 Ø 1,75 mm</p>	<p><b>T04132-00</b> 049 103 385 (10x)</p>	<p><b>V30584-00</b> 026 198 025 A 8,5 mm Kork</p>	<p><b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675</p>	<p><b>X04875-01</b> 026 129 717 D</p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X07854-01</b> <sup>14</sup> 841 253 115 B</p>	<p>4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)</p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	

VOLKSWAGEN													
1,4 ABD	40-44 kW (55-60 PS)	GOLF VENTO	10/91-09/98	<p><b>S31187-00</b> <sup>12</sup> <sup>13</sup> →07/94</p> <p><b>S32714-00</b> <sup>12</sup> <sup>13</sup> Mot.→ABD 558 154</p> <p><b>S32715-00</b> <sup>12</sup> <sup>13</sup> Mot.ABD 558 155→</p> <p><b>D31187-00</b> <sup>12</sup> 030 198 012 A →07/94</p> <p><b>D32714-00</b> <sup>12</sup> 030 198 012 B Mot.→ABD 558 154</p> <p><b>D32710-00</b> <sup>12</sup> 030 198 012 D Mot.ABD 558 155→</p> <p><b>B30579-00</b> <sup>13</sup> 052 198 011 A</p>	<p><b>H04125-00</b> 030 103 383 K 76,5 Ø 1,75 mm</p>	<p><b>T04125-00</b> 049 103 384 B (10x)</p>	<p><b>V31187-00</b> →07/94</p> <p><b>X07908-01</b> 030 103 483 G NBR Mot.→ABD 558 154</p> <p><b>X53497-01</b> 030 103 483 K NBR Mot.ABD 558 155→</p>	<p><b>N90300-00</b> 026 109 675 (8x) →07/92</p> <p><b>N91190-00</b> 027 109 675 (8x) 08/92→</p> <p><b>P76531-00</b> 026 109 675 →07/92</p> <p><b>P76532-00</b> 027 109 675 08/92→</p>	<p><b>X03745-01</b> 030 129 717 D</p>	<p><b>X03743-01</b> 030 253 039 A →07/94</p> <p><b>X51584-01</b> 032 253 039 E 08/94→</p> <p><b>X51310-01</b> <sup>13</sup> 861 253 115 A</p>	<p><b>X03370-01</b> 032 103 609 B</p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>	
1,4 AEX	40-44 kW (55-60 PS)	CADDY GOLF POLO VENTO	10/91-01/04	<p><b>S32705-00</b> <sup>12</sup> <sup>13</sup> Mot.→AEX 908 121</p> <p><b>D32705-00</b> <sup>12</sup> 032 198 012 B</p> <p><b>B32705-00</b> <sup>13</sup> 030 198 011 A Mot.→AEX 908 121</p> <p><b>B32949-00</b> <sup>13</sup> <sup>35</sup> Mot.AEX 908 122→</p>	<p><b>H50505-00</b> 030 103 383 AH 77,5 Ø MLS</p>	<p><b>T50505-00</b> 032 103 384 (10x)</p>	<p><b>X53497-01</b> 030 103 483 K NBR</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>M37167-00</b> 030 198 717</p>	<p><b>X51584-01</b> 032 253 039 E</p>	<p><b>70-31414-10</b></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p>Mot.→AEX 908 121</p> <p><b>P77313-01</b> K ← 036 103 085 H 32x42x6/7 A SL RD NBR</p> <p>Mot.AEX 908 122→</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p>Mot.→AEX 908 121</p> <p><b>P77317-01</b> K → <sup>13</sup> 028 103 171 B PTFE</p> <p>Mot.AEX 908 122→</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>	
1,4 AFH	74 kW (100 PS)	POLO	04/96-10/99	<p><b>D32951-00</b> <sup>12</sup> 030 198 012 E</p> <p><b>B32705-00</b> <sup>13</sup> 030 198 011 A Mot.→AFH 030 000</p> <p><b>B37020-00</b> <sup>13</sup> <sup>35</sup> Mot.AFH 030 001→</p>	<p><b>H80266-00</b> 036 103 383 K 77,5 Ø MLS</p>	<p><b>T80266-00</b> 036 103 384 (10x)</p>	<p><b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675</p>	<p><b>X58997-01</b> 036 129 717 E</p>	<p><b>X52864-01</b> 036 253 039 C</p>	<p><b>70-31414-10</b></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p>Mot.→AFH 030 000</p> <p><b>P77317-01</b> K → <sup>13</sup> 028 103 171 B PTFE</p> <p>Mot.AFH 030 001→</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>		

VOLKSWAGEN													
1,4 AFK AKQ AQQ	55-74 kW (75-101 PS)	BORA GOLF LUPO POLO		08/97-06/06	 <b>D36621-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	 <b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS	 <b>T50943-00</b> 036 103 384 B (10x)	 <b>70-31414-10</b>	 <b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	 <b>X58997-01</b> 036 129 717 E 4x	 <b>X51579-01</b> 036 253 039 F	 <b>70-31414-10</b>	<b>P77313-01</b> K ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77818-01</b> K → 030 103 171 H PTFE <b>P77329-01</b> N 036 103 085 A 27x42x8 A SL RD NBR
1,4 AGY	62 kW (84 PS)				<b>D37196-00</b> <sup>12</sup> <b>B37196-00</b> <sup>13 35</sup>	<b>H80795-00</b> 17S 103 383 78,5 Ø MLS	<b>T50469-00</b> 050 103 384 (10x)	<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55430-01</b> 048 129 717 A 8x	<b>X03747-01</b> 026 129 589 A 4x	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P77317-01</b> K → 028 103 171 B PTFE <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,4 AHW	55 kW (75 PS)	BORA GOLF LUPO POLO	→1J 2 500 000 →1J 2 500 000 →6X 2 012 000	08/97-06/06	<b>D36621-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS	<b>T50943-00</b> 036 103 384 B (10x)	<b>70-31414-10</b>	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X58997-01</b> 036 129 717 E 4x	<b>X51579-01</b> 036 253 039 F	<b>70-31414-10</b>	<b>P77313-01</b> K ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77818-01</b> K → 030 103 171 H PTFE <b>P77329-01</b> N 036 103 085 A 27x42x8 A SL RD NBR
1,4 AKK AKP ANW AUD	40-44 kW (54-60 PS)	CADDY LUPO POLO		11/95-07/05	<b>D36554-00</b> <sup>12</sup>	<b>H80389-00</b> 030 103 383 AT 77,5 Ø MLS	<b>T50493-00</b> WHT 001 808 (10x)		<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	<b>M37167-00</b> 030 198 717 8x	<b>X51580-01</b> 030 253 039 H	<b>70-31414-10</b>	<b>P77313-01</b> K ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77350-01</b> K → 030 103 171 K PTFE <b>P77313-01</b> N 036 103 085 H 32x42x6/7 A SL RD NBR
1,4 AKV	44 kW (60 PS)	CADDY POLO		07/95-01/04	<b>S32705-00</b> <sup>12 13</sup> Mot.→AKV 095 009 <b>D32705-00</b> <sup>12</sup> 032 198 012 B <b>B32705-00</b> <sup>13</sup> 030 198 011 A Mot.→AKV 095 009 <b>B32949-00</b> <sup>13 35</sup> Mot.AKV 095 010→	<b>H50505-00</b> 030 103 383 AH 77,5 Ø MLS	<b>T50505-00</b> 032 103 384 (10x)	<b>X53497-01</b> 030 103 483 K NBR	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>M37167-00</b> 030 198 717 8x	<b>X51584-01</b> 032 253 039 E	<b>70-31414-10</b>	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM Mot.→095 009 <b>P77313-01</b> K ← 036 103 085 H 32x42x6/7 A SL RD NBR Mot.AKV 095 010→ <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AKV 095 009 <b>P77317-01</b> K → 028 103 171 B PTFE Mot.AKV 095 010→ <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
Ltr.												
1,4 AMF ATL BAY	55-66 kW (75-90 PS) LUPO TDI POLO TDI	01/99→										
			D36624-00 <sup>12</sup>  B32959-00 <sup>13 38</sup> 	H09198-00 045 103 383 AA 1,45 mm 1 MLS H19198-10 045 103 383 AB 1,53 mm 2 MLS H29198-20 045 103 383 AC 80,5 Ø 1,61 mm 3 MLS 	T09198-00 038 103 384 (8x) 	X83111-01 045 103 483 C NBR 	N92001-00 027 109 675 (6x) P76532-00 027 109 675	X86491-01 045 129 717 6x 	X52968-01 045 253 039  X52970-01 1H0 253 115 A	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM	
1,4 ANM	74 kW (101 PS)		D36621-00 <sup>12</sup>	H80140-00 036 103 383 AM 77,5 Ø MLS 	T50943-00 036 103 384 B (10x) 	70-31414-10 	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X58997-01 036 129 717 E 4x  X87493-01 03C 129 717 C 	X51579-01 036 253 039 F  X81385-01 155 253 115		P77313-01 K → 036 103 085 H 32x42x6/7 A SL RD NBR P77329-01 N 2x 036 103 085 A 27x42x8 A SL RD NBR	
1,4 ANX APQ	40-44 kW (54-60 PS) CADDY POLO	07/95-01/04	D32705-00 <sup>12</sup> 032 198 012 B B32949-00 <sup>13 35</sup>	H50505-00 030 103 383 AH 77,5 Ø MLS 	T50505-00 032 103 384 (10x) 	X53497-01 030 103 483 K NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	M37167-00 030 198 717 8x 	X51584-01 032 253 039 E 	70-31414-10 	P77313-01 K ← 036 103 085 H 32x42x6/7 A SL RD NBR P77317-01 K → 028 103 171 B PTFE P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM	
1,4 APE	55 kW (75 PS) BORA GOLF LUPO POLO →6X 2 012 000	08/97-06/06	D36621-00 <sup>12</sup> B32957-00 <sup>13 38</sup> 036 198 011	H80140-00 036 103 383 AM 77,5 Ø MLS 	T50943-00 036 103 384 B (10x) 	70-31414-10 	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X58997-01 036 129 717 E 4x 	X51579-01 036 253 039 F 	70-31414-10 	P77313-01 K ← 036 103 085 H 32x42x6/7 A SL RD NBR P77818-01 K → 030 103 171 H PTFE P77329-01 N 2x 036 103 085 A 27x42x8 A SL RD NBR	
1,4 ARR	77 kW (105 PS) LUPO FSI	02/01-07/05	D36621-00 <sup>12</sup> B32957-00 <sup>13 38</sup> 036 198 011	H80140-00 036 103 383 AM 77,5 Ø MLS 	T50943-00 036 103 384 B (10x) 	70-31414-10 	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X58997-01 036 129 717 E 4x  X87493-01 03C 129 717 C  X87494-01 <sup>10</sup> 036 129 717 K 	X51579-01 036 253 039 F  X81385-01 155 253 115	70-31414-10 	P77313-01 K ← 036 103 085 H 32x42x6/7 A SL RD NBR P77350-01 K → 030 103 171 K PTFE P77329-01 N ← 036 103 085 A 27x42x8 A SL RD NBR P77342-01 N → 036 103 085 F 35x46x7 A SL RD FPM	

VOLKSWAGEN														
1,4 AUA AXP	55 kW (75 PS)	BORA CADDY GOLF	1J 2 650 001→ 08/97-06/06 1J 2 650 001→	<b>D36621-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X58997-01</b> 036 129 717 E 4x 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77350-01 K</b> → 030 103 171 K PTFE <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR		
1,4 AUA AUB AXP	55-74 kW (75-101 PS)	BORA GOLF LUPO POLO	→1J 2 650 000 08/97-05/08 →1J 2 650 000 →6X 2 012 000 →6N 2 010 000	<b>D36621-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X58997-01</b> 036 129 717 E 4x 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77818-01 K</b> → 030 103 171 H PTFE <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR		
1,4 AXU	63 kW (86 PS)	POLO FSI	02/02-07/06	<b>S36776-00</b> <sup>12 13 38</sup> <b>D36776-00</b> <sup>12</sup>	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X87493-01</b> 03C 129 717 C 4x 	<b>X89175-01</b> <sup>10</sup> 03C 129 717 A 4x 	<b>X81446-01</b> 03C 253 039 D 	<b>X52978-01</b> <sup>10</sup> 1J0 253 115 S 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77351-01 K</b> → 030 103 171 L PTFE
1,4 BBY BBZ BCA BCC BKY BUD	55-74 kW (75-101 PS)	BORA CADDY GOLF LUPO POLO	08/97→	<b>D36621-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X58997-01</b> 036 129 717 E 4x 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR		
1,4 BKG BLN	66 kW (90 PS)	GOLF FSI	10/03-11/06	<b>S36776-00</b> <sup>12 13 38</sup> <b>D36776-00</b> <sup>12</sup>	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X87493-01</b> 03C 129 717 C 4x 	<b>X89175-01</b> <sup>10</sup> 03C 129 717 A 4x 	<b>X81446-01</b> 03C 253 039 D 	<b>X52978-01</b> <sup>10</sup> 1J0 253 115 S 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77376-01 K</b> → 030 103 171 S PTFE
1,4 BKR BLM BTJ CNBA <b>[NEW]</b>	55-63 kW (75-86 PS)	FOX	04/05→	<b>D37167-00</b> <sup>12</sup> <b>B37167-00</b> <sup>13 38</sup>	<b>H80786-00</b> 032 103 383 N 77,7 Ø MLS 	<b>T80786-00</b> WHT 001 865 (10x) 	<b>70-31414-10</b> 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x 	<b>X89552-01</b> 030 129 717 E 4x 	<b>X51580-01</b> 030 253 039 H 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77313-01 N</b> 036 103 085 H 32x42x6/7 A SL RD NBR		
1,4 BLG CAVD CFB CFBA <b>[NEW]</b>	96-125 kW (131-170 PS)	BEETLE TSI EOS TSI GOLF TSI JETTA TSI SCIROCCO TIGUAN TSI	11/05→	<b>S37091-00</b> <sup>12 13 38</sup>	<b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	<b>T80752-00</b> WHT 000 912 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X87493-01</b> 03C 129 717 C 4x 	<b>X89175-01</b> <sup>10</sup> 03C 129 717 A 4x 	<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM	

VOLKSWAGEN												
1,4 BMG CDDA	55-63 kW (75-85 PS)	POLO	06/09→	 <b>S80752-00</b> 12 13 38	 <b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	 <b>T59457-00</b> WHT 000 675 (10x) 	 <b>70-31414-10</b> 	 <b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x		 <b>X82517-01</b> 03C 253 039 E 	 <b>70-31414-10</b> 	 <b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM
1,4 BMS BWB	51-59 kW (70-80 PS)	POLO TDI	04/05-11/09	 <b>D37057-00</b> 12  <b>B32959-00</b> 13 38	 <b>H09198-00</b> 045 103 383 AA 1,45 mm 1 MLS <b>H19198-10</b> 045 103 383 AB 1,53 mm 2 MLS <b>H29198-20</b> 045 103 383 AC 80,5 Ø 1,61 mm 3 MLS 	 <b>T09198-00</b> 038 103 384 (8x) 	 <b>X83126-01</b> 045 103 483 E NBR 	 <b>N92001-00</b> 027 109 675 (6x) <b>P76532-00</b> 027 109 675	 <b>X86491-01</b> 045 129 717 6x 	 <b>X81831-01</b> 045 253 039 B 	 <b>70-31414-10</b> 	 <b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,4 BMY	103 kW (140 PS)	GOLF TSI JETTA TSI TOURAN TSI	02/06-10/10	 <b>S37091-00</b> 12 13 38	 <b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	 <b>T80752-00</b> WHT 000 912 (10x) 		 <b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	 <b>X87493-01</b> 03C 129 717 C 16x <b>X89175-01</b> 10 4x 03C 129 717 A 	 <b>X81446-01</b> 03C 253 039 D 	 <b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE Mot.BMY 033 816→	
1,4 BNM BNV	51-59 kW (70-80 PS)	FOX TDI POLO TDI	04/05→	 <b>D37013-00</b> 12  <b>B32959-00</b> 13 38	 <b>H09198-00</b> 045 103 383 AA 1,45 mm 1 MLS <b>H19198-10</b> 045 103 383 AB 1,53 mm 2 MLS <b>H29198-20</b> 045 103 383 AC 80,5 Ø 1,61 mm 3 MLS 	 <b>T09198-00</b> 038 103 384 (8x) 	 <b>X83111-01</b> 045 103 483 C NBR 	 <b>N92001-00</b> 027 109 675 (6x) <b>P76532-00</b> 027 109 675	 <b>X86491-01</b> 045 129 717 6x 	 <b>X52968-01</b> 045 253 039 <b>X52970-01</b> 1H0 253 115 A 	 <b>70-31414-10</b> 	 <b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,4 BWK CAVA CAVE CKMA CMSB CNWA CNWB CTHA CTHB CTHC CTHD CTHE CTKA	90-132 kW (122-180 PS)	BEETLE TSI CC TSI EOS TSI GOLF TSI JETTA TSI PASSAT TSI POLO GTI SCIROCCO SHARAN TSI TIGUAN TSI TOURAN TSI	09/07→	 <b>S37091-00</b> 12 13 38	 <b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	 <b>T80752-00</b> WHT 000 912 (10x) 	 <b>70-31414-10</b> 	 <b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	 <b>X87493-01</b> 03C 129 717 C 16x <b>X89175-01</b> 10 4x 03C 129 717 A 	 <b>X81446-01</b> 03C 253 039 D 	 <b>70-31414-10</b> 	 <b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE

VOLKSWAGEN															
1,4 CAVB CAVC	103-125 kW (140-170 PS)	TOURAN TSI	02/06-05/15	<b>S37091-00</b> <sup>12</sup> <sup>13</sup> <sup>38</sup>	<b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	<b>T80752-00</b> WHT 000 912 (10x) 		<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X87493-01</b> 03C 129 717 C 16x  <b>X89175-01</b> <sup>10</sup> 03C 129 717 A 4x 		<b>X81446-01</b> 03C 253 039 D 		<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE		
1,4 CAXA	90 kW (122 PS)	EOS TSI GOLF TSI JETTA TSI PASSAT TSI SCIROCCO TIGUAN TSI	05/07→	<b>S37091-00</b> <sup>12</sup> <sup>13</sup> <sup>38</sup>	<b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	<b>T80752-00</b> WHT 000 912 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X87493-01</b> 03C 129 717 C 16x  <b>X89175-01</b> <sup>10</sup> 03C 129 717 A 4x 		<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE Mot.CAXA 010 452→		
1,4 CDGA	110 kW (150 PS)	PASSAT TSI TOURAN TSI	01/09-05/15		<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T80752-00</b> WHT 000 912 (10x) 	<b>70-31414-10</b> 	<b>N93133-00</b> 036 109 675 A (8x) +03C 109 675 A (8x) <b>P76662-00</b> 036 109 675 <b>P76844-00</b> 03C 109 675 A	<b>X87493-01</b> 03C 129 717 C 8x  <b>X89175-01</b> <sup>10</sup> 03C 129 717 A 4x 		<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE		
1,4 CGGA CGGB CMAA	59-63 kW (80-85 PS)	GOLF POLO	05/06→	<b>D36621-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13</sup> <sup>38</sup> 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X58997-01</b> 036 129 717 E 16x 	4x	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77479-01 K</b> → 036 103 171B PTFE <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR		
1,4 CHPA CMBA CNLA CPVA CPVB CPWA CRJA CUKB CXSA CXSB CZCA CZDA <b>[NEW]</b>	81-110 kW (110-150 PS)	BEETLE TSI CADDY TGI CC TSI GOLF GOLF TGI GOLF TSI JETTA TSI PASSAT TSI SCIROCCO TOURAN TSI	04/11→	<b>D38727-00</b> <sup>12</sup> <b>B38725-00</b> <sup>13</sup> <sup>38</sup>	<b>H40706-00</b> 04E 103 383 BJ 75 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 	<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00 AS</b> 04E 109 675 A <b>P76961-00 ES</b> 04E 109 675	<b>X58997-01</b> 036 129 717 E 8x  8x 	4x	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77881-01 K</b> → 04E 103 170 A PTFE <b>P77843-01 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01 N</b> → 04E 103 085 24x39x8 A SL LD PTFE		
1,4 CLPA	63 kW (85 PS)	POLO	06/09→	<b>S80752-00</b> <sup>12</sup> <sup>13</sup> <sup>38</sup>	<b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	<b>T59457-00</b> WHT 000 675 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X58997-01</b> 036 129 717 E 16x 	4x	<b>X82517-01</b> 03C 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE		

VOLKSWAGEN												
1,4 CPTA CZEA <b>[NEW]</b>	103-110 kW (140-150 PS)	GOLF TSI PASSAT TSI POLO TSI	10/12→	 D38727-01 <sup>12</sup> B38725-00 <sup>13</sup> <sup>38</sup>	 H40706-00 04E 103 383 BJ 75 Ø MLS 	 T40706-00 WHT 004 926 (10x) 	 X59930-01 04E 103 483 H 	 N93196-00 04E 109 675 (8x) +04E 109 675 A (8x) P76960-00 AS 04E 109 675 A P76961-00 ES 04E 109 675 8x 8x	 X58997-01 036 129 717 E 4x 	 X59925-01 04E 253 039 D 	 70-31414-10 	 P77841-01 K ← 04C 103 085 30x40x7 A SL RD PTFE ACM P77881-01 K → 04E 103 170 A PTFE P77843-01 N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM P77840-01 N → 04E 103 085 C 28x39x7 A SL LD PTFE
1,4 CSSA CSTA <b>[NEW]</b>	96-110 kW (131-150 PS)				 H84831-00 04E 103 383 BF 75 Ø MLS 	 T40706-00 WHT 004 926 (10x) 	 X59930-01 04E 103 483 H 	 N93196-00 04E 109 675 (8x) +04E 109 675 A (8x) P76960-00 AS 04E 109 675 A P76961-00 ES 04E 109 675 8x 8x	 X58997-01 036 129 717 E 4x 	 X59925-01 04E 253 039 D 	 70-31414-10 	 P77841-01 K ← 04C 103 085 30x40x7 A SL RD PTFE ACM P77843-01 N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM P77844-01 N → 04E 103 085 24x39x8 A SL LD PTFE
1,4 1W	35 kW (48 PS)	POLO D →80 NW 500 000	08/90-09/94	 S31188-00 <sup>12</sup> <sup>13</sup>  D31188-00 <sup>12</sup> 031 198 012 A  B30579-00 <sup>13</sup> 052 198 011 A	 H07907-00 031 103 383 M 1,53 mm 1 H17907-10 031 103 383 N 1,57 mm 2 H27907-20 031 103 383 P 76,5 Ø 1,61 mm 3 	 T02673-00 068 103 384 A (10x) 	 V31187-00 	 N90300-00 026 109 675 (8x) P76531-00 026 109 675 8x	 X58344-01 030 129 717 D 8x 	 X03743-01 030 253 039 A 2x 	 X03370-01 032 103 609 B 	 P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 2x 068 103 085 E 32x47x10 A SL WD FPM
1,4 1W	35 kW (48 PS)	POLO D 80 PW 000 001→	08/90-09/94	 S31187-00 <sup>12</sup> <sup>13</sup>  D37026-00 <sup>12</sup> 031 198 012 C  B30579-00 <sup>13</sup> 052 198 011 A	 H07907-00 031 103 383 M 1,53 mm 1 H17907-10 031 103 383 N 1,57 mm 2 H27907-20 031 103 383 P 76,5 Ø 1,61 mm 3 	 T02673-00 068 103 384 A (10x) 	 V31187-00 	 N91190-00 027 109 675 (8x) P76532-00 027 109 675 8x	 X58344-01 030 129 717 D 8x 	 X03743-01 030 253 039 A 2x 	 X03370-01 032 103 609 B 	 P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 2x 068 103 085 E 32x47x10 A SL WD FPM
1,5 CK	37 kW (50 PS)	GOLF D JETTA D PASSAT D	08/76-07/80	 S30435-00 <sup>12</sup> <sup>13</sup> 068 198 001  D30435-00 <sup>12</sup> 068 198 012 L  B30584-00 <sup>13</sup> 037 198 011 C	 H08038-00 068 103 383 FB 1,4 mm 3 H18038-10 068 103 383 FC 1,5 mm 4 H28038-20 068 103 383 FD 78,5 Ø 1,6 mm 5 	 T02673-00 068 103 384 A (10x) 	 V30584-00 026 198 025 A 8,5 mm Kork  V31265-00 056 198 025 6,5 mm 	 N90300-00 026 109 675 (8x) P76531-00 026 109 675 8x	 X04875-01 026 129 717 D 8x  X55899-01 068 129 717 E 	 X03747-01 026 129 589 A 4x  X07854-01 841 253 115 B 	 P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM	



VOLKSWAGEN												
1,5 FB FF FH FK YJ ZB ZC	48-63 kW (65-86 PS)	GOLF PASSAT SCIROCCO	05/73→	<b>S30584-00</b> <sup>(12)</sup> <sup>(13)</sup> 056198001A <b>D30584-00</b> <sup>(12)</sup> 056 198 012 D <b>B30584-00</b> <sup>(13)</sup> 037 198 011 C	<b>H04128-00</b> 049 103 383 M 78,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V31265-00</b> 056 198 025 6,5 mm 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D 8x 	<b>X03747-01</b> 026 129 589 A 4x  <b>X07854-01</b> <sup>(A)</sup> 841 253 115 B 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,5 GH JB	51 kW (70 PS)	CADDY GOLF JETTA SCIROCCO	08/77-02/84	<b>S30587-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>D30587-00</b> <sup>(12)</sup> 049 198 012 H <b>B30584-00</b> <sup>(13)</sup> 037 198 011 C	<b>H04129-00</b> 049 103 383 K 81 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V31265-00</b> <sup>(X)</sup> 056 198 025 6,5 mm 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D 8x 	<b>X03747-01</b> 026 129 589 A 4x  <b>X07854-01</b> <sup>(A)</sup> 841 253 115 B 		<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,5 H K L	29-33 kW (40-45 PS)	KAEFER KARMANN 1500 181	04/61→	<b>A30576-00</b> <sup>(14)</sup> 111 998 007 <b>D30252-00</b> <sup>(18)</sup> 113 998 101 A			<b>X00991-01</b> 2x 113 101 481 F Kork 		<b>X00995-01</b> 2x 113 129 717 A  <b>X03811-01</b> 2x 311 129 707 	<b>X03808-01</b> 4x 111 251 261 C 		<b>P76303-01</b> K → 113 105 245 F 70x90x10 A LD ACM
1,6 ABN EW EWA EZ EZA HM HN PN RE RF	51-55 kW (70-75 PS)	CADDY GOLF JETTA PASSAT SCIROCCO	01/83→	<b>S31192-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>D31192-00</b> <sup>(12)</sup> 026 198 012 AB <b>B30584-00</b> <sup>(13)</sup> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> <sup>(X)</sup> 026 198 025 C 6,5 mm Gummi  1 Dichtlippe 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D 8x  <b>X55170-01</b> 026 129 717 F  <b>X07853-01</b> <sup>(10)</sup> 035 121 171 C 	<b>X03747-01</b> 026 129 589 A 4x  <b>X07854-01</b> <sup>(A)</sup> 841 253 115 B  <b>X07867-01</b> <sup>(A)</sup> 533 253 115 D 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,6 ABU	55 kW (75 PS)	GOLF VENTO	09/92-09/98	<b>S32205-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>D32205-00</b> <sup>(12)</sup> 032198012B <b>B32205-00</b> <sup>(13)</sup> 030 198 011	<b>H50442-00</b> 032 103 383 H 77 Ø 	<b>T50505-00</b> 032 103 384 (10x) 	<b>V31187-00</b>  <b>X07908-01</b> 030 103 483 G NBR  <b>X07909-01</b> 3x NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X57506-01</b> 032 129 717 C 8x 	<b>X51584-01</b> 032 253 039 E 	<b>X03370-01</b> 032.103.609 B 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
Ltr.												
1,6 ACR 53 kW (72 PS)		1										
			<b>S31192-00</b> <sup>12</sup> <sup>13</sup> <b>D31192-00</b> <sup>12</sup> 026 198 012 AB <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> <sup>X</sup> 026 198 025 C 6,5 mm Gummi  - 1 Dichtlippe 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D 8x  <b>X55170-01</b> 026 129 717 F  <b>X07853-01</b> <sup>10</sup> 035 121 171 C 	<b>X03747-01</b> 026 129 589 A 4x  <b>X07854-01</b> <sup>11</sup> 841 253 115 B  <b>X07867-01</b> <sup>11</sup> 533 253 115 D  <b>X51169-01</b> <sup>11</sup> 431 253 115 A 	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM	
1,6 AD AE AF AH AJ AK B P T U	34-40 kW (46-54 PS)	KAEFER KARMANN TRANSPORTER 1500	07/64-09/92	<b>A30576-00</b> <sup>14</sup> 111 198 007 <b>D30252-00</b> <sup>16</sup> 113 198 101 A			<b>X00991-01</b> 2x 113 101 481 F Kork 		<b>X00995-01</b> 2x 113 129 717 A  <b>X03811-01</b> 2x 311 129 707 	<b>X03808-01</b> 4x 111 251 261 C 		<b>P76303-01</b> K → 113 105 245 F 70x90x10 A LD ACM
1,6 ADP	74 kW (101 PS)	PASSAT	10/96-11/00	<b>S32242-00</b> <sup>12</sup> <sup>13</sup> <b>D32242-00</b> <sup>12</sup> 050 198 012 B <b>B32242-00</b> <sup>13</sup> 050 198 011	<b>H50475-00</b> 050 103 383 82,5 Ø MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X53263-01</b> 051 103 483 A ACM  - 2 Dichtlippen 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X57668-01</b> 8x 037 129 717 C 	<b>X51641-01</b>  <b>X51156-01</b> <sup>11</sup> 443 253 115 A 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,6 AEA	55 kW (75 PS)	GOLF POLO VENTO	09/92-10/99	<b>D32713-00</b> <sup>12</sup> 032 198 012 A <b>B30579-00</b> <sup>13</sup> 052 198 011 A	<b>H50505-00</b> 030 103 383 AH 77,5 Ø MLS 	<b>T50505-00</b> 032 103 384 (10x) 	<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X57506-01</b> 8x 032 129 717 C 	<b>X51584-01</b> 032 253 039 E 	<b>X03370-01</b> 032 103 609 B  <b>70-31414-10</b> 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,6 AEE	55 kW (75 PS)	CADDY GOLF POLO VENTO	09/92-09/01	<b>D32705-00</b> <sup>12</sup> 032 198 012 B <b>B32705-00</b> <sup>13</sup> 030 198 011 A Mot.→AEE 562 757 <b>B32949-00</b> <sup>13</sup> <sup>35</sup> Mot.AEE 567 758→	<b>H50505-00</b> 030 103 383 AH 77,5 Ø MLS 	<b>T50505-00</b> 032 103 384 (10x) 	<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>M37167-00</b> 8x 030 198 717 	<b>X51584-01</b> 032 253 039 E 	<b>70-31414-10</b> 	<b>P77313-01</b> K ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AEE 562 757 <b>P77317-01</b> K → 028 103 171 B PTFE Mot.AEE 562 758→ <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
1,6 AEH AKL	74 kW (100-101 PS)	BORA GOLF POLO	12/95-05/05	<b>S32239-00</b> <sup>12</sup> <sup>13</sup> <b>D32239-00</b> <sup>12</sup> 06A 198 012 <b>B32239-00</b> <sup>13</sup> <sup>38</sup> 06A 198 011	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X53263-01</b> 051 103 483 A ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X57666-01</b> 06A 133 398 F 4x 	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1,6 AEK AFT AKS	74 kW (100-101 PS)	GOLF PASSAT POLO VENTO	07/94-06/02	<b>D32952-00</b> <sup>12</sup> 037 198 012 K <b>B32952-00</b> <sup>13</sup> 051 198 011 C	<b>H50475-00</b> 050 103 383 82,5 Ø MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X53263-01</b> 051 103 483 A ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X57668-01</b> 037 129 717 C 8x  <b>X51712-01</b> <sup>10</sup> 037 129 717 D 	<b>X51638-01</b> 037 253 039 D  <b>X07867-01</b> <sup>10</sup> 533 253 115 D 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1,6 AFX BHJ	64-74 kW (87-101 PS)			<b>D37197-00</b> <sup>12</sup> <b>B37196-00</b> <sup>13</sup> <sup>35</sup>	<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X53263-01</b> 051 103 483 A ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X55430-01</b> 048 129 717 A 8x  <b>X57668-01</b> 037 129 717 C  <b>X51712-01</b> <sup>10</sup> 037 129 717 D 	<b>X03747-01</b> 026 129 589 A 4x 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P77317-01 K</b> → 028 103 171 B PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1,6 AHL ANA ARM	74 kW (101 PS)	PASSAT	10/96-11/00	<b>D36630-00</b> <sup>12</sup> <b>B32936-00</b> <sup>13</sup> <sup>35</sup>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X53263-01</b> 051 103 483 A ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X57668-01</b> 037 129 717 C 8x  <b>X87424-01</b> 06B 129 717 A 4x 	<b>X03747-01</b> 026 129 589 A  <b>X51169-01</b> <sup>10</sup> 431 253 115 A 	<b>70-31414-10</b> 4x 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,6 AHS	55 kW (75 PS)	POLO	10/94-10/99	<b>D32705-00</b> <sup>12</sup> 032 198 012 B <b>B32705-00</b> <sup>13</sup> 030 198 011 A Mot.→AHS 050 001 <b>B32949-00</b> <sup>13</sup> <sup>35</sup> Mot.AHS 050 000→	<b>H50505-00</b> 030 103 383 AH 77,5 Ø MLS 	<b>T50505-00</b> 032 103 384 (10x) 	<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>M37167-00</b> 030 198 717 8x 	<b>X51584-01</b> 032 253 039 E 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AHS 050 000 <b>P77317-01 K</b> → 028 103 171 B PTFE Mot.AHS 050 000→ <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN													
1,6 Ltr.			<b>1</b>										
1,6 AJV ATN AUS	77-88 kW (105-120 PS) BORA GOLF POLO GTI	09/98-06/06	6N X 048 817, 6N X 104 315→	<b>D37021-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	<b>H80344-00</b> 036 103 383 AN 77 Ø MLS 	<b>T80344-00</b> 036 103 384 E (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X87612-01</b> 036 129 717 G 		<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77350-01 K</b> → 030 103 171 K PTFE <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR
1,6 AJV	88 kW (120 PS) POLO GTI	→6N X 048 817, 09/98-10/99 6N X 104 314		<b>D37021-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	<b>H80344-00</b> 036 103 383 AN 77 Ø MLS 	<b>T80344-00</b> 036 103 384 E (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X87612-01</b> 036 129 717 G 		<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77818-01 K</b> → 030 103 171 H PTFE <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR
1,6 ALM	55 kW (75 PS) POLO	11/95-09/01		<b>D32705-00</b> <sup>12</sup> 032 198 012 B <b>B32705-00</b> <sup>13</sup> 030 198 011 A Mot.→ALM 000 706 <b>B32949-00</b> <sup>13 35</sup> Mot.AL M 000 707→	<b>H50505-00</b> 030 103 383 AH 77,5 Ø MLS 	<b>T50505-00</b> 032 103 384 (10x) 	<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	8x <b>M37167-00</b> 030 198 717 		<b>X51584-01</b> 032 253 039 E 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM Mot.→ALM 000 706 <b>P77317-01 K</b> → 028 103 171 B PTFE Mot.AL M 000 707→ <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1,6 ALZ	75 kW (102 PS) PASSAT	11/00-05/05		<b>D36631-00</b> <sup>12</sup> <b>B32936-00</b> <sup>13 35</sup>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	8x <b>X87424-01</b> 06B 129 717 A 	4x 	<b>X03747-01</b> 026 129 589 A 	4x <b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,6 APF AUR AWH	74 kW (100-101 PS) BORA GOLF NEW BEETLE POLO	12/95-05/05		<b>D36632-00</b> <sup>12</sup> <b>B32936-00</b> <sup>13 35</sup>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	8x <b>X57666-01</b> 06A 133 398 F 	4x 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

VOLKSWAGEN												
1,6 ARC AVY	92 kW (125 PS)	LUPO GTI POLO GTI	10/99-07/05	<b>D36650-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	<b>H80344-00</b> 036 103 383 AN 77 Ø MLS 	<b>T80344-00</b> 036 103 384 E (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X87612-01</b> 036 129 717 G 	<b>X51579-01</b> 036 253 039 F  <b>X81385-01</b> <sup>14</sup> 155 253 115 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77350-01 K</b> → <sup>15</sup> 030 103 171 K PTFE <b>P77329-01 N</b> ← 036 103 085 A 27x42x8 A SL RD NBR <b>P77342-01 N</b> → 036 103 085 F 35x46x7 A SL RD FPM
1,6 AS CT CZ	34-37 kW (46-50 PS)	KAEFER TRANSPORTER	08/68→	<b>A30576-00</b> <sup>14</sup> 111 198 007 <b>S37028-00</b> <sup>13</sup> <b>D30252-00</b> <sup>18</sup> 113 198 101 A			<b>X00991-01</b> 2x 113 101 481 F Kork 		<b>X00995-01</b> 2x 113 129 717 A  <b>X03811-01</b> 2x 311 129 707 	<b>X03808-01</b> 4x 111 251 261 C 		<b>P76303-01 K</b> → 113 105 245 F 70x90x10 A LD ACM
1,6 AVU AYD BFQ BFS CCSA CHGA CMXA	75 kW (102 PS)	BORA CADDY GOLF GOLF BiFuel JETTA NEW BEETLE	06/00→	<b>D36633-00</b> <sup>12</sup> <b>B32936-00</b> <sup>13 35</sup>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	8x <b>X57666-01</b> 06A 133 398 F 	<b>X52965-01</b> 06A 253 039 L  <b>X07867-01</b> <sup>14</sup> 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → <sup>15</sup> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,6 AWB	78 kW (107 PS)	BORA	06/02-10/04	<b>D32934-00</b> <sup>12</sup> <b>B32934-00</b> <sup>13 38</sup> 06A 198 011 A <b>Z36190-00</b> <sup>8</sup> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x) 	<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	20x <b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → <sup>15</sup> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,6 AWB	78 kW (107 PS)	GOLF	08/03-06/05	<b>D32934-00</b> <sup>12</sup> <b>B32934-00</b> <sup>13 38</sup> 06A 198 011 A	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x) 		<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	20x <b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>P77183-01 K</b> → <sup>15</sup> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,6 AZD BCB	77 kW (105 PS)	BORA GOLF	02/00-06/06	<b>D37022-00</b> <sup>12</sup> <b>B32957-00</b> <sup>13 38</sup> 036 198 011	<b>H80344-00</b> 036 103 383 AN 77 Ø MLS 	<b>T80344-00</b> 036 103 384 E (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x <b>X58997-01</b> 036 129 717 E 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77351-01 K</b> → <sup>15</sup> 030 103 171 L PTFE <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR

VOLKSWAGEN												
1,6 BAD	81 kW (110 PS)	BORA FSI GOLF FSI	01/02-06/06	<b>D36705-00</b> <sup>12</sup> <b>B36705-00</b> <sup>13 35</sup>	<b>H80344-00</b> 036 103 383 AN 77 Ø MLS 	<b>T80344-00</b> 036 103 384 E (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X87493-01</b> 03C 129 717 C 16x  <b>X87494-01</b> <sup>10</sup> 036 129 717 K 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77351-01 K</b> → 030 103 171 L PTFE <b>P77329-01 N</b> ← 036 103 085 A 27x42x8 A SL RD NBR <b>P77342-01 N</b> → 036 103 085 F 35x46x7 A SL RD FPM
1,6 BAG BLF BLP	85 kW (115 PS)	GOLF FSI →1K 4 600 000 TOURAN FSI →1T 4 270 000	02/03-07/08	<b>S36776-00</b> <sup>12 13 38</sup> <b>D36776-00</b> <sup>12</sup>	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X87493-01</b> 03C 129 717 C 16x  <b>X89175-01</b> <sup>10</sup> 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D  <b>X52978-01</b> 1J0 253 115 S	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77350-01 K</b> → 030 103 171 K PTFE
1,6 BAG BLF BLP	85 kW (115 PS)	GOLF FSI 1K 4 600 001→ JETTA FSI PASSAT FSI TOURAN FSI 1T 4 270 001→	02/03-10/10	<b>S36776-00</b> <sup>12 13 38</sup> <b>D36776-00</b> <sup>12</sup>	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X87493-01</b> 03C 129 717 C 16x  <b>X89175-01</b> <sup>10</sup> 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D  <b>X52978-01</b> 1J0 253 115 S	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77376-01 K</b> → 030 103 171 S PTFE
1,6 BAH BJA BLH BPA CCRA CFZA	74 kW (101 PS)	FOX GOLF POLO VOYAGE	02/01→	<b>D37167-00</b> <sup>12</sup> <b>B37167-00</b> <sup>13 38</sup>	<b>H80786-00</b> 032 103 383 N 77,7 Ø MLS 	<b>T80786-00</b> WHT 001 865 (10x) 	<b>70-31414-10</b> 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	<b>M37167-00</b> 030 198 717 8x 	<b>X51580-01</b> 030 253 039 H 	<b>70-31414-10</b> 	<b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77313-01 N</b> 036 103 085 H 32x42x6/7 A SL RD NBR
1,6 BGU BSE BSF	75 kW (102 PS)	CADDY GOLF JETTA PASSAT TOURAN	07/03→	<b>D36633-00</b> <sup>12</sup> <b>B36706-00</b> <sup>13 35</sup>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675	<b>X57666-01</b> 4x 06A 133 398 F 8x  <b>X88303-01</b> <sup>10</sup> 4x 06A 133 227 B 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77352-01 K</b> → 06B 103 171 E <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,6 BJF BJY BWX UNF UPD	67-73 kW (91-99 PS)	GOL GOLF	12/98→		<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 		<b>X59501-01</b> 026 103 483 2 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55899-01</b> 8x 068 129 717 E 	<b>X03747-01</b> 4x 026 129 589 A 	<b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN													
Ltr.													
1,6 BJH	75 kW (102 PS) BORA GOLF	08/00-06/05											
				<b>H80447-00</b> 06A 103 383 AE MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 	<b>X57666-01</b> 06A 133 398 F 8x 	4x	<b>X51947-01</b> 037 253 039 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	
1,6 BMH CDE CDEA CDF <b>[NEW]</b>	74-77 kW (101-105 PS)			<b>S80752-00</b> <sup>12 13 38</sup> 	<b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	<b>T59457-00</b> WHT 000 675 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 		<b>X82517-01</b> 03C 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM	
1,6 BRY	74 kW (101 PS)				<b>H80447-00</b> 06A 103 383 AE MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x 	<b>X57666-01</b> 06A 133 398 F 4x 		<b>X51947-01</b> 037 253 039 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,6 BTS	77 kW (105 PS) POLO	05/06-11/09		<b>S37014-00</b> <sup>12 13 38</sup> 	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X58997-01</b> 036 129 717 E 4x 		<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM
1,6 BWH	74-77 kW (101-105 PS)				<b>H80447-00</b> 06A 103 383 AE MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x 	<b>X57666-01</b> 06A 133 398 F 4x 		<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

VOLKSWAGEN												
1,6 CAYA CAYB CAYC CLNA	55-77 kW (75-105 PS)	CADDY TDI GOLF TDI JETTA TDI PASSAT TDI POLO TDI TOURAN TDI	02/09→	<b>D38310-00</b> <sup>12</sup> 10/09→   <b>B38300-00</b> <sup>13 35</sup>	<b>H40582-00</b> 03L 103 383 BQ 80,5 Ø 1,55 mm 1 MLS <b>H40582-10</b> 03L 103 383 BR 80,5 Ø 1,63 mm 2 MLS <b>H40582-20</b> 03L 103 383 BS 80,5 Ø 1,71 mm 3 MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59484-01</b> 03L 103 483 H +03L 103 070 A (4x)  <b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59484-01</b> 03L 103 483 H  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X59477-01</b> 03L 129 717 J 4x  <b>X59479-01</b> 03L 129 717 H 4x 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM →09/09 <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM 10/09→
1,6 CAYC CAYD CAYE	55-77 kW (75-105 PS)	BEETLE TDI BEETLE TSI CADDY TDI TOURAN TDI	05/10→	<b>D38310-00</b> <sup>12</sup>   <b>B38300-00</b> <sup>13 35</sup>	<b>H40582-00</b> 03L 103 383 BQ 80,5 Ø 1,55 mm 1 MLS <b>H40582-10</b> 03L 103 383 BR 80,5 Ø 1,63 mm 2 MLS <b>H40582-20</b> 03L 103 383 BS 80,5 Ø 1,71 mm 3 MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59484-01</b> 03L 103 483 H +03L 103 070 A (4x)  <b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59484-01</b> 03L 103 483 H  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X59477-01</b> 03L 129 717 J 4x  <b>X59479-01</b> 03L 129 717 H 4x 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
1,6 CFNA CFNB CNKA	60-77 kW (82-105 PS)	JETTA POLO	05/10→	<b>S37014-00</b> <sup>12 13 38</sup>	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x 	<b>X58997-01</b> 036 129 717 E 4x 	<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171 B PTFE



VOLKSWAGEN												
Ltr.    1 1,6 CLHA CLHB CRKA CRKB <b>[NEW]</b>	66-81 kW (90-110 PS)	GOLF TDI TOURAN TDI	08/12→	<b>D38750-00</b> <sup>12</sup>  	<b>H40700-00</b> 04L 103 383 C 80,5 Ø 1,55 mm 1 □ MLS <b>H40700-10</b> 04L 103 383 D 80,5 Ø 1,63 mm 2 □ MLS <b>H40700-20</b> 04L 103 383 E 80,5 Ø 1,71 mm 3 □ MLS 	<b>T40709-00</b> WHT 005 673 (10x) 	<b>V59933-00</b> 03L 103 483 S +04L 103 070 (4x)  <b>V90072-00</b>  <b>X59933-01</b> 03L 103 483 S  <b>X90116-01</b> 04L 103 483 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59929-01</b> 04L 129 717 B 	<b>X59927-01</b> 04L 253 039 G 	<b>70-31414-10</b> 	<b>P77831-01 K</b> → 04L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 ARD FPM
1,6 CLR CLRA <b>[NEW]</b>	77 kW (105 PS)	JETTA	12/11→	<b>S80752-00</b> <sup>12 13 38</sup>	<b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	<b>T59457-00</b> WHT 000 675 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X58997-01</b> 036 129 717 E 4x 	<b>X82517-01</b> 03C 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM
1,6 CLSA	77 kW (105 PS)	POLO	05/10→	<b>S80752-00</b> <sup>12 13 38</sup>	<b>H80752-00</b> 03C 103 383 AM 77,5 Ø MLS 	<b>T59457-00</b> WHT 000 675 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X58997-01</b> 036 129 717 E 4x 	<b>X82517-01</b> 03C 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171B PTFE
1,6 CMR	70-72 kW (95-98 PS)				<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X59498-01</b> 051 103 483 D 2 Dichtlippen 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x		<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,6 CNXA CPDA CSRA CUCA CWSA <b>[NEW]</b>	70-88 kW (95-120 PS)			<b>D90181-00</b> <sup>12</sup> <b>B38725-00</b> <sup>13 38</sup>	<b>H84801-00</b> 04E 103 383 BK 77,5 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 	<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00 AS</b> 04E 109 675 A <b>P76961-00 ES</b> 04E 109 675 8x 8x	<b>X58997-01</b> 036 129 717 E 4x  <b>X59876-01</b> 04C 129 717 B 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01 N</b> → 04E 103 085 24x39x8 A SL LD PTFE

VOLKSWAGEN

Ltr.

1,6 CPJA **[NEW]** 77 kW (105 PS)

1,6 CR 40 kW (54 PS) PASSAT D 02/79-03/88

S80752-00 <sup>12</sup> <sup>13</sup> <sup>38</sup>	H80752-00 03C 103 383 AM 77,5 Ø MLS 	T50943-00 036 103 384 B (10x) 	70-31414-10 	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X58997-01 036 129 717 E 4x 16x 	X82517-01 03C 253 039 E 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM
S30435-00 <sup>12</sup> <sup>13</sup> 068 198 001  D30435-00 <sup>12</sup> 068 198 012 L  B30584-00 <sup>13</sup> 037 198 011 C	H02633-00 068 103 383 ES 1,5 mm 1 Mot.→CR 176 338 H12633-10 068 103 383 ET 1,6 mm 2 Mot.→CR 176 338 H22633-20 068 103 383 FA 78 Ø 1,7 mm 3 Mot.→CR 176 338  H02673-00 068 103 383 FE 1,4 mm 1 Mot.CR 176 339→ H12673-10 068 103 383 FF 1,5 mm 2 Mot.CR 176 339→ H22673-20 068 103 383 FG 78 Ø 1,6 mm 3 Mot.CR 176 339→ 	T02673-00 068 103 384 A (10x) 	V30584-00 026 198 025 A 8,5 mm Kork 	N90300-00 026 109 675 (8x) P76531-00 026 109 675	X04875-01 026 129 717 D 8x  X55899-01 068 129 717 E 	X03747-01 026 129 589 A 4x X07854-01 841 253 115 B X51157-01 433 253 115	E30584-00 044 103 609 D +N 905 927 02 (20x) 	P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
Ltr.												
1,6 CS	37 kW (50 PS)	TRANSPORTER	01/81-07/87	<p><b>S30435-00</b> <sup>12</sup> <sup>13</sup> 068 198 001</p> <p></p> <p><b>D30435-00</b> <sup>12</sup> 068 198 012 L</p> <p></p> <p><b>B30584-00</b> <sup>13</sup> 037 198 011 C</p>	<p><b>H02633-00</b> 068 103 383 ES 1,5 mm 1 </p> <p><b>H12633-10</b> 068 103 383 ET 1,6 mm 2 </p> <p><b>H22633-20</b> 068 103 383 FA 78 Ø 1,7 mm 3 </p> <p>Mot.→000 338</p> <p></p> <p><b>H03675-00</b> 068 103 383 FE 1,6 mm 1 </p> <p>Mot.000 339→</p> <p><b>H13675-10</b> 068 103 383 FF 1,65 mm 2 </p> <p>Mot.000 339→</p> <p><b>H23675-20</b> 068 103 383 FG 78 Ø 1,7 mm 3 </p> <p>Mot.000 339→</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V30584-00</b> 026 198 025 A 8,5 mm Kork</p> <p></p>	<p><b>N90300-00</b> 026 109 675 (8x)</p> <p><b>P76531-00</b> 026 109 675</p>	<p><b>X04875-01</b> 026 129 717 D</p> <p>8x</p> <p></p> <p><b>X55899-01</b> 068 129 717 E</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X07854-01</b> </p> <p>841 253 115 B</p> <p><b>X51157-01</b> </p> <p>433 253 115</p>	<p>4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) Mot.000339→</p> <p></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>
1,6 CWVA CWVB <b>[NEW]</b>	66-81 kW (90-110 PS)	GOLF POLO	05/14→	<p><b>D84799-00</b> <sup>12</sup></p> <p><b>B38725-00</b> <sup>13</sup> <sup>38</sup></p>	<p><b>H84801-00</b> 04E 103 383 BK 77,5 Ø MLS</p> <p></p>	<p><b>T40706-00</b> WHT 004 926 (10x)</p> <p></p>	<p><b>X59930-01</b> 04E 103 483 H</p> <p></p>	<p><b>N95992-00</b> 04E 109 675 (16x)</p> <p><b>P76961-00</b> 04E 109 675</p>	<p><b>X58997-01</b> 036 129 717 E</p> <p>4x</p> <p></p> <p><b>X59876-01</b> 04C.129 717 B</p> <p></p>	<p><b>X59925-01</b> 04E 253 039 D</p> <p></p>	<p><b>70-31414-10</b></p> <p></p>	<p><b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM</p> <p><b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM</p> <p><b>P77844-01</b> N → 04E 103 085 24x39x8 A SL LD PTFE</p>

VOLKSWAGEN												
1,6 CY JK JP JR	40-51 kW (54-70 PS)	CADDY D GOLF D JETTA D PASSAT TD	04/82-07/92	<p><b>S30435-00</b> <sup>(12)</sup> <sup>(13)</sup> 068 198 001</p> <p></p> <p><b>D30435-00</b> <sup>(12)</sup> 068 198 012 L</p> <p></p> <p><b>B30584-00</b> <sup>(13)</sup> 037 198 011 C</p>	<p><b>H02673-00</b> 068 103 383 FE 1,4 mm 1 </p> <p>→07/85</p> <p><b>H12673-10</b> 068 103 383 FF 1,5 mm 2 </p> <p>→07/85</p> <p><b>H22673-20</b> 068 103 383 FG 78 Ø</p> <p>1,6 mm 3 </p> <p>→07/85</p> <p></p> <p><b>H02674-00</b> 068 103 383 EH 1,6 mm 1 </p> <p>08/85→</p> <p><b>H12674-10</b> 068 103 383 EJ 1,65 mm 2 </p> <p>08/85→</p> <p><b>H22674-20</b> 068 103 383 EK 78 Ø</p> <p>1,7 mm 3 </p> <p>08/85→</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V30584-00</b> 026 198 025 A 8,5 mm Kork</p> <p></p> <p><b>V53509-00</b> </p> <p>026 198 025 C 6,5 mm Gummi</p> <p></p> <p>1 Dichtlippe</p> <p></p>	<p><b>N90300-00</b> 026 109 675 (8x)</p> <p><b>P76531-00</b> 026 109 675</p>	<p><b>X04875-01</b> 026 129 717 D</p> <p>8x</p> <p></p> <p><b>X55899-01</b> 068 129 717 E</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p> <p><b>X07854-01</b> </p> <p>841 253 115 B</p> <p></p> <p><b>X51157-01</b> </p> <p>433 253 115</p> <p></p>	<p>4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)</p> <p></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>
1,6 DT DTA JU PP RL	51-55 kW (69-75 PS)	PASSAT SANTANA	08/80→	<p><b>S31446-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>D31446-00</b> <sup>(12)</sup> 050 198 012 A</p> <p><b>B30584-00</b> <sup>(13)</sup> 037 198 011 C</p>	<p><b>H04843-00</b> 026 103 383 P 82 Ø</p> <p>1,75 mm</p> <p></p>	<p><b>T04125-00</b> 049 103 384 B (10x)</p> <p></p>	<p><b>V30584-00</b> 026 198 025 A 8,5 mm Kork</p> <p></p> <p><b>V53509-00</b> </p> <p>026 198 025 C 6,5 mm Gummi</p> <p></p> <p>1 Dichtlippe</p> <p></p>	<p><b>N90300-00</b> 026 109 675 (8x)</p> <p><b>P76531-00</b> 026 109 675</p>	<p><b>X04875-01</b> 026 129 717 D</p> <p>8x</p> <p></p> <p><b>X55170-01</b> 026 129 717 F</p> <p></p> <p><b>X07853-01</b> <sup>(10)</sup> 035 121 171 C</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p> <p><b>X07854-01</b> </p> <p>841 253 115 B</p> <p></p> <p><b>X51156-01</b> </p> <p>443 253 115 A</p> <p></p>	<p>4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)</p> <p></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>
1,6 EM FN FP FR FS FT FV WP WV WY YH YK YN YP YS YU YY	48-81 kW (65-110 PS)	CADDY GOLF GOLF GTI JETTA PASSAT SANTANA SCIROCCO	08/75→	<p><b>S30587-00</b> <sup>(12)</sup> <sup>(13)</sup> <b>D30587-00</b> <sup>(12)</sup> 049 198 012 H</p> <p><b>B30584-00</b> <sup>(13)</sup> 037 198 011 C</p>	<p><b>H04129-00</b> 049 103 383 K 81 Ø</p> <p>1,75 mm</p> <p></p>	<p><b>T04132-00</b> 049 103 385 (10x)</p> <p></p>	<p><b>V30584-00</b> 026 198 025 A 8,5 mm Kork</p> <p></p> <p><b>V31265-00</b> </p> <p>056 198 025 6,5 mm</p> <p></p>	<p><b>N90300-00</b> 026 109 675 (8x)</p> <p><b>P76531-00</b> 026 109 675</p>	<p><b>X04875-01</b> 026 129 717 D</p> <p>8x</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p> <p><b>X07854-01</b> </p> <p>841 253 115 B</p> <p></p>	<p>4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x)</p> <p></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>

VOLKSWAGEN												
1,6 JX	51 kW (69-70 PS)	TRANSPORTER	08/84-07/92	<b>S30435-00</b> <sup>12</sup> <sup>13</sup> 068 198 001  <b>D30435-00</b> <sup>12</sup> 068 198 012 L  <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H03675-00</b> 068 103 383 FE 1,6 mm 1 <b>H13675-10</b> 068 103 383 FF 1,65 mm 2 <b>H23675-20</b> 068 103 383 FG 78 Ø 1,7 mm 3 	<b>T02673-00</b> 068 103 384 A (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X55899-01</b> 068 129 717 E 8x 	<b>X03747-01</b> 026 129 589 A 	4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,6 ME	40 kW (54-55 PS)	CADDY D GOLF D JETTA D	08/82-07/92	<b>S30435-00</b> <sup>12</sup> <sup>13</sup> 068 198 001  <b>D30435-00</b> <sup>12</sup> 068 198 012 L  <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H02674-00</b> 068 103 383 EH 1,6 mm 1 <b>H12674-10</b> 068 103 383 EJ 1,65 mm 2 <b>H22674-20</b> 068 103 383 EK 78 Ø 1,7 mm 3 	<b>T02673-00</b> 068 103 384 A (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x <b>X04875-01</b> 026 129 717 D  <b>X55899-01</b> 068 129 717 E 	<b>X03747-01</b> 026 129 589 A  <b>X07854-01</b> 841 253 115 B <b>X51157-01</b> 433 253 115	4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,6 MF RA SB 1V	44-59 kW (60-80 PS)	GOLF TD JETTA TD PASSAT TD	08/83-09/93	<b>S30435-00</b> <sup>12</sup> <sup>13</sup> 068 198 001  <b>D30435-00</b> <sup>12</sup> 068 198 012 L  <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H02674-00</b> 068 103 383 EH 1,6 mm 1 <b>H12674-10</b> 068 103 383 EJ 1,65 mm 2 <b>H22674-20</b> 068 103 383 EK 78 Ø 1,7 mm 3 	<b>T02673-00</b> 068 103 384 A (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x <b>X04875-01</b> 026 129 717 D  <b>X55899-01</b> 068 129 717 E 	<b>X03747-01</b> 026 129 589 A 	4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,6 1F	53-55 kW (72-75 PS)	CADDY PASSAT POLO	02/88-09/97	<b>D36400-00</b> <sup>12</sup> 051 198 012 D <b>B32952-00</b> <sup>13</sup> 051 198 011 C	<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>X53263-01</b> 051 103 483 A ACM  2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	8x <b>X86528-01</b> 048 129 717 D 	<b>X51947-01</b> 037 253 039 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
1,7 AHB	42 kW (57 PS)	CADDY SDI	07/96-09/00	<p><b>D32721-00</b> <sup>12</sup> 028 198 012 F</p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D Mot.→AHB 005 000</p> <p><b>B37015-00</b> <sup>13 35</sup> Mot.AHB 005 001→</p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X81385-01</b> </p> <p>155 253 115</p>	<p>4x <b>X54624-01</b> 044 103 609 D ACM</p> <p><b>70-31414-10</b></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AHB 005 000 <b>P77317-01</b> K →  028 103 171 B PTFE Mot.AHB 005 001→ <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>
1,7 AHG	42 kW (57 PS)	POLO SDI	04/97-10/99	<p><b>D32721-00</b> <sup>12</sup> 028 198 012 F</p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D Mot.→AHG 010 000</p> <p><b>B37015-00</b> <sup>13 35</sup> Mot.AHG 010 001→</p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X81385-01</b> </p> <p>155 253 115</p>	<p>4x <b>X54624-01</b> 044 103 609 D ACM</p> <p><b>70-31414-10</b></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AHG 010 000 <b>P77317-01</b> K →  028 103 171 B PTFE Mot.AHG 010 001→ <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>
1,7 AKU	44 kW (60 PS)	LUPO SDI POLO SDI	08/97-07/05	<p><b>D32721-00</b> <sup>12</sup> 028 198 012 F</p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D Mot.→AKU 013 000</p> <p><b>B37015-00</b> <sup>13 35</sup> Mot.AKU 013 001→</p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X81385-01</b> </p> <p>155 253 115</p>	<p>4x <b>X54624-01</b> 044 103 609 D ACM</p> <p><b>70-31414-10</b></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AKU 013 000 <b>P77317-01</b> K →  028 103 171 B PTFE Mot.AKU 013 001→ <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>
1,7 AKW	42 kW (57 PS)	POLO SDI	07/97-09/01	<p><b>D32721-00</b> <sup>12</sup> 028 198 012 F</p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X81385-01</b> </p> <p>155 253 115</p>	<p>4x <b>X54361-01</b> 037 115 220 B NBR</p> <p><b>X54624-01</b> 044 103 609 D ACM</p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P77183-01</b> K →  06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>

VOLKSWAGEN														
1,7 CA CB CD CE V W Z	46-59 kW (62-80 PS)	TRANSPORTER 411,412 412	07/68→	<b>S37029-00</b> <sup>13</sup> 021 198 009 D	<b>H80722-00</b> 021101343 90 Ø 0,7 mm 	4x	<b>X53150-01</b> 021 101 481 Kork 	2x	<b>X89183-01</b> 021 129 707 D 	4x	<b>X81944-01</b> 021 256 251 A  <b>X81354-01</b> <sup>13</sup> 025 251 261 	4x 2x	<b>P76152-01</b> K ← 021 105 247 A 42x62x10 A SL RD FPM <b>P76325-01</b> K → 029 105 245 B 75x95x10/9,5 A LD FPM	
1,7 KY	42 kW (57 PS)	TRANSPORTER	08/85-07/92	<b>S30435-00</b> <sup>12</sup> <sup>13</sup> 068 198 001  <b>D30435-00</b> <sup>12</sup> 068 198 012 L  <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H02393-00</b> 033 103 383 K 1,53 mm 1 <b>H12393-10</b> 033 103 383 L 1,57 mm 2 <b>H22393-20</b> 033 103 383 M 81 Ø 1,61 mm 3	<b>T02673-00</b> 068 103 384 A (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> <sup>13</sup> 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x	<b>X55899-01</b> 068 129 717 E 	<b>X03747-01</b> 026 129 589 A 	4x	<b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,7 WL YX	55 kW (75 PS)	ILTIS	03/79-12/88	<b>D30587-00</b> <sup>12</sup> 049 198 012 H	<b>H04129-00</b> 049 103 383 K 81 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V31265-00</b> <sup>13</sup> 056 198 025 6,5 mm 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x	<b>X04875-01</b> 026 129 717 D 	<b>X03747-01</b> 026 129 589 A  <b>X07854-01</b> <sup>13</sup> 841 253 115 B 	4x	<b>X04116-01</b> 026 103 609 D 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 AAM	55 kW (75 PS)	GOLF →1H P 490 000, 1H PB 140 000, 1H PW 490 000 PASSAT →31 P 160 000 VENTO →1H P 490 000, 1H PB 140 000, 1H PW 490 000	08/90-06/02	<b>S31640-00</b> <sup>12</sup> <sup>13</sup> <b>D36400-00</b> <sup>12</sup> 051 198 012 D Mot.AAM 408 198→ <b>D31640-00</b> <sup>12</sup> 051 198 012 B <b>B32952-00</b> <sup>13</sup> 051 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm Mot.→AAM 408 197  <b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS Mot.AAM 408 198→ 	<b>T04125-00</b> 049 103 384 B (10x) Mot.→AAM 408 197  <b>T50469-00</b> 050 103 384 (10x) Mot.AAM 408 198→ 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> <sup>13</sup> 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) Mot.→AAM 408 197 <b>N91190-00</b> 027 109 675 (8x) Mot.AAM 408 198→ <b>P76531-00</b> 026 109 675 Mot.→AAM 408 197 <b>P76532-00</b> 027 109 675 Mot.AAM 408 198→	8x 8x	<b>X04875-01</b> 026 129 717 D Mot.→AAM 408 197  <b>X86528-01</b> 048 129 717 D Mot.AAM 408 198→ 	<b>X03747-01</b> 026 129 589 A  <b>X51947-01</b> 037 253 039 	4x	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN													
1,8 AAM	55 kW (75 PS)	GOLF PASSAT VENTO	1H P 490 001, 1H PB 140 001, 1H PW 490 001→ 31 P 160 001→ 1H P 490 001, 1H PB 140 001, 1H PW 490 001→	08/90-06/02	<b>D36400-00</b> <sup>12</sup> 051 198 012 D Mot.AAM 408 198→ <b>B32952-00</b> <sup>13</sup> 051 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm Mot.→AAM 408 197  <b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS Mot.AAM 408 198→ 	<b>T04125-00</b> 049 103 384 B (10x) Mot.→AAM 408 197  <b>T50469-00</b> 050 103 384 (10x) Mot.AAM 408 198→ 	<b>X53263-01</b> 051 103 483 A ACM  2 Dichtlippen	<b>N90300-00</b> 026 109 675 (8x) Mot.→AAM 408 197 <b>N91190-00</b> 027 109 675 (8x) Mot.AAM 408 198→ <b>P76531-00</b> 026 109 675 Mot.→AAM 408 197 <b>P76532-00</b> 027 109 675 Mot.AAM 408 198→	<b>X04875-01</b> 026 129 717 D Mot.→AAM 408 197  <b>X86528-01</b> 048 129 717 D Mot.AAM 408 198→ 	<b>X03747-01</b> 026 129 589 A  <b>X51947-01</b> 037 253 039 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 ABS	66 kW (90 PS)	GOLF PASSAT VENTO	→1H P 490 000, 1H PB 140 000, 1H PW 490 000 →31 P 160 000 →1H P 490 000, 1H PB 140 000, 1H PW 490 000	02/88-04/99	<b>S31640-00</b> <sup>12</sup> <sup>13</sup> <b>D36400-00</b> <sup>12</sup> 051 198 012 D Mot.ABS 935 646→ <b>D31640-00</b> <sup>12</sup> 051 198 012 B <b>B32952-00</b> <sup>13</sup> 051 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm Mot.→ABS 935 645  <b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS Mot.ABS 935 646→ 	<b>T04125-00</b> 049 103 384 B (10x) Mot.→ABS 935 645  <b>T50469-00</b> 050 103 384 (10x) Mot.ABS 935 646→ 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✕ 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) Mot.→ABS 935 645 <b>N91190-00</b> 027 109 675 (8x) Mot.ABS 935 646→ <b>P76531-00</b> 026 109 675 Mot.→ABS 935 645 <b>P76532-00</b> 027 109 675 Mot.ABS 935 646→	<b>X04875-01</b> 026 129 717 D Mot.→ABS 935 645  <b>X86528-01</b> 048 129 717 D Mot.ABS 935 646→ 	<b>X03747-01</b> 026 129 589 A  <b>X51947-01</b> 037 253 039 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 ABS	66 kW (90 PS)	GOLF PASSAT VENTO	1H P 490 001, 1H PB 140 001, 1H PW 490 001→ 31 P 160 001→ 1H P 490 001, 1H PB 140 001, 1H PW 490 001→	02/88-04/99	<b>D36400-00</b> <sup>12</sup> 051 198 012 D Mot.ABS 935 646→ <b>B32952-00</b> <sup>13</sup> 051 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm Mot.→ABS 935 645  <b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS Mot.ABS 935 646→ 	<b>T04125-00</b> 049 103 384 B (10x) Mot.→ABS 935 645  <b>T50469-00</b> 050 103 384 (10x) Mot.ABS 935 646→ 	<b>X53263-01</b> 051 103 483 A ACM  2 Dichtlippen	<b>N90300-00</b> 026 109 675 (8x) Mot.→ABS 935 645 <b>N91190-00</b> 027 109 675 (8x) Mot.ABS 935 646→ <b>P76531-00</b> 026 109 675 Mot.→ABS 935 645 <b>P76532-00</b> 027 109 675 Mot.ABS 935 646→	<b>X04875-01</b> 026 129 717 D Mot.→ABS 935 645  <b>X86528-01</b> 048 129 717 D Mot.ABS 935 646→ 	<b>X03747-01</b> 026 129 589 A  <b>X51947-01</b> 037 253 039 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 ACC	66 kW (90 PS)	GOLF		11/91-08/97	<b>D36400-00</b> <sup>12</sup> 051 198 012 D <b>B32952-00</b> <sup>13</sup> 051 198 011 C	<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X53263-01</b> 051 103 483 A ACM  2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	8x <b>X86528-01</b> 048 129 717 D 	<b>X51947-01</b> 037 253 039 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM



VOLKSWAGEN												
1,8 ADD	66 kW (90 PS)	POLO	01/97-09/01	<b>D37023-00</b> <sup>12</sup> <b>B32233-00</b> <sup>13</sup> 037 198 011 G <b>B37023-00</b> <sup>13</sup> <sup>35</sup>	<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X53263-01</b> 051 103 483 A ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x 	<b>X55170-01</b> 026 129 717 F 8x 	<b>X03747-01</b> 026 129 589 A 4x 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P77317-01</b> K → 028 103 171 B PTFE <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 ADR AEB AFY	85-112 kW (115-152 PS)	PASSAT PASSAT T	10/96-12/01	<b>S32232-00</b> <sup>12</sup> <sup>13</sup> <b>D32233-00</b> <sup>12</sup> 058 198 012 +058 198 025 A <b>B32232-00</b> <sup>13</sup> 058 198 011 <b>B37030-00</b> <sup>13</sup> <sup>35</sup> 	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T10468-00</b> 058 103 385 B (10x) 	<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x 	<b>X57659-01</b> 058 129 717 B 20x 	<b>X51632-01</b> 058 253 039 L 	<b>X54226-01</b> 058 103 609 Aluminium 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P77317-01</b> K → 028 103 171 B PTFE <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 ADZ	66 kW (90 PS)	GOLF PASSAT POLO VENTO	02/88-06/02	<b>D31640-00</b> <sup>12</sup> 051 198 012 B Mot.→ADZ 011 565 <b>D36400-00</b> <sup>12</sup> 051 198 012 D Mot.ADZ 011 566→ <b>B32952-00</b> <sup>13</sup> 051 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm Mot.→ADZ 011 565 	<b>T04125-00</b> 049 103 384 B (10x) Mot.→ADZ 011 565 	<b>X53263-01</b> 051 103 483 A ACM 	<b>N90300-00</b> 026 109 675 (8x) Mot.→ADZ 011 565 <b>N91190-00</b> 027 109 675 (8x) Mot.ADZ 011 566→ <b>P76531-00</b> 026 109 675 Mot.→ADZ 011 565 <b>P76532-00</b> 027 109 675 Mot.ADZ 011 566→ 8x 	<b>X04875-01</b> 026 129 717 D Mot.→ADZ 011 565 8x 	<b>X51947-01</b> 037 253 039 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 AFE	72 kW (98 PS)	SANTANA	01/95→	<b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X53263-01</b> 051 103 483 A ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x 	<b>X55626-01</b> 048 129 717 A 8x 	<b>X03747-01</b> 026 129 589 A 4x 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
1.8 AGN	92 kW (125 PS)	BORA GOLF	08/97-06/06	<b>D36707-00</b> <sup>12</sup> <b>B32934-00</b> <sup>13 38</sup> 06A 198 011 A <b>Z36190-00</b> <sup>8</sup> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T80109-00</b> 06A 103 385 C (10x) Mot.→AGN 107 000  <b>T50468-00</b> 06A 103 385 A (10x) Mot.AGN 107 001→ 	<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x	<b>X88304-01</b> 06A 133 398 D 4x 	<b>X51632-01</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
1.8 AGU AJH APH AQA ARX ARZ AUM AUQ AVC AWC AWD AWM AWP AWT AWU AWV AWW BAE BBU BGC BJX BKF BNU CED CEDA CFUA	110-132 kW (150-180 PS)	BORA BORA T GOLF T NEW BEETLE PASSAT T POLO GTI SHARAN T	08/97→	<b>D32934-00</b> <sup>12</sup> <b>B32934-00</b> <sup>13 38</sup> 06A 198 011 A <b>Z36190-00</b> <sup>8</sup> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x) 	<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
1.8 AN AP AT	50-63 kW (68-86 PS)	TRANSPORTER 411,412 412	07/73-07/75	<b>A31438-00</b> <sup>14</sup> 029 198 009 A 	<b>H51289-00</b> 4x 051101341A 93 Ø 	<b>X53150-01</b> 2x 021 101 481 Kork 	<b>X55893-01</b> 4x 021 129 707 E 	<b>X51285-01</b> 4x 039 256 251  <b>X81354-01</b> <sup>15</sup> 2x 025 251 261 	<b>P76152-01 K</b> ← 021 105 247 A 42x62x10 A SL RD FPM			
1.8 ANB APT APU ARG	92-110 kW (125-150 PS)	PASSAT PASSAT T	10/96-11/00	<b>D32232-00</b> <sup>12</sup> 058 198 012 +058 198 025 A <b>B37030-00</b> <sup>13 35</sup>  <b>Z36190-00</b> <sup>8</sup> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T10468-00</b> 058 103 385 B (10x) 	<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L  <b>X51169-01</b> <sup>16</sup> 431 253 115 A 	<b>X54226-01</b> 058 103 609 Aluminium  <b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P77317-01 K</b> → 028 103 171 B PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
1.8 ANN ANP	55-66 kW (75-90 PS)	GOLF	07/93-06/02	<b>D36400-00</b> <sup>(12)</sup> 051 198 012 D <b>B37023-00</b> <sup>(13) (35)</sup>	<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X53263-01</b> 051 103 483 A ACM <b>2 Dichtlippen</b> 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X86528-01</b> 048 129 717 D 8x 	<b>X51638-01</b> 037 253 039 D 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P77317-01 K</b> → 028 103 171 B PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1.8 ANQ	92 kW (125 PS)			<b>D32934-00</b> <sup>(12)</sup> <b>B32934-00</b> <sup>(13) (38)</sup> 06A 198 011 A <b>Z36190-00</b> <sup>(8)</sup> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x) 	<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B 20x 	<b>X51632-01</b> 058 253 039 L <b>X07867-01</b> 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
1.8 AWL BPL	110 kW (150 PS)	PASSAT T	11/00→	<b>D32934-00</b> <sup>(12)</sup> <b>B32934-00</b> <sup>(13) (38)</sup> 06A 198 011 A <b>Z36190-00</b> <sup>(8)</sup> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x) 	<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X57659-01</b> 058 129 717 B 20x 	<b>X51632-01</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
1.8 BAF	92 kW (125 PS)	BORA GOLF	08/97-06/05	<b>D36707-00</b> <sup>(12)</sup> <b>B32934-00</b> <sup>(13) (38)</sup> 06A 198 011 A <b>Z36190-00</b> <sup>(8)</sup> 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x)  <b>T80109-00</b> 06A 103 385 C (10x) 	<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675	<b>X88304-01</b> 4x 06A 133 398 D 	<b>X51632-01</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
1.8 BHG BNY BSL UDH	67-78 kW (91-106 PS)				<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 		<b>X59501-01</b> 026 103 483 2 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55899-01</b> 8x 068 129 717 E 	<b>X03747-01</b> 4x 026 129 589 A 	<b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
1.8 BKT BKU CKZA <b>[NEW]</b>	74 kW (101 PS)				<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X59498-01</b> 051 103 483 D <b>2 Dichtlippen</b> 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	8x	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

VOLKSWAGEN												
Ltr.												
1,8 BSA 74 kW (101 PS)					<b>H80097-00</b> 050 103 383 B 82,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X59498-01</b> 051 103 483 D 2 Dichtlippen 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55430-01</b> 048 129 717 A 8x 	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77745-01 K</b> → 030 103 171 Q PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
1,8 BYJ 118 kW (160 PS)					<b>H80727-00</b> 06H 103 383 Q 82,5 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89272-01</b> 06J 129 717 16x 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K</b> ← 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K</b> →
1,8 BZB 118 kW (160 PS)		PASSAT TSI	05/07-01/12	<b>D40567-00</b> <sup>12</sup> <b>B38289-00</b> <sup>13 35</sup>	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89272-01</b> 06J 129 717 16x 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K</b> ← 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K</b> → 06H 103 171 F 85x132/152x15,7 PTFE
1,8 CDA CDAB CGYA		CC TSI GOLF TSI PASSAT TSI	05/07→	<b>D40567-00</b> <sup>12</sup> <b>B38289-00</b> <sup>13 35</sup>	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x)  <b>T80727-00</b> 06D 103 385 D (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89272-01</b> 06J 129 717 16x  <b>X89273-01</b> 06F 129 717 D 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K</b> ← 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K</b> → 06H 103 171 F 85x132/152x15,7 PTFE
1,8 CEA CEAA <b>[NEW]</b>				<b>D40567-00</b> <sup>12</sup> <b>B38289-00</b> <sup>13 35</sup>	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89273-01</b> 06F 129 717 D 16x 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K</b> ← 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K</b> → 06H 103 171 F 85x132/152x15,7 PTFE
1,8 CNSA CNSB CXBA CXBB <b>[NEW]</b>				<b>D40708-01</b> <sup>12</sup> <b>B82501-00</b> <sup>13</sup>	<b>H40708-00</b> 06K 103 383 K 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X59914-01</b> 06K 129 717 A 16x 	<b>X59924-01</b> 06L 253 039 	<b>X90114-01</b> 06K 103 649  <b>70-31414-10</b> 	<b>P77842-01 K</b> ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77846-01 K</b> → 06K 103 171 A PTFE
1,8 CPKA CPRA <b>[NEW]</b>		BEETLE TSI	12/13→	<b>D90195-00</b> <sup>12</sup> <b>B82496-00</b> <sup>13</sup>	<b>H40708-00</b> 06K 103 383 K 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 	<b>70-31414-10</b> 	<b>N96006-00</b> 06L 109 675 (8x) +036 109 675 A (8x) <b>P76662-00 ES</b> 036 109 675 <b>P93254-00 AS</b> 06L 109 675	<b>X59914-01</b> 06K 129 717 A 8x  8x 	<b>X59924-01</b> 06L 253 039 	<b>70-31414-10</b> 	<b>P77842-01 K</b> ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77846-01 K</b> → 06K 103 171 A PTFE →03/14

VOLKSWAGEN												
1,8 CPKA CPRA <b>[NEW]</b>	125 kW (170 PS)	JETTA TSI	07/14→	<b>D90195-00</b> <sup>12</sup> <b>B82496-00</b> <sup>13</sup>	<b>H40708-00</b> 06K 103 383 K 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 	<b>70-31414-10</b> 	<b>N96006-00</b> 06L 109 675 (8x) +036 109 675 A (8x) <b>P76662-00</b> ES 036 109 675 <b>P93254-00</b> AS 06L 109 675	<b>X59914-01</b> 06K 129 717 A  8x	<b>X59924-01</b> 06L 253 039 	<b>70-31414-10</b> 	<b>P77842-01</b> K ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM
1,8 DS DX EV EX GU GX GZ HT HV JH JJ KT PB PF RD RG RH RM RP RV 1P 2H	62-82 kW (84-112 PS)	CADDY GOLF GOLF GTI JETTA PASSAT SANTANA SCIROCCO SCIROCCO GTI	08/82→	<b>S31192-00</b> <sup>12</sup> <sup>13</sup> <b>D31192-00</b> <sup>12</sup> 026 198 012 AB <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✕ 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D  8x <b>X55170-01</b> 026 129 717 F  <b>X07853-01</b> <sup>10</sup> 035 121 171 C 	<b>X03747-01</b> 026 129 589 A  <b>X07854-01</b> <sup>10</sup> 841 253 115 B  <b>X07867-01</b> <sup>10</sup> 533 253 115 D  <b>X51169-01</b> <sup>10</sup> 431 253 115 A 	4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 DZ	82 kW (112 PS)	PASSAT	12/83-03/88	<b>S31448-00</b> <sup>12</sup> <sup>13</sup> <b>D31448-00</b> <sup>12</sup> 026 198 012 AD <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✕ 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D  8x <b>X55170-01</b> 026 129 717 F 	<b>X03747-01</b> 026 129 589 A  <b>X51169-01</b> <sup>10</sup> 431 253 115 A 	4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 JN	66 kW (90 PS)	PASSAT	01/83-03/88	<b>S31443-00</b> <sup>12</sup> <sup>13</sup> <b>D31443-00</b> <sup>12</sup> <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork  <b>V53509-00</b> ✕ 026 198 025 C 6,5 mm Gummi  1 Dichtlippe	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X04875-01</b> 026 129 717 D  8x <b>X55170-01</b> 026 129 717 F 	<b>X03747-01</b> 026 129 589 A  <b>X51157-01</b> <sup>10</sup> 433 253 115 	4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN													
1,8 KR PL	95-102 kW (129-140 PS)	CORRADO GOLF GTI JETTA PASSAT SCIROCCO	10/85-09/93	<b>S31196-00</b> <sup>12</sup> <sup>13</sup> <b>D31196-00</b> <sup>12</sup> 027 198 012 K <b>B30584-00</b> <sup>13</sup> 037 198 011 C	<b>H04843-00</b> 026 103 383 P 82 Ø 1,75 mm 	<b>T04843-00</b> 027 103 385 C (10x) 	<b>V31196-00</b> 027 198 025 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	2x <b>X07866-01</b> 037 129 717 F 16x <b>X07865-01</b> <sup>10</sup> 027 129 717 D 		<b>X07855-01</b> 027 129 589 A 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 PD	49 kW (67 PS)	TRANSPORTER	12/90-07/92	<b>S31643-00</b> <sup>12</sup> <sup>13</sup> <b>D31643-00</b> <sup>12</sup> 044 198 012 <b>B31643-00</b> <sup>13</sup> 044 198 011 A	<b>H50155-00</b> 044 103 383 D 82,7 Ø 	<b>T04132-00</b> 049 103 385 (10x) 	<b>V30584-00</b> 026 198 025 A 8,5 mm Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x <b>X04875-01</b> 026 129 717 D 		<b>X03747-01</b> 026 129 589 A 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
1,8 PG	118 kW (160 PS)	CORRADO G60 GOLF G60 PASSAT G60	08/88-05/97	<b>D32717-00</b> <sup>12</sup> 037 198 012 D <b>B32717-00</b> <sup>13</sup> 037 198 011 D	<b>H50154-00</b> 037 103 383 L 82,5 Ø MLS 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X53064-01</b> 037 103 483 C NBR 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	8x <b>X04875-01</b> 026 129 717 D 		<b>X03747-01</b> 026 129 589 A 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM



































VOLKSWAGEN												
Ltr.												
1,9 AAZ	55 kW (75 PS) GOLF TD PASSAT TD VENTO TD	03/91-04/99	<b>S31598-00</b> <sup>12</sup> <sup>13</sup> Mot.→AAZ 678 000  <b>D31598-00</b> <sup>12</sup> 028 198 012 B Mot.→AAZ 678 000  <b>D32719-00</b> <sup>12</sup> 028 198 012 E Mot.AAZ 678 001→  <b>B31598-00</b> <sup>13</sup> 028 198 011 B 	<b>H02390-00</b> 028 103 383 BB 1,6 mm 1 Mot.→AAZ 462 614 <b>H12390-10</b> 028 103 383 BC 1,65 mm 2 <b>H22390-20</b> 028 103 383 BD 81 Ø 1,7 mm 3 Mot.→AAZ 462 614  <b>H02391-00</b> 028 103 383 BH 1,53 mm 1 MLS Mot.AAZ 462 615→ <b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 MLS Mot.AAZ 462 615→ <b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 MLS Mot.AAZ 462 615→ 	<b>T02673-00</b> 068 103 384 A (10x) 	<b>V31598-00</b> 028 198 025  <b>X53152-01</b> 028 103 483 B ACM 	<b>N90300-00</b> 026 109 675 (8x) Mot.→AAZ 678 000 <b>N91190-00</b> 027 109 675 (8x) Mot.AAZ 678 001→ <b>P76531-00</b> 8x 026 109 675 Mot.→AAZ 678 000 <b>P76532-00</b> 8x 027 109 675 Mot.AAZ 678 001→	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 	4x <b>X54361-01</b> 037 115 220 B NBR 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	
1,9 ABL	50 kW (68 PS) TRANSPORTER	10/92-04/03	<b>S31598-00</b> <sup>12</sup> <sup>13</sup>  <b>D31598-00</b> <sup>12</sup> 028 198 012 B Mot.→ABL 076 000  <b>B31598-00</b> <sup>13</sup> 028 198 011 B 	<b>H02391-00</b> 028 103 383 BH 1,53 mm 1 MLS <b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 MLS <b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 	<b>V31598-00</b> 028 198 025 	<b>N90300-00</b> 026 109 675 (8x) Mot.→ABL 076 000 <b>N91190-00</b> 027 109 675 (8x) Mot.ABL 076 001→ <b>P76531-00</b> 8x 026 109 675 Mot.→ABL 076 000 <b>P76532-00</b> 027 109 675 Mot.ABL 076 001→	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 	4x <b>X54361-01</b> 037 115 220 B NBR Mot.→ABL 070 000  <b>X04116-01</b> 026 103 609 D Mot.ABL 070 001→ Mot.→ABL 076 000 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	

VOLKSWAGEN												
Ltr.												
1,9 AEF	47 kW (64 PS) CADDY D POLO D	10/94-09/01	<p><b>D32718-00</b> <sup>12</sup> 028 198 012 D Mot.→AEF 007 000</p> <p></p> <p><b>D32719-00</b> <sup>12</sup> 028 198 012 E Mot.AEF 007 001→</p> <p></p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D Mot.→AEF265 000</p> <p></p> <p><b>B32239-00</b> <sup>13 35</sup> 06A 198 011 Mot.AEF265 001→</p>	<p><b>H02391-00</b> 028 103 383 BH 1,53 mm 1 </p> <p>MLS</p> <p><b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 </p> <p>MLS</p> <p><b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 </p> <p>MLS</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V31598-00</b> 028 198 025</p> <p></p>	<p><b>N90300-00</b> 026 109 675 (8x) Mot.→AEF 007 0000</p> <p><b>N91190-00</b> 027 109 675 (8x) Mot.AEF 007 001→</p> <p><b>P76531-00</b> 8x 026 109 675 Mot.→AEF007 0000</p> <p><b>P76532-00</b> 8x 027 109 675 Mot.AEF 007 001→</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p> <p><b>X51641-01</b></p> <p></p>	<p>4x <b>X54361-01</b> </p> <p>037 115 220 B NBR</p> <p></p> <p><b>X54624-01</b> </p> <p>044 103 609 D ACM</p> <p></p>	<p><b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AEF265 000</p> <p><b>P77317-01 K</b> → </p> <p>028 103 171 B PTFE Mot.AEF 265 001→</p> <p><b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	
1,9 AEY	47 kW (64 PS) CADDY SDI GOLF SDI POLO SDI VENTO SDI	07/95-01/04	<p><b>D32721-00</b> <sup>12</sup> 028 198 012 F</p> <p></p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D Mot.→AEY 050 000</p> <p></p> <p><b>B37015-00</b> <sup>13 35</sup> Mot.AEY 050 001→</p> <p></p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p> <p></p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p>	<p>4x <b>X54624-01</b> 044 103 609 D ACM</p> <p></p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AEY 050 000</p> <p><b>P77317-01 K</b> → </p> <p>028 103 171 B PTFE Mot.AEY 050 001→</p> <p><b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	
1,9 AFD	58 kW (79 PS)		<p><b>D32721-00</b> <sup>12</sup> 028 198 012 F</p> <p></p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D Mot.→AFD 000 999</p> <p></p> <p><b>B37015-00</b> <sup>13 35</sup> Mot.AFD 001 000→</p> <p></p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p> <p></p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p>	<p>4x <b>X54624-01</b> 044 103 609 D ACM</p> <p></p> <p><b>70-31414-10</b></p> <p></p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AFD 000 999</p> <p><b>P77317-01 K</b> → </p> <p>028 103 171 B PTFE Mot.AFD 001 000→</p> <p><b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	



VOLKSWAGEN												
Ltr.			<b>1</b>									
1,9 AFN	81 kW (110 PS) GOLF TDI PASSAT TDI POLO TDI SHARAN TDI VENTO TDI	03/96-06/02	<p><b>D32231-00</b> <sup>12</sup> 028 198 012 C Mot.→AFN 002 000</p> <p></p> <p><b>D32721-00</b> <sup>12</sup> 028 198 012 F Mot.AFN 002 001→</p> <p></p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D Mot.→AFN 576 000</p> <p></p> <p><b>B37015-00</b> <sup>13 35</sup> Mot.AFN 576 001→</p> <p></p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p> <p></p>	<p><b>N90300-00</b> 026 109 675 (8x) Mot.→AFN 002 000</p> <p><b>N91190-00</b> 027 109 675 (8x) Mot.AFN 002 001→</p> <p><b>P76531-00</b> 026 109 675 8x</p> <p>Mot.→AFN 002 000</p> <p><b>P76532-00</b> 027 109 675 8x</p> <p>Mot.AFN 002 001→</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X52970-01</b> <sup>14</sup> 1H0 253 115 A</p> <p></p>	<p>4x <b>X54361-01</b> 037 115 220 B NBR</p> <p></p> <p><b>X54624-01</b> 044 103 609 D ACM</p> <p></p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AFN 576 000</p> <p><b>P77317-01 K</b> → <sup>15</sup> 028 103 171 B PTFE Mot.AFN 576 001→</p> <p><b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	
1,9 AGD	47 kW (64 PS) POLO SDI	07/96-09/01	<p><b>D32721-00</b> <sup>12</sup> 028 198 012 F</p> <p></p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D Mot.→AGD 015 000</p> <p></p> <p><b>B37015-00</b> <sup>13 35</sup> Mot.AGD 015 001→</p> <p></p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p> <p></p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p> <p>8x</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X81385-01</b> <sup>14</sup> 155 253 115</p> <p></p>	<p>4x <b>X54624-01</b> 044 103 609 D ACM</p> <p></p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AGD 015 000</p> <p><b>P77317-01 K</b> → <sup>15</sup> 028 103 171 B PTFE Mot.AGD 015 001→</p> <p><b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>	

VOLKSWAGEN

Ltr. 		1										
1,9 AGP	50 kW (68 PS)	BORA SDI GOLF SDI POLO SDI	08/97-06/06	<p><b>S32241-00</b> <sup>12</sup> <sup>13</sup></p>  <p><b>D32241-00</b> <sup>12</sup></p> <p>038 198 012</p>   <p><b>B32241-00</b> <sup>13</sup> <sup>38</sup></p> <p>038 198 011</p> 	<p><b>H06033-00</b></p> <p>038 103 383 G</p> <p>1,45 mm 1 </p> <p>MLS</p> <p>Mot.→AGP 028 000</p> <p><b>H16033-10</b></p> <p>038 103 383 F</p> <p>1,53 mm 2 </p> <p>MLS</p> <p>Mot.→AGP 028 000</p> <p><b>H26033-20</b></p> <p>038 103 383 E</p> <p>80,5 Ø</p> <p>1,61 mm 3 </p> <p>MLS</p> <p>Mot.→AGP 028 000</p>  <p><b>H03518-00</b></p> <p>038 103 383 AL</p> <p>1,47 mm 1 </p> <p>MLS</p> <p>Mot.AGP 028 001→</p> <p><b>H13518-10</b></p> <p>038 103 383 AM</p> <p>1,57 mm 2 </p> <p>MLS</p> <p>Mot.AGP 028 001→</p> <p><b>H23518-20</b></p> <p>038 103 383 AN</p> <p>80,5 Ø</p> <p>1,67 mm 3 </p> <p>MLS</p> <p>Mot.AGP 028 001→</p> 	<p><b>T02673-00</b></p> <p>068 103 384 A (10x)</p> 	<p><b>N91190-00</b></p> <p>027 109 675 (8x)</p> <p><b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>		<p><b>X03747-01</b></p> <p>026 129 589 A</p>  <p><b>X51706-01</b> </p> <p>3A0 253 115</p>  <p><b>X52970-01</b>  </p> <p>1H0 253 115 A</p> 	<p>4x <b>70-31414-10</b></p> 	<p><b>P76096-01 K</b> ←</p> <p>054 115 147 B</p> <p>35x48x10</p> <p>A SL RD FPM</p> <p><b>P77183-01 K</b> → </p> <p>06A 103 171 A</p> <p>85x131/152x15,7</p> <p>PTFE</p> <p><b>P76087-01 N</b></p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p>

VOLKSWAGEN												
Ltr.												
1,9 AGR	66 kW (90 PS)	BORA TDI GOLF TDI POLO TDI	09/96-05/06	<p><b>S32241-00</b> <sup>12</sup> <sup>13</sup></p> <p><b>D32241-00</b> <sup>12</sup></p> <p>038 198 012</p> <p><b>B32241-00</b> <sup>13</sup> <sup>38</sup></p> <p>038 198 011</p>	<p><b>H06033-00</b></p> <p>038 103 383 G</p> <p>1,45 mm 1 </p> <p>MLS</p> <p>Mot.→AGR 151 000</p> <p><b>H16033-10</b></p> <p>038 103 383 F</p> <p>1,53 mm 2 </p> <p>MLS</p> <p>Mot.→AGR 151 000</p> <p><b>H26033-20</b></p> <p>038 103 383 E</p> <p>80,5 Ø</p> <p>1,61 mm 3 </p> <p>MLS</p> <p>Mot.→AGR 151 000</p> <p><b>H03518-00</b></p> <p>038 103 383 AL</p> <p>1,47 mm 1 </p> <p>MLS</p> <p>Mot.AGR 151 001→</p> <p><b>H13518-10</b></p> <p>038 103 383 AM</p> <p>1,57 mm 2 </p> <p>MLS</p> <p>Mot.AGR 151 001→</p> <p><b>H23518-20</b></p> <p>038 103 383 AN</p> <p>80,5 Ø</p> <p>1,67 mm 3 </p> <p>MLS</p> <p>Mot.AGR 151 001→</p>	<p><b>T02673-00</b></p> <p>068 103 384 A (10x)</p>	<p><b>N91190-00</b></p> <p>027 109 675 (8x)</p> <p><b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b></p> <p>026 129 589 A</p> <p><b>X51706-01</b> </p> <p>3A0 253 115</p> <p><b>X52970-01</b> </p> <p>1H0 253 115 A</p>	<p>4x <b>70-31414-10</b></p>	<p><b>P76096-01 K</b> ←</p> <p>054 115 147 B</p> <p>35x48x10</p> <p>A SL RD FPM</p> <p><b>P77183-01 K</b> → </p> <p>06A 103 171 A</p> <p>85x131/152x15,7</p> <p>PTFE</p> <p><b>P76087-01 N</b></p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p>	

VOLKSWAGEN												
Ltr.												
1,9 AHF	81 kW (110 PS) BORA TDI GOLF TDI	08/97-05/04	<p><b>S32241-00</b> <sup>12</sup> <sup>13</sup></p> <p><b>D32241-00</b> <sup>12</sup></p> <p><b>B32241-00</b> <sup>13</sup> <sup>38</sup></p>	<p><b>H06033-00</b> 038 103 383 G 1,45 mm 1 </p> <p>MLS Mot.→AHF 140 000</p> <p><b>H16033-10</b> 038 103 383 F 1,53 mm 2 </p> <p>MLS Mot.→AHF 140 000</p> <p><b>H26033-20</b> 038 103 383 E 80,5 Ø 1,61 mm 3 </p> <p>MLS Mot.→AHF 140 000</p> <p><b>H03518-00</b> 038 103 383 AL 1,47 mm 1 </p> <p>MLS Mot.AHF 140 001→</p> <p><b>H13518-10</b> 038 103 383 AM 1,57 mm 2 </p> <p>MLS Mot.AHF 140 001→</p> <p><b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 </p> <p>MLS Mot.AHF 140 001→</p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>		<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>		<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X51706-01</b> </p> <p>3A0 253 115</p> <p><b>X52970-01</b> </p> <p>1H0 253 115 A</p>	<p>4x <b>70-31414-10</b></p>	<p><b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p><b>P77183-01 K</b> → </p> <p>06A 103 171 A 85x131/152x15,7 PTFE</p> <p><b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>
1,9 AHH ASX AVG	47-81 kW (64-110 PS) GOLF TDI PASSAT TDI POLO SDI SHARAN TDI	09/96-06/02	<p><b>D32721-00</b> <sup>12</sup></p> <p><b>B37015-00</b> <sup>13</sup> <sup>35</sup></p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>		<p><b>X03747-01</b> 026 129 589 A</p>	<p>4x <b>X54624-01</b> 044 103 609 D ACM</p> <p><b>70-31414-10</b></p>	<p><b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P77317-01 K</b> → </p> <p>028 103 171 B PTFE</p> <p><b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>

VOLKSWAGEN												
1,9 AHU	66-67 kW (90-91 PS)	CADDY TDI GOLF TDI PASSAT TDI POLO TDI SHARAN TDI VENTO TDI	09/93-03/10	<p><b>S32721-00</b> <sup>12</sup> <sup>13</sup></p> <p><b>D32721-00</b> <sup>12</sup></p> <p>028 198 012 F</p> <p><b>B32231-00</b> <sup>13</sup></p> <p>028 198 011 D Mot.→AHU 390 000</p> <p><b>B37015-00</b> <sup>13</sup> <sup>35</sup></p> <p>Mot.AHU 390 001→</p>	<p><b>H02392-00</b></p> <p>028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b></p> <p>028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b></p> <p>028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p>	<p><b>T02673-00</b></p> <p>068 103 384 A (10x)</p>	<p><b>V32231-00</b></p> <p>028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p>	<p><b>N91190-00</b></p> <p>027 109 675 (8x) <b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b></p> <p>026 129 589 A</p> <p>4x </p>	<p><b>X54624-01</b></p> <p>044 103 609 D ACM</p>	<p><b>P76087-01 K</b> ←</p> <p>068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11 K</b> →</p> <p>068 103 051 P 85x105x9 A SL LD FPM Mot.→AHU 390 000</p> <p><b>P77317-01 K</b> → </p> <p>028 103 171 B PTFE Mot.AHU 390 001→</p> <p><b>P76087-01 N</b></p> <p>068 103 085 E 32x47x10 A SL WD FPM</p>
1,9 AJM ANU ASZ ATD ATJ AUY AVB AVF AWX AXB AXC AXR BEW BLT BPZ BSW BTB BVK	63-110 kW (85-150 PS)	BORA TDI GOLF TDI MULTIVAN TDI NEW BEETLE PASSAT TDI POLO TDI SHARAN TDI TRANSPORTER	09/95→	<p><b>D32937-00</b> <sup>12</sup></p> <p><b>B32937-00</b> <sup>13</sup> <sup>35</sup></p>	<p><b>H09538-00</b></p> <p>038 103 383 DE 80,5 Ø 1,45 mm 1 </p> <p>MLS</p> <p><b>H19538-10</b></p> <p>038 103 383 DF 80,5 Ø 1,53 mm 2 </p> <p>MLS</p> <p><b>H29538-20</b></p> <p>038 103 383 DG 80,5 Ø 1,61 mm 3 </p> <p>MLS</p>	<p><b>T03518-00</b></p> <p>038 103 384 (10x)</p>	<p><b>X53715-01</b></p> <p>038 103 483 D ACM</p>	<p><b>N91190-00</b></p> <p>027 109 675 (8x) <b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b></p> <p>026 129 589 A</p> <p>4x </p> <p><b>X51638-01</b></p> <p>037 253 039 D</p> <p><b>X51706-01</b> </p> <p>3A0 253 115</p> <p><b>X52970-01</b> </p> <p>1H0 253 115 A</p>	<p><b>70-31414-10</b></p>	<p><b>P76096-11 K</b> ←</p> <p>038 103 085 E 35x48x10 A SL RD PTFE ACM</p> <p><b>P77183-01 K</b> → </p> <p>06A 103 171 A 85x131/152x15,7 PTFE</p> <p><b>P77181-01 N</b></p> <p>038 103 085 A 32x47x10 A SL RD PTFE ACM</p>
1,9 ALE	66 kW (90 PS)	CADDY TDI GOLF TDI POLO TDI VENTO TDI	09/93-01/04	<p><b>D32721-00</b> <sup>12</sup></p> <p>028 198 012 F</p> <p><b>B32231-00</b> <sup>13</sup></p> <p>028 198 011 D Mot.→ALE 576 000</p> <p><b>B37015-00</b> <sup>13</sup> <sup>35</sup></p> <p>Mot.ALE 576 001→</p>	<p><b>H02392-00</b></p> <p>028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b></p> <p>028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b></p> <p>028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p>	<p><b>T02673-00</b></p> <p>068 103 384 A (10x)</p>	<p><b>V32231-00</b></p> <p>028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p>	<p><b>N91190-00</b></p> <p>027 109 675 (8x) <b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b></p> <p>026 129 589 A</p> <p>4x </p> <p><b>X52970-01</b> </p> <p>1H0 253 115 A</p>	<p><b>X54624-01</b></p> <p>044 103 609 D ACM</p>	<p><b>P76087-01 K</b> ←</p> <p>068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11 K</b> →</p> <p>068 103 051 P 85x105x9 A SL LD FPM Mot.→ALE 576 000</p> <p><b>P77317-01 K</b> → </p> <p>028 103 171 B PTFE Mot.ALE 576 001→</p> <p><b>P76087-01 N</b></p> <p>068 103 085 E 32x47x10 A SL WD FPM</p>

VOLKSWAGEN												
Ltr.												
1,9 ALH	66 kW (90 PS)	09/96-05/06	<p><b>S32241-00</b> <sup>12</sup> <sup>13</sup></p> <p></p> <p><b>D32241-00</b> <sup>12</sup></p> <p></p> <p></p> <p><b>B32241-00</b> <sup>13</sup> <sup>38</sup></p> <p></p>	<p><b>H06033-00</b></p> <p>038 103 383 G</p> <p>1,45 mm 1 </p> <p>MLS</p> <p>Mot.→ALH 085 000</p> <p><b>H16033-10</b></p> <p>038 103 383 F</p> <p>1,53 mm 2 </p> <p>MLS</p> <p>Mot.→ALH 085 000</p> <p><b>H26033-20</b></p> <p>038 103 383 E</p> <p>80,5 Ø</p> <p>1,61 mm 3 </p> <p>MLS</p> <p>Mot.→ALH 085 000</p> <p></p> <p><b>H03518-00</b></p> <p>038 103 383 AL</p> <p>1,47 mm 1 </p> <p>MLS</p> <p>Mot.ALH 085 001→</p> <p><b>H13518-10</b></p> <p>038 103 383 AM</p> <p>1,57 mm 2 </p> <p>MLS</p> <p>Mot.ALH 085 001→</p> <p><b>H23518-20</b></p> <p>038 103 383 AN</p> <p>80,5 Ø</p> <p>1,67 mm 3 </p> <p>MLS</p> <p>Mot.ALH 085 001→</p> <p></p>	<p><b>T02673-00</b></p> <p>068 103 384 A (10x)</p> <p></p>	<p><b>N91190-00</b></p> <p>027 109 675 (8x)</p> <p><b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b></p> <p>026 129 589 A</p> <p></p> <p><b>X51706-01</b> <sup>A</sup></p> <p>3A0 253 115</p> <p></p> <p><b>X52970-01</b> <sup>A</sup></p> <p>1H0 253 115 A</p> <p></p>	<p>4x <b>70-31414-10</b></p> <p></p>	<p><b>P76096-01 K</b> ←</p> <p>054 115 147 B</p> <p>35x48x10</p> <p>A SL RD FPM</p> <p><b>P77183-01 K</b> → <sup>A</sup></p> <p>06A 103 171 A</p> <p>85x131/152x15,7</p> <p>PTFE</p> <p><b>P76087-01 N</b></p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p>		
1,9 ANC	44 kW (60 PS)		<p><b>D32241-00</b> <sup>12</sup></p> <p>038 198 012</p> <p></p> <p></p> <p><b>B32959-00</b> <sup>13</sup> <sup>38</sup></p>	<p><b>H03518-00</b></p> <p>038 103 383 AL</p> <p>1,47 mm 1 </p> <p>MLS</p> <p><b>H13518-10</b></p> <p>038 103 383 AM</p> <p>1,57 mm 2 </p> <p>MLS</p> <p><b>H23518-20</b></p> <p>038 103 383 AN</p> <p>80,5 Ø</p> <p>1,67 mm 3 </p> <p>MLS</p> <p></p>	<p><b>T02673-00</b></p> <p>068 103 384 A (10x)</p> <p></p>	<p><b>N91190-00</b></p> <p>027 109 675 (8x)</p> <p><b>P76532-00</b></p> <p>027 109 675</p>	<p><b>X55431-01</b></p> <p>028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b></p> <p>026 129 589 A</p> <p></p>	<p>4x <b>70-31414-10</b></p> <p></p>	<p><b>P76096-11 K</b> ←</p> <p>038 103 085 E</p> <p>35x48x10</p> <p>A SL RD PTFE ACM</p> <p><b>P77183-01 K</b> → <sup>A</sup></p> <p>06A 103 171 A</p> <p>85x131/152x15,7</p> <p>PTFE</p> <p><b>P77181-01 N</b></p> <p>038 103 085 A</p> <p>32x47x10</p> <p>A SL RD PTFE ACM</p>		

VOLKSWAGEN												
Ltr.			<b>1</b>									
1,9 AQM AYQ	47-50 kW (64-68 PS) BORA SDI CADDY SDI GOLF SDI POLO SDI	11/95-06/06	<b>D37016-00</b> <sup>12</sup>  <b>B32241-00</b> <sup>13 38</sup> 038 198 011 	<b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS <b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 		<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X51638-01</b> 037 253 039 D <b>X81385-01</b> 155 253 115 	<b>70-31414-10</b> 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	
1,9 ARD AVM BEQ BEU BJC BXT	30-63 kW (41-86 PS) BORA TDI CADDY TDI GOLF TDI POLO TDI	11/95-06/06	<b>D32241-00</b> <sup>12</sup> 038 198 012  <b>B32937-00</b> <sup>13 35</sup> 	<b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS <b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 		<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	
1,9 ARL	110 kW (150 PS) BORA TDI GOLF TDI	02/00-06/05	<b>D32937-00</b> <sup>12</sup>  <b>B32937-00</b> <sup>13 35</sup> 	<b>H09538-00</b> 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS <b>H19538-10</b> 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS <b>H29538-20</b> 038 103 383 DG 80,5 Ø 1,61 mm 3 MLS 	<b>T09538-00</b> 038 103 384 C (10x) 	<b>X53715-01</b> 038 103 483 D ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 026 129 589 A  <b>X51706-01</b> 3A0 253 115 	4x <b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	
1,9 ASV	81 kW (110 PS) BORA TDI GOLF TDI	08/97-05/04	<b>S32241-00</b> <sup>12 13</sup>  <b>D32241-00</b> <sup>12</sup> 038 198 012  <b>B32241-00</b> <sup>13 38</sup> 038 198 011 	<b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS <b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 		<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X51638-01</b> 037 253 039 D <b>X51706-01</b> 3A0 253 115  <b>X52970-01</b> 1H0 253 115 A 	<b>70-31414-10</b> 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	

VOLKSWAGEN												
1,9 ASY 47 kW (64 PS)	POLO SDI	10/01→		<p><b>D32937-00</b> <sup>12</sup></p> <p><b>B32937-00</b> <sup>13 35</sup></p>	<p><b>H03518-00</b> 038 103 383 AL 1,47 mm 1 </p> <p><b>H13518-10</b> 038 103 383 AM 1,57 mm 2 </p> <p><b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 </p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>	<p><b>X53715-01</b> 038 103 483 D ACM</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X03747-01</b> 026 129 589 A</p> <p><b>X81385-01</b> <sup>14</sup> 155 253 115</p>	<p>4x <b>70-31414-10</b></p>	<p><b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → </p> <p>06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM</p>
1,9 AVQ BJB BKC BRU BXE BXF	66-77 kW (90-105 PS)	CADDY TDI GOLF TDI JETTA TDI PASSAT TDI TOURAN TDI	02/03-10/10	<p><b>D32937-00</b> <sup>12</sup></p> <p><b>B36708-00</b> <sup>13 35</sup></p>	<p><b>H09538-00</b> 038 103 383 DE 80,5 Ø</p> <p><b>H19538-10</b> 038 103 383 DF 80,5 Ø 1,53 mm 2 </p> <p><b>H29538-20</b> 038 103 383 DG 80,5 Ø 1,61 mm 3 </p>	<p><b>T03518-00</b> 038 103 384 (10x)</p>	<p><b>X53715-01</b> 038 103 483 D ACM</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X51638-01</b> 037 253 039 D</p> <p><b>X51706-01</b> <sup>14</sup> 3A0 253 115</p>	<p><b>70-31414-10</b></p>	<p><b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K</b> → </p> <p>038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM</p>
1,9 BGG	47 kW (64 PS)			<p><b>D32719-00</b> <sup>12</sup> 028 198 012 E</p> <p><b>B37015-00</b> <sup>13 35</sup></p>	<p><b>H02391-00</b> 028 103 383 BH 1,53 mm 1 </p> <p><b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 </p> <p><b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 </p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>	<p><b>V31598-00</b> 028 198 025</p> <p><b>X53152-01</b> 028 103 483 B ACM</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X51947-01</b> 037 253 039</p>	<p><b>X54361-01</b> 037 115 220 B NBR</p>	<p><b>P77181-01 K</b> ← 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77317-01 K</b> → </p> <p>028 103 171 B PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM</p>
1,9 BGL BGM CDXA CDXB	29-55 kW (39-75 PS)			<p><b>D32241-00</b> <sup>12</sup> 038 198 012</p> <p><b>B32959-00</b> <sup>13 38</sup></p>	<p><b>H03518-00</b> 038 103 383 AL 1,47 mm 1 </p> <p><b>H13518-10</b> 038 103 383 AM 1,57 mm 2 </p> <p><b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 </p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p>		<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X03747-01 L</b> 026 129 589 A</p> <p><b>X81409-01 R</b> 034 129 589 B</p>	<p>2x <b>70-31414-10</b></p> <p>2x</p>	<p><b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → </p> <p>06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM</p>



VOLKSWAGEN												
1.9 BLS BMT BSU BXJ	55-77 kW (75-105 PS)	CADDY TDI GOLF TDI JETTA TDI PASSAT TDI POLO TDI TOURAN TDI	10/01-10/10	 D37051-00 <sup>12</sup> B36708-00 <sup>13 35</sup>	H09538-00 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS H19538-10 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS H29538-20 038 103 383 DG 80,5 Ø 1,61 mm 3 	T03518-00 038 103 384 (10x) 	X53715-01 038 103 483 D ACM  X83120-01 03G 103 483 D NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X55431-01 028 129 717 D 8x 	X81833-01 03G 253 039 A 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
1.9 BRM	74 kW (101 PS)			 D37051-00 <sup>12</sup> B36708-00 <sup>13 35</sup>	H09538-00 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS H19538-10 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS H29538-20 038 103 383 DG 80,5 Ø 1,61 mm 3 	T03518-00 038 103 384 (10x) 	X83120-01 03G 103 483 D NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X55431-01 028 129 717 D 8x 	X81833-01 03G 253 039 A 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
1.9 BRR BRS	62-75 kW (84-102 PS)	MULTIVAN TDI TRANSPORTER	01/06-11/09	 D37058-00 <sup>12</sup> B36708-00 <sup>13 35</sup>	H09538-00 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS H19538-10 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS H29538-20 038 103 383 DG 80,5 Ø 1,61 mm 3 	T03518-00 038 103 384 (10x) 	X83127-01 03G 103 483 F NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X55431-01 028 129 717 D 8x 	X51638-01 037 253 039 D 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
1.9 DF DG DH GW SP	44-68 kW (60-92 PS)	TRANSPORTER	08/82→	S31503-00 <sup>13</sup> 025 198 009 B D31503-00 025 198 012 A B31503-00 <sup>13</sup>	H50048-00 4x 025 101 343 B 95 Ø 		X00991-01 2x 113 101 481 F Kork 		X55316-01 2x 025 129 717 E  X55877-01 2x 025 129 717 C 	X51158-01 4x N 901 316 02 		P76253-01 K ← 025 105 247 A 48x68x10 A SL RD FPM P76325-01 K → 029 105 245 B 75x95x10/9,5 ALD FPM

VOLKSWAGEN												
Ltr.												
1,9 WN	85 kW (115 PS) PASSAT SANTANA	01/81-07/83	<b>S31200-00</b> <sup>12</sup> <sup>13</sup> <b>D31200-00</b> <sup>12</sup> 035 198 012 L <b>B30567-00</b> <sup>13</sup> 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	<b>V30567-00</b> ✕ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 035 129 717 M 	<b>X03747-01</b> 026 129 589 A 	5x <b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM 2x	
1,9 1X	44-45 kW (60-61 PS) TRANSPORTER	07/90-12/95	<b>S31598-00</b> <sup>12</sup> <sup>13</sup>  <b>D31598-00</b> <sup>12</sup> 028 198 012 B  <b>B31598-00</b> <sup>13</sup> 028 198 011 B 	<b>H02390-00</b> 028 103 383 BB 1,6 mm 1 Mot.→1X 104 630 <b>H12390-10</b> 028 103 383 BC 1,65 mm 2 Mot.→1X 104 630 <b>H22390-20</b> 028 103 383 BD 81 Ø 1,7 mm 3 Mot.→1X 104 630  <b>H02391-00</b> 028 103 383 BH 1,53 mm 1 MLS Mot.1X 104 631→ <b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 MLS Mot.1X 104 631→ <b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 MLS Mot.1X 104 631→ 	<b>T02673-00</b> 068 103 384 A (10x) 	<b>V31598-00</b> 028 198 025  <b>X53152-01</b> 028 103 483 B ACM 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 026 129 589 A 	4x <b>X54361-01</b> 037 115 220 B NBR 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM	

VOLKSWAGEN												
1,9 1Y	47-50 kW (64-68 PS)	CADDY D GOLF D PASSAT D POLO D VENTO D	05/89-01/04	<p><b>D31598-00</b> <sup>12</sup> 028 198 012 B Mot.→1Y 580 000</p> <p></p> <p><b>D32719-00</b> <sup>12</sup> 028 198 012 E Mot.1Y 580 001→</p> <p></p> <p><b>B31598-00</b> <sup>13</sup> 028 198 011 B</p> <p></p>	<p><b>H02390-00</b> 028 103 383 BB 1,6 mm 1 </p> <p>Mot.→1Y315599</p> <p><b>H12390-10</b> 028 103 383 BC 1,65 mm 2 </p> <p>Mot.→1Y315599</p> <p><b>H22390-20</b> 028 103 383 BD 81 Ø 1,7 mm 3 </p> <p>Mot.→1Y315599</p> <p></p> <p><b>H02391-00</b> 028 103 383 BH 1,53 mm 1 </p> <p>MLS Mot.1Y315600→</p> <p><b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 </p> <p>MLS Mot.1Y315600→</p> <p><b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 </p> <p>MLS Mot.1Y315600→</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V31598-00</b> 028 198 025</p> <p></p> <p><b>X53152-01</b> 028 103 483 B ACM</p> <p></p>	<p><b>N90300-00</b> 026 109 675 (8x) Mot.→1Y 580 000</p> <p><b>N91190-00</b> 027 109 675 (8x) Mot.1Y 580 001→</p> <p><b>P76531-00</b> 8x 026 109 675</p> <p><b>P76532-00</b> 8x 027 109 675 Mot.1Y 580 001→</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p> <p><b>X81385-01</b> <sup>13</sup> 155 253 115</p> <p></p>	<p>4x <b>X54361-01</b> 037 115 220 B NBR</p> <p></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>
1,9 1Z	66 kW (90 PS)	CADDY TDI GOLF TDI PASSAT TDI SHARAN TDI VENTO TDI	09/93-03/10	<p><b>D32231-00</b> <sup>12</sup> 028 198 012 C Mot.→1Z 770 000</p> <p></p> <p><b>D32721-00</b> <sup>12</sup> 028 198 012 F Mot.1Z 770 001→</p> <p></p> <p><b>B32231-00</b> <sup>13</sup> 028 198 011 D</p> <p></p>	<p><b>H02392-00</b> 028 103 383 BL 1,45 mm 1 </p> <p>MLS</p> <p><b>H12392-10</b> 028 103 383 BM 1,53 mm 2 </p> <p>MLS</p> <p><b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 </p> <p>MLS</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p> <p></p>	<p><b>N90300-00</b> 026 109 675 (8x) Mot.→1Z 770 000</p> <p><b>N91190-00</b> 027 109 675 (8x) Mot.1Z 770 001→</p> <p><b>P76531-00</b> 8x 026 109 675</p> <p><b>P76532-00</b> 8x 027 109 675 Mot.1Z 770 001→</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p> <p><b>X81385-01</b> <sup>13</sup> 155 253 115</p> <p></p>	<p>4x <b>X54624-01</b> 044 103 609 D ACM</p> <p></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>
2,0 AAC	62 kW (84 PS)	TRANSPORTER VENTO	07/90-04/03	<p><b>S32723-00</b> <sup>12</sup> <sup>13</sup> <b>D31643-00</b> <sup>12</sup> 044 198 012 <b>B32723-00</b> <sup>13</sup> 044 198 011</p>	<p><b>H50155-00</b> 044 103 383 D 82,7 Ø</p> <p></p>	<p><b>T02673-00</b> 068 103 384 A (10x)</p> <p></p>	<p><b>V30584-00</b> 026 198 025 A 8,5 mm Kork</p> <p></p> <p><b>V53509-00</b>  026 198 025 C 6,5 mm Gummi</p> <p></p> <p>1 Dichtlippe</p>	<p><b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675</p>	<p><b>X04875-01</b> 026 129 717 D</p> <p>8x </p> <p><b>X55430-01</b> 048 129 717 A</p> <p></p>	<p><b>X03747-01</b> 026 129 589 A</p> <p></p>	<p>4x <b>X04116-01</b> 026 103 609 D</p> <p></p>	<p><b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>

VOLKSWAGEN												
Ltr.												
2,0 ABF	110 kW (150 PS)	GOLF GTI PASSAT	08/92-08/97	<b>D32722-00</b> <sup>12</sup> 037 198 012 F Mot.→ABF 031 251 <b>D32724-00</b> <sup>12</sup> 037 198 012 J Mot.ABF 031 252→ <b>B32233-00</b> <sup>13</sup> 037 198 011 G	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm Mot.→ABF 031 251  <b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS Mot.ABF 031 252→ 	<b>T04843-00</b> 027 103 385 C (10x) Mot.→ABF 031 251  <b>T50151-00</b> 053 103 385 (10x) Mot.ABF 031 252→ 	<b>V31196-00</b> 027 198 025 Mot.→ABF 031 251  <b>V32233-00</b> 051 198 025 Mot.ABF 031 252→ 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	2x <b>X07866-01</b> 037 129 717 F 16x <b>X51711-01</b> <sup>10</sup> 037 129 717 E 	<b>X07855-01</b> 027 129 589 A  <b>X07867-01</b> <sup>10</sup> 533 253 115 D 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
2,0 ADC	85 kW (116 PS)			<b>D37031-00</b> <sup>12</sup> 037 198 012 N <b>B32233-00</b> <sup>13</sup> 037 198 011 G	<b>H80287-00</b> 037 103 383 N 83,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X57668-01</b> 037 129 717 C 8x <b>X51712-01</b> <sup>10</sup> 037 129 717 D 	<b>X51638-01</b> 037 253 039 D  <b>X07867-01</b> <sup>10</sup> 533 253 115 D 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P77317-01</b> K → 028 103 171 B PTFE <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
2,0 ADY AEP AGG AKR	79-85 kW (107-116 PS)	CORRADO GOLF PASSAT SHARAN VENTO	02/90-03/10	<b>D32725-00</b> <sup>12</sup> 037 198 012 L <b>B32233-00</b> <sup>13</sup> 037 198 011 G	<b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS 	<b>T50469-00</b> 050 103 384 (10x) 	<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X55170-01</b> 026 129 717 F 8x	<b>X03747-01</b> 026 129 589 A  <b>X51638-01</b> 037 253 039 D  <b>X07867-01</b> <sup>10</sup> 533 253 115 D 	4x <b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01</b> K ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P77317-01</b> K → 028 103 171 B PTFE <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
2,0 AEG	85 kW (115 PS)	NEW BEETLE	01/98-09/10	<b>D36646-00</b> <sup>12</sup> <b>B32937-00</b> <sup>13 35</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	8x <b>X75011-01</b> 06A 129 717 D  <b>X52681-01</b> <sup>10</sup> 06A 129 717 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01</b> K → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM

VOLKSWAGEN												
2,0 AEG PR-ML8 BBX BEJ BER BHP BHY BXX CBPA CGZ CGZA <b>[NEW]</b>	85-88 kW (115-120 PS)	GOLF JETTA NEW BEETLE	01/98→	D36712-00 <sup>12</sup> B32937-00 <sup>13 35</sup>	H80098-00 06A 103 383 AN 83,5 Ø MLS 	T50474-00 06A 103 384 C (10x) 	X53809-01 06A 103 483 C NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X57668-01 037 129 717 C 8x  X75011-01 06A 129 717 D 4x  X52681-01 <sup>10</sup> 06A 129 717  X88392-01 <sup>10</sup> 06A 129 717 F 	X52965-01 06A 253 039 L 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 ALT	96 kW (130 PS)	PASSAT	11/01-05/05	D36711-00 <sup>12</sup> B36711-00 <sup>13 35</sup>	H50827-00 06B 103 383 R 83,5 Ø MLS 	T50827-00 06B 103 385 (10x) 	X83031-01 06B 103 483 H NBR 	N90298-00 036 109 675 (20x) P76662-00 036 109 675	X88305-01 058 129 717 C 20x 	X81686-01 06B 253 039 E 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77318-01 K → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM 2x
2,0 APK AQY AZH	85 kW (115 PS)	BORA GOLF NEW BEETLE	01/98-09/10	D36646-00 <sup>12</sup> B32937-00 <sup>13 35</sup>	H80098-00 06A 103 383 AN 83,5 Ø MLS 	T50474-00 06A 103 384 C (10x) 	X53263-01 051 103 483 A ACM 2 Dichtlippen 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X52681-01 <sup>10</sup> 06A 129 717 8x 	X52965-01 06A 253 039 L 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 ATM AXA	85 kW (115 PS)	MULTIVAN SHARAN SHARAN LPG TRANSPORTER	09/95→	D36712-00 <sup>12</sup> B32937-00 <sup>13 35</sup>	H80098-00 06A 103 383 AN 83,5 Ø MLS 	T50474-00 06A 103 384 C (10x) 	X53809-01 06A 103 483 C NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X57668-01 037 129 717 C 8x  X88392-01 <sup>10</sup> 06A 129 717 F 	X52965-01 06A 253 039 L 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 ATU AWF AWG	85 kW (115 PS)	GOLF	06/98-06/02	D37032-00 <sup>12</sup> B37023-00 <sup>13 35</sup>	H80287-00 037 103 383 N 83,5 Ø 1,65 mm MLS 	T50469-00 050 103 384 (10x) 	X53263-01 051 103 483 A ACM 2 Dichtlippen 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X57668-01 037 129 717 C 8x  X51712-01 <sup>10</sup> 037 129 717 D 	X51638-01 037 253 039 D  X07867-01 <sup>10</sup> 533 253 115 D 	X54624-01 044 103 609 D ACM 	P77181-01 K ← 038 103 085 A 32x47x10 A SL RD PTFE ACM P77317-01 K → 028 103 171 B PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM

VOLKSWAGEN												
2,0 AVH AZG BBW BEV	85 kW (115 PS)	BORA GOLF NEW BEETLE	01/98-10/10	<b>D36712-00</b> <sup>12</sup> <b>B32937-00</b> <sup>13 35</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X53809-01</b> 06A 103 483 C NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X57668-01</b> 037 129 717 C 8x  <b>X52681-01</b> <sup>10</sup> 06A 129 717  <b>X88392-01</b> <sup>10</sup> 06A 129 717 F 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 K</b> ← 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 AXW	110 kW (150 PS)	GOLF FSI TOURAN FSI	10/03-11/08	<b>D36713-00</b> <sup>12</sup> <b>B36711-00</b> <sup>13 38</sup>	<b>H80451-00</b> 06D 103 383 L 84 Ø MLS 	<b>T80450-00</b> 06D 103 385 (10x) 	<b>X83032-01</b> 06D 103 483 D 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 	<b>X88306-01</b> 06D 129 717 D 16x 	<b>X81686-01</b> 06B 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 AXX BPY BWA BYD CDLA CDLC CDLF CDLG CDLJ CDLK CRZA	147-206 kW (200-280 PS)	EOS TFSI GOLF GTI GOLF R GOLF TFSI JETTA TFSI PASSAT TFSI POLO R SCIROCCO SCIROCCO R	10/04→	<b>D37050-00</b> <sup>12</sup> <b>B36707-00</b> <sup>13 35</sup>	<b>H80449-00</b> 06F 103 383 G 83,5 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 	<b>X83119-01</b> 06F 103 483 D NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 	<b>X89273-01</b> 06F 129 717 D 16x 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 AZJ BDC BEH BGD	85 kW (115-116 PS)	BORA GOLF GOLF Bi-Fuel NEW BEETLE	01/98-10/10	<b>B32937-00</b> <sup>13 35</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X53809-01</b> 06A 103 483 C NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X57666-01</b> 4x 06A 133 398 F 8x  <b>X88303-01</b> <sup>10</sup> 4x 06A 133 227 B 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 AZM BFF BNL	85 kW (115-116 PS)	PASSAT	11/00→	<b>D37017-00</b> <sup>12</sup> <b>B32937-00</b> <sup>13 35</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 	<b>X87424-01</b> 4x 06B 129 717 A 8x 	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

VOLKSWAGEN												
2,0 AZV BKD BKP BMA BVE BWV	88-103 kW (120-140 PS)	GOLF TDI JETTA TDI PASSAT TDI TOURAN TDI	02/03-12/13	 D36710-00 <sup>12</sup> B36708-00 <sup>13 35</sup>	H08124-00 03G 103 383 1,55 mm 1 MLS H18124-10 03G 103 383 A 1,63 mm 2 MLS H28124-20 03G 103 383 B 82 Ø 1,7 mm 3 MLS 	T08124-00 03G 103 384 (10x) 	X83030-01 03G 103 483 NBR 	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X87466-01 03G 129 717 B 16x  X89274-01 03G 129 717 C 	X81685-01 03G 253 039 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 BDJ BDK BST	51-55 kW (70-75 PS)	CADDY SDI GOLF SDI	01/04-08/10	 D32937-00 <sup>12</sup> B36708-00 <sup>13 35</sup>	H08007-00 038 103 383 CH 1,41 mm 1 MLS H18007-10 038 103 383 CJ 1,51 mm 2 MLS H28007-20 038 103 383 CK 82 Ø 1,61 mm 3 MLS 	T03518-00 038 103 384 (10x) 	X53715-01 038 103 483 D ACM 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X55431-01 028 129 717 D 8x 	X51638-01 037 253 039 D 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 BEF	43 kW (58 PS)			B36707-00 <sup>13 35</sup>	H80753-00 06G 103 383 A MLS 	T50474-00 06A 103 384 C (10x) 	X53263-01 051 103 483 A ACM 2 Dichtlippen 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X75011-01 4x 06A 129 717 D 8x 	X51947-01 037 253 039 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 BGW BHW	100 kW (136 PS)	PASSAT TDI	12/03-05/05	 D32937-00 <sup>12</sup> B32937-00 <sup>13 35</sup>	H08008-00 038 103 383 CP 1,45 mm 1 MLS H18008-10 038 103 383 CQ 1,53 mm 2 MLS H28008-20 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	T03518-00 038 103 384 (10x) 	X53715-01 038 103 483 D ACM 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X55431-01 8x 028 129 717 D 	X51638-01 037 253 039 D 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM

VOLKSWAGEN													
2,0 BZJ	85 kW (115 PS)	TOURAN FSI	10/04-05/10	 D36712-00 <sup>12</sup> B32937-00 <sup>13 35</sup>	 H80098-00 06A 103 383 AN 83,5 Ø MLS	 T50474-00 06A 103 384 C (10x)	 X53809-01 06A 103 483 C NBR	 N91190-00 027 109 675 (8x) P76532-00 027 109 675	 X75011-01 06A 129 717 D 4x 8x		 X52965-01 06A 253 039 L	 70-31414-10	 P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 BLR BLX BLY BVX BVY BVZ	110 kW (150 PS)	EOS FSI GOLF FSI JETTA FSI PASSAT FSI TOURAN FSI	10/03-11/10	 D37018-00 <sup>12</sup> B36711-00 <sup>13 35</sup>	 H80451-00 06D 103 383 L 84 Ø MLS	 T80450-00 06D 103 385 (10x)	 X83112-01 06D 103 483 E NBR	 N92990-00 036 109 675 (16x) P76662-00 036 109 675	 X88306-01 06D 129 717 D 16x		 X81686-01 06B 253 039 E	 70-31414-10	 P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77318-01 K → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 BMM BMP	103 kW (140 PS)	CADDY TDI EOS TDI GOLF TDI JETTA TDI PASSAT TDI TOURAN TDI	08/04-05/11	 D37051-00 <sup>12</sup>  B36708-00 <sup>13 35</sup>	 H08008-00 038 103 383 CP 1,45 mm 1 MLS H18008-10 038 103 383 CQ 1,53 mm 2 MLS H28008-20 038 103 383 CR 82 Ø 1,61 mm 3 MLS	 T03518-00 038 103 384 (10x)	 X53715-01 038 103 483 D ACM X83120-01 03G 103 483 D NBR	 N91190-00 027 109 675 (8x) P76532-00 027 109 675	 X55431-01 028 129 717 D 8x		 X81833-01 03G 253 039 A	 70-31414-10	 P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 BMN BMR BUZ	120-125 kW (163-170 PS)	GOLF TDI JETTA TDI PASSAT TDI TOURAN TDI	08/05-11/10	 D37052-00 <sup>12</sup>  B36708-00 <sup>13 35</sup>	 H08124-00 03G 103 383 1,55 mm 1 MLS H18124-10 03G 103 383 A 1,63 mm 2 MLS H28124-20 03G 103 383 B 82 Ø 1,7 mm 3 MLS	 T08124-00 03G 103 384 (10x)	 X83121-01 03G 103 483 C NBR	 N92990-00 036 109 675 (16x) P76662-00 036 109 675	 X87466-01 03G 129 717 B 16x X89274-01 03G 129 717 C		 X81981-01 03G 253 039 C	 70-31414-10	 P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM



VOLKSWAGEN														
Ltr. 2,0 BRT BVH	100-103 kW (136-140 PS)	SHARAN TDI	11/05-03/10	 <b>D37058-00</b> <sup>12</sup>  <b>B36708-00</b> <sup>13 35</sup>	<b>H08008-00</b> 038 103 383 CP 1,45 mm 1 MLS <b>H18008-10</b> 038 103 383 CQ 1,53 mm 2 MLS <b>H28008-20</b> 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	<b>T03518-00</b> 038 103 384 (10x) 	<b>X83127-01</b> 03G 103 483 F NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x 		<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K</b> → 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	
2,0 BSX CBSA CFEA CKJA [NEW]	37-88 kW (50-120 PS)	CADDY JETTA TOURAN	02/06→	<b>D37092-00</b> <sup>12</sup> <b>B32937-00</b> <sup>13 35</sup>	<b>H80753-00</b> 06G 103 383 A MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X53809-01</b> 06A 103 483 C NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X75011-01</b> 4x 06A 129 717 D 8x 		<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	
2,0 BTL	80-85 kW (109-116 PS)				<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	<b>X59498-01</b> 051 103 483 D 2 Dichtlippen 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	8x 		<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	
2,0 CAAA CAAB CAAC CAAD CAAE CCHA CCHB	62-103 kW (84-140 PS)	MULTIVAN TDI TRANSPORTER	09/09→	 <b>D38308-00</b> <sup>12</sup>  <b>B38299-00</b> <sup>13 35</sup>	<b>H40583-00</b> 03L 103 383 AM 82 Ø 1,55 mm 1 MLS <b>H40583-10</b> 03L 103 383 AN 82 Ø 1,63 mm 2 MLS <b>H40583-20</b> 03L 103 383 AP 82 Ø 1,71 mm 3 MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x 		<b>X59474-01</b> 03L 129 717 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 ARD FPM	
2,0 CAWA CAWB CBLA CGMA [NEW]	125-147 kW (170-200 PS)	EOS TFSI GOLF GTI GOLF TFSI JETTA TFSI PASSAT TFSI PASSAT TSI SCIROCCO TIGUAN TFSI	10/04→	<b>D40567-00</b> <sup>12</sup> <b>B38289-00</b> <sup>13 35</sup>	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x 		<b>X89273-01</b> 06F 129 717 D 	<b>70-31414-10</b> 	<b>X81829-01</b> 06F 253 039 F 	<b>P77451-01 K</b> ← 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K</b> → 06H 103 171 F 85x132/152x15,7 PTFE

VOLKSWAGEN													
2,0 CBA CBAB CBAC CBBA CBBB CBDA CBDB CBDC CBEA CJAA	81-125 kW (110-170 PS)	BEETLE TDI EOS TDI GOLF TDI JETTA TDI PASSAT TDI SCIROCCO TIGUAN TDI	01/05→	 <b>D38107-00</b> 12  <b>B38109-00</b> 13 35	<b>H01461-00</b> 03L 103 383 82 Ø 1,55 mm 1 MLS <b>H11461-10</b> 03L 103 383 A 82 Ø 1,63 mm 2 MLS <b>H21461-20</b> 03L 103 383 B 82 Ø 1,71 mm 3 MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>X83360-01</b> 03L 103 483 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89884-01</b> 03L 129 717 16x <b>X90063-01</b> 03L 129 717 B 	<b>X81685-01</b> 03G 253 039 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	
2,0 CBFA CCTA CCTB CCZA CCZB CCZC CCZD CFPA	118-155 kW (160-211 PS)	AMAROK TSI BEETLE TSI CC TSI EOS TFSI EOS TSI GOLF GOLF GTI GOLF TFSI GOLF TSI JETTA TFSI JETTA TSI PASSAT FSI PASSAT TFSI PASSAT TSI SCIROCCO SHARAN TSI TIGUAN TFSI TIGUAN TSI TRANSPORTER	10/04→	<b>D40567-00</b> 12 <b>B38289-00</b> 13 35	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x)  <b>T80727-00</b> 06D 103 385 D (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89273-01</b> 06F 129 717 D 16x	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K</b> ← 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K</b> → 06H 103 171 F 85x132/152x15,7 PTFE	
2,0 CBHA CBKA	47-74 kW (64-101 PS)			<b>D37051-00</b> 12  <b>B36708-00</b> 13 35	<b>H08008-00</b> 038 103 383 CP 1,45 mm 1 MLS <b>H18008-10</b> 038 103 383 CQ 1,53 mm 2 MLS <b>H28008-20</b> 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	<b>T03518-00</b> 038 103 384 (10x) 	<b>X83120-01</b> 03G 103 483 D NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X81833-01</b> 03G 253 039 A 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K</b> → 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	

VOLKSWAGEN												
2,0 CBJB	55 kW (75 PS)		1	<p><b>D32937-00</b> <sup>12</sup></p> <p><b>B36708-00</b> <sup>13 35</sup></p>	<p><b>H08008-00</b> 038 103 383 CP 1,45 mm 1 </p> <p><b>H18008-10</b> 038 103 383 CQ 1,53 mm 2 </p> <p><b>H28008-20</b> 038 103 383 CR 82 Ø 1,61 mm 3 </p>	<p><b>T03518-00</b> 038 103 384 (10x)</p>	<p><b>X53715-01</b> 038 103 483 D ACM</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X55431-01</b> 028 129 717 D</p> <p>8x </p>	<p><b>X51638-01</b> 037 253 039 D</p>	<p><b>70-31414-10</b></p>	<p><b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K</b> → </p> <p><b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM</p>
2,0 CDBA CDCA CNFA CNFB	90-120 kW (122-163 PS)	AMAROK BiTDI AMAROK TDI	09/10→	<p><b>D38311-00</b> <sup>12</sup></p> <p><b>B38299-00</b> <sup>13 35</sup></p>	<p><b>H40583-00</b> 03L 103 383 AM 82 Ø 1,55 mm 1 </p> <p><b>H40583-10</b> 03L 103 383 AN 82 Ø 1,63 mm 2 </p> <p><b>H40583-20</b> 03L 103 383 AP 82 Ø 1,71 mm 3 </p>	<p><b>T50034-00</b> WHT 002 131 (10x)</p>	<p><b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)</p> <p><b>X59500-01</b> 03L 103 483 C</p>	<p><b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675</p>	<p><b>X59470-01</b> 03L 129 717 D</p> <p>16x </p>	<p><b>X82518-01</b> 03L 253 039 G</p>	<p><b>70-31414-10</b></p>	<p><b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → </p> <p><b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM</p>
2,0 CEN	88 kW (120 PS)				<p><b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS</p>	<p><b>T50474-00</b> 06A 103 384 C (10x)</p>	<p><b>X53809-01</b> 06A 103 483 C NBR</p>	<p><b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675</p>	<p><b>X75011-01</b> 06A 129 717 D</p> <p>8x </p>	<p><b>X52965-01</b> 06A 253 039 L</p>	<p><b>70-31414-10</b></p>	<p><b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → </p> <p><b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM</p>
2,0 CENA <b>[NEW]</b>	88 kW (120 PS)				<p><b>H80796-00</b> 036 103 383 AF 68 Ø MLS</p>	<p><b>T80786-00</b> WHT 001 865 (10x)</p>	<p><b>70-31414-10</b></p>	<p><b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675</p> <p>8x</p>		<p><b>X51580-01</b> 030 253 039 H</p>	<p><b>70-31414-10</b></p>	<p><b>P77313-01 K</b> ← 036 103 085 H 32x42x6/7 A SL RD NBR</p>

VOLKSWAGEN													
2,0 CFCA	132 kW (180 PS)	MULTIVAN TRANSPORTER	→7H-F-999 999, 7J-F-999 999	09/09→	 <b>D38307-00</b> <sup>12</sup>  <b>B38299-00</b> <sup>13 35</sup>	<b>H40583-00</b> 03L 103 383 AM 82 Ø 1,55 mm 1 □ MLS <b>H40583-10</b> 03L 103 383 AN 82 Ø 1,63 mm 2 □ MLS <b>H40583-20</b> 03L 103 383 AP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X59474-01</b> 03L 129 717 E 16x 	<b>X82521-01</b> 03C 253 039 F 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
2,0 CFCA	132 kW (180 PS)	MULTIVAN TRANSPORTER	7H-F-000 001, 7H-G-000 001→	09/09→	 <b>D38307-00</b> <sup>12</sup>  <b>B38299-00</b> <sup>13 35</sup>	<b>H84868-00</b> 03L 103 383 DC 82 Ø 1,55 mm 1 □ MLS <b>H84868-10</b> 03L 103 383 DD 82 Ø 1,63 mm 2 □ MLS <b>H84868-20</b> 03L 103 383 DE 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X59474-01</b> 03L 129 717 E 16x 	<b>X82521-01</b> 03C 253 039 F 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
2,0 CFFA CFFB CFFD CFFE CFHB CFHC CFHE CFHF CLCA CLCB CLJA	62-103 kW (85-140 PS)	BEETLE TDI CADDY TDI CC TDI EOS TDI GOLF TDI JETTA TDI PASSAT TDI SCIROCCO SHARAN TDI TIGUAN TDI TOURAN TDI		01/05→	 <b>D38308-00</b> <sup>12</sup>  <b>B38299-00</b> <sup>13 35</sup>	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X59474-01</b> 03L 129 717 E 16x 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM

VOLKSWAGEN												
2,0 CFGB CFGC CLLA	125-130 kW (170-177 PS)	CC TDI GOLF TDI PASSAT TDI SCIROCCO SHARAN TDI TIGUAN TDI	09/07→	 D38731-00 <sup>12</sup> B38299-01 <sup>13 38</sup>	H40584-00 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS H40584-10 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS H40584-20 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS	T50034-00 WHT 002 131 (10x)	V59500-00 03L 103 483 C +03L 103 070 (4x)	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X59474-01 03L 129 717 E 16x	X59891-01 04L 253 039 D	70-31414-10	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77689-01 K → 03L 103 171 A PTFE P77774-01 N 03L 103 085 32x47x10 A RD FPM
2,0 CFJA CFJB <b>[NEW]</b>	125-130 kW (170-177 PS)	CADDY TDI TOURAN TDI	05/10→	 D38731-00 <sup>12</sup> B38299-00 <sup>13 35</sup>	H40584-00 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS H40584-10 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS H40584-20 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS	T50034-00 WHT 002 131 (10x)	V59500-00 03L 103 483 C +03L 103 070 (4x)	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X59474-01 03L 129 717 E 16x	X59891-01 04L 253 039 D	70-31414-10	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77689-01 K → 03L 103 171 A PTFE P77774-01 N 03L 103 085 32x47x10 A RD FPM
2,0 CGM	147 kW (200 PS)	TIGUAN TSI	03/10→	D40567-00 <sup>12</sup>	H40567-00 06H 103 383 AC 83 Ø MLS	T80727-00 06D 103 385 D (10x)	70-31414-10	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X89273-01 06F 129 717 D 16x	X81829-01 06F 253 039 F	70-31414-10	P77451-01 K ← 06H 103 383 G 45x60x8 AB SL RD FPM
2,0 CH	55 kW (75 PS)	LT	04/75-09/83	D31645-00 <sup>12</sup> 047 198 012 B37007-00 <sup>13</sup> 060 198 011 B	H50164-00 046 103 383 J 88,5 Ø 1,55 mm	T02673-00 068 103 384 A (10x) Mot.0008796→	V31645-00 060 198 025 A	N92632-00 046 109 675 A (8x) P76661-00 046 109 675 A	X56304-01 060 129 717 A 8x	X51297-01 048 129 589 X52208-01 048 129 589 A 4x X51169-01 431 253 115 A	E37007-00 060 198 041 A	P77438-01 K ← 048 115 147 35x54x10 A SL RD FPM P77439-01 K → 059 103 051 D 96x117x10,5/12 A SL LD NBR P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM
2,0 CHHA CHHB CJXB CJXC CNTA CULA CULC CXCA CXDA <b>[NEW]</b>	132-221 kW (180-300 PS)	BEETLE TSI EOS TFSI GOLF GTI GOLF R GOLF TSI PASSAT TSI SCIROCCO	04/13→	D40708-01 <sup>12</sup> B82501-00 <sup>13</sup>	H40708-00 06K 103 383 K 83 Ø MLS	T40708-00 WHT 005 305 (10x)	70-31414-10	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X59914-01 06K 129 717 A 16x	X59924-01 06L 253 039	X90114-01 06K 103 649 70-31414-10	P77842-01 K ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM P77846-01 K → 06K 103 171 A PTFE

VOLKSWAGEN													
2,0 CJ GE	51 kW (69-70 PS)	TRANSPORTER	08/75-07/79	<b>A31438-00</b> <sup>14</sup> 029 198 009 A 	<b>H51289-00</b> 051101341A 93 Ø 	4x	<b>X53150-01</b> 021 101 481 Kork 	2x	<b>X55893-01</b> 021 129 707 E 	4x	<b>X51285-01</b> 039 256 251  <b>X81354-01</b> <sup>13</sup> 025 251 261 	4x 2x	<b>P76152-01 K</b> ← 021 105 247 A 42x62x10 A SL RD FPM
2,0 CJK CJKB	110-150 kW (150-204 PS)	MULTIVAN TSI TRANSPORTER	05/11→	<b>D40567-00</b> <sup>12</sup> <b>B38289-01</b> <sup>13 35</sup>	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 	<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x	<b>X89273-01</b> 06F 129 717 D 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77842-01 K</b> ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77754-01 K</b> → <sup>13</sup> 06H 103 171 F 85x132/152x15,7 PTFE
2,0 CKFC CRBC CRLB CRMB CRUA CUNA CUUA CUUB CUWA CUXA CVCA <b>[NEW]</b>	81-135 kW (110-184 PS)	BEETLE TDI CADDY TDI CC TDI GOLF GTD GOLF TDI JETTA TDI PASSAT TDI SCIROCCO TIGUAN TDI	11/12→	<b>D38750-00</b> <sup>12</sup> 	<b>H40701-00</b> 04L 103 383 BJ 82 Ø 1,55 mm 1 □ MLS <b>H40701-10</b> 04L 103 383 BK 82 Ø 1,63 mm 2 □ MLS <b>H40701-20</b> 04L 103 383 BL 82 Ø 1,71 mm 3 □ MLS 	<b>T40709-00</b> WHT 005 673 (10x) 	<b>V59933-00</b> 03L 103 483 S +04L 103 070 (4x)  <b>V90072-00</b>  <b>X59933-01</b> 03L 103 483 S  <b>X90116-01</b> 04L 103 483 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x	<b>X59929-01</b> 04L 129 717 B 	<b>X59927-01</b> 04L 253 039 G 	<b>70-31414-10</b> 	<b>P77831-01 K</b> → <sup>13</sup> 04L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 ARD FPM
2,0 CKRA <b>[NEW]</b>	103 kW (140 PS)			<b>D38307-00</b> <sup>12</sup>  <b>B38299-00</b> <sup>13 35</sup>	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x	<b>X59474-01</b> 03L 129 717 E 	<b>X82521-01</b> 03C 253 039 F 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → <sup>13</sup> 03L 103 171 A PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 ARD FPM

VOLKSWAGEN

Ltr. 





1 




2,0 CKTB 80-120 kW CRAFTER TDI 05/11→

(109-163 PS)


CKTC  
CKUB  
CKUC  
CSNA  
**[NEW]**





**D38311-00** <sup>12</sup>  
  
**B38299-00** <sup>13 35</sup>


**H40583-00**  
03L 103 383 AM  
82 Ø  
1,55 mm 1   
MLS  
→10/13  
**H40583-10**  
03L 103 383 AN  
82 Ø  
1,63 mm 2   
MLS  
→10/13  
**H40583-20**  
03L 103 383 AP  
82 Ø  
1,71 mm 3   
MLS  
→10/13





**H84868-00**  
03L 103 383 DC  
82 Ø  
1,55 mm 1   
MLS  
11/13→

**H84868-10**  
03L 103 383 DD  
82 Ø  
1,63 mm 2   
MLS  
11/13→


**H84868-20**  
03L 103 383 DE  
82 Ø  
1,71 mm 3   
MLS  
11/13→




**T50034-00**  
WHT 002 131 (10x)  



**V59500-00**  
03L 103 483 C  
+03L 103 070 (4x)  
  
**X59500-01**  
03L 103 483 C  


**N92990-00**  
036 109 675 (16x)  
**P76662-00**  
036 109 675

**X59470-01**  
03L 129 717 D  
16x 

**X82518-01**  
03L 253 039 G  


**70-31414-10**  


**P76096-11 K** ←  
038 103 085 E  
35x48x10  
A SL RD PTFE ACM  
**P77689-01 K** →   
03L 103 171 A  
PTFE  
**P77774-01 N**  
03L 103 085  
32x47x10  
A RD FPM

VOLKSWAGEN												
Ltr.												
2,0 CNEA CSHA	132 kW (180 PS) AMAROK TDI	11/11→	<b>D38311-00</b> <sup>12</sup>  <b>B38299-00</b> <sup>13 35</sup>	<b>H40583-00</b> 03L 103 383 AM 82 Ø 1,55 mm 1 MLS →07/14 <b>H40583-10</b> 03L 103 383 AN 82 Ø 1,63 mm 2 MLS →07/14 <b>H40583-20</b> 03L 103 383 AP 82 Ø 1,71 mm 3 MLS →07/14  <b>H84868-00</b> 03L 103 383 DC 82 Ø 1,55 mm 1 MLS 08/14→ <b>H84868-10</b> 03L 103 383 DD 82 Ø 1,63 mm 2 MLS 08/14→ <b>H84868-20</b> 03L 103 383 DE 82 Ø 1,71 mm 3 MLS 08/14→ 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X59470-01</b> 03L 129 717 D 16x 		<b>X82518-01</b> 03L 253 039 G 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
2,0 CPLA CPPA	155 kW (210-211 PS) BEETLE TSI JETTA TSI	12/12→	<b>D90195-00</b> <sup>12</sup> <b>B82496-00</b> <sup>13</sup>	<b>H40708-00</b> 06K 103 383 K 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x) 	<b>70-31414-10</b> 	<b>N96006-00</b> 06L 109 675 (8x) +036 109 675 A (8x) <b>P76662-00 ES</b> 036 109 675 <b>P93254-00 AS</b> 06L 109 675	<b>X59914-01</b> 06K 129 717 A 8x  8x	<b>X59924-01</b> 06L 253 039 	<b>70-31414-10</b> 	<b>P77842-01 K</b> ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM <b>P77846-01 K</b> → 06K 103 171 A PTFE →03/14	



VOLKSWAGEN												
2,0 CRVA CRVC <b>[NEW]</b>	81-105 kW (110-143 PS)	GOLF TDI	08/12→ 	 <b>D38750-01</b> <sup>12</sup> 	<b>H40701-00</b> 04L 103 383 BJ 82 Ø 1,55 mm 1 MLS <b>H40701-10</b> 04L 103 383 BK 82 Ø 1,63 mm 2 MLS <b>H40701-20</b> 04L 103 383 BL 82 Ø 1,71 mm 3 MLS 	<b>T40709-00</b> WHT 005 673 (10x) 	<b>V59933-00</b> 03L 103 483 S +04L 103 070 (4x)  <b>V90072-00</b>  <b>X59933-01</b> 03L 103 483 S  <b>X90116-01</b> 04L 103 483 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59929-01</b> 04L 129 717 B 	<b>X59891-01</b> 04L 253 039 D 	<b>70-31414-10</b> 	<b>P77831-01 K</b> → 04L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 ARD FPM
2,0 CSLB <b>[NEW]</b>	84 kW (114 PS)	CRAFTER TDI	11/13→	<b>D38311-00</b> <sup>12</sup>  <b>B38299-00</b> <sup>13</sup> <sup>35</sup> 	<b>H84868-00</b> 03L 103 383 DC 82 Ø 1,55 mm 1 MLS <b>H84868-10</b> 03L 103 383 DD 82 Ø 1,63 mm 2 MLS <b>H84868-20</b> 03L 103 383 DE 82 Ø 1,71 mm 3 MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59470-01</b> 03L 129 717 D 	<b>X82518-01</b> 03L 253 039 G 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 ASL RD PTFE ACM <b>P77689-01 K</b> → 03L 103 171 A PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 ARD FPM
2,0 CU CV	51 kW (69-70 PS)	TRANSPORTER	05/79-04/86	<b>S37033-00</b> <sup>13</sup> 071 198 009 A	<b>H80723-00</b> 4x 039 101 343 B 94 Ø 0,7 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	<b>X53150-01</b> 2x 021 101 481 Kork 	<b>X55893-01</b> 4x 021 129 707 E 	<b>X81357-01 L</b> 2x 029 256 251 A  <b>X81358-01 R</b> 2x 029 256 252 A  <b>X81354-01</b> 2x 025 251 261 	<b>P76152-01 K</b> ← 021 105 247 A 42x62x10 ASL RD FPM <b>P76325-01 K</b> → 029 105 245 B 75x95x10/9,5 ALD FPM		
2,0 HP JS	85 kW (115-116 PS)	PASSAT SANTANA	08/83-03/88	<b>S30567-00</b> <sup>12</sup> <sup>13</sup> <b>D30567-00</b> <sup>12</sup> 035 198 012 N <b>B30567-00</b> <sup>13</sup> 034 198 011 C	<b>H02641-00</b> 034 103 383 AA 82,7 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	<b>V30567-00</b> 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x	<b>X02658-01</b> 035 129 717 M 	<b>X03747-01</b> 026 129 589 A  <b>X51169-01</b> 431 253 115 A 	<b>X02643-01</b> 5x 054 103 609 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 ASL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 ASL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 ASL WD FPM

VOLKSWAGEN													
2,0 UQG	82-90 kW (112-122 PS)				<b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS	<b>T04132-00</b> 049 103 385 (10x) 	<b>X59501-01</b> 026 103 483 2 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55899-01</b> 068 129 717 E 8x 	<b>X03747-01</b> 026 129 589 A 	4x <b>70-31414-10</b> 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P77317-01 K</b> → 028 103 171 B PTFE	
2,0 2E	85 kW (115-116 PS)	GOLF PASSAT VENTO	→1H P 490 000, 1H PB 140 000, 1H PW 490 000 →31 P 160 000 →1H P 490 000, 1H PB 140 000, 1H PW 490 000	02/90-04/99	<b>S31641-00</b> ⑫ ⑬ 037198011E+ <b>D31641-00</b> ⑫ 037 198 012 B <b>B30584-00</b> ⑬ 037 198 011 C	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X53064-01</b> 037 103 483 C NBR 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X55430-01</b> 048 129 717 A 8x 	<b>X03747-01</b> 026 129 589 A <b>X07867-01</b> ⚠ 533 253 115 D 	4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
2,0 2E	85 kW (115-116 PS)	GOLF PASSAT VENTO	1H P 490 001, 1H PB 140 001, 1H PW 490 001→ 31 P 160 001→ 1H P 490 001, 1H PB 140 001, 1H PW 490 001→	02/90-04/99	<b>D36352-00</b> ⑫ 037198012G <b>B30584-00</b> ⑬ 037 198 011 C	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm 	<b>T04125-00</b> 049 103 384 B (10x) 	<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X55430-01</b> 048 129 717 A 8x 	<b>X03747-01</b> 026 129 589 A <b>X07867-01</b> ⚠ 533 253 115 D 	4x <b>E30584-00</b> 044 103 609 D +N 905 927 02 (20x) 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
2,0 9A	100 kW (136 PS)	CORRADO PASSAT		08/88-12/95	<b>S31642-00</b> ⑫ ⑬ Mot.→9A 131 460 <b>D31642-00</b> ⑫ 051 198 012 A Mot.→9A 131 460 <b>D37035-00</b> ⑫ Mot.9A 131 461→ <b>B30584-00</b> ⑬ 037 198 011 C	<b>H50151-00</b> 048 103 383 B 83,5 Ø 1,75 mm Mot.→9A 131 460  <b>H50469-00</b> 048 103 383 D 83,5 Ø 1,65 mm MLS Mot.9A 131 461→ 	<b>T04843-00</b> 027 103 385 C (10x) Mot.→9A 131 460  <b>T50151-00</b> 053 103 385 (10x) Mot.9A 131 461→ 	<b>V31196-00</b> 027 198 025 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	2x <b>X07866-01</b> 037 129 717 F 16x <b>X07865-01</b> ⑩ 027 129 717 D 	<b>X07855-01</b> 027 129 589 A <b>X07867-01</b> ⚠ 533 253 115 D 	4x <b>X04116-01</b> 026 103 609 D 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
2,1 DJ MV SR SS	64-82 kW (87-112 PS)	TRANSPORTER		08/84-07/92	<b>S31503-00</b> ⑬ 025 198 009 B <b>D31503-00</b> 025 198 012 A <b>B31503-00</b> ⑬	<b>H50048-00</b> 4x 025 101 343 B 2x 95 Ø 	<b>X00991-01</b> 2x 113 101 481 F Kork 	<b>X55877-01</b> 2x 025 129 717 C 	<b>X51158-01</b> 4x N 901 316 02 	<b>P76253-01 K</b> ← 025 105 247 A 48x68x10 A SL RD FPM <b>P76325-01 K</b> → 029 105 245 B 75x95x10/9,5 A LD FPM			

VOLKSWAGEN												
2,1 WE	85 kW (115 PS)	PASSAT SANTANA	01/81-12/83	<b>S31200-00</b> <sup>12</sup> <sup>13</sup> <b>D31200-00</b> <sup>12</sup> 035 198 012 L <b>B30567-00</b> <sup>13</sup> 034 198 011 C	<b>H07872-00</b> 035 103 383 K 81,5 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	<b>V30567-00</b> ✕ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x 	<b>X02658-01</b> 035 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM 2x
2,2 HY	100 kW (136 PS)	PASSAT	01/85-03/88	<b>S30567-00</b> <sup>12</sup> <sup>13</sup> <b>D30567-00</b> <sup>12</sup> 035 198 012 N <b>B30567-00</b> <sup>13</sup> 034 198 011 C	<b>H02641-00</b> 034 103 383 AA 82,7 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	<b>V30567-00</b> ✕ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x 	<b>X02658-01</b> 035 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x  <b>X51169-01</b> <sup>7</sup> 431 253 115 A 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM
2,2 JT KV KX	85-100 kW (115-136 PS)	PASSAT	01/85-03/88	<b>S30567-00</b> <sup>12</sup> <sup>13</sup> <b>D30567-00</b> <sup>12</sup> 035 198 012 N <b>B30567-00</b> <sup>13</sup> 034 198 011 C	<b>H02641-00</b> 034 103 383 AA 82,7 Ø 1,75 mm 	<b>T02641-00</b> 049 103 384 B (12x) 	<b>V30567-00</b> ✕ 034 198 025 Kork  <b>V31634-00</b> 034 198 025 D NBR 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675 10x 	<b>X02658-01</b> 035 129 717 M 	<b>X03747-01</b> 026 129 589 A 5x  <b>X51169-01</b> <sup>7</sup> 431 253 115 A 	<b>X02643-01</b> 054 103 609 	<b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
2,2 4Y	69 kW (94 PS)	TARO	06/89-07/94	<b>S37036-00</b> <sup>12</sup> <sup>13</sup> J04 111 730 44 <b>D37036-00</b> <sup>12</sup> J04 112 730 43	<b>H40028-00</b> J11 115 730 30 93 Ø 1,6 mm <b>H40028-10</b> 93 Ø 2 mm 	<b>T50670-00</b> J90 105 120 56 (10x) 	<b>X83115-01</b> J11 213 710 20 NBR 	<b>N92321-00</b> J90 913 021 10 (8x) 	<b>X81945-01</b> <sup>7</sup> J17 172 730 10 	<b>X54906-01</b>  70-31414-10 		
2,3 AGL	105 kW (143 PS)	LT	05/96-07/06	<b>D36044-00</b> <sup>12</sup> <b>B31936-00</b> <sup>13</sup> 00A 198 011	<b>H80500-00</b> 00A 103 383 92 Ø 1,75 mm 	<b>T50309-00</b> 00A 103 385 (10x) 	<b>V31937-00</b> 00A 103 483 +00A 103 484 (4x) NBR 	<b>N92567-00</b> 00A 198 675 (16x) <b>P76792-00</b> 00A 109 675 16x 	<b>X56560-01</b> 00A 133 227 	<b>X51359-01</b> 00A 253 039 	<b>X54089-01</b> 00A 103 609 A 	<b>P76235-11</b> K ← 00A 103 085 A 45x67x8 A SL RD FPM <b>P76377-01</b> K → 00A 103 085 93x114x13 A SL LD FPM
2,3 AGZ	110 kW (150 PS)	BORA V5 GOLF V5 PASSAT V5	10/96-06/06	<b>B36716-00</b> <sup>13</sup>	<b>H80095-00</b> 071103383 84 Ø MLS 	<b>T80095-00</b> 021 103 384 G (9x) +021 103 384 K (6x) +021 103 384 L (3x) 		<b>N90710-01</b> 026 109 675 (10x) <b>P76532-00</b> 027 109 675 10x 	<b>X89179-01</b> 071 133 237 A 2x  <b>X89180-01</b> 071 133 237 3x  <b>X89181-01</b> 071 133 237 D 5x 	<b>X07867-01</b> <sup>7</sup> 533 253 115 D 	70-31414-10 	<b>P76096-11</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01</b> K → 021 103 051 C 85x105x11 A SL LD PTFE ACM

VOLKSWAGEN													
2,3 AQN AZX	125 kW (170 PS)	BORA V5 GOLF V5 NEW BEETLE PASSAT V5	→1J 5D001 000, 10/00-09/10 1J 5U001 500, 1J 5W050 000 →1J 5D001 000, 1J 5U001 500, 1J 5W050 000 →9C 3 626 062 →3B 5 050 000, 3B 5E100 000	D37019-00 <sup>12</sup> B37019-00 <sup>13</sup>	H80444-00 066 103 383 G 82 Ø MLS 	T80444-00 022 103 384 C (12x) +022 103 384 D (6x) 	X83113-01 066 103 483 F NBR 	N90298-00 036 109 675 (20x) P76662-00 036 109 675	X89178-01 066 133 237 20x 	X81436-01 066 253 039 A 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	
2,3 AQN AZX	125 kW (170 PS)	BORA V5 GOLF V5 NEW BEETLE PASSAT V5	1J 5D001 001, 10/00-09/10 1J 5U001 501, 1J 5W050 001→ 1J 5D001 001, 1J 5U001 501, 1J 5W050 001→ 9C 3 626 063→ 3B 5 050 001, 3B 5E100 001→	D37019-00 <sup>12</sup>	H80444-00 066 103 383 G 82 Ø MLS 	T80444-00 022 103 384 C (12x) +022 103 384 D (6x) 	X83113-01 066 103 483 F NBR 	N90298-00 036 109 675 (20x) P76662-00 036 109 675	X89178-01 066 133 237 20x 	X81436-01 066 253 039 A 	70-31414-10 	P77820-01 K ← 022 103 151 D P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	
2,4 AAB	57 kW (78 PS)	TRANSP.	→70 R 160 000 07/90-09/98	D31637-00 <sup>12</sup> 074 198 012  B31637-00 <sup>13</sup> 074 198 011 A	H02394-00 074 103 383 C 1,53 mm 1 Mot.→AAB 110 000 H12394-10 074 103 383 D 1,57 mm 2 Mot.→AAB 110 000 H22394-20 074 103 383 E 81 Ø 1,61 mm 3 Mot.→AAB 110 000  H00997-00 074 103 383 M 1,53 mm 1 MLS Mot.AAB 110 001→ H10997-10 074 103 383 N 1,57 mm 2 MLS Mot.AAB 110 001→ H20997-20 074 103 383 P 81 Ø 1,61 mm 3 MLS Mot.AAB 110 001→ 	T07896-00 068 103 384 A (12x) 	V31637-00 	N90710-01 026 109 675 (10x) P76531-00 026 109 675	X56210-01 074 129 717 10x 	X03747-01 026 129 589 A 	5x X54131-01 074 103 609 F 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 2x 068 103 085 E 32x47x10 A SL WD FPM	

VOLKSWAGEN													
Ltr.													
2,4 AAB	57 kW (78 PS)	TRANSP.	70 R 160 001→ 07/90-09/98	<p><b>D32840-00</b> <sup>12</sup> 074 198 012 A</p> <p><b>B31637-00</b> <sup>13</sup> 074 198 011 A</p>	<p><b>H02394-00</b> 074 103 383 C 1,53 mm 1 </p> <p>Mot.→AAB 110 000</p> <p><b>H12394-10</b> 074 103 383 D 1,57 mm 2 </p> <p>Mot.→AAB 110 000</p> <p><b>H22394-20</b> 074 103 383 E 81 Ø 1,61 mm 3 </p> <p>Mot.→AAB 110 000</p> <p><b>H00997-00</b> 074 103 383 M 1,53 mm 1 </p> <p>MLS</p> <p>Mot.AAB 110 001→</p> <p><b>H10997-10</b> 074 103 383 N 1,57 mm 2 </p> <p>MLS</p> <p>Mot.AAB 110 001→</p> <p><b>H20997-20</b> 074 103 383 P 81 Ø 1,61 mm 3 </p> <p>MLS</p> <p>Mot.AAB 110 001→</p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>		<p><b>N90710-01</b> 026 109 675 (10x)</p> <p><b>P76531-00</b> 026 109 675</p>	<p><b>X56210-01</b> 074 129 717</p> <p>10x</p>		<p><b>X03747-01</b> 026 129 589 A</p>	<p>5x <b>X54131-01</b> 074 103 609 F</p>	<p><b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p><b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM</p>
2,4 ACL	70 kW (95 PS)	LT TD	06/92-06/96		<p><b>H00569-00</b> 072 103 383 CT 1,4 mm</p> <p>Mot.→ACL 014 031</p> <p><b>H10569-10</b> 072 103 383 DA 1,5 mm 2 </p> <p>Mot.→ACL 014 031</p> <p><b>H20569-20</b> 072 103 383 DB 78 Ø 1,6 mm 3 </p> <p>Mot.→ACL 014 031</p> <p><b>H05685-00</b> 075 103 383 D 1,53 mm 1 </p> <p>MLS</p> <p>Mot.ACL 014 032→</p> <p><b>H15685-10</b> 075 103 383 E 1,57 mm 2 </p> <p>MLS</p> <p>Mot.ACL 014 032→</p> <p><b>H25685-20</b> 075 103 383 F 78 Ø 1,61 mm 3 </p> <p>MLS</p> <p>Mot.ACL 014 032→</p>	<p><b>T08968-00</b> 068 103 384 A (14x)</p>	<p><b>X53843-01</b> 075 103 483 F NBR</p>	<p><b>N91210-00</b> 026 109 675 (12x)</p> <p><b>P76531-00</b> 026 109 675</p>	<p><b>X08969-01</b> 072 129 717 A</p> <p>12x</p>		<p><b>X03747-01</b> 026 129 589 A</p>	<p>6x <b>X54130-01</b> 075 103 609 C</p>	<p><b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p><b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM</p> <p><b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM</p>

VOLKSWAGEN												
Ltr.												
2,4 ACT	51 kW (69-70 PS)	LT D	08/89-06/96	<p><b>H00569-00</b> 072 103 383 CT 1,4 mm Mot.→ACT 011 319</p> <p><b>H10569-10</b> 072 103 383 DA 1,5 mm 2 </p> <p>Mot.→ACT 011 319</p> <p><b>H20569-20</b> 072 103 383 DB 78 Ø 1,6 mm 3 </p> <p>Mot.→ACT 011 319</p> <p><b>H05685-00</b> 075 103 383 D 1,53 mm 1 </p> <p>MLS Mot.ACT 011 320→</p> <p><b>H15685-10</b> 075 103 383 E 1,57 mm 2 </p> <p>MLS Mot.ACT 011 320→</p> <p><b>H25685-20</b> 075 103 383 F 78 Ø 1,61 mm 3 </p> <p>MLS Mot.ACT 011 320→</p>	<p><b>T08968-00</b> 068 103 384 A (14x)</p>	<p><b>X53843-01</b> 075 103 483 F NBR</p>	<p><b>N91210-00</b> 026 109 675 (12x)</p> <p><b>P76531-00</b> 026 109 675</p>	<p><b>X08969-01</b> 072 129 717 A</p> <p>12x </p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p>6x <b>X54130-01</b> 075 103 609 C</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM</p>	
2,4 AJA	55 kW (75 PS)	TRANSPORTER	08/97-04/03	<p><b>D36651-00</b> <sup>12</sup></p> <p><b>B32840-00</b> 074 198 011 B Mot.→AJA 028 554</p> <p><b>B36651-00</b> <sup>13</sup> <sup>35</sup> Mot.AJA 028 555→ Mot.→AJA 050 000</p> <p><b>B36656-00</b> <sup>13</sup> <sup>35</sup> Mot.AJA 050 001→</p>	<p><b>H00997-00</b> 074 103 383 M 1,53 mm 1 </p> <p>MLS <b>H10997-10</b> 074 103 383 N 1,57 mm 2 </p> <p>MLS <b>H20997-20</b> 074 103 383 P 81 Ø 1,61 mm 3 </p> <p>MLS </p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>	<p><b>N90710-01</b> 026 109 675 (10x)</p> <p><b>P76531-00</b> 026 109 675</p> <p>10x</p>	<p><b>X56210-01</b> 074 129 717</p> <p>10x </p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p>5x <b>X54131-01</b> 074 103 609 F Mot.→AJA 050 000</p> <p><b>X54722-01</b> 074 103 609 H Stahl Mot.AJA 050 001→</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AJA 028 554 <b>P77317-01</b> K →  028 103 171 B PTFE Mot.AJA 028 555→ <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM</p>	
2,4 CP	55 kW (75 PS)	LT D	→28 J 014 000 12/78-07/92	<p><b>D30282-00</b> <sup>12</sup> 076 198 015 B</p> <p><b>B31458-00</b> <sup>13</sup> 075 198 011 B</p>	<p><b>H18968-10</b> 072 103 383 DH 1,5 mm 2 </p> <p><b>H28968-20</b> 072 103 383 DJ 78,5 Ø 1,6 mm 3 </p>	<p><b>T08968-00</b> 068 103 384 A (14x)</p>	<p><b>V31458-00</b> 072 198 025 A</p>	<p><b>N91210-00</b> 026 109 675 (12x)</p> <p><b>P76531-00</b> 026 109 675</p>	<p><b>X08969-01</b> 072 129 717 A</p> <p>12x </p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p>6x <b>X54130-01</b> 075 103 609 C</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM</p>

VOLKSWAGEN												
2,4 CP	55 kW (75 PS)	LT D	28 J 014 001→ 12/78-07/92	 <b>S31458-00</b> <sup>12</sup> <sup>13</sup>  <b>D31458-00</b> <sup>12</sup> 072 198 012 A  <b>B31458-00</b> <sup>13</sup> 075 198 011 B	<b>H00569-00</b> 072 103 383 CT 1,4 mm <b>H10569-10</b> 072 103 383 DA 1,5 mm 2 <b>H20569-20</b> 072 103 383 DB 78 Ø 1,6 mm 3 	<b>T08968-00</b> 068 103 384 A (14x) 	<b>V31458-00</b> 072 198 025 A 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 026 109 675 12x	<b>X08969-01</b> 072 129 717 A 	<b>X03747-01</b> 026 129 589 A 6x 	<b>X54130-01</b> 075 103 609 C 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 DL HS 1E	62-69 kW (82-94 PS)	LT	12/82→	<b>S31646-00</b> <sup>12</sup> <sup>13</sup> <b>D31646-00</b> <sup>12</sup> 073 198 012 A <b>B31458-00</b> <sup>13</sup> 075 198 011 B	<b>H50165-00</b> 073 103 383 C 78,5 Ø 1,9 mm 	<b>T08968-00</b> 068 103 384 A (14x) 	<b>V31646-00</b> 073 198 025 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 026 109 675 12x	<b>X51298-01</b> 073 129 717 A 	<b>X03747-01</b> 026 129 589 A 6x 	<b>X54130-01</b> 075 103 609 C 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 DV DW 1G	55-75 kW (75-102 PS)	LT D LT TD	→28 J 014 000 08/78-09/93 →28 J 014 000	<b>D30282-00</b> <sup>12</sup> 076 198 015 B  <b>B31458-00</b> <sup>13</sup> 075 198 011 B	<b>H18968-10</b> 072 103 383 DH 1,5 mm 2 <b>H28968-20</b> 072 103 383 DJ 78,5 Ø 1,6 mm 3 	<b>T08968-00</b> 068 103 384 A (14x) 	<b>V31458-00</b> 072 198 025 A 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 026 109 675 12x	<b>X08969-01</b> 072 129 717 A 	<b>X03747-01</b> 026 129 589 A 6x  <b>X81946-01</b> <sup>10</sup> 075 253 115 	<b>X54130-01</b> 075 103 609 C 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 DV DW 1G	55-75 kW (75-102 PS)	LT D LT TD	28 J 014 001→ 08/78-09/93 28 J 014 001→	<b>S31458-00</b> <sup>12</sup> <sup>13</sup>  <b>D31458-00</b> <sup>12</sup> 072 198 012 A  <b>B31458-00</b> <sup>13</sup> 075 198 011 B	<b>H00569-00</b> 072 103 383 CT 1,4 mm <b>H10569-10</b> 072 103 383 DA 1,5 mm 2 <b>H20569-20</b> 072 103 383 DB 78 Ø 1,6 mm 3 	<b>T08968-00</b> 068 103 384 A (14x) 	<b>V31458-00</b> 072 198 025 A 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 026 109 675 12x	<b>X08969-01</b> 072 129 717 A 	<b>X03747-01</b> 026 129 589 A 6x  <b>X81946-01</b> <sup>10</sup> 075 253 115 	<b>X54130-01</b> 075 103 609 C 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 1S	51 kW (69-70 PS)	LT D	08/89-06/96	<b>S31458-00</b> <sup>12</sup> <sup>13</sup>  <b>D31458-00</b> <sup>12</sup> 072 198 012 A  <b>B31458-00</b> <sup>13</sup> 075 198 011 B	<b>H00569-00</b> 072 103 383 CT 1,4 mm <b>H10569-10</b> 072 103 383 DA 1,5 mm 2 <b>H20569-20</b> 072 103 383 DB 78 Ø 1,6 mm 3 	<b>T08968-00</b> 068 103 384 A (14x) 	<b>V31458-00</b> 072 198 025 A 	<b>N91210-00</b> 026 109 675 (12x) <b>P76531-00</b> 026 109 675 12x	<b>X08969-01</b> 072 129 717 A 	<b>X03747-01</b> 026 129 589 A 6x 	<b>X54130-01</b> 075 103 609 C 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 22R	84 kW (114 PS)	TARO	06/89-03/97	<b>S80951-00</b> <sup>12</sup> <sup>13</sup> J04 111 353 60 <b>D80951-00</b> <sup>12</sup> J04 112 353 30	<b>H80951-00</b> J11 115 350 60 94,5 Ø 	<b>T50621-00</b> J90 105 120 92 (10x) 	<b>V37937-00</b> 	<b>P76554-00</b> J90 913 021 10 8x	<b>X89715-01</b> J17 177 350 50  <b>X89828-01</b> <sup>10</sup> J17 176 350 20 	<b>X82237-01</b> J17 173 351 20 	<b>X54907-01</b> 	<b>P76338-11 K</b> → 80x100x10 A SL LD FPM

VOLKSWAGEN													
Ltr.			<b>1</b>										
2,5 AAF ACU AEN	81 kW (110 PS)	TRANSPORTER	11/90-04/03	<b>S31644-00</b> <sup>12</sup> <sup>13</sup> <b>D31644-00</b> <sup>12</sup> 023 198 012 <b>B31637-00</b> <sup>13</sup> 074 198 011 A	<b>H50163-00</b> 023 103 383 B 82,5 Ø 1,8 mm 	<b>T07896-00</b> 068 103 384 A (12x) 	<b>V31637-00</b> 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	10x <b>X55159-01</b> 034 129 717 F 		5x <b>X03747-01</b> 026 129 589 A 	5x <b>X54131-01</b> 074 103 609 F 	<b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM
2,5 ACV	75 kW (102 PS)	TRANSP. →ACV 115 395	09/95-04/03	<del><b>D36651-00</b> <sup>12</sup></del> <del></del> <del><b>B32840-00</b> 074 198 011 B</del> <del></del> <b>B32840-00</b> 074 198 011 B Mot.→ACV 115 395 <b>B36651-00</b> <sup>13</sup> <sup>35</sup> Mot.AC.V 115 396→ Mot.→ACV 185 000 <b>B36656-00</b> <sup>13</sup> <sup>35</sup> Mot.AC.V 185 001→	<b>H02396-00</b> 074 103 383 AJ 1,53 mm 1	<b>T07896-00</b> 068 103 384 A (12x) 	<b>X59781-01</b> X 	<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	10x <b>X56210-01</b> 074 129 717 		5x <b>X03747-01</b> 026 129 589 A 	5x <b>X54131-01</b> 074 103 609 F Mot.→ACV 185 000  <b>X54722-01</b> 074 103 609 H Stahl Mot.AC.V 185 001→ 	<b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77317-01</b> K →
2,5 AET	85 kW (115 PS)	TRANSPORTER	07/96-04/03	<b>D36660-00</b> <b>B32840-00</b> 074 198 011 B Mot.→AET 017 277 <b>B36651-00</b> <sup>13</sup> <sup>35</sup> Mot.AET 017 278→ Mot.→AET 025 000 <b>B36656-00</b> <sup>13</sup> <sup>35</sup> Mot.AET 025 001→	<b>H50163-00</b> 023 103 383 B 82,5 Ø 1,8 mm 	<b>T07896-00</b> 068 103 384 A (12x) 		<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	10x <b>X55159-01</b> 034 129 717 F 		5x <b>X03747-01</b> 026 129 589 A 	5x <b>X54131-01</b> 074 103 609 F Mot.→AET 025 000  <b>X54722-01</b> 074 103 609 H Stahl Mot.AET 025 001→ 	<b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AET 017 277 <b>P77317-01</b> K →
2,5 AEU	81 kW (110 PS)	TRANSPORTER	11/90-04/03	<b>D36660-00</b> <b>B32840-00</b> 074 198 011 B Mot.→AEU 002 001 <b>B36651-00</b> <sup>13</sup> <sup>35</sup> Mot.AEU 002 002→ Mot.→AEU 003 000 <b>B36656-00</b> <sup>13</sup> <sup>35</sup> Mot.AEU 003 001→	<b>H50163-00</b> 023 103 383 B 82,5 Ø 1,8 mm 	<b>T07896-00</b> 068 103 384 A (12x) 		<b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	10x <b>X55159-01</b> 034 129 717 F 		5x <b>X03747-01</b> 026 129 589 A 	5x <b>X54131-01</b> 074 103 609 F Mot.→AEU 003 000  <b>X54722-01</b> 074 103 609 H Stahl Mot.AEU 003 001→ 	<b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AEU 002 001 <b>P77317-01</b> K →



VOLKSWAGEN												
2,5 AFB AKN	110 kW (150 PS)	PASSAT V6 TDI	07/98-05/05	<p><b>D32940-00</b> <sup>12</sup></p> <p><b>B32940-00</b> <sup>13</sup></p>	<p><b>H03136-00</b> 2x 059 103 383 BQ 1,1 mm 1 </p> <p><b>H113136-10</b> 2x 059 103 383 BR 1,15 mm 2 </p> <p><b>H23136-20</b> 2x 059 103 383 BS 79 Ø 1,2 mm 3 </p>	<p><b>T03136-00</b> 059 103 384 (16x)</p>	<p><b>V32940-00</b> 2x 059 198 025</p>	<p><b>N92830-00</b> 036 109 675 (24x)</p> <p><b>P76662-00</b> 24x 036 109 675</p>	<p><b>X58943-01</b> 2x 059 129 717 G</p>	<p><b>X52307-01</b> 6x 059 253 039 B</p> <p><b>X52930-01</b> </p>	<p><b>X54465-01</b> 059 103 609 J</p> <p><b>70-31414-10</b></p> <p><b>X54464-01</b> <sup>11</sup> 059 103 610 B</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p><b>P77440-01</b> K → 070 103 051 A 85x105x12 A SL LD PTFE</p> <p><b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM</p>
2,5 AGX	55 kW (75 PS)	LT SDI	07/96-07/06	<p><b>D36651-00</b> <sup>12</sup></p> <p><b>B32840-00</b> 074 198 011 B Mot.→AGX 009 000</p> <p><b>B36651-00</b> <sup>13 35</sup> Mot.AGX 009 001→ Mot.→AGX 016 876</p> <p><b>B36656-00</b> <sup>13 35</sup> Mot.AGX 016 877→</p>	<p><b>H02396-00</b> 074 103 383 AJ 1,53 mm 1 </p> <p><b>H12396-10</b> 074 103 383 AH 1,57 mm 2 </p> <p><b>H22396-20</b> 074 103 383 AG 82 Ø 1,61 mm 3 </p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>	<p><b>X59781-01</b> </p>	<p><b>N90710-01</b> 026 109 675 (10x)</p> <p><b>P76531-00</b> 10x 026 109 675</p>	<p><b>X56210-01</b> 074 129 717</p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p><b>X54131-01</b> 5x 074 103 609 F Mot.→AGX 016 876</p> <p><b>X54722-01</b> 074 103 609 H Stahl Mot.AGX 016 877→</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p>Mot.→AGX 009 000</p> <p><b>P77317-01</b> K → </p> <p>028 103 171 B PTFE Mot.AGX 009 001→</p> <p><b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM</p>
2,5 AHD	75 kW (102 PS)	LT TDI	05/96-08/99	<p><b>D36651-00</b> <sup>12</sup></p> <p><b>B32840-00</b> 074 198 011 B Mot.→AHD 036 065</p> <p><b>B36651-00</b> <sup>13 35</sup> Mot.AHD 036 066→ Mot.→AHD 063 000</p> <p><b>B36656-00</b> <sup>13 35</sup> Mot.AHD 063 001→</p>	<p><b>H02396-00</b> 074 103 383 AJ 1,53 mm 1 </p> <p><b>H12396-10</b> 074 103 383 AH 1,57 mm 2 </p> <p><b>H22396-20</b> 074 103 383 AG 82 Ø 1,61 mm 3 </p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>	<p><b>X59781-01</b> </p>	<p><b>N90710-01</b> 026 109 675 (10x)</p> <p><b>P76531-00</b> 10x 026 109 675</p>	<p><b>X56210-01</b> 074 129 717</p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p><b>X54131-01</b> 5x 074 103 609 F Mot.→AHD 063 000</p> <p><b>X54722-01</b> 074 103 609 H Stahl Mot.AHD 063 001→</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p><b>P76355-11</b> K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p>Mot.→AHD 036 065</p> <p><b>P77317-01</b> K → </p> <p>028 103 171 B PTFE Mot.AHD 036 066→</p> <p><b>P76087-01</b> N 2x 068 103 085 E 32x47x10 A SL WD FPM</p>
2,5 AHY	111 kW (151 PS)	TRANSPORTER	05/98-04/03	<p><b>D36656-00</b> <sup>12</sup></p> <p><b>B36651-00</b> <sup>13 35</sup> Mot.→AHY 005 000</p> <p><b>B36656-00</b> <sup>13 35</sup> Mot.AHY 005 001→</p>	<p><b>H02396-00</b> 074 103 383 AJ 1,53 mm 1 </p> <p><b>H12396-10</b> 074 103 383 AH 1,57 mm 2 </p> <p><b>H22396-20</b> 074 103 383 AG 82 Ø 1,61 mm 3 </p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>	<p><b>X59781-01</b> </p>	<p><b>N90710-01</b> 026 109 675 (10x)</p> <p><b>P76531-00</b> 10x 026 109 675</p>	<p><b>X56210-01</b> 074 129 717</p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p><b>X54131-01</b> 5x 074 103 609 F Mot.→AHY 005 000</p> <p><b>X54722-01</b> 074 103 609 H Stahl Mot.AHY 005 001→</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p><b>P77317-01</b> K → </p> <p>028 103 171 B PTFE</p> <p><b>P77181-01</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM</p> <p><b>P77182-01</b> N 028 103 086 32x47x10 A SL LD PTFE</p>

VOLKSWAGEN												
2,5 AJT	65 kW (88 PS)	TRANSPORTER	05/98-04/03	<p><b>D36656-00</b> <sup>12</sup></p> <p><b>B36651-00</b> <sup>13 35</sup> Mot.→AJT 016 000</p> <p><b>B36656-00</b> <sup>13 35</sup> Mot.AJT 016 001→</p>	<p><b>H02396-00</b> 074 103 383 AJ 1,53 mm 1 </p> <p><b>H12396-10</b> 074 103 383 AH 1,57 mm 2 </p> <p><b>H22396-20</b> 074 103 383 AG 82 Ø 1,61 mm 3 </p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>	<p><b>X59781-01</b> </p>	<p><b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675</p>	<p><b>X56210-01</b> 074 129 717</p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p>5x <b>X54131-01</b> 074 103 609 F Mot.→AJT 016 000</p> <p><b>X54722-01</b> 074 103 609 H Stahl</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77317-01</b> K → </p> <p>028 103 171 B PTFE</p> <p><b>P77181-01</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77182-01</b> N 028 103 086 32x47x10 A SL LD PTFE</p>
2,5 ANF ANG ANH BBR BCT BCU BCV	40-111 kW (54-151 PS)			<p><b>D36656-00</b> <sup>12</sup></p> <p><b>B36656-00</b> <sup>13 35</sup></p>	<p><b>H02396-00</b> 074 103 383 AJ 1,53 mm 1 </p> <p><b>H12396-10</b> 074 103 383 AH 1,57 mm 2 </p> <p><b>H22396-20</b> 074 103 383 AG 82 Ø 1,61 mm 3 </p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>	<p><b>X59781-01</b> </p>	<p><b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675</p>	<p><b>X56210-01</b> 074 129 717</p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p>5x <b>X54722-01</b> 074 103 609 H Stahl</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77317-01</b> K → </p> <p>028 103 171 B PTFE</p> <p><b>P77181-01</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77182-01</b> N 028 103 086 32x47x10 A SL LD PTFE</p>
2,5 ANJ APA AUF AVR AXG AXL AYC AYY BBE BBF	61-111 kW (83-151 PS)	LT TDI TRANSPORTER	09/95-07/06	<p><b>D36656-00</b> <sup>12</sup></p> <p><b>B36656-00</b> <sup>13 35</sup></p>	<p><b>H02396-00</b> 074 103 383 AJ 1,53 mm 1 </p> <p><b>H12396-10</b> 074 103 383 AH 1,57 mm 2 </p> <p><b>H22396-20</b> 074 103 383 AG 82 Ø 1,61 mm 3 </p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>	<p><b>X59781-01</b> </p>	<p><b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675</p>	<p><b>X56210-01</b> 074 129 717</p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p>5x <b>X54722-01</b> 074 103 609 H Stahl</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77317-01</b> K → </p> <p>028 103 171 B PTFE</p> <p><b>P77181-01</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77182-01</b> N 028 103 086 32x47x10 A SL LD PTFE</p>
2,5 APL AVT	85 kW (115 PS)	TRANSPORTER	07/96-04/03	<p><b>D36660-00</b> <b>B36656-00</b> <sup>13 35</sup></p>	<p><b>H50163-00</b> 023 103 383 B 82,5 Ø 1,8 mm</p>	<p><b>T07896-00</b> 068 103 384 A (12x)</p>		<p><b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675</p>	<p><b>X55159-01</b> 034 129 717 F</p>	<p><b>X03747-01</b> 026 129 589 A</p>	<p>5x <b>X54722-01</b> 074 103 609 H Stahl</p>	<p><b>P76096-01</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77317-01</b> K → </p> <p>028 103 171 B PTFE</p> <p><b>P77181-01</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77182-01</b> N 028 103 086 32x47x10 A SL LD PTFE</p>

VOLKSWAGEN													
2,5 Ltr.	AXD AXE BAC BLJ BLK	96-128 kW (130-174 PS)	MULTIVAN TDI TOUAREG R5 TRANSPORTER	01/03→	 D37059-00 <sup>12</sup>  B37059-00 <sup>13</sup>	H01895-00 070 103 383 M 1,27 mm 1 MLS H11895-10 070 103 383 N 1,35 mm 2 MLS H21895-20 070 103 383 P 83 Ø 1,43 mm 3 MLS 	T08127-00 070 103 384 (12x) 	70-31414-10 	N93137-00 027 109 675 (10x) P76532-00 027 109 675	X89297-01 070 129 717 A 10x  X89298-01 070 129 717  X89299-01 070 129 717 B 2x 	X81444-01 070 253 039 C 	70-31414-10 	P77440-01 K ← 070 103 051 A 85x105x12 A SL LD PTFE
2,5 BAU BDG BDH	120-132 kW (163-180 PS)	PASSAT V6 TDI	01/03-05/05	D32940-00 <sup>12</sup>  B32940-00 <sup>13</sup> 	H03136-00 2x 059 103 383 BQ 1,1 mm 1 MLS H13136-10 2x 059 103 383 BR 1,15 mm 2 MLS H23136-20 2x 059 103 383 BS 79 Ø 1,2 mm 3 MLS 	T80448-00 057 103 384 A (16x) 	V32940-00 2x 059 198 025 	N92830-00 036 109 675 (24x) P76662-00 036 109 675	X58943-01 2x 059 129 717 G 24x 	X52307-01 6x 059 253 039 B  X52930-01	70-31414-10 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P77440-01 K → 070 103 051 A 85x105x12 A SL LD PTFE P76087-01 N 2x 068 103 085 E 32x47x10 A SL WD FPM	
2,5 BGP BPR BPS BTK	110 kW (150 PS)	JETTA NEW BEETLE	07/05-10/10	D37093-00 <sup>12</sup>	H80754-00 07K 103 383 F MLS 	T80754-00 06D 103 385 D (12x) 	X83140-01 07K 103 483 NBR 	N90298-00 036 109 675 (20x) P76662-00 036 109 675	X89311-01 5x 07K 129 717 A 20x 	X81830-01 07K 253 039 C 	70-31414-10 	P77817-01 K ← 07K 103 151 B PTFE P77440-01 K → 070 103 051 A 85x105x12 A SL LD PTFE	
2,5 BGQ CBTA CBUA CCCA	110-125 kW (150-170 PS)	BEETLE JETTA FSI	07/08→	D37093-00 <sup>12</sup>	H80754-00 07K 103 383 F MLS 	T80754-00 06D 103 385 D (12x) 	X83140-01 07K 103 483 NBR 	N90298-00 036 109 675 (20x) P76662-00 036 109 675	X89311-01 5x 07K 129 717 A 20x 	X81830-01 07K 253 039 C 	70-31414-10 	P77440-01 K → 070 103 051 A 85x105x12 A SL LD PTFE	
2,5 BJJ BJK BJL BJM	65-120 kW (88-163 PS)	BUS 30-35 KASTEN 30-50 PRITSCH 30-50	04/06→	D37060-00 <sup>12</sup>  B37060-00 <sup>13</sup> <sup>36</sup>	H01896-00 076 103 383 C 1,53 mm 1 MLS H11896-10 076 103 383 D 1,57 mm 2 MLS H21896-20 076 103 383 E 81,5 Ø 1,61 mm 3 MLS 	T07896-00 068 103 384 A (12x) 	X59781-01	N90710-01 026 109 675 (10x) P76531-00 026 109 675	X56210-01 10x 074 129 717 	X81985-01 074 253 039 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM	

VOLKSWAGEN												
2,5 BNC BPC BPD BPE	96-128 kW (130-174 PS)	MULTIVAN TDI TOUAREG R5 TRANSPORTER	01/03→	 <b>D37061-00</b> ⑫  <b>B37059-00</b> ⑬	 <b>H01895-00</b> 070 103 383 M 1,27 mm 1 MLS <b>H11895-10</b> 070 103 383 N 1,35 mm 2 MLS <b>H21895-20</b> 070 103 383 P 83 Ø 1,43 mm 3 MLS 	 <b>T08127-00</b> 070 103 384 (12x) 	 <b>70-31414-10</b> 	 <b>N93137-00</b> 027 109 675 (10x) <b>P76532-00</b> 027 109 675	 <b>X88926-01</b> 070 129 717 D <b>X88931-01</b> 070 129 717 E <b>X88932-01</b> 070 129 717 C	 <b>X81444-01</b> 070 253 039 C 	 <b>70-31414-10</b> 	 <b>P77440-01 K</b> ← 070 103 051 A 85x105x12 A SL LD PTFE
2,5 CEBA CEBB CECA CECB	65-120 kW (88-163 PS)	BUS 30-35 KASTEN 30-50 PRITSCH 30-50	04/06→	 <b>D37060-00</b> ⑫  <b>B37060-00</b> ⑬ ⑳	 <b>H01896-00</b> 076 103 383 C 1,53 mm 1 MLS <b>H11896-10</b> 076 103 383 D 1,57 mm 2 MLS <b>H21896-20</b> 076 103 383 E 81,5 Ø 1,61 mm 3 MLS 	 <b>T07896-00</b> 068 103 384 A (12x) 	 <b>X59781-01</b> X 	 <b>N90710-01</b> 026 109 675 (10x) <b>P76531-00</b> 026 109 675	 <b>X56210-01</b> 074 129 717 	 <b>X81985-01</b> 074 253 039 	 <b>70-31414-10</b> 	 <b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77821-01 K</b> → 076 103 171 B PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,7 CG	48 kW (65 PS)	LT D	11/75-01/80	 <b>D30900-00</b> ⑫ 061198012 <b>B30900-00</b> ⑬ 061198011	 <b>H02898-00</b> 61103383 97,5 Ø 		 <b>X02602-01</b> 61103483 Kork 	 <b>N90880-00</b>	 <b>X02601-01</b> 36866201 	 <b>X02600-01</b> 3686442 <b>X02599-01</b> ⚠ 049204 	 <b>70-31414-10</b> 	 <b>P76402-01 K</b> → 073034 101,6x120x12 A LD FPM
2,8 AAA	120-128 kW (163-174 PS)	GOLF V6 PASSAT V6 SHARAN V6 VENTO V6	06/91-04/00	 <b>D32726-00</b> ⑫ 021 198 012 A Mot.→AAA 146 000 <b>D36996-00</b> ⑫ Mot.AAA 146 001→ <b>B32726-00</b> ⑬ 021 198 011 Mot.→AAA 146 000 <b>B36996-00</b> ⑬ 021 198 011 A Mot.AAA 146 001→	 <b>H50150-00</b> 021 103 383 H 83 Ø 	 <b>T50150-00</b> 021 103 384 D (10x) +021 103 384 E (7x) +021 103 384 F (3x) 	 <b>X53502-01</b> 021 103 483 B NBR Mot.→AAA 146 000  <b>X83104-01</b> 021 103 483 D NBR Mot.AAA 146 001→ 	 <b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675	 <b>X58346-01</b> 021 133 227 J <b>X58345-01</b> ⑩ 021 133 227 H 	 <b>X51973-01</b> 021 253 039 E Zyl. 1 - 3  <b>X51974-01</b> 021 253 050 B Zyl. 4 - 6  <b>X81690-01</b> ⚠ 357 253 115 D 	 <b>X54363-01</b> 021 103 609 Mot.→AAA 146 000  <b>X54676-01</b> 021 103 609 B ACM Mot.AAA 146 001→ 	 <b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM
2,8 ACK AGE ALG AMX APR ATX	132-142 kW (180-193 PS)	PASSAT V6 →3B W 500 000	08/96-05/05	 <b>D36714-00</b> 078 198 012 B <b>B32943-00</b> 079198011A <b>Z36190-00</b> ⑧ 058 198 217	 <b>H80491-00</b> 078 103 383 L 83,5 Ø MLS 	 <b>T50999-00</b> 078 103 385 K (16x) 	 <b>V53716-00</b> 078 198 025 	 <b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675	 <b>X58942-01</b> 078 129 717 J 	 <b>X52306-01</b> 078 253 039 C 	 <b>X54463-01</b> 078 103 610 E  <b>70-31414-10</b> 	 <b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN													
2.8 ACK AGE ALG AMX APR AQD ATQ ATX	132-142 kW (180-193 PS)	PASSAT V6	3B X 000 001→	08/96-05/05	<b>D36715-00</b> 078 198 012 F +068 103 085 E (2x) <b>B32943-00</b> 079198011A <b>Z36190-00</b> (8) 058 198 217	2x <b>H80491-00</b> 078 103 383 L 83,5 Ø MLS 	2x <b>T50999-00</b> 078 103 385 K (16x) 	<b>V53716-00</b> 078 198 025 	2x <b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675 30x 	<b>X58942-01</b> 078 129 717 J 2x 	<b>X52308-01</b> 078 253 039 G 2x 	<b>X54463-01</b> 078 103 610 E  <b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM
2.8 AES	103 kW (140 PS)	TRANSPORTER		11/95-05/00	<b>B36996-00</b> (13) 021 198 011 A Mot.→AES 009 433	<b>H50150-00</b> 021 103 383 H 83 Ø Mot.→AES 009 433  <b>H80100-00</b> 021 103 383 N 83,5 Ø MLS Mot.AES 009 434→ 	<b>T50150-00</b> 021 103 384 D (10x) +021 103 384 E (7x) +021 103 384 F (3x) Mot.→AES 009 433  <b>T50478-00</b> 021 103 384 G (10x) +021 103 384 K (7x) +021 103 384 L (3x) Mot.AES 009 434→ 	<b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675	12x <b>X89184-01</b> 021 133 227 K  <b>X58345-01</b> (10) 021 133 227 H 	<b>X51973-01</b> 021 253 039 E Zyl. 1 - 3  <b>X51974-01</b> 021 253 050 B Zyl. 4 - 6 	<b>X54676-01</b> 021 103 609 B ACM Mot.→AES 009 433  <b>70-31414-10</b> Mot.AES 009 434→ 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM	
2.8 AGK ATA	92-96 kW (125-130 PS)	LT TDI		07/97-07/06	<b>D36661-00</b> (12) <b>B36661-00</b> (13)	<b>H80472-00</b> 062 103 383 A 96 Ø 	<b>T80472-00</b> 062 103 384 (10x) 	<b>X83011-01</b> 062 103 483 NBR 	<b>N93117-00</b> 062 109 675 (12x) <b>P76775-00</b> 062 109 675 12x 	<b>X87650-01</b> 062 129 717 	<b>X81505-01</b> 062 129 589 4x  <b>X81506-01</b> (A) 	<b>X54721-01</b> 062 103 609 	<b>P77445-01 K</b> ← 062 115 147 64x80x9 B SL RD FPM <b>P77446-01 K</b> → 062 103 051 91x111x10 AB SL LD FPM
2.8 AMV AYL BDE BDF	147-150 kW (200-204 PS)	BORA V6  GOLF V6  SHARAN V6 TRANSP.	→1J 5D001 000, 1J 5U001 500, 1J 5W050 000 →1J 5D001 000, 1J 5U001 500, 1J 5W050 000 →7M 5 021 000	03/99→	<b>D36998-00</b> (12) <b>B36716-00</b> (13)	<b>H80099-00</b> 022 103 383 F 82,5 Ø MLS 	<b>T80099-00</b> 022 103 384 C (12x) +022 103 384 D (6x) 	<b>X83108-01</b> 022 103 483 E NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675 24x 	<b>X88307-01</b> 022 133 237 A 	<b>X81437-01</b> 022 253 039 B Zyl. 1 - 3  <b>X81689-01</b> 022 253 050 B Zyl. 4 - 6  <b>X81690-01</b> (A) 357 253 115 D 2x 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
2.8 AMY	128 kW (174 PS)	SHARAN V6		09/95-04/00	<b>D36997-00</b> (12) <b>B36997-00</b> (13)	<b>H80100-00</b> 021 103 383 N 83,5 Ø MLS 	<b>T50478-00</b> 021 103 384 G (10x) +021 103 384 K (7x) +021 103 384 L (3x) 	<b>X83104-01</b> 021 103 483 D NBR 	<b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675 12x 	<b>X58346-01</b> 021 133 227 J  <b>X58345-01</b> (10) 021 133 227 H 	<b>X51973-01</b> 021 253 039 E Zyl. 1 - 3  <b>X51974-01</b> 021 253 050 B Zyl. 4 - 6  <b>X81690-01</b> (A) 357 253 115 D 2x 	<b>70-31414-10</b> 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM

VOLKSWAGEN															
2,8 AQT ATQ	142 kW (193 PS)	PASSAT V6 →3B W 500 000	08/96-05/05	<b>D36714-00</b> 078 198 012 B <b>B32943-00</b> 079198011A <b>Z36190-00</b> ⑧ 058 198 217	2x  2x	<b>H80491-00</b> 078 103 383 L 83,5 Ø MLS	2x 	<b>T50999-00</b> 078 103 385 K (16x) 	<b>V53716-00</b> 078 198 025 	2x <b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675	30x 	<b>X58942-01</b> 078 129 717 J 2x 	<b>X52306-01</b> 078 253 039 C 2x 	<b>X54463-01</b> 078 103 610 E  <b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM
2,8 AQP AUE	150 kW (204 PS)	BORA V6 GOLF V6	03/99-06/06	<b>D37024-00</b> ⑫ <b>B36716-00</b> ⑬	<b>H80099-00</b> 022 103 383 F 82,5 Ø MLS 	<b>T80099-00</b> 022 103 384 C (12x) +022 103 384 D (6x) 	<b>X83033-01</b> 022 103 483 D NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	24x <b>X88307-01</b> 022 133 237 A 	<b>X81437-01</b> 022 253 039 B Zyl. 1 - 3  <b>X81689-01</b> 022 253 050 B Zyl. 4 - 6  <b>X81690-01</b> ⚠ 357 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM			
2,8 AUH BCQ	116 kW (158 PS)	LT TDI	05/01-07/06	<b>D40556-01</b> ⑫ <b>B36661-00</b> ⑬	<b>H40556-00</b> 062 103 383 B 96 Ø MLS 	<b>T80472-00</b> 062 103 384 (10x) 	<b>X83011-01</b> 062 103 483 NBR 	<b>N93117-00</b> 062 109 675 (12x) <b>P76775-00</b> 062 109 675	12x <b>X87650-01</b> 062 129 717 	<b>X81505-01</b> 062 129 589  <b>X81506-01</b> ⚠ 	4x <b>X54721-01</b> 062 103 609 	<b>P77445-01 K</b> ← 062 115 147 64x80x9 B SL RD FPM <b>P77446-01 K</b> → 062 103 051 91x111x10 AB SL LD FPM			
2,8 AYL BDE	150 kW (204 PS)	BORA V6 GOLF V6 SHARAN V6	03/99-03/10	<b>D36998-00</b> ⑫	<b>H80099-00</b> 022 103 383 F 82,5 Ø MLS 	<b>T80099-00</b> 022 103 384 C (12x) +022 103 384 D (6x) 	<b>X83108-01</b> 022 103 483 E NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	24x <b>X88307-01</b> 022 133 237 A 	<b>X81437-01</b> 022 253 039 B Zyl. 1 - 3  <b>X81689-01</b> 022 253 050 B Zyl. 4 - 6  <b>X81690-01</b> ⚠ 357 253 115 D 2x 	<b>70-31414-10</b> 	<b>P77820-01 K</b> ← ⚠ 022 103 151 D <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM			
2,8 BBG	140 kW (190 PS)	PASSAT V6	09/99-11/00	<b>D36715-00</b> 078 198 012 F +068 103 085 E (2x) <b>Z36190-00</b> ⑧ 058 198 217	2x  2x	<b>H80491-00</b> 078 103 383 L 83,5 Ø MLS	2x 	<b>T50999-00</b> 078 103 385 K (16x) 	<b>V53716-00</b> 078 198 025 	2x <b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675	30x 	<b>X58942-01</b> 078 129 717 J 2x 	<b>X52308-01</b> 078 253 039 G 2x 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN													
2,9 ABV	135-140 kW (184-190 PS)	CORRADO V6 GOLF V6 PASSAT V6	08/91-04/99	<b>D32726-00</b> <sup>12</sup> 021 198 012 A Mot.→ABV 023 000 <b>D36996-00</b> <sup>12</sup> Mot.ABV 023 001→ <b>B32726-00</b> <sup>13</sup> 021 198 011 Mot.→ABV 023 000 <b>B36996-00</b> <sup>13</sup> 021 198 011 A Mot.ABV 023 001→	<b>H50150-00</b> 021 103 383 H 83 Ø 	<b>T50150-00</b> 021 103 384 D (10x) +021 103 384 E (7x) +021 103 384 F (3x) 	<b>X53502-01</b> 021 103 483 B NBR Mot.→ABV 023 000  <b>X83104-01</b> 021 103 483 D NBR Mot.ABV 023 001→ 	<b>N92450-00</b> 027 109 675 (12x) <b>P76532-00</b> 027 109 675 	<b>X58346-01</b> 021 133 227 J 12x <b>X58345-01</b> <sup>10</sup> 021 133 227 H 	<b>X51973-01</b> 021 253 039 E Zyl. 1 - 3  <b>X51974-01</b> 021 253 050 B Zyl. 4 - 6 	<b>X54363-01</b> 021 103 609 Mot.→ABV 023 000  <b>X54676-01</b> 021 103 609 B ACM Mot.ABV 023 001→ 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM	
3,0 BKS BMK BSP	165 kW (224-225 PS)	PHAETON V6 TOUAREG TDI	09/04→	<b>D37054-00</b> <sup>12</sup> Zyl. 1 - 3  <b>D37055-00</b> <sup>12</sup> Zyl. 4 - 6  <b>B37054-00</b> <sup>13</sup>	<b>H01841-00</b> 059 103 383 CM 1,1 mm 1 MLS Zyl. 1 - 3 <b>H11841-10</b> 059 103 383 CN 1,15 mm 2 MLS Zyl. 1 - 3 <b>H21841-20</b> 059 103 383 CP 1,2 mm 3 MLS Zyl. 1 - 3  <b>H01842-00</b> 059 103 383 CQ 1,1 mm 1 MLS Zyl. 4 - 6 <b>H11842-10</b> 059 103 383 CR 1,15 mm 2 MLS Zyl. 4 - 6 <b>H21842-20</b> 059 103 383 CS 1,2 mm 3 MLS Zyl. 4 - 6 	<b>T80448-00</b> 057 103 384 A (16x) 	<b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR  <b>X83106-01</b> 059 103 483 M Zyl. 4 - 6 NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675 	<b>X89125-01</b> 2x 059 129 717 J 24x	<b>X81941-01</b> 2x 059 253 039 D 2x	<b>70-31414-10</b> 	<b>P77441-01 K</b> ← 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	

VOLKSWAGEN												
Ltr.												
3,0 BUN	155 kW (211 PS)	TOUAREG TDI	04/06-05/10	<p><b>D37054-00</b> <sup>12</sup> Zyl. 1 - 3 </p> <p><b>D37055-00</b> <sup>12</sup> Zyl. 4 - 6 </p> <p><b>B37054-00</b> <sup>13</sup></p>	<p><b>H01841-00</b> 059 103 383 CM 1,1 mm 1 </p> <p>MLS Zyl. 1 - 3</p> <p><b>H11841-10</b> 059 103 383 CN 1,15 mm 2 </p> <p>MLS Zyl. 1 - 3</p> <p><b>H21841-20</b> 059 103 383 CP 1,2 mm 3 </p> <p>MLS Zyl. 1 - 3</p> <p><b>H01842-00</b> 059 103 383 CQ 1,1 mm 1 </p> <p>MLS Zyl. 4 - 6</p> <p><b>H11842-10</b> 059 103 383 CR 1,15 mm 2 </p> <p>MLS Zyl. 4 - 6</p> <p><b>H21842-20</b> 059 103 383 CS 1,2 mm 3 </p> <p>MLS Zyl. 4 - 6</p>	<p><b>T80448-00</b> 057 103 384 A (16x)</p>	<p><b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR</p> <p><b>X83106-01</b> 059 103 483 M Zyl. 4 - 6 NBR</p>	<p><b>N92830-00</b> 036 109 675 (24x)</p> <p><b>N92993-00</b> 036 109 675 (12x)</p> <p><b>P76662-00</b> 036 109 675</p>	<p><b>X89125-01</b> 2x 059 129 717 J</p> <p>24x</p>	<p><b>X81941-01</b> 2x 059 253 039 D</p>	<p><b>P77441-01</b> K ← 079 103 051 D 55x70x8 A SL RD PTFE</p> <p><b>P77362-01</b> K → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM</p> <p><b>P76087-01</b> N 068 103 085 E 32x47x10 A SL WD FPM</p>	



VOLKSWAGEN												
Ltr.												
3,0 CARA CASA CASB CASC CASD CATA CEXA CEXB <b>[NEW]</b>	150-180 kW (204-245 PS) PHAETON TDI TOUAREG TDI	11/04 →										
			<b>D37055-01</b> <sup>12</sup> Zyl. 4 - 6  <b>D38060-00</b> <sup>12</sup> Zyl. 1-3  <b>B38110-00</b> <sup>13</sup>	<b>H01404-00</b> 059 103 383 EP 84 Ø 1,1 mm 1 MLS Zyl. 4-6 <b>H11404-10</b> 059 103 383 EQ 84 Ø 1,15 mm 2 MLS Zyl. 4-6 <b>H21404-20</b> 059 103 383 ER 84 Ø 1,2 mm 3 MLS Zyl. 4-6  <b>H01406-00</b> 059 103 383 ES 84 Ø 1,1 mm 1 MLS Zyl. 1-3 <b>H11406-10</b> 059 103 383 ET 84 Ø 1,15 mm 2 MLS Zyl. 1-3 <b>H21406-20</b> 059 103 383 FA 84 Ø 1,2 mm 3 MLS Zyl. 1-3 	<b>T80448-00</b> 057 103 384 A (16x) 	<b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR  <b>X83106-01</b> 059 103 483 M Zyl. 4 - 6 NBR 	<b>N92993-00</b> 036 109 675 (12x) <b>P76662-00</b> 036 109 675 24x	<b>X89125-01</b> 2x 059 129 717 J 24x	<b>X81941-01</b> 2x 059 253 039 D 	<b>70-31414-10</b> 	<b>P77441-01 K</b> ← 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	

VOLKSWAGEN																	
Ltr.																	
3,0 CEZA	195 kW (265 PS)			<b>D37055-00</b> <sup>12</sup> Zyl. 4 - 6 	<b>D38060-00</b> <sup>12</sup> Zyl. 1-3 	<b>B38110-00</b> <sup>13</sup>	<b>H01841-00</b> 059 103 383 CM 1,1 mm 1	<b>H11841-10</b> 059 103 383 CN 1,15 mm 2	<b>H21841-20</b> 059 103 383 CP 1,2 mm 3	<b>T80448-00</b> 057 103 384 A (16x) 	2x <b>X83105-01</b> 059 103 483 N Zyl. 1 - 3 NBR 	<b>X83106-01</b> 059 103 483 M Zyl. 4 - 6 NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	24x <b>X89125-01</b> 059 129 717 J	2x <b>X81941-01</b> 059 253 039 D 	2x <b>70-31414-10</b> 	<b>P77441-01 K</b> ← 079 103 051 D 55x70x8 A SL RD PTFE <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
3,0 CGEA CGFA CJTA	213-245 kW (290-333 PS)	TOUAREG TSI	04/10→	<b>D38069-00</b> <sup>12</sup> Zyl. 1-3 <b>D38070-00</b> <sup>12</sup> Zyl. 4-6 <b>B38111-00</b> <sup>13</sup> <sup>35</sup>	<b>H40461-00</b> 06E 103 148 AD 85,2 Ø MLS Zyl. 1-3 	<b>H40462-00</b> 06E 103 149 AD 85,2 Ø MLS Zyl. 4-6 	<b>T80728-00</b> 06E 103 385 (8x) 	2x <b>X83361-01</b> 06E 103 484 P Zyl. 1-3 	<b>X83362-01</b> 06E 103 483 Q Zyl. 4-6 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	24x <b>X59476-01</b> 079 129 717 D	6x <b>X89852-01</b> <sup>10</sup> 079 129 717 B 	6x <b>X81442-01</b> 06E 253 039 C 	2x <b>70-31414-10</b> 	<b>P77452-01 K</b> ← 06E 103 153 E PTFE <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM		

VOLKSWAGEN													
Ltr.    1 3,0 CJGD C.JMA CNRB CRCA	150-180 kW (204-245 PS)	TOUAREG TDI	01/10→	 <b>D38407-00</b> <sup>12</sup>  <b>B38736-00</b> <sup>13</sup>	<b>H40585-00</b> 059 103 383 JL 84 Ø 1,58 mm 1 MLS Zyl. 1-3 <b>H40585-10</b> 059 103 383 JM 84 Ø 1,63 mm 2 MLS Zyl. 1-3 <b>H40585-20</b> 059 103 383 JN 84 Ø 1,68 mm 3 MLS Zyl. 1-3 	<b>T40585-00</b> WHT 005 262 (8x) 	2x <b>X83407-01</b> 059 103 484 Zyl. 1-3 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675 24x	<b>X59478-01</b> 059 129 717 N 6x 	<b>X59481-01</b> 059 129 718 A 6x 	<b>X82514-01</b> 059 253 039 N 2x 	<b>70-31414-10</b> 	<b>P77441-01 K</b> ← 079 103 051 D 55x70x8 A SL RD PTFE <b>P77766-01 K</b> → 059 103 051 K 85x105x8 A SL LD FPM
3,0 CNGA	184 kW (250 PS)			<b>D37064-01</b> <sup>12</sup>	<b>H80734-00</b> 03H 103 383 H 85 Ø MLS 	<b>T80734-00</b> WHT 000 497 A (13x) +WHT 000 789 A (7x) 	<b>X83128-01</b> 03H 103 483 C NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675 24x	<b>X89886-01</b> 03H 133 237 D 24x 	<b>X82352-01</b> 03H 253 039 H Zyl. 1-3 	<b>X82353-01</b> 03H 253 050 D Zyl. 4-6 	<b>70-31414-10</b> 	<b>P77822-01 K</b> ← 03H 03 151 B <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM



VOLKSWAGEN														
Ltr.				<b>1</b>										
3,0 CPFA <b>[NEW]</b>	184 kW (250 PS)				<b>D37064-01</b> <sup>12</sup> <b>B82499-00</b> <sup>13</sup>	<b>H80734-00</b> 03H 103 383 H 85 Ø MLS 	<b>T80734-00</b> WHT 000 497 A (13x) +WHT 000 789 A (7x) 	<b>X83128-01</b> 03H 103 483 C NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	<b>X89886-01</b> 03H 133 237 D 24x		<b>X82352-01</b> 03H 253 039 H Zyl. 1-3  <b>X82353-01</b> 03H 253 050 D Zyl. 4-6 	<b>70-31414-10</b> 	<b>P77822-01 K</b> ← 03H 03 151 B <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
3,2 AXJ	165 kW (224 PS)	NEW BEETLE RSI		04/00-05/01		<b>H80453-00</b> 022 103 383 M 85 Ø MLS 		<b>X83033-01</b> 022 103 483 D NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	<b>X88307-01</b> 022 133 237 A 24x		<b>X81441-01</b> 022 253 050 C Zyl. 4 - 6  <b>X81963-01</b> 022 253 039 E Zyl. 1 - 3 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
3,2 AXZ	184 kW (250 PS)	PASSAT V6 FSI	3C 6 075 001, 3C 6E 088 001→	11/05-11/10	<b>D37064-00</b> <sup>12</sup>  <b>B82500-00</b> <sup>13</sup>	<b>H80734-00</b> 03H 103 383 H 85 Ø MLS 	<b>T80734-00</b> WHT 000 497 A (13x) +WHT 000 789 A (7x) 	<b>X83128-01</b> 03H 103 483 C NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	<b>X89300-01</b> 03H 133 237 B 24x		<b>X81832-01</b> 03H 253 039 E Zyl. 1 - 3  <b>X81834-01</b> 03H 253 050 B Zyl. 4 - 6 	<b>70-31414-10</b> 	<b>P77820-01 K</b> ← 022 103 151 D <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
3,2 AYT AZZ BAA BDL BFH BJS BKK BKL BML BMV BMX BRJ BRK CFLA	162-177 kW (220-241 PS)	GOLF  MULTIVAN PHAETON TOUAREG TRANSP.	1J 5D001 001, 1J 5U001 501, 1J 5W050 001→ 7H 5 070 001→ 3D 5 004 001→ 7L 5 055 001→ 7H 5 070 001→	04/02→	<b>D37008-00</b> <sup>12</sup>	<b>H80453-00</b> 022 103 383 M 85 Ø MLS 	<b>T80453-00</b> 022 103 384 L (13x) +022 103 384 M (7x) 	<b>X83108-01</b> 022 103 483 E NBR 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	<b>X89128-01</b> 022 133 237 C 24x		<b>X81441-01</b> 022 253 050 C Zyl. 4 - 6  <b>X81963-01</b> 022 253 039 E Zyl. 1 - 3 	<b>70-31414-10</b> 	<b>P77820-01 K</b> ← 022 103 151 D <b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM

VOLKSWAGEN													
3,2 AYT BDL BFH BJS BKK BKL BML BRK CFLA	170-177 kW (231-241 PS)	GOLF  MULTIVAN PHAETON TRANSP.	→1J 5D001 000, 04/02→ 1J 5U001 000, 1J 5W050 000 →7H 5 070 000 →3D 5 004 000 →7H 5 070 000	D37008-00 <sup>12</sup>	H80453-00 022 103 383 M 85 Ø MLS 	T80453-00 022 103 384 L (13x) +022 103 384 M (7x) 	X83108-01 022 103 483 E NBR 	N92830-00 036 109 675 (24x) P76662-00 036 109 675	X89128-01 022 133 237 C 24x	X81441-01 022 253 050 C Zyl. 4 - 6  X81963-01 022 253 039 E Zyl. 1 - 3 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	
3,2 AZZ BAA BKJ BMV BMX BRJ	162-177 kW (220-241 PS)	TOUAREG	→7L 5 055 000 10/02-11/06	D37008-00 <sup>12</sup>	H80453-00 022 103 383 M 85 Ø MLS 	T80453-00 022 103 384 L (13x) +022 103 384 M (7x) 	X83108-01 022 103 483 E NBR 	N92830-00 036 109 675 (24x) P76662-00 036 109 675	X89128-01 022 133 237 C 24x	X81441-01 022 253 050 C Zyl. 4 - 6  X81963-01 022 253 039 E Zyl. 1 - 3 	70-31414-10 	P77447-01 K ← 022 103 085 35x48x10 A RD PTFE ACM P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	
3,2 BUB CBRA	184 kW (250 PS)	EOS V6 GOLF V6	11/05-05/09	D37008-00 <sup>12</sup>	H80453-00 022 103 383 M 85 Ø MLS 	T80453-00 022 103 384 L (13x) +022 103 384 M (7x) 	X83108-01 022 103 483 E NBR 	N92830-00 036 109 675 (24x) P76662-00 036 109 675	X89128-01 022 133 237 C 24x	X81441-01 022 253 050 C Zyl. 4 - 6  X81963-01 022 253 039 E Zyl. 1 - 3 	70-31414-10 	P77820-01 K ← 022 103 151 D P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	
3,6 BHK BHL BLV	206 kW (280 PS)	PASSAT TOUAREG	7L 6 030 001→ 7L 6 030 001→ 10/05-01/12	D37064-00 <sup>12</sup>  B82500-00 <sup>13</sup>	H80734-00 03H 103 383 H 85 Ø MLS 	T80734-00 WHT 000 497 A (13x) +WHT 000 789 A (7x) 	X83128-01 03H 103 483 C NBR 	N92830-00 036 109 675 (24x) P76662-00 036 109 675	X89300-01 03H 133 237 B 24x	X81832-01 03H 253 039 E Zyl. 1 - 3  X81834-01 03H 253 050 B Zyl. 4 - 6 	70-31414-10 	P77820-01 K ← 022 103 151 D P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	



















VOLKSWAGEN													
3,6 BWS CDVA CDVB CGRA CHNA CMTA CMVA	183-220 kW (249-300 PS)	CC FSI EOS PASSAT FSI PASSAT R36 PHAETON TOUAREG FSI	04/07→	D37064-01 <sup>12</sup> B82499-00 <sup>13</sup>	H80734-00 03H 103 383 H 85 Ø MLS 	T80734-00 WHT 000 497 A (13x) +WHT 000 789 A (7x) 	X83128-01 03H 103 483 C NBR 	N92830-00 036 109 675 (24x) P76662-00 036 109 675	X89886-01 03H 133 237 D 24x 	X82352-01 03H 253 039 H Zyl. 1-3 	X82353-01 03H 253 050 D Zyl. 4-6 	70-31414-10 	P77822-01 K ← 03H 03 151 B P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM
4,0 BDN BDP	202 kW (275 PS)	PASSAT W8	09/01-09/04		H80445-00 07D 103 148 J MLS Zyl. 1 - 4 	T80721-00 07D 103 384 A (10x) +07D 103 385 A (5x) 	2x X83344-01 07D 103 483 C Zyl. 5-8 	N92002-00 036 109 675 (15x) P76662-00 036 109 675	2x 30x	X81942-01 07D 253 039 A 2x 	X54809-01 07D 103 609 H 2x 	70-31414-10 	P77442-01 K ← 06C 103 085 42x55x7 AB SL RD PTFE ACM P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM
4,2 AXQ BGH BGJ	228-246 kW (310-335 PS)	PHAETON V8 TOUAREG V8	12/02→	D32944-00 <sup>12</sup> 077198012E	H80001-00 077 103 383 BS 86 Ø MLS Zyl. 5 - 8 	T80002-00 077 103 385 D (10x) 	2x V32944-00 077 198 025 A 2x 	N90298-00 036 109 675 (20x) P76662-00 036 109 675	2x 40x	X58947-01 077 129 717 Q 2x 	X52312-01 077 253 039 C 2x 	70-31414-10 	P76443-01 K ← 55x68x8 A SL RD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN													
Ltr.			<b>1</b>										
4,2 BAR	257 kW (350 PS)	TOUAREG 7L 8 035 001→	06/06-05/10	<p><b>H80764-00</b> 079 103 383 AQ MLS Zyl. 1 - 4</p> <p><b>H80765-00</b> 079 103 383 AR MLS Zyl. 5 - 8</p>	<p><b>X59872-01 R</b> 079 103 484 C</p> <p><b>X59873-01 L</b> 079 103 483 T</p>	<p><b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675</p>	2x 32x	<p><b>X90076-01</b> 079 133 074 B</p> <p><b>X89852-01</b> <sup>(10)</sup> 079 129 717 B</p>	2x 8x	<p><b>X90075-01</b> 079 253 039 F</p>	2x	<p><b>70-31414-10</b></p>	<p><b>P77444-01 K</b> ← 079 103 051 G 55x72x8 A SL RD FPM <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM</p>
4,2 CGNA	265 kW (360 PS)	TOUAREG	01/11→	<p><b>H80764-00</b> 079 103 383 AQ MLS Zyl. 1 - 4</p> <p><b>H80765-00</b> 079 103 383 AR MLS Zyl. 5 - 8</p>	<p><b>X59872-01 R</b> 079 103 484 C</p> <p><b>X59873-01 L</b> 079 103 483 T</p>	<p><b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675</p>	2x 32x	<p><b>X89852-01</b> <sup>(10)</sup> 079 129 717 B</p>	8x	<p><b>X90075-01</b> 079 253 039 F</p>	2x	<p><b>70-31414-10</b></p>	<p><b>P77444-01 K</b> ← 079 103 051 G 55x72x8 A SL RD FPM <b>P77362-01 K</b> → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM</p>

VOLKSWAGEN

Ltr.    1

4,2 CKDA 250 kW (340 PS) TOUAREG TDI 01/10→

									
	<p><b>H40580-00</b> 057 103 383 HF 84 Ø 1,1 mm 1 <input type="checkbox"/> MLS Zyl. 1-4</p> <p><b>H40580-10</b> 057 103 383 HG 84 Ø 1,15 mm 2 <input type="checkbox"/> MLS Zyl. 1-4</p> <p><b>H40580-20</b> 057 103 383 HH 84 Ø 1,2 mm 3 <input type="checkbox"/> MLS Zyl. 1-4</p>  <p><b>H40581-00</b> 057 103 383 HJ 84 Ø 1,1 mm 1 <input type="checkbox"/> MLS Zyl. 5-8</p> <p><b>H40581-10</b> 057 103 383 HK 84 Ø 1,15 mm 2 <input type="checkbox"/> MLS Zyl. 5-8</p> <p><b>H40581-20</b> 057 103 383 HL 84 Ø 1,2 mm 3 <input type="checkbox"/> MLS Zyl. 5-8</p> 	<p><b>T80610-00</b> 057 103 384 A (10x)</p> 	<p>2x <b>X59505-01</b> 057 103 484 Zyl. 1-4</p>  <p><b>X59506-01</b> 057 103 483 J Zyl. 5-8</p> 	<p><b>N92990-00</b> 036 109 675 (16x)</p> <p><b>P76662-00</b> 036 109 675</p>	<p>2x <b>X59471-01 O</b> 057 129 717 H</p> <p>32x <b>X59472-01 U</b> 057 129 717 G</p> 		<p>2x <b>X59646-01</b> 057 253 039 K</p> <p><b>X59647-01</b> 057 253 039 K</p> 	<p>2x <b>70-31414-10</b></p> 	<p><b>P77765-01 K</b> ← 057 103 051 55x70x8 A SL RD FPM</p> <p><b>P77766-01 K</b> → 059 103 051 K 85x105x8 A SL LD FPM</p> <p><b>P77182-01 N</b> 028 103 086 32x47x10 A SL LD PTFE</p>



VOLKSWAGEN													
Ltr.			<b>1</b>		<p><b>H01856-00</b> 07Z 103 148 1  MLS Zyl. 1 - 5 <b>H11856-10</b> 07Z 103 148 A 2  MLS Zyl. 1 - 5 <b>H21856-20</b> 07Z 103 148 B 3  MLS Zyl. 1 - 5</p> <p><b>H01857-00</b> 07Z 103 149 1  MLS Zyl. 6 - 10 <b>H11857-10</b> 07Z 103 149 A 2  MLS Zyl. 6 - 10 <b>H21857-20</b> 07Z 103 149 B 3  MLS Zyl. 6 - 10</p>			<p><b>N92111-00</b> 027 109 675 (20x) <b>P76532-00</b> 027 109 675</p>	<p><b>X89186-01</b> 07Z 129 717 A</p>		<p><b>X81949-01</b> 07Z 253 039 D</p>	<p><b>70-31414-10</b></p>	<p><b>P77448-01 K</b> ← 07Z 103 051 93x114x10 AB SL LD PTFE <b>P77449-01 K</b> → 07Z 103 085 A 63x76x8,8 AB SL RD PTFE</p>
5,0 AJS AYH BLE BWF CBWA	230-257 kW (313-350 PS) PHAETON V10 TDI TOUAREG TDI	10/02→											
6,0 CFRA	331 kW (450 PS) TOUAREG W12	08/04-05/10		<p><b>H80732-00</b> 07C 103 148 T MLS Zyl. 1 - 6</p> <p><b>H80733-00</b> 07C 103 149 Q MLS Zyl. 7 - 12</p>	<p><b>T80732-00</b> 07D 103 384 A (14x) +07D 103 385 A (7x)</p>	<p>2x <b>X83346-01</b> 07C 103 484 C Zyl. 7-12</p> <p><b>X83347-01</b> 07C 103 483 C Zyl. 1-6</p>	<p>2x <b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675</p>	<p>48x</p>	<p><b>X81983-01</b> 07C 253 039 D</p>	<p>4x <b>70-31414-10</b></p>	<p><b>P77354-01 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM</p>		