

HONDA													
1,0 ECA1	50-56 kW (68-76 PS)	INSIGHT INSIGHT VTEC	04/00-12/06	<b>D40097-00</b> <sup>(12)</sup> 06110-PHM-000 <b>B37934-00</b> <sup>(13)</sup> 06111-PHM-000	<b>H40097-00</b> 12251-PHM-004 73 Ø MLS 		<b>X83324-01</b> 12341-PHM-000 	<b>N93047-01</b> 12210-PZ004 (6x) +12211-PZ1-004 (6x) 	<b>X89790-01</b> 17106-PHM-006 3x  <b>X89841-01</b> <sup>(10)</sup> 17146-PHM-004 		<b>X82305-01</b> 18115-PHM-004 	<b>E37934-00</b> 11251-PHM-000 +11252-PHM-000 	<b>P76115-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77565-01</b> K → 91214-PHM-003 65x88x10 A SL LD
1,2 ER1 ER2 ER4	33-41 kW (45-56 PS)	CITY JAZZ	11/80-10/86	<b>S37226-00</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PE8-000 +061B1-PC0-020 <b>D37226-00</b> <sup>(12)</sup> 061A1-PE8-000	<b>H80905-00</b> 12251-PC0-010 61,9 Ø 		<b>X83200-01</b> 12341-PC1-010 			<b>X82433-01</b> <sup>(7)</sup> 18115-PC0-014 		<b>X54871-01</b> 11251-PC0-014 	<b>P77585-01</b> K ← 91213-PH1-003 35x50x8 A SL RD NBR <b>P77510-01</b> K → 91214-634-004 74x98x12 A SL RD MVQ <b>P77600-01</b> N 91203-PG6-003 27x43x9 A SL LD NBR
1,2 L12A1	57-58 kW (78-79 PS)	CIVIC JAZZ	04/01-07/08	<b>D40511-00</b> <sup>(12)</sup> 06110-PWA-030 <b>B59319-00</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>H40511-00</b> 12251-PWA-J01 MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>V38233-00</b> 12341-PWA-000 	<b>N93139-00</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>M38234-00</b> 17105-PWA-007 (4x)  <b>X59320-01</b> <sup>(10)</sup> 17146-PWA-004 		<b>X59318-01</b> 18115-PWA-003 	<b>X59319-01</b> 11252-PWA-000  70-31414-10	<b>P76115-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1,2 L12A2 L12A3	58-61 kW (79-83 PS)	CITY	05/03→	<b>D40512-00</b> <sup>(12)</sup> 06110-REA-Z00 <b>B59319-00</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>H40512-00</b> 12251-REA-Z01 MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>V38233-00</b> 12341-PWA-000 	<b>N93139-00</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>M38234-00</b> 17105-PWA-007 (4x)  <b>X59320-01</b> <sup>(10)</sup> 17146-PWA-004 		<b>X59318-01</b> 18115-PWA-003 	<b>X59319-01</b> 11252-PWA-000  70-31414-10	<b>P76115-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1,2 L12B1	66 kW (90 PS)	JAZZ	07/08→	<b>D40603-00</b> <sup>(12)</sup> <sup>(19)</sup> 06110-RB0-010 <b>B59319-00</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>H40603-00</b> 12251-RB0-004 0,65 mm MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>X83414-01</b> 12341-RB0-003 ACM 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X83422-01</b> 17105-RB0-004  <b>M82547-00</b> <sup>(10)</sup> 17115-RB0-007 (4x) 		<b>X83423-01</b> 18115-RB0-007 	<b>X59319-01</b> 11252-PWA-000  70-31414-10	<b>P76115-00</b> K ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
1,2 ZA2	40 kW (54 PS)	CIVIC	01/84-10/87	<b>D80902-01</b> <sup>(12)</sup> 061A1-PE3-020 <b>B54868-00</b> <sup>(13)</sup> 061B1-PE0-010	<b>H80902-10</b> 12251-PE3-014 74,5 Ø 		<b>X83197-01</b> 12341-PE0-000 		<b>X89620-01</b> 17105-PE1-650 		<b>X82146-01</b> 18110-PE0-010 	2x <b>X54868-01</b> 11251-PE0-020 	<b>P77671-01</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR

HONDA													
1,3 D13B1 D13B2	55 kW (75 PS)	CIVIC	10/87-11/95	<b>S80906-00</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PM3-000 +061B14-PM3-000 <b>D80906-00</b> <sup>(12)</sup> 061A1-PM3-000	<b>H80906-00</b> 12251-PM3-003 75,5 Ø 		<b>X83204-01</b> 12341-PM6-010 	<b>N93046-00</b> 12210-PT2-004 (8x) +12211-PT2-004 (8X) 	<b>X89616-01</b> 17105-PM3-004 		<b>X82144-01</b> 18115-PM3-003 	<b>X54868-01</b> 11251-PE0-020 	<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,3 D13B7	48 kW (65 PS)	LOGO	03/99-03/02	<b>D40101-00</b> <sup>(12)</sup> 06110-P7A-G00 <b>B54918-00</b> <sup>(13)</sup> 06111-P7A-G00	<b>H40101-00</b> 12251-P7A-G01 76 Ø 0,65 mm MLS 		<b>V83228-00</b> 12030-P2A-000 		<b>X89793-01</b> 17105-P7A-004 		<b>X82308-01</b> 18115-PEJ-004 	<b>X54919-01</b> 11251-P1J-E00 	<b>P77563-01 K</b> ← 91212-P7A-004 31x46x7 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,3 EN1 EN2 EN4	33-52 kW (45-71 PS)	CIVIC	09/79-12/84	<b>D80899-00</b> <sup>(12)</sup> 061A1-PA1-026 <b>B54868-00</b> <sup>(13)</sup> 061B1-PE0-010	<b>H80899-10</b> 12251-642-020 74 Ø 		<b>X83196-01</b> 12341-PA1-000 		<b>X89968-01</b> 2x 17105-634-000 		<b>X82141-01</b> 4x 18110-PA1-000 	<b>X54868-01</b> 11251-PE0-020 	<b>P77585-01 K</b> ← 91213-PH1-003 35x50x8 A SL RD NBR <b>P77510-01 K</b> → 91214-634-004 74x98x12 A SL RD MVQ <b>P77600-01 N</b> 91203-PG6-003 27x43x9 A SL LD NBR
1,3 EV2	52 kW (71 PS)	CIVIC CRX	08/83-12/87	<b>D80902-01</b> <sup>(12)</sup> 061A1-PE3-020 <b>B54868-00</b> <sup>(13)</sup> 061B1-PE0-010	<b>H80902-10</b> 12251-PE3-014 74,5 Ø 		<b>X83197-01</b> 12341-PE0-000 		<b>X89620-01</b> 17105-PE1-650 		<b>X82146-01</b> 2x 18110-PE0-010 	<b>X54868-01</b> 11251-PE0-020 	<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,3 L13A1 L13A7 L13A8	61-85 kW (83-116 PS)	CITY CIVIC FIT JAZZ JAZZ DSI	03/02→	<b>D40511-00</b> <sup>(12)</sup> 06110-PWA-030 <b>B59319-00</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>H40511-00</b> 12251-PWA-J01 MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>V38233-00</b> 12341-PWA-000 	<b>N93139-00</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>M38234-00</b> 17105-PWA-007 (4x)  <b>X59320-01</b> <sup>(10)</sup> 17146-PWA-004 		<b>X59318-01</b> 18115-PWA-003 	<b>X59319-01</b> 11252-PWA-000  70-31414-10 	<b>P76115-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR
1,3 L13A3 L13A5	60-65 kW (82-88 PS)	CITY	10/05→	<b>D40512-00</b> <sup>(12)</sup> 06110-REA-Z00 <b>B59319-00</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>H40512-00</b> 12251-REA-Z01 MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>V38233-00</b> 12341-PWA-000 	<b>N93139-00</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>M38234-00</b> 17105-PWA-007 (4x)  <b>X59320-01</b> <sup>(10)</sup> 17146-PWA-004 		<b>X59318-01</b> 18115-PWA-003 	<b>X59319-01</b> 11252-PWA-000  70-31414-10 	<b>P76115-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR

HONDA												
Ltr.												
1,3 L13Z1	73 kW (100 PS) JAZZ	07/08→	<b>D40603-00</b> <sup>(12)</sup> <sup>(19)</sup> 06110-RB0-010 <b>B59319-00</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>H40603-00</b> 12251-RB0-004 0,65 mm MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>X83414-01</b> 12341-RB0-003 ACM 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X83422-01</b> 17105-RB0-004 <b>M82547-00</b> <sup>(10)</sup> 17115-RB0-007 (4x) 	<b>X83423-01</b> 18115-RB0-007 	<b>X59319-01</b> 11252-PWA-000 <b>70-31414-10</b> 	<b>P76115-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR	
1,4 D14A3 D14A4	55-66 kW (75-90 PS) CIVIC	11/95-02/01	<b>D40095-00</b> <sup>(12)</sup> 06110-P2A-030	<b>H40095-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>V83228-00</b> 12030-P2A-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89783-01</b> 17105-P2A-014 	<b>X82302-01</b> 18115-P2A-004 	<b>X54919-01</b> 11251-P1J-E00 	<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,4 D14A7 D14A8	55-66 kW (75-90 PS) CIVIC CONCERTO	08/89-02/01	<b>D40095-01</b> <sup>(12)</sup> 06110-P1J-E00 <b>B54919-01</b> <sup>(13)</sup> 06111-P2A-010	<b>H40095-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>V83228-00</b> 12030-P2A-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>M38276-00</b> 17105-P1J-E01 (3x) +17106-P1J-E01 (1x) 	<b>X82302-01</b> 18115-P2A-004 	<b>X54919-01</b> 11251-P1J-E00 	<b>P77736-01 K</b> ← 91212-P01-003 31x46x7 A SL LD <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,4 D14Z1	55 kW (75 PS) CIVIC	11/95-02/01	<b>D40095-00</b> <sup>(12)</sup> 06110-P2A-030	<b>H40095-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 		<b>V83228-00</b> 12030-P2A-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89783-01</b> 17105-P2A-014 	<b>X82302-01</b> 18115-P2A-004 	<b>X54919-01</b> 11251-P1J-E00 	<b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,4 D14Z5 D14Z6	55-66 kW (75-90 PS) CIVIC	12/00-09/05	<b>D40096-02</b> <sup>(12)</sup> 06110-PSM-E00 <b>B54919-00</b> <sup>(13)</sup> 06111-PSG-Y10	<b>H40096-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 		<b>V38003-00</b> 123030-PLC-010 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89794-01</b> 4x 17105-PLA-G01  <b>X89843-01</b> <sup>(10)</sup> 17055-PLD-004 	<b>X82304-01</b> 18115-PLC-J01 	<b>X54919-01</b> 11251-P1J-E00 	<b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,4 L13Z1	73-74 kW (99-101 PS) CITY CIVIC JAZZ	09/08→	<b>D40603-00</b> <sup>(12)</sup> <sup>(19)</sup> 06110-RB0-010 <b>B59319-00</b> <sup>(13)</sup> 06111-PWA-010 +06114-PWA-000	<b>H40603-00</b> 12251-RB0-004 0,65 mm MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>X83414-01</b> 12341-RB0-003 ACM 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X83422-01</b> 17105-RB0-004 <b>M82547-00</b> <sup>(10)</sup> 17115-RB0-007 (4x) 	<b>X83423-01</b> 18115-RB0-007 	<b>X59319-01</b> 11252-PWA-000 <b>70-31414-10</b> 	<b>P76115-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR	

HONDA														
1,5 D15A1	63 kW (86 PS)	INTEGRA	10/85-08/89	<b>D80902-01</b> <sup>12</sup> 061A1-PE3-020 <b>B54868-00</b> <sup>13</sup> 061B1-PE0-010	<b>H80902-10</b> 12251-PE3-014 74,5 Ø 									<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,5 D15B2	61-74 kW (83-101 PS)	CIVIC CONCERTO	10/87-12/95	<b>S80906-01</b> <sup>12</sup> <sup>13</sup> 061A1-PM6-000 +061B1-PM3-000 <b>D80906-01</b> <sup>12</sup> 061A1-PM6-000	<b>H80906-00</b> 12251-PM3-003 75,5 Ø 									<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,5 D15B7	74-77 kW (101-105 PS)	CITY CIVIC CRX	08/93-09/03	<b>S80965-00</b> <sup>12</sup> <sup>13</sup> 06110-PO3-000 +06111-PO7-000 <b>D80965-00</b> <sup>12</sup> 06110-PO3-000	<b>H80965-00</b> 12251-PM5-S02 75,5 Ø 									<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,5 D15Z1	69-88 kW (94-120 PS)	CIVIC	10/91-11/95	<b>S80967-00</b> <sup>12</sup> <sup>13</sup> 06110-PO8-000 +06111-PO8-000 <b>D80967-00</b> <sup>12</sup> 06110-PO8-000	<b>H80967-00</b> 12251-PO8-004 75,8 Ø MLS 									<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
1,5 D15Z3	66 kW (90 PS)	CIVIC CIVIC VTEC-E	09/94-01/97	<b>D40095-00</b> <sup>12</sup> 06110-P2A-030	<b>H40095-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 									<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> ← 91213-PE1-721 29x45x8 A SL LD NBR

HONDA													
Ltr.													
1,5 EW2	63 kW (86 PS) CIVIC	10/83-10/87	<b>D80902-01</b> <sup>12</sup> 061A1-PE3-020 <b>B54868-00</b> <sup>13</sup> 061B1-PE0-010	<b>H80902-10</b> 12251-PE3-014 74,5 Ø 		<b>X83197-01</b> 12341-PE0-000 	<b>N93023-00</b> 12211-PE0-004 (12x)	<b>X89620-01</b> 17105-PE1-650 		<b>X82146-01</b> 18110-PE0-010 	2x <b>X54868-01</b> 11251-PE0-020 	<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,5 EW3 EW4	66-74 kW (90-101 PS) CIVIC CRX	10/83-10/87	<b>D80902-00</b> <sup>12</sup> 061A1-PE7-020	<b>H80902-10</b> 12251-PE3-014 74,5 Ø 		<b>X83199-01</b> 12341-PE2-003 		<b>X89620-01</b> 17105-PE1-650 		<b>X82146-01</b> 18110-PE0-010 	2x <b>X54868-01</b> 11251-PE0-020 	<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,5 L15A1	70-79 kW (95-107 PS) CITY	09/04→	<b>D40605-00</b> <sup>12</sup> <sup>19</sup> 06110-REB-Z01 <b>B59319-00</b> <sup>13</sup> 06111-PWA-010 +06114-PWA-000	<b>H40605-00</b> 12251-REB-Z01 0,85 mm MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>V83416-00</b> 12030-PWC-000 ACM 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>M38234-00</b> 17105-PWA-007 (4x)  <b>X59320-01</b> <sup>10</sup> 17146-PWA-004 		<b>X59318-01</b> 18115-PWA-003 	<b>X59319-01</b> 11252-PWA-000  <b>70-31414-10</b> 	<b>P76115-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR	
1,5 L15A2 L15A3	81-88 kW (110-120 PS) JAZZ	07/08→	<b>D40512-00</b> <sup>12</sup> 06110-REA-Z00 <b>B59319-00</b> <sup>13</sup> 06111-PWA-010 +06114-PWA-000	<b>H40512-00</b> 12251-REA-Z01 MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>V38233-00</b> 12341-PWA-000 	<b>N93139-00</b> 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	<b>M38234-00</b> 17105-PWA-007 (4x)  <b>X59320-01</b> <sup>10</sup> 17146-PWA-004 		<b>X59318-01</b> 18115-PWA-003 	<b>X59319-01</b> 11252-PWA-000  <b>70-31414-10</b> 	<b>P76115-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR	
1,5 L15A7	88 kW (120 PS) CITY JAZZ	07/08→	<b>D40603-00</b> <sup>12</sup> <sup>19</sup> 06110-RB0-010 <b>B59319-00</b> <sup>13</sup> 06111-PWA-010 +06114-PWA-000	<b>H40603-00</b> 12251-RB0-004 0,65 mm MLS 	<b>T40512-00</b> 90008-PWA-003 (10x) 	<b>X83414-01</b> 12341-RB0-003 ACM 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X83422-01</b> 17105-RB0-004  <b>M82547-00</b> <sup>10</sup> 17115-RB0-007 (4x) 		<b>X83423-01</b> 18115-RB0-007 	<b>X59319-01</b> 11252-PWA-000  <b>70-31414-10</b> 	<b>P76115-00 K</b> ← 91212-PWA-003 40x55x8 A SL RD MVQ <b>P77526-01 K</b> → 91214-PWA-003 80x98x10 A SL LD NBR	
1,6 B16A1	110 kW (150 PS) CIVIC VTEC CRX VTEC	10/89-02/92	<b>D40056-00</b> <sup>12</sup> 061A1-PR3-305	<b>H40056-00</b> 12251-P30-014 81,5 Ø 0,6 mm MLS 		<b>V37993-00</b> 12030-PR3-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89765-01</b> 17105-P30-004 		<b>X82284-01</b> 18115-P30-003 		<b>P77600-01 N</b> 2x 91203-PG6-003 27x43x9 A SL LD NBR	

HONDA													
1,6 D16A6 D16A7	79-96 kW (107-130 PS)	CIVIC CRX	09/87-10/95	<b>S80965-00</b> <sup>(12)</sup> <sup>(13)</sup> 06110-PO3-000 +06111-PO7-000 <b>D80965-00</b> <sup>(12)</sup> 06110-PO3-000	<b>H80965-00</b> 12251-PM5-S02 75,5 Ø 	<b>V37946-00</b> 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89621-01</b> 17105-PO0-T02 		<b>X82144-01</b> 18115-PM3-003 	<b>X54868-01</b> 11251-PE0-020 	<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,6 D16A8 D16A9 D16Z5	90-96 kW (122-131 PS)	CIVIC CONCERTO CRX	09/87-03/95	<b>S80968-00</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PM7-G00 +061B1-PM7-000 <b>D80968-00</b> <sup>(12)</sup> 061A1-PM7-G00	<b>H80968-00</b> 12251-PM7-003 75,5 Ø 	<b>X83229-01</b> 12341-PM7-000 	<b>N93050-00</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x)			<b>X82144-01</b> 18115-PM3-003 	<b>X54868-01</b> 11251-PE0-020 	<b>P77600-01 N</b> 91203-PG6-003 27x43x9 A SL LD NBR	
1,6 D16V1	81 kW (110 PS)	CIVIC	02/01-12/05	<b>D40096-02</b> <sup>(12)</sup> 06110-PSM-E00 <b>B37209-00</b> <sup>(13)</sup> 06111-PMM-A01	<b>H40096-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 	<b>V38003-00</b> 123030-PLC-010 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89794-01</b> 4x 17105-PLA-G01  <b>X89843-01</b> <sup>(10)</sup> 17055-PLD-004 		<b>X82304-01</b> 18115-PLC-J01 	<b>70-31414-10</b> 	<b>P77731-01 K</b> ← 91212-PLC-003 38x50x7 A SL LD <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,6 D16W5	91 kW (124 PS)	HR-V	10/99→	<b>D40095-00</b> <sup>(12)</sup> 06110-P2A-030 01/03→	<b>H40095-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 	<b>V83228-00</b> 12030-P2A-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89783-01</b> 17105-P2A-014 		<b>X82302-01</b> 18115-P2A-004 		<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	
1,6 D16Y7	77-79 kW (105-107 PS)	CIVIC	01/94-03/00	<b>D40095-00</b> <sup>(12)</sup> 06110-P2A-030	<b>H40095-00</b> 12251-P2J-004 76 Ø 0,7 mm MLS 	<b>V83228-00</b> 12030-P2A-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89783-01</b> 17105-P2A-014 		<b>X82302-01</b> 18115-P2A-004 	<b>X54919-01</b> 11251-P1J-E00 	<b>P77736-01 K</b> ← 91212-P01-003 31x46x7 A SL LD <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> ← 91213-PE1-721 29x45x8 A SL LD NBR	
1,6 D16Z2	78-82 kW (106-112 PS)	CIVIC CONCERTO DOMANI	10/87-12/97	<b>D80906-01</b> <sup>(12)</sup> 061A1-PM6-000	<b>H80906-00</b> 12251-PM3-003 75,5 Ø 	<b>X83204-01</b> 12341-PM6-010 	<b>N93046-00</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x)	<b>X89621-01</b> 17105-PO0-T02 		<b>X82144-01</b> 18115-PM3-003 	<b>X54868-01</b> 11251-PE0-020 	<b>P77671-01 K</b> ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR	

HONDA													
1,6 D16Z6 D16Z7 D16Z9	92-96 kW (125-131 PS)	CIVIC CIVIC VTEC CRX	10/91-12/98	<b>S80967-00</b> <sup>(12)</sup> <sup>(13)</sup> 06110-PO8-000 +06111-PO8-000 <b>D80967-00</b> <sup>(12)</sup> 06110-PO8-000	<b>H80967-00</b> 12251-PO8-004 75,8 Ø MLS 		<b>V83228-00</b> 12030-P2A-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89642-01</b> 17105-PO7-004  <b>X89826-01</b> <sup>(10)</sup> 17105-PO8-004 		<b>X82147-01</b> 18115-PO0-004 	<b>X54868-01</b> 11251-PE0-020 	<b>P77671-01</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,6 EY	65 kW (88 PS)	ACCORD	11/85-12/89	<b>D80903-01</b> <sup>(12)</sup> 061A1-PC7-660 <b>B54872-00</b> <sup>(13)</sup> 061B1-PD2-000	<b>H80903-10</b> 12251-PD6-013 81 Ø 		<b>X83205-01</b> 12341-PH4-000 		<b>X89656-01</b> 17105-PD2-000 		<b>X82187-01</b> 18115-PD2-000  <b>X82188-01</b> 18116-PD2-000 	2x <b>X54872-01</b> 11251-PC6-010 	<b>P77487-01</b> K ← 91212-PC6-003 35x54x8 A SL LD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,6 EZ	65 kW (88 PS)	ACCORD	09/83-10/85	<b>S80903-00</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PC7-660 +061B1-PC7-660 <b>D80903-01</b> <sup>(12)</sup> 061A1-PC7-660 <b>B54872-00</b> <sup>(13)</sup> 061B1-PD2-000	<b>H80903-10</b> 12251-PD6-013 81 Ø 		<b>X83205-01</b> 12341-PH4-000 		<b>X89656-01</b> 17105-PD2-000 		<b>X82187-01</b> 18115-PD2-000  <b>X82188-01</b> 18116-PD2-000 	2x <b>X54872-01</b> 11251-PC6-010 	<b>P77487-01</b> K ← 91212-PC6-003 35x54x8 A SL LD MVQ <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR
1,6 ZC1	92 kW (125 PS)	CRX	03/86-10/87	<b>D40648-00</b> <sup>(12)</sup> 061A1-PJ1-000	<b>H40648-00</b> 12251-PG6-003 75,5 Ø 		<b>X83229-01</b> 12341-PM7-000 	<b>N93050-00</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x)	<b>X89617-01</b> 17105-PG6-010 		<b>X82144-01</b> 18115-PM3-003 		<b>P77671-01</b> K ← 91212-PD6-A01 31x46x8 A SL LD NBR <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77600-01</b> N 91203-PG6-003 27x43x9 A SL LD NBR
1,7 D17A2	92 kW (125 PS)	EDIX FR-V STREAM	05/01→	<b>D40096-01</b> <sup>(12)</sup> 06110-RJH-000 <b>B37209-00</b> <sup>(13)</sup> 06111-PMM-A01	<b>H40096-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 		<b>V38003-00</b> 123030-PLC-010 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89789-01</b> 17105-PMR-A01  <b>X89843-01</b> <sup>(10)</sup> 17055-PLD-004 	4x	<b>X82304-01</b> 18115-PLC-J01 	<b>70-31414-10</b> 	<b>P77731-01</b> K ← 91212-PLC-003 38x50x7 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR

HONDA														
Ltr.														
1,7 D17A5	92 kW (125 PS)	CIVIC VTEC	05/01-12/05	<b>D40096-00</b> ⑫ 06110-PLL-Y01 <b>B54919-00</b> ⑬ 06111-PSG-Y10	<b>H40096-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 		<b>V38003-00</b> 123030-PLC-010 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89784-01</b> 17055-PLC-004  <b>X89789-01</b> 17105-PMR-A01 4x 		<b>X82304-01</b> 18115-PLC-J01 	<b>X54919-01</b> 11251-P1J-E00 	<b>P77731-01</b> K ← 91212-PLC-003 38x50x7 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR	
1,7 D17A8	88 kW (120 PS)	CIVIC	05/01-12/05	<b>D40096-00</b> ⑫ 06110-PLL-Y01 <b>B37209-00</b> ⑬ 06111-PMM-A01	<b>H40096-00</b> 12251-PLC-003 76 Ø 0,73 mm MLS 		<b>V38003-00</b> 123030-PLC-010 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89784-01</b> 17055-PLC-004  <b>X89789-01</b> 17105-PMR-A01 4x 		<b>X82304-01</b> 18115-PLC-J01 	<b>70-31414-10</b> 	<b>P77731-01</b> K ← 91212-PLC-003 38x50x7 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR	
1,7 4EE-2	74 kW (100 PS)	CIVIC CTDi	01/02-09/05	<b>D37122-00</b> ⑫  <b>B37122-00</b> ⑬	<b>H08698-00</b> 12251-PLZ-D00 1,45 mm 1 MLS <b>H18698-10</b> 12251-PLZ-D10 1,5 mm 2 MLS <b>H28698-20</b> 12251-PLZ-D20 80 Ø 1,55 mm 3 MLS 	<b>T07916-00</b> 	<b>X83101-01</b> 12341-PLZ-D00 	<b>N92990-00</b> 12211-PLZ-D00 (16x) <b>P76662-00</b> 12211-PLZ-D00 16x	<b>X89160-01</b> 17105-PLZ-D00 		<b>X81516-01</b> 18115-PLZ-D00 	<b>70-31414-10</b> 	<b>P77427-01</b> K ← 91220-PLZ-D00 40x52x6 A SL RD FPM <b>P76373-01</b> K → 91220-PLZ-D10 87x100x8 A SL LD ACM <b>P76130-01</b> N 91214-PLZ-D00 38x50x8 A SL RD FPM	
1,8 B18C4 B18C6	124-140 kW (169-190 PS)	CIVIC INTEGRA Type-R	01/97-10/01		<b>H40056-00</b> 12251-P30-014 81,5 Ø 0,6 mm MLS 		<b>V37993-00</b> 12030-PR3-000 					<b>X82284-01</b> 18115-P30-003 		
1,8 ET1	74 kW (101 PS)	ACCORD	09/83-10/85	<b>S80903-00</b> ⑫ ⑬ 061A1-PC7-660 +061B1-PC7-660 <b>D80903-01</b> ⑫ 061A1-PC7-660 <b>B54872-00</b> ⑬ 061B1-PD2-000	<b>H80903-10</b> 12251-PD6-013 81 Ø 		<b>X83205-01</b> 12341-PH4-000 	<b>N93007-00</b> 12210-PC1-003 (4x) +12211-PE0-004 (8x)	<b>X89656-01</b> 17105-PD2-000 		<b>X82187-01</b> 18115-PD2-000  <b>X82188-01</b> 18116-PD2-000 	<b>X54872-01</b> 11251-PC6-010 2x 	<b>P77487-01</b> K ← 91212-PC6-003 35x54x8 A SL LD MVQ <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR	



HONDA													
Ltr.			<b>1</b>										
1,8 ET2 ET3 ET4	74-77 kW (101-105 PS) PRELUDE	11/83-04/87	<b>S80903-00</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PC7-660 +061B1-PC7-660 <b>D80903-01</b> <sup>(12)</sup> 061A1-PC7-660	<b>H80903-10</b> 12251-PD6-013 81 Ø 	<b>X83205-01</b> 12341-PH4-000 	<b>N93007-00</b> 12210-PC1-003 (4x) +12211-PE0-004 (8x)	<b>X89658-01</b> 17105-PC7-000 		<b>X82187-01</b> 18115-PD2-000 	<b>X82188-01</b> 18116-PD2-000 	<b>X54872-01</b> 11251-PC6-010 	<b>P77487-01</b> K ← 91212-PC6-003 35x54x8 A SL LD MVQ <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR	
1,8 F18B2	100 kW (136 PS) ACCORD	10/98-12/02	<b>D40098-01</b> <sup>(12)</sup> 06110-PDA-E00 <b>B37212-00</b> <sup>(13)</sup> 06111-PAA-A01 	<b>H40098-00</b> 12251-POA-004 86 Ø 0,7 mm MLS 	<b>T40100-00</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>V38006-00</b> 12030-POA-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X59451-01</b> 17105-POA-A02 	<b>X82512-01</b> 18115-PAA-L21 	<b>70-31414-10</b> 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ		
1,8 R18A1 R18A2	103 kW (140 PS) CIVIC CROSSROAD FR-V STREAM VTEC	09/05→	<b>D38243-00</b> <sup>(12)</sup> 06110-RNA-000 +06114-RNA-010	<b>H40531-00</b> 12251-RNA-A02 MLS 	<b>T40531-00</b> 90005-RNA-A01 (10x) 	<b>X59333-01</b> 12341-RNA-A01 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>M38245-00</b> 17105-RNA-A01 (4x) +17106-RNA-A01 (1x)  <b>M38260-00</b> <sup>(10)</sup> 17103-RNA-A01 (2x) +17104-RNA-A01 (4x) 	<b>X59334-01</b> 18115-RNA-004 	<b>70-31414-10</b> 	<b>P77720-01</b> K ← 91212-RNA-A01 43x58x7 A SL RD FPM <b>P77526-01</b> K → 91214-PWA-003 80x98x10 A SL LD NBR		
1,8 XUD7T	58 kW (79 PS) CITY D	02/97-11/99	<b>S31587-00</b> <sup>(12)</sup> <sup>(13)</sup>  <b>D31587-00</b> <sup>(12)</sup>  <b>B30527-00</b> <sup>(13)</sup>	<b>H02299-00</b> 1,6 mm 2 <b>H12299-10</b> 82 Ø 1,75 mm 3 	<b>T08280-00</b> 	<b>X07796-01</b> 	<b>N90300-00</b> <b>P76531-00</b> 8x		<b>X51239-01</b> <sup>(7)</sup> 	<b>X03013-01</b> <sup>(A)</sup> 	<b>X04848-01</b> NBR <b>X07793-01</b> 	<b>P76151-01</b> K ← 42x62x7 A RD FPM <b>P76386-01</b> K → 90x110x7 A SL LD FPM <b>P76099-11</b> N 35x50x8 A SL WD FPM 2x	
2,0 A20A1 A20A2 A20A3	75-85 kW (102-116 PS) ACCORD	11/85-12/89	<b>D80907-00</b> <sup>(12)</sup> 061A1-PJ0-000 →12/87 <b>D80907-01</b> <sup>(12)</sup> 061A1-PJ0-A00 01/88→	<b>H80907-00</b> 12251-PH4-003 86 Ø 	<b>X83205-01</b> 12341-PH4-000 	<b>N93007-00</b> 12210-PC1-003 (4x) +12211-PE0-004 (8x)	<b>X89618-01</b> 17105-PH3-000 		<b>X82187-01</b> 18115-PD2-000 	<b>X82188-01</b> 18116-PD2-000 	<b>X82318-01</b> <sup>(A)</sup> 18212-SA0-003 →12/87 	<b>X54872-01</b> 11251-PC6-010 	<b>P77487-01</b> K ← 91212-PC6-003 35x54x8 A SL LD MVQ 01/88→ <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01</b> N 91213-PE1-721 29x45x8 A SL LD NBR

HONDA												
Ltr. 2,0 A20A4 90 kW (122 PS) ACCORD	 11/85-12/87	 ACCORD	 <b>D80907-00</b> <sup>12</sup> 061A1-PJ0-000	 <b>H80907-00</b> 12251-PH4-003 86 Ø 	 <b>X83205-01</b> 12341-PH4-000 	 <b>N93007-00</b> 12210-PC1-003 (4x) +12211-PE0-004 (8x)	 <b>X89618-01</b> 17105-PH3-000 	 <b>X82187-01</b> 18115-PD2-000 	 <b>X82188-01</b> 18116-PD2-000 	 <b>X82318-01</b> <sup>A</sup> 18212-SA0-003 	 <b>X54872-01</b> 11251-PC6-010 	 <b>P77487-01 K</b> ← 91212-PC6-003 35x54x8 A SL LD MVQ <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR
2,0 B20A1 B20A2 B20A8 98-101 kW (133-137 PS) ACCORD PRELUDE	04/86-12/89	ACCORD PRELUDE	<b>D80908-00</b> <sup>12</sup> 061A1-PH3-000	<b>H80908-00</b> 12251-PH3-023 82,5 Ø 	<b>V37945-00</b> 12341-PK2-000 +12342-PG6-000 (4x) 	<b>X89618-01</b> 17105-PH3-000 	<b>X82145-01</b> 18115-PK2-000 	<b>X54873-01</b> 11251-PH3-000 	<b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77600-01 N</b> 2x 91203-PG6-003 27x43x9 A SL LD NBR			
2,0 B20A5 B20A7 B20A9 101-110 kW (137-150 PS) PRELUDE	04/87-01/92	PRELUDE	<b>D80909-00</b> <sup>12</sup> 061A1-PK2-660	<b>H80909-00</b> 12251-PK1-662 82 Ø 	<b>V37945-00</b> 12341-PK2-000 +12342-PG6-000 (4x) 	<b>X89659-01</b> 17105-PK3-A00 	<b>X82145-01</b> 18115-PK2-000 	<b>X82319-01</b> <sup>A</sup> 2x 18212-SB2-961 	<b>X54874-01</b> 11251-PK1-010 	<b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77604-01 N</b> 91213-PE1-721 29x45x8 A SL LD NBR		
2,0 B20B B20B3 B20Z1 94-108 kW (128-147 PS) CR-V	10/95→	CR-V	<b>D38244-00</b> <sup>12</sup> 06110-P3F-902	<b>H40532-00</b> 12251-P8R-004 MLS 	<b>V38244-00</b> 12030-PR4-000 	<b>N93050-00</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x)	<b>X59335-01</b> 17105-PHK-004 	<b>X82190-01</b> 18115-PR3-003 	<b>X54897-01</b> 11251-PR3-000 	<b>P77733-01 K</b> ← 91212-PR3-003 38x50x7,4 A SL LD FPM <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77600-01 N</b> 2x 91203-PG6-003 27x43x9 A SL LD NBR		
2,0 F20A2 F20A4 F20A6 F20A7 F20A8 F20Z3 66-98 kW (90-133 PS) ACCORD PRELUDE	01/90-10/00	ACCORD PRELUDE	<b>S80970-00</b> <sup>12</sup> <sup>13</sup> 061A1-PT3-000 +061B1-PT3-000 <b>D80970-00</b> <sup>12</sup> 061A1-PT3-000	<b>H80970-00</b> 12251-PT0-J02 86 Ø MLS 	<b>V38004-00</b> 12030-PT0-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89657-01</b> 17105-PT2-004 	<b>X82310-01</b> 18115-PT0-004 	<b>X54896-01</b> 11251-PT0-000 	<b>P77594-01 K</b> ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01 N</b> 91213-PT0-003 28x42x8 A SL LD MVQ		

HONDA													
Ltr.													
2,0 F20B3	100 kW (136 PS)	ACCORD	09/93-02/98	<b>D40098-00</b> ⑫ 06110-POD-030 <b>B54917-00</b> ⑬ 06111-PT1-010	<b>H40098-00</b> 12251-P0A-004 86 Ø 0,7 mm MLS 	<b>T40098-00</b> 90005-PT0-003 (9x) +90006-PT0-003 (1x)	<b>V38004-00</b> 12030-PT0-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89791-01</b> 17105-P0A-004 		<b>X82306-01</b> 18115-P0A-003 	<b>X54896-01</b> 11251-PT0-000 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,0 F20B5	108 kW (147 PS)	ACCORD	02/98-06/03	<b>D40098-02</b> ⑫ 06110-PAD-G00 <b>B37212-00</b> ⑬ 06111-PAA-A01 	<b>H40098-00</b> 12251-P0A-004 86 Ø 0,7 mm MLS 	<b>T40100-00</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>V38006-00</b> 12030-P0A-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>M37919-00</b> 17105-PAA-A01 		<b>X82306-01</b> 18115-P0A-003 	<b>70-31414-10</b> 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,0 F20B7	107-108 kW (145-147 PS)	ACCORD	02/98-06/03	<b>D40098-02</b> ⑫ 06110-PAD-G00 <b>B37212-00</b> ⑬ 06111-PAA-A01 	<b>H40098-00</b> 12251-P0A-004 86 Ø 0,7 mm MLS 	<b>T40100-00</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>V38006-00</b> 12030-P0A-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89792-01</b> 17105-PAA-L01 		<b>X82306-01</b> 18115-P0A-003 	<b>70-31414-10</b> 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,0 F20C VTEC	177 kW (240 PS)	S2000	06/99→	<b>D40094-00</b> ⑫ 06110-PCX-020 <b>B77561-00</b> ⑬ 06111-PCX-020 	<b>H40094-00</b> 12251-PCX-004 88 Ø 0,65 mm MLS 		<b>V38002-00</b> 12040-PCX-305 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89782-01</b> 17105-PCX-004 		<b>X82301-01</b> 18115-PCX-004 	<b>70-31414-10</b> 	<b>P77562-01</b> K ← 91212-PCX-003 43x58x8 A SL RD FPM <b>P77561-01</b> K → 91214-PCX-003 80x98x10 A SL LD MVQ
2,0 F20C1	170 kW (231 PS)	S 2000 VTEC	03/99-10/03	<b>D40094-00</b> ⑫ 06110-PCX-020 <b>B77561-00</b> ⑬ 06111-PCX-020 	<b>H40094-00</b> 12251-PCX-004 88 Ø 0,65 mm MLS 	<b>T40100-01</b> 90005-PCX-003 (10x) 	<b>V38002-00</b> 12040-PCX-305 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89782-01</b> 17105-PCX-004 		<b>X82301-01</b> 18115-PCX-004 	<b>70-31414-10</b> 	<b>P77562-01</b> K ← 91212-PCX-003 43x58x8 A SL RD FPM <b>P77561-01</b> K → 91214-PCX-003 80x98x10 A SL LD MVQ

HONDA													
Ltr.													
2,0 F20Z1	96 kW (131 PS)	ACCORD	03/93-10/98	<b>D80970-01</b> ⑫ 06110-PT5-020 <b>B54917-00</b> ⑬ 06111-PT1-010	<b>H80970-00</b> 12251-PT0-J02 86 Ø MLS 		<b>V38004-00</b> 12030-PT0-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89657-01</b> 17105-PT2-004 		<b>X82310-01</b> 18115-PT0-004 	<b>X54896-01</b> 11251-PT0-000 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,0 F20Z2	85 kW (116 PS)	ACCORD	03/93-01/96	<b>D80970-01</b> ⑫ 06110-PT5-020 <b>B54917-00</b> ⑬ 06111-PT1-010	<b>H80970-00</b> 12251-PT0-J02 86 Ø MLS 	<b>T40098-00</b> 90005-PT0-003 (9x) +90006-PT0-003 (1x)	<b>V38004-00</b> 12030-PT0-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89795-01</b> 17105-PT2-014 		<b>X82310-01</b> 18115-PT0-004 	<b>X54896-01</b> 11251-PT0-000 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,0 K20A1	115 kW (156 PS)	STREAM	05/01→	<b>D40104-00</b> ⑫ 06110-PNA-020 <b>B77567-00</b> ⑬ 06114-RBA-020 	<b>H40104-00</b> 12251-PNA-004 86,5 Ø 0,6 mm MLS 	<b>T40104-00</b> 90005-PNA-003 (10x) 	<b>V38008-00</b> 12030-PNC-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89796-01</b> 17105-PNA-J01  <b>X89845-01</b> ⑩ 17055-PNA-004 		<b>X82312-01</b> 18115-PNA-004 →12/03  <b>X82311-01</b> 18115-PRB-A01 01/04→ 	<b>70-31414-10</b> 	<b>P77567-01</b> K ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>P77526-01</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
2,0 K20A6 <b>[NEW]</b>	114 kW (155 PS)	ACCORD	02/03-05/08	<b>D40103-00</b> ⑫ 06110-RBA-E01 <b>B77567-00</b> ⑬ 06114-RBA-020 	<b>H40103-00</b> 12251-RAC-004 87 Ø 0,68 mm MLS 	<b>T40104-00</b> 90005-PNA-003 (10x) 	<b>V38008-00</b> 12030-PNC-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X37920-01</b> 17115-RAA-A01 		<b>X82311-01</b> 18115-PRB-A01 	<b>70-31414-10</b> 	<b>P77720-01</b> K ← 91212-RNA-A01 43x58x7 A SL RD FPM <b>P77526-01</b> K → 91214-PWA-003 80x98x10 A SL LD NBR
2,0 R20A1 R20A2 R20A3	110-115 kW (150-156 PS)	ACCORD CR-V STEPWAGON	01/07→	<b>D38243-00</b> ⑫ 06110-RNA-000 +06114-RNA-010	<b>H40531-00</b> 12251-RNA-A02 MLS 	<b>T40531-00</b> 90005-RNA-A01 (10x) 	<b>X59333-01</b> 12341-RNA-A01 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>M38245-00</b> 17105-RNA-A01 (4x) +17106-RNA-A01 (1x)  <b>M38260-00</b> ⑩ 17103-RNA-A01 (2x) +17104-RNA-A01 (4x) 		<b>X59334-01</b> 18115-RNA-004 	<b>70-31414-10</b> 	<b>P77720-01</b> K ← 91212-RNA-A01 43x58x7 A SL RD FPM <b>P77526-01</b> K → 91214-PWA-003 80x98x10 A SL LD NBR

HONDA												
Ltr. 2,0 20T2N 74-77 kW (101-105 PS) ACCORD TDi CIVIC D CIVIC TDIC	 04/96-12/02	 <b>S36055-00</b> <sup>12</sup> <sup>13</sup> <b>D36055-00</b> <sup>12</sup>   <b>H03732-00</b> 1,05 mm 1 MLS <b>H13732-10</b> 1,2 mm 2 MLS <b>H23732-20</b> 85,5 Ø 1,35 mm 3 	<b>X53700-01</b> 	<b>N90170-00</b> 	<b>X52283-01</b> <sup>7</sup> 	<b>X54457-01</b> NBR 	<b>P77126-01</b> K ← 35x45x7 A SL RD FPM <b>P77397-01</b> K → FPM					
2,2 F22A3 F22A7 F22A8 108-110 kW (147-150 PS) ACCORD ASCOT	01/90-10/96	<b>S80970-00</b> <sup>12</sup> <sup>13</sup> 061A1-PT3-000 +061B1-PT3-000 <b>D80970-00</b> <sup>12</sup> 061A1-PT3-000 	<b>H80970-00</b> 12251-PT0-J02 86 Ø MLS 	<b>V38004-00</b> 12030-PT0-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	<b>X89657-01</b> 17105-PT2-004 	<b>X82189-01</b> 18115-PT3-A21 	<b>X54896-01</b> 11251-PT0-000 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ			
2,2 F22B5 F22B8 110 kW (150 PS) ACCORD SHUTTLE	09/93-02/98	<b>D40098-00</b> <sup>12</sup> 06110-P0D-030 <b>B54917-00</b> <sup>13</sup> 06111-PT1-010 	<b>H40098-00</b> 12251-P0A-004 86 Ø 0,7 mm MLS 	<b>T40098-00</b> 90005-PT0-003 (9x) +90006-PT0-003 (1x) 	<b>V38004-00</b> 12030-PT0-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	<b>X89791-01</b> 17105-P0A-004 	<b>X82306-01</b> 18115-P0A-003 	<b>X54896-01</b> 11251-PT0-000 	<b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ		
2,2 N22A1 103 kW (140 PS) ACCORD CTDi FR-V CTDi	01/04→	<b>D38009-00</b> <sup>12</sup> →12/05  <b>B77568-00</b> <sup>13</sup> 06111-RBD-E01  	<b>H01097-00</b> 12251-RBD-E01 86 Ø 1,3 mm 1 MLS <b>H01097-10</b> 12252-RBD-E01 86 Ø 1,35 mm 2 MLS <b>H01097-20</b> 12253-RBD-E01 86 Ø 1,4 mm 0 MLS <b>H11097-30</b> 12254-RBD-E01 86 Ø 1,45 mm 3 MLS <b>H11097-40</b> 12255-RBD-E01 86 Ø 1,5 mm 4 MLS 	<b>V38009-00</b> 12030-RBD-E01 →12/05 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	<b>X89797-01</b> 17105-RBD-E01 	<b>X82313-01</b> 18115-RBD-E01 	<b>70-31414-10</b> 	<b>P77567-01</b> K ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>P77568-01</b> K → 91214-RBD-E01 87x104x10 A SL LD MVQ			

HONDA												
Ltr.												
2,2 N22A2	103 kW (140 PS) CIVIC CR-V CTDi	02/05→	<b>B77568-00</b> <sup>13</sup> 06111-RBD-E01 	<b>H01097-00</b> 12251-RBD-E01 86 Ø 1,3 mm 1 MLS <b>H01097-10</b> 12252-RBD-E01 86 Ø 1,35 mm 2 MLS <b>H01097-20</b> 12253-RBD-E01 86 Ø 1,4 mm 0 MLS <b>H11097-30</b> 12254-RBD-E01 86 Ø 1,45 mm 3 MLS <b>H11097-40</b> 12255-RBD-E01 86 Ø 1,5 mm 4 MLS 			<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89797-01</b> 17105-RBD-E01 		<b>X82313-01</b> 18115-RBD-E01 	<b>70-31414-10</b> 	<b>P77567-01 K</b> ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>P77568-01 K</b> → 91214-RBD-E01 87x104x10 A SL LD MVQ
2,2 N22B1 N22B2 <b>[NEW]</b>	110-132 kW (150-180 PS) ACCORD DTEC	07/08→	<b>D90201-00</b> <sup>12</sup> 	<b>H84850-00</b> 12251-RL0-G01 86 Ø 1,25 mm MLS <b>H84850-10</b> 12252-RL0-G01 86 Ø 1,3 mm MLS <b>H84850-20</b> 12253-RL0-G01 86 Ø 1,35 mm MLS <b>H84850-30</b> 12254-RL0-G01 86 Ø 1,4 mm MLS <b>H84850-40</b> 12255-RL0-G01 86 Ø 1,45 mm MLS 	<b>T84840-00</b> 90005-RBD-E01 (10X) 	<b>V90179-00</b> 12030-RL0-G00 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X90207-01</b> 17105-RL0-G01 		<b>X90206-01</b> 18115-RL0-G01 	<b>70-31414-10</b> 	<b>P77567-01 K</b> ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>P77568-01 K</b> → 91214-RBD-E01 87x104x10 A SL LD MVQ

HONDA													
Ltr.													
2,2 N22B3 <b>[NEW]</b>	110 kW (150 PS)	CR-V	01/07→	<b>D90201-00</b> ⑫ 01/10→ 	<b>H84850-00</b> 12251-RL0-G01 86 Ø 1,25 mm MLS 01/10→ <b>H84850-10</b> 12252-RL0-G01 86 Ø 1,3 mm MLS 01/10→ <b>H84850-20</b> 12253-RL0-G01 86 Ø 1,35 mm MLS 01/10→ <b>H84850-30</b> 12254-RL0-G01 86 Ø 1,4 mm MLS 01/10→ <b>H84850-40</b> 12255-RL0-G01 86 Ø 1,45 mm MLS 01/10→ 	<b>T84840-00</b> 90005-RBD-E01 (10X) 01/10→ 	<b>V90179-00</b> 12030-RL0-G00 01/10→ 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 01/10→	<b>X90207-01</b> 17105-RL0-G01 01/10→ 		<b>X90206-01</b> 18115-RL0-G01 01/10→ 	<b>70-31414-10</b> 01/10→ 	<b>P77567-01 K</b> ← 91212-RBD-E01 43x58x7 A SL RD ACM 01/10→ <b>P77568-01 K</b> → 91214-RBD-E01 87x104x10 A SL LD MVQ 01/10→
2,3 F23A1	110 kW (150 PS)	ACCORD	03/97-01/99	<b>D40100-02</b> ⑫ 06110-PAB-A00 <b>B37212-00</b> ⑬ 06111-PAA-A01 	<b>H40100-00</b> 12251-PAA-A02 87 Ø 0,72 mm MLS 	<b>T40100-00</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>V38006-00</b> 12030-POA-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>M37919-00</b> 17105-PAA-A01 →12/97  <b>X89792-01</b> 17105-PAA-L01 01/98→ 	<b>X82306-01</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>P77594-01 K</b> ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01 K</b> ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01 N</b> 91213-PT0-003 28x42x8 A SL LD MVQ	
2,3 F23A1	113 kW (154 PS)	ACCORD	01/01-06/03	<b>D40100-02</b> ⑫ 06110-PAB-A00 <b>B37212-00</b> ⑬ 06111-PAA-A01 	<b>H40100-00</b> 12251-PAA-A02 87 Ø 0,72 mm MLS 	<b>T40100-00</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>V38006-00</b> 12030-POA-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	<b>X89792-01</b> 17105-PAA-L01 	<b>X82306-01</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>P77594-01 K</b> ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01 K</b> ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01 K</b> → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01 N</b> 91213-PT0-003 28x42x8 A SL LD MVQ	

HONDA												
2,3 F23A3 F23A6 F23A7 F23A8	110-118 kW (150-160 PS)	ACCORD ACCORD VTI ODYSSEY SHUTTLE	10/97→	<b>D40100-02</b> ⑫ 06110-PAB-A00 <b>B37212-00</b> ⑬ 06111-PAA-A01 	<b>H40100-00</b> 12251-PAA-A02 87 Ø 0,72 mm MLS 	<b>T40100-00</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>V38006-00</b> 12030-POA-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	<b>M37919-00</b> 17105-PAA-A01 	<b>X82306-01</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,3 F23A5	100-101 kW (136-137 PS)			<b>B37212-00</b> ⑬ 06111-PAA-A01 	<b>H40098-00</b> 12251-POA-004 86 Ø 0,7 mm MLS 	<b>T40100-00</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>V38006-00</b> 12030-POA-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	<b>M37919-00</b> 17105-PAA-A01 	<b>X82306-01</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,3 F23Z5	113 kW (154 PS)	ACCORD	11/00-06/03	<b>D40100-02</b> ⑫ 06110-PAB-A00 <b>B37212-00</b> ⑬ 06111-PAA-A01 	<b>H40100-00</b> 12251-PAA-A02 87 Ø 0,72 mm MLS 	<b>T40100-00</b> 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	<b>V38006-00</b> 12030-POA-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	<b>X59451-01</b> 17105-POA-A02 	<b>X82306-01</b> 18115-POA-003 	<b>70-31414-10</b> 	<b>P77594-01</b> K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ <b>P77735-01</b> K ← 91233-PT0-003 27x40x8 A SL LD <b>P77672-01</b> K → 91214-PH1-004 80x100x10 A SL RD MVQ <b>P77602-01</b> N 91213-PT0-003 28x42x8 A SL LD MVQ
2,3 H23A2 H23A3	116-118 kW (158-160 PS)	ACCORD PRELUDE	02/92-09/96	<b>D40102-00</b> ⑫ 06110-P14-010 <b>B54912-00</b> ⑬ 06111-P14-030 	<b>H40102-00</b> 12251-P14-A02 88 Ø 0,68 mm MLS 		<b>V38007-00</b> 12030-PT2-000 	<b>N93050-00</b> 12210-PT2-004 (8x) +12211-PT2-004 (8x) 	<b>X89795-01</b> 17105-PT2-014  <b>X89844-01</b> ⑩ 17121-PT2-003 	<b>X82310-01</b> 18115-PT0-004 	<b>X54912-01</b> 11251-POA-000 	<b>P77602-01</b> N 2x 91213-PT0-003 28x42x8 A SL LD MVQ
2,4 K24A	124-140 kW (168-190 PS)	ACCORD CR-V ODYSSEY	02/03→	<b>D40103-00</b> ⑫ 06110-RBA-E01 <b>B77567-00</b> ⑬ 06114-RBA-020 	<b>H40103-00</b> 12251-RAC-004 87 Ø 0,68 mm MLS 		<b>V38008-00</b> 12030-PNC-000 	<b>N93047-00</b> 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	<b>X37920-01</b> 17115-RAA-A01 	<b>X82311-01</b> 18115-PRB-A01 	<b>70-31414-10</b> 	<b>P77567-01</b> K ← 91212-RBD-E01 43x58x7 A SL RD ACM <b>P77526-01</b> K → 91214-PWA-003 80x98x10 A SL LD NBR



HONDA													
Ltr.													
2,5 C25A1 C25A2	110-127 kW (150-173 PS) LEGEND V6	01/86-06/88	<b>S80910-00</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PH7-660 +061B1-PH7-660 <b>D80910-00</b> <sup>(12)</sup> 061A1-PH7-660	<b>H80910-00</b> 2x 12251-PH7-004 85 Ø 	<b>X83206-01</b> 2x 12341-PH7-000 	<b>N93007-02</b> 12210-PD2-004 (12x) +12211-PH7-004 (12x)	<b>X89619-01</b> 2x 18115-PH7-003 		<b>X82386-01</b> 2x 17105-PH7-003  <b>X82318-01</b> <sup>(10)</sup> 18212-SA0-003 	<b>X54932-01</b> 11251-PH7-000 	<b>P77585-01 N</b> 2x 91213-PH1-003 35x50x8 A SL RD NBR		
2,7 C27A1	124 kW (169 PS) LEGEND V6	10/87-12/90	<b>S80911-00</b> <sup>(12)</sup> <sup>(13)</sup> 061A1-PL2-000 +061B1-PH7-000 <b>D80911-00</b> <sup>(12)</sup> 061A1-PL2-000	<b>H80911-00</b> 2x 12251-PL2-003 88 Ø 	<b>X83206-01</b> 2x 12341-PH7-000 	<b>N93007-02</b> 12210-PD2-004 (12x) +12211-PH7-004 (12x)	<b>X89619-01</b> 2x 18115-PH7-003 		<b>X82386-01</b> 2x 17105-PH7-003 	<b>X54932-01</b> 11251-PH7-000 	<b>P77585-01 N</b> 91213-PH1-003 35x50x8 A SL RD NBR		
3,0 J30A1	147 kW (200 PS) ACCORD VTEC ACCORD V6 24v	03/97-12/03	<b>D40099-00</b> <sup>(12)</sup> R 06120-P8A-A13 <b>D40099-01</b> <sup>(12)</sup> L 06110-P8A-A21 <b>B77561-01</b> <sup>(13)</sup> 06111-P8A-A01 	<b>H40099-00</b> 2x 12251-P8A-A01 87 Ø 0,7 mm MLS 	<b>V38005-00</b> 2x 12030-P8A-A00 	<b>N93047-02</b> 12210-PZ1-A01 (12x) +12211-PZ1-004 (12x)	<b>M37917-00 R</b> 17065-P8A-A01  <b>M37918-00 L</b> 17055-P8A-A01  <b>X89842-01</b> <sup>(10)</sup> 17105-P8A-A01 		<b>X82307-01</b> 2x 18115-P8A-A01 	<b>70-31414-10</b> 	<b>P77621-01 N</b> 2x 91213-P8A-A01 39x53x8		