

LAND ROVER													
1,8 18K16	86-88 kW (117-120 PS)	FREELANDER 16V	02/98-10/06	 D37245-00 B37246-00	 H50497-10 LVB500190 82,5 Ø								
2,0 M 47 M 47 R	80-85 kW (109-116 PS)			 D82500-00 B54786-00 LVQ101240L	 H01312-00 LVB101820L 1,45 mm 1 MLS H11312-10 LVB101830L 1,55 mm 2 MLS H21312-20 LVB000100L 1,65 mm 3 MLS								
2,0 14TCIE	72 kW (98 PS)	FREELANDER DI	02/98-11/00	 S36055-00 D36055-00	 H03732-00 LVB100910 1,05 mm 1 MLS H13732-10 LVB100920 1,2 mm 2 MLS H23732-20 LVB100930 85,5 Ø 1,35 mm 3								
2,0 204PT	177 kW (241 PS)	FREELANDER 2 RANGE ROVER EVOQUE	06/11→	 S38576-00 D38576-00	 H40547-00 LR024975 MLS								
2,2 DW12BTED4 224DT	110-140 kW (150-190 PS)	FREELANDER 2 RANGE ROVER EVOQUE	10/06→	 D38112-02 B38113-00	 H01901-00 LR017303 1,25 mm MLS H11901-10 LR017304 1,3 mm MLS H21901-20 LR017305 1,35 mm MLS H31901-30 LR017307 85,9 Ø 1,37 mm MLS								

LAND ROVER												
Ltr.			1	 S37080-00 ¹² ¹³ D37080-00 ¹² 	H07770-00 LR004418 1,1 mm 1 MLS H17770-10 LR004419 1,15 mm 2 MLS H27770-20 LR004420 91 Ø 1,2 mm 3 MLS 	T05555-00 LR004369 (10x) +LR004370 (8x) 	X83024-01 LR004440 NBR 	N92986-00 LR005901 (16x) P76777-00 LR005901 16x	X88198-01 LR018370 8x 	X81992-01 LR004393 	E36738-00 LR006957 70-31414-10 	P77367-01 K ← LR029318 PTFE P77338-01 K → LR020609 PTFE
2,4 244DT	90 kW (122 PS)			D36884-00 ¹² Mot. → 1A736339 D36885-00 ¹² Mot. 2A736340 → B36884-00 ¹³	H08014-00 LVB000240 86 Ø 1,2 mm 2 MLS H18014-10 LVB000250 86 Ø 1,27 mm 1 MLS H28014-20 LVB000260 86 Ø 1,35 mm 3 MLS 	T08014-00 ERR5384 (12x) 	X83088-01 ERR7094 Mot. → 1A736339 X83089-01 LVP000020 Mot. 2A736340 → 	N92743-00 LJQ100940 (10x) P76839-00 LJQ100940 10x	X89134-01 LKJ000010 10x 	X81515-01 LKG100470 X82370-01 ESR3737 	X54795-01 LVF500040 	P77399-01 K ← ERR5992 50x65x8 AB SL RD FPM
2,5 Td5	102 kW (139 PS)	DISCOVERY Td5	01/99-06/04									

LAND ROVER														
Ltr.														
2,5 12 L 200TDi	83 kW (113 PS)	DEFENDER TDI DISCOVERY TDI	10/89→	D36117-00 ¹² STC362 	H01826-00 LVB5000200 1,3 mm MLS H11826-10 LVB500210 1,4 mm MLS H21826-20 LVB500220 1,5 mm MLS H31826-30 LVB500230 92 Ø 1,6 mm MLS H07879-00 ERR5261 1,42 mm 1 H17879-10 ERR5262 1,52 mm 2 H27879-20 ERR5263 92 Ø 1,62 mm 3 H37879-30 ERR7154 1,7 mm 	T07879-00 ETC8808 (4x) +ETC8809 (10x) +ETC8810 (4x) 	X53646-01 NBR 	N90700-00 ETC8663 (x8) P76636-00 ETC8663	8x	X52550-01 ⁷ ERR1208 	70-31414-10 	P76175-01 K ← ADU8891 48,6x63,65x8/9 RD NBR P76400-01 K → ERR2532 100x120x12 LD P76111-01 N 13510-V7200 40x52x7 RD FPM		
2,5 17 H 23 L	61-86 kW (83-117 PS)	DEFENDER 90/110	09/85→	S30103-00 ¹² ¹³ 501677 D30103-00 ¹² B30103-00 ¹³ RTC809	H02281-00 GEG338 95,2 Ø 	X03838-01 GEG431 Kork 	N90790-00 554727(x4)+ P76509-00 554728 P76510-00 554727	4x 4x	X02284-01 ⁷ 274171 	X02266-01 ⁷ GEG723	X03755-01 GEG537 	P76175-01 K ← ADU8891 48,6x63,65x8/9 RD NBR P76272-01 K → 523240 63,5x82,5x7,9 LD FPM		

LAND ROVER												
Ltr.			1									
2,5 21 L 300TDi	83 kW (113 PS) DEFENDER TDI DISCOVERY TDI	10/89-12/98	 D32149-00 ⁽¹²⁾ STC2802 B32149-00 ^{(13) (38)} STC2801	H07879-00 ERR5261 1,42 mm 1 H17879-10 ERR5262 1,52 mm 2 H27879-20 ERR5263 92 Ø 1,62 mm 3 H01826-00 LVB5000200 1,3 mm MLS H11826-10 LVB500210 1,4 mm MLS H21826-20 LVB500220 1,5 mm MLS H31826-30 LVB500230 92 Ø 1,6 mm MLS 	T01826-00 ERR1939 (10x) +ETC8808 (4x)	X53207-01 ERR2409 NBR 	N90700-00 ETC8663 (x8) P76636-00 ETC8663	8x	X51509-01 ⁽⁷⁾ ERR3785 	X54675-01 70-31414-10 	P76458-01 K ← 47x62x9 RD FPM P77400-01 K → LUF100430 FPM P76117-01 N 40x56x7 A SL RD MVQ	
2,5 25 K4F	130 kW (177 PS) FREELANDER V6	11/00-10/06	D36106-00 ⁽¹²⁾ B36106-00 ^{(13) (35)}	H80102-00 2x LVB101630L 82,5 Ø 	T40360-00 2x 	X83157-01 2x LVP100470L 	N95980-00 LUB100350L P76632-00 LUB100350L	24x	X85000-01 2x LKJ100680L 	X52551-01 2x LKG100290L 	P77461-01 K ← LQX100070L 32x45x6,8 A RD P77462-01 K → LUF100300L	
2,7 276DT	140 kW (190 PS) DISCOVERY TD RANGE ROVER TDVM	07/04→	 D38757-00 ⁽¹²⁾ B38756-00 ^{(13) (35)}	H01902-00 2x LR009719 82,5 Ø 1,17 mm 2 MLS H01902-10 2x LR009721 82,5 Ø 1,22 mm 3 MLS H01902-20 2x LR009722 82,5 Ø 1,27 mm 4 MLS H11902-30 2x LR009723 82,5 Ø 1,32 mm 5 MLS 	T01902-00 2x 1331316 (8x) 	X83359-01 2x LR029132 	N93132-00 1311285 (24x) P76843-00 1311285	24x	X82334-01 2x 1336543 	X54926-01 2x LR005994 X59640-01 1365280 	P77681-01 K ← 1102415 35x50x7 A SL RD PTFE ACM P77677-01 K → LR036542 P77624-01 N 3x 1311318 26x45x8 A SL WD FPM	

LAND ROVER												
Ltr.												
3,0 30DDTX 306DT	155-250 kW (211-340 PS) DISCOVERY RANGE ROVER	09/09→		D38339-01 ¹² B38339-01 ¹³	H40636-00 2x LR013063 85 Ø 1,17 mm 2 MLS H40636-10 2x LR013066 85 Ø 1,22 mm 3 MLS H40636-20 2x LR013070 85 Ø 1,27 mm 4 MLS H40636-30 2x LR013073 85 Ø 1,32 mm 5 MLS 	T01902-00 2x 1331316 (8x) 	X83359-01 2x LR029132 	N93132-00 1311285 (24x) P76843-00 24x 1311285		X82334-01 2x 1336543 	X54926-01 2x LR005994 	P77681-01 K ← 1102415 35x50x7 A SL RD PTFE ACM P77677-01 K → LR036542 P77624-01 N 3x 1311318 26x45x8 A SL WD FPM
3,2 i6	170 kW (231 PS)			D38089-00 ¹² B38133-00 ¹³	H40376-00 LR006664 84,85 Ø MLS 	T50037-00 LR002553 (14x) 	V38118-00 LR001808 (6x) +LR001978 		X89889-01 6x LR001454 	X82354-01 2x LR001455 	P77815-01 K ← 19x38,5x8 A SL RD PTFE P77353-01 K → LR001418 98x118x10 A SL LD PTFE ACM	
3,9 SEV8 V06VEi 3.9V8EFI 42 D	136-140 kW (185-190 PS) RANGE ROVER	07/94→		D36122-00 ¹² STC2822 B36122-00 ¹³ STC2823				N92744-00 ERR1782 (16x)				
3,9 35 D	134 kW (182 PS) DISCOVERY V8	09/93-10/98		D36121-00 ¹² STC1641 Mot.→35D08927B D36122-00 ¹² STC2822 Mot.35D08928B→ B36122-00 ¹³ STC2823 Mot.35D08928B→								
3,9 35 D	134 kW (182 PS) RANGE ROVER	11/88-07/94		D36121-00 ¹² STC1641 Mot.→35D08927B D36122-00 ¹² STC2822 Mot.35D08928B→ B36122-00 ¹³ STC2823 Mot.35D08928B→				N92744-00 ERR1782 (16x) Mot.35D08928B→				
3,9 36 D	134 kW (182 PS) DISCOVERY V8	09/93-10/98		D36121-00 ¹² STC1641 Mot.→36D25154B D36122-00 ¹² STC2822 Mot.36D25155B→ B36122-00 ¹³ STC2823 Mot.36D25155B→								

LAND ROVER															
Ltr.				1											
3,9 36 D	134 kW (182 PS)	RANGE ROVER	11/88-07/94	D36121-00 ¹² STC1641 Mot.→36D25154B D36122-00 ¹² STC2822 Mot.36D25155B→ B36122-00 ¹³ STC2823 Mot.36D25155B→					N92744-00 ERR1782 (16x) Mot.36D25155B→						
3,9 37 D	127 kW (173 PS)	RANGE ROVER	11/88-07/94	D36121-00 ¹² STC1641 Mot.→37D02931B D36122-00 ¹² STC2822 Mot.37D02932B→ B36122-00 ¹³ STC2823 Mot.37D02932B→					N92744-00 ERR1782 (16x) Mot.37D02932B→						
3,9 38 D	127 kW (173 PS)	RANGE ROVER	11/88-07/94	D36121-00 ¹² STC1641 Mot.→38D27237B D36122-00 ¹² STC2822 Mot.38D27238B→ B36122-00 ¹³ STC2823 Mot.38D27238B→					N92744-00 ERR1782 (16x) Mot.38D37238B→						
3,9 3.9V8EFI	127 kW (173 PS)	RANGE ROVER	11/88-07/94	D36121-00 ¹² STC1641 →12/93 D36122-00 ¹² STC2822 01/94→ B36122-00 ¹³ STC2823 01/94→					N92744-00 ERR1782 (16x)						
4,0 MGRV8	136 kW (185 PS)	DISCOVERY V8	11/98-06/04	D36122-00 ¹² STC2822 B36122-00 ¹³ STC2823					N92744-00 ERR1782 (16x)				X54928-01 LVF100400 Gummi 		
4,3 40 D	149 kW (203 PS)	RANGE ROVER	09/92-07/94	D36122-00 ¹² STC2822 B36122-00 ¹³ STC2823											
4,3 4.2V8EFI	149 kW (203 PS)	RANGE ROVER	09/92-07/94	D36122-00 ¹² STC2822 B36122-00 ¹³ STC2823					N92744-00 ERR1782 (16x)						
4,6 46 D	165 kW (224 PS)	RANGE ROVER	07/94-03/02	D36122-00 ¹² STC2822 B36122-00 ¹³ STC2823											