



FIAT

 Code 

**0-9**

132 A.000 ..... 94

138 A.000 ..... 94

146 C1.000 ..... 94

149 B1.000 ..... 98

154 C3.000 ..... 106

169 B ..... 96

170 B ..... 106

182 B5.098 ..... 94

220 A2.000 ..... 94

223 A6.000 ..... 100

230 A2.000 ..... 100



230 A3.000 ..... 100

230 A4.000 ..... 100

263 A3.000 ..... 96

280 A1.000 ..... 100

4HP ..... 108

 Code 

4HR ..... 108

4HS ..... 108

4HT (DW12BTED4) ..... 108

4HW ..... 108

8140.27 ..... 112

8140.27.2100 ..... 112

8140.43 ..... 114

8140.47 ..... 112

8140.63 ..... 114

8140.67 ..... 112

8142.61 ..... 110



8144.21 ..... 112

8144.61 ..... 110, 114

8144.81.2000 ..... 110

**C**

CRD ..... 110

 Code 

**D**

D8B ..... 98

D9B ..... 98

DHX (XUD9TF/L) ..... 98

DJY ..... 98

DW10BTED4 ..... 102

**F**

F1AE0481C ..... 110

F1AE0481D ..... 110



F1CE0481D ..... 114

**L**

LFW ..... 96

**P**

P8C ..... 108

 Code 

**R**

RFL ..... 102

RFN ..... 102

RFN (EW10J4) ..... 102

RFU (XU10J2C) ..... 102

RFV ..... 102

RFW ..... 104

RGX (XU10J2CTE) ..... 104

RHM (DW10ATED4) ..... 104

RHW ..... 104

RHX ..... 106

RHZ ..... 106

**X**

XN 1T ..... 106

FIAT

 Code 

 Code 

 Code 

 Code 

FIAT					
Ltr.					
1,3 138 A.000	37-48 kW (50-65 PS)	1	<p><b>S31223-00</b> ⑫ ⑬ 5881645 →12/82 →4286854→ <b>S31204-00</b> ⑫ ⑬ →01/83→ <b>S30465-00</b> ⑫ ⑬ 5881135 →4286853 <b>D31223-00</b> ⑫ 5881647 →12/82 →4286854→ <b>D31204-00</b> ⑫ 5881971 →01/83→ <b>D30465-00</b> ⑫ 5881137 →4286853 <b>B30465-00</b> ⑬</p>	<p><b>H01616-00</b> 4387618 1,2 mm →12/82</p> <p><b>H11616-10</b> 4406740 81,5 Ø 1,8 mm →12/82</p> <p><b>H05082-00</b> 5951683 81 Ø →01/83→</p>	<p><b>T05082-00</b> 46430687(5x) +46430688 (5x) →01/83→</p>
1,4 146 C1.000	51-53 kW (69-72 PS)		<p><b>S31221-00</b> ⑫ ⑬ 5892410 <b>D31221-00</b> ⑫ 5888262 <b>B31976-00</b> ⑬</p>	<p><b>H00639-00</b> 7666858 81 Ø</p> <p><b>T05082-00</b> 46430687(5x) +46430688 (5x)</p>	
1,6 132 A.000	72 kW (98 PS)		<p><b>S30480-00</b> ⑫ ⑬ <b>D30524-00</b> ⑫ 5880451 <b>B30480-00</b> ⑬</p>	<p><b>H06980-00</b> 4387624 1,35 mm <b>H16980-10</b> 85 Ø 1,8 mm</p> <p><b>H50763-00</b> 46410960 87 Ø</p> <p><b>T05082-00</b> 46430687(5x) +46430688 (5x)</p>	
1,6 182 B5.098	72 kW (98 PS)		<p><b>D32694-00</b> ⑫ 5895663</p>	<p><b>H00593-10</b> 46414567 87 Ø</p> <p><b>T05082-00</b> 46430687(5x) +46430688 (5x)</p>	
1,6 220 A2.000	58 kW (79 PS) SCUDO	02/96-12/06	<p><b>S32919-00</b> ⑫ ⑬ <b>D32919-00</b> ⑫ <b>B32919-00</b> ⑬</p>	<p><b>H00593-10</b> 46414567 87 Ø</p> <p><b>T05082-00</b> 46430687(5x) +46430688 (5x)</p>	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<p><b>X01993-01</b> 4179085 →4286853</p> <p><b>X01619-01</b> 5892522</p> <p><b>X59441-01</b> 4448677 Kork</p>	<p><b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415</p>	<p><b>X01617-01</b> ⑦ 2x</p>	<p><b>X04968-01</b> ⑦ 4147260</p>	<p><b>X02252-01</b> 4179038 Kork</p>	<p><b>P76117-01</b> K ← 40x56x7 A SL RD MVQ <b>P76273-01</b> K → 64x80x8 A SL LD MVQ <b>P76060-01</b> N 40004940 30x52x7 AB SL RD FPM</p>
<p><b>X00665-01</b> 7554851 Kork</p> <p><b>X01619-01</b> 5892522</p>	<p><b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415</p>	<p><b>X00667-01</b> ⑦ 2x 7772495</p>	<p><b>X00688-01</b> 7554363 Gummi</p>	<p><b>P76117-01</b> K ← 40x56x7 A SL RD MVQ <b>P76273-01</b> K → 64x80x8 A SL LD MVQ <b>P76060-01</b> N 40004940 30x52x7 AB SL RD FPM</p>	
<p><b>X04986-01</b> 2x 4388512</p> <p><b>X07172-01</b> 2x 4158646 Kork</p> <p><b>X53493-01</b> 2x 7773831</p>	<p><b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415</p>	<p><b>X04982-01</b> 4194060</p> <p><b>X04985-01</b> 4177112</p> <p><b>X04955-01</b> ⑦ 4166914</p>	<p><b>X07553-01</b> 4331606 Kork</p>	<p><b>P76117-01</b> K ← 40x56x7 A SL RD MVQ <b>P76303-01</b> K → 70x90x10 A LD ACM <b>P76060-01</b> N 2x 40004940 30x52x7 AB SL RD FPM</p>	
<p><b>X53493-01</b> 2x 7773831</p> <p><b>X53175-01</b>   7738383 Kork</p> <p><b>X53734-01</b> 7738383 Kork</p>	<p><b>N92850-00</b> 7581344 (16x) <b>P76532-00</b> 46440885</p>	<p><b>X58335-01</b> 46410505</p> <p><b>X58434-01</b> 4x 46402220</p>	<p><b>X51964-01</b> 46412116</p>	<p><b>P76117-01</b> K ← 40x56x7 A SL RD MVQ <b>P77321-01</b> K → 70x112/167x20 PTFE <b>P76060-01</b> N 2x 40004940 30x52x7 AB SL RD FPM</p>	
<p><b>X53175-01</b>   7738383 Kork</p> <p><b>X53734-01</b> 7738383 Kork</p>	<p><b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415</p>	<p><b>X51425-01</b> ⑦</p>	<p><b>X00688-01</b> 7554363 Gummi</p>	<p><b>P76117-01</b> K ← 40x56x7 A SL RD MVQ <b>P76273-01</b> K → 64x80x8 A SL LD MVQ <b>P76060-01</b> N 40004940 30x52x7 AB SL RD FPM</p>	

| interior / innen / inside / intérieur / interno / внутри



FIAT				
Ltr.				
1,6 263 A3.000	74 kW (101 PS)	<b>D59714-01</b> 71769839	<b>H40656-00</b> 55221093 80,5 Ø 0,82 mm MLS 0	<b>T38336-00</b> 55214378 (10x)  RIBE
<b>[NEW]</b>		<b>B38531-00</b> 71753736 +71718365	<b>H40656-10</b> 55221094 80,5 Ø 0,92 mm MLS 1	
			<b>H40656-20</b> 55221095 80,5 Ø 1,02 mm MLS 2	
1,8 LFW	73 kW (99 PS) ULYSSE	<b>S31580-00</b> 0197.63	<b>H01025-00</b> 9613314680 84,3 Ø 1,2 mm	<b>T11025-00</b> 
		<b>D31580-00</b> <b>B31580-00</b> <b>R31124-00</b>	<b>H11025-10</b> 84,3 Ø 1,5 mm	
1,8 LFW	73 kW (99 PS) ULYSSE	<b>S31580-00</b> 0197.63	<b>H01025-00</b> 9613314680 84,3 Ø 1,2 mm	<b>T01025-00</b> 9600597780 (10x) 
		<b>D31580-00</b> <b>B31580-00</b> <b>R31124-00</b>	<b>H11025-10</b> 84,3 Ø 1,5 mm	
1,8 169 B	49 kW (67 PS) DUCATO	<b>S30778-00</b> <b>D30778-00</b>	<b>H02666-00</b> 9152061980 86,7 Ø	<b>T02666-00</b> →06/85 <b>T02760-00</b> →07/85→

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



<b>X59714-01</b> 55205111 	<b>N93126-00</b> 55183812 (16x) <b>P76812-00</b> 55183812 16x	<b>M59515-00</b> 71754211 	<b>X59732-01</b> 55210879  <b>X59721-01</b> 55206838 	<b>70-31414-10</b> 	<b>P76444-01 K ←</b> 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K →</b> 71718365 PTFE <b>P77404-01 N</b> 46802577 30x45x7 AB SL RD NBR
<b>X53101-01</b> 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x	<b>X56171-01</b> 5894954  <b>X56170-01</b> 9569138780 <sup>⑩</sup> 2x	<b>X52670-01</b> 	<b>X04848-01</b> 0127.05 NBR <b>X07793-01</b> 91505500 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P76133-01 N</b> 9400236499 36x50x7 A RD FPM
<b>X53101-01</b> 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x	<b>X56171-01</b> 5894954  <b>X56170-01</b> 9569138780 <sup>⑩</sup> 2x	<b>X52670-01</b> 	<b>X04848-01</b> 0127.05 NBR <b>X07793-01</b> 91505500 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P76133-01 N</b> 9400236499 36x50x7 A RD FPM
<b>X04835-01</b> 9400249149 NBR 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x	<b>X07480-01</b> 5892455 	<b>X04833-01</b> 9400349949 	<b>X04848-01</b> 0127.05 NBR <b>X54253-01</b> Kork 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76005-01 N</b> 16x21x4,5 NBR

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

③ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



FIAT						
Ltr.						
1,9 DHX (XUD9TF/L) DJY D9B	50-66 kW (68-90 PS)	DUCATO D DUCATO TD SCUDO D SCUDO TD ULYSSE TD	02/95-12/06	<b>S31582-00</b> ⑫ ⑬ 95602514  <b>D31582-00</b> 9567221180  <b>B31582-00</b> ⑬	<b>H05876-00</b> 9623068080 1,36 mm 1 <b>H05876-10</b> 9623068180 1,4 mm 2 <b>H05876-20</b> 9623068280 1,44 mm 3 <b>H15876-30</b> 9623068380 1,48 mm 4 <b>H15876-40</b> 9623068480 84 Ø 1,53 mm 5	<b>T08280-00</b> 9607384680 (10x) 
1,9 D8B	68 kW (92 PS)	SCUDO TD	02/96-12/06	<b>S31582-00</b> ⑫ ⑬ 95602514  <b>D31582-00</b> 9567221180  <b>B31582-00</b> ⑬	<b>H05877-00</b> 9621917180 1,36 mm 1 MLS <b>H05877-10</b> 9621917280 1,4 mm 2 MLS <b>H05877-20</b> 9621917380 1,44 mm 3 MLS <b>H15877-30</b> 9621917480 1,48 mm 4 MLS <b>H15877-40</b> 9621917580 84 Ø 1,53 mm 5 MLS	<b>T02360-00</b> 
1,9 149 B1.000	52 kW (71 PS)	DUCATO D	02/87-03/94	<b>S31206-00</b> ⑫ ⑬ 5882358  <b>D31206-00</b> ⑫ 5892423  <b>B31206-00</b> ⑬	<b>H05055-00</b> 5962711 1,65 mm <b>H15055-10</b> 5962712 1,8 mm 1 <b>H25055-20</b> 5962713 84,3 Ø 1,95 mm 2	<b>T05055-00</b> 7653650 (10x)  RIBE

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>X07796-01</b> 9400249919 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x	<b>X03013-01</b> ⚠  <b>X51239-01</b> ⑦ 9567224080 	<b>X07793-01</b> 91505500 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P76099-11 N</b> 2x 9400236149 35x50x8 A SL WD FPM	
<b>X07796-01</b> 9400249919 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x	<b>X03013-01</b> ⚠  <b>X51239-01</b> ⑦ 9567224080 	<b>X07793-01</b> 91505500 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P76099-11 N</b> 2x 9400236149 35x50x8 A SL WD FPM	
<b>X05059-01</b> 4394109 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x	<b>X05058-01</b> ⑦ 2x 4436580 	<b>X05073-01</b> 5959226 Kork  <b>X54008-01</b> 7647596 Gummi 	<b>P76243-01 K ←</b> 40004260 30x43x8 AB SL RD FPM <b>P76313-11 K →</b> 40004300 74x90x10 AB SL LD FPM <b>P76060-01 N</b> 40004940 30x52x7 AB SL RD FPM	



FIAT						
Ltr.						
1,9 223 A6.000	03/01→	46 kW (63 PS)	DOBLO D	<b>S36186-00</b> ⑫ ⑬ 71715698  <b>D36186-00</b> ⑫ 71715699  <b>B32911-00</b> ⑬ 	<b>H07601-00</b> 46529117 0,82 mm MLS <b>H17601-10</b> 46529118 0,92 mm 1 MLS <b>H27601-20</b> 46529119 83 Ø 1,02 mm 2 MLS 	<b>T03925-00</b> 7775920 (10x)  RIBE
1,9 230 A2.000 230 A3.000 230 A4.000	03/94-04/02	51-60 kW (69-82 PS)	DUCATO D DUCATO TD	<b>S31206-00</b> ⑫ ⑬ 5882358  <b>D31206-00</b> ⑫ 5892423  <b>B31206-00</b> ⑬ 	<b>H05900-00</b> 46431639 1,65 mm <b>H15900-10</b> 46431640 1,8 mm 1 <b>H25900-20</b> 46431641 83,5 Ø 1,95 mm 2 	<b>T05055-00</b> 7653650 (10x)  RIBE
1,9 280 A1.000	03/89-03/94	60 kW (82 PS)	DUCATO TD	<b>S31206-00</b> ⑫ ⑬ 5882358  <b>D31218-00</b> ⑫  <b>B31218-00</b> ⑬ 	<b>H00592-00</b> 7630180 1,65 mm <b>H10592-10</b> 46431640 1,8 mm 1 <b>H20592-20</b> 46431642 83,2 Ø 1,95 mm 2 	<b>T05055-00</b> 7653650 (10x)  RIBE

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

<b>X53789-01</b> 46552748 NBR 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x 	<b>X85371-01</b>   4x 46548459  <b>X85372-01</b> 4x 46548450 	<b>X51966-01</b> 46467747 	<b>70-31414-10</b> 	<b>P76444-01</b> K ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01</b> K → 71713041 93 LD FPM <b>P76063-11</b> N 40004400 30x42x7 A SL RD FPM
<b>X05059-01</b> 4394109 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x 	<b>X05058-01</b> ⑦ 2x 4436580 	<b>X05073-01</b> 5959226 Kork  <b>X54008-01</b> 7647596 Gummi 	<b>P76243-01</b> K ← 40004260 30x43x8 AB SL RD FPM <b>P76313-11</b> K → 40004300 74x90x10 AB SL LD FPM <b>P76060-01</b> N 40004940 30x52x7 AB SL RD FPM	
<b>X05059-01</b> 4394109 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415 8x 	<b>X85522-01</b> ⑦ 46462772 	<b>X05073-01</b> 5959226 Kork  <b>X54008-01</b> 7647596 Gummi 	<b>P76243-01</b> K ← 40004260 30x43x8 AB SL RD FPM <b>P76313-11</b> K → 40004300 74x90x10 AB SL LD FPM <b>P76060-01</b> N 40004940 30x52x7 AB SL RD FPM	

I interior / innen / inside / intérieur / interno / внутри



FIAT						
Ltr.						
2,0 DW10BTD4	01/07→	100 kW (136 PS) SCUDO		<b>S37090-00</b> (12) (13) 9464861680 +9654983280  <b>D37090-00</b> (12) 9464861580 +9654983280 	<b>H01900-00</b> 9644450580 86 Ø 1,25 mm 2 MLS <b>H11900-10</b> 9644450680 86 Ø 1,3 mm 3 MLS <b>H21900-20</b> 9644450780 86 Ø 1,35 mm 4 MLS <b>H31900-30</b> 9644450880 86 Ø 1,4 mm 5 MLS 	<b>T05133-00</b> 9802033280 (10x) 
2,0 RFL	04/02→	81 kW (110 PS) DUCATO		<b>D32987-00</b> (12) 9566937980 <b>B31581-00</b> (13)	<b>H50161-00</b> 9616067680 87 Ø 1,2 mm 	<b>T08280-00</b> 9607384680 (10x) 
2,0 RFN RFN (EW10J4)	05/00→	100 kW (136 PS) SCUDO SCUDO 16V ULYSSE ULYSSE 16V		<b>S36504-00</b> (12) (13) <b>D36504-00</b> (12) <b>B36503-00</b> (13)	<b>H80351-00</b> 9636017380 85,5 Ø MLS 	<b>T07586-00</b> 9647888280 (10x) 
2,0 RFU (XU10J2C)	06/94-08/02	89 kW (121 PS) ULYSSE		<b>S32987-00</b> (12) (13) <b>D32987-00</b> (12) 9566937980 <b>B32987-00</b> (13) 95650948	<b>H50161-00</b> 9616067680 87 Ø 1,2 mm 	<b>T08280-00</b> 9607384680 (10x) 
2,0 RFV	05/98-09/00	97 kW (132 PS) ULYSSE 16V		<b>S32981-00</b> (12) (13) → 7965 <b>S36401-00</b> (12) (13) → 7966 <b>D32981-00</b> (12) → 7965 <b>D36401-00</b> (12) → 7966 <b>B32982-00</b> (13) → 7965 <b>B32981-00</b> (13) → 7966	<b>H80031-10</b> 87 Ø 1,45 mm → 7966 → 7965 <b>H80031-00</b> 87 Ø 1,2 mm → 7965	<b>T50162-00</b> 9605999480 (10x) 



<b>V37090-00</b> 9654983280 	<b>N92635-01</b> 9400956489 (16x) 		<b>X81070-01</b> 9400349129 	<b>70-31414-10</b> 	<b>P77464-01 K</b> ← 9614194980 42x62x7 A SL RD PTFE <b>P77465-01 K</b> → 9400127459 90x110x7 A SL LD PTFE <b>P77142-01 N</b> 9400807289 27x47x7 A SL RD FPM	
<b>X01021-01</b> 9400249489 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415	8x	<b>X01022-01</b> 91505500 	<b>X07793-01</b> 91505500 	<b>P76151-01 K</b> ← 9614194980 42x62x7 A RD FPM <b>P76386-01 K</b> → 9614379380 90x110x7 A SL LD FPM <b>P76133-01 N</b> 9400236499 36x50x7 A RD FPM	
<b>X53933-01 L</b> 9463377480 <b>X53934-01 R</b> 9463377580	<b>N92657-00</b> 0956.45 (16x) <b>P76657-00</b> 0956.45	16x	<b>X86822-01</b> 9463260280 	<b>X81109-01</b> 9464038380 	<b>70-31414-10</b> 	<b>P77304-01 K</b> ← 40x55x6,5 A SL RD FPM <b>P76386-01 K</b> → 9614379380 90x110x7 A SL LD FPM <b>P76133-01 N</b> 9400236499 36x50x7 A RD FPM
<b>X01021-01</b> 9400249489 	<b>N90300-00</b> 5930415 (8x) → 7665 <b>P76531-00</b> 5930415	8x	<b>X58564-01</b> 9569138780 	<b>X06151-01</b> 0349.70 	<b>70-31414-10</b> 	<b>P76151-01 K</b> ← 9614194980 42x62x7 A RD FPM <b>P76386-01 K</b> → 9614379380 90x110x7 A SL LD FPM <b>P76133-01 N</b> 9400236499 36x50x7 A RD FPM
<b>X53731-01 L</b> 9463330280 → 7966 → 7965 <b>X53732-01 R</b> 9463330180 → 7966 → 7965	<b>N92657-00</b> 0956.45 (16x) → 7966 <b>P76750-00</b> → 7965 <b>P76657-00</b> 0956.45 → 7966	16x 16x	<b>X58967-01</b> → 7965 	<b>X52325-01</b> → 7965 	<b>70-31414-10</b> 	<b>P76151-01 K</b> ← 9614194980 42x62x7 A RD FPM <b>P76386-01 K</b> → 9614379380 90x110x7 A SL LD FPM <b>P76133-01 N</b> 9400236499 36x50x7 A RD FPM



FIAT						
Ltr.						
2,0 RFW	03/94-04/02	80 kW (109 PS)	DUCATO	<b>S31581-00</b> ⑫ ⑬ 9568993 <b>D31581-00</b> ⑫ <b>B31581-00</b> ⑬	<b>H50161-00</b> 9616067680 87 Ø 1,2 mm 	<b>T08280-00</b> 9607384680 (10x) 
2,0 RGX (XU10J2CTE)	06/94-08/02	108 kW (147 PS)	ULYSSE Turbo	<b>D36906-00</b> ⑫  <b>B31581-00</b> ⑬	<b>H50161-00</b> 9616067680 87 Ø 1,2 mm 	<b>T08280-00</b> 9607384680 (10x) 
2,0 RHM (DW10ATED4) RHW	08/02-08/06	79-80 kW (107-109 PS)	ULYSSE JTD	<b>S36517-00</b> ⑫ ⑬ 9463378980   <b>D36517-00</b> ⑫ 9463380080  <b>B36517-00</b> ⑬	<b>H01900-00</b> 9644450580 86 Ø 1,25 mm 2 ■ MLS <b>H11900-10</b> 9644450680 86 Ø 1,3 mm 3 ■ MLS <b>H21900-20</b> 9644450780 86 Ø 1,35 mm 4 ■ MLS <b>H31900-30</b> 9644450880 86 Ø 1,4 mm 5 ■ MLS 	<b>T17586-00</b> 9646397880 

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X53101-01</b> 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415	<b>X58564-01</b> 2x 9569138780  <b>X56170-01</b> ⑩ 2x 9569138780 	<b>X01022-01</b> 4x 91505500 	<b>X07793-01</b> 91505500  <b>70-31414-10</b> 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P76133-01 N</b> 9400236499 36x50x7 A RD FPM
<b>X01021-01</b> 9400249489 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415	<b>X56528-01</b> 9612595180  <b>X58564-01</b> 2x 9569138780 		<b>X07793-01</b> 91505500 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P76133-01 N</b> 9400236499 36x50x7 A RD FPM <b>P77333-01 N</b> 32x45x7 RD
<b>X53953-01</b> 9463380380 	<b>N92635-00</b> 2x <b>P76698-00</b> 16x 9400956489		<b>X81070-01</b> 9400349129 	<b>70-31414-10</b> 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P77142-01 N</b> 9400807289 27x47x7 A SL RD FPM



FIAT

FIAT						
Ltr.						
2,0 RHX RHZ	69-80 kW (94-109 PS) SCUDO JTD ULYSSE JTD	10/99-12/06	<b>S32989-00</b> 9569752880 → 8331   <b>S36550-00</b> → 8332→   <b>D32989-00</b> 9569752780 → 8331  <b>D36550-00</b> → 8332→  <b>B32989-00</b>	<b>H05133-00</b> 9635967180 1,3 mm MLS <b>H05133-10</b> 9635967280 1,35 mm MLS <b>H05133-20</b> 9635967380 1,4 mm MLS <b>H15133-30</b> 9635967480 1,45 mm MLS <b>H15133-40</b> 9635967580 86 Ø 1,5 mm MLS	<b>T05133-00</b> 9802033280 (10x) 	
2,0 XN 1T	58 kW (79 PS) DUCATO	01/82-08/90	<b>D30777-00</b> 5894379	<b>H02760-00</b> 91520180 90,2 Ø 1,2 mm 		
2,0 154 C3.000	88 kW (120 PS)		<b>S31439-00</b> <b>D31439-00</b> 5892007	<b>H50125-00</b> 7660966 85 Ø 	<b>T00340-00</b> 60807357 (10x)  RIBE	
2,0 170 B	55 kW (75 PS) DUCATO	07/85-08/90	<b>S30777-00</b> 9400197139 <b>D30777-00</b> 5894379 <b>B30777-00</b> <b>R30547-00</b>	<b>H02760-00</b> 91520180 90,2 Ø 1,2 mm <b>H12760-10</b> 0209.49 90,2 Ø 1,6 mm 	<b>T02760-00</b> → 04/89  <b>T01025-00</b> 9600597780 (10x) → 05/89→ 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



<b>X53885-01</b> 9630142380 	<b>N92991-00</b> → 8331 <b>N92635-00</b> → 8332→ <b>P76662-00</b> 46556651 → 8331 <b>P76698-00</b> 9400956489 → 8332→	<b>X58968-01</b> 9569623180 	<b>X52326-01</b> 9569626380 	<b>70-31414-10</b> 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P77142-01 N</b> 9400807289 27x47x7 A SL RD FPM
<b>X04835-01</b> 9400249149 NBR 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415	<b>X07480-01</b> 5892455 	<b>X04833-01</b> 9400349949 	<b>X05060-01</b> 9151183860 Kork 	<b>P76150-01 K ←</b> 42x60x8 A RD FPM
<b>X00342-01</b> 7660565 Kork  <b>X51145-01</b> 7684064 	2x <b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415	8x <b>X55012-01</b> 7700197 	<b>X04985-01</b> 4177112 	<b>X54004-01</b> 7646248 Kork 	<b>P76243-01 K ←</b> 40004260 30x43x8 AB SL RD FPM <b>P76273-01 K →</b> 64x80x8 A SL LD MVQ <b>P76060-01 N</b> 40004940 30x52x7 AB SL RD FPM
<b>X04835-01</b> 9400249149 NBR 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 5930415	8x <b>X07480-01</b> 5892455 	<b>X04833-01</b> 9400349949 	<b>X04848-01</b> 0127.05 NBR <b>X54253-01</b> Kork 	2x <b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76005-01 N</b> 16x21x4,5 NBR





FIAT						
Ltr.						
2,1 P8C	80 kW (109 PS) ULYSSE TD	03/96-10/99	<b>S31584-00</b> <sup>(12)</sup> <sup>(13)</sup>  <b>D31584-00</b> <sup>(12)</sup> 9567526380  <b>B31584-00</b> <sup>(13)</sup>	<b>H07761-00</b> 1,35 mm MLS <b>H07761-10</b> 1,52 mm MLS <b>H07761-20</b> 1,57 mm MLS <b>H17761-30</b> 1,62 mm MLS <b>H17761-40</b> 1,67 mm MLS <b>H17761-50</b> 9620480980 1,73 mm MLS <b>H27761-60</b> 9628139280 86 Ø 1,77 mm MLS 	<b>T02356-00</b> 9638586480 	
2,2 4HP 4HR 4HS 4HT (DW12BTED4) <b>[NEW]</b>	120-125 kW (163-170 PS)		<b>D38112-00</b> <sup>(12)</sup>  <b>B38113-00</b> <sup>(13)</sup>	<b>H01901-00</b> 9655638580 1,25 mm MLS <b>H11901-10</b> 9655638680 1,3 mm MLS <b>H21901-20</b> 9655638780 1,35 mm MLS <b>H31901-30</b> 9655638880 85,9 Ø 1,37 mm MLS 	<b>T05133-00</b> 9802033280 (10x) 	
2,2 4HW	94 kW (128 PS) ULYSSE JTD	08/02-08/06	<b>S36517-00</b> <sup>(12)</sup> <sup>(13)</sup> 9463378980   <b>D36517-00</b> <sup>(12)</sup> 9463380080  <b>B36517-00</b> <sup>(13)</sup>	<b>H01900-00</b> 9644450580 86 Ø 1,25 mm 2 MLS <b>H11900-10</b> 9644450680 86 Ø 1,3 mm 3 MLS <b>H21900-20</b> 9644450780 86 Ø 1,35 mm 4 MLS <b>H31900-30</b> 9644450880 86 Ø 1,4 mm 5 MLS 	<b>T17586-00</b> 9646397880 	



<b>X53584-01</b> 9608064880 	<b>N91210-00</b> 7553637 (12x) <b>P76531-00</b> 5930415 12x	<b>X56183-01</b> 9400348969 	<b>X51245-01</b> 9400349769 	<b>X04848-01</b> 2x 0127.05 NBR <b>X07793-01</b> 91505500 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P76099-11 N</b> 2x 9400236149 35x50x8 A SL WD FPM
<b>V38102-00</b> 9682131780 +9682131280 (2x) +9656742280 	<b>N93131-00</b> 9400956639 (16x)	<b>M38101-00</b> 9661413780 	<b>X81999-01</b> 9653365180 	<b>70-31414-10</b> 	<b>P77464-01 K ←</b> 9614194980 42x62x7 A SL RD PTFE <b>P77465-01 K →</b> 9400127459 90x110x7 A SL LD PTFE <b>P77142-01 N</b> 9400807289 27x47x7 A SL RD FPM
<b>X53953-01</b> 9463380380 	<b>N92635-00</b> 2x <b>P76698-00</b> 16x 9400956489		<b>X81070-01</b> 9400349129 	<b>70-31414-10</b> 	<b>P76151-01 K ←</b> 9614194980 42x62x7 A RD FPM <b>P76386-01 K →</b> 9614379380 90x110x7 A SL LD FPM <b>P77142-01 N</b> 9400807289 27x47x7 A SL RD FPM



FIAT						
Ltr.						
2,3 F1AE0481C F1AE0481D	81-88 kW (110-120 PS) DUCATO DUCATO JTD	04/02→				
			<b>S37072-00</b> 504049360  <b>D37072-00</b> 2996092 	<b>H08653-00</b> 5500387067 1,1 mm MLS <b>H18653-10</b> 5500387068 1,2 mm MLS <b>H28653-20</b> 5500387069 88,5 Ø 1,3 mm MLS 	<b>T01844-00</b> 500347039 (6x) +500347040 (4x) 	
2,4 8142.61 8144.61	53 kW (72 PS) DUCATO D	01/82→				
			<b>S36355-00</b>  <b>D36355-00</b>  <b>B36355-00</b>	<b>H07684-00</b> 5891282 95 Ø 1,9 mm 10 mm 	<b>T07684-00</b> 4828150 (12x) +4854648 (10x) 	
2,4 8144.81.2000	66-74 kW (90-101 PS)					
			<b>S31980-00</b> 574799→  <b>D31980-00</b> 574799→  <b>B31980-00</b> 574799→	<b>H07684-00</b> 5891282 95 Ø 1,9 mm 10 mm 574799→ 	<b>T07684-00</b> 4828150 (12x) +4854648 (10x) 574799→ 	
2,5 CRD	55 kW (75 PS)	01/86→				
			<b>S30253-00</b> 75513625 <b>D30253-00</b> <b>B30253-00</b>	<b>H00666-00</b> 5493998 96,3 Ø 	<b>T06345-00</b> 	



<b>X83132-01</b> 504019494 → 133429  <b>X83049-01</b> 504052452 → 133430→ 	<b>N91011-00</b> 500395378 (16x) <b>P76818-00</b> 500395378 16x	<b>X88806-01</b> 504037859 	<b>X81804-01</b> 500376626 	<b>X54817-01</b> 504018307 NBR 	<b>P77455-01 K ←</b> 504123772 50x80x14 FPM <b>P77456-01 K →</b> 504101720 83x113x13 FPM <b>P77457-01 N</b> 500350049 34x60x10 AB RD FPM
<b>X07685-01</b> 7301481 → 574798  <b>X02037-01</b> 7302293 → 574799→ 	<b>N92430-00</b> <b>P76544-00</b> 4830224 8x	<b>X07694-01</b> 98425767 4x 	<b>X51326-11</b> 7303077 4x 	<b>X07688-01</b> 7301683 	<b>P76305-11 K ←</b> 40100301 70x90x10 A SL RD FPM <b>P76364-11 K →</b> 40100311 90x115x13/9,5 AB SL LD FPM <b>P76188-01 N</b> 50x70x10 B RD MVQ <b>P76201-11 N</b> 5000815434 55x70x8 AB SL RD FPM
<b>X02037-01</b> 7302293 → 574799→ 	<b>N92430-00</b> → 574799→ <b>P76544-00</b> 4830224 → 574799→ 8x	<b>X07694-01</b> 98425767 → 574799→ 4x 	<b>X51326-11</b> 7303077 → 574799→ 4x 	<b>X07688-01</b> 7301683 → 574799→ 	<b>P76305-11 K ←</b> 40100301 70x90x10 A SL RD FPM → 574799→ <b>P76364-11 K →</b> 40100311 90x115x13/9,5 AB SL LD FPM → 574799→ <b>P76188-01 N</b> 50x70x10 B RD MVQ → 574799→ <b>P76201-11 N</b> 5000815434 55x70x8 AB SL RD FPM → 574799→
<b>X00742-01</b> NBR  <b>X01015-01</b> 5893816 	<b>N91300-00</b> 5469955	<b>X00837-01</b>  4x	<b>X00881-01</b> 5452930 4x  <b>X07493-01</b> 	<b>X07498-01</b> 7543388080B 	<b>P76178-01 K ←</b> 48x65x10 A SL MVQ <b>P76051-01 N</b> 95550398 29x46x10 LD MVQ



FIAT

<b>FIAT</b>						
Ltr.						
2,5 8140.27	70 kW (95 PS) DUCATO DUCATO TD	09/86-03/94	<b>S36356-00</b> (12) (13)  <b>S31988-00</b> (12) (13)  <b>D36356-00</b> (12)  <b>B36356-00</b> (13) 		<b>T07684-00</b> 4828150 (12x) +4854648 (10x) 	
2,5 8140.27.2100	70 kW (95 PS)		<b>S31987-00</b> (12) (13)  <b>D31987-00</b> (12) 	<b>H50000-00</b> 98471766 95 Ø 1,2 mm 10 mm 	<b>T07684-00</b> 4828150 (12x) +4854648 (10x) 	
2,5 8140.47 8140.67	62-85 kW (84-116 PS) DUCATO DUCATO D DUCATO TDI	03/94-04/02	<b>S31988-00</b> (12) (13) 		<b>T07684-00</b> 4828150 (12x) +4854648 (10x) 	
2,5 8144.21	68 kW (92 PS) DUCATO TD	01/86-08/90	<b>S31311-01</b> (12) (13)  <b>D31311-00</b> (12)  <b>B31311-00</b> (13) 	<b>H50000-00</b> 98471766 95 Ø 1,2 mm 10 mm 	<b>T07684-00</b> 4828150 (12x) +4854648 (10x) 	



<b>X02037-01</b> 7302293 → 1815309 	<b>N92430-00</b> <b>P76544-00</b> 8x 4830224			<b>X54617-01</b> 7300766 Kork → 1815309  <b>X54446-01</b> → 1815310  <b>X54494-01</b> NBR → 1815310 	<b>P76303-01</b> K ← 70x90x10 A LD ACM <b>P76364-11</b> K → 40100311 90x115x13/9,5 AB SL LD FPM <b>P76388-11</b> K → 1227942L00 100x118x10/12 A SL LD FPM <b>P76201-11</b> N 5000815434 55x70x8 AB SL RD FPM
<b>X02037-01</b> 7302293 	<b>N92430-00</b> <b>P76544-00</b> 8x 4830224	<b>X07694-01</b> 4x 98425767 	<b>X51326-11</b> 3x 7303077  <b>X52638-01</b> 7303077 	<b>X54617-01</b> 7300766 Kork 	<b>P76364-11</b> K → 40100311 90x115x13/9,5 AB SL LD FPM <b>P76188-01</b> N 50x70x10 B RD MVQ
<b>X02037-01</b> 7302293 → 1815309 	<b>N92430-00</b> <b>P76544-00</b> 8x 4830224			<b>X54446-01</b>  <b>X54494-01</b> NBR 	<b>P76305-11</b> K ← 40100301 70x90x10 A SL RD FPM <b>P76364-11</b> K → 40100311 90x115x13/9,5 AB SL LD FPM <b>P76388-11</b> K → 1227942L00 100x118x10/12 A SL LD FPM <b>P76188-01</b> N 50x70x10 B RD MVQ <b>P76201-11</b> N 5000815434 55x70x8 AB SL RD FPM
<b>X02037-01</b> 7302293 	<b>N92430-00</b> <b>P76544-00</b> 8x 4830224		<b>X52638-01</b> 7303077  <b>X00503-01</b>	<b>X07688-01</b> 7301683 	<b>P76305-11</b> K ← 40100301 70x90x10 A SL RD FPM <b>P76364-11</b> K → 40100311 90x115x13/9,5 AB SL LD FPM <b>P76188-01</b> N 50x70x10 B RD MVQ <b>P76201-11</b> N 5000815434 55x70x8 AB SL RD FPM



FIAT

FIAT						
Ltr.						
2,5 8144.61	55 kW (75 PS) DUCATO	09/86-05/90	<b>S36355-00</b> (12) (13)  <b>D36355-00</b> (12)  <b>B36355-00</b> (13)	<b>H07684-00</b> 5891282 95 Ø 1,9 mm 10 mm 	<b>T07684-00</b> 4828150 (12x) +4854648 (10x) 	
2,8 8140.43	90 kW (122 PS) DUCATO DUCATO TDI	10/97-04/02	<b>S36266-01</b> (12) (13) (35) 99477116  <b>D36266-01</b> (12) 99477119  <b>B36266-00</b> (13)	<b>H08023-01</b> 99432353 1,3 mm <b>H18023-11</b> 99460983 1,4 mm <b>H28023-21</b> 99458402 1,5 mm 	<b>T07684-00</b> 4828150 (12x) +4854648 (10x) 	
2,8 8140.63	64 kW (87 PS) DUCATO DUCATO D	02/98-04/02	<b>S38020-00</b> (12) 71713988  <b>D38020-00</b> (12) 71713987 	<b>H07778-00</b> 500306170 1,6 mm 13 mm <b>H17778-10</b> 5306171 1,7 mm 13 mm  <b>H27778-20</b> 500306172 96 Ø 1,8 mm 13 mm 		
3,0 F1CE0481D	116 kW (158 PS) DUCATO	07/06→	<b>S37073-00</b> (12) 8094874 <b>S37073-03</b> (12) (13)  <b>D37073-00</b> (12) 8094873 <b>D37073-03</b> (12) 	<b>H80737-00</b> 504093500 1,1 mm MLS <b>H80737-10</b> 504093499 1,2 mm MLS <b>H80737-20</b> 504093501 1,3 mm MLS 	<b>T38521-00</b> 504081515 (6x) +504081531 (4x) +504081543 (4x) +504081546 	

35 contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X07685-01</b> 7301481 → 574798 <b>X02037-01</b> 7302293 → 574799 →	<b>N92430-00</b> <b>P76544-00</b> 4830224 8x	<b>X07694-01</b> 98425767 4x	<b>X51326-11</b> 7303077 4x	<b>X07688-01</b> 7301683 	<b>P76305-11 K</b> ← 40100301 70x90x10 A SL RD FPM <b>P76364-11 K</b> → 40100311 90x115x13/9,5 AB SL LD FPM <b>P76188-01 N</b> 50x70x10 B RD MVQ <b>P76201-11 N</b> 5000815434 55x70x8 AB SL RD FPM
<b>X59298-01</b> 500388382 	<b>N92430-00</b> <b>P76544-00</b> 4830224 8x	<b>X07694-01</b> 98425767 4x	<b>X51326-11</b> 7303077 4x	<b>X54446-01</b> 	<b>P76188-01 N</b> 50x70x10 B RD MVQ <b>P76201-11 N</b> 5000815434 55x70x8 AB SL RD FPM
<b>X53812-01</b> 500388381 	<b>N92430-00</b> <b>P76544-00</b> 4830224 8x	<b>X07694-01</b> 98425767 4x	<b>X51326-11</b> 7303077 4x	<b>X54494-01</b> NBR 	
<b>X83071-01</b> 504161187 	<b>N91011-00</b> 500395378 (16x) <b>P76818-00</b> 500395378 16x	<b>X89001-01</b> 504047974 	<b>X81859-01</b> 504022754 	<b>X54818-01</b> 504083813 NBR 	<b>P77458-01 K</b> ← 504056152 50x70x11 PTFE <b>P77459-01 K</b> → 504014232 90x120x13,65 FPM

