

CITROEN



0-9	
108C	352
109/5	354
109/5E	356
109/5F	354
109K	354
129/5	356
150A	364
150B (XY8)	364
150C	364
150D	364
150D (XY7)	364
150F	364
1580 SPI	372
159A	380
161 (XUD7)	376
161A (XUD7)	376
162 (XUD9)	386
169 (XM7T)	378
169B	378
170A (XN1T)	398
170B (XN1T)	398
170C (XN1T)	398-400
171A	368
171B	368
171C	368
171D	368
180A (XU5J)	372
180Z	368
1KR-FE	350
220 A2.000	372
3FZ (EW12J4)	404
4HN (DW12MTED4)	404
4HT (DW12BTED4)	404
4HU (P22DTE)	404
4HV (P22DTE)	404
4HW (DW12TED4)	406
4HX (DW12TED4)	406
4HY (DW12UTED4)	406
5FR (EP6DT)	372
5FS (EP6C)	374
5FT (EP6DT)	372
5FU (EP6DTS)	372
5FV (EP6CDT)	372
5FV (EP6DT)	372
5FW (EP6)	374
5FX (EP6DT)	372
6FY (EW7A)	378
6FZ (EW7J4)	380
8140.43S	412
829 A5	400
8FS (EP3)	364
8HR (DV4C)	364
8HS (DV4TD)	366
8HS (DV4TED)	366
8HT (DV4TD)	366
8HX (DV4TD)	358
8HY (DV4TED4)	366
9HT (DV6BTED4)	374
9HT (DV6BUTED4)	374
9HX (DV6ATED4)	374
9HY (DV6TED4)	374
9HZ (DV6TED4)	374
A	
A06/635	348



A79/0 (AYA)	348
A79/1 (AYA2)	348
A8A (XUD7TE)	374
A9A (XUD7)	376
AJZ (XUD7TE)	374
B	
B1A (XU51C/K)	368
B1E (XU51C)	368
B20/614	388
B22615	402
B25/637	406
B6D	368
B6E	368
BAY (XU5CP)	368
BAZ (XU5CP)	368
BDY (XU5M)	368
BDZ (XU5M)	368
BFZ (XU5JP)	368
C	
C1A	350
C3A	350
CDY (TU9M)	350
CDZ (TU9M)	350
CRD90	402
CRD93L (U25-661)	408
CRD93LS (U25-673)	408
D	
D2A (XU92C)	380
D2C (XU92C)	380
D2F	384
D6A (XU9J2)	384
D6C (XU9J4)	380
D6E (XU9JA)	386
D8B (XUD9TF)	382
D8C (XUD9UTF)	382
D9A (XUD9)	386
D9B (XUD9A/L)	384
D9B (XUD9A/U)	384
DDZ (XU9M)	380
DFW (XU9J4)	380
DFZ (XU9J1)	380
DHV (XUD9BSD)	382
DHW (XUD9SD)	382
DHX (XUD9TF/BTF)	382
DHY (XUD9TE/Y)	382
DJY (XUD9A)	384
DJZ (XUD9Y)	384
DKZ (XU9JA)	380
DT17ED4	410
DT20C	412
DV4D	358
DV6B	368
E	
E1A	352
F	
F1CE0481D (F30DT)	412
F28TDCR	412
G	
G10	350



G10/612	350
G11/631	352
G12/611	356
G12/612	356
G12/619	356
G13/625	358
G13/646	358
G1A	356
H	
H1A	352
H1B	352
HAZ (TU1CP)	352
HDZ (TU1M+)	352-354
HFX (TU1JP)	354
J	
J6T A500	402
K	
K1B	360
K1F	360
K1G	360
K1H (TU3A)	360
K2A	360
K2B	360
K2D	360
K3A	360
K9A (TUD3)	362
K9Y (TUD3Y)	362
KAY (TU3CP)	360
KAZ	360
KDX (TU3M/Z)	360
KDY (TU3FM)	360
KDY (TU3M)	360
KDZ (TU3M/Z)	360
KFU (ET3J4)	360
KFV (TU3JP)	362
KFW (TU3JP)	362
KFX (TU3JP)	362
KFY (TU3FJ2)	362
KFZ (TU3FJ2)	362
L	
LFX (XU7JB)	376
LFY (XU7JP4)	376
LFZ (XU7JP)	378
M	
M20-616	388
M22-617	402
M22-621	402
M23-622	406
M23-623	406
M23-639	406
M25-629	408
M25-648	408
M25-659	408
M25-660	408
M25-666	408
M25-669	408
M28 (AM2)	348
M28/1 (AK2)	348
M4 (AM)	348
M4A	358



N	
NFR (TU5JP4B)	370
NFS (TU5JP4S)	370
NFT	370
NFU (TU5JP4)	370
NFV (TU5JP)	370
NFX (TU5J4)	372
NFZ (TU5JP)	370
P	
P8A (XUD11ATE)	400
P8C (XUD11BTE)	400
P9A (XUD11A)	400
PHZ (XUD11ATE)	400
PJZ (XUD11ATE)	400
R	
R6A	398
RDZ (XU10MZ)	388
RFJ (EW10A)	388
RFK (EW10J4S)	388
RFN (EW10J4)	390
RFS (XU10J4RS)	390
RFT (XU10J4/Z)	390
RFU (XU10J2/C)	390
RFV (XU10J4R)	390
RFW (XU10J2U)	392
RFX (XU10J2C)	392
RFX (XU10J2C/Z L3)	392
RFY (XU10J4/Z)	392
RFZ (XU10J2)	388
RGX (XU10J2TE)	392
RGY (XU10J2TE/Z)	392
RHE (DW10CTED4)	394
RHH (DW10CTED4)	394
RHJ (DW10BTED4)	394
RHK (DW10UTED4)	394
RHM (DW10ATED4)	396
RHR (DW10BTED4)	394
RHS (DW10ATED)	396
RHT (DW10ATED4)	396
RHV (DW10UTD)	396
RHW (DW10ATED4)	396
RHX (DW10BTED)	396
RHY (DW10TD)	396
RHZ (DW10ATED)	396
RLZ (EW10D)	398
S	
SFZ (ZPJ/Z)	414
SKZ (ZPJ4/Z)	414
T	
T8A (DJ5T)	410
T9A (DJ5)	410
THX (DJ5TED)	410
THY (DK5ATE)	410
THZ (DJ5T)	410
TU9	350
U	
UFZ (ZPJ/Z)	414
UHZ (DT17BTED4)	410
UKZ (ZPJ4/Z)	414

CITROEN




V	
V06/665	348
V06 630	348
V06 644	348
VJY (TUD5)	366



VJZ (TUD5)	366
W	
WJY (DW8B)	386
WJZ (DW8)	386



X	
XFU (ES9A)	414
XFV (ES9A)	414
AFX (ES9J4S)	416
AFX (ES9J4)	416



XU102C	388
XU10J2	398
XU52C	368
XV8	350

CITROEN						
Ltr.						
0,4 A79/0 (AYA)	13 kW (18 PS) DYANE 4	08/67-03/68	A30034-00 (12) (14) ZC900026U S30034-00 (12) (13) ZC9000266U 			
0,4 A79/1 (AYA2)	17 kW (23 PS) DYANE 4 2 CV 4	04/68-12/75	A30746-00 (12) (14) 5463048G S30746-00 (12) (13) 0197.51 D30746-00 (12) 			
0,6 A06/635 M28 (AM2) M28/1 (AK2) M4 (AM)	18-24 kW (24-33 PS) ACADIANE 6 AMI 6 AMI 8 DYANE 6 MEHARI 2 CV 6	01/63-10/88	A30746-00 (12) (14) 5463048G S30746-00 (12) (13) 0197.51 D30746-00 (12) 			
0,6 V06 630	25-26 kW (34-35 PS) LNA VISA	09/78-06/88	S30998-00 (12) (13) 95539522 D30998-00 (12) 			
0,6 V06 644 V06/665	24-26 kW (33-35 PS) LNA VISA	09/78-03/91	S30307-00 (12) (13) 95552708 			
0,7 V06 644	25 kW (34 PS) AXEL	10/81-03/91	S30307-00 (12) (13) 95552708 			

(14) sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



X01457-01 A123-3 NBR 	2x	N91020-00 AYA124-63 P76531-00 0249.48 P76539-00 0956.19	2x 2x	X00774-01 AM141-2A 	4x X01458-01 Kork
X01142-01 75 516 398 NBR 	2x	N91020-00 AYA124-63 P76531-00 0249.48 P76539-00 0956.19	2x 2x	X00765-01 AM141-2D 	X00766-01 75505394
X01142-01 75 516 398 NBR 	2x	N91020-00 AYA124-63 P76531-00 0249.48 P76539-00 0956.19	2x 2x	X00765-01 AM141-2D 	X00766-01 75505394
X01142-01 75 516 398 NBR 	2x	N91020-00 AYA124-63 P76531-00 0249.48 P76539-00 0956.19	2x 2x	X00765-01 AM141-2D 	X00766-01 75505394
X01142-01 75 516 398 NBR 	2x	N91020-00 AYA124-63 P76531-00 0249.48 P76539-00 0956.19	2x 2x	X00765-01 AM141-2D 	X00766-01 75505394
X01142-01 75 516 398 NBR 	2x	N91020-00 AYA124-63 P76531-00 0249.48 P76539-00 0956.19	2x 2x	X00765-01 AM141-2D 	X00766-01 75505394



CITROEN						
Ltr.						
1,0 CDY (TU9M) CDZ (TU9M) C1A C3A TU9	10/84-06/03	30-37 kW (41-50 PS)	AX 10 C15 SAXO	S31113-00 ⑫ ⑬ 95619476 D31113-00 ⑫ 0197.H8 +0209.89 B31062-00 ⑬ ⑮ R30712-00 ③ 7701348178 (x4)	H07953-00 0209.89 74,3 Ø 1,3 mm H17953-10 74,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,0 G10 G10/612	09/70-12/77	40 kW (54 PS)	AMI 10 GS	S30460-00 ⑫ ⑬ 75518008 D30460-00 ⑫ 75518008 		
1,0 XV8	09/84-12/97	33 kW (45 PS)	C15 VISA	S31053-00 ⑫ ⑬ 95586978+91503885 S31586-00 ⑫ ⑬ 95586978+97531974 D31053-00 ⑫ 0197.75 D31586-00 ⑫ 95586979+97531974 B31053-00 ⑬ 0197.76 R30712-00 ③ 7701348178 (x4)	H00687-00 0209.G8 76 Ø 1,2 mm Centering 16 mm H10687-10 0203.23 76,3 Ø 1,4 mm Centering 16 mm H02370-00 0209.A6 76 Ø 1,2 mm Centering 14 mm H12370-10 0209.53 76,3 Ø 1,4 mm Centering 14 mm 	
1,0 1KR-FE	06/05→	50 kW (68 PS)	C1	S36775-00 ⑫ ⑬ 0197.AF D36775-00 ⑫ 0197.AG	H80621-00 0209.EC MLS 	T80621-00 6822.JC (8x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 X06310-01 1709.10 	X54035-01 ⑮ 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01270-01 2x 5491244 X01271-01 2x GX0127401A NBR 	N91500-00 0249.48 (4x) +0956.19 (4x) P76531-00 0249.48 P76539-00 0956.19 4x 4x	X01274-01 4x 75491223 	X01273-01 4x 75491350 		P76057-01 K ← 30x42x8 WD MVQ P76250-01 K → 7903087093 57,5x120x10 LD
X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.16 X81933-01 1710.41 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76353-01 K → 0514.74 85x105x8 A SL LD FPM
X83080-01 0349.C9 NBR 	N92658-00 0956.54 (12x)	X89098-01 0348.S4 	X81894-01 0349.L1 	70-31414-10 	P77413-01 K ← 6822.RC 38x50x6 A SL RD NBR P77436-01 K → 6822.X0 74x89x8,5 A SL LD MVQ

⑮ material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



CITROEN						
Ltr.						
1,0 108C	33 kW (45 PS) LNA VISA	07/84-06/88	S30652-00 ⑫ ⑬ 95551299 1 → 11/85 S31579-00 ⑫ ⑬ 12/85 → D30652-00 ⑫ 1 → 11/85 D31579-00 ⑫ 0197.74 12/85 → B31053-00 ⑬ 0197.76 12/85 → R30652-00 ③ 7910003960 R30712-00 ③ 7701348178 (x4)	H07125-00 74,3 Ø 1,2 mm Centering 16 mm 1 → 11/85 H17125-10 020322 74,3 Ø 1,4 mm Centering 16 mm 1 → 11/85 H02371-00 0209.46 74,3 Ø 1,2 mm Centering 14 mm 12/85 → H12371-10 0209.52 74,3 Ø 1,4 mm Centering 14 mm 12/85 → 		
1,1 E1A	35 kW (48 PS) C15	10/84-12/96	S30872-00 ⑫ ⑬ 16837800 D30872-00 ⑫ 0017476000	H05910-00 0013166700 76,7 Ø H15910-10 0209.28 76,7 Ø 1,8 mm 		
1,1 G11/631	40-42 kW (54-57 PS) AXEL 11 GS	09/77-03/91	S30460-00 ⑫ ⑬ 75518008 D30460-00 ⑫ 75518008 			
1,1 HAZ (TU1CP) HDZ (TU1M+) H1A H1B	40-44 kW (54-60 PS) AX 11 BERLINGO BX 11 C15 SAXO ZX	09/86 →	S31062-00 ⑫ ⑬ ⑤① 95619476+97520616 D31062-00 ⑫ ⑤① 0197.A7 B31062-00 ⑬ ⑤① R30712-00 ③ 7701348178 (x4)	H01004-10 ⑤① 0209.CJ 76,3 Ø 1,3 mm H11004-20 ⑤① 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.16 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR
X05764-01 0249.53 Kork 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07198-01 0348.80 	X05769-01 0349.E2 	X05920-01 0304.32 Kork X05923-01 0012853400 	P76119-01 K ← 00167744200 40x58x8 RD P76310-01 K → 0013195100 71x88x8 LD
X01270-01 2x 5491244 X01271-01 2x GX0127401A NBR 	N91500-00 0249.48 (4x) +0956.19 (4x) P76531-00 0249.48 P76539-00 0956.19 4x 4x	X01274-01 4x 75491223 	X01273-01 4x 75491350 		P76057-01 K ← 30x42x8 WD MVQ P76250-01 K → 7903087093 57,5x120x10 LD
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 X06310-01 1709.10 	X54035-01 ⑤① 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑤① material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



CITROEN

CITROEN						
Ltr.						
1,1 HDZ (TU1M+)	40 kW (54 PS)	SAXO	05/96-09/03	S31113-00 ⑫ ⑬ 95619476 D31113-00 ⑫ 0197.H8 +0209.89 B31062-00 ⑬ ⑤① R30712-00 ③ 7701348178 (x4)	H07953-00 0209.89 74,3 Ø 1,3 mm H17953-10 74,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,1 HFX (TU1JP)	44 kW (60 PS)	BERLINGO C2 C3 SAXO	05/96→	D36677-00 ⑫ B37002-00 ⑬	H80370-00 0209.Y0 73,5 Ø 1,25 mm 	T01004-00 0204.83 (10x)
1,1 109K 109/5 109/5F	35-42 kW (48-57 PS)	C15 VISA 11	09/78-12/96	S31588-00 ⑫ ⑬ 95551299 ① →12/85 S31589-00 ⑫ ⑬ 0198.59 ① 01/86→ D31588-00 ⑫ 0197.74 ① →12/85 D31589-00 ⑫ 0197.75 +0209.A6 ① 01/86→ B31588-00 0197.76 R30712-00 ③ 7701348178 (x4)	H00687-00 0209.G8 76 Ø 1,2 mm Centering 16 mm ① →12/85 H10687-10 0203.23 76,3 Ø 1,4 mm Centering 16 mm ① →12/85 	H02370-00 0209.A6 76 Ø 1,2 mm Centering 14 mm ① 01/86→ H12370-10 0209.53 76,3 Ø 1,4 mm Centering 14 mm ① 01/86→

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 	X54035-01 ⑤① 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X87172-01 4x 0342.E0 	X82381-01 ✗ 0349.J6 	X54035-01 ⑤① 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.16 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR

⑤① material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



CITROEN						
Ltr.						
1,1 109/5E	37 kW (50 PS) LNA	07/82-04/85	S31588-00 ⑫ ⑬ 95551299 D31588-00 ⑫ 0197.74 B31588-00 0197.76 R30712-00 ③ 7701348178 (x4)	H00687-00 0209.G8 76 Ø 1,2 mm 16 mm H10687-10 0203.23 76,3 Ø 1,4 mm 16 mm 		
1,2 G12/611 G12/612 G12/619	43-46 kW (58-63 PS) GS GS X 2	04/73-07/79	S30460-00 ⑫ ⑬ 75518008 D30460-00 ⑫ 75518008 			
1,2 129/5	47 kW (64 PS) VISA Super X	07/80-06/82	S31588-00 ⑫ ⑬ 95551299 D31588-00 ⑫ 0197.74 B31588-00 0197.76 R30712-00 ③ 7701348178 (x4)	H00687-00 0209.G8 76 Ø 1,2 mm Centering 16 mm H10687-10 0203.23 76,3 Ø 1,4 mm Centering 16 mm H02370-00 0209.A6 76 Ø 1,2 mm Centering 14 mm H12370-10 0209.53 76,3 Ø 1,4 mm Centering 14 mm 		
1,3 G1A	47 kW (64 PS) C15	07/87-05/88	S30741-00 ⑫ ⑬ 0017477200 D30741-00 ⑫ 0016806800	H06900-00 0209.J0 78,5 Ø 1,2 mm 		

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.16 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR
X01270-01 2x 5491244 X01271-01 2x GX0127401A NBR 	N91500-00 0249.48 (4x) +0956.19 (4x) P76531-00 0249.48 P76539-00 0956.19 4x 4x	X01274-01 4x 75491223 	X01273-01 4x 75491350 		P76057-01 K ← 30x42x8 WD MVQ P76250-01 K → 7903087093 57,5x120x10 LD
X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.16 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR
X05764-01 0249.53 Kork 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X05917-01 0055204500 X07198-01 0348.80 	X05769-01 0349.E2 X07077-01 0016175200 	X05920-01 0304.32 Kork X05923-01 0012853400 	P76119-01 K ← 00167744200 40x58x8 RD P76310-01 K → 0013195100 71x88x8 LD



CITROEN						
Ltr.						
1,3 G13/625 G13/646	48 kW (65 PS) GS	09/79-07/86	S30460-00 ⑫ ⑬ 75518008 D30460-00 ⑫ 75518008 			
1,3 M4A	70 kW (95 PS) AX 13 Sport	04/87-12/88	S31437-00 ⑫ ⑬ D31437-00 ⑫ B31062-00 ⑬ ⑮ R30712-00 ③ 7701348178 (x4)	H01004-10 ⑤① 0209.CJ 76,3 Ø 1,3 mm H11004-20 ⑤① 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x) 	
1,4 DV4D 8HX (DV4TD)	40-50 kW (54-68 PS) C1 HDI C2 HDI C3 HDI C3 Pluriel HDI XSARA HDi XSARA HDI	02/02→	S36724-00 ⑫ ⑬ D36724-00 ⑫ B36724-00 ⑬	H08129-00 0209.AC 1,2 mm 2 MLS H08129-10 0209.AE 1,3 mm 3 MLS H08129-20 0209.AF 1,35 mm 1 MLS H18129-30 0209.AG 1,4 mm 4 MLS H18129-40 0209.AH 74,7 Ø 1,45 mm 5 MLS 	T08130-00 0204.A2 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X01270-01 2x 5491244 	N91500-00 0249.48 (4x) +0956.19 (4x) P76531-00 4x 0249.48 P76539-00 4x 0956.19	X01274-01 4x 75491223 	X01273-01 4x 75491350 		P76057-01 K ← 30x42x8 WD MVQ P76250-01 K → 7903087093 57,5x120x10 LD
X01271-01 2x GX0127401A NBR 					
X06304-01 0249.54 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X06306-01 2x 0349.A6 X06310-01 1709.10 	X54035-01 ⑤① 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
V38516-00 0249.F8 +0348.T8 (4x) +0348.S8 (2x) 	N92983-00 0956.50 (8x) P76779-00 0956.50 8x	W88317-01 4x 0348.R2 	X81696-01 0349.J8 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM
X83035-01 0249.F8 NBR 					

⑤① material bloque motor Alumini / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



CITROEN						
Ltr.						
1,4 KAY (TU3CP) KAZ KDX (TU3M/Z) KDY (TU3FM) KDY (TU3M) K1B K1F K1G K1H (TU3A) K2A K2B K2D K3A	40-62 kW (54-85 PS)	AX AX 14 BX 14 C15 ZX	04/83→	S31062-00 (12) (13) (51) 95619476+97520616 S31600-00 (12) (13) (53) 0197.J1+0209.A9 D31062-00 (12) (51) 0197.A7 D31600-00 (12) (53) 0197.J0 +0209.A9 B31062-00 (13) (51) B31600-00 (13) R30712-00 (3) 7701348178 (x4)	H01004-10 (51) 0209.CJ 76,3 Ø 1,3 mm H11004-20 (51) 0209.CK 76,3 Ø 1,5 mm H08191-00 (53) 0209.A9 76,3 Ø 1,2 mm H18191-10 (53) 0209.92 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,4 KDZ (TU3M/Z)	55 kW (75 PS)	AX 14 BX 14 ZX	04/87-06/97	S31062-00 (12) (13) (51) 95619476+97520616 D31062-00 (12) (51) 0197.A7 B31062-00 (13) (51) R30712-00 (3) 7701348178 (x4)	H01004-10 (51) 0209.CJ 76,3 Ø 1,3 mm H11004-20 (51) 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,4 KFU (ET3J4)	65 kW (88 PS)	C3 16V C4 16V	12/03→	D37222-00 (12) B37222-00 (13)	H80612-00 0209.FL 76 Ø 1,4 mm 	T80612-00 0204.A5 (10x)
1,4 KFU (ET3J4)	65 kW (90 PS)	C2	06/06→	D37222-00 (12) B37222-00 (13)	H80612-00 0209.FL 76 Ø 1,4 mm 	T80612-00 0204.A5 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра
 ⑤ material bloque motor Alumini / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 X06310-01 1709.10 	X54035-01 (51) 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 X06310-01 1709.10 	X54035-01 (51) 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X83066-01 R 0249.C5 X83067-01 L 0249.C4 	N93130-00 0956.52 (16x) P76841-00 0956.52 16x	M36836-00 0348.S1 	X81664-01 0349.J4 X82404-01 1709.29 	70-31414-10 	P77669-01 K ← 0514.A3 42x66x7 A SL RD P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77492-01 N 0807.32 36x50x8 A SL RD PTFE ACM P77593-01 N 0807.33 24x50x8 A SL RD
X83066-01 R 0249.C5 X83067-01 L 0249.C4 	N93130-00 0956.52 (16x) P76841-00 0956.52 16x	M36836-00 0348.S1 	X82016-01 0349.L6 X82404-01 1709.29 	70-31414-10 	P77669-01 K ← 0514.A3 42x66x7 A SL RD P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77492-01 N 0807.32 36x50x8 A SL RD PTFE ACM P77593-01 N 0807.33 24x50x8 A SL RD

⑤ material bloque motor Fonte grise / Motorblockmaterial Grauguß / engine Block Material Grey Cast Iron / matériel pour bloc-moteur / materiale blocco motore A getto di ghisa grigia / материал блока двигателя Серый чугун



CITROEN						
Ltr.						
1,4 KfV (TU3JP) KfW (TU3JP) KfX (TU3JP)	48-55 kW (65-75 PS)	BERLINGO C2 C3 C3 Pluriel SAXO VTS XSARA ZX	03/91→	S32984-00 ⑫ ⑬ D32984-00 ⑫ 0197.H8+0209.CJ B31600-00 ⑬ R30712-00 ③ 7701348178 (x4)	H01004-10 ⑤① 0209.CJ 76,3 Ø 1,3 mm H11004-20 ⑤① 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,4 KfY (TU3FJ2) KfZ (TU3FJ2)	66-74 kW (90-100 PS)	AX 14 GTI	06/91-12/96	D37003-00 ⑫ 0197.J0 +0209.D6 R30712-00 ③ 7701348178 (x4)	H80549-00 0209.D6 77 Ø 1,2 mm H80549-10 0209.C1 77 Ø 1,4 mm 	T01004-00 0204.83 (10x)
1,4 K9A (TUD3) K9Y (TUD3Y)	37-38 kW (50-52 PS)	AX 14 D ZX D	09/88-12/97	S31055-00 ⑫ ⑬ 0197.K2 D31055-00 ⑫ 0197.K3 B31055-00 ⑬ R30712-00 ③ 7701348178 (x4)	H03751-00 0209.E9 76,3 Ø H80573-00 0209.N4 MLS 	T03751-00 0204.84 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X87172-01 0342.E0 4x 	X06306-01 2x 0349.A6 X82381-01 ✗ 0349.J6 Emission reduction FL5 X82382-01 ✗ 0349.J3 Exhaust norm L4 X06310-01 ⚠ 1709.10 	X54035-01 ⑤① 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 ⚠ X06310-01 1709.10 	70-31414-10 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X05398-01 0249.76 	N90300-00 0249.48 (8x) P76532-00 0956.19 8x		X05443-01 0349.E4 X05444-01 ⚠ 1710.58 	X54035-01 ⑤① 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑤① material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



CITROEN						
Ltr.						
1,4 150A 150B (XY8) 150C 150D 150D (XY7) 150F	44-58 kW (60-79 PS)	BX BX 14 C15 VISA 14 VISA 14 GT	03/82→	S31053-00 ⑫ ⑬ 95586978+91503885 S31586-00 ⑫ ⑬ 95586978+97531974 D31053-00 ⑫ 0197.75 D31586-00 ⑫ 95586979+97531974 B31053-00 ⑬ 0197.76 R30712-00 ③ 7701348178 (x4)	H00687-00 0209.G8 76 Ø 1,2 mm Centering 16 mm H10687-10 0203.23 76,3 Ø 1,4 mm Centering 16 mm H02370-00 0209.A6 76 Ø 1,2 mm Centering 14 mm H12370-10 0209.53 76,3 Ø 1,4 mm Centering 14 mm 	
1,4 8FS (EP3)	70 kW (95 PS)	C3	02/09→	D40616-00 ⑫ ⑰ D40616-01 ⑫ H40616-00 0209.EW 78 Ø 0,9 mm MLS H40616-10 X 78 Ø 1,2 mm MLS 	T40616-00 0204.C1 	
1,4 8HR (DV4C)	50 kW (68 PS)			H40604-00 0209.HH 74,7 Ø 1,25 mm MLS 4 M H40604-10 0209.HJ 74,7 Ø 1,3 mm MLS 5 M H40604-20 0209.HK 74,7 Ø 1,35 mm MLS 3 M H40604-30 0209.HL 74,7 Ø 1,4 mm MLS 6 M H40604-40 0209.HN 74,7 Ø 1,45 mm MLS 7 M 	T40595-00 0205.57 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.16 X81933-01 1710.41 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR
V38326-00 0249.F4 	N93158-00 0956.60 P93158-00 16x	M59582-00 0348.T4 (4X) 	X59642-01 1723.CH 	70-31414-10 	P77789-01 K ← 0514.C8 61x75x8 A SL RD P77670-01 K → 0514.A2 85x105x8 A SL LD
X83409-01 0249.G2 	N92983-00 0956.50 (8x) P76779-00 0956.50 8x	X59534-01 0349.N9 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM	

⑰ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



CITROEN						
Ltr.						
1,4	8HS (DV4TD) 8HS (DV4TED) 8HT (DV4TD) [NEW]	40-50 kW (54-68 PS) NEMO HDI	02/08→	S36724-01 0197.AV +0956.50 (8x) D36724-00 	H08129-00 0209.AC 1,2 mm MLS H08129-10 0209.AE 1,3 mm MLS H08129-20 0209.AF 1,35 mm MLS H18129-30 0209.AG 1,4 mm MLS H18129-40 0209.AH 74,7 Ø 1,45 mm MLS 	T08130-00 0204.A2 (10x)
1,4	8HY (DV4TED4)	66 kW (90 PS) C3 HDI 16V	02/02→	S36730-00 D36730-00 B36724-00	H40137-00 0209.AJ 74,7 Ø 1,25 mm MLS H40137-10 0209.AK 74,7 Ø 1,3 mm MLS H40137-20 0209.AL 74,7 Ø 1,35 mm MLS H40137-30 0209.AN 74,7 Ø 1,4 mm MLS H40137-40 0209.AP 74,7 Ø 1,45 mm MLS 	T08130-00 0204.A2 (10x)
1,5	VJY (TUD5) VJZ (TUD5)	40-43 kW (54-58 PS) AX 15 D SAXO D XSARA D	08/94-09/03	S31599-00 D31599-00 0197.V1 +0209.T8 B31599-00 0197.V0 R30712-00 7701348178 (x4)	H80263-00 0209.T8 78 Ø MLS 	T50321-00 0204.85 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



V38516-00 0249.F8 +0348.T8 (4x) +0348.S8 (2x) 	N92983-00 0956.50 (8x) P76779-00 0956.50 8x		X81696-01 0349.J8 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM
X83035-01 0249.F8 NBR 	N93118-00 0956.51 (16x) P76780-00 0956.51 16x	W88321-01 0348.R4 4x W88322-01 0348.R5 4x 	X81696-01 0349.J8 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM
X53099-01 0249.81 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x		X05443-01 0349.E4 X05444-01 1710.58 	70-31414-10 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM



CITROEN						
Ltr.						
1,6 BAY (XU5CP) BAZ (XU5CP) BDY (XU5M) BDZ (XU5M) B1A (XU51C/K) B1E (XU51C)	01/87-10/97	53-65 kW (72-88 PS) BX 16 ZX	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T01025-00 0204.57 (10x)	
1,6 BFZ (XU5JP)	03/91-01/98	65 kW (88 PS) XANTIA ZX	S31580-00 ⑫ ⑬ D31580-00 ⑫ 0197.G4 B31580-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T01025-00 0204.57 (10x)	
1,6 B6D B6E XU52C 171A 171B 171C 171D 180Z	10/82-12/94	64-85 kW (87-116 PS) BX BX 16 VISA 16 GTI	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T11025-00 0204.89 (10x) ① →03/87 T01025-00 0204.57 (10x) ① 04/87→	
1,6 DV6B	07/05→	55 kW (75 PS) BERLINGO HDI 75	D36730-00 ⑫ B36724-00 ⑬	H08130-00 0209.CA 76 Ø 1,25 mm 4 MLS H08130-10 0209.CC 76 Ø 1,3 mm 5 MLS H08130-20 0209.CE 76 Ø 1,35 mm 3 MLS H18130-30 0209.CF 76 Ø 1,4 mm 6 MLS H18130-40 0209.CG 76 Ø 1,45 mm 7 MLS	T08130-00 0204.A2 (10x)	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07803-01 X07804-01 	X01022-01 0349.70 4x X03013-01 1721.01 	X04848-01 0127.05 NBR 2x X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X53101-01 0249.71 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56171-01 0348.F6 2x X56170-01 ⑩ 2x 0348.E6 	X52670-01 1723.63 	X04848-01 0127.05 NBR 2x X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07803-01 X07804-01 	X01022-01 0349.70 4x X03013-01 1721.01 	X04848-01 0127.05 NBR 2x X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X83038-01 0249.C2 NBR 	N93118-00 0956.51 (16x) P76780-00 0956.51 16x	W88321-01 0348.R4 4x W88322-01 0348.R5 4x 	X81696-01 0349.J8 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



CITROEN						
1,6 NFR (TU5JP4B)	66 kW (90 PS)	BERLINGO	04/08→	D36693-00 ⑫ B36693-00 ⑬	H80497-00 0209.1E 78,5 Ø MLS 	T04220-00 0204.81 (10x)
1,6 NFS (TU5JP4S)	90 kW (122 PS)	C2 VTS	01/05→	D38024-00 ⑫ B38100-00 ⑬	H80497-00 0209.1E 78,5 Ø MLS 	T04220-00 0204.81 (10x)
1,6 NFT NFV (TU5JP) NFZ (TU5JP)	65-74 kW (88-101 PS)	SAXO SAXO VTL,VTR SAXO VTS XSARA XSARA PICASSO	02/96→	S31601-00 ⑫ ⑬ 0197.J1 D31601-00 ⑫ 0197.J0 B31600-00 ⑬ 	H08194-00 0209.F6 79 Ø →07874 H09196-00 0209.W8 1,38 mm MLS →07875→ H19196-10 0209.W9 79,7 Ø 1,57 mm MLS →07875→ 	T01004-00 0204.83 (10x)
1,6 NFU (TU5JP4)	80-81 kW (109-110 PS)	BERLINGO BERLINGO 16V C2 C3 Pluriel C3 16V C4 C4 16V XSARA PICASSO 16V XSARA 16V	09/00→	D36693-00 ⑫ B36693-00 ⑬	H80497-00 0209.1E 78,5 Ø MLS 	T04220-00 0204.81 (10x)

X83028-01 0249.A9 NBR 	2x	N92004-00 0956.40 (16x) P76809-00 0956.40	16x	M74443-00 0348.05 	X81664-01 0349.J4 X81500-01 1709.25 	X54807-01 0304.55 NBR 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77141-01 N 2x 0807.24 38x50x6 A SL RD FPM
X83028-01 0249.A9 NBR →2336722 X59782-01 X 2x →2336723→ 	2x	N92004-00 0956.40 (16x) P76809-00 0956.40	16x	X89345-01 0342.J6 X89880-01 0342.J5 	X82016-01 0349.L6 	70-31414-10 	P77669-01 K ← 0514.A3 42x66x7 A SL RD P77670-01 K → 0514.A2 85x105x8 A SL LD P77623-01 N 2x 0807.34 38x50x7 A SL RD
X06304-01 0249.54 		N91190-00 0956.19 (8x) P76532-00 0956.19	8x	M38099-00 0348.P3 (4x) X86028-01 0348.E5 →07874 X82384-01 0348.P3 →07875→ 	X06306-01 2x 0349.A6 X82382-01 0349.J3 X81500-01 1709.25 		P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76355-11 K → 85x105x9 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X83028-01 0249.A9 NBR →2336722 X59782-01 X 2x →2336723→ 	2x	N92004-00 0956.40 (16x) P76809-00 0956.40	16x	M74443-00 0348.05 	X81664-01 0349.J4 X81500-01 1709.25 	X54807-01 0304.55 NBR 	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77141-01 N 2x 0807.24 38x50x6 A SL RD FPM

I interior / innen / inside / intérieur / interno / внутри



CITROEN

CITROEN						
Ltr.						
1,6 NFX (TU5J4)	87-88 kW (118-120 PS)	SAXO SAXO VTS	02/96-04/04	S32979-00 ⑫ ⑬ 0197.F1 D32979-00 ⑫ B32979-00 ⑬	H04220-00 0209.Z0 1,4 mm 6 ■ MLS H14220-10 0209.W3 1,57 mm 7 ■ MLS H24220-20 0209.Z1 79,7 Ø 1,77 mm 8 ■ MLS	T04220-00 0204.81 (10x)
1,6 1580 SPI 220 A2.000	58 kW (79 PS)	JUMPY	10/95→	S32919-00 ⑫ ⑬ D32919-00 ⑫ B32919-00 ⑬	H00593-10 0209.P9 87 Ø	T05082-00
1,6 180A (XU5J)	76 kW (103 PS)	VISA 16 GTI	01/85-06/86	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T11025-00 0204.89 (10x)
1,6 5FR (EP6DT) 5FT (EP6DT) 5FU (EP6DTS) 5FV (EP6CDT) 5FV (EP6DT) 5FX (EP6DT)	103-135 kW (140-184 PS)	C4 C5 DS3 DS4 DS5	07/08→	D40634-00 ⑫ ⑰ D40634-01 ⑫ 	H40634-00 0209.ER 78 Ø 0,9 mm MLS H40634-10 X 0209.HP 78 Ø 1,3 mm MLS	T40616-00 0204.C1

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

⑰ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



70-31414-10 	N92004-00 0956.40 (16x) P76809-00 0956.40	X58964-01 0348.L0	4x	X52322-01 0349.F9 X52323-01 1709.12	70-31414-10
X01619-01 U 	N90300-00 0249.48 (8x) P76531-00 0249.48	X51425-01 ⑦ 	8x	X00688-01 0304.49 Gummi	P76154-01 K ← 0514.72 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77141-01 N 2x 0807.24 38x50x6 A SL RD FPM
X53175-01 0 	X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48	8x	X07803-01 	P76117-01 K ← 40x56x7 A SL RD MVQ P76273-01 K → 64x80x8 A SL LD MVQ P76060-01 N 30x52x7 AB SL RD FPM
X53734-01 0249.84 Kork 	X07804-01 	X07803-01 	8x	X01022-01 0349.70	X04848-01 2x 0127.05 NBR X07793-01 0304.34
V38327-00 0249.E6 +0249.E7 	N93158-00 0956.60 P93158-00	M59583-00 0348.S9	16x	X03013-01 ① 1721.01 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
		X59643-01 1723.AZ 		70-31414-10 	P77789-01 K ← 0514.C8 61x75x8 A SL RD P77670-01 K → 0514.A2 85x105x8 A SL LD

① con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров

0 arriba / oben / top / haut / superiore / сверху
U debajo / unten / bottom / bas / inferiore / снизу



CITROEN						
Ltr.						
1,6 5FS (EP6C) 5FW (EP6)	07/08→	88 kW (120 PS) BERLINGO C3 C4 C5 DS3 DS4	D40616-00 ⑫ ⑬ D40616-01 ⑫	H40616-00 0209.EW 78 Ø 0,9 mm MLS H40616-10 X 78 Ø 1,2 mm MLS	T40616-00 0204.C1	
1,6 9HT (DV6BTED4) 9HT (DV6BUTED4) 9HX (DV6ATED4) 9HY (DV6TED4) 9HZ (DV6TED4)	05/04→	55-80 kW (75-109 PS) BERLINGO HDI BERLINGO HDI 90 C2 HDI C3 HDI C3 HDI 16V C4 C4 HDI C4 HDI 110 FAP C4 HDI 90 C5 HDI XSARA PICASSO HDI	S36730-00 ⑫ ⑬ D36730-00 ⑫ B36724-00 ⑬	H08130-00 0209.CA 76 Ø 1,25 mm 4 M MLS H08130-10 0209.CC 76 Ø 1,3 mm 5 M MLS H08130-20 0209.CE 76 Ø 1,35 mm 3 M MLS H18130-30 0209.CF 76 Ø 1,4 mm 6 M MLS H18130-40 0209.CG 76 Ø 1,45 mm 7 M MLS	T08130-00 0204.A2 (10x)	
1,8 AJZ (XUD7TE) A8A (XUD7TE)	03/88-12/94	66 kW (90 PS) BX TRD BX 18 TRD	S31587-00 ⑫ ⑬ 0197.H5 D31587-00 ⑫ B30527-00 ⑬	H02299-00 0209.Q0 1,6 mm 2 M H12299-10 0209.G0 82 Ø 1,75 mm 3 M	T08280-00 0204.65 (10x)	

⑫ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



V38326-00 0249.F4	N93158-00 0956.60 P93158-00 16x	M59582-00 0348.T4 (4X)	X59642-01 1723.CH	70-31414-10	P77789-01 K ← 0514.C8 61x75x8 A SL RD P77670-01 K → 0514.A2 85x105x8 A SL LD
X83038-01 0249.C2 NBR	N93118-00 0956.51 (16x) P76780-00 0956.51 16x	W88321-01 4x 0348.R4 W88322-01 4x 0348.R5	X81696-01 0349.J8	70-31414-10	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM
X07796-01 0249.91	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X51229-01 ⑦ 0348.89 ① →12/90 X51239-01 ⑦ 0348.J0 ① 01/91→	X04848-01 2x 0127.05 NBR X07793-01 0304.34	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM	

⑬ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



CITROEN						
Ltr.						
1,8 A9A (XUD7) 161 (XUD7) 161A (XUD7)	43-44 kW (58-60 PS) BERLINGO D BX 18 D C15 D VISA 17 D XSARA D ZX D	04/84→	S30527-00 ⑫ ⑬ 0197.H5 D30527-00 ⑫ 0197.H4 +0956.22 (8x) B30527-00 ⑬	H05875-00 0209.S0 1,36 mm 1 H05875-10 0209.S1 1,4 mm 2 H05875-20 0209.S2 1,44 mm 3 H15875-30 0209.S3 1,48 mm 4 H15875-40 0209.S4 82 Ø 1,53 mm 5 H08280-00 0209.F9 1,57 mm 2 H18280-10 1,7 mm 3	T08280-00 0204.65 (10x) 	
1,8 LFX (XU7JB)	66 kW (90 PS) BERLINGO XANTIA XSARA	04/97→	S36241-00 ⑫ D36241-00 ⑫ B31580-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 		
1,8 LFY (XU7JP4)	81-82 kW (110-111 PS) XANTIA 16V XSARA 16V ZX ZX 16V	06/95-04/03	S37004-00 ⑫ ⑬ 0197.V5 +0209.Q3 +0249.A2 +0249.A3 → 07965 S32980-00 ⑫ ⑬ 0197.X7 +0209.Q3 +0249.A2 +0249.A3 → 07966→ D37004-00 ⑫ → 07965 D32980-00 ⑫ → 07966→ B32980-00 ⑬	H80030-00 0209.Q3 84 Ø 	T80030-00 0204.80 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X07796-01 0249.91 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X55498-01 0348.99 2x X55499-01 0348.98 	X07782-01 0349.78 2x X03013-01 1721.01 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM
X53101-01 0249.71 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X85532-01 0348.L7 4x 	X52670-01 1723.63 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X53731-01 L 0249.A2 X53732-01 R 0249.A3 	N93063-00 0956.34 (16x) → 07363 N93062-00 0956.42 (16x) → 07364→ → 07965 N92657-00 0956.45 (16x) → 07966→ P76817-00 0956.34 → 07363 P76750-00 0956.42 → 07364→ → 07965 P76657-00 0956.45 → 07966→	X56177-01 0348.C8 → 07037 X58966-01 0348.K6 4x → 07038→ 	X52325-01 0349.F4 → 07664 X52324-01 0349.H0 → 07665→ 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM



CITROEN						
Ltr.						
1,8 LFZ (XU7JP)	73 kW (99 PS) EVASION	05/97-07/02	D31580-02 ⑫ B31580-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T01025-00 0204.57 (10x) 	
1,8 LFZ (XU7JP)	74 kW (101 PS) XANTIA XSARA ZX	07/92-09/00	S31580-00 ⑫ ⑬ D31580-00 ⑫ 0197.G4 B31580-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T11025-00 0204.89 (10x) → PR3975 T01025-00 0204.57 (10x) → PR3975 	
1,8 169 (XM7T) 169B	49-51 kW (68-69 PS) C25	11/81→	S30778-00 ⑫ ⑬ D30778-00 ⑫	H02666-00 86,7 Ø 	T02666-00 i → 06/85 T02760-00 0204.51 (10x) i 07/85-04/89 T01025-00 0204.57 (10x) i 05/89→ 	
1,8 169 (XM7T)	51 kW (69 PS) C25 Bus	07/87-02/94	S30778-00 ⑫ ⑬ D30778-00 ⑫	H02666-00 86,7 Ø 	T02760-00 0204.51 (10x) i → 04/89 T01025-00 0204.57 (10x) i 05/89→ 	
1,8 6FY (EW7A)	92 kW (125 PS) C4 C5 C5 16V	09/05→		H80768-00 0209.FR MLS 	T80768-00 0204.A3 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x 	X56171-01 0348.F6 2x 	X01022-01 0349.70 4x 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X53101-01 0249.71 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x 	X56171-01 0348.F6 2x X56170-01 ⑩ 2x 0348.E6 	X52670-01 1723.63 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x 	X07480-01 	X04833-01 0349.03 	X04848-01 2x 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x 	X07480-01 	X04833-01 0349.03 	X04848-01 2x 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
	N92657-00 0956.45 (16x) P76657-00 0956.45 16x 	X89881-01 0348.S2 4x 	X82335-01 0349.L4 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM P77626-01 N 0236.74 39x50x7 A SL RD

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



CITROEN						
Ltr.						
1,8 6FZ (EW7J4)	85 kW (115-116 PS) C5 16V XSARA XSARA PICASSO 16V	02/00→	S36503-00 ⑫ ⑬ 0197.Y1 +0209.QG +0249.A4 +0249.A5 D36503-00 ⑫ B36503-00 ⑬	H80288-00 0209.QG 83 Ø MLS 	T07586-00 0204.A7 (10x) 	
1,9 DDZ (XU9M) DFZ (XU9J1) DKZ (XU9JA) D2A (XU92C) D2C (XU92C) 159A	70-88 kW (95-120 PS) BX 19 BX 19 GTI ZX →PR3975 →PR3975 →PR3975	07/86-06/97	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T11025-00 0204.89 (10x) 	
1,9 DDZ (XU9M) DFZ (XU9J1) DKZ (XU9JA) D2A (XU92C) D2C (XU92C) 159A	70-88 kW (95-120 PS) BX 19 BX 19 GTI ZX →PR3976→ →PR3976→ →PR3976→	07/86-06/97	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T01025-00 0204.57 (10x) 	
1,9 DFW (XU9J4) D6C (XU9J4)	108-116 kW (147-158 PS) BX 19 GTI 16V	09/87-02/93	S31051-00 ⑫ ⑬ 95625018+0209.L3 D31051-00 ⑫ 0197.J2 +0209.L3 B31051-00 ⑬ R31124-00 ③	H07312-00 0209.L7 84,3 Ø 	T01025-00 0204.57 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X53933-01 L 0249.A4 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X86822-01 4x 0348.P1 	X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X53934-01 R 0249.A5 					
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07803-01 X07804-01 	X01022-01 4x 0349.70 X03013-01 △ 1721.01 X07798-01 △ 1710.39 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07803-01 X07804-01 	X01022-01 4x 0349.70 X03013-01 △ 1721.01 X07798-01 △ 1710.39 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X07519-01 0249.74 NBR 	N91190-00 0956.19 (8x) P76532-00 0956.19 16x	X07309-01 2x 0348.G4 	X05751-01 0349.E8 	X04848-01 2x 0127.05 NBR X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76128-11 N 2x 0236.24 32x45x8 A LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM



CITROEN						
Ltr.						
1,9 DHV (XUD9BSD)	55 kW (75 PS) XSARA D XSARA SD	01/98-09/00	B30527-00 ¹³	H05877-00 0209.Q8 1,36 mm MLS 1 H05877-10 0209.Q9 1,4 mm MLS 2 H05877-20 0209.R0 1,44 mm MLS 3 H15877-30 0209.R1 1,48 mm MLS 4 H15877-40 0209.R2 84 Ø 1,53 mm MLS 5 	T02360-00 0204.73 (10x) 	
1,9 DHW (XUD9SD) DHX (XUD9TF/BTF) DHY (XUD9TE/Y) D8B (XUD9TF) D8C (XUD9UTF)	55-68 kW (75-92 PS) EVASION EVASION TD JUMPER Bus TD JUMPER TD JUMPY TD XANTIA SD XANTIA TD XSARA TD ZX TD	07/92→	S31582-00 ^{12 13} 0197.H5 D31582-00 0197.H4 B31582-00 ¹³	H02360-00 0209.Q5 1,65 mm H12360-10 0209.Q6 1,75 mm H05877-00 0209.Q8 1,36 mm MLS 1 H05877-10 0209.Q9 1,4 mm MLS 2 H05877-20 0209.R0 1,44 mm MLS 3 H15877-30 0209.R1 1,48 mm MLS 4 H15877-40 0209.R2 84 Ø 1,53 mm MLS 5 H15877-50 0209.T7 84 Ø 1,59 mm MLS H15877-60 84 Ø 1,7 mm MLS 	T02360-00 0204.73 (10x) 	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



X07796-01 0249.91 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X03013-01 1721.01 	X07793-01 0304.34 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM
X07796-01 0249.91 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X03013-01 ⁷ 1721.01 	X07793-01 0304.34 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM



CITROEN						
Ltr.						
1,9 DJY (XUD9A) DJZ (XUD9Y) D9B (XUD9A/L) D9B (XUD9A/U)	47-51 kW (64-70 PS)	BERLINGO D BX 19 D C25 Bus D C25 D JUMPER Bus D JUMPER D JUMPY D XANTIA D XSARA D ZX D	09/83→	S31582-00 0197.H5 D31582-00 0197.H4 B31582-00	H02359-00 0209.K0 84 Ø 1,6 mm 2 H12359-10 84 Ø 1,7 mm 3 H05876-00 0209.S5 1,36 mm 1 H05876-10 0209.S6 1,4 mm 2 H05876-20 0209.S7 1,44 mm 3 H15876-30 0209.S8 1,48 mm 4 H15876-40 0209.S9 84 Ø 1,53 mm 5	T08280-00 0204.65 (10x)
1,9 D2F D6A (XU9J2)	80-92 kW (109-125 PS)	BX BX 19 BX 19 GTI	PR3976→ 07/86-12/94 PR3976→	S30559-00 0197.89 D30559-00 0197.H6 +0209.E1 B30559-00 R31124-00	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T01025-00 0204.57 (10x)
1,9 D6A (XU9J2)	90-92 kW (122-125 PS)	BX BX 19 GTI	PR3975 07/86-12/94 PR3975	S30559-00 0197.89 D30559-00 0197.H6 +0209.E1 B30559-00 R31124-00	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T11025-00 0204.89 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X07796-01 0249.91 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X03013-01 1721.01 X51229-01 0348.89 	X04848-01 0127.05 NBR X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM 2x	
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07803-01 X07804-01 	X01022-01 0349.70 4x X03013-01 1721.01 X07798-01 1710.39 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07803-01 X07804-01 	X01022-01 0349.70 4x X03013-01 1721.01 X07798-01 1710.39 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



CITROEN						
Ltr.						
1,9 D6E (XU9JA)	93 kW (126 PS) ZX	03/91-06/97	S31411-00 ⑫ ⑬ 95659565 D31411-00 ⑫ 95659566 R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T01025-00 0204.57 (10x)	
1,9 D9A (XUD9) 162 (XUD9)	47 kW (64 PS) BX 19 D	09/83-11/94	S30527-00 ⑫ ⑬ 0197.H5 D30527-00 ⑫ 0197.H4 +0956.22 (8x) B30527-00 ⑬	H05876-00 0209.S5 1,36 mm 1 H05876-10 0209.S6 1,4 mm 2 H05876-20 0209.S7 1,44 mm 3 H15876-30 0209.S8 1,48 mm 4 H15876-40 0209.S9 84 Ø 1,53 mm 5 H07781-00 0209.K0 1,58 mm H17781-10 0209.K1 1,7 mm	T08280-00 0204.65 (10x)	
1,9 WJY (DW8B) WJZ (DW8)	51 kW (69-70 PS) BERLINGO D JUMPY D XSARA D	04/98→	S32985-00 ⑫ ⑬ 0197.X6 +0127.28 +0326.22 +0807.14 D32985-00 ⑫ 0197.X5 +0807.14 B32989-00 ⑬	H05616-00 0209.X0 84 Ø 1,26 mm 3 H05616-10 0209.X1 1,3 mm 4 H05616-20 0209.X2 1,34 mm 5 H15616-30 0209.X3 1,38 mm 6 H15616-40 0209.X4 1,42 mm 7 H15616-50 0209.1C 84 Ø 1,47 mm 4 MLS	T08280-00 0204.65 (10x) → 08469 T05616-00 0204.97 (10x) → 08470→ 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X06152-01 0349.91 	X06151-01 0349.70 4x X07798-01 1710.39 	X04848-01 0127.05 NBR X07793-01 0304.34 2x 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X07796-01 0249.91 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X55498-01 0348.99 ① → 03/87 X55499-01 0348.98 ① → 03/87 	X07782-01 0349.78 ① → 03/87 X03013-01 1721.01 X51229-01 ⑦ 0348.89 ① 04/87→ 	X07793-01 0304.34 2x 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM 2x
X53733-01 U 0249.97 X53780-01 O 0249.95 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X58969-01 0348.N2 2x X58970-01 0348.N1 	X52327-01 0349.H7 2x 	X07793-01 0304.34 2x 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM

O arriba / oben / top / haut / superiore / сверху
 U debajo / unten / bottom / bas / inferiore / снизу



CITROEN						
Ltr.						
2,0 B20/614	11/73-01/94	65 kW (88 PS)	C35 C35 Bus	S30006-00 ⑬ 5451440H D30006-00 5451439X R30713-00 ③	H00677-00 5478690 92,7 Ø 	
2,0 M20-616	09/74-05/79	75 kW (102 PS)	CX 2000	S30966-00 ⑫ ⑬ 5477993C D30966-00 ⑫ 5477992S B30966-00 ⑬ R30713-00 ③	H00677-00 5478690 92,7 Ø 	
2,0 RDZ (XU10MZ) RFZ (XU10J2) XU102C	05/89-06/94	79-89 kW (107-121 PS)	XM	S31115-00 ⑫ ⑬ 95650948 D31115-00 ⑫ 0197.C8 +0209.N1 B31115-00 ⑬	H07967-00 0209.N1 87,3 Ø 	T08280-00 0204.65 (10x)
2,0 RFJ (EW10A)	09/04→	103 kW (140 PS)	C4 C4 16V C5 C5 16V C8 16V	S80781-00 ⑫ ⑬ ⑰ D80781-00 ⑫ ⑰ B38333-00 ⑬	H80781-00 0209.FS MLS 	T80768-00 0204.A3 (10x)
2,0 RFK (EW10J4S)	11/04→	130 kW (177 PS)	C4 C4 16V	S36504-03 ⑫ ⑬ ⑰ D36504-03 ⑫ ⑰ B36503-03 ⑬	H80351-00 0209.Z3 85,5 Ø MLS 	T80768-00 0204.A3 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра

⑰ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



X07492-01 5412579F 	N91010-00 P76531-00 0249.48 P76543-00 0956.05 4x 4x	X00828-01 5414063 X00830-01 5414064 2x 	X00680-01 5412149G 4x 	X00709-01 5448221U X00716-01 Kork	P76001-01 K ← 10x18x5 NBR P76051-01 K → 95550398 29x46x10 LD MVQ
X07492-01 5412579F 	N91010-00 P76531-00 0249.48 P76543-00 0956.05 4x 4x	X07495-01 ⑩ 2x 562033Z 	X00701-01 5440398L 4x X07494-01 5490878 2x X07493-01 5 434 181 	X07498-01 7543388080B 	P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56528-01 0348.E0 	X06151-01 0349.70 4x 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X89881-01 0348.S2 4x 	X82335-01 0349.L4 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM P77626-01 N 0236.74 39x50x7 A SL RD
X53933-01 L 0249.A4 X53934-01 R 0249.A5 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X89343-01 0348.R8 	X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑩ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



CITROEN						
Ltr.						
2,0 RFN (EW10J4)	100 kW (136 PS) C4 16V C5 16V C8 EVASION 16V JUMPY XSARA PICASSO 16V XSARA 16V	04/00→	S36504-00 ⑫ ⑬ 0197.Y1 +0209.Z3 +0249.A4 +0249.A5 D36504-00 ⑫ B36503-00 ⑬	H80351-00 0209.Z3 85,5 Ø MLS 	T07586-00 0204.A7 (10x) 	
2,0 RFS (XU10J4RS)	120-122 kW (163-166 PS) XSARA 16V ZX ZX 16V	05/96-03/05	S36087-00 ⑫ ⑬ 0197.W2 +0209.Z2 D36087-00 ⑫ B32981-00 ⑬	H80033-00 0209.Z2 87 Ø MLS 	T50162-00 0204.72 (10x) 	
2,0 RFT (XU10J4/Z)	110-112 kW (150-152 PS) XANTIA 16V ZX 16V	07/92-01/98	S31583-00 ⑫ ⑬ 95668993 D31583-00 ⑫ 0197.G7 +0209.N0 B31583-00 ⑬	H50162-00 0209.N0 87 Ø 	T50162-00 0204.72 (10x) 	
2,0 RFU (XU10J2/C)	89 kW (121 PS) EVASION	06/94-07/02	D32987-00 ⑫ 0197.T4 +0209.J8 B31581-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	
2,0 RFV (XU10J4R)	97 kW (132 PS) EVASION 16V XANTIA 16V XM 16V XSARA 16V	05/94-04/03	S32981-00 ⑫ ⑬ 0197.W2 → 07965 S36401-00 ⑫ ⑬ 0197.X8 +0209.N6 +0249.A2 +0249.A3 → 07966→ D32981-00 ⑫ → 07965 D36401-00 ⑫ 0197.H3 → 07966→ B32982-00 ⑬ → 07965 B32981-00 ⑬ → 07966→	H80031-00 0209.N6 87 Ø 1,2 mm H80031-10 0209.T9 87 Ø 1,45 mm 	T50162-00 0204.72 (10x) 	



X53933-01 L 0249.A4 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X86822-01 0348.P1 4x 	X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X53934-01 R 0249.A5 					
70-31414-10 	N92990-00 0956.38 (16x) P76662-00 0956.38 16x	X58967-01 0348.C8 	X52325-01 0349.F4 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X07519-01 0249.74 NBR 	N91190-00 0956.19 (8x) P76532-00 0956.19 2x 16x	X56177-01 0348.C8 	X51249-01 0349.98 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X58564-01 0348.N0 2x 	X01022-01 0349.70 4x 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X53731-01 L 0249.A2 	N93063-00 0956.34 (16x) → 07359 N93062-00 0956.42 (16x) → 07360→ → 07965 N92657-00 0956.45 (16x) → 07966→ P76817-00 0956.34 → 07359 P76750-00 0956.42 → 07360→ → 07965 P76657-00 0956.45 → 07966→ 16x 16x 16x	X58967-01 0348.C8 	X52325-01 0349.F4 → 07664 X52324-01 0349.H0 → 07765→ 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X53732-01 R 0249.A3 		X86611-01 0348.L3 4x 			



CITROEN						
Ltr.						
2,0 RFW (XU10J2U)	80 kW (109 PS) JUMPER JUMPER Bus	02/94-04/02	S31581-00 ⑫ ⑬ 9568993 D31581-00 ⑫ 0197.G6 +0209.J8 B31581-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	
2,0 RFX (XU10J2C) RFX (XU10J2C/Z L3)	89-95 kW (121-129 PS) XANTIA ZX	07/92→	S31581-00 ⑫ ⑬ 9568993 D31581-00 ⑫ 0197.G6 +0209.J8 B32982-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	
2,0 RFY (XU10J4/Z)	112 kW (152 PS) XANTIA 16V ZX 16V	07/92-01/98	S31583-00 ⑫ ⑬ 9568993 ① 06/93→ D31583-00 ⑫ 0197.G7 +0209.N0 ① 06/93→ D38545-00 ⑫ 0197.G7 B31583-00 ⑬	H07967-00 0209.N1 87,3 Ø ① →05/93 H50162-00 0209.N0 87 Ø ① 06/93→ 	T08280-00 0204.65 (10x) ① →05/93 T50162-00 0204.72 (10x) ① 06/93→ 	
2,0 RGX (XU10J2TE) RGY (XU10J2TE/Z)	104-108 kW (141-147 PS) EVASION Turbo XANTIA Turbo XM Turbo	09/92-04/03	D36906-00 ⑫ 0197.H3 	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56171-01 0348.F6 2x X56170-01 ⑩ 2x 0348.E6 	X01022-01 0349.70 4x 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM	
X53101-01 0249.71 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X58564-01 0348.N0 2x X56170-01 ⑩ 2x 0348.E6 	X01022-01 0349.70 4x 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM	
X07519-01 0249.74 NBR 	N91190-00 0956.19 (8x) P76532-00 0956.19 16x	X56177-01 0348.C8 2x 	X51249-01 0349.98 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM	
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56528-01 0348.E0 → 07664 2x X58564-01 0348.N0 → 07665→ 	X06151-01 0349.70 4x 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76128-11 N 0236.24 32x45x8 A LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM	



CITROEN										
Ltr. [NEW] 2,0 RHE (DW10CTED4) 120 kW (163 PS) C4 HDI RHH (DW10CTED4) C5 C5 HDI C8 HDI DS4 HDI DS5 HDI JUMPY HDI	03/06→	S38513-00 ⑫ ⑬ 0197.AW +0249.G8 +0348.V7 D38513-00 ⑫ 0197.AX +0348.V7 	H40649-00 0209.GL 1,25 mm 1 MLS H40649-10 0209.GN 1,3 mm 2 MLS H40649-20 0209.GP 1,35 mm 3 MLS H40649-30 0209.GQ 1,4 mm 2 MLS 	T05133-00 0204.A6 (10x) 	X59687-01 0348.V7 	N93131-00 0956.58 (16x) P76842-00 16x 0956.58	X59682-01 0349.N2 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM	
2,0 RHJ (DW10BTED4) 100 kW (136 PS) C4 HDI RHR (DW10BTED4) C4 HDI 135 FAP C4 HDI 135 FFAP C5 HDI C8 HDI JUMPY HDI 140	09/04→	S37090-00 ⑫ ⑬ 0197.AE +0348.S3 D37090-00 ⑫ 0197.AC +0348.S3 	H01900-00 0209.AV 86 Ø 1,25 mm 2 MLS H11900-10 0209.AW 86 Ø 1,3 mm 3 MLS H21900-20 0209.AX 86 Ø 1,35 mm 4 MLS H31900-30 0209.AY 86 Ø 1,4 mm 5 MLS 	T05133-00 0204.A6 (10x) 	V37090-00 0348.S3 	N92635-00 2x 0956.48 (8x) P76698-00 16x 0956.48	X81070-01 0349.J2 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM	
2,0 RHK (DW10UTED4) 88 kW (120 PS) C8 JUMPY HDI 120	01/07→	S37090-00 ⑫ ⑬ 0197.AE +0348.S3 D37090-00 ⑫ 0197.AC +0348.S3 	H01900-00 0209.AV 86 Ø 1,25 mm 2 MLS H11900-10 0209.AW 86 Ø 1,3 mm 3 MLS H21900-20 0209.AX 86 Ø 1,35 mm 4 MLS H31900-30 0209.AY 86 Ø 1,4 mm 5 MLS 	T05133-00 0204.A6 (10x) 	V37090-00 0348.S3 	N92635-00 2x 0956.48 (8x) P76698-00 16x 0956.48	X82339-01 0349.L9 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM	

⑫ ⑬ L R

← → K N (A)

CITROEN

CITROEN						
Ltr.						
2,0 RHM (DW10ATED4) RHT (DW10ATED4) RHW (DW10ATED4)	79-80 kW (107-109 PS) C8 HDI EVASION HDI	09/99→	S36517-00 0197.Y6 D36517-00 0197.Y7 +0249.A6 B36517-00	H01900-00 0209.AV 86 Ø 1,25 mm MLS 2 H11900-10 0209.AW 86 Ø 1,3 mm MLS 3 H21900-20 0209.AX 86 Ø 1,35 mm MLS 4 H31900-30 0209.AY 86 Ø 1,4 mm MLS 5 	T17586-00 0204.96 (10x) 	
2,0 RHS (DW10ATED) RHX (DW10BTED) RHY (DW10TD) RHZ (DW10ATED)	66-80 kW (90-109 PS) BERLINGO HDI BERLINGO HDI 90 C5 HDI EVASION HDI JUMPY HDI XANTIA HDI 109 XANTIA HDI 90 XSARA HDI 109 XSARA HDI 90 XSARA PICASSO HDI	02/99→	S36550-00 0197.X4 +0249.99 D36550-00 0197.X3 +0249.99 B32989-00	H05133-00 0209.X5 1,3 mm MLS 1 H05133-10 0209.X6 1,35 mm MLS 2 H05133-20 0209.X7 1,4 mm MLS 3 H15133-30 0209.X8 1,45 mm MLS 4 H15133-40 0209.X9 86 Ø 1,5 mm MLS 5 	T05133-00 0204.A6 (10x) 	
2,0 RHV (DW10UTD)	62 kW (84 PS) JUMPER Bus HDI JUMPER HDI	11/01→	S36550-00 0197.X4 +0249.99 D36550-00 0197.X3 +0249.99 B32989-00	H05133-00 0209.X5 1,3 mm MLS 1 H05133-10 0209.X6 1,35 mm MLS 2 H05133-20 0209.X7 1,4 mm MLS 3 H15133-30 0209.X8 1,45 mm MLS 4 H15133-40 0209.X9 86 Ø 1,5 mm MLS 5 	T05133-00 0204.A6 (10x) 	



X53953-01 0249.A6 	N92635-00 0956.48 (8x) P76698-00 0956.48 2x 16x		X81070-01 0349.J2 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM
X53885-01 0249.99 	N92991-00 0956.38 (8x) → 08331 N92635-00 0956.48 (8x) → 08332→ P76662-00 0956.38 → 08331 P76698-00 0956.48 → 08332→ 8x 8x	X58968-01 0348.N4 	X52326-01 0349.H4 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM
X53885-01 0249.99 	N92635-00 0956.48 (8x) P76698-00 0956.48 8x	X58968-01 0348.N4 	X52326-01 0349.H4 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM



CITROEN						
Ltr.						
2,0 RLZ (EW10D)	103 kW (140 PS) C5 16V C5 16V HPI	03/01-08/04	S36504-01 ⑫ ⑬ 0197.Y1 +0209.Z3 +0249.A8 +0249.A7 (4x) D36504-01 ⑫ B36503-00 ⑬	H80351-00 0209.Z3 85,5 Ø MLS 	T07586-00 0204.A7 (10x) 	
2,0 R6A	94 kW (130 PS) XM	05/89-06/94	D31581-00 ⑫ 0197.G6 +0209.J8 ① →03/94 B31581-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	
2,0 XU10J2	81 kW (110 PS) JUMPER JUMPER Bus	02/03→	D32987-00 ⑫ 0197.T4 +0209.J8 B31581-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	
2,0 170A (XN1T) 170B (XN1T)	58 kW (79 PS) C25 C25 Bus	09/81-03/94	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 ③ R30547-00	H02760-00 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T02666-00 ① →06/85 T02760-00 0204.51 (10x) ① 07/85-04/89 T01025-00 0204.57 (10x) ① 05/89→ 	
2,0 170C (XN1T)	62 kW (84 PS) C25	01/87-03/94	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 ③ R30547-00	H02760-00 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T02760-00 0204.51 (10x) ① →04/89 T01025-00 0204.57 (10x) ① 05/89→ 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X53954-01 0249.A8 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x		X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM P77437-01 N 0236.65 39x50x7 A SL RD FPM
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07803-01 X07804-01 	X06151-01 0349.70 4x 	X07793-01 0304.34 ① →09/93 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56171-01 0348.F6 2x X56170-01 ⑩ 2x 0348.E6 	X06151-01 0349.70 4x 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 	X04833-01 0349.03 	X04848-01 0127.05 NBR 2x X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 	X04833-01 0349.03 	X04848-01 0127.05 NBR 2x X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



CITROEN						
Ltr.						
2,0 170C (XN1T)	62 kW (84 PS) C25 C25 Bus	02/91-03/94	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 R30547-00 ③	H02760-00 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T01025-00 0204.57 (10x) 	
2,0 829 A5	78 kW (106 PS) CX 20 CX 20 RE CX 2000	06/79-12/92	S31063-00 ⑫ ⑬ 95568475 D31063-00 ⑫ 95568474 R30961-00 ③	H00749-00 95605041 89,3 Ø 		
2,1 PHZ (XUD11ATE) PJZ (XUD11ATE) P8A (XUD11ATE) P8C (XUD11BTE)	80 kW (109 PS) EVASION TD XANTIA TD 12V XM TD 12V	05/89-07/02	S31584-00 ⑫ ⑬ D31584-00 ⑫ 0197.H1 B31584-00 ⑬	H07761-00 0209.T6 1,35 mm MLS H07761-10 0209.R4 1,52 mm MLS H07761-20 0209.R5 1,57 mm MLS H17761-30 0209.R6 1,62 mm MLS H17761-40 0209.R7 1,67 mm MLS H17761-50 0209.R8 1,73 mm MLS H27761-60 0209.T4 86 Ø 1,77 mm MLS 	T02356-00 0204.68 (10x) 	
2,1 P9A (XUD11A)	60 kW (82 PS) XM XM D 12V	05/89-08/96	S31584-00 ⑫ ⑬ D31584-00 ⑫ 0197.H1 B31584-00 ⑬	H02354-00 0209.H1 1,58 mm 2 H12354-10 0209.A0 87 Ø 1,7 mm 3 	T02354-00 0204.67 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 	X04833-01 0349.03 	X04848-01 2x 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X04583-01 7700 614 729 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X00690-01 4x 7700 616 523 	X06303-01 	X00696-01 9549265880 Kork 	P76186-01 K ← 50x68x10 A RD FPM P76094-01 K → 0236.09 35x47x7 A RD MVQ P76363-01 K → 90x110x13 LD P76054-11 N 30x40x7 A SL RD FPM
X53584-01 0249.70 	N91210-00 0956.22 (12x) P76531-00 0249.48 12x	X56183-01 0348.96 	X51245-01 0349.76 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM
X53584-01 0249.70 	N91210-00 0956.22 (12x) P76531-00 0249.48 12x	X56183-01 0348.96 	X51245-01 0349.76 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM



CITROEN						
Ltr.						
2,2 B22615 CRD90	45-46 kW (61-62 PS) C35 Bus D C35 D	11/73→	S30005-00 ⑫ ⑬ 5451033J D30005-00 ⑫ 95534760	H00755-00 75491733 93,3 ∅ 	T06345-00 0204.41 (8x) +0204.42 (9x) 	
2,2 J6T A500	83-85 kW (113-115 PS) CX 22 TRS CX 22TRS CX 2200	06/81-12/92	S31063-00 ⑫ ⑬ 95568475 D31063-00 ⑫ 95568474 R30961-00 ③	H00749-00 95605041 89,3 ∅ 		
2,2 M22-617	82 kW (112 PS) CX 2200	09/74-07/76	S30992-00 ⑫ ⑬ 5470968U D30992-00 ⑫ 5477994N B30966-00 ⑬ R30713-00 ③	H07579-00 5433873 93,3 ∅ 		
2,2 M22-621	49 kW (67 PS) CX 2200 D	10/75-02/79	S30991-00 ⑫ ⑬ 5478737P D30991-00 ⑫ 5478736D	H00750-00 75491734 93,3 ∅ 		
2,2 3FZ (EW12J4)	116 kW (158 PS) C8	07/02→	S37005-00 ⑫ ⑬ 0197.Y8 +0209.0H +0249.A4 +0249.A5 D37005-00 ⑫	H80475-00 0209.0H 87 ∅ MLS 	T80475-00 0204.95(x10) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X00742-01 5 450 155 NBR 	N91300-00 5469955 P76531-00 0249.48 P76543-00 0956.05 4x 4x	X00837-01 4x 	X00881-01 0349.F0 4x 	X00709-01 5448221U X00716-01 Kork 	P76178-11 K ← 48x65x10 A NBR
X04583-01 7700 614 729 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X00690-01 7700 616 523 4x 	X06303-01 	X00696-01 9549265880 Kork 	P76186-01 K ← 50x68x10 A RD FPM P76094-01 K → 0236.09 35x47x7 A RD MVQ P76363-01 K → 90x110x13 LD P76054-11 N 30x40x7 A SL RD FPM
X07492-01 5412579F 	N91010-00 P76531-00 0249.48 P76543-00 0956.05 4x 4x	X07495-01 ⑩ 2x 562033Z 	X07494-01 5490878 X07493-01 5 434 181 	X07498-01 7543388080B 	P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ
X00742-01 5 450 155 NBR 	N91010-00 P76531-00 0249.48 P76543-00 0956.05 4x 4x	X00837-01 4x 	X00881-01 0349.F0 4x X07493-01 5 434 181 	X07498-01 7543388080B 	P76178-11 K ← 48x65x10 A NBR P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ
X53933-01 L 0249.A4 X53934-01 R 0249.A5 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X81726-01 0348.P6 	X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM P77437-01 N 0236.65 39x50x7 A SL RD FPM

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



CITROEN						
Ltr.						
2,2 4HN (DW12MTED4)	115 kW (156 PS) C-CROSSER HDI	02/07→	D38112-00 ¹² B38113-00 ¹³	H01901-00 0209.FT 1,25 mm MLS H11901-10 0209.FV 1,3 mm MLS H21901-20 0209.FW 1,35 mm MLS H31901-30 0209.FX 85,9 Ø 1,37 mm MLS 	T05133-00 0204.A6 (10x) 	
2,2 4HT (DW12BTED4)	125 kW (170 PS) C5 HDI C6 HDI C8	04/06→	D38112-00 ¹² B38113-00 ¹³	H01901-00 0209.FT 1,25 mm MLS H11901-10 0209.FV 1,3 mm MLS H21901-20 0209.FW 1,35 mm MLS H31901-30 0209.FX 85,9 Ø 1,37 mm MLS 	T05133-00 0204.A6 (10x) 	
2,2 4HU (P22DTE) 4HV (P22DTE)	74-88 kW (101-120 PS) JUMPER HDI 100 JUMPER HDI 120	04/06→	D38555-00 B36738-00 ¹³ ³⁵	H40597-00 0209.EH 87,5 Ø 1,1 mm MLS H40597-10 0209.ES 87,5 Ø 1,15 mm MLS H40597-20 0209.ET 87,5 Ø 1,2 mm MLS 	T59572-00 0204.C0 (10x) +0204.A9 (8x) 	

³⁵ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



V38102-00 0249.E4 +0249.E5 (2x) +0249.E3 X83357-01 2x 0249.E5 X83358-01 0249.E4 	N93131-00 0956.58 (16x) P76842-00 0956.58 16x	M38101-00 0348.T2 	X81999-01 0349.P1 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM
V38102-00 0249.E4 +0249.E5 (2x) +0249.E3 X83357-01 2x 0249.E5 X83358-01 0249.E4 	N93131-00 0956.58 (16x) P76842-00 0956.58 16x	M38101-00 0348.T2 	X81999-01 0349.P1 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM
X83135-01 0249.E9 NBR 	N92986-00 0956.59 (16x) P76777-00 0956.59 16x	X88198-01 0348.T1 	8x X81992-01 0349.L5 X82543-01 	E36738-00 0304.58 70-31414-10 	P77367-01 K ← 0514.C6 PTFE P77338-01 K → 0514.C4 PTFE



CITROEN							
Ltr.							
2,2	4HW (DW12TED4) 4HX (DW12TED4)	94-98 kW (128-133 PS)	C5 HDI C8 HDI	03/01→	S36517-00 ⑫ ⑬ 0197.Y6 D36517-00 ⑫ 0197.Y7 +0249.A6 B36517-00 ⑬ 	H01900-00 0209.AV 86 Ø 1,25 mm 2 MLS H11900-10 0209.AW 86 Ø 1,3 mm 3 MLS H21900-20 0209.AX 86 Ø 1,35 mm 4 MLS H31900-30 0209.AY 86 Ø 1,4 mm 5 MLS 	T17586-00 0204.96 (10x)
2,2	4HY (DW12UTED4) [NEW]	74 kW (101 PS)	JUMPER Bus HDI JUMPER HDI	02/02→	S36550-00 ⑫ ⑬ 0197.X4 +0249.99 D36550-00 ⑫ 0197.X3 +0249.99 	H06254-00 0209.AQ 1,25 mm 1 MLS H06254-10 0209.AR 1,3 mm 2 MLS H06254-20 0209.AS 1,35 mm 3 MLS H16254-30 0209.AT 86 Ø 1,4 mm 4 MLS 	T17586-00 0204.96 (10x)
2,3	M23-622 M23-623 M23-639	85-96 kW (116-131 PS)	CX 2400 CX 2400 GTI	08/76-06/83	S30713-00 ⑫ ⑬ 584768U D30713-00 ⑫ 5484766X R30967-00 ③	H07491-00 9558649980 96,5 Ø 	
2,5	B25/637	51 kW (69 PS)	C35 Bus D C35 D	02/80-01/94	S30459-00 ⑫ ⑬ 95569124 D30459-00 ⑫ 95568472+95393121	H01014-00 95542219 96,3 Ø 	T06345-00 0204.41 (8x) +0204.42 (9x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X53953-01 0249.A6 	N92635-00 2x 0956.48 (8x) P76698-00 16x 0956.48		X81070-01 0349.J2 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM
X53885-01 0249.99 	N92635-00 8x 0956.48 (8x) P76698-00 0956.48	X58968-01 0348.N4 	X81070-01 0349.J2 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM
X07492-01 5412579F 	N91010-00 4x P76531-00 4x 0249.48 P76543-00 0956.05	X00702-01 2x 5469837 X07495-01 ⑩ 2x 562033Z 	X07494-01 4x 5490878 X07493-01 5 434 181 	X07498-01 7543388080B 	P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ
X00742-01 5 450 155 NBR I →07/81 X01015-01 0249.78 I 07/81→ 	N91300-00 4x 5469955 P76531-00 4x 0249.48 P76543-00 4x 0956.05	X00837-01 4x 	X00881-01 4x 0349.F0 	X00709-01 5448221U 	P76178-11 K ← 48x65x10 A NBR P76369-01 K → 95533957 95x112x12,5 RD FPM

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



CITROEN						
Ltr.						
2,5 CRD93L (U25-661) M25-660	54-55 kW (73-75 PS) CX 25 D C25 Bus D C25 D	11/81-02/94	S31078-00 (12) (13) 95605463 D30253-00 (12)	H00666-00 0209.L5 96,3 Ø	T06345-00 0204.41 (8x) +0204.42 (9x)	
2,5 CRD93LS (U25-673) M25-648 M25-669	70-88 kW (95-120 PS) CX 25 TD CX 2500 TD C25 Bus TD C25 DT	04/83-02/94	S31052-00 (12) (13) 95593755 D31052-00 (12) B31052-00 (13)	H06345-00 0209.L6 95,6 Ø	T06345-00 0204.41 (8x) +0204.42 (9x)	
2,5 M25-629	55 kW (75 PS) CX 2500 D	02/78-08/85	S30253-00 (12) (13) 75513625 D30253-00 (12) B30253-00 (13)	H00666-00 0209.L5 96,3 Ø	T06345-00 0204.41 (8x) +0204.42 (9x)	
2,5 M25-659	100 kW (136 PS) CX 25 TRI CX 25 TRI	07/83-12/92	S31065-00 (12) (13) 95603251+95496000 D31065-00 (12) 95603252+95496000 R30713-00 (3)	H00864-00 94,5 Ø		
2,5 M25-666	122 kW (168 PS)		S31064-00 (12) (13) 95614914+95598981 D31064-00 (12) 95614945+95598981 R30713-00 (3)	H00587-00 96 18 348 180 94,5 Ø		

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X00742-01 5 450 155 NBR	N91300-00 5469955 P76531-00 0249.48 P76543-00 0956.05	X00837-01 4x	X00881-01 4x 0349.F0 X07493-01 5 434 181	X07498-01 7543388080B X07506-01 Kork 2x	P76314-01 K ← 0514.32 75x90x11,5 A SL RD FPM P76368-11 K → 26126699J 95x112x12,5 LD FPM P76183-01 N 48x72x10 RD FPM
X01015-01 0249.78	N91300-00 5469955 P76531-00 0249.48 P76543-00 0956.05	X00837-01 4x	X00881-01 4x 0349.F0	X07498-01 7543388080B X07506-01 Kork 2x	P76314-01 K ← 0514.32 75x90x11,5 A SL RD FPM P76368-11 K → 26126699J 95x112x12,5 LD FPM P76183-01 N 48x72x10 RD FPM
X00742-01 5 450 155 NBR	N91300-00 5469955 P76531-00 0249.48 P76543-00 0956.05	X00837-01 4x	X00881-01 4x 0349.F0 X07493-01 5 434 181	X07498-01 7543388080B X07506-01 Kork 2x	P76178-11 K ← 48x65x10 A NBR P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ
X07492-01 5412579F	N91010-00 P76531-00 0249.48 P76543-00 0956.05	X06381-01 2x	X07494-01 5490878 X07493-01 5 434 181	X07498-01 7543388080B	P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ
X07492-01 5412579F	N91010-00 P76531-00 0249.48 P76543-00 0956.05	X06385-01 2x	X06387-01 4x	X07498-01 7543388080B	P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ



CITROEN						
Ltr.						
2,5 THX (DJ5TED)	79 kW (107 PS) JUMPER Bus TDI JUMPER TDI	12/96-04/02	S32990-00 ⑫ ⑬ 0197.W4 +0209.T5 D32990-00 ⑫ 0197.W3 +0209.T5 B32148-00 ⑬	H80034-00 0209.T5 93 ∅ 	T80034-00 0204.87 (14x) +0204.88 (8x) 	
2,5 THY (DK5ATE) THZ (DJ5T) T8A (DJ5T) T9A (DJ5)	63-95 kW (86-129 PS) JUMPER Bus D JUMPER Bus TD JUMPER D JUMPER TD XM TD	03/94→	S32148-00 ⑫ ⑬ 0197.T7 +0209.R3 D32148-00 ⑫ 0197.T6 +0209.R3 B32148-00 ⑬	H50390-00 0209.R3 93 ∅ 	T50390-00 0204.74 (14x) +0204.75 (8x) 	
2,7 DT17ED4 UHZ (DT17BTED4)	150 kW (204 PS) C5 HDI C6 HDI 205 FAP	09/05→	D38339-00 ⑫ B38339-00 ⑬	H01902-00 2x 0209.CW 82,5 ∅ 1,17 mm MLS H01902-10 2x 0209.CX 82,5 ∅ 1,22 mm MLS H01902-20 2x 0209.CY 82,5 ∅ 1,27 mm MLS H11902-30 2x 0209.CZ 82,5 ∅ 1,32 mm MLS 	T01902-00 2x 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

⑰ para vehículos con aire acondicionado / für Fahrzeuge mit Klimaanlage / for vehicles with air conditioning / pour véhicules avec système de climatisation / per veicoli con aria condizionata / оснащение / оборудование для автомобилей с кондиционером



X53585-01 0249.79 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X58971-01 2x 0348.K4 	X52328-01 0349.G4 	70-31414-10 	P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P76098-01 N V 0514.15 35x50x7 A SL RD FPM P77143-01 N H 0807.26 32x52x7 A SL LD FPM
X53585-01 0249.79 	N92450-00 0659.19 (12x) P76532-00 0956.19 12x	X56189-01 0348.K1 X57008-01 ⑩ 0348.F9 	X51508-01 0349.E7 	70-31414-10 	P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P76098-01 N ← 0514.15 35x50x7 A SL RD FPM P76034-01 N → ⑳ 0807.15 40x62x7 A SL LD ACM FPM P76047-01 N → ㉑ 0807.21 47,5x62x7 A SL LD ACM FPM
X83359-01 2x 0249.E1 	N93132-00 0956.53 (24x) P76843-00 0956.53 24x		X82334-01 2x 0349.L0 	X54926-01 0164.75 X59640-01 0304.57 	P77681-01 K ← 0326.29 35x50x7 A SL RD PTFE ACM P77677-01 K → ㉒ 0514.C0 P77624-01 N 2x 0807.36 26x45x8 A SL WD FPM

⑳ para vehículos sin aire acondicionado / für Fahrzeuge ohne Klimaanlage / for vehicles without air conditioning / pour véhicules sans système de climatisation / per veicoli senza aria condizionata / оснащение / оборудование для автомобилей без кондиционера

H posterior / hinten / rear / arrière / posteriore / сзади
V delante / vorne / front / avant / anteriore / спереди



CITROEN						
Ltr.						
2,8 F28TDCR	94 kW (128 PS) JUMPER HDI	02/02-06/06		H08023-01 0209.0C 1,3 mm H18023-11 0209.0E 1,4 mm H28023-21 0209.0F 1,5 mm	T07684-00 	
2,8 8140.43S	93-94 kW (126-128 PS) JUMPER JUMPER Bus HDI JUMPER HDI	09/00→	S38249-02 ⑫ ⑭ 0197.Y2 D38249-02 ⑫ 0197.Y3 	H08023-01 0209.0C 1,3 mm H18023-11 0209.0E 1,4 mm H28023-21 0209.0F 1,5 mm		
3,0 DT20C	177 kW (241 PS) C5 HDI	04/09→		H40636-00 2x 0209.GX 85 Ø 1,17 mm 2 MLS H40636-10 2x 0209.GY 85 Ø 1,22 mm 3 MLS H40636-20 2x 0209.GZ 85 Ø 1,27 mm 4 MLS H40636-30 2x 0209.HA 85 Ø 1,32 mm 5 MLS	T01902-00 2x 	
3,0 F1CE0481D (F30DT) [NEW]	115-116 kW (156-157 PS) JUMPER HDI 155 JUMPER HDI 160	09/06→	S37073-00 ⑫ 0197.AR S37073-03 ⑫ ⑬ D37073-00 ⑫ 0197.AQ D37073-03 ⑫ 	H80737-00 0209.FJ 1,1 mm MLS H80737-10 1,2 mm MLS H80737-20 1,3 mm MLS	T38521-00 0204.C6 (6x) +0204.C7 (4x) +0204.C8 (4x) +0204.C9 (1x) 	

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



X53812-01 0249.C3 		X07692-01 4x 	X07689-01 4x 		
X53812-01 0249.C3 X59298-01 0249.A0 	N93138-00 P76804-00 8x	X07692-01 4x 	X51326-11 4x 0349.H5 	X54494-01 NBR X59306-01 Gummi 	
X83359-01 2x 0249.E1 	N93132-00 0956.53 (24x) P76843-00 24x 0956.53		X82334-01 2x 0349.L0 	X54926-01 0164.75 X59640-01 0304.57 	P77681-01 K ← 0326.29 35x50x7 A SL RD PTFE ACM P77677-01 K → 0514.C0 P77624-01 N 0807.36 26x45x8 A SL WD FPM
X83071-01 0249.F7 	N91011-00 P76818-00 16x	X89001-01 0348.T7 	X81859-01 0349.L8 	X54818-01 0304.59 NBR 	P77458-01 K ← 0514.C9 50x70x11 PTFE P77459-01 K → 0514.E4 90x120x13,65 FPM



CITROEN					
Ltr.					
3,0 SFZ (ZPJ/Z) UFZ (ZPJ/Z)	123 kW (167 PS) XM XM V6	05/89-10/00	S31114-00 ⑫ ⑬ 95653027 D31114-00 ⑫ 0197.E1 +0209.A4 +0209.A5 +0956.30 (12x) B31114-00 ⑬ R31114-00 ③	H08263-00 R 0209.A4 H08264-00 L 0209.A5 95 Ø 	T08263-00 0204.53 (16x)
3,0 SKZ (ZPJ4/Z) UKZ (ZPJ4/Z)	147 kW (200 PS) XM V6 24V	07/90-10/00	S31585-00 ⑫ ⑬ 95659411 D31585-00 ⑫ 95656101 B31585-00 ⑬ R31114-00 ③	H08263-00 R 0209.A4 H08264-00 L 0209.A5 95 Ø 	T08263-00 0204.53 (16x)
3,0 XFU (ES9A) XFV (ES9A)	152-155 kW (207-211 PS) C5 C5 V6 C6 V6	09/04→		H08012-00 V 0209.OX 89 Ø 0,74 mm MLS H08013-00 H 0209.OY 89 Ø 0,74 mm MLS 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



70-31414-10 	N91210-00 0956.22 (12x) P76531-00 0249.48 12x	X07897-01 2x X51325-01 6x 96 130 969 	70-31414-10 	P76152-01 K ← 42x62x10 A SL RD FPM P76345-01 K → 80x100x13 A SL LD MVQ P76128-11 N 2x 0236.24 32x45x8 A LD FPM	
70-31414-10 	N92920-00 P76532-00 0956.19 24x	X51247-01 ⑦ 2x 0349.74 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76345-01 K → 80x100x13 A SL LD MVQ P76128-11 N 2x 0236.24 32x45x8 A LD FPM	
70-31414-10 	N92830-00 P76662-00 0956.38 24x	X89882-01 0348.Q0 X89883-01 2x 0348.P9 	X52329-01 2x 0349.G0 	70-31414-10 	P77682-01 K ← 0514.A9 42x56x6,5 A SL RD P77683-01 K → 0119.18 98x120x9 A SL LD P77623-01 N 4x 0807.34 38x50x7 A SL RD

H posterior / hinten / rear / arrière / posteriore / сзади
 V delante / vorne / front / avant / anteriore / спереди



CITROEN						
Ltr.						
3,0 XFX (ES9J4S)	150-155 kW (204-211 PS) C5 V6 C6 V6 C8 V6	03/01→	D37116-00 ⑫ V D37117-00 ⑫ H D37118-00 ⑫ B37213-00 ⑬ → 10086 B37117-00 ⑬ → 10087→	H08012-00 V 0209.OX 89 Ø 0,74 mm MLS H18012-10 V 0209.OZ 89 Ø 0,95 mm MLS H08013-00 H 0209.OY 89 Ø 0,74 mm MLS H18013-10 H 0209.1A 89 Ø 0,95 mm MLS 		
3,0 XfZ (ES9J4)	140 kW (190 PS) XANTIA V6 XANTIA 24V XM V6	01/97-04/03	D37119-00 ⑫ R → 0008570→ D37120-00 ⑫ L → 008570→ B37213-00 ⑬	H80044-00 L 0209.ON MLS → 0008570→ H80045-00 R 0209.OP 89 Ø MLS → 0008570→ 		

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



70-31414-10 	N92830-00 P76662-00 24x 0956.38	X89882-01 2x 0348.Q0 X89883-01 2x 0348.P9 	X52329-01 2x 0349.G0 	70-31414-10 	P76144-11 K ← 0514.82 42x56x7 A SL RD FPM → 10086 P77682-01 K ← 0514.A9 42x56x6,5 A SL RD → 10087→ P76065-01 K → 0119.14 98x120x7 A SL LD FPM → 10086 P77683-01 K → 0119.18 98x120x9 A SL LD → 10087→ P77141-01 N 4x 0807.24 38x50x6 A SL RD FPM
70-31414-10 	N92830-00 P76662-00 24x 0956.38	X58973-01 2x 0348.L5 X58972-01 ⑩ 0348.K7 	X52329-01 2x 0349.G0 	70-31414-10 	P76144-11 K ← 0514.82 42x56x7 A SL RD FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P77141-01 N 4x 0807.24 38x50x6 A SL RD FPM

H posterior / hinten / rear / arrière / posteriore / сзади
V delante / vorne / front / avant / anteriore / спереди

