

PEUGEOT

PEUGEOT



0-9	
1580 SPI (222A2)	1164
1KR (384F)	1138
4HN (DW12MTED4)	1200
4HU (P22DTE)	1202
4HV (P22DTE)	1202
5FR (EP6DT)	1158
5FS (EP6C)	1158
5FT (EP6DT)	1158
5FV (EP6DT)	1158
5FX (EP6DT)	1158
5FY (EP6DTS)	1158
8140.43S (F28DTCR)	1208
8FS (EP3)	1148
8HS (DV4TD)	1154
8HT (DV4TD)	1154
9HR (DV6C)	1158
9HV (DV6ATED4)	1156
C	
CRD93	1204
CRD93L	1204
CRD93LS	1204
D	
DEW10J4 (RFR)	1182
DJ5 (T9A)	1204
DJ5T (T8A)	1204
DJ5TED (THX)	1204
DK5ATE (THY)	1204
DT17BTED4 (UHZ)	1206
DT17TED4	1206
DT17TED4 (UHZ)	1206
DT20C	1210
DV4TD (8HX)	1148
DV4TD (8HZ)	1148
DV6ATED4 (9HX)	1156
DV6C	1158
DV6TED4 (9HY)	1156
DV6TED4 (9HZ)	1156
DW10ATED (RHS)	1182
DW10ATED (RHZ)	1182
DW10ATED4 (RHM)	1184
DW10ATED4 (RHT)	1184
DW10ATED4 (RHW)	1184
DW10ATED4 (RHX)	1182
DW10ATED4 (RHR)	1184
DW10CTED4 (RHH)	1184
DW10TD (RHY)	1182
DW10UTD (RHV)	1186
DW10UTED4 (RHK)	1186
DW12BTED4 (4HT)	1198
DW12TED4 (4HX)	1198
DW12UTED (4HY)	1198
DW8 (WJZ)	1172
DW8B (WJY)	1172
E	
E1	1138
EP3	1148
EP6	1158
EP6CDT	1158
EP6CDTX	1158
ES9A (XFV)	1210
ES9J4 (XFZ)	1210
ES9J4S (XFX)	1212



ET3J4 (KFU)	1148
EW10 (RFH)	1186
EW10A (RFJ)	1186
EW10D (RLZ)	1188
EW10J4 (RFN)	1182
EW10J4S (RFK)	1188
EW12J4 (3FY)	1200
EW12J4 (3FZ)	1200
EW7A (6FY)	1164
EW7J4 (6FZ)	1166
F	
F1	1142
F1CE0481D (FG30DT)	1212
G	
G1A	1144
K	
KF5	1166
KF6	1166
N	
NFR (TU5JP4B)	1160
R	
RHE (DW10CTED4)	1184
T	
TU1JP (HFX)	1138
TU1JP (HFZ)	1138
TU1M (HDY)	1138
TU1M (HDZ)	1138-1140
TU24	1144
TU32	1150
TU3A (K1D)	1150
TU3A (KFV)	1150
TU3CP (KAY)	1150
TU3J2/Z (KFZ)	1152
TU3JP (KFV)	1152
TU3JP (KFW)	1152
TU3JP (KFX)	1152
TU3M (KDY)	1150
TU3M (KDZ)	1150
TU3MC (KDX)	1150
TU3S (K2B)	1150
TU5J2 (NFW)	1160
TU5J2 (NFY)	1160
TU5J4 (NFX)	1160
TU5JP (NFT)	1160
TU5JP (NFZ)	1160
TU5JP4 (N6A)	1160
TU5JP4 (NFU)	1160
TU9	1136
TU9M (CDY)	1136
TU9M (CDZ)	1136
TUD3 (K9Y)	1150
TUD5 (VJX)	1154
TUD5 (VJY)	1154
X	
XB5	1156
XB5P	1156
XC5P	1162
XC6	1162
XC7P	1162



XD2 (134)	1202
XD2P94	1202
XD2PX94	1202
XD2S (147)	1202
XD3 (155)	1206
XD3P	1206
XD3T (152A)	1206
XD3TE	1206
XD3TE (152B)	1206
XD4X88	1174
XDP85	1166
XDP88	1174
XDP90	1196
XDPX90	1194
XK	1140
XK4	1140
XK5	1140
XL3	1144
XL3S	1144
XL4D	1144, 1152
XL5	1146
XL5 (118)	1146
XL5S	1146
XLD	1142
XM	1166
XM7	1166-1168
XM7 (105)	1168
XM7A (105C)	1168
XM7P	1168
XM7T (169B)	1168-1170
XN1	1188
XN1 (106)	1188
XN1A (106E)	1188-1190
XN1P	1188-1190
XN1T	1188
XN1T (170)	1190
XN1T (170B)	1190
XN1TA	1190
XN1TA (170C)	1190
XN2 (107)	1190
XR5 (142)	1156
XR5A (142)	1156
XR5S (117)	1156
XU102C (R5A)	1192
XU10J2 (RFU)	1190
XU10J2 (RFW)	1192
XU10J2 (RFX)	1192
XU10J2TE (RGX)	1192
XU10J2TE (RGY)	1192
XU10J2U (RFL)	1192
XU10J2Z (RFZ)	1192
XU10J4 (RFT)	1192
XU10J4R (RFV)	1194
XU10J4RS (RFS)	1194
XU10J4TE/Z (RGZ)	1192
XU10J4Z (RFY)	1192
XU51C (B1A)	1164
XU51C (B1D)	1164
XU51C (B1E)	1164
XU52C/K (B2A)	1164
XU5CP (BAZ)	1164
XU5J (180A)	1164
XU5J (180Z)	1164
XU5J (B6B)	1164
XU5JP (BFZ)	1164
XU5M (BDY)	1164



XU5M (BDZ)	1164
XU5S (171)	1164
XU7JB (LFX)	1170
XU7JP (LFW)	1172
XU7JP (LFZ)	1172
XU7JP4 (LFY)	1172
XU92C (D2A)	1180
XU92C (D2C)	1180-1182
XU9J1 (DFZ)	1180
XU9J2 (D6A)	1180
XU9J4 (D6C)	1180
XU9J4Z (DFW)	1180
XU9JA (D6B)	1178
XU9JAZ (DKZ)	1178
XU9M (DDZ)	1180
XU9S (159)	1180
XU9S (D2B)	1180
XUD11A (P9A)	1196
XUD11ATE (PHZ)	1196
XUD11BTE (P8C)	1196
XUD7 (161A)	1170
XUD7 (A9A)	1170
XUD7T	1170
XUD7TE (A8A)	1170
XUD7TE (A8B)	1170
XUD7TE (AJZ)	1170
XUD9	1174
XUD9 (162)	1174-1176
XUD9 (D9A)	1174-1176
XUD9 (DJZ)	1174
XUD9A (D9B)	1176
XUD9A (DJY)	1176
XUD9AU (D8C)	1176
XUD9BSD (DHW)	1178
XUD9SD (DHW)	1178
XUD9TE	1178
XUD9TE (D8B)	1178
XUD9TE (DHX)	1178
XUD9TE (DHY)	1178
XUD9UTF (D8C)	1178
XV3 (108)	1136
XV5 (108)	1136
XV8 (108C)	1136
XW3 (109)	1140
XW3S	1140
XW3S (121)	1140
XW7 (109F)	1140
XW7 (109N)	1140
XY6B (150)	1154
XY7 (150D)	1154
XY7 (150G)	1154
XY8 (150B)	1154
XY8 (150H)	1154
XZ5 (129)	1142
Z	
ZDJ (851)	1200
ZDJL (851B)	1200
ZDJL (851X)	1200
ZEJ (829)	1194
ZM (112)	1208
ZMJ (140)	1208
ZN3J (154X)	1208
ZPJ (UFZ)	1212
ZPJ4 (UKZ)	1214



PEUGEOT						
Ltr.						
0,9 XV3 (108) XV5 (108)	33-34 kW (45-46 PS)	104	10/72-10/83	S30652-00 ⑫ ⑬ 95551299 S31579-00 ⑫ ⑬ D30652-00 ⑫ 0198.58 D31579-00 ⑫ 0197.74 B31053-00 ⑬ 0197.76 R30652-00 ③ 7910003960 R30712-00 ③ 7701348178 (x4)	H02371-00 0209.46 74,3 Ø 1,2 mm 14 mm H12371-10 0209.52 74,3 Ø 1,4 mm 14 mm H07125-00 0203.84 74,3 Ø 1,2 mm 16 mm H17125-10 020322 74,3 Ø 1,4 mm 16 mm 	
1,0 TU9 TU9M (CDY) TU9M (CDZ)	33-37 kW (45-50 PS)	106 205	10/87→	S31113-00 ⑫ ⑬ 95619476 D31113-00 ⑫ 0197.H8 +0209.89 B31062-00 ⑬ ⑮ R30712-00 ③ 7701348178 (x4)	H07953-00 0209.89 74,3 Ø 1,3 mm H17953-10 74,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,0 XV8 (108C)	32-33 kW (44-45 PS)	104 205	02/83-06/88	S30652-00 ⑫ ⑬ 95551299 S31579-00 ⑫ ⑬ D30652-00 ⑫ 0198.58 D31579-00 ⑫ 0197.74 B31053-00 ⑬ 0197.76 R30652-00 ③ 7910003960 R30712-00 ③ 7701348178 (x4)	H02371-00 0209.46 74,3 Ø 1,2 mm 14 mm H12371-10 0209.52 74,3 Ø 1,4 mm 14 mm H07125-00 0203.84 74,3 Ø 1,2 mm 16 mm H17125-10 020322 74,3 Ø 1,4 mm 16 mm 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.C4 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 X06310-01 ⑮ 1709.10 	X54035-01 ⑮ 70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.C4 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR

⑮ material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



PEUGEOT						
Ltr.						
1,0 1KR (384F)	06/05→	50 kW (68 PS)	107	S36775-00 (12) (13) 0197.AF D36775-00 (12) 0197.AG	H80621-00 0209.EC MLS 	T80621-00 6822.JC (8x)
1,1 E1	10/85-07/89	40 kW (54 PS)	205 309	S30740-00 (12) (13) 0003840000 D30740-00 (12) 0003799700 B30740-00 (13)	H05910-00 0013166700 76,7 Ø H15910-10 0209.28 76,7 Ø 1,8 mm 	
1,1 TU1JP (HFZ) TU1JP (HFZ)	05/96→	44 kW (60 PS)	PARTNER 106 206 206 SW	D36677-00 (12) B37002-00 (13)	H80370-00 0209.Y0 73,5 Ø 1,25 mm 	T01004-00 0204.83 (10x)
1,1 TU1M (HDY) TU1M (HDZ)	07/89→	40-44 kW (54-60 PS)	106 205 306 309	S31062-00 (12) (13) (51) 95619476+97520616 D31062-00 (12) (51) 0197.A7 B31062-00 (13) (51) R30712-00 (3) 7701348178 (x4)	H01004-10 (51) 0209.CJ 76,3 Ø 1,3 mm H11004-20 (51) 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X83080-01 0349.C9 NBR 	N92658-00 0956.54 (12x)	X89098-01 0348.S4 	X81894-01 0349.L1 	70-31414-10 	P77413-01 K ← 6822.RC 38x50x6 A SL RD NBR P77436-01 K → 6822.X0 74x89x8,5 A SL LD MVQ
X05764-01 0249.53 Kork 	N90300-00 0249.48 (8x) P76531-00 0249.48	X07198-01 0348.80 	X05769-01 0349.E2 X07077-01 0016175200 	E30207-00 0012853300+ X05920-01 0304.32 Kork X05923-01 0012853400 	P76119-01 K ← 00167744200 40x58x8 RD P76310-01 K → 0013195100 71x88x8 LD
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19	X87172-01 0342.E0 	4x X82381-01 ✗ 0349.J6 Emission reduction FL5 X82382-01 0349.J3 Exhaust norm L4 X81500-01 ⚠ 1709.25 	X54035-01 (51) 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19	X56780-01 	2x X06306-01 0349.A6 X06310-01 1709.10 	X54035-01 (51) 70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑤ material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



PEUGEOT						
Ltr.						
1,1 TU1M (HDZ)	06/96→	44 kW (60 PS)	PARTNER	S31062-00 ⑫ ⑬ ⑤① 95619476+97520616 D31062-00 ⑫ ⑤① 0197.A7 B31062-00 ⑬ ⑤① R30712-00 ③ 7701348178 (x4)	H01004-10 ⑤① 0209.CJ 76,3 Ø 1,3 mm H11004-20 ⑤① 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,1 XK XK4	10/65-10/77	39-40 kW (53-55 PS)	204	S30787-00 ⑫ ⑬ 0199.58 D30787-00 ⑫ 0199.59 R30787-00 ③	H02719-00 0199.75 78 Ø 	
1,1 XK5	09/75-12/88	43 kW (58 PS)	204 304 305	S30788-00 ⑫ ⑬ 0198.10 D30788-00 ⑫ 0197.92 R30788-00 ③	H08000-00 0209.G7 81 Ø H18000-10 81 Ø 1,4 mm 	T08000-00 0204.36 (10x)
1,1 XW3 (109) XW3S XW3S (121) XW7 (109N)	09/73-10/90	36-49 kW (49-67 PS)	104 205	S31588-00 ⑫ ⑬ 95551299 D31588-00 ⑫ 0197.74 B31588-00 0197.76 R30712-00 ③ 7701348178 (x4)	H00687-00 0209.G8 76 Ø 1,2 mm 16 mm H10687-10 0203.23 76,3 Ø 1,4 mm 16 mm 	
1,1 XW7 (109F)	08/79-06/88	37 kW (50 PS)	104 205	S31589-00 ⑫ ⑬ 0198.59 D31589-00 ⑫ 0197.75 +0209.A6 B31588-00 0197.76 R30712-00 ③ 7701348178 (x4)	H02370-00 0209.A6 76 Ø 1,2 mm 14 mm H12370-10 0209.53 76,3 Ø 1,4 mm 14 mm 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 X06310-01 ① 1709.10 	X54035-01 ⑤① 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X03012-01 0249.21 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X08001-01 0349.23 X03013-01 ① 1721.01 X03015-01 ① 1710.11 	X05037-01 0304.09 Kork 	P76113-01 K ← 2074.07 40x49,5x5,5/7 FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM
X03012-01 0249.21 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X08001-01 0349.23 X03015-01 ① 1710.11 	X05037-01 0304.09 Kork 	P76113-01 K ← 2074.07 40x49,5x5,5/7 FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM
X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.C4 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR
X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.C4 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR

⑤① material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



PEUGEOT						
Ltr.						
1,2 F1	47 kW (64 PS) 205	01/87-12/90	S30207-00 ⑫ ⑬ 4033036320 D30207-00 ⑫ 4033036320 B30207-00	H05910-00 0013166700 76,7 Ø H15910-10 0209.28 76,7 Ø 1,8 mm 		
1,2 XLD	29 kW (39 PS) 204 D	05/68-05/73	S30546-00 ⑫ ⑬ 0199.76 → 7931040 S30789-00 ⑫ ⑬ 0198.32 7931041 → D30546-00 ⑫ 0199.75 → 7931040 D30789-00 ⑫ 0198.26 7931041 →	H03026-00 0203.38 78,5 Ø → 7931040 H08002-00 0203.56 78,5 Ø 7931041 → 		
1,2 XZ5 (129)	42 kW (57 PS) 104	08/79-06/83	S31588-00 ⑫ ⑬ 95551299 D31588-00 ⑫ 0197.74 B31588-00 0197.76 R30712-00 ③ 7701348178 (x4)	H00687-00 0209.68 76 Ø 1,2 mm 16 mm H10687-10 0203.23 76,3 Ø 1,4 mm 16 mm 		

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X05764-01 0249.53 Kork 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X05917-01 0055204500 	X05769-01 0349.E2 	E30207-00 0012853300+ X05920-01 0304.32 Kork X05923-01 0012853400 	P76119-01 K ← 00167744200 40x58x8 RD P76310-01 K → 0013195100 71x88x8 LD
X02721-01 0249.23 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07101-01 0349.13 X07116-01 0349.12 2x X03015-01 1710.11 	X05037-01 0304.09 Kork 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM 7931041 →	
X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07565-01 0348.54 	X07126-01 0349.C4 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR



PEUGEOT						
Ltr.						
1,3 G1A	02/84-07/92	47 kW (62-64 PS)	205 309	1		
				S30741-00 0017477200 D30741-00 0016806800	(12) (13)	H06900-00 0209.29 78,5 Ø 1,2 mm
1,3 TU24	10/87-10/90	74 kW (101 PS)	205			
				S31437-00 D31437-00 B31062-00 R30712-00 7701348178 (x4)	(12) (13)	H01004-10 (51) 0209.CJ 76,3 Ø 1,3 mm H11004-20 (51) 0209.CK 76,3 Ø 1,5 mm
						T01004-00 0204.83 (10x)
1,3 XL3 XL3S	10/69-07/76	48-55 kW (65-75 PS)	304			
				S30787-00 0199.58 D30787-00 0199.59 R30787-00	(12) (13)	H02719-00 0199.75 78 Ø
1,3 XL4D	01/73-10/77	33 kW (45 PS)	204 D			
				S30790-00 0198.35 D30790-00 0198.36 	(12) (13)	H08003-00 0203.61 80,5 Ø 1,4 mm H18003-10 0203.62 80,5 Ø 1,6 mm

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X05764-01 0249.53 Kork 	N90300-00 0249.48 (8x) P76531-00 0249.48	X05917-01 0055204500 X07198-01 0348.80 	X05769-01 0349.E2 X07077-01 0016175200 	E30207-00 0012853300+ X05920-01 0304.32 Kork X05923-01 0012853400 	P76119-01 K ← 00167744200 40x58x8 RD P76310-01 K → 0013195100 71x88x8 LD
X06304-01 0249.54 	N90300-00 0249.48 (8x) P76531-00 0249.48	X06306-01 0349.A6 X06310-01 1709.10 	2x X08001-01 0349.23 X03015-01 1710.11 	X54035-01 (51) 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X03012-01 0249.21 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	X08001-01 0349.23 X03015-01 1710.11 	X05037-01 0304.09 Kork 	X05037-01 0304.09 Kork 	P76113-01 K ← 2074.07 40x49,5x5,5/7 FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM
X02721-01 0249.23 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	X07116-01 0349.12 X08005-01 0349.18 X03015-01 1710.11 	2x X05037-01 0304.09 Kork 	X05037-01 0304.09 Kork 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM

⑤ material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



PEUGEOT						
Ltr.						
1,3 XL5	48 kW (65 PS) 304 305	09/70-09/82	S30788-00 ⑫ ⑬ 0198.10 D30788-00 ⑫ 0197.92 R30788-00 ③	H08000-00 0209.67 81 Ø H18000-10 81 Ø 1,4 mm 	T08000-00 0204.36 (10x) 	
1,3 XL5 (118)	44 kW (60 PS) 305	11/77-08/86	S30788-00 ⑫ ⑬ 0198.10 D30788-00 ⑫ 0197.92 R30788-00 ③	H08000-00 0209.67 81 Ø H18000-10 81 Ø 1,4 mm 	T08000-00 0204.36 (10x) 	
1,3 XL5S	55 kW (75 PS) 304	08/72-09/75	S30788-00 ⑫ ⑬ 0198.10 D30788-00 ⑫ 0197.92 R30788-00 ③	H08000-00 0209.67 81 Ø H18000-10 81 Ø 1,4 mm 	T08000-00 0204.36 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X03012-01 0249.21 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X08001-01 0349.23 X03013-01 ① 1721.01 X03015-01 ① 1710.11 X04201-01 ① 1710.09 	X05037-01 0304.09 Kork 	P76113-01 K ← 2074.07 40x49,5x5,5/7 FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM
X03012-01 0249.21 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X08001-01 0349.23 X81934-01 0349.36 X03015-01 ① 1710.11 X04201-01 ① 1710.09 	X05037-01 0304.09 Kork 	P76113-01 K ← 2074.07 40x49,5x5,5/7 FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM
X03012-01 0249.21 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X08001-01 0349.23 X03013-01 ① 1721.01 X03015-01 ① 1710.11 	X05037-01 0304.09 Kork 	P76113-01 K ← 2074.07 40x49,5x5,5/7 FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM



PEUGEOT

PEUGEOT						
Ltr.						
1,4 DV4TD (8HX) DV4TD (8HZ)	50-51 kW (68-69 PS)	1007 HDI 206 HDI 206 SW HDI 207 HDI 307 HDi 307 HDI	09/01→	S36724-00 ⁽¹²⁾ ⁽¹³⁾ D36724-00 ⁽¹²⁾ B36724-00 ⁽¹³⁾	H08129-00 0209.AC 1,2 mm 2 MLS H08129-10 0209.AE 1,3 mm 3 MLS H08129-20 0209.AF 1,35 mm 1 MLS H18129-30 0209.AG 1,4 mm 4 MLS H18129-40 0209.AH 74,7 Ø 1,45 mm 5 MLS 	T08130-00 0204.A2 (10x)
1,4 EP3 8FS (EP3)	70 kW (95 PS)	207 308	06/07→	D40616-00 ⁽¹²⁾ ⁽¹⁹⁾ D40616-01 ⁽¹²⁾ H40616-00 0209.EW 78 Ø 0,9 mm MLS H40616-10 78 Ø 1,2 mm MLS 	H40616-00 0209.EW 78 Ø 0,9 mm MLS H40616-10 78 Ø 1,2 mm MLS 	T40616-00 0204.C1
1,4 ET3J4 (KFU)	65 kW (88 PS)	1007 16V 206 SW 16V 206 16V 207 307 SW 16V 307 16V	10/03→	D37222-00 ⁽¹²⁾ B37222-00 ⁽¹³⁾	H80612-00 0209.FL 76 Ø 1,4 mm 	T80612-00 0204.A5 (10x)

⁽¹⁹⁾ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



V38516-00 0249.F8 +0348.T8 (4x) +0348.S8 (2x) X83035-01 0249.F8 NBR 	N92983-00 0956.50 (8x) P76779-00 0956.50 8x	W88317-01 0348.R2 4x 	X81696-01 0349.J8 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM
V38326-00 0249.F4 	N93158-00 0956.60 P93158-00 16x	M59582-00 0348.T4 (4X) 	X59642-01 1723.CH 	70-31414-10 	P77789-01 K ← 0514.C8 61x75x8 A SL RD P77670-01 K → 0514.A2 85x105x8 A SL LD
X83066-01 R 0249.C5 X83067-01 L 0249.C4 	N93130-00 0956.52 (16x) P76841-00 0956.52 16x	M36836-00 0348.S1 	X81664-01 0349.J4 X82404-01 1709.29 	70-31414-10 	P77669-01 K ← 0514.A3 42x66x7 A SL RD P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77492-01 N 0807.32 36x50x8 A SL RD PTFE ACM P77593-01 N 0807.33 24x50x8 A SL RD



PEUGEOT						
Ltr.						
1,4 TUD3 (K9Y)	37 kW (50 PS)	106 D	09/92-04/96	S31055-00 (12) (13) 0197.K2 D31055-00 (12) 0197.K3 B31055-00 (13) R30712-00 (3) 7701348178 (x4)	H03751-00 0209.E9 76,3 Ø H80573-00 0209.N4 MLS 	T03751-00 0204.84 (10x)
1,4 TU3A (KFV)	53-55 kW (72-75 PS)	BIPPER PARTNER 206 206 SW 207	07/02→		H01004-10 (51) 0209.CJ 76,3 Ø 1,3 mm H11004-20 (51) 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,4 TU3A (K1D) TU3CP (KAY) TU3M (KDY) TU3M (KDZ) TU3MC (KDX) TU3S (K2B) TU32	44-62 kW (60-84 PS)	PARTNER 106 205 306 309 405	06/87→	S31062-00 (12) (13) (51) 95619476+97520616 S31600-00 (12) (13) (53) 0197.J1+0209.A9 D31062-00 (12) (51) 0197.A7 D31600-00 (12) (53) 0197.J0 +0209.A9 B31062-00 (13) (51) B31600-00 (13) R30712-00 (3) 7701348178 (x4)	H01004-10 (51) 0209.CJ 76,3 Ø 1,3 mm H11004-20 (51) 0209.CK 76,3 Ø 1,5 mm H08191-00 (53) 0209.A9 76,3 Ø 1,2 mm H18191-10 (53) 0209.92 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра

⑤ material bloque motor Aluminí / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



X05398-01 0249.76 	N90300-00 0249.48 (8x) P76532-00 0956.19 8x		X05443-01 0349.E4 X05444-01 1710.58 	X54035-01 (51) 70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x		X82382-01 0349.J3 	70-31414-10 	P77669-01 K ← 0514.A3 42x66x7 A SL RD P77670-01 K → 0514.A2 85x105x8 A SL LD
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X56780-01 2x 	X06306-01 2x 0349.A6 X06310-01 1709.10 	X54035-01 (51) 70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑤ material bloque motor Fonte grise / Motorblockmaterial Grauguß / engine Block Material Grey Cast Iron / matériel pour bloc-moteur / materiale blocco motore A getto di ghisa grigia / материал блока двигателя Серый чугун



PEUGEOT						
Ltr.						
1,4 TU3JP (KFV) TU3JP (KFW) TU3JP (KFX)	54-55 kW (73-75 PS)	PARTNER 1007 106 205 206 206 SW 306 307	07/88→	S32984-00 ⑫ ⑬ D32984-00 ⑫ 0197.H8+0209.CJ B31600-00 ⑬ R30712-00 ③ 7701348178 (x4)	H01004-10 ⑤① 0209.CJ 76,3 Ø 1,3 mm H11004-20 ⑤① 0209.CK 76,3 Ø 1,5 mm 	T01004-00 0204.83 (10x)
1,4 TU3J2/Z (KFZ)	69 kW (94 PS)	106	09/91-04/96	D37003-00 ⑫ 0197.J0 +0209.D6 B31600-00 ⑬ 	H80549-00 0209.D6 77 Ø 1,2 mm H80549-10 0209.C1 77 Ø 1,4 mm 	T01004-00 0204.83 (10x)
1,4 XL4D	33 kW (45 PS)	204 D 304 D	09/73-10/79	S30790-00 ⑫ ⑬ 0198.35 D30790-00 ⑫ 0198.36 	H08003-00 0203.61 80,5 Ø 1,4 mm 1 M H18003-10 0203.62 80,5 Ø 1,6 mm 2 M 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	X87172-01 0342.E0 4x 	X06306-01 2x 0349.A6 X82381-01 X 0349.J6 Emission reduction FL5 X82382-01 X 0349.J3 Exhaust norm L4 X06310-01 Δ 1709.10 	X54035-01 ⑤① 70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x		X06306-01 2x 0349.A6 X06310-01 Δ 1709.10 	70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X02721-01 0249.23 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X07116-01 2x 0349.12 X08005-01 0349.18 X03015-01 Δ 1710.11 	X05037-01 0304.09 Kork 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM

⑤① material bloque motor Alumini / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



PEUGEOT						
Ltr.						
1,4 XY6B (150) XY7 (150D) XY7 (150G) XY8 (150B) XY8 (150H)	44-59 kW (60-80 PS) 104 205	08/79-05/89	S31053-00 ⑫ ⑬ 95586978+91503885 S31586-00 ⑫ ⑬ 95586978+97531974 D31053-00 ⑫ 0197.75 D31586-00 ⑫ 95586979+97531974 B31053-00 ⑬ 0197.76 R30712-00 ③ 7701348178 (x4)	H00687-00 0209.G8 76 Ø 1,2 mm 16 mm H10687-10 0203.23 76,3 Ø 1,4 mm 16 mm H02370-00 0209.A6 76 Ø 1,2 mm 14 mm H12370-10 0209.53 76,3 Ø 1,4 mm 14 mm 		
1,4 8HS (DV4TD) 8HT (DV4TD) [NEW]	40-50 kW (54-68 PS) BIPPER HDI 107 HDI	06/05→	S36724-01 ⑫ ⑬ 0197.AV +0956.50 (8x) D36724-00 ⑫ 	H08129-00 0209.AC 1,2 mm 2 MLS H08129-10 0209.AE 1,3 mm 3 MLS H08129-20 0209.AF 1,35 mm 1 MLS H18129-30 0209.AG 1,4 mm 4 MLS H18129-40 0209.AH 74,7 Ø 1,45 mm 5 MLS 	T08130-00 0204.A2 (10x) 	
1,5 TUD5 (VJX) TUD5 (VJY)	40-42 kW (54-57 PS) 106 D	06/94→	S31599-00 ⑫ ⑬ D31599-00 ⑫ 0197.V1 +0209.T8 B31599-00 ⑬ 0197.V0 R30712-00 ③ 7701348178 (x4)	H50321-00 78 Ø H80263-00 0209.T8 78 Ø MLS 	T50321-00 0204.85 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X07128-01 0249.39 	N90300-00 0249.48 (8x) P76531-00 0249.48 	X07565-01 0348.54 	X07126-01 0349.C4 X81933-01 1710.41 	X07129-01 0304.46 	P76099-11 K ← 0236.14 35x50x8 A SL WD FPM P76321-01 K → 0514.14 78x100x10 A SL LD MVQ P76003-01 N 0526.06 14x19x4,5 NBR
V38516-00 0249.F8 +0348.T8 (4x) +0348.S8 (2x) 	N92983-00 0956.50 (8x) P76779-00 0956.50 		X81696-01 0349.J8 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM
X53099-01 0249.81 	N91190-00 0956.19 (8x) P76532-00 0956.19 		X05443-01 0349.E4 X05444-01 1710.58 	70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM



PEUGEOT

PEUGEOT						
Ltr.						
1.5 XB5 XB5P	39-61 kW (53-83 PS)	J7	08/68→	A30791-00 ⑫ ⑭ 0198.35 D30791-00 ⑫ 0199.36 R30553-00 ③ 0112.17(4)	H03545-00 0203.26 82,5 Ø 	
1.5 XR5 (142) XR5A (142) XR5S (117)	50-65 kW (68-88 PS)	305	11/79-07/90	S30788-00 ⑫ ⑬ 0198.10 D30788-00 ⑫ 0197.92 R30788-00 ③	H08000-00 0209.G7 81 Ø H18000-10 81 Ø 1,4 mm 	T08000-00 0204.36 (10x)
1.6 DV6ATED4 (9HX) DV6TED4 (9HY) DV6TED4 (9HZ) 9HV (DV6ATED4)	66-80 kW (90-110 PS)	EXPRESS TD PARTNER HDI 1007 HDI 206 CC HDI FAP 110 206 HDI FAP 110 206 SW HDI FAP 110 207 CC HDI 207 HDI 3008 HDI 307 D 307 HDI 307 HDI 110 FAP 307 SW HDI 110 FAP 308 HDI 407 HDI 110 FAP 407 SW HDI 110 FAP 5008 HDI	02/04→	S36730-00 ⑫ ⑬ D36730-00 ⑫ B36724-00 ⑬	H08130-00 0209.CA 76 Ø 1,25 mm 4 ■ H08130-10 0209.CC 76 Ø 1,3 mm 5 ■ H08130-20 0209.CE 76 Ø 1,35 mm 3 ■ H18130-30 0209.CF 76 Ø 1,4 mm 6 ■ H18130-40 0209.CG 76 Ø 1,45 mm 7 ■ 	T08130-00 0204.A2 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04834-01 0348.06 	X04833-01 0349.03 X03013-01 △ 1721.01 X05087-01 △ 1710.15 	X04838-01 0304.03 Kork 	
X03012-01 0249.21 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X08001-01 0349.23 X03015-01 △ 1710.11 X04201-01 △ 1710.09 	X05037-01 0304.09 Kork 	P76113-01 K ← 2074.07 40x49,5x5,5/7 FPM P76268-01 K → 2109.06 60,5x78x9 A RD FPM
X83038-01 0249.C2 NBR 	N93118-00 0956.51 (16x) P76780-00 0956.51 16x	W88321-01 4x 0348.R4 W88322-01 4x 0348.R5 	X81696-01 0349.J8 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



PEUGEOT						
Ltr.						
1,6 DV6C 9HR (DV6C) [NEW]	82 kW (110-112 PS)	207 HDI 3008 HDI 308 HDI 5008 HDI 508 HDI	06/09→			
				H40595-00 0209.JF 75,7 Ø 1,25 mm 5	T40595-00 0205.57 (10x) 	
				H40595-10 0209.JG 75,7 Ø 1,3 mm 6		
				H40595-20 0209.JH 75,7 Ø 1,35 mm 4		
				H40595-30 0209.JJ 75,7 Ø 1,4 mm 7		
				H40595-40 0209.JK 75,7 Ø 1,45 mm 8		
1,6 EP6 5FS (EP6C)	88 kW (120 PS)	PARTNER 207 207 CC 3008 308 5008 508	02/07→	D40616-00 D40616-01 	H40616-00 0209.EW 78 Ø 0,9 mm MLS H40616-10	T40616-00 0204.C1
1,6 EP6CDT EP6CDTX 5FR (EP6DT) 5FT (EP6DT) 5FV (EP6DT) 5FX (EP6DT) 5FY (EP6DTS)	103-147 kW (140-200 PS)	RCZ 205 207 207 CC 207 CC TURBO 207 TURBO 3008 THP 308 308 CC 5008 508 508 SW	02/06→	D40634-00 D40634-01 	H40634-00 0209.ER 78 Ø 0,9 mm MLS H40634-10	T40616-00 0204.C1

⑬ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров

X83409-01 0249.G2 	N92983-00 0956.50 (8x) P76779-00 0956.50 8x		X59533-01 0349.N5 	70-31414-10 	P77361-01 K ← 0127.42 40x55x6,4 A SL RD PTFE ACM P77362-01 K → 0127.43 85x105x8,8 A SL LD PTFE ACM P77668-01 N 0807.30 27x47x7 A SL RD PTFE ACM
			X59534-01 0349.N9 		
V38326-00 0249.F4 	N93158-00 0956.60 P93158-00 16x	M59582-00 0348.T4 (4X) 	X59642-01 1723.CH 	70-31414-10 	P77789-01 K ← 0514.C8 61x75x8 A SL RD P77670-01 K → 0514.A2 85x105x8 A SL LD
V38327-00 0249.E6 +0249.E7 	N93158-00 0956.60 P93158-00 16x	M59583-00 0348.S9 	X59643-01 1723.AZ 	70-31414-10 	P77789-01 K ← 0514.C8 61x75x8 A SL RD P77670-01 K → 0514.A2 85x105x8 A SL LD

PEUGEOT



PEUGEOT						
Ltr.						
1,6 NFR (TU5JP4B) TU5JP4 (N6A) [NEW]	66-83 kW (90-113 PS) PARTNER	04/08→		D36693-00 ⑫ B36693-00 ⑬	H80497-00 0209.1E 78,5 Ø MLS 	T04220-00 0204.81 (10x)
1,6 TU5JP (NFT) TU5JP (NFZ) TU5J2 (NFW) TU5J2 (NFY)	65-76 kW (88-103 PS) 106 206 306	05/93→		S31601-00 ⑫ ⑬ 0197.J1 D31601-00 ⑫ 0197.J0 B31600-00 ⑬ 	H08194-00 0209.F6 79 Ø →07874 H09196-00 0209.W8 1,38 mm MLS →07875→ H19196-10 0209.W9 79,7 Ø 1,57 mm MLS →07875→ 	T01004-00 0204.83 (10x)
1,6 TU5JP4 (NFU)	80-82 kW (109-112 PS) PARTNER PARTNER 16V 1007 16V 206 206 CC 16V 206 SW 16V 206 16V 207 307 307 CC 16V 307 SW 16V 307 16V 308	08/00→		D36693-00 ⑫ B36693-00 ⑬	H80497-00 0209.1E 78,5 Ø MLS 	T04220-00 0204.81 (10x)
1,6 TU5J4 (NFX)	87 kW (118 PS) 106	05/96→		S32979-00 ⑫ ⑬ 0197.F1 D32979-00 ⑫ B32979-00 ⑬	H04220-00 0209.Z0 1,4 mm 6 ■ MLS H14220-10 0209.W3 1,57 mm 7 ■ MLS H24220-20 0209.Z1 79,7 Ø 1,77 mm 8 ■ MLS 	T04220-00 0204.81 (10x)

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X83028-01 2x 0249.A9 NBR 	N92004-00 0956.40 (16x) P76809-00 0956.40 16x	M74443-00 0348.05 	X81664-01 0349.J4 X81500-01 1709.25 	X54807-01 0304.55 NBR 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77141-01 N 2x 0807.24 38x50x6 A SL RD FPM
X06304-01 0249.54 	N91190-00 0956.19 (8x) P76532-00 0956.19 8x	M38099-00 0348.P3 (4x) X86028-01 0348.E5 →07874 X82384-01 0348.P3 →07875→ 	X06306-01 2x 0349.A6 X82382-01 0349.J3 X81500-01 1709.25 	70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P76355-11 K → 85x105x9 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X83028-01 2x 0249.A9 NBR →2336722 X59782-01 X →2336723→ 	N92004-00 0956.40 (16x) P76809-00 0956.40 16x	M74443-00 0348.05 	X81664-01 0349.J4 X81500-01 1709.25 	X54807-01 0304.55 NBR 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77141-01 N 2x 0807.24 38x50x6 A SL RD FPM
70-31414-10 	N92990-00 0956.38 (16x) P76662-00 0956.38 16x	X58964-01 4x 0348.L0 X59969-01 ⑩ 2x 0348.L1 	X52322-01 0349.F9 X52323-01 1709.12 	70-31414-10 	P76154-01 K ← 0514.38 42x66x6 A SL RD MVQ P76353-01 K → 0514.74 85x105x8 A SL LD FPM P77141-01 N 2x 0807.24 38x50x6 A SL RD FPM



PEUGEOT						
Ltr.						
1,6 XC5P	08/68-03/80	50 kW (68 PS)	J7 J7 Bus	A30548-00 ⑫ ⑭ 0199.40 D30548-00 ⑫ 0199.84 R30553-00 ③ 0112.17(4)	H04608-00 0203.24 86,8 Ø 	
1,6 XC6	11/67-12/71	50-54 kW (68-73 PS)	404 404 GT	A30548-00 ⑫ ⑭ 0199.40 D30548-00 ⑫ 0199.84 R30553-00 ③ 0112.17(4)	H04608-00 0203.24 86,8 Ø 	
1,6 XC7P	08/68-03/80	44 kW (60 PS)	J7 J7 Bus	A30547-00 ⑫ ⑭ D30547-00 ⑫ R30547-00 ③	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x)
1,6 XC7P	01/80-06/87	44-46 kW (60-63 PS)	J9 504	A30547-00 ⑫ ⑭ D30547-00 ⑫ R30547-00 ③	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x) i → 06/85 T02760-00 0204.51 (10x) i 07/85 →

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04834-01 0348.06 4x 	X04833-01 0349.03 X03013-01 Δ 1721.01 X04201-01 Δ 1710.09 X05087-01 Δ 1710.15 	X04838-01 0304.03 Kork 	
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04834-01 0348.06 4x 	X04833-01 0349.03 X03013-01 Δ 1721.01 X04201-01 Δ 1710.09 X05087-01 Δ 1710.15 	X04838-01 0304.03 Kork 	
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X04833-01 0349.03 X03013-01 Δ 1721.01 X04201-01 Δ 1710.09 X05087-01 Δ 1710.15 	X54253-01 Kork 	
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X04833-01 0349.03 X03013-01 Δ 1721.01 X04201-01 Δ 1710.09 X05087-01 Δ 1710.15 	X54253-01 Kork 	

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



PEUGEOT						
Ltr.						
1,6 XU5CP (BAZ) XU5J (180A) XU5J (180Z) XU5M (BDY) XU5M (BDZ) XU5S (171) XU51C (B1A) XU51C (B1E) XU52C/K (B2A)	53-76 kW (72-103 PS)	205 205 GTI 309 405	03/87-09/98	S30559-00 0197.89 D30559-00 0197.H6 +0209.E1 B30559-00 R31124-00	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T01025-00 0204.57 (10x)
1,6 XU5CP (BAZ) XU5J (B6B) XU5J (180A) XU5J (180Z) XU5S (171) XU51C (B1A) XU51C (B1D) XU52C/K (B2A)	54-76 kW (73-103 PS)	205 205 GTI 305 309 405	10/82→	S30559-00 0197.89 D30559-00 0197.H6 +0209.E1 B30559-00 R31124-00	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T11025-00 0204.89 (10x) i →03/87 T01025-00 0204.57 (10x) i 04/87→
1,6 XU5JP (BFZ)	65 kW (88 PS)	405 406	08/92-05/04	S31580-00 D31580-00 0197.G4 B31580-00 R31124-00	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T11025-00 0204.89 (10x) →07448 T01025-00 0204.57 (10x) →07449→
1,6 1580 SPI (222A2)	58 kW (79 PS)	EXPERT	02/96→	S32919-00 D32919-00 B32919-00	H00593-10 0209.P9 87 Ø	T05082-00
1,8 EW7A (6FY)	92 kW (125 PS)	407 SW 16V 407 16V	09/05→		H80768-00 0209.FR MLS	T80768-00 0204.A3 (10X)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/de scarico / прокладка всасывающего/выпускного колена



X01021-01 0249.48	N90300-00 0249.48 (8x) P76531-00 0249.48	X07804-01	X01022-01 0349.70	4x	X04848-01 0127.05 NBR X07793-01 0304.34	2x	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01021-01 0249.48	N90300-00 0249.48 (8x) P76531-00 0249.48	X07804-01	X01022-01 0349.70	4x	X04848-01 0127.05 NBR X07793-01 0304.34	2x	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X53101-01 0249.71	N90300-00 0249.48 (8x) P76531-00 0249.48	X56171-01 0348.F6 X56170-01 0348.E6	X52670-01 1723.63	2x	X04848-01 0127.05 NBR X07793-01 0304.34	2x	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01619-01 U 0249.48 X53175-01 O X53734-01 0249.84 Kork	N90300-00 0249.48 (8x) P76531-00 0249.48		X51425-01 ⑦	8x	X00688-01 0304.49 Gummi		P76117-01 K ← 0304.49 40x56x7 A SL RD MVQ P76273-01 K → 64x80x8 A SL LD MVQ P76060-01 N 30x52x7 AB SL RD FPM
	N92657-00 0956.45 (16x) P76657-00 0956.45	X89881-01 0348.S2	X82335-01 0349.L4	4x	70-31414-10		P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM P77626-01 N 0236.74 39x50x7 A SL RD

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора

O arriba / oben / top / haut / superiore / сверху
U debajo / unten / bottom / bas / inferiore / снизу



PEUGEOT						
Ltr.						
1,8 EW7J4 (6FZ)	10/00→	85 kW (116 PS) 406 16V 407 407 SW	S36503-00 ⑫ ⑬ 0197.Y1 +0209.QG +0249.A4 +0249.A5 D36503-00 ⑫ B36503-00 ⑬	H80288-00 0209.QG 83 Ø MLS 	T07586-00 0204.A7 (10x) 	
1,8 KF5 KF6	07/68-02/71	71 kW (97 PS) 504	A30558-00 ⑫ ⑭ D30558-00 ⑫ 0199.89 R30553-00 ③ 0112.17(4)	H02667-00 0203.40 87,5 Ø 		
1,8 XDP85		35-44 kW (48-60 PS)	S30129-00 ⑫ ⑬ 0198.24 D30129-00 ⑫ 0199.48 R30794-00 ③	H03040-00 0203.51 92 Ø 		
1,8 XM XM7	07/68-06/83	55-60 kW (75-82 PS) 504	A30547-00 ⑫ ⑭ D30547-00 ⑫ R30547-00 ③	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x) 	
1,8 XM7	07/87-12/89	53 kW (72 PS) 504	A30547-00 ⑫ ⑭ D30547-00 ⑫ R30547-00 ③	H02666-00 86,7 Ø 	T02760-00 0204.51 (10x) i →04/89 T01025-00 0204.57 (10x) i 05/89→ 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X53933-01 L 0249.A4 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X86822-01 0348.P1 4x 	X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X53934-01 R 0249.A5 					
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X05047-01 0348.18 	X04833-01 0349.03 X04201-01 1710.09 	X05060-01 0304.44 Kork 	
X03043-01 0249.17 Kork 	N90270-00 0956.01 (8x) P76539-00 0956.19 8x	X06855-01 0348.52 3x 	X03037-01 1710.04 X07092-01 0349.08 2x X05087-01 1710.15 	X03048-01 0313.19 	P76150-01 K ← 0514.11 42x60x8 A RD FPM X05262-01 K → 2x
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X04833-01 0349.03 X04201-01 1710.09 X05087-01 1710.15 	X54253-01 Kork 	
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x		X04833-01 0349.03 X04201-01 1710.09 X05087-01 1710.15 	X54253-01 Kork 	

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



PEUGEOT						
Ltr.						
1,8 XM7 XM7 (105)	54-60 kW (73-82 PS)	504 505	04/71-10/86	A30547-00 D30547-00 R30547-00 ⑫ ⑭ ⑫ ③	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x) ① →06/85 T02760-00 0204.51 (10x) ① 07/85→
1,8 XM7A (105C)	62 kW (84 PS)	505	09/85-10/86	A30547-00 D30547-00 R30547-00 ⑫ ⑭ ⑫ ③	H02666-00 86,7 Ø 	T02760-00 0204.51 (10x)
1,8 XM7P	48 kW (65 PS)	J7 J7 Bus	07/70-03/80	A30547-00 D30547-00 R30547-00 ⑫ ⑭ ⑫ ③	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x)
1,8 XM7T (169B)	51 kW (69 PS)	J5	01/83-11/88	S30778-00 D30778-00 ⑫ ⑬ ⑫	H02666-00 86,7 Ø 	T02666-00 0204.21 (10x) ① →06/85 T02760-00 0204.51 (10x) ① 07/85→

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04833-01 0349.03 X04201-01 1710.09 X05087-01 1710.15 	X04833-01 0349.03 X04201-01 1710.09 X05087-01 1710.15 	X54253-01 Kork 	
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04833-01 0349.03 X04201-01 1710.09 X05087-01 1710.15 	X04833-01 0349.03 X04201-01 1710.09 X05087-01 1710.15 	X54253-01 Kork 	
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x X07480-01 0348.33 	X04833-01 0349.03 X03013-01 1721.01 X04201-01 1710.09 X05087-01 1710.15 	X04848-01 2x 0127.05 NBR X54253-01 Kork
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04833-01 0349.03 X03013-01 1721.01 X04201-01 1710.09 X05087-01 1710.15 	X04848-01 2x 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



PEUGEOT						
Ltr.						
1,8 XM7T (169B)	09/90-01/94	51 kW (69 PS)	J5	S30778-00 D30778-00 ⑫ ⑬	H02666-00 86,7 Ø 	T01025-00 0204.57 (10x)
1,8 XUD7 (A9A) XUD7 (161A)	11/82→	43-44 kW (58-60 PS)	PARTNER D 205 D 305 D 306 D 309 D	S30527-00 0197.H5 D30527-00 0197.37 +0956.22 (8x) B30527-00 ⑬	H05875-00 0209.S0 1,36 mm 1 H05875-10 0209.S1 1,4 mm 2 H05875-20 0209.S2 1,44 mm 3 H15875-30 0209.S3 1,48 mm 4 H15875-40 0209.S4 82 Ø 1,53 mm 5 H08280-00 0209.F9 1,57 mm 2 H18280-10 1,7 mm 3	T08280-00 0204.65 (10x)
1,8 XUD7T XUD7TE (AJZ) XUD7TE (A8A) XUD7TE (A8B)	03/88-09/98	57-66 kW (78-90 PS)	205 205 TD 309 TD 405 TD	S31587-00 0197.H5 D31587-00 B30527-00 ⑬	H02299-00 0209.G0 1,6 mm 2 H12299-10 0209.G0 82 Ø 1,75 mm 3	T08280-00 0204.65 (10x)
1,8 XU7JB (LFX)	05/97→	66 kW (90 PS)	PARTNER 406	S36241-00 D36241-00 B31580-00 R31124-00 ⑫ ⑬ ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 0348.33 	X04833-01 0349.03 	X04848-01 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X07796-01 0249.46 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X55498-01 0348.99 X55499-01 0348.98 	X07782-01 0349.47 X03013-01 1721.01 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM
X07796-01 0249.46 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X03013-01 1721.01 X51229-01 ⑦ 0348.89 i → 12/90 X51239-01 ⑦ 0348.J0 i 01/91→ 	X04848-01 0127.05 NBR X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM	
X53101-01 0249.71 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X85532-01 0348.L7 	X52670-01 1723.63 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



PEUGEOT						
Ltr.						
1,8 XU7JP (LFW) XU7JP (LFZ)	08/92-08/02	73-74 kW (99-101 PS)	EXPERT 306 405 806	S31580-00 ⑫ ⑬ D31580-00 ⑫ 0197.G4 B31580-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T11025-00 0204.89 (10x) → PR3975 T01025-00 0204.57 (10x) → PR3975
1,8 XU7JP4 (LFY)	11/95-04/02	81 kW (110 PS)	306 16V 406 16V	S37004-00 ⑫ ⑬ 0197.V5 +0209.Q3 +0249.A2 +0249.A3 → 07965 S32980-00 ⑫ ⑬ 0197.X7 +0209.Q3 +0249.A2 +0249.A3 → 07966 D37004-00 ⑫ → 07965 D32980-00 ⑫ → 07966 B32980-00 ⑬	H80030-00 0209.Q3 84 Ø 	T80030-00 0204.80 (10x)
1,9 DW8 (WJZ) DW8B (WJY)	06/96→	51 kW (69 PS)	EXPERT D PARTNER D 206 D 306 D	S32985-00 ⑫ ⑬ 0197.X6 +0127.28 +0326.22 +0807.14 D32985-00 ⑫ 0197.X5 +0807.14 B32989-00 ⑬	H05616-00 0209.X0 84 Ø 1,26 mm 3 MLS H05616-10 0209.X1 1,3 mm 4 MLS H05616-20 0209.X2 1,34 mm 5 MLS H15616-30 0209.X3 1,38 mm 6 MLS H15616-40 0209.X4 1,42 mm 7 MLS H15616-50 0209.1C 84 Ø 1,47 mm 4 MLS 	T08280-00 0204.65 (10x) → 08469 T05616-00 0204.97 (10x) → 08470

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X53101-01 0249.71 	N90300-00 0249.48 (8x) P76531-00 0249.48	X56171-01 0348.F6 2x X56170-01 ⑩ 2x 0348.E6 	X52670-01 1723.63 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X53731-01 L 0249.A2 X53732-01 R 0249.A3 	N93063-00 0956.34 (16x) → 07363 N93062-00 0956.42 (16x) → 07364 → 07965 N92657-00 0956.45 (16x) → 07966 P76817-00 0956.34 → 07363 P76750-00 0956.42 → 07364 → 07965 P76657-00 0956.45 → 07966	X56177-01 0348.C8 → 07037 X58966-01 0348.K6 → 07038 	X52325-01 0349.F4 → 07664 X52324-01 0349.H0 → 07665 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X53733-01 U 0249.97 X53780-01 O 0249.95 	N90300-00 0249.48 (8x) P76531-00 0249.48	X58969-01 0348.N2 2x X58970-01 0348.N1 	X52327-01 0349.H7 2x 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM

O arriba / oben / top / haut / superiore / сверху

U debajo / unten / bottom / bas / inferiore / снизу



PEUGEOT						
Ltr.						
1,9 XDP88	40 kW (55 PS) J7 Bus D J7 D	08/68-07/78	S30226-00 ⑬ 0198.14 → 2053776 S30794-00 ⑫ ⑬ 0198.40 → 2053777→ D30226-00 0197.08 → 2053776 D30794-00 ⑫ 0197.09 → 2053777→ B30756-00 ⑬ ⑯ → 4586484→ R30794-00 ③	H02668-00 0209.L2 94 Ø → 2053776 H07635-00 0203.70 1,6 mm → 2053777→ H17635-10 94 Ø 1,7 mm → 2053777→ 		
1,9 XD4X88	40 kW (54 PS) 504 D	03/73-12/89	S30226-00 ⑬ 0198.14 → 2053776 S30794-00 ⑫ ⑬ 0198.40 → 2053777→ D30226-00 0197.08 → 2053776 D30794-00 ⑫ 0197.09 → 2053777→ B30756-00 ⑬ ⑯ R30794-00 ③	H02668-00 0209.L2 94 Ø → 2053776 H07635-00 0203.70 1,6 mm → 2053777→ H17635-10 94 Ø 1,7 mm → 2053777→ 		
1,9 XUD9 XUD9 (DJZ) XUD9 (D9A) XUD9 (162)	47-51 kW (64-69 PS) PARTNER D 205 D 306 D 306 SLD 306 STD 309 D 405 D	10/87-05/01	S30527-00 ⑫ ⑬ 0197.H5 D30527-00 ⑫ 0197.37 +0956.22 (8x) B30527-00 ⑬	H05876-00 0209.S5 1,36 mm 1 H05876-10 0209.S6 1,4 mm 2 H05876-20 0209.S7 1,44 mm 3 H15876-30 0209.S8 1,48 mm 4 H15876-40 0209.S9 84 Ø 1,53 mm 5 H07781-00 0209.K0 1,58 mm H17781-10 0209.K1 1,7 mm 	T08280-00 0204.65 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X06833-01 0249.25 NBR 	N90270-00 0956.01 (8x)	X06855-01 0348.52 3x 	X07092-01 2x 0349.08 X05087-01 1710.15 X07094-01 1710.07 X07489-01 1710.19 	X03048-01 0313.19 X07098-01 0304.12 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76005-01 N 16x21x4,5 NBR
X06833-01 0249.25 NBR 	N90270-00 0956.01 (8x)	X06855-01 0348.52 3x 	X07092-01 2x 0349.08 X03013-01 1721.01 X51229-01 ⑦ 0348.89 	X03048-01 0313.19 X07098-01 0304.12 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

⑯ con anillos para camisa de cilindro / mit Zylinderlaufbuchsenringe / with cylinder liner rings / avec joints de chemises de cylindre / con anelli tenuta canna cilindro / с прокладками гильзы цилиндров



PEUGEOT						
Ltr.						
1,9 XUD9 (D9A) XUD9 (162)	47-48 kW (64-65 PS) 305 D 309 D	10/82-07/89		<p>S30527-00 ⑫ ⑬ 0197.H5</p> <p></p> <p>D30527-00 ⑫ 0197.37 +0956.22 (8x)</p> <p></p> <p>B30527-00 ⑬</p>	<p>H05876-00 0209.S5 1,36 mm 1 </p> <p>H05876-10 0209.S6 1,4 mm 2 </p> <p>H05876-20 0209.S7 1,44 mm 3 </p> <p>H15876-30 0209.S8 1,48 mm 4 </p> <p>H15876-40 0209.S9 84 Ø 1,53 mm 5 </p> <p></p> <p>H07781-00 0209.K0 1,58 mm</p> <p>H17781-10 0209.K1 1,7 mm</p> <p></p>	<p>T08280-00 0204.65 (10x)</p> <p></p>
1,9 XUD9A (DJY) XUD9A (D9B) XUD9AU (D8C)	50-51 kW (68-70 PS) BOXER Bus D BOXER D EXPERT D J5 Bus D J5 D PARTNER D 306 D 306 SLD 405 D	03/88→		<p>S31582-00 ⑫ ⑬ 0197.H5</p> <p></p> <p>D31582-00 0197.37</p> <p></p> <p>B31582-00 ⑬</p>	<p>H02359-00 0209.K0 84 Ø 1,6 mm 2 </p> <p>H12359-10 84 Ø 1,7 mm 3 </p> <p></p> <p>H05876-00 0209.S5 1,36 mm 1 </p> <p>H05876-10 0209.S6 1,4 mm 2 </p> <p>H05876-20 0209.S7 1,44 mm 3 </p> <p>H15876-30 0209.S8 1,48 mm 4 </p> <p>H15876-40 0209.S9 84 Ø 1,53 mm 5 </p> <p></p>	<p>T08280-00 0204.65 (10x)</p> <p></p>

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<p>X07796-01 0249.46</p> <p></p>	<p>N90300-00 0249.48 (8x) P76531-00 0249.48</p> <p>8x</p>	<p>X55498-01 0348.99 ① →03/87</p> <p></p> <p>X55499-01 0348.98 ① →03/87</p> <p></p> <p>X51229-01 ⑦ 0348.89 ① 04/87→</p> <p></p>	<p>X07782-01 0349.47 ① →03/87</p> <p></p> <p>X03013-01 1721.01</p> <p></p>	<p>X07793-01 0304.34</p> <p></p>	<p>P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM</p>
<p>X07796-01 0249.46</p> <p></p>	<p>N90300-00 0249.48 (8x) P76531-00 0249.48</p> <p>8x</p>	<p>X03013-01 1721.01</p> <p></p> <p>X51239-01 ⑦ 0348.J0</p> <p></p>	<p>X07793-01 0304.34</p> <p></p>	<p>P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM</p>	



PEUGEOT						
Ltr.						
1,9 XUD9BSD (DHV) XUD9SD (DHW) XUD9TE XUD9TE (DHX) XUD9TE (DHY) XUD9TE (D8B) XUD9UTF (D8C)	55-68 kW (75-92 PS) BOXER BOXER Bus TD BOXER TD EXPERT TD 306 D 306 DT 306 SRDT 306 TD 405 TD 406 D 406 TD 806 TD	08/92→		S31582-00 ⑫ ⑬ 0197.H5 D31582-00 0197.37 B31582-00 ⑬	H02360-00 0209.Q5 1,65 mm H12360-10 0209.Q6 1,75 mm H05877-00 0209.Q8 1,36 mm 1 H05877-10 0209.Q9 1,4 mm 2 H05877-20 0209.R0 1,44 mm 3 H15877-30 0209.R1 1,48 mm 4 H15877-40 0209.R2 84 Ø 1,53 mm 5 	T02360-00 0204.73 (10x)
1,9 XU9JA (D6B) XU9JAZ (DKZ)	88-94 kW (120-128 PS) 205 205 GTI 309 GTI 405	10/86-05/97	→PR3975 →PR3975 →PR3975 →PR3975	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T11025-00 0204.89 (10x)
1,9 XU9JA (D6B) XU9JAZ (DKZ)	88-94 kW (120-128 PS) 205 205 GTI 309 GTI 405	10/86-05/97	→PR3976→ →PR3976→ →PR3976→ →PR3976→	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T01025-00 0204.57 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X07796-01 0249.46 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X01023-01 2x 91508659 X07803-01 X07804-01 	X03013-01 ⑦ 1721.01 X51239-01 ⑦ 0348.J0 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 2x 0236.14 35x50x8 A SL WD FPM
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X01023-01 2x 91508659 X07803-01 X07804-01 	X01022-01 4x 0349.70 X03013-01 ⑦ 1721.01 X07798-01 ⑦ 1710.39 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X01023-01 2x 91508659 X07803-01 X07804-01 	X01022-01 4x 0349.70 X03013-01 ⑦ 1721.01 X07798-01 ⑦ 1710.39 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



PEUGEOT							
Ltr.							
1,9 XU9J1 (DFZ) XU9M (DDZ) XU9S (D2B) XU9S (159) XU92C (D2A)	72-80 kW (98-109 PS)	205 205 CTI 205 GTI 305 309 405	→PR3975 →PR3975 →PR3975 →PR3975 →PR3975 →PR3975	09/84-05/97	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T11025-00 0204.89 (10x)
1,9 XU9J1 (DFZ) XU9M (DDZ) XU9S (D2B) XU9S (159) XU92C (D2A)	72-80 kW (98-109 PS)	205 205 CTI 205 GTI 305 309 405	→PR3976→ →PR3976→ →PR3976→ →PR3976→ →PR3976→ →PR3976→	09/84-05/97	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T01025-00 0204.57 (10x)
1,9 XU9J2 (D6A)	90 kW (122 PS)	405		01/89-12/92	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B31051-00 ⑬	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	
1,9 XU9J4 (D6C) XU9J4Z (DFW)	108-116 kW (147-158 PS)	309 GTI 16V 405		06/87-12/93	S31051-00 ⑫ ⑬ 95625018+0209.L3 D31051-00 ⑫ 0197.J2 +0209.L3 B31051-00 ⑬ R31124-00 ③	H07312-00 0209.L7 84,3 Ø	T01025-00 0204.57 (10x)
1,9 XU92C (D2C)	70 kW (95 PS)	405	→PR3975	07/87-12/92	S30559-00 ⑫ ⑬ 0197.89 D30559-00 ⑫ 0197.H6 +0209.E1 B30559-00 ⑬ R31124-00 ③	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm	T11025-00 0204.89 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X01021-01 0249.48	N90300-00 0249.48 (8x) P76531-00 0249.48	X01023-01 91508659 2x X07803-01 X07804-01	X01022-01 0349.70 4x X03013-01 1721.01 X07798-01 1710.39	X07793-01 0304.34	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01021-01 0249.48	N90300-00 0249.48 (8x) P76531-00 0249.48	X01023-01 91508659 2x X07803-01 X07804-01	X01022-01 0349.70 4x X03013-01 1721.01 X07798-01 1710.39	X07793-01 0304.34	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X01021-01 0249.48	N90300-00 0249.48 (8x) P76531-00 0249.48	X06152-01 0348.76	X01022-01 0349.70 4x X03013-01 1721.01	X07793-01 0304.34	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM
X07519-01 0249.74 NBR	N91190-00 0956.19 (8x) P76532-00 0956.19	X07309-01 0348.G4 2x	X05751-01 0349.E8	X04848-01 0127.05 NBR X07793-01 0304.34	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76128-11 N 2x 0236.24 32x45x8 A LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X01021-01 0249.48	N90300-00 0249.48 (8x) P76531-00 0249.48	X01023-01 91508659 2x X07803-01 X07804-01	X01022-01 0349.70 4x X03013-01 1721.01	X07793-01 0304.34	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM



PEUGEOT

PEUGEOT						
Ltr.						
1,9 XU92C (D2C)	70 kW (95 PS)	405	PR3976 → 07/87-12/92	S30559-00 (12) (13) 0197.89 D30559-00 (12) 0197.H6 +0209.E1 B30559-00 (13) R31124-00 (3)	H01025-00 0209.E1 84,3 Ø 1,2 mm H11025-10 0209.L3 84,3 Ø 1,5 mm 	T01025-00 0204.57 (10x)
2,0 DEW10J4 (RFR) EW10J4 (RFN)	99-100 kW (135-136 PS)	EXPERT 206 206 CC 206 SW 16V 307 307 CC 16V 307 SW 16V 307 16V 406 16V 407 407 SW 607 806 16V 807	01/99 →	S36504-00 (12) (13) 0197.Y1 +0209.Z3 +0249.A4 +0249.A5 D36504-00 (12) B36503-00 (13)	H80351-00 0209.Z3 85,5 Ø MLS 	T07586-00 0204.A7 (10x)
2,0 DW10ATED (RHS) DW10ATED (RHZ) DW10BTED (RHX) DW10TD (RHY)	66-80 kW (90-109 PS)	EXPERT HDI PARTNER HDI 206 HDI 206 SW HDI 306 HDI 90 307 HDI 307 HDI 110 FAP 307 HDI 90 307 SW HDI 110 FAP 307 SW HDI 90 406 HDI 110 406 HDI 110 FAP 406 HDI 110 FAP 406 HDI 90 607 HDI 806 HDI	06/98 →	S36550-00 (12) (13) 0197.X4 +0249.99 D36550-00 (12) 0197.X3 +0249.99 B32989-00 (13)	H05133-00 0209.X5 1,3 mm 1 MLS H05133-10 0209.X6 1,35 mm 2 MLS H05133-20 0209.X7 1,4 mm 3 MLS H15133-30 0209.X8 1,45 mm 4 MLS H15133-40 0209.X9 86 Ø 1,5 mm 5 MLS 	T05133-00 0204.A6 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x 	X01023-01 2x 91508659 X07803-01 X07804-01 	X01022-01 4x 0349.70 X03013-01 1721.01 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM
X53933-01 L 0249.A4 X53934-01 R 0249.A5 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x 	X86822-01 4x 0348.P1 	X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X53885-01 0249.99 	N92991-00 0956.38 (8x) → 08331 N92635-00 0956.48 (8x) → 08332 → P76662-00 0956.38 → 08331 P76698-00 0956.48 → 08332 → 8x 8x 	X58968-01 0348.N4 	X52326-01 0349.H4 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM



PEUGEOT												
Ltr.												
2,0 DW10ATED4 (RHM) DW10ATED4 (RHT) (107-109 PS) DW10ATED4 (RHW)	79-80 kW EXPERT EXPERT HDI 806 HDI 16V 807 HDI 807 HDI FAP	08/99→	S36517-00 0197.Y6 D36517-00 0197.Y7 +0249.A6 B36517-00	H01900-00 0209.AV 86 Ø 1,25 mm 2 MLS H11900-10 0209.AW 86 Ø 1,3 mm 3 MLS H21900-20 0209.AX 86 Ø 1,35 mm 4 MLS H31900-30 0209.AY 86 Ø 1,4 mm 5 MLS 	T17586-00 0204.96 (10x) 	X53953-01 0249.A6 	N92635-00 0956.48 (8x) 2x P76698-00 0956.48 16x	X81070-01 0349.J2 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM		
2,0 DW10BTD4 (RHR)	100-103 kW (136-140 PS) EXPERT HDI EXPERT TEPEE HDI 307 CC HDI 135 FAP 307 HDI 135 FAP 307 SW HDI 135 FAP 308 CC HDI 308 HDI 407 HDI 407 HDI 135 FAP 407 SW HDI 135 FAP 508 HDI 607 HDI 807 HDI	10/03→	S37090-00 0197.AE +0348.S3 D37090-00 0197.AC +0348.S3 	H01900-00 0209.AV 86 Ø 1,25 mm 2 MLS H11900-10 0209.AW 86 Ø 1,3 mm 3 MLS H21900-20 0209.AX 86 Ø 1,35 mm 4 MLS H31900-30 0209.AY 86 Ø 1,4 mm 5 MLS 	T05133-00 0204.A6 (10x) 	V37090-00 0348.S3 	N92635-00 0956.48 (8x) 2x P76698-00 0956.48 16x	X81070-01 0349.J2 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM		
2,0 DW10CTED4 (RHH) RHE (DW10CTED4) (150-200 PS)	110-147 kW EXPERT HDI RCZ HDI 3008 HDI 308 308 CC HDI 308 HDI 407 407 Coupe 407 HDI 5008 HDI 508 HDI 807 HDI	06/09→	S38513-00 0197.AW +0249.G8 +0348.V7 D38513-00 0197.AX +0348.V7 	H40649-00 0209.GL 1,25 mm 1 MLS H40649-10 0209.GN 1,3 mm 2 MLS H40649-20 0209.GP 1,35 mm 3 MLS H40649-30 0209.GQ 1,4 mm 2 MLS 	T05133-00 0204.A6 (10x) 	X59687-01 0348.V7 	N93131-00 0956.58 (16x) P76842-00 0956.58 16x	X59682-01 0349.N2 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM		



PEUGEOT

PEUGEOT						
Ltr.						
2,0 DW10UTD (RHV)	62 kW (84 PS)	BOXER Bus HDI BOXER HDI	08/01→	S36550-00 (12) (13) 0197.X4 +0249.99 D36550-00 (12) 0197.X3 +0249.99 B32989-00 (13)	H05133-00 0209.X5 1,3 mm MLS H05133-10 0209.X6 1,35 mm MLS H05133-20 0209.X7 1,4 mm MLS H15133-30 0209.X8 1,45 mm MLS H15133-40 0209.X9 86 Ø 1,5 mm MLS 	T05133-00 0204.A6 (10x)
2,0 DW10UTED4 (RHK)	88 kW (120 PS)	EXPERT HDI EXPERT TEPEE HDI 807 HDI	02/06→		H01900-00 0209.AV 86 Ø 1,25 mm MLS H11900-10 0209.AW 86 Ø 1,3 mm MLS H21900-20 0209.AX 86 Ø 1,35 mm MLS H31900-30 0209.AY 86 Ø 1,4 mm MLS 	T05133-00 0204.A6 (10x)
2,0 EW10 (RFH) EW10A (RFJ)	103 kW (140 PS)	EXPERT 307 CC 16V 307 SW 16V 307 16V 308 407 407 SW 16V 407 16V 807 16V	03/05→	S80781-00 (12) (13) (19) D80781-00 (12) (19) B38333-00 (13)	H80781-00 0209.FS MLS 	T80768-00 0204.A3 (10x)

(19) con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров

X53885-01 0249.99 	N92635-00 0956.48 (8x) P76698-00 0956.48	8x	X58968-01 0348.N4 	X52326-01 0349.H4 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM
V37090-00 0348.S3 	N92635-00 0956.48 (8x) P76698-00 0956.48	2x 16x		X82339-01 0349.L9 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM
	N92657-00 0956.45 (16x) P76657-00 0956.45	16x	X89881-01 0348.S2 	X82335-01 0349.L4 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM P77626-01 N 0236.74 39x50x7 A SL RD



PEUGEOT						
Ltr.						
2,0 EW10D (RLZ)	103 kW (140 PS) 406 16V HPI	05/01-10/04	S36504-01 (12) (13) 0197.Y1 +0209.Z3 +0249.A8 D36504-01 (12) B36503-00 (13)	H80351-00 0209.Z3 85,5 Ø MLS 	T07586-00 0204.A7 (10x) 	
2,0 EW10J4S (RFK)	130 kW (177 PS) 206 307 CC 16V 307 16V	07/03→	S36504-03 (12) (13) (19) D36504-03 (12) (19) B36503-03 (13)	H80351-00 0209.Z3 85,5 Ø MLS 	T80768-00 0204.A3 (10x) 	
2,0 XN1 XN1 (106) XN1P	57-71 kW (78-97 PS) J9 J9 Bus 504 505	03/71-06/87	S30777-00 (12) (13) 9400197139 D30777-00 (12) B30777-00 R30547-00 (3)	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T02666-00 0204.21 (10x) i → 06/85 T02760-00 0204.51 (10x) i 07/85→ 	
2,0 XN1	69-79 kW (94-107 PS) 504 505	09/79-11/82	S30777-00 (12) (13) 9400197139 D30777-00 (12) B30777-00 R30547-00 (3)	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T02666-00 0204.21 (10x) 	
2,0 XN1A (106E) XN1T	55-72 kW (75-98 PS) J5 505	09/85-09/95	S30777-00 (12) (13) 9400197139 D30777-00 (12) B30777-00 R30547-00 (3)	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm 	T02760-00 0204.51 (10x) i → 04/89 T01025-00 0204.57 (10x) i 05/89→ 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X53954-01 0249.A8 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x		X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM P77437-01 N 0236.65 39x50x7 A SL RD FPM
X53933-01 L 0249.A4 X53934-01 R 0249.A5 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X89343-01 0348.R8 	X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM 2x
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 0348.33 	X04833-01 0349.03 	X04848-01 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 0348.33 	X04833-01 0349.03 	X04848-01 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X07480-01 0348.33 	X04833-01 0349.03 	X04848-01 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR

⑱ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



PEUGEOT						
Ltr.						
2,0 XN1A (106E)	72 kW (98 PS) 505	09/85-11/87	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 R30547-00 ③	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm	T02760-00 0204.51 (10x) 	
2,0 XN1P XN1T (170) XN1T (170B) XN1TA (170C)	55-62 kW (75-85 PS) J5 J5 Bus	09/81→	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 R30547-00 ③	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm	T02666-00 0204.21 (10x) ① →06/85 T02760-00 0204.51 (10x) ① 07/85-04/89 T01025-00 0204.57 (10x) ① 05/89→ 	
2,0 XN1TA	62 kW (84 PS) J5	09/90-01/94	S30777-00 ⑫ ⑬ 9400197139 D30777-00 ⑫ B30777-00 R30547-00 ③	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm	T01025-00 0204.57 (10x) 	
2,0 XN2 (107)	78 kW (106 PS) 504 504 TI	01/71-08/84	A30557-00 ⑭ 0198.08 D30557-00 0198.09 R30547-00 ③	H02760-00 0209.46 90,2 Ø 1,2 mm H12760-10 0209.49 90,2 Ø 1,6 mm		
2,0 XU10J2 (RFU)	89 kW (121 PS) 806	06/94-08/02	D32987-00 ⑫ 0197.T4 +0209.J8 B31581-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm	T08280-00 0204.65 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	X07480-01 0348.33 	X04833-01 0349.03 	X04848-01 2x 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	X07480-01 0348.33 	X04833-01 0349.03 	X04848-01 2x 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	X07480-01 0348.33 	X04833-01 0349.03 	X04848-01 2x 0127.05 NBR X54253-01 Kork 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76005-01 N 16x21x4,5 NBR
X04835-01 0249.14 NBR 	N90300-00 0249.48 (8x) P76531-00 0249.48	X05047-01 0348.18 	X04833-01 0349.03 X04201-01 1710.09 	X05060-01 0304.44 Kork 	
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48	X58564-01 2x 0348.N0 	X01022-01 4x 0349.70 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



PEUGEOT							
Ltr.							
2,0 XU10J2 (RFW) XU10J2U (RFL)	80-81 kW (109-110 PS)	BOXER BOXER Bus	03/94→	S31581-00 ⑫ ⑬ 9568993 D31581-00 ⑫ 0197.G6 +0209.J8 B31581-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	
2,0 XU10J2 (RFX)	89 kW (121 PS)	306 306 XSi 405	08/92-04/02	D31581-00 ⑫ 0197.G6 +0209.J8 B31582-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	
2,0 XU10J2TE (RGX) XU10J2TE (RGY)	104-108 kW (141-147 PS)	406 406 Turbo 605 Turbo 806 Turbo	07/91-10/04	D36906-00 ⑫ 0197.H3 B36902-00 ⑬	H50161-00 0209.J8 87 Ø 1,2 mm 	T08280-00 0204.65 (10x) 	
2,0 XU10J2Z (RFZ) XU102C (R5A)	84-89 kW (114-121 PS)	605	06/89-09/99	S31115-00 ⑫ ⑬ 95650948 D31115-00 ⑫ 0197.C9 +0209.N1 B31115-00 ⑬	H07967-00 0209.N1 87,3 Ø 	T08280-00 0204.65 (10x) 	
2,0 XU10J4 (RFT) XU10J4TE/Z (RGZ) XU10J4Z (RFY)	110-144 kW (150-196 PS)	306 306 S16 405 405 Turbo 405 16V	08/92-05/01	S31583-00 ⑫ ⑬ 95668993 D31583-00 ⑫ 0197.G7 +0209.N0 B31583-00 ⑬	H50162-00 0209.N0 87 Ø 	T50162-00 0204.72 (10x) 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56171-01 0348.F6 2x X56170-01 ⑩ 2x 0348.E6 	X01022-01 0349.70 4x 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM		
X53101-01 0249.71 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X58564-01 0348.N0 2x X56170-01 ⑩ 2x 0348.E6 	X01022-01 0349.70 4x 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM		
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56528-01 0348.E0 → 07664 8x X58564-01 0348.N0 → 07665 2x 	X06151-01 0349.70 4x 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76128-11 N 0236.24 32x45x8 A LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM		
X01021-01 0249.48 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X56528-01 0348.E0 8x 	X06151-01 0349.70 4x 	X07793-01 0304.34 ⑩ → 09/93 70-31414-10 ⑩ 10/93→ 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM		
X07519-01 0249.74 NBR 	N91190-00 0956.19 (8x) P76532-00 0956.19 16x	X56177-01 0348.C8 2x 	X51249-01 0349.98 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM		2x



PEUGEOT						
Ltr.						
2,0 XU10J4R (RFV)	07/94-12/04	97 kW (132 PS)	306 306 16V 406 16V 605 16V 806 16V	S32981-00 ⑫ ⑬ 0197.W2 → 07965 S36401-00 ⑫ ⑬ 0197.X8 +0209.N6 +0249.A2 +0249.A3 → 07966→ D32981-00 ⑫ → 07965 D36401-00 ⑫ 0197.H3 → 07966→ B32982-00 ⑬ → 07965 B32981-00 ⑬ → 07966→	H80031-00 0209.N6 87 Ø 1,2 mm H80031-10 0209.T9 87 Ø 1,45 mm	T50162-00 0204.72 (10x)
2,0 XU10J4RS (RFS)	03/96-05/01	120 kW (163 PS)	306 S16	S36087-00 ⑫ ⑬ 0197.W2 +0209.Z2 D36087-00 ⑫ B32981-00 ⑬	H80033-00 0209.Z2 87 Ø MLS	T50162-00 0204.72 (10x)
2,0 ZEJ (829)	08/79-09/89	81 kW (110 PS)	505	S30759-00 ⑫ ⑬ D30759-00 ⑫ 0199.01 B30759-00 7701467612 R30961-00 ③	H04580-00 89,3 Ø	T50132-00
2,1 XDPX90	03/80-06/87	41 kW (56 PS)	J9 D	S30226-00 ⑬ 0198.14 → 4586483 S30794-00 ⑫ ⑬ 0198.40 → 4586484→ D30226-00 0197.08 → 4586483 D30794-00 ⑫ 0197.09 → 4586484→ B30756-00 ⑬ ⑯ → 4572282→ R30794-00 ③	H02668-00 0209.L2 94 Ø → 4586483 H07635-00 0203.70 1,6 mm → 4586484→ H17635-10 94 Ø 1,7 mm → 4586484→	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X53731-01 L 0249.A2	N93063-00 0956.34 (16x) → 07359 N93062-00 0956.42 (16x) → 07360→ → 07965 N92657-00 0956.45 (16x) → 07966→ 0956.34 → 07359 P76750-00 0956.42 → 07360→ → 07965 P76657-00 0956.45 → 07966→	X58967-01 0348.C8	X52325-01 0349.F4 → 07664 X52324-01 0349.H0 → 07765→	70-31414-10	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X53732-01 R 0249.A3	N92990-00 0956.38 (16x) P76662-00 0956.38	X58967-01 0348.C8	X52325-01 0349.F4	70-31414-10	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 2x 0236.21 36x50x7 A RD FPM
X04583-01 0249.43	N90300-00 0249.48 (8x) P76531-00 0249.48	X04587-01 0348.46	X04581-01 0349.32 X04582-01 1710.24 X07747-01	X04584-01 0304.20	P76186-01 K ← 0127.11 50x68x10 A RD FPM P76363-01 K → 0127.12 90x110x13 LD P76094-01 N 0236.09 35x47x7 A RD MVQ
X06833-01 0249.25 NBR	N90270-00 0956.01 (8x)	X06855-01 0348.52	X07092-01 0349.08 X05087-01 1710.15 X07094-01 1710.07 X07489-01 1710.19	X03048-01 0313.19 X07098-01 0304.12	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76005-01 N 16x21x4,5 NBR

⑯ con anillos para camisa de cilindro / mit Zylinderlaufbuchsenringe / with cylinder liner rings / avec joints de chemises de cylindre / con anelli tenuta canna cilindro / с прокладками гильзы цилиндров



PEUGEOT						
Ltr.						
2,1 XDP90	42 kW (57 PS) J7 Bus D J7 D	08/68-07/77	S30226-00 ⑬ 0198.14 → 4586483 S30794-00 ⑫ ⑬ 0198.40 → 4586484→ D30226-00 0197.08 → 4586483 D30794-00 ⑫ 0197.09 → 4586484→ B30756-00 ⑬ ⑯ R30794-00 ③	H02668-00 0209.L2 94 Ø → 4586483 H07635-00 0203.70 1,6 mm → 4586484→ H17635-10 94 Ø 1,7 mm → 4586484→ 		
2,1 XUD11A (P9A)	60 kW (82 PS) 605 D	06/89-07/95	S31584-00 ⑫ ⑬ D31584-00 ⑫ 0197.H1 B31584-00 ⑬	H02354-00 0209.H1 1,58 mm 2 M H12354-10 0209.A0 87 Ø 1,7 mm 3 M 	T02354-00 0204.67 (10x) 	
2,1 XUD11ATE (PHZ) XUD11BTE (P8C)	80 kW (109 PS) 406 TD 12V 605 TD 605 TD 12V 806 TD 12V	06/89-10/04	S31584-00 ⑫ ⑬ D31584-00 ⑫ 0197.H1 B31584-00 ⑬	H07761-00 0209.T6 1,35 mm MLS H07761-10 0209.R4 1,52 mm MLS H07761-20 0209.R5 1,57 mm MLS H17761-30 0209.R6 1,62 mm MLS H17761-40 0209.R7 1,67 mm MLS H17761-50 0209.R8 1,73 mm MLS H27761-60 0209.T4 86 Ø 1,77 mm MLS 	T02356-00 0204.68 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра










































X06833-01 0249.25 NBR 	N90270-00 0956.01 (8x) 	X06855-01 0348.52 	3x X07092-01 0349.08 X05087-01 1710.15 X07094-01 1710.07 X07489-01 1710.19 	2x X03048-01 0313.19 X07098-01 0304.12 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76005-01 N 16x21x4,5 NBR
X53584-01 0249.70 	N91210-00 0956.22 (12x) P76531-00 0249.48 12x	X56183-01 0348.96 	X51245-01 0349.76 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM 2x
X53584-01 0249.70 	N91210-00 0956.22 (12x) P76531-00 0249.48 12x	X56183-01 0348.96 	X51245-01 0349.76 	X07793-01 0304.34 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76099-11 N 0236.14 35x50x8 A SL WD FPM 2x

⑯ con anillos para camisa de cilindro / mit Zylinderlaufbuchsenringe / with cylinder liner rings / avec joints de chemises de cylindre / con anelli tenuta canna cilindro / с прокладками гильзы цилиндров



PEUGEOT

PEUGEOT				  			     					
Ltr. 				 D38112-00 ⑫  B38113-00 ⑬	H01901-00 0209.FT 1,25 mm MLS H11901-10 0209.FV 1,3 mm MLS H21901-20 0209.FW 1,35 mm MLS H31901-30 0209.FX 85,9 Ø 1,37 mm MLS 	T05133-00 0204.A6 (10x) 	V38102-00 0249.E4 +0249.E5 (2x) +0249.E3  X83357-01 2x 0249.E5  X83358-01 0249.E4 	N93131-00 0956.58 (16x) P76842-00 0956.58 16x	M38101-00 0348.T2 	X81999-01 0349.P1 	70-31414-10 	P77464-01 K ← 0127.47 42x62x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM
2,2 DW12TED4 (4HX)	94-98 kW (128-133 PS)	406 HDI FAP 607 HDI 807 HDI FAP	02/00→	S36517-00 ⑫ ⑬ 0197.Y6   D36517-00 ⑫ 0197.Y7 +0249.A6  B36517-00 ⑬	H01900-00 0209.AV 86 Ø 1,25 mm 2 M MLS H11900-10 0209.AW 86 Ø 1,3 mm 3 M MLS H21900-20 0209.AX 86 Ø 1,35 mm 4 M MLS H31900-30 0209.AY 86 Ø 1,4 mm 5 M MLS 	T17586-00 0204.96 (10x) 	X53953-01 0249.A6 	N92635-00 2x 0956.48 (8x) P76698-00 16x 0956.48		X81070-01 0349.J2 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM
2,2 DW12UTED (4HY)	74 kW (101 PS)	BOXER Bus HDI BOXER HDI	04/02→	S36550-00 ⑫ ⑬ 0197.X4 +0249.99   D36550-00 ⑫ 0197.X3 +0249.99 	H06254-00 0209.AQ 1,25 mm 1 M MLS H06254-10 0209.AR 1,3 mm 2 M MLS H06254-20 0209.AS 1,35 mm 3 M MLS H16254-30 0209.AT 86 Ø 1,4 mm 4 M MLS 	T17586-00 0204.96 (10x) 	X53885-01 0249.99 	N92635-00 8x 0956.48 (8x) P76698-00 0956.48	X58968-01 0348.N4 	X81070-01 0349.J2 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P77142-01 N 0807.28 27x47x7 A SL RD FPM



PEUGEOT						
Ltr.						
2.2 EW12J4 (3FY) EW12J4 (3FZ)	02/00→	116-120 kW (158-163 PS)	406 407 407 SW 407 SW 16V 607 16V 807	S37005-00 ⑫ ⑬ 0197.Y8 +0209.0H +0249.A4 +0249.A5 D37005-00 ⑫	H80475-00 0209.0H 87 Ø MLS 	T80475-00 0204.95(x10)
2.2 ZDJ (851) ZDJL (851B) ZDJL (851X)	05/81-12/93	84-90 kW (114-122 PS)	505 505 GTI	S30759-00 ⑫ ⑬ D30759-00 ⑫ 0199.01 B30759-00 7701467612 R30961-00 ③	H04580-00 89,3 Ø 	T50132-00
2.2 4HN (DW12MTED4) [NEW]	02/07→	115 kW (156 PS)	4007 HDI	D38112-00 ⑫ B38113-00 ⑬	H01901-00 0209.FT 1,25 mm MLS H11901-10 0209.FV 1,3 mm MLS H21901-20 0209.FW 1,35 mm MLS H31901-30 0209.FX 85,9 Ø 1,37 mm MLS 	T05133-00 0204.A6 (10x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



X53933-01 L 0249.A4 	N92657-00 0956.45 (16x) P76657-00 0956.45 16x	X81726-01 0348.P6 	X81109-01 0349.H8 	70-31414-10 	P77304-01 K ← 0326.27 40x55x6,5 A SL RD FPM P76386-01 K → 0127.28 90x110x7 A SL LD FPM P76133-01 N 0236.21 36x50x7 A RD FPM P77437-01 N 0236.65 39x50x7 A SL RD FPM
X53934-01 R 0249.A5 	N90300-00 0249.48 (8x) P76531-00 0249.48 8x	X04587-01 4x 0348.46 	X04581-01 0349.32 X04582-01 1710.24 X07747-01 	X04584-01 0304.20 	P76186-01 K ← 0127.11 50x68x10 A RD FPM P76363-01 K → 0127.12 90x110x13 LD P76094-01 N 0236.09 35x47x7 A RD MVQ
V38102-00 0249.E4 +0249.E5 (2x) +0249.E3 	N93131-00 0956.58 (16x)	M38101-00 0348.T2 	X81999-01 0349.P1 	70-31414-10 	P77464-01 K ← 0127.47 42x68x7 A SL RD PTFE P77465-01 K → 0127.45 90x110x7 A SL LD PTFE P77142-01 N 0807.28 27x47x7 A SL RD FPM
X83357-01 2x 0249.E5 					
X83358-01 0249.E4 					



PEUGEOT						
Ltr.						
2,2 4HU (P22DTE) 4HV (P22DTE)	74-88 kW (101-120 PS)	BOXER HDI	04/06→	D38555-00 B36738-00 ⑬ ⑳	H40597-00 0209.EH 87,5 Ø 1,1 mm MLS 1	T59572-00 0204.C0 (10x) +0204.A9 (8x)
					H40597-10 0209.ES 87,5 Ø 1,15 mm MLS 2	
					H40597-20 0209.ET 87,5 Ø 1,2 mm MLS 3	
2,3 XD2 (134)	51 kW (69 PS)	504 D	07/75-12/89	S30756-00 ⑫ ⑬ 0198.94 D30756-00 ⑫ 0198.54 	H07986-00 1,53 mm 2 H17986-10 1,63 mm 3 H27986-20 0209.C6 96 Ø 1,73 mm 4 	T16656-00 0204.55 (15x) +0204.56 (7x) cyl.head height 83mm T17986-00 0204.54 (8x) +0204.55 (7x) +0204.56 (7x) cyl.head height 73mm
2,3 XD2PX94 XD2P94	49 kW (67 PS)	J7 Bus D J7 D J9 Bus D J9 D	07/77-07/82	A30243-00 ⑫ ⑭ 0197.25 S30243-00 ⑬ D30243-00 ⑫ 0197.08 	H06656-00 0209.C2 1,58 mm 2 H16656-10 0209.C4 96 Ø 1,7 mm 3 	
2,3 XD2S (147)	59 kW (80 PS)	505 D 505 TD 604 TD	09/79-06/86	S30979-00 ⑫ ⑬ 0199.06 D30979-00 ⑫ 0199.05 B30979-00 ⑬	H07986-00 1,53 mm 2 H17986-10 1,63 mm 3 H27986-20 0209.C6 96 Ø 1,73 mm 4 	T16656-00 0204.55 (15x) +0204.56 (7x) T17986-00 0204.54 (8x) +0204.55 (7x) +0204.56 (7x)

⑬ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



X83135-01 0249.E9 NBR 	N92986-00 0956.59 (16x) P76777-00 0956.59 16x	X88198-01 0348.T1 8x 	X81992-01 0349.L5 X82543-01 	E36738-00 0304.58 70-31414-10 	P77367-01 K ← 0514.C6 PTFE P77338-01 K → 0514.C4 PTFE
X06833-01 0249.25 NBR 	N90270-00 0956.01 (8x) P76539-00 0956.19 8x	X06855-01 0348.52 3x 	X07092-01 2x 0349.08 X07489-01 1710.19 	X03048-01 0313.19 X07098-01 0304.12 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76005-01 N 16x21x4,5 NBR
X06833-01 0249.25 NBR 		X08241-01 2x 0349.44 	X07092-01 2x 0349.08 X08240-01 1710.34 X08245-01 1710.15 	X08253-01 	P76150-01 K ← 0514.11 42x60x8 A RD FPM X08246-01 K → 2x 1227968610
X06833-01 0249.25 NBR 	N90270-00 0956.01 (8x) P76539-00 0956.19 8x	X06855-01 0348.52 3x 	X06857-01 2x 0349.34 	E30794-00 0313.07+0127.05(x2) X03048-01 0313.19 X07098-01 0304.12 	P76150-01 K ← 0514.11 42x60x8 A RD FPM P76005-01 N 16x21x4,5 NBR

⑳ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



PEUGEOT							
Ltr.							
2,5 CRD93	54 kW (73 PS)	J5 J5 Bus D J5 D	09/81-03/94	S30253-00 ⑫ ⑬ 75513625 D30253-00 ⑫ B30253-00 ⑬	H00666-00 0209.75 96,3 Ø	T06345-00 0204.41 (8x) +0204.42 (9x)	
2,5 CRD93L CRD93LS	70 kW (95 PS)	J5 Bus TD J5 DT J5 TD	09/81-03/94	S31052-00 ⑫ ⑬ 95593755 D31052-00 ⑫ B31052-00 ⑬	H06345-00 0209.L6 95,6 Ø	T06345-00 0204.41 (8x) +0204.42 (9x)	
2,5 DJ5 (T9A) DJ5T (T&A) DK5ATE (THY)	63-95 kW (86-129 PS)	BOXER Bus D BOXER Bus TD BOXER D BOXER TD 605 TD	03/94-04/02	S32148-00 ⑫ ⑬ 0197.T7 +0209.R3 D32148-00 ⑫ 0197.T6 +0209.R3 B32148-00 ⑬	H50390-00 0209.R3 93 Ø	T50390-00 0204.74 (14x) +0204.75 (8x)	
2,5 DJ5TED (THX)	79 kW (107 PS)	BOXER Bus TDI BOXER TDI	01/97-04/02	S32990-00 ⑫ ⑬ 0197.W4 +0209.T5 D32990-00 ⑫ 0197.W3 +0209.T5 B32148-00 ⑬	H80034-00 0209.T5 93 Ø	T80034-00 0204.87 (14x) +0204.88 (8x)	

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

⑬ para vehículos con aire acondicionado / für Fahrzeuge mit Klimaanlage / for vehicles with air conditioning / pour véhicules avec système de climatisation / per veicoli con aria condizionata / оснащение / оборудование для автомобилей с кондиционером



X00742-01 5 450 155 NBR 	N91300-00 5469955 P76531-00 4x 0249.48 P76543-00 4x 0956.05	X00837-01 4x 	X00881-01 4x 0349.F0 X07493-01 4x 5 434 181 	X07498-01 7543388080B 	P76178-11 K ← 48x65x10 A NBR P76368-11 K → 26126699J 95x112x12,5 LD FPM P76051-01 N 95550398 29x46x10 LD MVQ
X01015-01 0249.45 	N91300-00 5469955 P76531-00 4x 0249.48 P76543-00 4x 0956.05	X00837-01 4x 	X00881-01 4x 0349.F0 	X07498-01 7543388080B 	P76314-01 K ← 0514.32 75x90x11,5 A SL RD FPM P76368-11 K → 26126699J 95x112x12,5 LD FPM P76183-01 N 48x72x10 RD FPM
X53585-01 0249.79 	N92450-00 0956.19 (12x) P76532-00 12x 0956.19	X56189-01 0348.K1 X57008-01 ⑩ 0348.F9 	X51508-01 0349.E7 	70-31414-10 	P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P76098-01 N ← 0807.14 35x50x7 A SL RD FPM P76034-01 N → ⑳ 0807.15 40x62x7 A SL LD ACM FPM P76047-01 N → ㉑ 0807.21 47,5x62x7 A SL LD ACM FPM
X53585-01 0249.79 	N91190-00 0956.19 (8x) P76532-00 8x 0956.19	X58971-01 2x 0348.K4 	X52328-01 0349.G4 	70-31414-10 	P76053-01 K ← 0326.25 64x88x6 A SL RD ACM FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P76098-01 N V 0807.14 35x50x7 A SL RD FPM P77143-01 N H 0807.26 32x52x7 A SL LD FPM

⑳ para vehículos sin aire acondicionado / für Fahrzeuge ohne Klimaanlage / for vehicles without air conditioning / pour véhicules sans système de climatisation / per veicoli senza aria condizionata / оснащение / оборудование для автомобилей без кондиционера

H posterior / hinten / rear / arrière / posteriore / сзади

V delante / vorne / front / avant / anteriore / спереди



PEUGEOT						
Ltr.						
2,5 XD3 (155) XD3P	51-55 kW (69-75 PS) J9 Bus D J9 D 505 D	06/81-12/93	S30241-00 0197.P0 D30241-00 0197.N9 	H07986-00 1,53 mm 2 H17986-10 1,63 mm 3 H27986-20 0209.C6 96 Ø 1,73 mm 4 	T16656-00 0204.55 (15x) +0204.56 (7x) cyl.head height 83mm T17986-00 0204.54 (8x) +0204.55 (7x) +0204.56 (7x) cyl.head height 73mm 	
2,5 XD3T (152A) XD3TE XD3TE (152B)	54-77 kW (73-105 PS) 505 TD 604 TD	08/83→	S30244-00 0197.28 D30244-00 0199.05 	H07986-00 1,53 mm 2 H17986-10 1,63 mm 3 H27986-20 0209.C6 96 Ø 1,73 mm 4 	T16656-00 0204.55 (15x) +0204.56 (7x) cyl.head height 83mm T17986-00 0204.54 (8x) +0204.55 (7x) +0204.56 (7x) cyl.head height 73mm 	
2,7 DT17BTED4 (UHZ) DT17TED4 DT17TED4 (UHZ)	150 kW (204 PS) 407 HDI 607 HDI 24V	12/04→	D38339-00 B38339-00	H01902-00 2x 0209.CW 82,5 Ø 1,17 mm 2 MLS H01902-10 2x 0209.CX 82,5 Ø 1,22 mm 3 MLS H01902-20 2x 0209.CY 82,5 Ø 1,27 mm 4 MLS H11902-30 2x 0209.CZ 82,5 Ø 1,32 mm 5 MLS 	T01902-00 2x 	



X06833-01 0249.25 NBR 	N92637-00 0956.01 (8x)	X08241-01 2x 0349.44 	X08240-01 1710.34 X08245-01 1710.15 	X08253-01 	P76150-01 K ← 0514.11 42x60x8 A RD FPM X08246-01 K → 2x 1227968610
X06833-01 0249.25 NBR 	N92637-00 0956.01 (8x)	X06855-01 3x 0348.52 	X08252-01 2x X06577-01 1710.27 	E30244-00 X08253-01 	P76163-01 K ← 45x60x8/9 A SL RD MVQ X08246-01 K → 2x 1227968610
X83359-01 2x 0249.E1 	N93132-00 0956.53 (24x) P76843-00 0956.53 24x	X82334-01 2x 0349.L0 	X54926-01 0164.75 X59640-01 0304.57 	P77681-01 K ← 0326.29 35x50x7 A SL RD PTFE ACM P77677-01 K → 0514.C0 P77624-01 N 2x 0807.36 26x45x8 A SL WD FPM	



PEUGEOT

PEUGEOT						
Ltr.						
2,7 ZM (112) ZMJ (140)	100-106 kW (136-144 PS)	504 604	08/77-08/84	S30758-00 ⑫ ⑬ 0197.75 D34758-00 ⑫ D35758-00 ⑫ L 0198.67 B30758-00 ⑬ R30758-00 ③	H07627-00 R 0203.67 90,2 Ø H07628-00 L 0203.66 90,2 Ø 	T08263-00 0204.53 (16x)
2,8 ZN3J (154X)	105 kW (143 PS)	505 GTI V6	06/86-12/93	S31260-00 ⑫ ⑬ 0198.99 D31260-00 ⑫ B31258-00 ⑬	H08978-00 R 0209.41 93 Ø H08979-00 L 0209.39 93 Ø 	T08263-00 0204.53 (16x)
2,8 8140.43S (F28DTCR)	93-94 kW (126-128 PS)	BOXER Bus HDI BOXER HDI	10/00→	S38249-02 ⑫ ⑭ 0197.Y2 D38249-02 ⑫ 0197.Y3 	H08023-01 0209.0C 1,3 mm H18023-11 0209.0E 1,4 mm H28023-21 0209.0F 1,5 mm 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра
 ⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



X07629-01 ⑳ R 0249.31 X07630-01 ⑳ L 0249.37 X07631-01 ⑳ R 0249.30 X07632-01 ⑳ L 0249.29 	N91210-00 0956.22 (12x) P76531-00 12x 0249.48 	X07636-01 6x 0348.43 X07777-01 2x 0348.25 	X07634-01 2x 0349.88 	X07633-01 0123.19 	P76152-01 K ← 0514.21 42x62x10 A SL RD FPM P76345-01 K → 80x100x13 A SL LD MVQ P76128-11 N 0236.24 32x45x8 A LD FPM
X07629-01 R 0249.31 X07630-01 L 0249.37 	N91210-00 0956.22 (12x) P76531-00 12x 0249.48 	X07636-01 4x 	X07634-01 2x 0349.88 X06790-01 2x 	X07633-01 0123.19 	P76152-01 K ← 0514.21 42x62x10 A SL RD FPM P76345-01 K → 80x100x13 A SL LD MVQ
X53812-01 ✗ 0249.C3 X59298-01 0249.A0 	N93138-00 P76804-00 8x 	X07692-01 4x 	X51326-11 4x 0349.H5 	X54494-01 ✗ NBR X59306-01 Gummi 	

⑳ material culata chapa de acero / Zylinderkopfaubenmaterial Stahlblech / valve cover material sheet steel / couvre-culasse tôle d'acier / materiale coperchio valvole in Lamiera d'acciaio / материал кожуха головки блока цилиндров - стальное литье
 ㉑ material culata aluminio fundido / Zylinderkopfaubenmaterial Aluguß / valve cover material cast aluminium / couvre-culasse fonte d'aluminium / materiale coperchio valvole in alluminio fuso / материал кожуха головки блока цилиндров - алюминиевое литье



PEUGEOT						
Ltr.						
3,0 DT20C	177 kW (241 PS) 407 HDI	06/09→		H40636-00 2x 0209.GX 85 Ø 1,17 mm 2 MLS H40636-10 2x 0209.GY 85 Ø 1,22 mm 3 MLS H40636-20 2x 0209.GZ 85 Ø 1,27 mm 4 MLS H40636-30 2x 0209.HA 85 Ø 1,32 mm 5 MLS 	T01902-00 2x 	
3,0 ES9A (XFV)	155 kW (211 PS) 407 SW, 407 V6, 607 V6 24V	03/04→		H08012-00 V 0209.OX 89 Ø 0,74 mm MLS H08013-00 H 0209.OY 89 Ø 0,74 mm MLS 		
3,0 ES9J4 (XFZ)	140 kW (190 PS) 406 V6 24V, 605 V6	10/96-12/04	D37119-00 ¹² R 0008570→ D37120-00 ¹² L 0008570→ B37213-00 ¹³	H80044-00 L 0209.ON MLS 0008570→ H80045-00 R 0209.OP 89 Ø MLS 0008570→ 		

¹⁰ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X83359-01 2x 0249.E1 	N93132-00 0956.53 (24x) P76843-00 24x 0956.53		X82334-01 2x 0349.L0 	X54926-01 0164.75 X59640-01 0304.57 	P77681-01 K ← 0326.29 35x50x7 A SL RD PTFE ACM P77677-01 K → 0514.C0 P77624-01 N 0807.36 26x45x8 A SL WD FPM
70-31414-10 	N92830-00 P76662-00 24x 0956.38	X89882-01 0348.00 X89883-01 2x 0348.P9 	X52329-01 2x 0349.G0 	70-31414-10 	P77682-01 K ← 0514.A9 42x56x6,5 A SL RD P77683-01 K → 0119.18 98x120x9 A SL LD P77623-01 N 4x 0807.34 38x50x7 A SL RD
70-31414-10 	N92830-00 P76662-00 24x 0956.38	X58973-01 2x 0348.L5 X58972-01 ¹⁰ 0348.K7 	X52329-01 2x 0349.G0 	70-31414-10 	P76144-11 K ← 0514.82 42x56x7 A SL RD FPM P76065-01 K → 0119.14 98x120x7 A SL LD FPM P77141-01 N 4x 0807.24 38x50x6 A SL RD FPM

H posterior / hinten / rear / arrière / posteriore / сзади
 V delante / vorne / front / avant / anteriore / спереди



PEUGEOT						
Ltr.						
3,0 ES9J4S (XFX)	150-152 kW (204-207 PS) 406 V6 24V 607 V6 24V 807 V6 24V	02/00→	D37116-00 ⑫ V D37117-00 ⑫ H D37118-00 ⑫ B37213-00 ⑬ → 10086 B37117-00 ⑬ ← 10087→	H08012-00 V 0209.OX 89 Ø 0,74 mm MLS H18012-10 V 0209.OZ 89 Ø 0,95 mm MLS H08013-00 H 0209.OY 89 Ø 0,74 mm MLS H18013-10 H 0209.1A 89 Ø 0,95 mm MLS 		
3,0 F1CE0481D (FG30DT)	116 kW (156 PS) BOXER HDI BOXER HDI 160	04/06→	S37073-00 ⑫ 0197.AR S37073-03 ⑫ ⑬ D37073-00 ⑫ 0197.AQ D37073-03 ⑫ 	H80737-00 0209.FJ 1,1 mm MLS H80737-10 X 1,2 mm MLS H80737-20 X 1,3 mm MLS 	T38521-00 0204.C6 (6x) +0204.C7 (4x) +0204.C8 (4x) +0204.C9 (1x) 	
3,0 ZPJ (UFZ)	123 kW (167 PS) 605	10/89-09/99	S31114-00 ⑫ ⑬ 95653027 D31114-00 ⑫ 0197.E1 +0209.A4 +0209.A5 +0956.30 (12x) B31114-00 ⑬ R31114-00 ③	H08263-00 R 0209.A4 H08264-00 L 0209.A5 95 Ø 	T08263-00 0204.53 (16x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



70-31414-10 	N92830-00 P76662-00 0956.38 24x	X89882-01 0348.00 X89883-01 0348.P9 2x	X52329-01 0349.G0 2x 	70-31414-10 	P76144-11 K ← 0514.82 42x56x7 A SL RD FPM P77682-01 K ← 0514.A9 42x56x6,5 A SL RD P76065-01 K → 0119.14 98x120x7 A SL LD FPM P77683-01 K → 0119.18 98x120x9 A SL LD P77141-01 N 4x 0807.24 38x50x6 A SL RD FPM
X83071-01 0249.F7 	N91011-00 P76818-00 16x	X89001-01 0348.T7 	X81859-01 0349.L8 	X54818-01 0304.59 NBR 	P77458-01 K ← 0514.C9 50x70x11 PTFE P77459-01 K → 0514.E4 90x120x13,65 FPM
70-31414-10 	N91210-00 0956.22 (12x) P76531-00 0249.48 12x		X07897-01 2x X51325-01 6x 96 130 969 	70-31414-10 	P76152-01 K ← 0514.21 42x62x10 A SL RD FPM P76345-01 K → 80x100x13 A SL LD MVQ P76128-11 N 2x 0236.24 32x45x8 A LD FPM

H posterior / hinten / rear / arrière / posteriore / сзади
V delante / vorne / front / avant / anteriore / спереди



PEUGEOT				
Ltr.				
3,0 ZPJ4 (UKZ)	147 kW (200 PS) 605 SV 24	08/89-09/99		
		S31585-00 ⑫ ⑬ 95659411 D31585-00 ⑫ 95656101 B31585-00 ⑬ R31114-00 ③	H08263-00 R 0209.A4 H08264-00 L 0209.A5 95 Ø 	T08263-00 0204.53 (16x)

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



70-31414-10 	N92920-00 P76532-00 24x 0956.19	X51247-01 ⑦ 2x 0349.74 	70-31414-10 	P76151-01 K ← 0326.12 42x62x7 A RD FPM P76388-11 K → 100x118x10/12 A SL LD FPM P76128-11 N 2x 0236.24 32x45x8 A LD FPM	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

