

VOLKSWAGEN														
Ltr.			1											
1,6 AD AE AF AH	34-37 kW (47-50 PS)	TRANSPORTER	08/67-07/79	A30576-00 ¹⁴ 111 198 007 D30252-00 ¹⁸ 113 198 101 A			X00991-01 113 101 481 F Kork 	2x	X00995-01 113 129 717 A X03811-01 311 129 707 	2x	X03808-01 111 251 261 C 	4x	P76303-01 K → 113 105 245 F 70x90x10 ALD ACM	
1,6 AS CT	37 kW (50 PS)	TRANSPORTER	08/68-12/82	A30576-00 ¹⁴ 111 198 007 S37028-00 ¹³ D30252-00 ¹⁸ 113 198 101 A			X00991-01 113 101 481 F Kork 	2x	X00995-01 113 129 717 A X03811-01 311 129 707 	2x	X03808-01 111 251 261 C 	4x	P76303-01 K → 113 105 245 F 70x90x10 ALD ACM	
1,6 CS	37 kW (50 PS)	TRANSPORTER	01/81-07/87	S30435-00 ¹² ¹³ 068 198 001 D30435-00 ¹² 068 198 012 L B30584-00 ¹³ 037 198 011 C	H02633-00 068 103 383 ES 1,5 mm 1 Mot.→000 338 H12633-10 068 103 383 ET 1,6 mm 2 Mot.→000 338 H22633-20 068 103 383 FA 78 Ø 1,7 mm 3 Mot.→000 338 H03675-00 068 103 383 FE 1,6 mm 1 Mot.000 339→ H13675-10 068 103 383 FF 1,65 mm 2 Mot.000 339→ H23675-20 068 103 383 FG 78 Ø 1,7 mm 3 Mot.000 339→ 	T02673-00 068 103 384 A (10x) 	V30584-00 026 198 025 A 8,5 mm Kork 	N90300-00 026 109 675 (8x) P76531-00 026 109 675	X04875-01 026 129 717 D X55899-01 068 129 717 E 	8x	X03747-01 026 129 589 A X07854-01 841 253 115 B X51157-01 433 253 115	4x	E30584-00 044 103 609 D +N 905 927 02 (20x) Mot.000339→ 	P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM
1,6 JX	51 kW (69-70 PS)	TRANSPORTER	08/84-07/92	S30435-00 ¹² ¹³ 068 198 001 D30435-00 ¹² 068 198 012 L B30584-00 ¹³ 037 198 011 C	H03675-00 068 103 383 FE 1,6 mm 1 H13675-10 068 103 383 FF 1,65 mm 2 H23675-20 068 103 383 FG 78 Ø 1,7 mm 3 	T02673-00 068 103 384 A (10x) 	V30584-00 026 198 025 A 8,5 mm Kork V53509-00 026 198 025 C 6,5 mm Gummi 1 Dichtlippe 	N90300-00 026 109 675 (8x) P76531-00 026 109 675	X55899-01 068 129 717 E 	8x	X03747-01 026 129 589 A 	4x	E30584-00 044 103 609 D +N 905 927 02 (20x) 	P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
Ltr.			1									
1,6 YG	61 kW (83 PS)			S30587-00 ¹² ¹³ D30587-00 ¹² 049 198 012 H B30584-00 ¹³ 037 198 011 C	H04129-00 049 103 383 K 81 Ø 1,75 mm 	T04132-00 049 103 385 (10x) 	V30584-00 026 198 025 A 8,5 mm Kork V31265-00 ✕ 056 198 025 6,5 mm 	N90300-00 026 109 675 (8x) P76531-00 026 109 675	X04875-01 026 129 717 D 8x 	X03747-01 026 129 589 A 4x X07854-01 ⚠ 841 253 115 B 	E30584-00 044 103 609 D +N 905 927 02 (20x) 	P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM
1,7 CA CB	49 kW (66-67 PS)	TRANSPORTER	08/71-12/73	S37029-00 ¹³ 021 198 009 D	H80722-00 4x 021101343 90 Ø 0,7 mm 		X53150-01 2x 021 101 481 Kork 		X89183-01 4x 021 129 707 D 	X81944-01 4x 021 256 251 A X81354-01 ⚠ 2x 025 251 261 		P76152-01 K ← 021 105 247 A 42x62x10 A SL RD FPM P76325-01 K → 029 105 245 B 75x95x10/9,5 A LD FPM
1,7 KY	42 kW (57 PS)	TRANSPORTER	10/86-07/92	S30435-00 ¹² ¹³ 068 198 001 ✕ D30435-00 ¹² 068 198 012 L ✕ B30584-00 ¹³ 037 198 011 C	H02393-00 033 103 383 K 1,53 mm 1 H12393-10 033 103 383 L 1,57 mm 2 H22393-20 033 103 383 M 81 Ø 1,61 mm 3 	T02673-00 068 103 384 A (10x) 	V30584-00 026 198 025 A 8,5 mm Kork V53509-00 ✕ 026 198 025 C 6,5 mm Gummi 1 Dichtlippe 	N90300-00 026 109 675 (8x) P76531-00 026 109 675	X55899-01 8x 068 129 717 E 	X03747-01 4x 026 129 589 A 	E30584-00 044 103 609 D +N 905 927 02 (20x) 	P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM
1,8 AP	50 kW (68 PS)	TRANSPORTER	11/73-07/75	A31438-00 ¹⁴ 029 198 009 A ✕	H51289-00 4x 051101341A 93 Ø 		X53150-01 2x 021 101 481 Kork 		X55893-01 4x 021 129 707 E 	X51285-01 4x 039 256 251 X81354-01 ⚠ 2x 025 251 261 		P76152-01 K ← 021 105 247 A 42x62x10 A SL RD FPM
1,8 PD	49 kW (67 PS)	TRANSPORTER	12/90-07/92	S31643-00 ¹² ¹³ D31643-00 ¹² 044 198 012 B31643-00 ¹³ 044 198 011 A	H50155-00 044 103 383 D 82,7 Ø 	T04132-00 049 103 385 (10x) 	V30584-00 026 198 025 A 8,5 mm Kork V53509-00 ✕ 026 198 025 C 6,5 mm Gummi 1 Dichtlippe 	N90300-00 026 109 675 (8x) P76531-00 026 109 675	X04875-01 8x 026 129 717 D X55430-01 048 129 717 A 	X03747-01 4x 026 129 589 A 	X54624-01 044 103 609 D ACM 	P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM

VOLKSWAGEN												
1.9 ABL	50 kW (68 PS)	TRANSPORTER	10/92-04/03	<p>S31598-00 ¹² ¹³</p> <p>D31598-00 ¹² 028 198 012 B Mot.→ABL 076 000</p> <p>B31598-00 ¹³ 028 198 011 B</p>	<p>H02391-00 028 103 383 BH 1,53 mm 1 </p> <p>H12391-10 028 103 383 BJ 1,57 mm 2 </p> <p>H22391-20 028 103 383 BK 81 Ø 1,61 mm 3 </p>	<p>T02673-00 068 103 384 A (10x)</p>	<p>V31598-00 028 198 025</p>	<p>N90300-00 026 109 675 (8x) Mot.→ABL 076 000</p> <p>N91190-00 027 109 675 (8x) Mot.ABL 076 001→</p> <p>P76531-00 8x 026 109 675 Mot.→ABL 076 000</p> <p>P76532-00 027 109 675 Mot.ABL 076 001→</p>	<p>X55431-01 028 129 717 D</p>	<p>X03747-01 026 129 589 A</p>	<p>4x X54361-01 037 115 220 B NBR Mot.→ABL 070 000</p> <p>X04116-01 026 103 609 D Mot.ABL 070 001→ Mot.→ABL 076 000</p>	<p>P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p>P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p>P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM</p>
1.9 AFD	58 kW (79 PS)			<p>D32721-00 ¹² 028 198 012 F</p> <p>B32231-00 ¹³ 028 198 011 D Mot.→AFD 000 999</p> <p>B37015-00 ¹³ ³⁵ Mot.AFD 001 000→</p>	<p>H02392-00 028 103 383 BL 1,45 mm 1 </p> <p>H12392-10 028 103 383 BM 1,53 mm 2 </p> <p>H22392-20 028 103 383 BN 81 Ø 1,61 mm 3 </p>	<p>T02673-00 068 103 384 A (10x)</p>	<p>V32231-00 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x)</p>	<p>N91190-00 027 109 675 (8x) P76532-00 027 109 675</p>	<p>X55431-01 028 129 717 D</p>	<p>X03747-01 026 129 589 A</p>	<p>4x X54624-01 044 103 609 D ACM</p> <p>70-31414-10</p>	<p>P76087-01 K ← 068 103 085 E 32x47x10 A SL WD FPM</p> <p>P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM</p> <p>Mot.→AFD 000 999</p> <p>P77317-01 K → </p> <p>PTFE Mot.AFD 001 000→</p> <p>P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM</p>
1.9 ANC	44 kW (60 PS)			<p>D32241-00 ¹² 038 198 012</p> <p>B32959-00 ¹³ ³⁸</p>	<p>H03518-00 038 103 383 AL 1,47 mm 1 </p> <p>H13518-10 038 103 383 AM 1,57 mm 2 </p> <p>H23518-20 038 103 383 AN 80,5 Ø 1,67 mm 3 </p>	<p>T02673-00 068 103 384 A (10x)</p>		<p>N91190-00 027 109 675 (8x) P76532-00 027 109 675</p>	<p>X55431-01 028 129 717 D</p>	<p>X03747-01 026 129 589 A</p>	<p>4x 70-31414-10</p>	<p>P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM</p> <p>P77183-01 K → </p> <p>06A 103 171 A 85x131/152x15,7 PTFE</p> <p>P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM</p>
1.9 ARD AVM BEQ BEU BJC	33-63 kW (45-86 PS)			<p>D32241-00 ¹² 038 198 012</p> <p>B32937-00 ¹³ ³⁵</p>	<p>H03518-00 038 103 383 AL 1,47 mm 1 </p> <p>H13518-10 038 103 383 AM 1,57 mm 2 </p> <p>H23518-20 038 103 383 AN 80,5 Ø 1,67 mm 3 </p>	<p>T02673-00 068 103 384 A (10x)</p>		<p>N91190-00 027 109 675 (8x) P76532-00 027 109 675</p>	<p>X55431-01 028 129 717 D</p>	<p>X51638-01 037 253 039 D</p>	<p>70-31414-10</p>	<p>P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM</p> <p>P77183-01 K → </p> <p>06A 103 171 A 85x131/152x15,7 PTFE</p> <p>P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM</p>

VOLKSWAGEN													
1.9 AXB AXC	63-77 kW (85-105 PS)	TRANSPORTER	04/03-11/09	 D32937-00 ¹² B32937-00 ^{13 35}	H09538-00 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS H19538-10 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS H29538-20 038 103 383 DG 80,5 Ø 1,61 mm 3 MLS 	T03518-00 038 103 384 (10x) 	X53715-01 038 103 483 D ACM 	N91190-00 027 109 675 (8x) P76532-00 027 109 675 	X55431-01 028 129 717 D 8x 	X03747-01 026 129 589 A 4x X51638-01 037 253 039 D X51706-01 3A0 253 115 X52970-01 1H0 253 115 A 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM	
1.9 BRR BRS	62-75 kW (84-102 PS)	TRANSPORTER	01/06-11/09	 D37058-00 ¹² B36708-00 ^{13 35}	H09538-00 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS H19538-10 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS H29538-20 038 103 383 DG 80,5 Ø 1,61 mm 3 MLS 	T03518-00 038 103 384 (10x) 	X83127-01 03G 103 483 F NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675 	X55431-01 028 129 717 D 8x 	X51638-01 037 253 039 D 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM	
1.9 CDXA CDXB	29-55 kW (40-75 PS)			D32241-00 ¹² 038 198 012 B32959-00 ^{13 38}	H03518-00 038 103 383 AL 1,47 mm 1 MLS H13518-10 038 103 383 AM 1,57 mm 2 MLS H23518-20 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	T02673-00 068 103 384 A (10x) 		N91190-00 027 109 675 (8x) P76532-00 027 109 675 	X55431-01 028 129 717 D 8x 	X03747-01 L 026 129 589 A 2x X81409-01 R 034 129 589 B 2x 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM	
1.9 DF DG DH GW	44-66 kW (60-90 PS)	TRANSPORTER	08/82-07/92	S31503-00 ¹³ 025 198 009 B D31503-00 025 198 012 A B31503-00 ¹³	H50048-00 4x 025 101 343 B 95 Ø 2x 		X00991-01 2x 113 101 481 F Kork 		X55316-01 2x 025 129 717 E X55877-01 2x 025 129 717 C 		X51158-01 4x N 901 316 02 		P76253-01 K ← 025 105 247 A 48x68x10 A SL RD FPM P76325-01 K → 029 105 245 B 75x95x10/9,5 A LD FPM

VOLKSWAGEN												
Ltr.			1									
1,9 1X	44-45 kW (60-61 PS)	TRANSPORTER	07/90-12/95	<p>S31598-00 ⁽¹²⁾ ⁽¹³⁾</p> <p>D31598-00 ⁽¹²⁾</p> <p>028 198 012 B</p> <p>B31598-00 ⁽¹³⁾</p> <p>028 198 011 B</p>	<p>H02390-00</p> <p>028 103 383 BB</p> <p>1,6 mm 1 </p> <p>Mot.→1X 104 630</p> <p>H12390-10</p> <p>028 103 383 BC</p> <p>1,65 mm 2 </p> <p>Mot.→1X 104 630</p> <p>H22390-20</p> <p>028 103 383 BD</p> <p>81 Ø</p> <p>1,7 mm 3 </p> <p>Mot.→1X 104 630</p> <p>H02391-00</p> <p>028 103 383 BH</p> <p>1,53 mm 1 </p> <p>MLS</p> <p>Mot.1X 104 631→</p> <p>H12391-10</p> <p>028 103 383 BJ</p> <p>1,57 mm 2 </p> <p>MLS</p> <p>Mot.1X 104 631→</p> <p>H22391-20</p> <p>028 103 383 BK</p> <p>81 Ø</p> <p>1,61 mm 3 </p> <p>MLS</p> <p>Mot.1X 104 631→</p>	<p>T02673-00</p> <p>068 103 384 A (10x)</p>	<p>V31598-00</p> <p>028 198 025</p> <p>X53152-01</p> <p>028 103 483 B</p> <p>ACM</p>	<p>N90300-00</p> <p>026 109 675 (8x)</p> <p>P76531-00</p> <p>026 109 675</p>	<p>X55431-01</p> <p>028 129 717 D</p> <p>8x</p>	<p>X03747-01</p> <p>026 129 589 A</p>	<p>4x X54361-01</p> <p>037 115 220 B</p> <p>NBR</p>	<p>P76087-01 K ←</p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p> <p>P76355-11 K →</p> <p>068 103 051 P</p> <p>85x105x9</p> <p>A SL LD FPM</p> <p>P76087-01 N</p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p>
2,0 AAC	62 kW (84 PS)	TRANSPORTER	07/90-04/03	<p>S32723-00 ⁽¹²⁾ ⁽¹³⁾</p> <p>D31643-00 ⁽¹²⁾</p> <p>044 198 012</p> <p>B32723-00 ⁽¹³⁾</p> <p>044 198 011</p>	<p>H50155-00</p> <p>044 103 383 D</p> <p>82,7 Ø</p>	<p>T02673-00</p> <p>068 103 384 A (10x)</p>	<p>V30584-00</p> <p>026 198 025 A</p> <p>8,5 mm</p> <p>Kork</p> <p>V53509-00 ^(X)</p> <p>026 198 025 C</p> <p>6,5 mm</p> <p>Gummi</p> <p>1 Dichtlippe</p>	<p>N90300-00</p> <p>026 109 675 (8x)</p> <p>P76531-00</p> <p>026 109 675</p>	<p>X04875-01</p> <p>026 129 717 D</p> <p>8x</p> <p>X55430-01</p> <p>048 129 717 A</p>	<p>X03747-01</p> <p>026 129 589 A</p>	<p>4x X04116-01</p> <p>026 103 609 D</p>	<p>P76087-01 K ←</p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p> <p>P76355-11 K →</p> <p>068 103 051 P</p> <p>85x105x9</p> <p>A SL LD FPM</p> <p>P76087-01 N</p> <p>068 103 085 E</p> <p>32x47x10</p> <p>A SL WD FPM</p>
2,0 AXA	85 kW (115 PS)	TRANSPORTER	11/03→	<p>D36712-00 ⁽¹²⁾</p> <p>B32937-00 ⁽¹³⁾ ⁽³⁵⁾</p>	<p>H80098-00</p> <p>06A 103 383 AN</p> <p>83,5 Ø</p> <p>MLS</p>	<p>T50474-00</p> <p>06A 103 384 C (10x)</p>	<p>X53809-01</p> <p>06A 103 483 C</p> <p>NBR</p>	<p>N91190-00</p> <p>027 109 675 (8x)</p> <p>P76532-00</p> <p>027 109 675</p>	<p>X57668-01</p> <p>037 129 717 C</p> <p>8x</p> <p>X88392-01 ⁽¹⁰⁾</p> <p>06A 129 717 F</p>	<p>X52965-01</p> <p>06A 253 039 L</p>	<p>70-31414-10</p>	<p>P76096-11 K ←</p> <p>038 103 085 E</p> <p>35x48x10</p> <p>A SL RD PTFE ACM</p> <p>P77183-01 K → </p> <p>06A 103 171 A</p> <p>85x131/152x15,7</p> <p>PTFE</p> <p>P77181-01 N</p> <p>038 103 085 A</p> <p>32x47x10</p> <p>A SL RD PTFE ACM</p>

VOLKSWAGEN												
2,0 CAAA CAAB CAAC CAAD CAAE CCHA CCHB	62-103 kW (84-140 PS)	TRANSPORTER TDI	09/09→ 	 D38308-00 ¹² B38299-00 ^{13 35}	H40583-00 03L 103 383 AM 82 Ø 1,55 mm 1 MLS H40583-10 03L 103 383 AN 82 Ø 1,63 mm 2 MLS H40583-20 03L 103 383 AP 82 Ø 1,71 mm 3 MLS 	T50034-00 WHT 002 131 (10x) 	V59500-00 03L 103 483 C +03L 103 070 (4x) X59500-01 03L 103 483 C 	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X59474-01 03L 129 717 E 16x	X59496-01 03L 253 039 E 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77689-01 K → 03L 103 171 A PTFE P77774-01 N 03L 103 085 32x47x10 A RD FPM
2,0 CBHA CBKA	47-74 kW (64-101 PS)			 D37051-00 ¹² B36708-00 ^{13 35}	H08008-00 038 103 383 CP 1,45 mm 1 MLS H18008-10 038 103 383 CQ 1,53 mm 2 MLS H28008-20 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	T03518-00 038 103 384 (10x) 	X83120-01 03G 103 483 D NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X55431-01 028 129 717 D 8x	X81833-01 03G 253 039 A 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 CBJB	55 kW (75 PS)			 D32937-00 ¹² B36708-00 ^{13 35}	H08008-00 038 103 383 CP 1,45 mm 1 MLS H18008-10 038 103 383 CQ 1,53 mm 2 MLS H28008-20 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	T03518-00 038 103 384 (10x) 	X53715-01 038 103 483 D ACM 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X55431-01 028 129 717 D 8x	X51638-01 037 253 039 D 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77353-11 K → 038 103 171 S PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,0 CBSA	37 kW (50 PS)			 D37092-00 ¹² B32937-00 ^{13 35}	H80753-00 06G 103 383 A MLS 	T50474-00 06A 103 384 C (10x) 	X53809-01 06A 103 483 C NBR 	N91190-00 027 109 675 (8x) P76532-00 027 109 675	X75011-01 06A 129 717 D 4x	X52965-01 06A 253 039 L 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77183-01 K → 06A 103 171 A 85x131/152x15,7 PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM

VOLKSWAGEN													
Ltr.													
2,0 CFCA	132 kW (180 PS)	TRANSP.	→7H-F-999 999, 7J-F-999 999	09/09→	D38307-00 ¹² B38299-00 ^{13 35}	H40583-00 03L 103 383 AM 82 Ø 1,55 mm 1 □ MLS H40583-10 03L 103 383 AN 82 Ø 1,63 mm 2 □ MLS H40583-20 03L 103 383 AP 82 Ø 1,71 mm 3 □ MLS	T50034-00 WHT 002 131 (10x)	V59500-00 03L 103 483 C +03L 103 070 (4x)	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X59474-01 03L 129 717 E 16x	X82521-01 03C 253 039 F	70-31414-10	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77689-01 K → 03L 103 171 A PTFE P77774-01 N 03L 103 085 32x47x10 A RD FPM
2,0 CFCA	132 kW (180 PS)	TRANSP.	7H-F-000 001, 7H-G-000 001→	09/09→	D38307-00 ¹² B38299-00 ^{13 35}	H84868-00 03L 103 383 DC 82 Ø 1,55 mm 1 □ MLS H84868-10 03L 103 383 DD 82 Ø 1,63 mm 2 □ MLS H84868-20 03L 103 383 DE 82 Ø 1,71 mm 3 □ MLS	T50034-00 WHT 002 131 (10x)	V59500-00 03L 103 483 C +03L 103 070 (4x)	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X59474-01 03L 129 717 E 16x	X82521-01 03C 253 039 F	70-31414-10	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77689-01 K → 03L 103 171 A PTFE P77774-01 N 03L 103 085 32x47x10 A RD FPM
2,0 CH	55 kW (75 PS)	LT		04/75-09/83	D31645-00 ¹² 047 198 012 B37007-00 ¹³ 060 198 011 B	H50164-00 046 103 383 J 88,5 Ø 1,55 mm	T02673-00 068 103 384 A (10x) Mot.0008796→	V31645-00 060 198 025 A	N92632-00 046 109 675 A (8x) P76661-00 046 109 675 A	X56304-01 060 129 717 A 8x	X51297-01 048 129 589 X52208-01 048 129 589 A X51169-01 431 253 115 A	E37007-00 060 198 041 A 4x	P77438-01 K ← 048 115 147 35x54x10 A SL RD FPM P77439-01 K → 059 103 051 D 96x117x10,5/12 A SL LD NBR P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM
2,0 CJ GE	51 kW (69-70 PS)	TRANSPORTER		08/75-07/79	A31438-00 ¹⁴ 029 198 009 A	H51289-00 4x 051101341A 93 Ø		X53150-01 2x 021 101 481 Kork		X55893-01 4x 021 129 707 E	X51285-01 4x 039 256 251 X81354-01 025 251 261 2x		P76152-01 K ← 021 105 247 A 42x62x10 A SL RD FPM
2,0 CJK CJKB	110-150 kW (150-204 PS)	TRANSPORTER TSI		05/11→	D40567-00 ¹² B38289-01 ^{13 35}	H40567-00 06H 103 383 AC 83 Ø MLS	T80727-00 06D 103 385 D (10x)	70-31414-10	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X89273-01 06F 129 717 D 16x	X81829-01 06F 253 039 F	70-31414-10	P77842-01 K ← 06L 103 085 B 45x60x8 A SL RD PTFE ACM P77754-01 K → 06H 103 171 F 85x132/152x15,7 PTFE

VOLKSWAGEN												
Ltr. 2,0 CKTB CKTC CKUB CKUC CSNA [NEW]	80-120 kW (109-163 PS)	CRAFTER TDI	05/11→	 D38311-00 ¹² B38299-00 ^{13 35}	H40583-00 03L 103 383 AM 82 Ø 1,55 mm 1 □ MLS →10/13 H40583-10 03L 103 383 AN 82 Ø 1,63 mm 2 □ MLS →10/13 H40583-20 03L 103 383 AP 82 Ø 1,71 mm 3 □ MLS →10/13 H84868-00 03L 103 383 DC 82 Ø 1,55 mm 1 □ MLS 11/13→ H84868-10 03L 103 383 DD 82 Ø 1,63 mm 2 □ MLS 11/13→ H84868-20 03L 103 383 DE 82 Ø 1,71 mm 3 □ MLS 11/13→ 	T50034-00 WHT 002 131 (10x) 	V59500-00 03L 103 483 C +03L 103 070 (4x) X59500-01 03L 103 483 C 	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X59470-01 03L 129 717 D 16x 	X82518-01 03L 253 039 G 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77689-01 K → 03L 103 171 A PTFE P77774-01 N 03L 103 085 32x47x10 A RD FPM
2,0 CSLB [NEW]	84 kW (114 PS)	CRAFTER TDI	11/13→	 D38311-00 ¹² B38299-00 ^{13 35}	H84868-00 03L 103 383 DC 82 Ø 1,55 mm 1 □ MLS H84868-10 03L 103 383 DD 82 Ø 1,63 mm 2 □ MLS H84868-20 03L 103 383 DE 82 Ø 1,71 mm 3 □ MLS 	T50034-00 WHT 002 131 (10x) 	V59500-00 03L 103 483 C +03L 103 070 (4x) X59500-01 03L 103 483 C 	N92990-00 036 109 675 (16x) P76662-00 036 109 675	X59470-01 03L 129 717 D 16x 	X82518-01 03L 253 039 G 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77689-01 K → 03L 103 171 A PTFE P77774-01 N 03L 103 085 32x47x10 A RD FPM

VOLKSWAGEN																							
Ltr.			1																				
2,0 CU CV	51 kW (69-70 PS)	TRANSPORTER	05/79-04/86	S37033-00 ¹³ 071 198 009 A	H80723-00 039 101 343 B 94 Ø 0,7 mm 	4x		X53150-01 021 101 481 Kork 	2x		X55893-01 021 129 707 E 	4x		X81357-01 L 029 256 251 A 	2x		X81358-01 R 029 256 252 A 	2x		X81354-01	2x		P76152-01 K ← 021 105 247 A 42x62x10 A SL RD FPM P76325-01 K → 029 105 245 B 75x95x10/9,5 A LD FPM
2,1 DJ MV SR SS	64-82 kW (87-112 PS)	TRANSPORTER	08/84-07/92	S31503-00 ¹³ 025 198 009 B D31503-00 025 198 012 A B31503-00 ¹³	H50048-00 025 101 343 B 95 Ø 	2x		X00991-01 113 101 481 F Kork 	2x		X55877-01 025 129 717 C 	2x		X51158-01 N 901 316 02 	4x		P76253-01 K ← 025 105 247 A 48x68x10 A SL RD FPM P76325-01 K → 029 105 245 B 75x95x10/9,5 A LD FPM						
2,3 AGL	105 kW (143 PS)	LT	05/96-07/06	D36044-00 ¹² B31936-00 ¹³ 00A 198 011	H80500-00 00A 103 383 92 Ø 1,75 mm 		T50309-00 00A 103 385 (10x) 	V31937-00 00A 103 483 +00A 103 484 (4x) NBR 		N92567-00 00A 198 675 (16x) P76792-00 00A 109 675 16x 		X56560-01 00A 133 227 		X51359-01 00A 253 039 		X54089-01 00A 103 609 A 	P76235-11 K ← 00A 103 085 A 45x67x8 A SL RD FPM P76377-01 K → 00A 103 085 93x114x13 A SL LD FPM						
2,4 AAB	57 kW (78 PS)	TRANSPORTER →70 R 160 000	07/90-09/98	D31637-00 ¹² 074 198 012 B31637-00 ¹³ 074 198 011 A	H02394-00 074 103 383 C 1,53 mm 1 Mot.→AAB 110 000 H12394-10 074 103 383 D 1,57 mm 2 Mot.→AAB 110 000 H22394-20 074 103 383 E 81 Ø 1,61 mm 3 Mot.→AAB 110 000 H00997-00 074 103 383 M 1,53 mm 1 MLS Mot.AAB 110 001→ H10997-10 074 103 383 N 1,57 mm 2 MLS Mot.AAB 110 001→ H20997-20 074 103 383 P 81 Ø 1,61 mm 3 MLS Mot.AAB 110 001→ 		T07896-00 068 103 384 A (12x) 	V31637-00 		N90710-01 026 109 675 (10x) P76531-00 026 109 675 10x 		X56210-01 074 129 717 	10x	X03747-01 026 129 589 A 	5x	X54131-01 074 103 609 F 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 2x 068 103 085 E 32x47x10 A SL WD FPM						

VOLKSWAGEN													
Ltr.			1										
2,4 AAB	57 kW (78 PS)	TRANSP. 70 R 160 001→	07/90-09/98	<p>D32840-00 ¹² 074 198 012 A</p> <p>B31637-00 ¹³ 074 198 011 A</p>	<p>H02394-00 074 103 383 C 1,53 mm 1 </p> <p>Mot.→AAB 110 000</p> <p>H12394-10 074 103 383 D 1,57 mm 2 </p> <p>Mot.→AAB 110 000</p> <p>H22394-20 074 103 383 E 81 Ø 1,61 mm 3 </p> <p>Mot.→AAB 110 000</p> <p>H00997-00 074 103 383 M 1,53 mm 1 </p> <p>MLS Mot.AAB 110 001→</p> <p>H10997-10 074 103 383 N 1,57 mm 2 </p> <p>MLS Mot.AAB 110 001→</p> <p>H20997-20 074 103 383 P 81 Ø 1,61 mm 3 </p> <p>MLS Mot.AAB 110 001→</p>	<p>T07896-00 068 103 384 A (12x)</p>		<p>N90710-01 026 109 675 (10x)</p> <p>P76531-00 026 109 675</p>	<p>X56210-01 074 129 717</p>		<p>X03747-01 026 129 589 A</p>	<p>5x X54131-01 074 103 609 F</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM</p>
2,4 ACL	70 kW (95 PS)	LT TD	06/92-06/96		<p>H00569-00 072 103 383 CT 1,4 mm</p> <p>Mot.→ACL 014 031</p> <p>H10569-10 072 103 383 DA 1,5 mm 2 </p> <p>Mot.→ACL 014 031</p> <p>H20569-20 072 103 383 DB 78 Ø 1,6 mm 3 </p> <p>Mot.→ACL 014 031</p> <p>H05685-00 075 103 383 D 1,53 mm 1 </p> <p>MLS Mot.ACL 014 032→</p> <p>H15685-10 075 103 383 E 1,57 mm 2 </p> <p>MLS Mot.ACL 014 032→</p> <p>H25685-20 075 103 383 F 78 Ø 1,61 mm 3 </p> <p>MLS Mot.ACL 014 032→</p>	<p>T08968-00 068 103 384 A (14x)</p>	<p>X53843-01 075 103 483 F NBR</p>	<p>N91210-00 026 109 675 (12x)</p> <p>P76531-00 026 109 675</p>	<p>X08969-01 072 129 717 A</p>		<p>X03747-01 026 129 589 A</p>	<p>6x X54130-01 075 103 609 C</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM</p>

VOLKSWAGEN												
Ltr.												
2,4 ACT	51 kW (69-70 PS)	LT D	08/89-06/96	<p>H00569-00 072 103 383 CT 1,4 mm Mot.→ACT 011 319</p> <p>H10569-10 072 103 383 DA 1,5 mm 2 </p> <p>Mot.→ACT 011 319</p> <p>H20569-20 072 103 383 DB 78 Ø 1,6 mm 3 </p> <p>Mot.→ACT 011 319</p> <p>H05685-00 075 103 383 D 1,53 mm 1 </p> <p>MLS Mot.ACT 011 320→</p> <p>H15685-10 075 103 383 E 1,57 mm 2 </p> <p>MLS Mot.ACT 011 320→</p> <p>H25685-20 075 103 383 F 78 Ø 1,61 mm 3 </p> <p>MLS Mot.ACT 011 320→</p>	<p>T08968-00 068 103 384 A (14x)</p>	<p>X53843-01 075 103 483 F NBR</p>	<p>N91210-00 026 109 675 (12x)</p> <p>P76531-00 026 109 675</p>	<p>X08969-01 072 129 717 A</p> <p>12x </p>	<p>X03747-01 026 129 589 A</p>	<p>6x X54130-01 075 103 609 C</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM</p> <p>2x</p>	
2,4 AJA	55 kW (75 PS)	TRANSPORTER	08/97-04/03	<p>D36651-00 ¹²</p> <p>B32840-00 074 198 011 B Mot.→AJA 028 554</p> <p>B36651-00 ¹³ ³⁵ Mot.AJA 028 555→ Mot.→AJA 050 000</p> <p>B36656-00 ¹³ ³⁵ Mot.AJA 050 001→</p>	<p>H00997-00 074 103 383 M 1,53 mm 1 </p> <p>MLS H10997-10 074 103 383 N 1,57 mm 2 </p> <p>MLS H20997-20 074 103 383 P 81 Ø 1,61 mm 3 </p> <p>MLS </p>	<p>T07896-00 068 103 384 A (12x)</p>	<p>N90710-01 026 109 675 (10x)</p> <p>P76531-00 026 109 675</p> <p>10x </p>	<p>X56210-01 074 129 717</p> <p>10x </p>	<p>X03747-01 026 129 589 A</p>	<p>5x X54131-01 074 103 609 F Mot.→AJA 050 000</p> <p>X54722-01 074 103 609 H Stahl Mot.AJA 050 001→</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AJA 028 554 P77317-01 K → </p> <p>028 103 171 B PTFE Mot.AJA 028 555→</p> <p>P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM</p> <p>2x</p>	
2,4 CP	55 kW (75 PS)	LT D	→28 J 014 000 12/78-07/92	<p>D30282-00 ¹² 076 198 015 B</p> <p>B31458-00 ¹³ 075 198 011 B</p>	<p>H18968-10 072 103 383 DH 1,5 mm 2 </p> <p>H28968-20 072 103 383 DJ 78,5 Ø 1,6 mm 3 </p>	<p>T08968-00 068 103 384 A (14x)</p>	<p>V31458-00 072 198 025 A</p>	<p>N91210-00 026 109 675 (12x)</p> <p>P76531-00 026 109 675</p>	<p>X08969-01 072 129 717 A</p> <p>12x </p>	<p>X03747-01 026 129 589 A</p>	<p>6x X54130-01 075 103 609 C</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM</p> <p>2x</p>

VOLKSWAGEN													
2,4 CP	55 kW (75 PS)	LT D	28 J 014 001→	12/78-07/92	 S31458-00 ¹² ¹³ D31458-00 ¹² 072 198 012 A B31458-00 ¹³ 075 198 011 B	H00569-00 072 103 383 CT 1,4 mm H10569-10 072 103 383 DA 1,5 mm 2 H20569-20 072 103 383 DB 78 Ø 1,6 mm 3 	T08968-00 068 103 384 A (14x) 	V31458-00 072 198 025 A 	N91210-00 026 109 675 (12x) P76531-00 026 109 675 12x	X08969-01 072 129 717 A 	X03747-01 026 129 589 A 	6x X54130-01 075 103 609 C 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 DL 1E	66-69 kW (90-94 PS)	LT		12/82-06/96	S31646-00 ¹² ¹³ D31646-00 ¹² 073 198 012 A B31458-00 ¹³ 075 198 011 B	H50165-00 073 103 383 C 78,5 Ø 1,9 mm 	T08968-00 068 103 384 A (14x) 	V31646-00 073 198 025 	N91210-00 026 109 675 (12x) P76531-00 026 109 675 12x	X51298-01 073 129 717 A 	X03747-01 026 129 589 A 	6x X54130-01 075 103 609 C 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 DV DW 1G	55-75 kW (75-102 PS)	LT D LT TD	→28 J 014 000 →28 J 014 000	08/78-09/93	D30282-00 ¹² 076 198 015 B B31458-00 ¹³ 075 198 011 B	H18968-10 072 103 383 DH 1,5 mm 2 H28968-20 072 103 383 DJ 78,5 Ø 1,6 mm 3 	T08968-00 068 103 384 A (14x) 	V31458-00 072 198 025 A 	N91210-00 026 109 675 (12x) P76531-00 026 109 675 12x	X08969-01 072 129 717 A 	X03747-01 026 129 589 A X81946-01 075 253 115 	6x X54130-01 075 103 609 C 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 DV DW 1G	55-75 kW (75-102 PS)	LT D LT TD	28 J 014 001→ 28 J 014 001→	08/78-09/93	S31458-00 ¹² ¹³ D31458-00 ¹² 072 198 012 A B31458-00 ¹³ 075 198 011 B	H00569-00 072 103 383 CT 1,4 mm H10569-10 072 103 383 DA 1,5 mm 2 H20569-20 072 103 383 DB 78 Ø 1,6 mm 3 	T08968-00 068 103 384 A (14x) 	V31458-00 072 198 025 A 	N91210-00 026 109 675 (12x) P76531-00 026 109 675 12x	X08969-01 072 129 717 A 	X03747-01 026 129 589 A X81946-01 075 253 115 	6x X54130-01 075 103 609 C 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM 2x
2,4 1S	51 kW (69-70 PS)	LT D		08/89-06/96	S31458-00 ¹² ¹³ D31458-00 ¹² 072 198 012 A B31458-00 ¹³ 075 198 011 B	H00569-00 072 103 383 CT 1,4 mm H10569-10 072 103 383 DA 1,5 mm 2 H20569-20 072 103 383 DB 78 Ø 1,6 mm 3 	T08968-00 068 103 384 A (14x) 	V31458-00 072 198 025 A 	N91210-00 026 109 675 (12x) P76531-00 026 109 675 12x	X08969-01 072 129 717 A 	X03747-01 026 129 589 A 	6x X54130-01 075 103 609 C 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM 2x

VOLKSWAGEN													
Ltr.			1										
2,5 AAF ACU AEN	81 kW (110 PS)	TRANSPORTER	11/90-04/03	S31644-00 ¹² ¹³ D31644-00 ¹² 023 198 012 B31637-00 ¹³ 074 198 011 A	H50163-00 023 103 383 B 82,5 Ø 1,8 mm 	T07896-00 068 103 384 A (12x) 	V31637-00 	N90710-01 026 109 675 (10x) P76531-00 026 109 675	10x X55159-01 034 129 717 F 		X03747-01 026 129 589 A	5x X54131-01 074 103 609 F 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM
2,5 ACV	75 kW (102 PS)	TRANSP. →ACV 115 395	09/95-04/03	D36651-00 ¹² B32840-00 074 198 011 B Mot.→ACV 115 395 B36651-00 ¹³ ³⁵ Mot.ACV 115 396→ Mot.→ACV 185 000 B36656-00 ¹³ ³⁵ Mot.ACV 185 001→	H02396-00 074 103 383 AJ 1,53 mm 1 MLS H12396-10 074 103 383 AH 1,57 mm 2 MLS H22396-20 074 103 383 AG 82 Ø 1,61 mm 3 MLS	T07896-00 068 103 384 A (12x) 	X59781-01 X 	N90710-01 026 109 675 (10x) P76531-00 026 109 675	10x X56210-01 074 129 717 		X03747-01 026 129 589 A	5x X54131-01 074 103 609 F Mot.→ACV 185 000 X54722-01 074 103 609 H Stahl Mot.ACV 185 001→ 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P77317-01 K → 028 103 171 B PTFE Mot.ACV 115 396→ P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM
2,5 AET	85 kW (115 PS)	TRANSPORTER	07/96-04/03	D36660-00 B32840-00 074 198 011 B Mot.→AET 017 277 B36651-00 ¹³ ³⁵ Mot.AET 017 278→ Mot.→AET 025 000 B36656-00 ¹³ ³⁵ Mot.AET 025 001→	H50163-00 023 103 383 B 82,5 Ø 1,8 mm 	T07896-00 068 103 384 A (12x) 		N90710-01 026 109 675 (10x) P76531-00 026 109 675	10x X55159-01 034 129 717 F 		X03747-01 026 129 589 A	5x X54131-01 074 103 609 F Mot.→AET 025 000 X54722-01 074 103 609 H Stahl Mot.AET 025 001→ 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AET 017 277 P77317-01 K → 028 103 171 B PTFE Mot.AET 017 278→ P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM P77182-01 N 028 103 086 32x47x10 A SL LD PTFE
2,5 AEU	81 kW (110 PS)	TRANSPORTER	11/90-04/03	D36660-00 B32840-00 074 198 011 B Mot.→AEU 002 001 B36651-00 ¹³ ³⁵ Mot.AEU 002 002→ Mot.→AEU 003 000 B36656-00 ¹³ ³⁵ Mot.AEU 003 001→	H50163-00 023 103 383 B 82,5 Ø 1,8 mm 	T07896-00 068 103 384 A (12x) 		N90710-01 026 109 675 (10x) P76531-00 026 109 675	10x X55159-01 034 129 717 F 		X03747-01 026 129 589 A	5x X54131-01 074 103 609 F Mot.→AEU 003 000 X54722-01 074 103 609 H Stahl Mot.AEU 003 001→ 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AEU 002 001 P77317-01 K → 028 103 171 B PTFE Mot.AEU 002 002→ P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM P77182-01 N 028 103 086 32x47x10 A SL LD PTFE

VOLKSWAGEN												
2,5 AGX	55 kW (75 PS)	LT SDI	07/96-07/06	<p>D36651-00 ¹²</p> <p>B32840-00 074 198 011 B Mot.→AGX 009 000</p> <p>B36651-00 ^{13 35} Mot.AGX 009 001→ Mot.→AGX 016 876</p> <p>B36656-00 ^{13 35} Mot.AGX 016 877→</p>	<p>H02396-00 074 103 383 AJ 1,53 mm 1 </p> <p>MLS</p> <p>H12396-10 074 103 383 AH 1,57 mm 2 </p> <p>MLS</p> <p>H22396-20 074 103 383 AG 82 Ø 1,61 mm 3 </p> <p>MLS</p>	<p>T07896-00 068 103 384 A (12x)</p>	<p>X59781-01 ^X</p>	<p>N90710-01 026 109 675 (10x)</p> <p>P76531-00 026 109 675</p> <p>10x</p>	<p>X56210-01 074 129 717</p>	<p>X03747-01 026 129 589 A</p>	<p>5x X54131-01 074 103 609 F Mot.→AGX 016 876</p> <p>X54722-01 074 103 609 H Stahl Mot.AGX 016 877→</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p>P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AGX 009 000</p> <p>P77317-01 K → </p> <p>028 103 171 B PTFE Mot.AGX 009 001→</p> <p>P76087-01 N 2x 068 103 085 E 32x47x10 A SL WD FPM</p>
2,5 AHD	75 kW (102 PS)	LT TDI	05/96-08/99	<p>D36651-00 ¹²</p> <p>B32840-00 074 198 011 B Mot.→AHD 036 065</p> <p>B36651-00 ^{13 35} Mot.AHD 036 066→ Mot.→AHD 063 000</p> <p>B36656-00 ^{13 35} Mot.AHD 063 001→</p>	<p>H02396-00 074 103 383 AJ 1,53 mm 1 </p> <p>MLS</p> <p>H12396-10 074 103 383 AH 1,57 mm 2 </p> <p>MLS</p> <p>H22396-20 074 103 383 AG 82 Ø 1,61 mm 3 </p> <p>MLS</p>	<p>T07896-00 068 103 384 A (12x)</p>	<p>X59781-01 ^X</p>	<p>N90710-01 026 109 675 (10x)</p> <p>P76531-00 026 109 675</p> <p>10x</p>	<p>X56210-01 074 129 717</p>	<p>X03747-01 026 129 589 A</p>	<p>5x X54131-01 074 103 609 F Mot.→AHD 063 000</p> <p>X54722-01 074 103 609 H Stahl Mot.AHD 063 001→</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p>P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM Mot.→AHD 036 065</p> <p>P77317-01 K → </p> <p>028 103 171 B PTFE Mot.AHD 036 066→</p> <p>P76087-01 N 2x 068 103 085 E 32x47x10 A SL WD FPM</p>
2,5 AHY	111 kW (151 PS)	TRANSPORTER	05/98-04/03	<p>D36656-00 ¹²</p> <p>B36651-00 ^{13 35} Mot.→AHY 005 000</p> <p>B36656-00 ^{13 35} Mot.AHY 005 001→</p>	<p>H02396-00 074 103 383 AJ 1,53 mm 1 </p> <p>MLS</p> <p>H12396-10 074 103 383 AH 1,57 mm 2 </p> <p>MLS</p> <p>H22396-20 074 103 383 AG 82 Ø 1,61 mm 3 </p> <p>MLS</p>	<p>T07896-00 068 103 384 A (12x)</p>	<p>X59781-01 ^X</p>	<p>N90710-01 026 109 675 (10x)</p> <p>P76531-00 026 109 675</p> <p>10x</p>	<p>X56210-01 074 129 717</p>	<p>X03747-01 026 129 589 A</p>	<p>5x X54131-01 074 103 609 F Mot.→AHY 005 000</p> <p>X54722-01 074 103 609 H Stahl Mot.AHY 005 001→</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p>P77317-01 K → </p> <p>028 103 171 B PTFE</p> <p>P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM</p> <p>P77182-01 N 028 103 086 32x47x10 A SL LD PTFE</p>
2,5 AJT	65 kW (88 PS)	TRANSPORTER	05/98-04/03	<p>D36656-00 ¹²</p> <p>B36651-00 ^{13 35} Mot.→AJT 016 000</p> <p>B36656-00 ^{13 35} Mot.AJT 016 001→</p>	<p>H02396-00 074 103 383 AJ 1,53 mm 1 </p> <p>MLS</p> <p>H12396-10 074 103 383 AH 1,57 mm 2 </p> <p>MLS</p> <p>H22396-20 074 103 383 AG 82 Ø 1,61 mm 3 </p> <p>MLS</p>	<p>T07896-00 068 103 384 A (12x)</p>	<p>X59781-01 ^X</p>	<p>N90710-01 026 109 675 (10x)</p> <p>P76531-00 026 109 675</p> <p>10x</p>	<p>X56210-01 074 129 717</p>	<p>X03747-01 026 129 589 A</p>	<p>5x X54131-01 074 103 609 F Mot.→AJT 016 000</p> <p>X54722-01 074 103 609 H Stahl Mot.AJT 016 001→</p>	<p>P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM</p> <p>P77317-01 K → </p> <p>028 103 171 B PTFE</p> <p>P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM</p> <p>P77182-01 N 028 103 086 32x47x10 A SL LD PTFE</p>

VOLKSWAGEN													
Ltr.													
2,5 ANF ANG ANH	55-111 kW (75-151 PS)		1	 D36656-00 ¹² B36656-00 ^{13 35}	H02396-00 074 103 383 AJ 1,53 mm 1 MLS H12396-10 074 103 383 AH 1,57 mm 2 MLS H22396-20 074 103 383 AG 82 Ø 1,61 mm 3 MLS 	T07896-00 068 103 384 A (12x) 		N90710-01 026 109 675 (10x) P76531-00 026 109 675	X56210-01 074 129 717 10x		X03747-01 026 129 589 A 	5x X54722-01 074 103 609 H Stahl 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P77317-01 K → 028 103 171 B PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM P77182-01 N 028 103 086 32x47x10 A SL LD PTFE
2,5 ANJ APA AUF AVR AXG AXL AYC AYY BBE BBF	61-111 kW (83-151 PS)	LT TDI TRANSPORTER	09/95-07/06	 D36656-00 ¹² B36656-00 ^{13 35}	H02396-00 074 103 383 AJ 1,53 mm 1 MLS H12396-10 074 103 383 AH 1,57 mm 2 MLS H22396-20 074 103 383 AG 82 Ø 1,61 mm 3 MLS 	T07896-00 068 103 384 A (12x) 	X59781-01	N90710-01 026 109 675 (10x) P76531-00 026 109 675	X56210-01 074 129 717 10x		X03747-01 026 129 589 A 	5x X54722-01 074 103 609 H Stahl 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P77317-01 K → 028 103 171 B PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM P77182-01 N 028 103 086 32x47x10 A SL LD PTFE
2,5 APL AVT	85 kW (115 PS)	TRANSPORTER	07/96-04/03	D36660-00 B36656-00 ^{13 35}	H50163-00 023 103 383 B 82,5 Ø 1,8 mm 	T07896-00 068 103 384 A (12x) 		N90710-01 026 109 675 (10x) P76531-00 026 109 675	X55159-01 034 129 717 F 10x		X03747-01 026 129 589 A 	5x X54722-01 074 103 609 H Stahl 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P77317-01 K → 028 103 171 B PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM P77182-01 N 028 103 086 32x47x10 A SL LD PTFE
2,5 AXD AXE BLJ	96-128 kW (130-174 PS)	TRANSPORTER	04/03-11/09	 D37059-00 ¹² B37059-00 ¹³	H01895-00 070 103 383 M 1,27 mm 1 MLS H11895-10 070 103 383 N 1,35 mm 2 MLS H21895-20 070 103 383 P 83 Ø 1,43 mm 3 MLS 	T08127-00 070 103 384 (12x) 	70-31414-10 	N93137-00 027 109 675 (10x) P76532-00 027 109 675	X89297-01 070 129 717 A 10x X89298-01 070 129 717 X89299-01 070 129 717 B 2x		X81444-01 070 253 039 C 	70-31414-10 	P77440-01 K ← 070 103 051 A 85x105x12 A SL LD PTFE

VOLKSWAGEN												
2,5 BJJ BJK BJL BJM	65-120 kW (88-163 PS)	BUS 30-35 KASTEN 30-50 PRITSCH 30-50	04/06→	 D37060-00 ¹² B37060-00 ¹³ ³⁸	H01896-00 076 103 383 C 1,53 mm 1 MLS H11896-10 076 103 383 D 1,57 mm 2 MLS H21896-20 076 103 383 E 81,5 Ø 1,61 mm 3 MLS 	T07896-00 068 103 384 A (12x) 	X59781-01 	N90710-01 026 109 675 (10x) P76531-00 026 109 675	X56210-01 074 129 717 10x	X81985-01 074 253 039 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,5 BNZ BPC	96-128 kW (130-174 PS)	TRANSPORTER	04/03-11/09	 D37061-00 ¹² B37059-00 ¹³	H01895-00 070 103 383 M 1,27 mm 1 MLS H11895-10 070 103 383 N 1,35 mm 2 MLS H21895-20 070 103 383 P 83 Ø 1,43 mm 3 MLS 	T08127-00 070 103 384 (12x) 	70-31414-10 	N93137-00 027 109 675 (10x) P76532-00 027 109 675	X88926-01 070 129 717 D 10x X88931-01 070 129 717 E X88932-01 2x 070 129 717 C	X81444-01 070 253 039 C 	70-31414-10 	P77440-01 K ← 070 103 051 A 85x105x12 A SL LD PTFE
2,5 CEBA CEBB CECA CECB	65-120 kW (88-163 PS)	BUS 30-35 KASTEN 30-50 PRITSCH 30-50	04/06→	 D37060-00 ¹² B37060-00 ¹³ ³⁸	H01896-00 076 103 383 C 1,53 mm 1 MLS H11896-10 076 103 383 D 1,57 mm 2 MLS H21896-20 076 103 383 E 81,5 Ø 1,61 mm 3 MLS 	T07896-00 068 103 384 A (12x) 	X59781-01 	N90710-01 026 109 675 (10x) P76531-00 026 109 675	X56210-01 074 129 717 10x	X81985-01 074 253 039 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77821-01 K → 076 103 171 B PTFE P77181-01 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
2,8 AES	103 kW (140 PS)	TRANSPORTER	11/95-05/00	B36996-00 ¹³ 021 198 011 A Mot.→AES 009 433	H50150-00 021 103 383 H 83 Ø Mot.→AES 009 433 H80100-00 021 103 383 N 83,5 Ø MLS Mot.AES 009 434→ 	T50150-00 021 103 384 D (10x) +021 103 384 E (7x) +021 103 384 F (3x) Mot.→AES 009 433 T50478-00 021 103 384 G (10x) +021 103 384 K (7x) +021 103 384 L (3x) Mot.AES 009 434→ 	N92450-00 027 109 675 (12x) P76532-00 027 109 675	X89184-01 021 133 227 K 12x X58345-01 ¹⁰ 021 133 227 H 	X51973-01 021 253 039 E Zyl. 1 - 3 X51974-01 021 253 050 B Zyl. 4 - 6 	X54676-01 021 103 609 B ACM Mot.→AES 009 433 70-31414-10 Mot.AES 009 434→ 	P76096-01 K ← 054 115 147 B 35x48x10 A SL RD FPM P76355-11 K → 068 103 051 P 85x105x9 A SL LD FPM	

VOLKSWAGEN															
Ltr.			1												
2.8 AGK ATA	92-96 kW (125-130 PS)	LT TDI	07/97-07/06	D36661-00 ¹² B36661-00 ¹³	H80472-00 062 103 383 A 96 Ø 	T80472-00 062 103 384 (10x) 	X83011-01 062 103 483 NBR 	N93117-00 062 109 675 (12x) P76775-00 062 109 675	X87650-01 062 129 717 12x 		X81505-01 062 129 589 4x 	X54721-01 062 103 609 	P77445-01 K ← 062 115 147 64x80x9 B SL RD FPM P77446-01 K → 062 103 051 91x111x10 AB SL LD FPM		
2.8 AMV	150 kW (204 PS)	TRANSPORTER	04/00-04/03	D36998-00 ¹² B36716-00 ¹³	H80099-00 022 103 383 F 82,5 Ø MLS 	T80099-00 022 103 384 C (12x) +022 103 384 D (6x) 	X83108-01 022 103 483 E NBR 	N92830-00 036 109 675 (24x) P76662-00 036 109 675	X88307-01 022 133 237 A 24x 		X81437-01 022 253 039 B Zyl. 1 - 3 	X81689-01 022 253 050 B Zyl. 4 - 6 	X81690-01 ¹² 357 253 115 D 2x 	70-31414-10 	P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM
2.8 AUH BCQ	116 kW (158 PS)	LT TDI	05/01-07/06	D40556-01 ¹² B36661-00 ¹³	H40556-00 062 103 383 B 96 Ø MLS 	T80472-00 062 103 384 (10x) 	X83011-01 062 103 483 NBR 	N93117-00 062 109 675 (12x) P76775-00 062 109 675	X87650-01 062 129 717 12x 		X81505-01 062 129 589 4x 	X54721-01 062 103 609 	P77445-01 K ← 062 115 147 64x80x9 B SL RD FPM P77446-01 K → 062 103 051 91x111x10 AB SL LD FPM		

VOLKSWAGEN

Ltr. 



1

3,0 BSP

165 kW
(224 PS)




D37054-00 ¹²
Zyl. 1 - 3





D37055-00 ¹²
Zyl. 4 - 6



B37054-00 ¹³


H01841-00
059 103 383 CM
1,1 mm 1 
MLS


H11841-10
059 103 383 CN
1,15 mm 2 
MLS


H21841-20
059 103 383 CP
1,2 mm 3 
MLS

Zyl. 1 - 3



H01842-00
059 103 383 CQ
1,1 mm 1 
MLS

H11842-10
059 103 383 CR
1,15 mm 2 
MLS

H21842-20
059 103 383 CS
1,2 mm 3 
MLS


Zvl. 4 - 6




T80448-00
057 103 384 A (16x)



X83105-01
059 103 483 N
Zyl. 1 - 3
NBR




X83106-01
059 103 483 M
Zyl. 4 - 6
NBR



N92830-00
036 109 675 (24x)
P76662-00
036 109 675



X89125-01 2x
059 129 717 J

X81941-01 2x
059 253 039 D



70-31414-10

P77441-01 K ←
079 103 051 D
55x70x8
A SL RD PTFE
P77362-01 K →
079 103 051 F
85x105x8,8
A SL LD PTFE ACM
P76087-01 N
068 103 085 E
32x47x10
A SL WD FPM



VOLKSWAGEN													
Ltr.													
3,0 CEZA	195 kW (265 PS)	1			<p>D37055-00 ¹² Zyl. 4 - 6</p> <p>D38060-00 ¹² Zyl. 1-3</p> <p>B38110-00 ¹³</p>	<p>H01841-00 059 103 383 CM 1,1 mm 1 </p> <p>H11841-10 059 103 383 CN 1,15 mm 2 </p> <p>H21841-20 059 103 383 CP 1,2 mm 3 </p> <p>Zyl. 1 - 3</p>	<p>T80448-00 2x 057 103 384 A (16x)</p>	<p>X83105-01 2x 059 103 483 N Zyl. 1 - 3 NBR</p> <p>X83106-01 059 103 483 M Zyl. 4 - 6 NBR</p>	<p>N92830-00 036 109 675 (24x) P76662-00 036 109 675</p>	<p>X89125-01 2x 059 129 717 J</p>	<p>X81941-01 2x 059 253 039 D</p>	<p>70-31414-10</p>	<p>P77441-01 K ← 079 103 051 D 55x70x8 A SL RD PTFE P77362-01 K → 079 103 051 F 85x105x8,8 A SL LD PTFE ACM P76087-01 N 068 103 085 E 32x47x10 A SL WD FPM</p>
3,2 BDL BKK	170-173 kW (231-235 PS)	TRANSP. →7H 5 070 000	04/03-11/09		<p>D37008-00 ¹²</p>	<p>H80453-00 022 103 383 M 85 Ø MLS</p>	<p>T80453-00 022 103 384 L (13x) +022 103 384 M (7x)</p>	<p>X83108-01 022 103 483 E NBR</p>	<p>N92830-00 036 109 675 (24x) P76662-00 036 109 675</p>	<p>X89128-01 24x 022 133 237 C</p>	<p>X81441-01 022 253 050 C Zyl. 4 - 6</p> <p>X81963-01 022 253 039 E Zyl. 1 - 3</p>	<p>70-31414-10</p>	<p>P76096-11 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM</p>
3,2 BDL BKK	170-173 kW (231-235 PS)	TRANSP. 7H 5 070 001→	04/03-11/09		<p>D37008-00 ¹²</p>	<p>H80453-00 022 103 383 M 85 Ø MLS</p>	<p>T80453-00 022 103 384 L (13x) +022 103 384 M (7x)</p>	<p>X83108-01 022 103 483 E NBR</p>	<p>N92830-00 036 109 675 (24x) P76662-00 036 109 675</p>	<p>X89128-01 24x 022 133 237 C</p>	<p>X81441-01 022 253 050 C Zyl. 4 - 6</p> <p>X81963-01 022 253 039 E Zyl. 1 - 3</p>	<p>70-31414-10</p>	<p>P77820-01 K ← 022 103 151 D P77354-01 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM</p>