

MINI													
1,4 N 12 B 14 A	55-70 kW (75-95 PS)	ONE	11/06-03/10	<p>D40616-00 ⁽¹²⁾ ⁽¹⁹⁾ 11 12 0 427 689 +11 12 7 570 859</p> <p>D40616-01 ⁽¹²⁾ 11 12 0 427 689</p>	<p>H40616-00 11 12 7 570 859 78 Ø 0,9 mm MLS</p> <p>H40616-10 ^(X) 11 12 7 570 860 78 Ø 1,2 mm MLS</p>	<p>T40616-00 11 12 7 560 274</p>	<p>V38326-00 11 12 7 567 877</p>	<p>N93158-00 11 34 0 033 950 P93158-00</p>	<p>M59582-00 11 61 7 528 173 (4x)</p> <p>16x </p>	<p>X59642-01 ^(X) 18 40 7 563 111</p>	<p>70-31414-10</p>	<p>P77789-01 K ← 11 11 7 568 264 61x75x8 A SL RD</p> <p>P77670-01 K → 11 11 7 568 263 85x105x8 A SL LD</p>	
1,4 1ND 1ND-TV	55-65 kW (75-88 PS)	ONE D	06/03-09/06	<p>S36926-00 ⁽¹²⁾ ⁽¹³⁾ 11 11 7 790 935 →09/05</p> <p>D36926-00 ⁽¹²⁾ 11 12 7 790 936 →09/05</p>	<p>H01827-00 11 12 7 790 954 0,95 mm 3 MLS →09/05</p> <p>H11827-10 11 12 7 790 955 1 mm 4 MLS →09/05</p> <p>H21827-20 11 12 7 790 956 74,6 Ø 1,05 mm 5 MLS →09/05</p>		<p>X83095-01 11 12 7 792 374</p>	<p>N92102-00 11 34 7 791 053 (8x)</p>		<p>X81911-01 11 65 7 791 076</p>		<p>P77413-01 K ← 11 14 7 790 962 38x50x6 A SL RD NBR</p> <p>P77414-01 K → 11 14 7 790 960 75x107x8 A SL LD MVQ</p>	
1,6 N 12 B 16 A	85-88 kW (115-120 PS)	COOPER	10/06→	<p>D40616-00 ⁽¹²⁾ ⁽¹⁹⁾ 11 12 0 427 689 +11 12 7 570 859</p> <p>D40616-01 ⁽¹²⁾ 11 12 0 427 689</p>	<p>H40616-00 11 12 7 570 859 78 Ø 0,9 mm MLS</p> <p>H40616-10 ^(X) 11 12 7 570 860 78 Ø 1,2 mm MLS</p>	<p>T40616-00 11 12 7 560 274</p>	<p>V38326-00 11 12 7 567 877</p>	<p>N93158-00 11 34 0 033 950 P93158-00</p>	<p>M59582-00 11 61 7 528 173 (4x)</p> <p>16x </p>	<p>X59642-01 ^(X) 18 40 7 563 111</p>	<p>70-31414-10</p>	<p>P77789-01 K ← 11 11 7 568 264 61x75x8 A SL RD</p> <p>P77670-01 K → 11 11 7 568 263 85x105x8 A SL LD</p>	
1,6 N 14 B 16 A	120-141 kW (163-192 PS)	COOPER S JOHN COOPER WORKS	10/06→	<p>D40634-00 ⁽¹²⁾ ⁽¹⁹⁾ 11 12 0 427 690 +11 12 7 560 276</p> <p>D40634-01 ⁽¹²⁾ 11 12 0 427 690</p>	<p>H40634-00 11 12 7 595 138 78 Ø 0,9 mm MLS</p> <p>H40634-10 ^(X) 11 12 7 586 908 78 Ø 1,3 mm MLS</p>	<p>T40616-00 11 12 7 560 274</p>	<p>V38327-00 11 12 7 572 851</p>	<p>N93158-00 11 34 0 033 950 P93158-00</p>	<p>M59583-00 11 61 7 528 340 (4x)</p> <p>16x </p>	<p>X59643-01 ^(X) 11 62 7 626 106</p>	<p>70-31414-10</p>	<p>P77789-01 K ← 11 11 7 568 264 61x75x8 A SL RD</p> <p>P77670-01 K → 11 11 7 568 263 85x105x8 A SL LD</p>	

MINI												
1,6 N 14 B 16 C	141-155 kW (192-211 PS)	JOHN COOPER WORKS	11/06→	<p>D40634-00 ¹² ¹⁹ 11 12 0 427 690 +11 12 7 560 276</p> <p>D40634-01 ¹² 11 12 0 427 690</p>	<p>H40634-00 11 12 7 595 138 78 Ø 0,9 mm MLS</p> <p>H40634-10 ✗ 11 12 7 586 908 78 Ø 1,3 mm MLS</p>	<p>T40616-00 11 12 7 560 274</p>	<p>V38327-00 11 12 7 572 851</p>	<p>N93158-00 11 34 0 033 950 P93158-00</p>	<p>M59583-00 11 61 7 528 340 (4x)</p> <p>16x </p> <p>X71053-01 ¹⁰</p>	<p>X59643-01 ✗ 11 62 7 626 106</p>	<p>70-31414-10</p>	<p>P77789-01 K ← 11 11 7 568 264 61x75x8 A SL RD</p> <p>P77670-01 K → 11 11 7 568 263 85x105x8 A SL LD</p>
1,6 N 16 B 16 A	55-90 kW (75-122 PS)	COOPER ONE	10/07→	<p>D38326-00</p>	<p>H40616-00 ✗ 11 12 7 570 859 78 Ø 0,9 mm MLS</p> <p>H40616-10 ✗ 11 12 7 570 860 78 Ø 1,2 mm MLS</p>	<p>T40616-00 11 12 7 560 274</p>	<p>V38326-00 11 12 7 567 877</p>	<p>N93158-00 11 34 0 033 950 P93158-00</p>	<p>M59582-00 11 61 7 528 173 (4x)</p> <p>16x </p> <p>X71037-01 ¹⁰ 11 61 7 528 174</p>	<p>X59642-01 ✗ 18 40 7 563 111</p>	<p>70-31414-10</p>	<p>P77789-01 K ← 11 11 7 568 264 61x75x8 A SL RD</p> <p>P77670-01 K → 11 11 7 568 263 85x105x8 A SL LD</p>
1,6 N 18 B 16 A N 18 B 16 B	120-160 kW (163-218 PS)	COOPER S ALL4 JWC	03/10→	<p>D38785-02</p>	<p>H40634-00 ✗ 11 12 7 595 138 78 Ø 0,9 mm MLS</p> <p>H40634-10 ✗ 11 12 7 586 908 78 Ø 1,3 mm MLS</p>	<p>T40616-00 11 12 7 560 274</p>	<p>V38785-00 11 12 7 582 400</p>	<p>N93158-00 11 34 0 033 950</p>	<p>M59583-00 11 61 7 528 340 (4x)</p> <p>16x </p> <p>X71053-01 ¹⁰</p>	<p>X59643-01 ✗ 11 62 7 626 106</p>	<p>70-31414-10</p>	<p>P77789-01 K ← 11 11 7 568 264 61x75x8 A SL RD</p> <p>P77670-01 K → 11 11 7 568 263 85x105x8 A SL LD</p>
1,6 N 18 B 16 C	155-160 kW (211-218 PS)	JOHN COOPER WORKS	02/12→	<p>D38785-02</p>	<p>H40634-00 ✗ 11 12 7 595 138 78 Ø 0,9 mm MLS</p> <p>H40634-10 ✗ 11 12 7 586 908 78 Ø 1,3 mm MLS</p>	<p>T40616-00 11 12 7 560 274</p>	<p>V38785-00 11 12 7 582 400</p>	<p>N93158-00 11 34 0 033 950 P93158-00</p>	<p>M59583-00 11 61 7 528 340 (4x)</p> <p>16x </p> <p>X71053-01 ¹⁰</p>	<p>X59643-01 ✗ 11 62 7 626 106</p>	<p>70-31414-10</p>	<p>P77789-01 K ← 11 11 7 568 264 61x75x8 A SL RD</p> <p>P77670-01 K → 11 11 7 568 263 85x105x8 A SL LD</p>

MINI												
Ltr.												
1,6 N 47 C 16 A	66-82 kW (90-112 PS)	COOPER D ALL4 ONE D	03/10→		H40755-00 11 12 8 509 149 78,7 Ø 0,95 mm 1	T38791-00 11 12 8 513 128 	V38782-00 11 12 8 511 814 	N93136-00 P76845-00 16x	X71038-01 11 61 8 507 332 4x 		70-31414-10 	P77356-01 K ← 11 11 7 802 665 55x68x8 RD FPM P77674-01 K → 11 14 7 797 490 90x104x8,5 LD FPM
1,6 W 10 B 16 A	66-85 kW (90-116 PS)	COOPER ONE	06/01-11/07	D36626-00 ¹² ¹⁹ 11 12 7 508 545 +11 12 7 508 543 D37221-00 ¹² 11 12 7 508 545 	H80433-00 11 12 7 508 543 78 Ø 0,65 mm MLS H80433-10 ^X 11 12 7 508 544 78 Ø 0,95 mm MLS 	T80433-00 07 13 1 487 226 	V36626-00 11 12 1 485 838 +11 12 7 513 066 (4x) 	N92103-00 11 34 0 029 571 P76774-00 11 12 1 487 220 16x	X87413-01 11 61 7 513 044 4x 	X81399-01 11 62 1 174 968 	X54710-01 11 13 1 487 221 NBR 	P77331-01 K ← 11 11 1 485 171 32x45x6 A SL RD ACM P77332-01 K → 11 11 1 492 244 90x111x9,5 A SL LD ACM
1,6 W 11 B 16 A	120-160 kW (163-218 PS)	COOPER S JOHN COOPER WORKS	03/02-11/07	D36925-00 ¹² 11 12 0 147 561 +11 12 7 508 543 D37221-01 ¹² 11 12 0 147 561 	H80433-00 11 12 7 508 543 78 Ø 0,65 mm MLS H80433-10 ^X 11 12 7 508 544 78 Ø 0,95 mm MLS 	T80433-00 07 13 1 487 226 	V36626-00 11 12 1 485 838 +11 12 7 513 066 (4x) 	N92103-00 11 34 0 029 571 P76774-00 11 12 1 487 220 16x	X89142-01 11 61 1 173 671 	X81399-01 11 62 1 174 968 	X54710-01 11 13 1 487 221 NBR 	P77331-01 K ← 11 11 1 485 171 32x45x6 A SL RD ACM P77332-01 K → 11 11 1 492 244 90x111x9,5 A SL LD ACM

MINI												
Ltr.												
1,6 9HZ (DV6TED4)	66-80 kW (90-109 PS)	COOPER D ONE D	11/06-09/10	<p>S36730-00 ¹² ¹³</p> <p>D36730-00 ¹²</p> <p>B36724-00 ¹³</p>	<p>H08130-00 11 12 7 805 931 76 Ø 1,25 mm 4 </p> <p>MLS</p> <p>H08130-10 11 12 7 805 932 76 Ø 1,3 mm 5 </p> <p>MLS</p> <p>H08130-20 11 12 7 805 933 76 Ø 1,35 mm 3 </p> <p>MLS</p> <p>H18130-30 11 12 7 805 934 76 Ø 1,4 mm 6 </p> <p>MLS</p> <p>H18130-40 11 12 7 805 935 76 Ø 1,45 mm 7 </p> <p>MLS</p>	<p>T08130-00 11 12 7 805 936</p>	<p>X83038-01 11 12 7 805 927 NBR</p>	<p>N93118-00 11 34 7 805 970 (16x)</p> <p>P76780-00 16x 11 34 7 805 970</p>	<p>W88321-01 11 61 7 805 028</p> <p>4x</p> <p>W88322-01 11 61 7 805 029</p> <p>4x</p>	<p>X81696-01 11 62 7 806 008</p>	<p>70-31414-10</p>	<p>P77361-01 K ← 11 11 7 805 945 40x55x6,4 A SL RD PTFE ACM</p> <p>P77362-01 K → 11 11 7 805 946 85x105x8,8 A SL LD PTFE ACM</p> <p>P77668-01 N 11 31 7 805 964 27x47x7 A SL RD PTFE ACM</p>
2,0 N 47 C 20 A	82-105 kW (112-143 PS)	COOPER D ALL4 COOPER SD	02/11→	<p>H40751-00 84,7 Ø 1,45 mm 1 </p> <p>MLS</p> <p>H40751-10 84,7 Ø 1,55 mm 2 </p> <p>MLS</p> <p>H40751-20 84,7 Ø 1,65 mm 3 </p> <p>MLS</p>	<p>T38791-00 11 12 8 513 128</p>	<p>V38782-00 11 12 8 511 814</p>	<p>N93136-00 P76845-00 16x</p>	<p>X71038-01 11 61 8 507 332</p> <p>4x</p>	<p>X82358-01 →02/13</p> <p>X71045-01 </p>	<p>70-31414-10 2x</p>	<p>P77356-01 K ← 11 11 7 802 665 55x68x8 RD FPM</p> <p>P77674-01 K → 11 14 7 797 490 90x104x8,5 LD FPM</p>	