

ALFA ROMEO														
Ltr.														
0,9 199 B6.000 <b>[NEW]</b>	74-77 kW (101-105 PS)				<b>D40647-01</b> <sup>12</sup> <b>B59733-00</b> <sup>13</sup>	<b>H40647-00</b> 55239522 82,7 Ø MLS 	<b>T40647-00</b> 55225419 (6X)	<b>V59818-00</b> 55238657 +55239505 	<b>N93186-00</b> 55225416 (8X) <b>P76952-00</b> 55225416	<b>M38520-00</b> 77365787 8x 	<b>X59767-01</b> 55230477 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77825-01 K</b> → 55229956 85x105x9 AB RD FPM	
0,9 312 A2.000	63 kW (86 PS)	MITO	07/11→		<b>D40647-00</b> <sup>12</sup> <b>B59733-00</b> <sup>13</sup>	<b>H40647-00</b> 55239522 82,7 Ø MLS 	<b>T40647-00</b> 55225419 (6X)	<b>V59818-00</b> 55238657 +55239505 	<b>N93186-00</b> 55225416 (8X) <b>P76952-00</b> 55225416	<b>M38520-00</b> 77365787 8x 	<b>X59767-01</b> 55230477 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77825-01 K</b> → 55229956 85x105x9 AB RD FPM	
1,2 AR 30102 AR 30104 AR 30500 AR 30585 AR 31000	44-50 kW (60-68 PS)	ALFASUD ARNA 33	06/72-12/89		<b>S31133-00</b> <sup>12</sup> <sup>13</sup> 60750541 <b>D31133-00</b> <sup>12</sup> 60860486	<b>H06779-00</b> 2x 60581645 81 Ø 		<b>X06740-01</b> 2x 60515689 Kork 	<b>N92000-00</b> 60535949 (x4) <b>P76544-00</b> 4830224	<b>X06750-01</b> 2x 60503077 <b>X06763-01</b> 2x 60523705 	<b>X06751-01</b> 4x 60502984 	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01 K</b> ← 60502891 40x56x10 B RD ACM <b>P76269-01 K</b> → 60502893 62x80x12 A LD ACM <b>P76106-01 N</b> 2x 60502913 35x58x10 A SL RD ACM	
1,3 AR 00530	64 kW (87 PS)	GIULIA GT SPIDER	01/66-12/78			<b>H07311-00</b> 60709171 82 Ø <b>H80657-00</b> 76 Ø 1,4 mm 		<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x 	<b>X06719-01</b> 4x 60534228 	<b>X06707-01</b> 4x 96411879  <b>X54829-01</b> <sup>11</sup> 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM	
1,3 AR 01644	66 kW (90 PS)	GIULIETTA	10/77-06/83		<b>S31124-00</b> <sup>12</sup> <sup>13</sup> 116447901000 <b>D31124-00</b> <sup>12</sup> 60778156 <b>R31124-00</b> <sup>3</sup> 60506888	<b>H07311-00</b> 60709171 82 Ø <b>H80657-00</b> 76 Ø 1,4 mm 		<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x 	<b>X08218-01</b> 60516700 	<b>X06719-01</b> 4x 60534228  <b>X06718-01</b> <sup>11</sup> 116003016501  <b>X08219-01</b> <sup>11</sup> 	<b>X06707-01</b> 2x 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM
1,3 AR 30160	51 kW (69 PS)	ALFASUD	01/79-09/84			<b>H07311-00</b> 60709171 82 Ø <b>H80657-00</b> 76 Ø 1,4 mm 		<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x 	<b>X06719-01</b> 4x 60534228 	<b>X06707-01</b> 4x 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM	

ALFA ROMEO																	
1,3 Ltr.			<b>1</b>														
1,3 AR 30164 AR 30168 AR 30180 AR 30184	48-63 kW (65-86 PS)	ALFASUD ARNA 33	09/76-12/89	<b>S31133-00</b> <sup>12</sup> <sup>13</sup> 60750541 <b>D31133-00</b> <sup>12</sup> 60860486	<b>H06779-00</b> 60581645 81 Ø 	2x	<b>X06740-01</b> 60515689 Kork 	2x	<b>N92000-00</b> 60535949 (x4) <b>P76544-00</b> 4830224	8x	<b>X06750-01</b> 60503077  <b>X06763-01</b> 60523705 	2x	<b>X06751-01</b> 60502984 	4x	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01</b> K ← 60502891 40x56x10 B RD ACM <b>P76269-01</b> K → 60502893 62x80x12 A LD ACM <b>P76106-01</b> N 60502913 35x58x10 A SL RD ACM	2x
1,3 AR 30502 AR 30586 AR 31010	55-63 kW (75-86 PS)	ARNA 33	03/83-12/89	<b>S31134-00</b> <sup>12</sup> <sup>13</sup> 60778163 <b>D31134-00</b> <sup>12</sup> 60778162	<b>H06777-00</b> 60591811 85 Ø 	2x	<b>X06740-01</b> 60515689 Kork 	2x	<b>N92000-00</b> 60535949 (x4) <b>P76544-00</b> 4830224	8x	<b>X06750-01</b> 60503077  <b>X06763-01</b> 60523705 	2x	<b>X06751-01</b> 60502984 	4x	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01</b> K ← 60502891 40x56x10 B RD ACM <b>P76269-01</b> K → 60502893 62x80x12 A LD ACM <b>P76106-01</b> N 60502913 35x58x10 A SL RD ACM	2x
1,3 AR 30587	63 kW (86 PS)	33	10/84-12/89	<b>S31991-00</b> <sup>12</sup> <sup>13</sup> 60778768 <b>D31991-00</b> <sup>12</sup> 60750652 <b>B31991-00</b> <sup>13</sup>	<b>H06779-00</b> 60581645 81 Ø 	2x	<b>X06740-01</b> 60515689 Kork 	2x	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	8x	<b>X55480-01</b> 60524717 	2x	<b>X06751-01</b> 60502984 	4x	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01</b> K ← 60502891 40x56x10 B RD ACM <b>P76269-01</b> K → 60502893 62x80x12 A LD ACM <b>P76106-01</b> N 60502913 35x58x10 A SL RD ACM	2x
1,3 199 A3.000	66 kW (90 PS)	MITO JTDM	09/08→	<b>D37062-01</b> <sup>12</sup> 71744288  <b>B37062-00</b> <sup>13</sup> 71744287 	<b>H08120-00</b> 55209070 70,5 Ø 0,72 mm MLS <b>H18120-10</b> 55209071 70,5 Ø 0,82 mm 1 MLS <b>H28120-20</b> 55209072 70,5 Ø 0,92 mm 2 MLS 	<b>T08128-00</b>  RIBE	<b>X83008-01</b> 73500063 Metall 	<b>N92990-00</b> 46556651 (16x) <b>P76662-00</b> 46556651	16x	<b>X59540-01</b> 71749369 	4x	<b>X81490-01</b> 73500058 	<b>70-31414-10</b> 	<b>P77355-01</b> K ← 55186757 40x52x7 AB SL RD ACM FPM <b>P77340-01</b> K → 55180937 78x100x9 A SL LD PTFE			

ALFA ROMEO													
Ltr.													
1,3 199 B1.000 199 B4.000	62-70 kW (84-95 PS) MITO MITO JTDM	10/09→	<b>D38343-00</b> ⑫ 71753908  <b>B38343-00</b> ⑬ 71753767 	<b>H08120-00</b> 55209070 70,5 Ø 0,72 mm MLS <b>H18120-10</b> 55209071 70,5 Ø 0,82 mm 1 MLS <b>H28120-20</b> 55209072 70,5 Ø 0,92 mm 2 MLS 	<b>T08128-00</b>  RIBE	<b>X83008-01</b> 73500063 Metall 	<b>N92990-00</b> 46556651 (16x) <b>P76662-00</b> 46556651	<b>X59540-01</b> 71749369 16x 	4x	<b>X81490-01</b> 73500058 	<b>70-31414-10</b> 	<b>P77355-01 K</b> ← 55186757 40x52x7 AB SL RD ACM FPM <b>P77340-01 K</b> → 55180937 78x100x9 A SL LD PTFE	
1,3 <b>[NEW]</b> 199 B8.000	59 kW (80 PS)		<b>D38343-00</b> ⑫ 71753908  <b>B38343-00</b> ⑬ 71753767 	<b>H08120-00</b> 55209070 70,5 Ø 0,72 mm MLS <b>H18120-10</b> 55209071 70,5 Ø 0,82 mm 1 MLS <b>H28120-20</b> 55209072 70,5 Ø 0,92 mm 2 MLS 	<b>T08128-00</b>  RIBE	<b>X83008-01</b> 73500063 Metall 	<b>N92990-00</b> 46556651 (16x) <b>P76662-00</b> 46556651	<b>X59540-01</b> 71749369 16x 		<b>X81490-01</b> 73500058 	<b>70-31414-10</b> 	<b>P77355-01 K</b> ← 55186757 40x52x7 AB SL RD ACM FPM <b>P77340-01 K</b> → 55180937 78x100x9 A SL LD PTFE	
1,4 AR 30164	55 kW (76 PS) ALFASUD	05/78-02/80	<b>S31133-00</b> ⑫ ⑬ 60750541 <b>D31133-00</b> ⑫ 60860486	<b>H06779-00</b> 2x 60581645 81 Ø 	<b>T08128-00</b>  RIBE	<b>X06740-01</b> 2x 60515689 Kork 	<b>N92000-00</b> 60535949 (x4) <b>P76544-00</b> 4830224	<b>X06750-01</b> 2x 60503077 8x  <b>X06763-01</b> 2x 60523705 		<b>X06751-01</b> 4x 60502984 	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01 K</b> ← 60502891 40x56x10 B RD ACM <b>P76269-01 K</b> → 60502893 62x80x12 A LD ACM <b>P76106-01 N</b> 2x 60502913 35x58x10 A SL RD ACM	
1,4 AR 30587	66 kW (90 PS) 33	01/84-12/88	<b>S31991-00</b> ⑫ ⑬ 60778768 <b>D31991-00</b> ⑫ 60750652 <b>B31991-00</b> ⑬	<b>H06779-00</b> 2x 60581645 81 Ø 	<b>T08128-00</b>  RIBE	<b>X06740-01</b> 2x 60515689 Kork 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	<b>X55480-01</b> 2x 60524717 8x 		<b>X06751-01</b> 4x 60502984 	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01 K</b> ← 60502891 40x56x10 B RD ACM <b>P76269-01 K</b> → 60502893 62x80x12 A LD ACM <b>P76106-01 N</b> 2x 60502913 35x58x10 A SL RD ACM	

ALFA ROMEO														
Ltr.														
1,4 AR 33503 AR 38501	76 kW (103 PS)	145 16V 146 16V	→3174686 →0165088	11/96-01/01	<b>S32900-00</b> ⑫ ⑬ 71711736 <b>D32900-00</b> ⑫ 71711735 <b>B32904-00</b> ⑬ 71730148 +71718365	<b>H50996-00</b> 60616864 83 Ø 	<b>T50996-00</b> 60665425 (10x) 	<b>V32900-00</b> 60607218 +60607219 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	16x <b>X58939-01</b> 60621381 		<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P76443-01 N</b> 55x68x8 A SL RD FPM <b>P77059-01 N</b> 30x42x6 RD FPM
1,4 AR 33503 AR 38501	76 kW (103 PS)	145 16V 146 16V	3174687→ 0165089→	11/96-01/01	<b>S36385-00</b> ⑫ ⑬ 71713630 <b>D36385-00</b> ⑫ 71713629 <b>B32904-00</b> ⑬ 71730148 +71718365	<b>H50996-00</b> 60616864 83 Ø 	<b>T50996-00</b> 60665425 (10x) 	<b>X53710-01</b> 60655592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	16x <b>X58939-01</b> 60621381 		<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P76443-01 N</b> 55x68x8 A SL RD FPM <b>P77059-01 N</b> 30x42x6 RD FPM
1,4 198 A1.000 940 A6.000 <b>[NEW]</b>	85-110 kW (116-150 PS)	GIULIETTA (940) MITO (955)		09/08→	<b>D37193-00</b> ⑫ 71749165 <b>B36892-00</b> ⑬ 71728839	<b>H80779-00</b> 55206232 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>X53735-01</b> 55194045 	<b>N92004-00</b> 46470334 (16x) <b>P76809-00</b> 46470334	16x <b>M37193-00</b> 77364551 		<b>X82037-01</b> 55210321 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM <b>P77108-01 N</b> 55195339 40x55x7 AB SL RD FPM
1,4 198 A4.000	88 kW (120 PS)	GIULIETTA GIULIETTA (940) MITO		09/08→	<b>D37193-00</b> ⑫ 71749165 <b>B36889-00</b> ⑬	<b>H80779-00</b> 55206232 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>X53735-01</b> 55194045 	<b>N92991-01</b> 46470334 (16x) <b>P76809-00</b> 46470334	16x <b>M37193-00</b> 77364551 		<b>X82037-01</b> 55210321 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM <b>P77108-01 N</b> 55195339 40x55x7 AB SL RD FPM
1,4 199 A8.000	114 kW (155 PS)	MITO		09/08→	<b>D37193-00</b> ⑫ 71749165 <b>B36889-00</b> ⑬	<b>H80779-00</b> 55206232 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>X53735-01</b> 55194045 		<b>M37193-00</b> 77364551 		<b>X82037-01</b> 55210321 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM
1,4 350 A1.000 955 A9.000	51-57 kW (69-78 PS)	MITO		03/11→	<b>D36972-00</b> ⑫ 71740655 <b>B36892-00</b> ⑬ 71728839	<b>H80651-00</b> 55183371 72 Ø MLS 	<b>T03969-00</b> 7696197 (10x) 	<b>V83092-00</b> 71740678 +71740677 (4x) 	<b>N92991-02</b> 46470334 (8x) <b>P76809-00</b> 46470334	8x <b>M36901-00</b> 77363787 		<b>X51429-01</b> 7749711 	2x <b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77152-01 K</b> → 71754491 74x88x8 AB SL LD FPM <b>P77108-01 N</b> 55195339 40x55x7 AB SL RD FPM

ALFA ROMEO													
Ltr.													
1,4 940 A2.000 955 A2.000 955 A7.000	99-125 kW (135-170 PS)	MITO	10/09→	<b>D80779-01</b> <sup>12</sup> <b>B38540-00</b> <sup>13</sup> <sup>35</sup> 	<b>H80779-00</b> 55206232 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>V59762-00 0</b> 55233643 +55233644 (4x)  <b>X53735-01 U</b> 55194045 	<b>N92991-01</b> 46470334 (16X) <b>P76809-00</b> 46470334 16x	<b>M37193-00</b> 77364551 16x	<b>X59813-01</b> 55225376 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM <b>P77408-01 N</b> 55189997 31x55x7 AB SL RD FPM	
1,4 940 B1.000	77 kW (105 PS)	GIULIETTA (940)	04/11→	<b>D37193-00</b> <sup>12</sup> 71749165 <b>B36892-00</b> <sup>13</sup> 71728839	<b>H80779-00</b> 55206232 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>X53735-01</b> 55194045 	<b>N92991-01</b> 46470334 (16X) <b>P76809-00</b> 46470334 16x	<b>M37193-00</b> 77364551 16x	<b>X82037-01</b> 55210321 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM <b>P77108-01 N</b> 55195339 40x55x7 AB SL RD FPM	
1,4 940 B7.000 940 B8.000 <b>[NEW]</b>	77-88 kW (105-120 PS)	GIULIETTA (940)	04/10→	<b>D37193-00</b> <sup>12</sup> 71749165 <b>B36892-00</b> <sup>13</sup> 71728839	<b>H80779-00</b> 55206232 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>X53735-01</b> 55194045 	<b>N92990-00</b> 46556651 (16x) <b>P76809-00</b> 46470334 16x	<b>M37193-00</b> 77364551 	<b>X82037-01</b> 55210321 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM <b>P77108-01 N</b> 55195339 40x55x7 AB SL RD FPM	
1,4 955 A1.000	57-58 kW (78 PS)	MITO	09/08→	<b>D38709-00</b> <sup>12</sup> 71745446 <b>B36889-00</b> <sup>13</sup>	<b>H80695-00</b> 55202800 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>X53735-01</b> 55194045 	<b>N92991-01</b> 46470334 (16X) <b>P76809-00</b> 46470334 16x	<b>M38528-00</b> 77364149 	<b>X52653-01</b> 46526271 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM <b>P77108-01 N</b> 55195339 40x55x7 AB SL RD FPM	
1,4 955 A6.000	77 kW (105 PS)	MITO	08/10→	<b>D80695-00</b> <sup>12</sup> <b>B38540-00</b> <sup>13</sup> <sup>35</sup> 	<b>H80695-00</b> 55202800 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>V59762-00 0</b> 55233643 +55233644 (4x)  <b>X53735-01 U</b> 55194045 	<b>N92991-01</b> 46470334 (16X) <b>P76809-00</b> 46470334 16x	<b>M36889-00</b> 71739944 16x	<b>X52653-01</b> 46526271 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM <b>P77408-01 N</b> 55189997 31x55x7 AB SL RD FPM	

ALFA ROMEO																
Ltr.																
1,4 955 A8.000 <b>[NEW]</b>	120 kW (163 PS)	GIULIETTA (940) MITO (955)	10/09→		<b>H80779-00</b> 55206232 73 Ø MLS 	<b>T50944-00</b> 7795992 (10x) 	<b>V59762-00</b> 55233643 +55233644 (4x) 	<b>N92990-00</b> 46556651 (16x)	<b>M37193-00</b> 77364551 		<b>X59813-01</b> 55225376 	<b>70-31414-10</b> 	<b>P77405-01 K</b> ← 71740681 27x37x7 AB RD FPM <b>P77406-01 K</b> → 46539824 FPM <b>P77408-01 N</b> 55189997 31x55x7 AB SL RD FPM			
1,5 AR 30124 AR 30128	61-70 kW (83-95 PS)	ALFASUD	05/78-01/87	<b>S31134-00</b> <sup>12</sup> <sup>13</sup> 60778163 <b>D31134-00</b> <sup>12</sup> 60778162	<b>H06777-00</b> 60591811 85 Ø 	2x	<b>X06740-01</b> 60515689 Kork 	2x	<b>N92000-00</b> 60535949 (x4) <b>P76544-00</b> 4830224	8x	<b>X06750-01</b> 60503077 	2x	<b>X06751-01</b> 60502984	4x	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01 K</b> ← 60502891 40x56x10 B RD ACM <b>P76269-01 K</b> → 60502893 62x80x12 A LD ACM <b>P76106-01 N</b> 2x 60502913 35x58x10 A SL RD ACM
1,5 AR 30143 AR 30146 AR 30504 AR 30508 AR 30514 AR 30588	62-77 kW (84-105 PS)	ALFASUD 33	01/80-12/89	<b>S31390-00</b> <sup>12</sup> <sup>13</sup> 60778167 <b>D31390-00</b> <sup>12</sup> 60778166	<b>H06778-00</b> 60591809 88 Ø 	2x	<b>X06740-01</b> 60515689 Kork 	2x	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	8x	<b>X55480-01</b> 60524717 	2x	<b>X06751-01</b> 60502984	4x	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01 K</b> ← 60502891 40x56x10 B RD ACM <b>P76269-01 K</b> → 60502893 62x80x12 A LD ACM <b>P76106-01 N</b> 2x 60502913 35x58x10 A SL RD ACM
1,5 AR 30182 AR 30520	66-70 kW (90-95 PS)	ARNA 33	05/83-12/93	<b>S31992-00</b> <sup>12</sup> <sup>13</sup> 60778163 <b>D31992-00</b> <sup>12</sup> 60591811 <b>B31991-00</b> <sup>13</sup>	<b>H06777-00</b> 60591811 85 Ø 	2x	<b>X06740-01</b> 60515689 Kork 	2x	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	8x	<b>X55480-01</b> 60524717 	2x	<b>X06751-01</b> 60502984	2x	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01 K</b> ← 60502891 40x56x10 B RD ACM <b>P76269-01 K</b> → 60502893 62x80x12 A LD ACM <b>P76106-01 N</b> 2x 60502913 35x58x10 A SL RD ACM
1,6 AR 00526 AR 00536 AR 01600 AR 06100 AR 61101	71-81 kW (97-110 PS)	ALFETTA GIULIA GIULIETTA GT SPIDER 75	06/64-02/92	<b>S31126-00</b> <sup>12</sup> <sup>13</sup> 60735226 <b>D31126-00</b> <sup>12</sup> 0060778182 <b>R31126-00</b> <sup>3</sup> 0060015503	<b>H08248-00</b> 60567018 80 Ø 		<b>X06739-01</b> 60534664 		<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x	<b>X06706-01</b> 60558501 		<b>X06719-01</b> 60534228 	4x	<b>X06707-01</b> 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM

ALFA ROMEO														
Ltr.				1										
1,6 AR 321.02	88kW (120PS) 156 16V			09/97-05/06		<b>H50764-00</b> 60812490 	<b>T50764-00</b> 7710582 (10x) 	<b>X53710-01</b> 60655592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 	<b>X58336-01</b> 60659747 16x 		<b>X51965-01</b> 60611531 	<b>731414</b> 	<b>P76444-01 K</b> ← 7628850 31X41X7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 <b>P76063-01 N</b> 30X42X7 A SL RD FPM <b>P76443-01 N</b> 50X68X8 AB SL RD FPM
1,6 AR 32103 AR 32104	88 kW (120 PS) 147 16V 156 16V			09/97-03/10	<b>D36388-00</b> <sup>12</sup> 71717685	<b>H80426-00</b> 60664642 84 Ø MLS 	<b>T50996-00</b> 60665425 (10x)  RIBE	<b>X53710-01</b> 60655592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 	<b>X58336-01</b> 60659747 16x 		<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM
1,6 AR 37203	77 kW (105 PS) 147 16V			01/01-03/10	<b>D36636-00</b> <sup>12</sup> 71717683	<b>H80426-00</b> 60664642 84 Ø MLS 	<b>T50996-00</b> 60665425 (10x)  RIBE	<b>X53710-01</b> 60655592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 	<b>X58939-01</b> 60621381 16x 		<b>X51965-01</b> 60611531 		<b>P76063-11 N</b> 2x 40004400 30x42x7 A SL RD FPM
1,6 AR 382.01 AR 676.01	88kW (120PS) 145 16V 146 16V 156 16V	→3174686 →0165087 →0084339		12/96-05/06	<b>S32901-00</b> 71711024 <b>D32901-00</b> 71711023	<b>H50764-00</b> 60812490 	<b>T50764-00</b> 7710582 (10x) 	<b>V32900-00</b> 60607218 +60607219 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 	<b>X58336-01</b> 60659747 16x 		<b>X51965-01</b> 60611531 	<b>731414</b> 	<b>P76444-01 K</b> ← 7628850 31X41X7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 <b>P76063-01 N</b> 30X42X7 A SL RD FPM <b>P76443-01 N</b> 50X68X8 AB SL RD FPM
1,6 AR 382.01 AR 676.01	88kW (120PS) 145 16V 146 16V 156 16V	3174687→ 0165088→ 0084340→		12/96-05/06		<b>H50764-00</b> 60812490 	<b>T50764-00</b> 7710582 (10x) 	<b>X53710-01</b> 60655592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 	<b>X58336-01</b> 60659747 16x 		<b>X51965-01</b> 60611531 	<b>731414</b> 	<b>P76444-01 K</b> ← 7628850 31X41X7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 <b>P76063-01 N</b> 30X42X7 A SL RD FPM <b>P76443-01 N</b> 50X68X8 AB SL RD FPM

ALFA ROMEO													
Ltr.													
1,6 AR 676.01	88kW (120PS) 155 16V		05/96-12/97	<b>S32901-00</b> 71711024 <b>D32901-00</b> 71711023	<b>H50764-00</b> 60812490 	<b>T50764-00</b> 7710582 (10x) 	<b>V32900-00</b> 60607218 +60607219 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	<b>X58336-01</b> 60659747 16x 	<b>X51965-01</b> 60611531 	<b>731414</b> 	<b>P76444-01 K</b> ← 7628850 31X41X7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 <b>P76063-01 N</b> 30X42X7 A SL RD FPM <b>P76443-01 N</b> 50X68X8 AB SL RD FPM	
1,6 198 A2.000 940 A3.000 955 A3.000	77-88 kW (105-120 PS)	MITO JTDM	09/08→	<b>D59714-01</b> <sup>12</sup> 71769839  <b>B38531-00</b> <sup>13 35</sup> 71753736 +71718365 	<b>H40656-00</b> 55221093 80,5 Ø 0,82 mm 0 MLS <b>H40656-10</b> 55221094 80,5 Ø 0,92 mm 1 MLS <b>H40656-20</b> 55221095 80,5 Ø 1,02 mm 2 MLS 	<b>T38336-00</b> 55214378 (10X)  RIBE	<b>X59714-01</b> 55205111 	<b>N93126-00</b> 55183812 (16x) <b>P76812-00</b> 55183812	<b>M59515-00</b> 71754211 16x 	<b>X59732-01</b> 55210879  <b>X59721-01</b> 55206838 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77404-01 N</b> 46802577 30x45x7 AB SL RD NBR	
1,6 <b>[NEW]</b> 955 A4.000	85 kW (115 PS)	MITO (955)	09/08→	<b>D59714-01</b> <sup>12</sup> 71769839  <b>B38531-00</b> <sup>13 35</sup> 71753736 +71718365 	<b>H40656-00</b> 55221093 80,5 Ø 0,82 mm 0 MLS <b>H40656-10</b> 55221094 80,5 Ø 0,92 mm 1 MLS <b>H40656-20</b> 55221095 80,5 Ø 1,02 mm 2 MLS 	<b>T08135-00</b> 55214216 (10x)  RIBE	<b>X59714-01</b> 55205111 	<b>N93126-00</b> 55183812 (16x) <b>P76812-00</b> 55183812	<b>M59515-00</b> 71754211 16x 	<b>X59732-01</b> 55210879 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77404-01 N</b> 46802577 30x45x7 AB SL RD NBR	
1,7 AR 30550 AR 30558 AR 30736 AR 30737 AR 30737 A	77-95 kW (105-129 PS) 33	ALFASUD	01/86-09/94	<b>S31390-00</b> <sup>12 13</sup> 60778167 <b>D31390-00</b> <sup>12</sup> 60778166	<b>H06778-00</b> 2x 60591809 88 Ø 	<b>X06740-01</b> 2x 60515689 Kork  <b>X06744-01</b> 2x 132842 Nylon 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	<b>X55480-01</b> 2x 60524717 8x 	<b>X06751-01</b> 4x 60502984 	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01 K</b> ← 60502891 40x56x10 B RD ACM <b>P76269-01 K</b> → 60502893 62x80x12 A LD ACM <b>P76106-01 N</b> 2x 60502913 35x58x10 A SL RD ACM		



ALFA ROMEO																
Ltr.			<b>1</b>													
1,7 AR 30746 AR 30747 AR 33401	95-101 kW (129-137 PS)	145 16V 146 16V 33 16V	01/90-12/96	<b>S31997-00</b> ⑫ ⑬ 60755077 <b>D31997-00</b> ⑫ <b>B31997-00</b> ⑬	<b>H50270-00</b> 60525822 88 Ø 	2x	<b>X53058-01 R</b> 60542965 NBR 	<b>X53059-01 L</b> 60525316 NBR 	<b>N91190-00</b> <b>P76532-00</b> 4357028	2x 16x	<b>X51421-01</b> 60546397 	4x	<b>X51447-01</b> 	4x	<b>X06743-01</b> 60570142 Kork 	<b>P76118-01 K</b> ← 60502891 40x56x10 B RD ACM <b>P76269-01 K</b> → 60502893 62x80x12 A LD ACM <b>P76066-01 N</b> 4x 60576823 25x47x10 RD FPM
1,7 AR 67103 AR 67105	83-85 kW (113-115 PS)	155	04/93-04/96	<b>S32902-00</b> ⑫ ⑬ 60777616 <b>D32902-00</b> ⑫ 60777615 <b>B32902-00</b> ⑬	<b>H80021-00</b> 60609156 85 Ø 	<b>T80020-00</b> 7712674 (10x) 	<b>X53282-01</b> 60609159 NBR 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	8x	<b>X58959-01</b> 60558505 	<b>X06975-01</b> 60507576 	4x	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76374-01 K</b> → 60811338 84x105x12 A LD FPM			
1,7 AR 67106	103 kW (140 PS)	155 16V	05/96-12/97	<b>S32901-00</b> ⑫ ⑬ 71711024 <b>D32901-00</b> ⑫ 71711023 <b>B32900-00</b> ⑬ 71730148	<b>H50764-00</b> 60812490 83 Ø 	<b>T50764-00</b> 7710582 (10x) 	<b>V32900-00</b> 60607218 +60607219 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	16x	<b>X58336-01</b> 60659747 	<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM			
1,8 AR 00548	83 kW (113 PS)	GT SPIDER 1750-2000	01/67-12/72	<b>S31124-00</b> ⑫ ⑬ 116447901000 <b>D31124-00</b> ⑫ 60778156 <b>R31124-00</b> ③ 60506888	<b>H07311-00</b> 60709171 82 Ø 	<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x	<b>X08218-01</b> 60516700 	<b>X06719-01</b> 60534228 	<b>X06718-01</b> 116003016501 <b>X08219-01</b>	4x 2x	<b>X06707-01</b> 96411879 	<b>X54829-01</b> (1) 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM	
1,8 AR 01354	110 kW (150 PS)	GIULIETTA Turbo	01/84-12/85	<b>S31139-00</b> ⑫ ⑬ 161447901000 <b>D31139-00</b> ⑫ 60778169 <b>R31124-00</b> ③ 60506888	<b>H06180-00</b> 60593329 82 Ø 	<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x	<b>X06389-01</b> 60558500 	<b>X06719-01</b> 60534228 	4x	<b>X06707-01</b> 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76374-01 K</b> → 60811338 84x105x12 A LD FPM			

ALFA ROMEO													
Ltr.													
1,8 AR 01608 AR 01608 X	85-89 kW (116-121 PS)	ALFETTA	01/74-12/84	<b>S31124-00</b> ⑫ ⑬ 116447901000 <b>D31124-00</b> ⑫ 60778156 <b>R31124-00</b> ③ 60506888	<b>H07311-00</b> 60709171 82 Ø 		<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x <b>X08218-01</b> 60516700 		<b>X06719-01</b> 60534228  <b>X06718-01</b> ⓐ 116003016501  <b>X08219-01</b> ⓐ 	4x <b>X06707-01</b> 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM
1,8 AR 01678	90 kW (122 PS)	ALFETTA GIULIETTA	04/79-04/85	<b>S31124-00</b> ⑫ ⑬ 116447901000 →12/82 <b>S31138-00</b> ⑫ ⑬ 60778180 01/83→ <b>D31124-00</b> ⑫ 60778156 →12/82 <b>D31138-00</b> ⑫ 60778158 01/83→ <b>R31124-00</b> ③ 60506888	<b>H07311-00</b> 60709171 82 Ø 		<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x <b>X08218-01</b> 60516700 →12/82 <b>X06706-01</b> 60558501 01/83→ 		<b>X06719-01</b> 60534228  <b>X08219-01</b> ⓐ →12/82  <b>X06718-01</b> ⓐ 116003016501 	4x <b>X06707-01</b> 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM <b>P76374-01 N</b> 60811338 84x105x12 A LD FPM
1,8 AR 06168	88 kW (120 PS)	75	09/88-02/92	<b>S31688-00</b> ⑫ ⑬ 60778172 <b>D31688-00</b> ⑫ 60778182 <b>B31688-00</b> ⑬ <b>R31391-00</b> ③ 60515503	<b>H07311-00</b> 60709171 82 Ø 		<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x <b>X06389-01</b> 60558500 		<b>X06719-01</b> 60534228  <b>X06718-01</b> ⓐ 116003016501 	4x <b>X06707-01</b> 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM
1,8 AR 06202	85-89 kW (116-121 PS)	75 90	10/84-06/89	<b>S31138-00</b> ⑫ ⑬ 60778180 <b>D31138-00</b> ⑫ 60778158 <b>R31124-00</b> ③ 60506888	<b>H07311-00</b> 60709171 82 Ø 		<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108	4x <b>X06706-01</b> 60558501 		<b>X06719-01</b> 60534228  <b>X06718-01</b> ⓐ 116003016501 	4x <b>X06707-01</b> 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM <b>P76374-01 N</b> 60811338 84x105x12 A LD FPM
1,8 AR 32201 AR 32205	103-106 kW (140-144 PS)	GT TS GTV 16V SPIDER 16V 145 16V 146 16V 156 16V	09/97-09/10	<b>S36386-00</b> ⑫ ⑬ 71713632 <b>D36386-00</b> ⑫ 71713631 <b>B32900-00</b> ⑬ 71730148	<b>H50764-00</b> 60812490 83 Ø 	<b>T50764-00</b> 7710582 (10x) 	<b>X53710-01</b> 60555592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	16x <b>X58336-01</b> 60659747 		<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM

ALFA ROMEO														
1.8 AR 38401	103 kW (140 PS)	145 16V 146 16V	11/96-01/01	<b>S32901-00</b> <sup>12</sup> <sup>13</sup> 71711024 <b>D32901-00</b> <sup>12</sup> 71711023 <b>B32900-00</b> <sup>13</sup> 71730148	<b>H50764-00</b> 60812490 83 Ø 	<b>T50764-00</b> 7710582 (10x) 	<b>V32900-00</b> 60607218 +60607219 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 16x	<b>X51965-01</b> 60611531 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM				
1.8 AR 61102 AR 61201	88-90 kW (120-122 PS)	75	09/88-02/92	<b>S31126-00</b> <sup>12</sup> <sup>13</sup> 60735226 <b>D31126-00</b> <sup>12</sup> 0060778182 <b>R31126-00</b> <sup>3</sup> 0060015503	<b>H08248-00</b> 60567018 80 Ø 		<b>X06739-01</b> 60534664 	<b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108 4x	<b>X06706-01</b> 60558501 4x 	<b>X06719-01</b> 60534228 4x <b>X06718-01</b> 116003016501 2x	<b>X06707-01</b> 96411879 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01 K</b> → 60517110 82x105x12 A LD FPM		
1.8 AR 67101 AR 67102	93-95 kW (127-129 PS)	155	01/92-12/96	<b>S32902-00</b> <sup>12</sup> <sup>13</sup> 60777616 <b>D32902-00</b> <sup>12</sup> 60777615 <b>B32902-00</b> <sup>13</sup>	<b>H80021-00</b> 60609156 85 Ø 	<b>T80020-00</b> 7712674 (10x) 	<b>X53282-01</b> 60609159 NBR 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637 8x	<b>X58959-01</b> 60558505 8x 	<b>X06975-01</b> 60507576 4x 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76374-01 K</b> → 60811338 84x105x12 A LD FPM			
1.8 AR 67106	103 kW (140 PS)	145 16V 146 16V	11/96-01/01	<b>S32901-00</b> <sup>12</sup> <sup>13</sup> 71711024 <b>D32901-00</b> <sup>12</sup> 71711023 <b>B32900-00</b> <sup>13</sup> 71730148	<b>H50764-00</b> 60812490 83 Ø 	<b>T50764-00</b> 7710582 (10x) 	<b>V32900-00</b> 60607218 +60607219 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 16x	<b>X58336-01</b> 60659747 16x 	<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM		
1.8 VM 82 A VM 96 A	54-62 kW (73-84 PS)	33 TD	01/86-09/94	<b>S31392-00</b> <sup>13</sup> 60778052  <b>D31392-00</b> 60778051  <b>R31392-00</b> <sup>3</sup>	<b>H06780-00</b> 60605900 1,42 mm <b>H16780-10</b> 60605899 1,52 mm 2 <b>H26780-20</b> 60605898 98,5 Ø 1,62 mm 1 <b>R31392-00</b> <sup>3</sup>	<b>T06780-00</b> 3x 	<b>X53110-01</b> 60778568 		<b>X06894-01</b> 116760160100 3x 	<b>X06781-01</b> 116760170403 3x <b>X06837-01</b> 116760179903	<b>P76194-01 K</b> ← 52x68x10 A SL RD <b>P76391-01 K</b> → 1054053 110x130x12,7 B SL LD FPM			

ALFA ROMEO													
Ltr.													
1,8 939 B1.000 940 A1.000	147-177 kW (200-241 PS)	BRERA SPIDER 159	05/09→		<b>H40664-00</b> 55215398 MLS 	<b>T40664-00</b> 55214072 (10x) 	<b>70-31414-10</b> 		<b>M38527-00</b> 77365293 		<b>X59790-01</b> 55214576 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77108-01 N</b> 2x 55195339 40x55x7 AB SL RD FPM
1,9 AR 32302	77 kW (105 PS)	145 JTD 146 JTD 156 JTD	09/97-01/01	<b>S32911-00</b> <sup>12</sup> <sup>13</sup> 71712830  <b>D32911-00</b> <sup>12</sup> 71712831  <b>B32911-00</b> <sup>13</sup> 	<b>H03637-00</b> 60814599 1,6 mm MLS <b>H13637-10</b> 60814600 1,7 mm 1 MLS <b>H23637-20</b> 60814601 83 Ø 1,8 mm 2 MLS 	<b>T03925-00</b> 7775920 (10x) 	<b>X53554-01</b> 7737607 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	<b>X58963-01</b> 71738458 8x 		<b>X51966-01</b> 46467747 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM
1,9 AR 33601 AR 67501	66 kW (90 PS)	145 TD 146 TD 155 TD	04/93-02/99	<b>S31218-00</b> <sup>12</sup> <sup>13</sup> 5892422  <b>D31218-00</b> <sup>12</sup>  <b>B31218-00</b> <sup>13</sup> 	<b>H00592-00</b> 1,65 mm <b>H08006-00</b> 60812121 1,67 mm MLS <b>H10592-10</b> 1,8 mm 1 <b>H18006-10</b> 60812122 1,75 mm 1 MLS <b>H20592-20</b> 83,2 Ø 1,95 mm 2  <b>H28006-20</b> 60812123 1,85 mm 2 MLS <b>H38006-30</b> 60812124 83,5 Ø 1,95 mm 3 MLS 	<b>T05055-00</b> 7653650 (10x) 	<b>X05059-01</b> 4394109 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	8x	<b>X85522-01</b> <sup>7</sup> 464662772 		<b>X05073-01</b> 5959226 Kork  <b>X54008-01</b> 7647596 Gummi 	<b>P76243-01 K</b> ← 40004260 30x43x8 AB SL RD FPM <b>P76313-11 K</b> → 40004300 74x90x10 AB SL LD FPM <b>P76060-01 N</b> 40004940 30x52x7 AB SL RD FPM





ALFA ROMEO													
1,9 939 A7.000	85 kW (115 PS)	147 JTDM 159 JTDM	10/04-11/11	<p><b>D37068-00</b> ⑫ 71718658 Mot.→4081110</p> <p><b>D37069-00</b> ⑫ 71739971 Mot.4081111→</p> <p><b>B36888-00</b> ⑬ ⑳ 71730213</p>	<p><b>H07600-00</b> 60816233 0,82 mm MLS</p> <p><b>H17600-10</b> 60816234 0,92 mm 1 </p> <p><b>H27600-20</b> 60816235 83 Ø 1,02 mm 2 </p> <p>MLS</p>	<p><b>T03925-00</b> 7775920 (10x) Mot.→5693776</p> <p><b>T08135-00</b> 55214216 (10x) Mot.5693777→</p>	<p><b>X53789-01</b> 46552748 NBR Mot.→4081110</p> <p><b>X83130-01</b> 55197598 NBR Mot.4081111→</p>	<p><b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637</p>	<p><b>X58963-01</b> 71738458</p> <p>8x </p>	<p><b>X51966-01</b> 46467747</p>	<p><b>70-31414-10</b></p>	<p><b>P76444-01</b> K ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01</b> K → </p> <p>71718365 PTFE <b>P76063-11</b> N 40004400 30x42x7 A SL RD FPM</p>	
1,9 939 A8.000	100 kW (136 PS)	159 JTDM	09/05-11/11	<p><b>D37070-00</b> ⑫ 71740085 Mot.→5192515</p> <p><b>D37070-01</b> ⑫ 71753437 Mot.5192516→</p> <p><b>B37070-00</b> ⑬ 71740084</p>	<p><b>H08135-00</b> 55200890 0,82 mm MLS</p> <p><b>H18135-10</b> 55201694 0,92 mm 1 </p> <p><b>H28135-20</b> 55201695 83 Ø 1,02 mm 2 </p> <p>MLS</p>	<p><b>T08135-00</b> 55214216 (10x)</p>	<p><b>X83091-01</b> 46814174</p>	<p><b>N92003-00</b> 46743167 (16x) Mot.→5192515 <b>N93126-00</b> 55183812 (16x) Mot.5192516→ <b>P76808-00</b> 46743167 Mot.→5192515 <b>P76812-00</b> 55183812 Mot.5192516→</p>	<p><b>X87664-01</b> 46816020</p> <p>16x </p> <p>16x </p>	<p><b>X51965-01</b> 60611531</p>	<p><b>70-31414-10</b></p>	<p><b>P76444-01</b> K ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01</b> K → </p> <p>71718365 PTFE <b>P77404-01</b> N 46802577 30x45x7 AB SL RD NBR</p>	
2,0 AR 00515 AR 01544 AR 01588 AR 06212 AR 11671	85-96 kW (116-131 PS)	GIULIETTA GTV SPIDER 75 90	01/77-12/93	<p><b>S31136-00</b> ⑫ ⑬ 60777795 <b>D31136-00</b> ⑫ 60777781 <b>R31124-00</b> ③ 60506888</p>	<p><b>H06705-00</b> 60567019 85,5 Ø</p>		<p><b>X06739-01</b> 60534664</p>	<p><b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108</p>	<p><b>X06706-01</b> 60558501</p> <p>4x </p>	<p><b>X06719-01</b> 60534228 <b>X06718-01</b>  116003016501</p>	<p>4x <b>X06707-01</b> 96411879</p> <p>2x </p>	<p><b>P76101-01</b> K ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01</b> K → 60517110 82x105x12 A LD FPM</p>	
2,0 AR 01590 AR 01655 AR 01713 AR 10520	93-97 kW (126-132 PS)	ALFETTA GIULIETTA GTV SPIDER 1750-2000 90	10/71-12/93	<p><b>S31123-00</b> ⑫ ⑬ 60777956 <b>D31123-00</b> ⑫ 60777776 <b>R31124-00</b> ③ 60506888</p>	<p><b>H06705-00</b> 60567019 85,5 Ø</p>		<p><b>X06739-01</b> 60534664</p>	<p><b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108</p>	<p><b>X08218-01</b> 60516700</p> <p>4x </p>	<p><b>X06719-01</b> 60534228 <b>X06718-01</b>  116003016501</p>	<p>4x <b>X06707-01</b> 96411879</p> <p>2x </p>	<p><b>P76101-01</b> K ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01</b> K → 60517110 82x105x12 A LD FPM <b>P76374-01</b> K → 60811338 84x105x12 A LD FPM</p>	
2,0 AR 01615 AR 11642	81-111 kW (110-150 PS)	GTV Turbodelta SPIDER	01/74-12/84	<p><b>S31124-00</b> ⑫ ⑬ 116447901000 <b>D31124-00</b> ⑫ 60778156 <b>R31124-00</b> ③ 60506888</p>	<p><b>H07311-00</b> 60709171 82 Ø</p>		<p><b>X06739-01</b> 60534664</p>	<p><b>N92010-00</b> 60507108(x4) <b>P76602-00</b> 60507108</p>	<p><b>X08218-01</b> 60516700</p> <p>4x </p>	<p><b>X06719-01</b> 60534228 <b>X06718-01</b>  116003016501</p>	<p>4x <b>X06707-01</b> 96411879</p> <p>2x </p>	<p><b>P76101-01</b> K ← 60507107 35x50x10 A SL RD MVQ <b>P76349-01</b> K → 60517110 82x105x12 A LD FPM</p>	

ALFA ROMEO														
Ltr.				1										
2,0 AR 06166 AR 06224	107-109 kW (146-148 PS)	75	05/85-02/92	<b>S31141-00</b> ⑫ ⑬ 60778000 <b>D31141-00</b> ⑫ 60777999 <b>R31124-00</b> ③ 60506888	<b>H06542-00</b> 60560916 85 Ø 	<b>V31142-00</b> 60513316  <b>X06973-01</b> 006051331600  <b>X06976-01</b> 3x 006051331100 NBR 	<b>N92940-00</b> <b>P76602-00</b> 60507108	8x <b>X06974-01</b> 60558499 		<b>X06975-01</b> 60507576  <b>X06718-01</b> ⚠ 116003016501 	4x <b>X06707-01</b> 96411879 	2x 	<b>P76101-01</b> K ← 60507107 35x50x10 A SL RD MVQ <b>P76374-01</b> K → 60811338 84x105x12 A LD FPM <b>P76349-01</b> N 60517110 82x105x12 A LD FPM	
2,0 AR 06210	97 kW (132 PS)	90	10/84-07/87	<b>S31132-00</b> ⑫ ⑬ 60777987 <b>D31132-00</b> ⑫ 60777988 <b>B31132-00</b> ⑬ <b>R31132-00</b> ③ 60506888	<b>H05315-00</b> R 60569895  <b>H05325-00</b> L 60569899 90 Ø 	<b>X07303-01</b> R 60808412  <b>X07307-01</b> L 60808971 	<b>N92960-00</b> <b>P76602-00</b> 60507108	2x 12x <b>X07712-01</b> 6x 60522310 		<b>X06975-01</b> 60507576 	6x <b>X06963-01</b> 96411871 		<b>P76220-01</b> K ← 48x65x10 AB SL RD FPM <b>P76374-01</b> K → 60811338 84x105x12 A LD FPM <b>P76032-01</b> N 3x 32x47x10 A RD NBR	
2,0 AR 06420	109 kW (148 PS)	164	06/87-12/90	<b>S31142-00</b> ⑫ ⑬ 60777797 <b>D31141-00</b> ⑫ 60777999 <b>R31124-00</b> ③ 60506888	<b>H06542-00</b> 60560916 85 Ø 	<b>V31142-00</b> 60513316  <b>X06973-01</b> 006051331600  <b>X06976-01</b> 3x 006051331100 NBR 	<b>N92940-00</b> <b>P76602-00</b> 60507108	8x <b>X06974-01</b> 60558499 		<b>X06975-01</b> 60507576  <b>X06718-01</b> ⚠ 116003016501 	4x 	2x 	<b>P76101-01</b> K ← 60507107 35x50x10 A SL RD MVQ <b>P76374-01</b> K → 60811338 84x105x12 A LD FPM	
2,0 AR 06476	128-129 kW (174-175 PS) 164 Turbo	164	10/87-09/98	<b>S31691-00</b> ⑫ ⑬ 6077803 →12/91 <b>D31691-00</b> ⑫ 60777804 →12/91 <b>B31972-00</b> ⑬	<b>H50125-00</b> 7709257 85 Ø →12/91 	<b>T00340-00</b> 60807357 (10x)  RIBE	<b>X00342-01</b> 2x 7660565 Kork  <b>X51145-01</b> 2x 7684064 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637	8x <b>X55012-01</b> 7700197 		<b>X04985-01</b> 4368925 	<b>X54004-01</b> 7646248 Kork 	<b>P76243-01</b> K ← 40004260 30x43x8 AB SL RD FPM <b>P76313-11</b> K → 40004300 74x90x10 AB SL LD FPM <b>P76060-01</b> N 2x 40004940 30x52x7 AB SL RD FPM	



ALFA ROMEO														
2.0 AR 16201	110 kW (150 PS)	GTV 16V SPIDER 16V	06/95-10/05	<b>S36387-00</b> ⑫ ⑬ 71711280 Mot.→581927 <b>D36387-00</b> ⑫	<b>H80022-00</b> 60608895 84 Ø 	<b>T50764-00</b> 7710582 (10x) 	<b>V32900-00</b> 60607218 +60607219 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	<b>X58336-01</b> 60659747 16x 	<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM		
2.0 AR 16202 AR 64101 AR 64102	148-150 kW (201-204 PS)	GTV V6 Turbo SPIDER V6 Turbo 164 V6 Turbo	03/91-04/05	<b>S31692-00</b> ⑫ ⑬ 60778115 <b>D31692-00</b> ⑫ 60778116 <b>B31692-00</b> ⑬	<b>H50271-00 R</b> 60566395 82 Ø  <b>H50272-00 L</b> 60566396 82 Ø 		<b>X07303-01 R</b> 60808412  <b>X07307-01 L</b> 60808971 	<b>N92960-00</b> <b>P76602-00</b> 60507108	<b>X07955-01</b> 2x 60563671 12x 	<b>X07578-01</b> 6x 60506636 	<b>X54027-01</b> 60777764 	<b>P76178-11 K</b> ← 48x65x10 A NBR <b>P76378-01 K</b> → 195460617700 90x110x12 A SL LD FPM <b>P76032-01 N</b> 2x 32x47x10 A RD NBR		
2.0 AR 32301 AR 34103	114 kW (155 PS)	GTV 16V SPIDER 16V 145 16V 146 16V 156 16V 166	09/97-06/02	<b>S32904-00</b> ⑫ ⑬ 71713634 <b>D32904-00</b> ⑫ 71713633 <b>B32904-00</b> ⑬ 71730148 +71718365	<b>H80022-00</b> 60608895 84 Ø 	<b>T50764-00</b> 7710582 (10x) 	<b>X53710-01</b> 60655592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	<b>X58336-01</b> 60659747 16x 	<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM		
2.0 AR 32310	110 kW (150 PS)	GTV 16V SPIDER 16V 147 16V 156 16V	06/95-03/10	<b>D36388-00</b> ⑫ 71717685 Mot.→2832058 <b>D36389-00</b> ⑫ Mot.2832058→ <b>B32900-00</b> ⑬ 71730148	<b>H80426-00</b> 60664642 84 Ø MLS Mot.→2832058  <b>H40562-00</b> 60677983 MLS Mot.2832058→ 	<b>T50996-00</b> 60665425 (10x) Mot.→2832058  <b>T50764-00</b> 7710582 (10x) Mot.2832058→ 	<b>X53710-01</b> 60655592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	<b>X58336-01</b> 60659747 16x 	<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM		

ALFA ROMEO												
2,0 AR 36301	110 kW (150 PS)	166	10/00-06/07	<b>S36389-00</b> <sup>12</sup> <sup>13</sup> Mot.2557365→ <b>D36388-00</b> <sup>12</sup> 71717685 Mot.→2557364 <b>D36389-00</b> <sup>12</sup> Mot.2557365→	<b>H80426-00</b> 60664642 84 Ø MLS Mot.→2557364  <b>H40562-00</b> 60677983 MLS Mot.2557365→ 	<b>T50996-00</b> 60665425 (10x) Mot.→2557364  RIBE <b>T50764-00</b> 7710582 (10x) Mot.2557365→  RIBE	<b>X53710-01</b> 60655592 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 16x 	<b>X58336-01</b> 60659747 Mot.→2557364 <b>X58939-01</b> 60621381 Mot.2557364→ 	<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM
2,0 AR 64103 AR 67201 AR 67202	104-106 kW (141-144 PS)	155 164	02/92-09/98	<b>S32902-00</b> <sup>12</sup> <sup>13</sup> 60777616 <b>D32902-00</b> <sup>12</sup> 60777615 <b>B32902-00</b> <sup>13</sup>	<b>H80021-00</b> 60609156 85 Ø 	<b>T80020-00</b> 7712674 (10x)  RIBE	<b>X53282-01</b> 60609159 NBR 	<b>N90300-00</b> 5930415 (8x) <b>P76531-00</b> 0007553637 8x 	<b>X58959-01</b> 60558505 	<b>X06975-01</b> 60507576 4x 	<b>P76101-01 K</b> ← 60507107 35x50x10 A SL RD MVQ <b>P76374-01 K</b> → 60811338 84x105x12 A LD FPM	
2,0 AR 67203	137-140 kW (186-190 PS)	155 16V Turbo	01/92-12/97	<b>S31687-00</b> <sup>12</sup> <sup>13</sup> 5893768 <b>D31687-00</b> <sup>12</sup>	<b>H50125-00</b> 7709257 85 Ø 	<b>T50125-00</b>  RIBE	<b>V38045-00</b>  <b>X53019-01</b> 1641037 NBR 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 16x 	<b>X56788-01</b> 7715139 	<b>X51004-01</b> 7700581 	<b>X54004-01</b> 7646248 Kork 	<b>P76243-01 K</b> ← 40004260 30x43x8 AB SL RD FPM <b>P76313-11 K</b> → 40004300 74x90x10 AB SL LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM
2,0 AR 67204	110 kW (150 PS)	145 16V 146 16V 155 16V	03/95-01/01	<b>S36387-00</b> <sup>12</sup> <sup>13</sup> 71711280 <b>D36387-00</b> <sup>12</sup>	<b>H80022-00</b> 60608895 84 Ø 	<b>T50764-00</b> 7710582 (10x)  RIBE	<b>V32900-00</b> 60607218 +60607219 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028 16x 	<b>X58336-01</b> 60659747 16x 	<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM
2,0 VM 4 HT VM 80 A	61-70 kW (83-95 PS)	GIULIETTA TD 75 TD	01/83-09/92	<b>S31137-00</b> <sup>13</sup> 60778053  <b>D31137-00</b> 11676015080001  <b>B31137-00</b> <b>R31392-00</b> <sup>3</sup>	<b>H06780-00</b> 60605900 1,42 mm <b>H16780-10</b> 60605899 1,52 mm 2 <b>H26780-20</b> 60605898 98,5 Ø 1,62 mm 1 	<b>T16780-00</b>  4x  4x  4x	<b>X06933-01</b> 60583721  <b>X53589-01</b> 	<b>X06894-01</b> 116760160100 4x 	<b>X06781-01</b> 116760170403 4x 	<b>X07518-01</b> 60583722 	<b>P76194-01 K</b> ← 52x68x10 A SL RD <b>P76391-01 K</b> → 1054053 110x130x12,7 B SL LD FPM	

ALFA ROMEO												
Ltr.												
2,0 932 A2.000 937 A1.000	119-122 kW (162-166 PS)	GT GT JTS GTV JTS SPIDER JTS 147 156 156 JTS	11/97-09/10	<b>D36638-00</b> <sup>12</sup> 71737152	<b>H80438-00</b> 55187704 84 Ø MLS 	<b>V36638-00</b> 55187339 +7715492 (4x)  <b>X53205-01</b> 4x NBR  <b>X83004-01</b> 60669492 NBR 	<b>N92850-00</b> 7500716 (16x) <b>P76532-00</b> 4357028	<b>X87434-01</b> 60673137 16x 	<b>X51965-01</b> 60611531 	<b>70-31414-10</b> 	<b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM <b>P76443-01 N</b> 55x68x8 A SL RD FPM	
2,0 939 B3.000 939 B4.000 940 A4.000 940 A5.000	100-125 kW (136-170 PS)	BRERA JTDM SPIDER 159 JTDM	05/09→	<b>D59714-01</b> <sup>12</sup> 71769839  <b>B38531-00</b> <sup>13 35</sup> 71753736 +71718365 	<b>H01408-00</b> 55211409 84 Ø 0,95 mm 0 MLS <b>H11408-10</b> 55211410 84 Ø 1,05 mm 1 MLS <b>H21408-20</b> 55211411 84 Ø 1,15 mm 2 MLS 	<b>T08135-00</b> 55214216 (10x)  RIBE	<b>X59714-01</b> 55205111 	<b>N93126-00</b> 55183812 (16x) <b>P76812-00</b> 55183812	<b>M59515-00</b> 71754211 16x 	<b>X59732-01</b> 55210879  <b>X59722-01</b> 55212785 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77404-01 N</b> 46802577 30x45x7 AB SL RD NBR
2,2 939 A5.000	136 kW (185 PS)	BRERA SPIDER JTS 159 JTS	09/05-11/11	<b>D40479-00</b> <sup>12</sup> 71741258 <b>B38529-00</b> <sup>13</sup> 	<b>H40479-00</b> 55192574 	<b>T80476-00</b> 71739374 (10x)  RIBE	<b>V38106-00</b> 55189690 	<b>P76771-00</b> 16x <b>X59800-01</b> 55182628 	<b>X59799-01</b> 55193545  <b>X59798-01</b> 55183724 2x 	<b>70-31414-10</b> 	<b>P77155-01 K</b> ← 71739386 42x55x7 A SL RD FPM <b>P76384-01 K</b> → 71739336 90x104x9/11 AB SL LD FPM	
2,4 AR 32501 AR 34202	100 kW (136 PS)	156 JTD 166 JTD	09/97-09/03	<b>S32912-00</b> <sup>12 13</sup> 60814970  <b>D32912-00</b> <sup>12</sup> 60814969  <b>B32912-00</b> <sup>13</sup> 	<b>H03638-00</b> 46442435 1,65 mm MLS <b>H13638-10</b> 46442436 1,75 mm 1 MLS <b>H23638-20</b> 46442437 83 Ø 1,85 mm 2 MLS 	<b>T03926-00</b> 7775920 (12x)  RIBE	<b>X53496-01</b> 46437256 NBR 	<b>N91710-00</b> 7553637(x10) <b>P76531-00</b> 0007553637	<b>X58961-01</b> 7735415 10x 	<b>X51968-01</b> 46414437 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77145-01 K</b> → 71713041 93 LD FPM <b>P76063-11 N</b> 40004400 30x42x7 A SL RD FPM

ALFA ROMEO													
Ltr.													
2,4 VM 81 A	81-82 kW (110-112 PS)	75 TD 90 TD	10/84-02/92	<b>S31137-00</b> <sup>13</sup> 60778053  <b>D31137-00</b> 11676015080001  <b>B31137-00</b> <b>R31392-00</b> <sup>3</sup>	<b>H06780-00</b> 60605900 1,42 mm <b>H16780-10</b> 60605899 1,52 mm 2 <b>H26780-20</b> 60605898 98,5 Ø 1,62 mm 1 	4x 4x 4x	<b>T16780-00</b> 	<b>X06933-01</b> 60583721  <b>X53589-01</b> 		<b>X06894-01</b> 116760160100 4x	<b>X06781-01</b> 116760170403 4x	<b>X07518-01</b> 60583722 	<b>P76194-01 K</b> ← 52x68x10 A SL RD <b>P76391-01 K</b> → 1054053 110x130x12,7 B SL LD FPM
2,4 8144.61.200	53 kW (72 PS)	AR 6 D	04/85-02/86	<b>S36355-00</b> <sup>12</sup> <sup>13</sup> 5892433  <b>D36355-00</b> <sup>12</sup> 5892434  <b>B36355-00</b> <sup>13</sup>	<b>H07684-00</b> 5891282 95 Ø 1,9 mm 10 mm 		<b>T07684-00</b> 4828150 (12x) +48546488 (10x) 	<b>X07685-01</b> 4738019 	<b>N92430-00</b> <b>P76544-00</b> 4830224 8x			<b>X07688-01</b> 	<b>P76305-11 K</b> ← 1226734 70x90x10 A SL RD FPM <b>P76364-11 K</b> → 90x115x13/9,5 AB SL LD FPM <b>P76188-01 N</b> 50x70x10 B RD MVQ <b>P76201-11 N</b> 98454041 55x70x8 AB SL RD FPM
2,4 839 A6.000 841 C.000	103-110 kW (140-150 PS)	156 JTD 166 JTD	10/00-06/07	<b>D37075-00</b> <sup>12</sup> 71718333  <b>B37075-00</b> <sup>13</sup> 71728831	<b>H01898-00</b> 55190359 0,82 mm MLS <b>H11898-10</b> 55190360 0,92 mm 1 MLS <b>H21898-20</b> 55190361 83 Ø 1,02 mm 2 MLS 		<b>T03926-00</b> 7775920 (12x)  RIBE	<b>X83133-01</b> 46739261 NBR 	<b>N90710-01</b> <b>P76531-00</b> 0007553637 10x	<b>X58961-01</b> 7735415 	<b>X51968-01</b> 46414437 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77059-01 N</b> 30x42x6 RD FPM
2,4 841 G.000 841 H.000 841 M.000	120-136 kW (163-185 PS)	156 156 JTD 166 166 JTD	06/03-06/07	<b>D37076-00</b> <sup>12</sup> 71734259 Mot.→5192516  <b>D37077-00</b> <sup>12</sup> Mot.5192517→  <b>B37076-00</b> <sup>13</sup> 71734258	<b>H01899-00</b> 55190353 0,82 mm MLS <b>H11899-10</b> 55190354 0,92 mm 1 MLS <b>H21899-20</b> 55190355 83 Ø 1,02 mm 2 MLS 			<b>X83070-01</b> 46814175 	<b>N92011-00</b> 46743167 (20x) Mot.→5192516 <b>N92013-00</b> 55183812 (20x) Mot.5192517→ <b>P76808-00</b> 46743167 20x <b>P76812-00</b> 55183812 20x Mot.5192517→	<b>X81865-01</b> 55190771 	<b>X51435-01</b> 7772358 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77404-01 N</b> 46802577 30x45x7 AB SL RD NBR

ALFA ROMEO													
2,4 841 N.000	120 kW (163 PS)	156 166	06/03-06/07	<b>D37076-00</b> <sup>12</sup> 71734259 Mot.→5192516  <b>D37077-00</b> <sup>12</sup> Mot.5192517→  <b>B37076-00</b> <sup>13</sup> 71734258	<b>H01899-00</b> 55190353 0,82 mm MLS <b>H11899-10</b> 55190354 0,92 mm 1 MLS <b>H21899-20</b> 55190355 83 Ø 1,02 mm 2 MLS 	<b>T01897-00</b> 55214216 (12x)  RIBE	<b>X83070-01</b> 46814175 	<b>N92011-00</b> 46743167 (20x) Mot.→5192516 <b>N92013-00</b> 55183812 (20x) Mot.5192517→ <b>P76808-00</b> 46743167 20x Mot.→5192516 <b>P76812-00</b> 55183812 20x Mot.5192517→	<b>X81865-01</b> 55190771 	<b>X51435-01</b> 7772358 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77404-01 N</b> 46802577 30x45x7 AB SL RD NBR	
2,4 936 B.000	136 kW (185 PS)	166 JTD	07/05-06/07	<b>D37076-00</b> <sup>12</sup> 71734259 Mot.→5192516  <b>D37077-00</b> <sup>12</sup> Mot.5192517→  <b>B37076-00</b> <sup>13</sup> 71734258	<b>H01897-00</b> 55184740 0,95 mm MLS <b>H11897-10</b> 55184741 1,05 mm 1 MLS <b>H21897-20</b> 55184742 1,15 mm 2 MLS 	<b>T01897-00</b> 55214216 (12x)  RIBE	<b>X83070-01</b> 46814175 	<b>N92011-00</b> 46743167 (20x) Mot.→5192516 <b>N92013-00</b> 55183812 (20x) Mot.5192517→ <b>P76808-00</b> 46743167 Mot.→5192516 <b>P76812-00</b> 55183812 Mot.5192517→	<b>X81865-01</b> 55190771 	<b>X51435-01</b> 7772358 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77404-01 N</b> 46802577 30x45x7 AB SL RD NBR	
2,4 939 A3.000 939 A9.000	147-154 kW (200-210 PS)	BRERA BRERA JTDM SPIDER JTDM 159 159 JTDM	09/05-11/11	<b>D36977-00</b> 71740961 Mot.→5192516  <b>D36977-01</b> <sup>12</sup> Mot.5192517→  <b>B36977-00</b> <sup>13</sup> 71740962	<b>H01897-00</b> 55184740 0,95 mm MLS <b>H11897-10</b> 55184741 1,05 mm 1 MLS <b>H21897-20</b> 55184742 1,15 mm 2 MLS 	<b>T01897-00</b> 55214216 (12x)  RIBE	<b>X83070-01</b> 46814175 	<b>P76808-00</b> 46743167 20x Mot.→5192516 <b>P76812-00</b> 55183812 20x Mot.5192517→	<b>X81865-01</b> 55190771 	<b>X51435-01</b> 7772358 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 7628850 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → 71718365 PTFE <b>P77404-01 N</b> 46802577 30x45x7 AB SL RD NBR	
2,5 AR 01646 AR 01911 AR 01928	110-116 kW (150-158 PS)	GTV 6 75 V6 90 V6	04/79-07/87	<b>S31132-00</b> <sup>12</sup> <sup>13</sup> 60777987 <b>D31132-00</b> <sup>12</sup> 60777988 <b>B31132-00</b> <sup>13</sup> <b>R31132-00</b> <sup>3</sup> 60506888	<b>H05315-00 R</b> 60569895  <b>H05325-00 L</b> 60569899 90 Ø 		<b>X07303-01 R</b> 60808412  <b>X07307-01 L</b> 60808971 	<b>N92940-00</b> 60507108 <b>P76602-00</b> 60507108	2x 12x <b>X07712-01</b> 60522310 6x	<b>X07578-01</b> 60506636 6x	<b>X06963-01</b> 96411871 	<b>P76220-01 K</b> ← 48x65x10 AB SL RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 A LD FPM <b>P76032-01 N</b> 3x 32x47x10 ARD NBR	

ALFA ROMEO												
Ltr.    1 2,5 AR 32401 AR 32405 AR 34201 AR 36201	138-141 kW (188-192 PS)	156 V6 24V 166 V6 24V	09/97-06/07	<b>S32908-00</b> <sup>12</sup> <sup>13</sup> 71712435 <b>D32908-00</b> <sup>12</sup> 71712434 <b>B32908-00</b>	<b>H80026-00 R</b> 0060608122  <b>H80027-00 L</b> 0060584488 90 Ø 	<b>T80024-00</b>	<b>V38097-00 R</b> 60609978 +60610548  <b>V38098-00 L</b> 60609979 +60610548  <b>X53729-01 R</b> 0060609978 NBR  <b>X53730-01 L</b> 0060609979 NBR 	<b>N92920-00</b> <b>P76532-00</b> 4357028 24x	<b>X56964-01</b> 60810616 2x  <b>X88997-01</b> 60513868 6x 	<b>X52321-01</b> 60810625 6x 	<b>P77139-01 K</b> ← 0060813277 48x65x8 RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 ALD FPM	
2,5 VM 07 B VM 08 B VM 31 B VM 84 A	84-92 kW (114-125 PS)	155 TD 164 TD	06/87-09/98	<b>S31137-00</b> <sup>13</sup> 60778053  <b>D31137-00</b> 11676015080001  <b>B31137-00</b> <b>R31392-00</b> <sup>3</sup>	<b>H06780-00</b> 60605900 1,42 mm <b>H16780-10</b> 60605899 1,52 mm 2 <b>H26780-20</b> 60605898 98,5 Ø 1,62 mm 1 	4x <b>T16780-00</b>  4x 4x	<b>X06933-01</b> 60583721  <b>X53589-01</b> 	<b>X06894-01</b> 116760160100 4x 	<b>X06781-01</b> 116760170403 4x 	<b>X07518-01</b> 60583722 	<b>P76194-01 K</b> ← 52x68x10 A SL RD <b>P76391-01 K</b> → 1054053 110x130x12,7 B SL LD FPM	
2,5 VM 5 HT	77 kW (105 PS)			<b>S31393-00</b> <sup>13</sup> 119207901000  <b>D31393-00</b> 11920015080001  <b>B31393-00</b>	<b>H06780-00</b> 60605900 1,42 mm <b>H16780-10</b> 60605899 1,52 mm 2 <b>H26780-20</b> 60605898 98,5 Ø 1,62 mm 1 	5x <b>T26780-00</b> AEU2078L(x12) 5x 5x	<b>X06933-01</b> 60583721  <b>X53111-01</b> 119200145700 	<b>X06894-01</b> 116760160100 5x 	<b>X06781-01</b> 116760170403 5x  <b>X06837-01</b> <sup>13</sup> 116760179903 	<b>X54090-01</b> 119200120500 NBR 	<b>P76194-01 K</b> ← 52x68x10 A SL RD <b>P76404-01 K</b> → 110x130x13 B SL LD PTFE ACM	

ALFA ROMEO													
Ltr.													
2,5 8144.67.220	55 kW (75 PS)	AR 6 D AR 8 D	03/86-12/89	<b>S36355-00</b> ⑫ ⑬ 5892433  <b>D36355-00</b> ⑫ 5892434  <b>B36355-00</b> ⑬	<b>H06236-00</b> 7701040179 1,65 mm 13 mm <b>H16236-10</b> 7701040180 95 Ø 1,75 mm 13 mm <b>H26236-20</b> 95,2 Ø 1,85 mm 	<b>T07684-00</b> 4828150 (12x) +48546488 (10x) 	<b>X07685-01</b> 4738019 Mot.→574798  <b>X02037-01</b> 7302293 Mot.574799→ 	<b>N92430-00</b> <b>P76544-00</b> 4830224 8x			<b>X07688-01</b> 	<b>P76305-11 K</b> ← 1226734 70x90x10 A SL RD FPM <b>P76364-11 K</b> → 90x115x13/9,5 AB SL LD FPM <b>P76388-11 K</b> → 1227942L00 100x118x10/12 A SL LD FPM <b>P76188-01 N</b> 50x70x10 B RD MVQ <b>P76201-11 N</b> 98454041 55x70x8 AB SL RD FPM	
3,0 AR 06120 AR 06124 AR 61501	133-152 kW (181-207 PS)	RZ V6 SZ V6 75 V6	01/87→	<b>S31131-00</b> ⑫ ⑬ 1954679100250 <b>D31131-00</b> ⑫ <b>R31130-00</b> ③ 60507425	<b>H07713-00 L</b> 60569896 95 Ø  <b>H07726-00 R</b> 60548751 95 Ø 		<b>X07303-01 R</b> 60808412  <b>X07307-01 L</b> 60808971 	<b>N92960-00</b> <b>P76602-00</b> 60507108 12x	<b>X07712-01</b> 60522310 12x 		<b>X07578-01</b> 60506636 6x 	<b>X06963-01</b> 96411871 	<b>P76220-01 K</b> ← 48x65x10 AB SL RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 A LD FPM <b>P76032-01 N</b> 3x 32x47x10 A RD NBR
3,0 AR 06410 AR 06412 AR 06430 AR 64301 AR 64305 AR 66303	132-147 kW (180-200 PS)	164 164 V6	06/87-09/98	<b>S31130-00</b> ⑫ ⑬ 5892689 <b>D31130-00</b> ⑫ 5892690 <b>R31130-00</b> ③ 60507425	<b>H07713-00 L</b> 60569896 95 Ø  <b>H07726-00 R</b> 60548751 95 Ø 		<b>X07303-01 R</b> 60808412  <b>X07307-01 L</b> 60808971 	<b>N92960-00</b> <b>P76602-00</b> 60507108 12x	<b>X07955-01</b> 60563671 2x 		<b>X07578-01</b> 60506636 6x 	<b>X07763-01</b> 60807818 	<b>P76220-01 K</b> ← 48x65x10 AB SL RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 A LD FPM <b>P76032-01 N</b> 3x 32x47x10 A RD NBR
3,0 AR 16101 AR 64304 AR 66301	141-171 kW (192-233 PS)	SPIDER V6 164 164 24V	09/92-04/05	<b>S31693-00</b> ⑫ ⑬ 60778799 <b>D31693-00</b> ⑫ 60778798 <b>B31693-00</b> ⑬	<b>H50273-00 R</b> 60570352  <b>H50274-00 L</b> 60570351 95 Ø 	<b>T80024-00</b>	<b>V31693-00 R</b> 60808412 <b>V32015-00 L</b> 60808971  <b>X53056-01 R</b> 60568809  <b>X53057-01 L</b> 60810603 NBR 	<b>N92920-00</b> <b>P76532-00</b> 4357028 24x	<b>X56964-01</b> 60810616 2x 		<b>X51431-01</b> 60630269 6x 	<b>X07763-01</b> 60807818 	<b>P76220-01 K</b> ← 48x65x10 AB SL RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 A LD FPM <b>P76032-01 N</b> 4x 32x47x10 A RD NBR

ALFA ROMEO																		
Ltr.			<b>1</b>															
3,0 AR 16102	162 kW (220 PS)	GTV V6 24V SPIDER V6 24V	10/96-10/03	<b>S32909-00</b> <sup>12</sup> <sup>13</sup> 71713724 <b>D32909-00</b> <sup>12</sup> 71713723	<b>H80028-00 R</b> 60602071  <b>H80029-00 L</b> 60548751 	 	<b>X53729-01 R</b> 0060609978 NBR  <b>X53730-01 L</b> 0060609979 NBR 	<b>N92920-00</b> <b>P76532-00</b> 4357028	24x	<b>X88997-01</b> 60513868	6x		<b>X52321-01</b> 60810625	6x		<b>70-31414-10</b> 	<b>P77139-01 K</b> ← 0060813277 48x65x8 RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 ALD FPM	
3,0 AR 16105 AR 34302	160-166 kW (218-226 PS)	GTV V6 24V SPIDER V6	09/94 →		<b>H80028-00 R</b> 60602071  <b>H80029-00 L</b> 60548751 	 	<b>V38097-00 R</b> 60609978 +60610548  <b>V38098-00 L</b> 60609979 +60610548 			<b>X56964-01</b> 60810616	2x							
3,0 AR 34301	166 kW (226 PS)	166 V6 24V	09/98-10/00	<b>S32909-00</b> <sup>12</sup> <sup>13</sup> 71713724 <b>D32909-00</b> <sup>12</sup> 71713723			<b>X53729-01 R</b> 0060609978 NBR  <b>X53730-01 L</b> 0060609979 NBR 	<b>N92920-00</b> <b>P76532-00</b> 4357028	24x	<b>X88997-01</b> 60513868	6x		<b>X52321-01</b> 60810625	6x		<b>70-31414-10</b> 	<b>P77139-01 K</b> ← 0060813277 48x65x8 RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 ALD FPM	



ALFA ROMEO													
Ltr.													
3,0 AR 36101	162 kW (220 PS)	166 V6 24V	10/00-06/07	<b>S32909-00</b> <sup>12</sup> <sup>13</sup> 71713724 <b>D32909-00</b> <sup>12</sup> 71713723	<b>H80028-00 R</b> 60602071  <b>H80029-00 L</b> 60548751 		<b>V38097-00 R</b> 60609978 +60610548  <b>V38098-00 L</b> 60609979 +60610548  <b>X53729-01 R</b> 0060609978 NBR  <b>X53730-01 L</b> 0060609979 NBR 	<b>N92920-00</b> <b>P76532-00</b> 4357028 24x	<b>X56964-01</b> 60810616 2x  <b>X88997-01</b> 60513868 6x 		<b>X52321-01</b> 60810625 6x 	<b>70-31414-10</b> 	<b>P77139-01 K</b> ← 0060813277 48x65x8 RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 ALD FPM
3,0 AR 64307 AR 64308 AR 66302 AR 66304	155-171 kW (211-233 PS)	164 24V	09/92→	<b>S31693-00</b> <sup>12</sup> <sup>13</sup> 60778799 <b>D31693-00</b> <sup>12</sup> 60778798 <b>B31693-00</b> <sup>13</sup>	<b>H50273-00 R</b> 60570352  <b>H50274-00 L</b> 60570351 95 Ø 	<b>T80024-00</b>	<b>V31693-00 R</b> 60808412 <b>V32015-00 L</b> 60808971  <b>X53056-01 R</b> 60568809  <b>X53057-01 L</b> 60810603 NBR 	<b>N92920-00</b> <b>P76532-00</b> 4357028 24x	<b>X56964-01</b> 60810616 2x 		<b>X51431-01</b> 60630269 6x 		<b>P76220-01 K</b> ← 48x65x10 AB SL RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 ALD FPM <b>P76032-01 N</b> 4x 32x47x10 ARD NBR
3,0 AR 64399	132-145 kW (180-197 PS)				<b>H07713-00 L</b> 60569896 95 Ø  <b>H07726-00 R</b> 60548751 95 Ø 		<b>N92960-00</b> <b>P76602-00</b> 60507108 12x	<b>X07955-01</b> 60563671 2x 		<b>X07578-01</b> 60506636 6x 	<b>X07763-01</b> 60807818 	<b>P76220-01 K</b> ← 48x65x10 AB SL RD FPM <b>P76374-01 K</b> → 60811338 84x105x12 ALD FPM	

