

SAAB													
Ltr.													
1,5 Ford V4	46-50 kW (63-68 PS)	95	10/65-08/80	<b>S30058-00</b> <sup>(12)</sup> <sup>(13)</sup> 88 14 279 <b>D30058-00</b> <sup>(12)</sup> 88 14 287	<b>H01834-00 R</b> 88 12 760 92,5 Ø 1,2 mm  <b>H01837-00 L</b> 88 12 752 92,5 Ø 1,2 mm 		<b>X01922-01</b> 88 11 077 Kork	2x <b>N90600-00</b> 88 12 067 (x8) <b>P76505-00</b> 88 12 067	8x <b>X01924-01</b> 88 31 034 		<b>X01909-01</b> 88 01 466  <b>X02952-01</b> <sup>(A)</sup> 	2x <b>E30057-00</b> 	<b>P76099-11 K</b> ← 35x50x8 A SL WD FPM <b>P76266-01 K</b> → 60,3x76,2x11,1 A SL LD MVQ
1,8 Z 18 XE	90 kW (122 PS)	9-3	01/04→	<b>D36514-00</b> <sup>(12)</sup> 91 17 672	<b>H80360-00</b> 93 179 932 81,5 Ø MLS 	<b>T50479-00</b> 90 412 701 (10x) 	<b>X53950-01</b> 90 536 414 NBR 	<b>N92115-00</b> 91 58 057 (16x) <b>P76707-00</b> 91 58 057	16x <b>X86876-01</b> 90 523 057 		<b>X81064-01</b> 90 536 199 	<b>70-31414-10</b> 	<b>P76054-01 K</b> ← 24 465 791 30x40x7 A SL RD MVQ <b>P76341-01 K</b> → 55 355 235 80x98x10 A SL LD FPM <b>P76095-01 N</b> 2x 45 03 983 35x48x7 A SL RD MVQ
1,9 Z 19 DT Z 19 DTH	88-110 kW (120-150 PS)	9-3 TiD 9-5 TiD	09/04→	<b>D36888-00</b> <sup>(12)</sup> 93 186 198  <b>B36888-00</b> <sup>(13)</sup> <sup>(38)</sup>	<b>H08135-00</b> 93 138 224 0,82 mm MLS <b>H18135-10</b> 93 138 226 0,92 mm 1 MLS <b>H28135-20</b> 93 138 227 83 Ø 1,02 mm 2 MLS 	<b>X83091-01</b> 93 178 481 	<b>N92003-00</b> 93 178 590 (16x) <b>P76808-00</b> 93 178 590	16x <b>X87664-01</b> 93 179 058 		<b>X51965-01</b> 93 178 708 	<b>70-31414-10</b> 	<b>P76444-01 K</b> ← 93 180 737 31x41x7 AB SL RD FPM <b>P77403-01 K</b> → <sup>(A)</sup> 93 178 503 PTFE <b>P77404-01 N</b> 93 178 980 30x45x7 AB SL RD NBR	
2,0 BSI 20 B20	74-107 kW (100-146 PS)	900 900 Turbo 99 Turbo	10/77-12/88		<b>H50490-00</b> 83 58 780 91 Ø 1,2 mm 	<b>X83096-01</b> 93 05 970 NBR 					<b>X51440-01</b> 83 61 842  <b>X51441-01</b> 83 61 859 	2x <b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM
2,0 BT20	79 kW (108 PS)	900	09/78-08/84		<b>H50490-00</b> 83 58 780 91 Ø 1,2 mm 	<b>X83096-01</b> 93 05 970 NBR 			<b>X56926-01</b> 75 82 315 		<b>X51440-01</b> 83 61 842  <b>X51500-01</b> 83 49 045 	2x <b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM

SAAB												
Ltr.												
2,0 B20C B20I	74 kW (100 PS)	99	09/74-12/84	<b>S31800-00</b> ⑬ 93 37 213 <b>D31800-00</b> 93 37 239 <b>B31800-00</b> ⑬ 95 49 050	<b>H50490-00</b> 83 58 780 91 Ø 1,2 mm →12/80  <b>H50315-00</b> 75 05 217 91 Ø 1,3 mm 		<b>X83097-01</b> 83 59 226 NBR →12/78  <b>X83096-01</b> 93 05 970 NBR 01/79-12/80  <b>X53035-01</b> 93 55 991 NBR 		<b>X57080-01</b> 93 07 257 	<b>X51500-01</b> 83 49 045 →12/78  <b>X81914-01</b> 83 56 933 01/79-12/80  <b>X51440-01</b> 83 61 842  <b>X51441-01</b> 83 61 859 	<b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM
2,0 B20I B20T B201XC	74-79 kW (100-108 PS)	90 900 99	03/76-12/88	<b>S31800-00</b> ⑬ 93 37 213 <b>D31800-00</b> 93 37 239 <b>B31800-00</b> ⑬ 95 49 050	<b>H50315-00</b> 75 05 217 91 Ø 1,3 mm 		<b>X53035-01</b> 93 55 991 NBR 		<b>X57080-01</b> 93 07 257 	<b>X51440-01</b> 83 61 842  <b>X51441-01</b> 83 61 859 	2x <b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM
2,0 B20I	74-81 kW (100-110 PS)	900 900 i 99	04/72-08/90		<b>H50490-00</b> 83 58 780 91 Ø 1,2 mm 		<b>X83097-01</b> 83 59 226 NBR 		<b>X56926-01</b> 75 82 315 	<b>X51440-01</b> 83 61 842  <b>X51441-01</b> 83 61 859 	<b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM
2,0 B201S B201XL	103-110 kW (140-150 PS)	900 Turbo	09/78-12/91	<b>S31802-00</b> ⑬ 93 37 254 <b>D31802-00</b> 93 37 254 <b>B31800-00</b> ⑬ 95 49 050	<b>H50315-00</b> 75 05 217 91 Ø 1,3 mm 	<b>T50315-00</b> 59 55 794 (10x) 	<b>X53035-01</b> 93 55 991 NBR 		<b>X56926-01</b> 75 82 315 	<b>X51440-01</b> 83 61 842  <b>X51441-01</b> 83 61 859 	2x <b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM
2,0 B201XI	85 kW (115 PS)	900 900 i	11/80-08/90	<b>S31801-00</b> ⑬ 93 37 221 <b>D31801-00</b> 93 37 247	<b>H50315-00</b> 75 05 217 91 Ø 1,3 mm 		<b>X53035-01</b> 93 55 991 NBR 		<b>X56926-01</b> 75 82 315  <b>X58522-01</b> 83 48 518 	<b>X51440-01</b> 83 61 842  <b>X51441-01</b> 83 61 859 	2x <b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM

SAAB												
Ltr.			<b>1</b>									
2,0 B202 B202XI	92-127 kW (125-172 PS) 900 9000 9000 Turbo	12/85-12/92	<b>D31803-00</b> ⑫ 88 18 007 +75 00 713 (16x) Mot.→G 52494 <b>D31804-00</b> ⑫ 88 19 831 +75 00 713 (16x) Mot.G 52495→	<b>H50316-00</b> 91 69 079 91 Ø 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31803-00</b> 88 17 512 Mot.→G 52494  <b>V31804-00</b> 93 21 464 Mot.G 52495→ 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713	16x <b>X56927-01</b> 75 84 436 	<b>X51442-01</b> 75 18 996 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P77415-01</b> K → 91 75 902 88x108x11,1 AB SL LD FPM		
2,0 B202I B202S	93-110 kW (126-150 PS) 900 9000 Turbo 9000 CD 9000 Turbo	10/87-12/98	<b>D31804-00</b> ⑫ 88 19 831 +75 00 713 (16x)	<b>H50316-00</b> 91 69 079 91 Ø 	<b>T50316-00</b> 75 18 343 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713	16x <b>X56927-01</b> 75 84 436 	<b>X51442-01</b> 75 18 996 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11</b> K → 91 75 902 88x108x11 A SL LD FPM		
2,0 B202L	129-150 kW (175-204 PS) 900 Turbo 9000 9000 Turbo	09/84-12/98	<b>D31803-00</b> ⑫ 88 18 007 +75 00 713 (16x)	<b>H50316-00</b> 91 69 079 91 Ø 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31803-00</b> 88 17 512 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713	16x <b>X56927-01</b> 75 84 436 	<b>X51442-01</b> 75 18 996 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11</b> K → 91 75 902 88x108x11 A SL LD FPM		
2,0 B202XL	118-129 kW (160-175 PS) 900 Turbo 9000 Turbo	01/84-06/94	<b>D31804-00</b> ⑫ 88 19 831 +75 00 713 (16x)	<b>H50316-00</b> 91 69 079 91 Ø 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713	16x <b>X56927-01</b> 75 84 436 	<b>X51442-01</b> 75 18 996 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11</b> K → 91 75 902 88x108x11 A SL LD FPM		
2,0 B204E B204I B204R	96-147 kW (131-200 PS) 900 9000 9000 CD 9000 Turbo 9-3 9-3 Turbo 9-5 Turbo	09/92-12/09	<b>D36105-00</b> ⑫ 88 22 033 +75 00 713 (16x) +88 22 041	<b>H80101-00</b> 91 85 695 91 Ø 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713	16x <b>X89145-01</b> 91 38 884 	<b>X81915-01</b> 91 66 497 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11</b> K → 91 75 902 88x108x11 A SL LD FPM		
2,0 B204L	136 kW (185 PS) 900 Turbo 9-3 Turbo	07/93-08/03	<b>D36105-00</b> ⑫ 88 22 033 +75 00 713 (16x) +88 22 041	<b>H80101-00</b> 91 85 695 91 Ø 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713	16x <b>X89145-01</b> 91 38 884 	<b>X81915-01</b> 91 66 497 	<b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11</b> K → 91 75 902 88x108x11 A SL LD FPM <b>P77415-01</b> N → 91 75 902 88x108x11 LD FPM	
2,0 B205E B205R	110-151 kW (150-205 PS) 9-3 Turbo 9-5 Turbo	09/97-12/09	<b>D36928-00</b> ⑫	<b>H80390-00</b> 59 55 174 91 Ø 0,4 mm MLS 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92106-00</b> 59 55 570 (16x) <b>P76813-00</b> 59 55 570	16x <b>X89146-01</b> 91 86 412  <b>X89147-01</b> ⑩ 91 86 404 	<b>X81915-01</b> 91 66 497 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11</b> K → 91 75 902 88x108x11 A SL LD FPM		

SAAB													
Ltr.													
2,0 B206I	98 kW (133 PS)	900	07/93-07/94	<b>D36105-00</b> ⑫ 88 22 033 +75 00 713 (16x) +88 22 041	<b>H80101-00</b> 91 85 695 91 Ø 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>P76532-00</b> 75 00 713	16x <b>X89145-01</b> 91 38 884 	<b>X81915-01</b> 91 66 497 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM		
2,0 B207E B207L B207R	110-177 kW (150-241 PS)	9-3 Turbo	09/02→	<b>D36927-00</b> ⑫	<b>H80488-00</b> 93 175 913 87 Ø MLS 	<b>T80476-00</b> 90 537 691 (10x) 	<b>V32927-00</b> 	<b>N92104-00</b> 90 537 241 (16x) <b>P76771-00</b> 90 537 241	16x <b>X87681-01</b> 12 786 262 	<b>X81512-01</b> 12 786 717 <b>X81913-01</b> 12 749 952 	<b>70-31414-10</b> 	<b>P77155-01 K</b> ← 90 571 925 42x55x7 A SL RD FPM <b>P76384-01 K</b> → 45 01 201 90x104x9/11 AB SL LD FPM	
2,1 B212I	100 kW (136 PS)	900	08/90-06/94	<b>D31806-00</b> ⑫ 93 21 597	<b>H50317-00</b> 87 87 111 94 Ø 1,3 mm 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713	16x <b>X56928-01</b> 91 26 277 	<b>X51442-01</b> 75 18 996 	<b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM	
2,2 D223L X 22 DTH	85-92 kW (115-125 PS)	9-3 T1D 9-5 T1D	02/98→	<b>D32751-00</b> ⑫  <b>B32751-00</b> ⑬	<b>H04274-00</b> 90 502 269 1,2 mm MLS <b>H14274-10</b> 95 44 669 1,3 mm 1 MLS <b>H24274-20</b> 93 179 233 85,5 Ø 1,4 mm 2 MLS 	<b>T04274-00</b> 95 43 018 (10x) 	<b>X53516-01</b> 47 73 420 ACM 	<b>N92990-00</b> 45 00 898 (16x) <b>P76662-00</b> 45 00 898	16x <b>X58518-01</b> 95 43 844 <b>X58519-01</b> ⑩ 95 43 919 	<b>X52089-01</b> 96 43 984 	<b>X54631-01</b> 47 72 026 Aluminium 	<b>P76443-01 K</b> ← 95 43 455 55x68x8 A SL RD FPM <b>P77157-01 K</b> → 47 71 143 99x114x11 A SL LD FPM	
2,2 Y 22 DTH	85-88 kW (116-120 PS)			<b>D32751-00</b> ⑫ 	<b>H04274-00</b> 90 502 269 1,2 mm MLS <b>H14274-10</b> 95 44 669 1,3 mm 1 MLS <b>H24274-20</b> 93 179 233 85,5 Ø 1,4 mm 2 MLS 	<b>T04274-00</b> 95 43 018 (10x) 	<b>X53516-01</b> 47 73 420 ACM 	<b>N92990-00</b> 45 00 898 (16x) <b>P76662-00</b> 45 00 898	16x <b>X58518-01</b> 95 43 844 	<b>X52089-01</b> 96 43 984 	<b>P76443-01 K</b> ← 95 43 455 55x68x8 A SL RD FPM <b>P77157-01 K</b> → 47 71 143 99x114x11 A SL LD FPM		
2,3 B234E B234I B234R	107-165 kW (146-224 PS)	900 9000 9000 AERO CS 9000 CD 9000 CDE Eco-Power 9000 Turbo	08/89-12/98	<b>D36105-00</b> ⑫ 88 22 033 +75 00 713 (16x) +88 22 041	<b>H80101-00</b> 91 85 695 91 Ø 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713	16x <b>X89145-01</b> 91 38 884 	<b>X81915-01</b> 91 66 497 	<b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01 K</b> ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11 K</b> → 91 75 902 88x108x11 A SL LD FPM	

SAAB														
2,3 B234L	143-147 kW (195-200 PS)	9000 CD Turbo 9000 Turbo	07/90-12/98	<b>D31807-00</b> ⑫ 93 21 605 +75 00 713 (16x) →09/93 <b>D36105-00</b> ⑫ 88 22 033 +75 00 713 (16x) +88 22 041 09/93→	<b>H50316-00</b> 91 69 079 91 Ø →09/93  <b>H80101-00</b> 91 85 695 91 Ø 09/93→ 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92850-00</b> 75 00 713 (16x) <b>P76532-00</b> 75 00 713 	<b>X56928-01</b> 91 26 277 →09/93  <b>X89145-01</b> 91 38 884 09/93→ 	<b>X51442-01</b> 75 18 996 →09/93  <b>X81915-01</b> 91 66 497 09/93→ 	<b>X54068-01</b> 75 14 946 Stahl 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11</b> K → 91 75 902 88x108x11 A SL LD FPM		
2,3 B235E B235L B235R	125-224 kW (170-305 PS)	9-3 9-3 Turbo 9-5 Turbo	09/97-12/09	<b>D36928-00</b> ⑫ 	<b>H80390-00</b> 59 55 174 91 Ø 0,4 mm MLS 	<b>T50315-00</b> 59 55 794 (10x) 	<b>V31804-00</b> 93 21 464 	<b>N92106-00</b> 59 55 570 (16x) <b>P76813-00</b> 59 55 570 	<b>X89146-01</b> 91 86 412  <b>X89147-01</b> ⑩ 91 86 404 	<b>X81915-01</b> 91 66 497 	<b>P76297-01</b> K ← 93 09 204 48x66,6x10 A SL RD FPM <b>P76359-11</b> K → 91 75 902 88x108x11 A SL LD FPM			
2,5 B258I	125 kW (170 PS)	900 V6	07/93-02/98	<b>D31630-00</b> ⑫ <b>B36929-00</b> ⑬ 	<b>H50220-00</b> 2x 45 01 045 83 Ø 	<b>T50220-00</b> 45 01 060 (16x) 	<b>V31630-00</b> 2x 93 21 969 	<b>N92830-00</b> 45 00 898 (24x) <b>P76662-00</b> 45 00 898 	<b>X51330-01</b> 2x 45 04 973  <b>X51331-01</b> ⑩ 45 04 965 	<b>X52446-01</b> 2x 	<b>P76130-01</b> K ← 90 322 669 38x50x8 A SL RD FPM <b>P76384-01</b> K → 45 01 201 90x104x9/11 AB SL LD FPM			
3,0 B308E	147 kW (200 PS)	9-5 V6t	01/98-12/09	<b>D32997-00</b> ⑫ <b>B36929-00</b> ⑬ 	<b>H80087-00</b> 2x 47 73 453 87,5 Ø 	<b>T50220-00</b> 45 01 060 (16x) 	<b>V36929-00</b> 2x 47 70 764 +45 04 247  <b>X53750-01</b> 2x 47 70 764 NBR 	<b>N92830-00</b> 45 00 898 (24x) <b>P76662-00</b> 45 00 898 	<b>X58991-01</b> 2x 47 70 418  <b>X85336-01</b> ⑩ 3x 47 70 426 	<b>X52446-01</b> 2x 	<b>X54798-01</b> 45 02 167 NBR 	<b>P76130-01</b> K ← 90 322 669 38x50x8 A SL RD FPM <b>P76384-01</b> K → 45 01 201 90x104x9/11 AB SL LD FPM <b>P76095-01</b> N 4x 45 03 983 35x48x7 A SL RD MVQ		
3,0 B308I	155 kW (211 PS)	9000 V6	07/94-12/98	<b>D36532-00</b> ⑫ <b>B36929-00</b> ⑬ 	<b>H50220-00</b> 2x 45 01 045 83 Ø 	<b>V31630-00</b> 2x 93 21 969 	<b>N92830-00</b> 45 00 898 (24x) <b>P76662-00</b> 45 00 898 	<b>X58991-01</b> 2x 47 70 418  <b>X85336-01</b> ⑩ 3x 47 70 426 	<b>X52446-01</b> 2x 	<b>P76130-01</b> K ← 90 322 669 38x50x8 A SL RD FPM <b>P76384-01</b> K → 45 01 201 90x104x9/11 AB SL LD FPM <b>P76095-01</b> N 4x 45 03 983 35x48x7 A SL RD MVQ				

SAAB																
Ltr.																
3,0 D308L	130 kW (177 PS)	9-5 TID	07/01-12/09	<b>D83348-00</b> <sup>12</sup>	2x	<b>H01828-00 R</b> 59 50 696 0,6 mm 1 MLS <b>H11828-10 R</b> 59 50 704 0,65 mm 2 MLS <b>H21828-20 R</b> 59 50 712 0,7 mm 3 MLS  <b>H01829-00 L</b> 59 50 662 0,6 mm 1 MLS <b>H11829-10 L</b> 59 50 670 0,65 mm 2 MLS <b>H21829-20 L</b> 59 50 688 0,7 mm 3 MLS 	<b>T01828-00</b> 	<b>X83348-01</b> 59 54 722 	2x	<b>N92107-00</b> 59 50 597 (24x) <b>P76814-00 ES</b> 59 50 597	24x	<b>X87680-01</b> 59 52 486 		<b>X81513-01</b> 59 52 684 		<b>P77416-01 K</b> ← 50x68x7,5 A SL RD FPM <b>P77358-01 K</b> → 5950415 95x118x13 A SL LD FPM <b>P77727-01 N</b> 45 03 983 37x50x7 A SL LD ACM